



# DueList Report

FALCON 2000

S/N 139 N26NJ

OWNER: SHORT HILLS AVIATION SERVICES, INC. ADDRESS: 18 AIRPORT ROAD MORRISTOWN NJ 07960 OFFICE: 973-292-3395 FAX:	OPERATOR: SHORT HILLS AVIATION SERVICES, INC. ADDRESS: 18 AIRPORT ROAD MORRISTOWN NJ 07960 OFFICE: 973-292-3395 FAX:	OPERATOR: GARDEN AIR LLC ADDRESS: C/O SIGNATURE FLIGHT SUPPORT MORRISTOWN NJ 07960 OFFICE: (973) 292-3395 FAX: (973) 292-3396
ANALYST: JON KURMANCHIK EMAIL: JKURMANCHIK@CAMPSYSTEMS.COM	631-619-4563 (DIRECT) +1-631-588-3200 (MAIN) WWW.CAMPSYSTEMS.COM	800-787-9749 (EFAX-CARDS) 631-980-4222 (FAX)

PROJECTED: 12 MOS. to 06-APR-2025

AIRCRAFT	SERIAL/REGNO: 139/N26NJ	MODEL: FALCON 2000	MANUFACTURER: DASSAULT AVIATION S.A.
----------	-------------------------	--------------------	--------------------------------------

CERTIFICATION DATE: 01-MAR-2000

LAST ACTUALS:	PROJECTED:
14354.4 A/C HRS as of 16-MAR-2024	14954.40
9502 AFL as of 16-MAR-2024	9862
11939 APH as of 16-JAN-2024	12539
14114 APS as of 16-JAN-2024	14834

APU	SERIAL/PART: P-324/3800548-2	MODEL: GTCP36-150(F2M)	MANUFACTURER: HONEYWELL
-----	------------------------------	------------------------	-------------------------

INSTALLED ON: 15-JUN-2022	LAST ACTUALS:	PROJECTED:
0 APU HRS 13630.3 A/C HRS	11890 APU HRS as of 30-JAN-2024	12490
APUS	14130 APUS as of 30-JAN-2024	14850

ENGINE NO. 1	SERIAL/PART: P105362/3050000-5	MODEL: CFE738-1-1B	MANUFACTURER: CFE
--------------	--------------------------------	--------------------	-------------------

INSTALLED ON: 28-FEB-2023	LAST ACTUALS:	PROJECTED:
11842.8 ENG. HRS 13865.3 A/C HRS	12332.2 ENG. HRS as of 30-JAN-2024	12932.20
7911 ENC	8234 ENC as of 30-JAN-2024	8714

ENGINE NO. 2	SERIAL/PART: P105414/3050000-5	MODEL: CFE738-1-1B	MANUFACTURER: CFE
--------------	--------------------------------	--------------------	-------------------

INSTALLED ON: 28-FEB-2023	LAST ACTUALS:	PROJECTED:
12003.3 ENG. HRS 13865.3 A/C HRS	12491.3 ENG. HRS as of 30-JAN-2024	13091.30
8045 ENC	8368 ENC as of 30-JAN-2024	8848



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
057135		NO. 1 ENGINE - 1600 HR BOROSCOPE INSPECTION						Package ATA:05
	MOS			20-Aug-19				
	HRS	1600 (+50)		10645.5	(12245.5)14267.7	12295.5	OVD	
	ENC			7219				
		REF:						
253A01 <sup>U</sup>		RESTORE MED-AIR FIRST AID KIT						Service ATA:25
PN:AFK 1.0	MOS	12		28-Mar-23	28-Mar-24		OVD	
SN:032012023	HRS			13908.8				
	AFL			9201				
		REF:						
345A03 <sup>U</sup>		UPDATE FMS NAV DATABASE						Service ATA:34
	DAYS	30		14-Feb-24	15-Mar-24		OVD	
	HRS			14354.4				
	AFL			9502				
		REF:						
55-10-00-270-801-01		ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS						Service ATA:55
	MOS	T:288 (+2m)		01-Mar-00	01-Mar-24	01-May-24	TOL (+25 d)	06-Apr-2024
	HRS			0				
	AFL	T:11250		0	11250		1748	
		REF: AMM 55-10-00-270-801						
55-30-00-270-801-01		ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS						Service ATA:55
	MOS	T:288 (+2m)		01-Mar-00	01-Mar-24	01-May-24	TOL (+25 d)	06-Apr-2024
	HRS			0				
	AFL	T:11250		0	11250		1748	
		REF: AMM 55-30-00-270-801						
32-11-00-700-802-01		CHECK AND ADJUSTMENT OF THE AXIAL PLAY TORQUE LINKS OF THE MAIN LANDING GEARS (MLG) - LH MLG LEG (5GA)						Service ATA:32
PN:D23345000-8	MOS	72 (+3%)		07-Aug-18	20-Mar-24 (M)	24-May-24	TOL (+48 d)	06-Apr-2024
SN:B76	HRS			11704.7				
	AFL	3000 (+3%)		7913	10913	11003	1411 (+90)	
		REF: AMM 32-11-00-700-802						
32-11-00-700-802-02		CHECK AND ADJUSTMENT OF THE AXIAL PLAY TORQUE LINKS OF THE MAIN LANDING GEARS (MLG) - RH MLG LEG (10GA)						Service ATA:32
PN:D23346000-8	MOS	72 (+3%)		07-Aug-18	20-Mar-24 (M)	24-May-24	TOL (+48 d)	06-Apr-2024
SN:B76	HRS			11704.7				
	AFL	3000 (+3%)		7913	10913	11003	1411 (+90)	
		REF: AMM 32-11-00-700-802						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>32-11-00-350-801-01 RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (5GA) Service ATA:32</b>								
PN:D23345000-8	MOS	144 (+3%)		22-Mar-12	22-Mar-24	31-Jul-24	TOL (+116 d)	06-Apr-2024
SN:B76	HRS			8486.2				
	AFL	6000		5707	11707		2205	
Disposition: OVERHAUL			REF: AMM 32-11-00-350-801					
<b>32-11-00-350-801-02 RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (10GA) Service ATA:32</b>								
PN:D23346000-8	MOS	144 (+3%)		22-Mar-12	22-Mar-24	31-Jul-24	TOL (+116 d)	06-Apr-2024
SN:B76	HRS			8486.2				
	AFL	6000		5707	11707		2205	
Disposition: OVERHAUL			REF: AMM 32-11-00-350-801					
<b>32-11-25-220-801-01 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA) Service ATA:32</b>								
	MOS	72 (+8m)			22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	06-Apr-2024
	HRS							
	AFL							
			REF: AMM 32-11-25-220-801					
<b>32-11-25-220-801-02 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA) Service ATA:32</b>								
	MOS	72 (+8m)			22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	06-Apr-2024
	HRS							
	AFL							
			REF: AMM 32-11-25-220-801					
<b>32-11-25-220-801-03 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA) Service ATA:32</b>								
	MOS	72 (+8m)			22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	06-Apr-2024
	HRS							
	AFL							
			REF: AMM 32-11-25-220-801					
<b>32-11-25-220-801-04 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA) Service ATA:32</b>								
	MOS	72 (+8m)			22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	06-Apr-2024
	HRS							
	AFL							
			REF: AMM 32-11-25-220-801					
<b>28-30-00-680-802-05 DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY Service ATA:28</b>								
	MOS	2 (+5d)		07-Feb-24	07-Apr-24	12-Apr-24	1 d (+5)	07-Apr-2024(6)
	HRS			14354.4				
	AFL			9502				
			REF: AMM 28-30-00-680-802					



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>28-30-00-680-804-01</b>								
<b>DRAINING WATER FROM THE FUEL TANKS</b>								
	MOS	2 (+5d)		07-Feb-24	07-Apr-24	12-Apr-24	1 d (+5)	Service ATA:28 07-Apr-2024(6)
	HRS			14354.4				
	AFL			9502				
REF: AMM 28-30-00-680-804								
<b>32-44-00-780-801-01</b>								
<b>PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES</b>								
	MOS	2 (+5d)		07-Feb-24	07-Apr-24	12-Apr-24	1 d (+5)	Service ATA:32 07-Apr-2024(6)
	HRS			14354.4				
	AFL			9502				
REF: AMM 32-44-00-780-801								
<b>49-90-00-280-801-01</b>								
<b>APU - SPECTROMETRIC ANALYSIS OF APU OIL AND OIL FILTER (SOAP)</b>								
	MOS			08-Sep-22				Service ATA:49 20-Apr-2024(2)
	HRS	500 (+3%)		11414	11914	11929	24 (+15)	
	APUS			13380				
REF: AMM 49-90-00-280-801								
<b>24-32-09-610-801-01</b>								
<b>SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY INSTRUMENTS BATTERY (330NH)</b>								
PN:804747	MOS	12 (+3%)		02-May-23	02-May-24	13-May-24	26 d (+11)	Service ATA:24 02-May-2024
SN:2945	HRS			13952.4				
	AFL			9231				
REF: AMM 24-32-09-610-801								
<b>24-32-09-610-801-02</b>								
<b>SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP)</b>								
PN:135687	MOS	12 (+3%)		02-May-23	02-May-24	13-May-24	26 d (+11)	Service ATA:24 02-May-2024
SN:2221	HRS			13952.4				
	AFL			9231				
REF: AMM 24-32-09-610-801								
<b>24-32-09-610-801-03</b>								
<b>SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)</b>								
PN:804747	MOS	12 (+3%)		02-May-23	02-May-24	13-May-24	26 d (+11)	Service ATA:24 02-May-2024
SN:2959	HRS			13952.4				
	AFL			9231				
REF: AMM 24-32-09-610-801								
<b>256K06<sup>U</sup></b>								
<b>INSPECT/RECERTIFY FIRST AID KIT</b>								
PN:500939	MOS	12		02-May-23	02-May-24		26 d	Service ATA:25 02-May-2024
SN:032012023	HRS			13952.4				
	AFL			9231				
REF:								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
26-20-09-220-801-01		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (L30WB)						
PN:861630	MOS	12 (+1m)		02-May-23	02-May-24	02-Jun-24	26 d (+31)	02-May-2024
SN:25784	HRS							
	AFL							
REF: AMM 26-20-09-220-801								
26-20-09-220-801-02		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (R30WB)						
PN:861630	MOS	12 (+1m)		02-May-23	02-May-24	02-Jun-24	26 d (+31)	02-May-2024
SN:55415	HRS							
	AFL							
REF: AMM 26-20-09-220-801								
26-20-09-220-801-03		WEIGHING OF THE FIRE EXTINGUISHERS - APU FIRE EXTINGUISHER (35WB)						
PN:861630	MOS	12 (+1m)		02-May-23	02-May-24	02-Jun-24	26 d (+31)	02-May-2024
SN:53916	HRS							
	AFL							
REF: AMM 26-20-09-220-801								
34-23-00-720-801-01		FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - ADU (470FE)						
PN:27100-01-01	MOS	24 (+3%)		05-May-22	05-May-24	27-May-24	29 d (+22)	05-May-2024
SN:M018275	HRS			13592.3				
	AFL			9008				
REF: AMM 34-23-00-720-801								
34-23-00-720-801-02		FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - SFD (320NH1)						
PN:39204-00-01	MOS	24 (+3%)		05-May-22	05-May-24	27-May-24	29 d (+22)	05-May-2024
SN:M017055	HRS			13592.3				
	AFL			9008				
REF: AMM 34-23-00-720-801								
34-23-05-700-881-01		TEST SECONDARY FLIGHT DISPLAY (SFD) DATA UNIT (FAR 91.411)						
PN:27100-01-01	MOS	24		05-May-22	05-May-24		29 d	05-May-2024
SN:M018275	HRS			13592.3				
	AFL			9008				
REF: FAR 91.411								
Disposition: MANDATORY								
34-51-01-820-801-01		CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L210NR)						
PN:622-7194-201	MOS	24 (+3%)		05-May-22	05-May-24	27-May-24	29 d (+22)	05-May-2024
SN:4CDU	HRS			13592.3				
	AFL			9008				
REF: AMM 34-51-01-820-801								



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>34-51-01-820-801-02 CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R210NR) Service ATA:34</b>								
PN:622-7194-201	MOS	24 (+3%)		05-May-22	05-May-24	27-May-24	29 d (+22)	05-May-2024
SN:4AMH	HRS			13592.3				
	AFL			9008				
REF: AMM 34-51-01-820-801								
<b>FAA 2023-18-08 ICE AND RAIN PROTECTION - WING ANTI-ICE SYSTEM - INSPECTION AD ATA:30</b>								
	MOS	T:6		EFF	07-May-24 *		31 d	07-May-2024
	HRS							
	AFL							
Disposition: MANDATORY			REF: AD					
<b>32-10-00-640-801-01 LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND MLG DOOR Service ATA:32</b>								
	MOS	8 (+1m)	Adj:-10d	29-Sep-23	19-May-24	19-Jun-24	43 d (+31)	19-May-2024(2)
	HRS			14169				
	AFL	400		9395	9795		293	
REF: AMM 32-10-00-640-801								
<b>32-10-00-640-801-02 LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND MLG DOOR Service ATA:32</b>								
	MOS	8 (+1m)	Adj:-10d	29-Sep-23	19-May-24	19-Jun-24	43 d (+31)	19-May-2024(2)
	HRS			14169				
	AFL	400		9395	9795		293	
REF: AMM 32-10-00-640-801								
<b>32-20-00-640-801-01 LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS Service ATA:32</b>								
	MOS	8 (+1m)	Adj:-10d	29-Sep-23	19-May-24	19-Jun-24	43 d (+31)	19-May-2024(2)
	HRS			14169				
	AFL	400		9395	9795		293	
REF: AMM 32-20-00-640-801								
<b>25-61-00-200-881-01 INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) Service ATA:25</b>								
	MOS	12		26-May-23	26-May-24		50 d	26-May-2024
	HRS			13996.4				
	AFL			9265				
Disposition: MANDATORY			REF: FAR 91.207					
<b>31-21-05-960-801-01 REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (L10FS) BATTERY Service ATA:31</b>								
PN:M877-24HR	MOS	25		05-May-22	05-Jun-24		60 d	05-Jun-2024
SN:11116	HRS			13592.3				
	AFL			9008				
Disposition: LIFE LIMIT			REF: AMM 31-21-05-960-801					

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>31-21-05-960-801-02</b>								
<b>REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (R10FS) BATTERY</b>								
PN:M877-24HR	MOS	25		05-May-22	05-Jun-24		60 d	Service ATA:31 05-Jun-2024
SN:11117	HRS			13592.3				
	AFL			9008				
Disposition: LIFE LIMIT REF: AMM 31-21-05-960-801								
<b>55-10-33-640-801-01</b>								
<b>LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS</b>								
	MOS	36 (+1m)		19-Jan-23	19-Jan-26	19-Feb-26	653 d (+31)	Service ATA:55 06-Jun-2024
	HRS	600 (+40)	Adj:-3.2	13859.4	14456.2	14496.2	101.8 (+40)	
	AFL			9175				
REF: AMM 55-10-33-640-801								
<b>80-10-05-700-801-01</b>								
<b>OIL LEVEL CHECK OF THE ENGINE PNEUMATIC STARTER - LH ENGINE PNEUMATIC STARTER (L10EX)</b>								
	MOS			13-Nov-23				Service ATA:80 10-Jun-2024(3)
	HRS	200 (+10%)		14262.6	14462.6	14482.6	108.2 (+20)	
	AFL			9450				
REF: AMM 80-10-05-700-801								
<b>80-10-05-700-801-02</b>								
<b>OIL LEVEL CHECK OF THE ENGINE PNEUMATIC STARTER - RH ENGINE PNEUMATIC STARTER (R10EX)</b>								
	MOS			13-Nov-23				Service ATA:80 10-Jun-2024(3)
	HRS	200 (+10%)		14262.6	14462.6	14482.6	108.2 (+20)	
	AFL			9450				
REF: AMM 80-10-05-700-801								
<b>24-33-05-220-805-01</b>								
<b>CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - APU STARTER-GENERATOR (30KA)</b>								
PN:8060-160	MOS			20-Dec-23				Service ATA:24 21-Jun-2024(4)
SN:3508	HRS			14292.8				
	AFL			9471				
	APH	150		11915	12065	12095	126 (+30)	
REF: AMM 24-33-05-220-805								
<b>057110</b>								
<b>NO. 1 ENGINE - 200 HOUR ROUTINE INSPECTION</b>								
	MOS			28-Dec-23				Package ATA:05 29-Jun-2024(3)
	HRS	200 (+10%)		12270.6	(12470.6)14492.8	12490.6	138.4 (+20)	
	ENC			8203				
REF: LMM 05-21-00								
<b>057110</b>								
<b>NO. 2 ENGINE - 200 HOUR ROUTINE INSPECTION</b>								
	MOS			28-Dec-23				Package ATA:05 29-Jun-2024(3)
	HRS	200 (+10%)		12429.6	(12629.6)14492.7	12649.6	138.3 (+20)	
	ENC			8337				
REF: LMM 05-21-00								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
27-53-01-220-801-01		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (40CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-220-801-02		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-220-801-03		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L20CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-220-801-04		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R20CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-220-801-05		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-220-801-06		CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (30CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-220-801						
27-53-01-640-803-01		GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (40CF)						Service ATA:27
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
		REF: AMM 27-53-01-640-803						





# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
27-53-01-640-803-02	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L25CF) Service ATA:27							
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
	REF: AMM 27-53-01-640-803							
27-53-01-640-803-03	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L20CF) Service ATA:27							
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
	REF: AMM 27-53-01-640-803							
27-53-01-640-803-04	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R20CF) Service ATA:27							
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
	REF: AMM 27-53-01-640-803							
27-53-01-640-803-05	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R25CF) Service ATA:27							
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
	REF: AMM 27-53-01-640-803							
27-53-01-640-803-06	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (30CF) Service ATA:27							
	MOS	8 (+1m)	Adj:-3d	13-Nov-23	10-Jul-24	10-Aug-24	95 d (+31)	10-Jul-2024(2)
	HRS			14262.6				
	AFL	400		9450	9850		348	
	REF: AMM 27-53-01-640-803							
26-20-09-350-801-01	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE FIRE Service ATA:26							
PN:861630	MOS	60		16-Jul-19	16-Jul-24		101 d	16-Jul-2024
SN:25784	HRS							
	AFL							
Disposition: MANDATORY	REF: AMM 26-20-09-350-801							
26-20-09-350-801-03	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU FIRE Service ATA:26							
PN:861630	MOS	60		16-Jul-19	16-Jul-24		101 d	16-Jul-2024
SN:53916	HRS							
	AFL							
Disposition: MANDATORY	REF: AMM 26-20-09-350-801							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L10WB)						Service	ATA:26
PN:861375	MOS	60		16-Jul-19	16-Jul-24		101 d	16-Jul-2024	
SN:UNKNOWN	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
52-10-03-960-801-01		DISCARD OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (10MA1)						Service	ATA:52
PN:222900-1M03	MOS	60		16-Jul-19	16-Jul-24		101 d	16-Jul-2024	
SN:2965	HRS			11761.3					
	AFL			7947					
Disposition: LIFE LIMIT		REF: AMM 52-10-03-960-801							
05-08-00-200-800-07		36M/2400FH INSPECTION						Package	ATA:05
	MOS	36 (+1m)	Adj:-271d	05-May-22	07-Aug-24	07-Sep-24	123 d (+31)	07-Aug-2024	
	HRS	2400 (+40)		13592.3	15992.3	16032.3	1637.9 (+40)		
	AFL			9008					
		REF: MPD 05-10-00							
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service	ATA:38
	MOS	6 (+1m)		08-Feb-24	08-Aug-24	08-Sep-24	124 d (+31)	08-Aug-2024(2)	
	HRS			14354.4					
	AFL			9502					
		REF: AMM 38-10-00-670-801							
05-60-00-200-801-01		BASIC INSPECTION						Service	ATA:05
	MOS	12 (+1m)		24-Oct-23	24-Oct-24	24-Nov-24	201 d (+31)	09-Aug-2024	
	HRS	400 (+40)	Adj:-59.1	14220.4	14561.3	14601.3	206.9 (+40)		
	AFL			9426					
		REF: MPD 05-10-00, AMM 05-60-00-200-801							
78-31-00-640-802-01		GREASING OF THE THRUST REVERSER DOOR HINGE BOLTS						Service	ATA:78
	MOS	12 (+1m)		06-Dec-23	06-Dec-24	06-Jan-25	244 d (+31)	09-Aug-2024	
	HRS	400 (+40)	Adj:-131.5	14292.8	14561.3	14601.3	206.9 (+40)		
	AFL			9471					
		REF: AMM 78-31-00-640-802							
057125		NO. 1 ENGINE - 800 HOUR MINOR INSPECTION						Package	ATA:05
	MOS			28-Sep-22				13-Aug-2024	
	HRS	800 (+50)		11745.4	(12545.4)14567.6	12595.4	213.2 (+50)		
	ENC			7866					
		REF:							



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
793010		NO. 2 ENGINE - DISCARD OIL FILTER ELEMENT						Service ATA:79
	MOS			28-Dec-23				28-Aug-2024(2)
	HRS	300 (+10%)		12429.6	(12729.6)14592.7	12759.6	238.3 (+30)	
	ENC			8337				
Disposition: SERVICE LIFE LIMIT		REF: LMM 79-20-01						
793010		NO. 1 ENGINE - DISCARD OIL FILTER ELEMENT						Service ATA:79
	MOS			28-Dec-23				29-Aug-2024(2)
	HRS	300 (+10%)		12270.6	(12570.6)14592.8	12600.6	238.4 (+30)	
	ENC			8203				
Disposition: SERVICE LIFE LIMIT		REF: LMM 79-20-01						
21-52-18-100-801-01		CLEANING OF THE WATER SEPARATOR FILTER - WATER SEPARATOR FILTER (40HF1)						Service ATA:21
	MOS	24 (+1m)		08-Sep-22	08-Sep-24	08-Oct-24	155 d (+30)	08-Sep-2024
	HRS	1200 (+40)	Adj:-12.4	13765.9	14953.5	14993.5	599.1 (+40)	
	AFL			9108				
		REF: AMM 21-52-18-100-801						
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS&#13;&#10;						Service ATA:05
	MOS	12 (+1m)		24-Oct-23	24-Oct-24	24-Nov-24	201 d (+31)	14-Sep-2024
	HRS	400 (+40)		14220.4	14620.4	14660.4	266 (+40)	
	AFL			9426				
		REF: MPD 05-10-00, AMM 05-60-00-200-801						
05-60-00-200-801-07		BASIC INSPECTION - CABIN WARNING TEST						Service ATA:05
	MOS	12 (+1m)		24-Oct-23	24-Oct-24	24-Nov-24	201 d (+31)	14-Sep-2024
	HRS	400 (+40)		14220.4	14620.4	14660.4	266 (+40)	
	AFL			9426				
		REF: MPD 05-10-00, AMM 05-60-00-200-801						
26-20-15-720-801-01		WEIGH COCKPIT PORTABLE EXTINGUISHER						Service ATA:26
PN:898052	MOS	24 (+3%)		15-Sep-22	15-Sep-24	06-Oct-24	162 d (+21)	15-Sep-2024
SN:A30842796	HRS							
	AFL							
		REF: AMM 26-20-15-720-801						
26-20-15-720-801-02		WEIGH FORWARD EXTINGUISHER						Service ATA:26
PN:898052	MOS	24 (+3%)		15-Sep-22	15-Sep-24	06-Oct-24	162 d (+21)	15-Sep-2024
SN:X-456906	HRS							
	AFL							
		REF: AMM 26-20-15-720-801						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
 -Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>26-20-15-720-801-03 WEIGH AFT CABIN EXTINGUISHER Service ATA:26</b>								
PN:898052	MOS	24 (+3%)		15-Sep-22	15-Sep-24	06-Oct-24	162 d (+21)	15-Sep-2024
SN:Y-626151	HRS							
	AFL							
REF: AMM 26-20-15-720-801								
<b>49-41-04-220-801-01 APU - DETAILED INSPECTION 9 O&amp;#39;CLOCK IGNITER PLUG Service ATA:49</b>								
PN:3888002-5	MOS			08-Sep-22				19-Sep-2024
SN:N/A	HRS	750 (+3%)		11414	12164	12186.5	274 (+22.5)	
	APUS			13380				
REF: MM 49-40-33								
<b>27-25-05-350-801-01 RESTORATION OF THE YAW MAIN AFU (FUNCTIONAL TEST / SERVICING) - YAW MAIN AFU (15CL) Service ATA:27</b>								
PN:105125-01	MOS	144 (+3%)		10-Oct-12	10-Oct-24	18-Feb-25	187 d (+131)	10-Oct-2024
SN:416	HRS							
	AFL							
REF: AMM 27-25-05-350-801								
<b>54-00-00-210-810-01 GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (L5EZ) Service ATA:54</b>								
	MOS	24 (+1m)		28-Feb-23	28-Feb-25	31-Mar-25	328 d (+31)	12-Oct-2024
	HRS	800 (+40)		13865.3	14665.3	14705.3	310.9 (+40)	
	AFL			9179				
REF: AMM 54-00-00-210-810								
<b>54-00-00-210-810-02 GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (R5EZ) Service ATA:54</b>								
	MOS	24 (+1m)		28-Feb-23	28-Feb-25	31-Mar-25	328 d (+31)	12-Oct-2024
	HRS	800 (+40)		13865.3	14665.3	14705.3	310.9 (+40)	
	AFL			9179				
REF: AMM 54-00-00-210-810								
<b>27-53-01-720-803-01 CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (40CF) Service ATA:27</b>								
PN:1-5319-3	MOS			24-Oct-23				15-Oct-2024
SN:6028	HRS	450		14220.4	14670.4		316	
	AFL			9426				
REF: AMM 27-53-01-720-803								
<b>27-53-01-720-803-01A CHECK LH OUTBOARD FLAP SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40) Service ATA:27</b>								
PN:1-5319-3	MOS			24-Oct-23				15-Oct-2024
SN:6028	HRS	450		14220.4	14670.4		316	
	AFL			9426				
Disposition: MANDATORY 5-40 REF: AMM 27-53-01-720-803								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
27-53-01-720-803-02		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)							Service ATA:27
PN:5318-3	MOS			24-Oct-23				15-Oct-2024	
SN:2407	HRS	450		14220.4	14670.4		316		
	AFL			9426					
REF: AMM 27-53-01-720-803									
27-53-01-720-803-02A		CHECK LH INBOARD LATERAL FLAP SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:5318-3	MOS			24-Oct-23				15-Oct-2024	
SN:2407	HRS	450		14220.4	14670.4		316		
	AFL			9426					
Disposition: MANDATORY 5-40 REF: AMM 27-53-01-720-803									
27-53-01-720-803-06		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (30CF)							Service ATA:27
PN:2-5319-3	MOS			24-Oct-23				15-Oct-2024	
SN:659	HRS	450		14220.4	14670.4		316		
	AFL			9426					
REF: AMM 27-53-01-720-803									
27-53-01-720-803-06A		CHECK RH OUTBOARD FLAP SCREW JACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:2-5319-3	MOS			24-Oct-23				15-Oct-2024	
SN:659	HRS	450		14220.4	14670.4		316		
	AFL			9426					
Disposition: MANDATORY 5-40 REF: AMM 27-53-01-720-803									
057115		NO. 1 ENGINE - 400 HOUR ROUTINE INSPECTION							Package ATA:05
	MOS			28-Dec-23				28-Oct-2024	
	HRS	400 (+10%)		12270.6	(12670.6)14692.8	12710.6	338.4 (+40)		
	ENC			8203					
REF:									
057115		NO. 2 ENGINE - 400 HOUR ROUTINE INSPECTION							Package ATA:05
	MOS			28-Dec-23				28-Oct-2024	
	HRS	400 (+10%)		12429.6	(12829.6)14692.7	12869.6	338.3 (+40)		
	ENC			8337					
REF:									
33-20-00-200-801-01		INSPECTION OF "ALC" LIGHTING TUBES							Service ATA:33
	MOS	12 (+1m)		27-Nov-23	27-Nov-24	27-Dec-24	235 d (+30)	28-Oct-2024	
	HRS	400 (+40)		14292.8	14692.8	14732.8	338.4 (+40)		
	AFL			9471					
REF: AMM 33-20-00-200-801									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
32-44-00-250-801-01		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG OUTBOARD WHEEL (L225GC)						Service ATA:32
PN:C20384200MIC	MOS			05-Jul-23				30-Oct-2024
SN:00952	HRS			14049.3				
	AFL	400 (+3%)		9307	9707	9807	205 (+100)	
REF: AMM 32-44-00-250-801								
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R220GC)						Service ATA:32
PN:C20384200MIC	MOS			05-Jul-23				30-Oct-2024
SN:00466	HRS			14049.3				
	AFL	400 (+3%)		9307	9707	9807	205 (+100)	
REF: AMM 32-44-00-250-801								
49-91-01-220-801-01		APU - INSPECTION OF THE APU MAGNETIC DRAIN PLUG						Service ATA:49
	MOS			19-Jan-23				30-Oct-2024
	HRS	750 (+3%)	Adj:-54	11535	12231	12253.5	341 (+22.5)	
	APUS			13561				
REF: MM 49-90-46								
73-40-00-700-801-01		INDICATION TEST OF APR						Service ATA:73
	MOS	12 (+1m)		15-Jan-24	15-Jan-25	15-Feb-25	284 d (+31)	17-Nov-2024
	HRS	400 (+40)		14325.5	14725.5	14765.5	371.1 (+40)	
	AFL			9488				
REF: AMM 73-40-00-700-801								
21-71-01-350-801-01		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - OZONE CONVERTER (L1HX)						Service ATA:21
PN:41098001	MOS			02-Jun-14				22-Nov-2024
SN:7341	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 21-71-01-350-801								
21-71-01-350-801-02		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - OZONE CONVERTER (R1HX)						Service ATA:21
PN:41098001	MOS			02-Jun-14				22-Nov-2024
SN:7342	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 21-71-01-350-801								
28-70-09-350-801-01		RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - LH VALVE BOX (L260QD)						Service ATA:28
PN:B04BA1006	MOS			02-Jun-14				22-Nov-2024
SN:1031	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 28-70-09-350-801								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>28-70-09-350-801-02 RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - RH VALVE BOX (R260QD) Service ATA:28</b>								
PN:B04BA1006	MOS			02-Jun-14				22-Nov-2024
SN:838	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 28-70-09-350-801								
<b>28-70-13-720-802-02 FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R80QD) Service ATA:28</b>								
PN:B06GA1052-1	MOS			02-Jun-14				22-Nov-2024
SN:5335	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 28-70-13-720-802								
<b>29-20-03-220-801-01 CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (10GS) Service ATA:29</b>								
PN:42032	MOS			02-Jun-14				22-Nov-2024
SN:AB773	HRS	5000 (+3%)		9733.1	14733.1	14883.1	378.7 (+150)	
	AFL			6566				
REF: AMM 29-20-03-220-801								
<b>35-30-05-210-801-01 GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (10WK) Service ATA:35</b>								
PN:56009M6A-FF30A	MOS	12 (+3%)		27-Nov-23	27-Nov-24	07-Dec-24	235 d (+10)	27-Nov-2024
SN:ST68537	HRS			14292.8				
	AFL			9471				
REF: AMM 35-30-05-210-801								
<b>33-50-37-960-802-01 DISCARD OF THE EPS BATTERY PACKS - EPS 1 (5LE) BATTERY PACK Service ATA:33</b>								
PN:C734-01-030	MOS	25		28-Oct-22	28-Nov-24		236 d	28-Nov-2024
SN:CF33808/41/21	HRS			13832.6				
	AFL			9154				
Disposition: LIFE LIMIT REF: AMM 33-50-37-960-802								
<b>49-41-04-220-801-02 APU - DETAILED INSPECTION 5 O&amp;#39;CLOCK IGNITER PLUG (IF INSTALLED) Service ATA:49</b>								
PN:CH34549	MOS			19-Jan-23				02-Dec-2024
SN:NA	HRS	750 (+3%)		11535	12285	12307.5	395 (+22.5)	
	APUS			13561				
REF: MM 49-40-33								
<b>29-12-05-710-801-01 OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 1 HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (30GPB) Service ATA:29</b>								
	MOS	12 (+1m)		30-Jan-24	30-Jan-25	28-Feb-25	299 d (+29)	04-Dec-2024
	HRS	400 (+40)	Adj:-2	14354.4	14752.4	14792.4	398 (+40)	
	AFL			9502				
REF: AMM 29-12-05-710-801								



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
29-12-05-710-801-03		OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM 2 SHUT-OFF VALVE (40GPB)						Service ATA:29
	MOS	12 (+1m)		30-Jan-24	30-Jan-25	28-Feb-25	299 d (+29)	04-Dec-2024
	HRS	400 (+40)	Adj:-2	14354.4	14752.4	14792.4	398 (+40)	
	AFL			9502				
		REF: AMM 29-12-05-710-801						
27-00-00-710-803-01		OPERATIONAL TEST OF THE SERVO-ACTUATOR ACCUMULATOR MONITORING LOGIC						Service ATA:27
	MOS	12 (+1m)		07-Feb-24	07-Feb-25	07-Mar-25	307 d (+28)	05-Dec-2024
	HRS	400 (+40)		14354.4	14754.4	14794.4	400 (+40)	
	AFL			9502				
		REF: AMM 27-00-00-710-803						
27-50-00-720-802-01		FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						Service ATA:27
	MOS	12 (+1m)		07-Feb-24	07-Feb-25	07-Mar-25	307 d (+28)	05-Dec-2024
	HRS	400 (+40)		14354.4	14754.4	14794.4	400 (+40)	
	AFL			9502				
		REF: AMM 27-50-00-720-802						
29-12-05-710-801-02		OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (30GPC)						Service ATA:29
	MOS	12 (+1m)		30-Jan-24	30-Jan-25	28-Feb-25	299 d (+29)	05-Dec-2024
	HRS	400 (+40)		14354.4	14754.4	14794.4	400 (+40)	
	AFL			9502				
		REF: AMM 29-12-05-710-801						
24-32-09-610-801-04		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)						Service ATA:24
PN:135687	MOS	12 (+3%)		06-Dec-23	06-Dec-24	17-Dec-24	244 d (+11)	06-Dec-2024
SN:4212	HRS			14292.8				
	AFL			9471				
		REF: AMM 24-32-09-610-801						
25-20-00-220-801-04		INSPECTION / TEST OF THE WASTE CONTAINERS - INSPECTION / TEST OF WASTE CONTAINERS						Service ATA:25
	MOS			08-Sep-22				06-Dec-2024
	HRS	1000	Adj:-9.8	13765.9	14756.1		401.7	
	AFL			9108				
		REF: AMM 25-20-00-220-801, SMM 25-90-17						
27-15-05-350-801-01		RESTORATION OF THE ROLL MAIN AFU (FUNCTIONAL TEST / SERVICING) - ROLL MAIN AFU (65CR)						Service ATA:27
PN:105124	MOS	144 (+3%)		06-Dec-12	06-Dec-24	15-Apr-25	244 d (+130)	06-Dec-2024
SN:391	HRS							
	AFL							
		REF: AMM 27-15-05-350-801						





# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>FAA 1974-08-09 R03 LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION AD ATA:25</b>								
	MOS			08-Sep-22				12-Dec-2024
	HRS	1000		13765.9	14765.9		411.5	
	AFL			9108				
Disposition: MANDATORY			REF: AD					
<b>73-40-00-700-801-01A TEST OF THE AUTOMATIC POWER RESERVE (APR) INDICATION (MANDATORY 5-40) Service ATA:73</b>								
	MOS			15-Jan-24				18-Dec-2024
	HRS	450		14325.5	14775.5		421.1	
	AFL			9488				
Disposition: MANDATORY 5-40			REF: AMM 73-40-00-700-801					
<b>34-16-00-720-801-01 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L320FE) Service ATA:34</b>								
PN:PN-UNKNOWN	MOS	12 (+3%)		19-Dec-23	19-Dec-24	30-Dec-24	257 d (+11)	19-Dec-2024
SN:YX5G	HRS			14292.8				
	AFL			9471				
			REF: AMM 34-16-00-720-801					
<b>34-16-00-720-801-02 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R320FE) Service ATA:34</b>								
PN:822-0374-439	MOS	12 (+3%)		19-Dec-23	19-Dec-24	30-Dec-24	257 d (+11)	19-Dec-2024
SN:25UC	HRS			14292.8				
	AFL			9471				
			REF: AMM 34-16-00-720-801					
<b>725050 NO. 1 ENGINE - TURBINE ROTOR INTERSTAGE SEAL Component ATA:72</b>								
PN:4106T90P01	MOS			05-Nov-12				21-Dec-2024
SN:BIW01AE7	HRS		TSN:2257	8078				
	ENC	4600	TSN:1562	5537	(8575)9843		341	
Disposition: LIFE LIMIT			REF: GENERIC NO REF					
<b>05-08-00-200-800-05 12M/800FH INSPECTION Package ATA:05</b>								
	MOS	12 (+1m)		27-Dec-23	27-Dec-24	27-Jan-25	265 d (+31)	27-Dec-2024
	HRS	800 (+40)		14292.8	15092.8	15132.8	738.4 (+40)	
	AFL			9471				
			REF: MPD 05-10-00					
<b>32-44-00-250-801-02 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG INBOARD WHEEL (L220GC) Service ATA:32</b>								
PN:C20384200	MOS			29-Aug-23				27-Dec-2024
SN:00800	HRS			14127.2				
	AFL	400 (+3%)		9364	9764	9864	262 (+100)	
			REF: AMM 32-44-00-250-801					

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
53-10-00-200-808-01C		INSPECTION OF THE NLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		27-Dec-23	27-Dec-24	27-Jan-25	265 d (+31)	27-Dec-2024
	HRS			14292.8				
	AFL			9471				
Disposition: CPCP		REF: AMM 53-10-00-200-808						
53-40-00-200-804-01C		INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		27-Dec-23	27-Dec-24	27-Jan-25	265 d (+31)	27-Dec-2024
	HRS			14292.8				
	AFL			9471				
Disposition: CPCP		REF: AMM 53-40-00-200-804						
53-40-00-200-804-02C		INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		27-Dec-23	27-Dec-24	27-Jan-25	265 d (+31)	27-Dec-2024
	HRS			14292.8				
	AFL			9471				
Disposition: CPCP		REF: AMM 53-40-00-200-804						
53-50-00-210-804-01C		GENERAL VISUAL INSPECTION OF THE AFT SERVICING COMPARTMENT (CPCP)						Service ATA:53
	MOS	12 (+1m)		27-Dec-23	27-Dec-24	27-Jan-25	265 d (+31)	27-Dec-2024
	HRS			14292.8				
	AFL			9471				
Disposition: CPCP		REF: AMM 53-50-00-210-804						
27-50-00-720-802-01A		FUNCTIONAL TEST OF FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)						Service ATA:27
	MOS			07-Feb-24				04-Jan-2025
	HRS	450		14354.4	14804.4		450	
	AFL			9502				
Disposition: MANDATORY 5-40		REF: AMM 27-50-00-720-802						
29-12-05-710-801-01A		OPERATIONAL TEST OF THE NO.1 ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40)						Service ATA:29
	MOS			30-Jan-24				04-Jan-2025
	HRS	450		14354.4	14804.4		450	
	AFL			9502				
Disposition: MANDATORY 5-40		REF: AMM 29-12-05-710-801						
29-12-05-710-801-02A		OPERATIONAL TEST OF THE NO.2 ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40)						Service ATA:29
	MOS			30-Jan-24				04-Jan-2025
	HRS	450		14354.4	14804.4		450	
	AFL			9502				
Disposition: MANDATORY 5-40		REF: AMM 29-12-05-710-801						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
29-12-05-710-801-03A	OPERATIONAL TEST OF THE NO.2 ENGINE HYDRAULIC SYSTEM 2 SHUT-OFF VALVE (MANDATORY 5-40)							Service ATA:29
	MOS			30-Jan-24				04-Jan-2025
	HRS	450		14354.4	14804.4		450	
	AFL			9502				
Disposition: MANDATORY 5-40		REF: AMM 29-12-05-710-801						
27-53-01-350-801-01	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (40CF)							Service ATA:27
PN:1-5319-3	MOS			04-Apr-11				10-Jan-2025
SN:6028	HRS			7883.8				
	AFL	4500		5278	9778		276	
		REF: AMM 27-53-01-350-801						
27-53-01-350-801-01A	RESTORATION LH OUTBOARD FLAP SCREWJACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)							Service ATA:27
PN:1-5319-3	MOS			04-Apr-11				10-Jan-2025
SN:6028	HRS			7883.8				
	AFL	4500		5278	9778		276	
		REF: AMM 27-53-01-350-801						
30-11-09-720-801-02	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (40DL)							Service ATA:30
PN:5035-700	MOS			05-May-22				21-Jan-2025
SN:302	HRS	1240 (+3%)		13592.3	14832.3	14869.5	477.9 (+37.2)	
	AFL	1000 (+3%)		9008	10008	10038	506 (+30)	
		REF: AMM 30-11-09-720-801						
31-54-00-720-801-01	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: ALARM TEST							Service ATA:31
	MOS			21-Dec-23				21-Jan-2025
	HRS	700	Adj:-160.6	14292.8	14832.2		477.8	
	AFL			9471				
		REF: AMM 31-54-00-720-801						
334C51 <sup>U</sup>	CHECK STROBE LIGHT INTENSITY							Service ATA:33
	MOS	12		07-Feb-24	07-Feb-25		307 d	07-Feb-2025
	HRS			14354.4				
	AFL			9502				
		REF:						
05-60-00-200-801-07A	PERFORM BASIC INSPECTION - CABIN WARNING TEST (MANDATORY 5-40)							Service ATA:05
	MOS			24-Oct-23				13-Feb-2025
	HRS	650		14220.4	14870.4		516	
	AFL			9426				
Disposition: MANDATORY 5-40		REF: AMM 05-60-00-200-801						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
<b>32-44-00-250-801-04</b>								
SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R225GC)								
PN:C20384200MIC	MOS			10-Oct-23				Service ATA:32 13-Feb-2025
SN:01309	HRS			14192				
	AFL	400 (+3%)		9411	9811	9911	309 (+100)	
REF: AMM 32-44-00-250-801								
<b>05-08-00-200-800-15</b>								
12M INSPECTION								
	MOS	12 (+1m)		14-Feb-24	14-Feb-25	14-Mar-25	314 d (+28)	Package ATA:05 14-Feb-2025
	HRS			14354.4				
	AFL			9502				
REF: MPD 05-10-00								
<b>49-31-07-960-801-01</b>								
APU - REPLACEMENT OF THE APU FUEL FILTER								
	MOS			08-Sep-22				Service ATA:49 18-Feb-2025
	HRS	1000 (+3%)		11414	12414	12444	524 (+30)	
	APUS			13380				
REF: MM 49-30-52, AMM 49-31-07-960-801								
<b>25-62-01-720-801-01</b>								
FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1)								
PN:DK120	MOS	25 (+3%)		19-Jan-23	19-Feb-25	12-Mar-25	319 d (+21)	Service ATA:25 19-Feb-2025
SN:SC45445	HRS			13859.4				
	AFL			9175				
REF: AMM 25-62-01-720-801								
<b>25-62-01-720-801-02</b>								
FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1) OR (715FZ1)								
PN:DK120/90	MOS	25 (+3%)		19-Jan-23	19-Feb-25	12-Mar-25	319 d (+21)	Service ATA:25 19-Feb-2025
SN:AT49143	HRS			13859.4				
	AFL			9175				
REF: AMM 25-62-01-720-801								
<b>33-50-37-960-802-03</b>								
DISCARD OF THE EPS BATTERY PACKS - EPS 3 (15LE) BATTERY PACK								
PN:C734-01-030	MOS	25		19-Jan-23	19-Feb-25		319 d	Service ATA:33 19-Feb-2025
SN:295098	HRS			13859.4				
	AFL			9175				
Disposition: LIFE LIMIT REF: AMM 33-50-37-960-802								
<b>EASA 2018-0022</b>								
ICE AND RAIN PROTECTION - WING ANTI-ICE SYSTEM / ANTI-ICE PIPE - INSPECTION / REPLACEMENT								
	MOS	25		19-Jan-23	19-Feb-25		319 d	AD ATA:30 19-Feb-2025
	HRS			13859.4				
	AFL			9175				
Disposition: MANDATORY REF: AD								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16  
-Mar-2024 Operator: SHORT HILLS AVIATION SERVICES, INC.

Report Date: 06-Apr-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
FAA 2018-19-14		ICE AND RAIN PROTECTION - WING ANTI-ICE SYSTEM / ANTI-ICE PIPE - INSPECTION / REPLACEMENT						AD ATA:30
	MOS	25		19-Jan-23	19-Feb-25		319 d	19-Feb-2025
	HRS			13859.4				
	AFL			9175				
Disposition: MANDATORY		REF: AD						
057120		NO. 1 ENGINE - 600 HOUR MINOR INSPECTION						Package ATA:05
	MOS			28-Dec-23				27-Feb-2025
	HRS	600 (+50)		12270.6	(12870.6)14892.8	12920.6	538.4 (+50)	
	ENC			8203				
		REF: LMM 05-21-00						
057120		NO. 2 ENGINE - 600 HOUR MINOR INSPECTION						Package ATA:05
	MOS			28-Dec-23				27-Feb-2025
	HRS	600 (+50)		12429.6	(13029.6)14892.7	13079.6	538.3 (+50)	
	ENC			8337				
		REF: LMM 05-21-00						
32-44-00-250-801-05		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L300GC)						Service ATA:32
PN:C20383000MIC	MOS			21-Jul-23				28-Feb-2025
SN:00185	HRS			14071.9				
	AFL	500 (+3%)		9326	9826	9841	324 (+15)	
		REF: AMM 32-44-00-250-801						
32-44-00-250-801-06		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R300GC)						Service ATA:32
PN:C20383000	MOS			21-Jul-23				28-Feb-2025
SN:F133	HRS			14071.9				
	AFL	500 (+3%)		9326	9826	9841	324 (+15)	
		REF: AMM 32-44-00-250-801						
54-00-00-210-810-01C		GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (L5EZ) (CPCP)						Service ATA:54
	MOS	24 (+1m)		28-Feb-23	28-Feb-25	31-Mar-25	328 d (+31)	28-Feb-2025
	HRS			13865.3				
	AFL			9179				
Disposition: CPCP		REF: AMM 54-00-00-210-810						
54-00-00-210-810-02C		GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (R5EZ) (CPCP)						Service ATA:54
	MOS	24 (+1m)		28-Feb-23	28-Feb-25	31-Mar-25	328 d (+31)	28-Feb-2025
	HRS			13865.3				
	AFL			9179				
Disposition: CPCP		REF: AMM 54-00-00-210-810						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time