



Status Report

FALCON 2000

S/N 139 N26NJ

OWNER: SHORT HILLS AVIATION SERVICES, INC. ADDRESS: 18 AIRPORT ROAD MORRISTOWN NJ 07960 OFFICE: 973-292-3395 FAX:	OPERATOR: SHORT HILLS AVIATION SERVICES, INC. ADDRESS: 18 AIRPORT ROAD MORRISTOWN NJ 07960 OFFICE: 973-292-3395 FAX:	OPERATOR: GARDEN AIR LLC ADDRESS: C/O SIGNATURE FLIGHT SUPPORT MORRISTOWN NJ 07960 OFFICE: (973) 292-3395 FAX: (973) 292-3396	
ANALYST: JON KURMANCHIK EMAIL: JKURMANCHIK@CAMPSYSTEMS.COM	631-619-4563 (DIRECT) +1-631-588-3200 (MAIN) WWW.CAMPSYSTEMS.COM	800-787-9749 (EFAX-CARDS) 631-980-4222 (FAX)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 139/N26NJ	MODEL: FALCON 2000	MANUFACTURER: DASSAULT AVIATION S.A.
	CERTIFICATION DATE: 01-MAR-2000	LAST ACTUALS:	
		14354.4 A/C HRS	as of 16-MAR-2024
		9502 AFL	as of 16-MAR-2024
		11939 APH	as of 16-JAN-2024
		14114 APS	as of 16-JAN-2024
APU	SERIAL/PART: P-324/3800548-2	MODEL: GTCP36-150(F2M)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 15-JUN-2022	LAST ACTUALS:	
	0 APU HRS 13630.3 A/C HRS	11890 APU HRS	as of 30-JAN-2024
	APUS	14130 APUS	as of 30-JAN-2024
ENGINE NO. 1	SERIAL/PART: P105362/3050000-5	MODEL: CFE738-1-1B	MANUFACTURER: CFE
	INSTALLED ON: 28-FEB-2023	LAST ACTUALS:	
	11842.8 ENG. HRS 13865.3 A/C HRS	12332.2 ENG. HRS	as of 30-JAN-2024
	7911 ENC	8234 ENC	as of 30-JAN-2024
ENGINE NO. 2	SERIAL/PART: P105414/3050000-5	MODEL: CFE738-1-1B	MANUFACTURER: CFE
	INSTALLED ON: 28-FEB-2023	LAST ACTUALS:	
	12003.3 ENG. HRS 13865.3 A/C HRS	12491.3 ENG. HRS	as of 30-JAN-2024
	8045 ENC	8368 ENC	as of 30-JAN-2024



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 00 - INFORMATION									
00-00-00-910-903-01 ^U	PERFORM FLAG FAULT MESSAGES CANCELLING							Service	ATA:00
	MOS/MSC		A/R						
	HRS								
WC#: 45.010	AFL								
PROC. REF: GENERIC NO REF									
A008-150717	APU - REVIEW CAMP CHANGE FORM - HONEYWELL, GTCP36-150[F2M] MAINTENANCE MANUAL REVISION 7 DATED JULY 17, 2015							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A008									
A008-161102	APU - REVIEW SIL APU-56 REV 2							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A008									
A008-161215	APU - REVIEW GTCP36-150(F2M) MM REV 7 TR 49-27							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A008									
A008-170109	APU - REVIEW GTCP36-150(F2M) MM REV 7 TR 49-28							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A008									
A008-170120	APU - REVIEW GTCP36-150(F2M) MM REV 7 TR 49-26							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A008									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
A008-170124	APU - REVIEW GTCP36-150(F2M) MM TR 49-29							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF A008			
A008-170203	APU - REVIEW REVIEW GTCP36-150(F2M) MM TR 49-30							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF A008			
A008-171115	APU - REVIEW GTCP36-150(F2M) MM REV 08							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF A008			
A008-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF APU-SIL-49			
A008-180730	APU - REVIEW HONEYWELL GTCP36-150(F2M) MM TR 49-32							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF A008			
A008-200319	APU - REVIEW GTCP36-150(F2M) MM REV 09							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
					PROC. REF: RCF A008			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 00 - INFORMATION									
FA2M-141217	REVIEW FALCON 2000 MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 5 - OCTOBER 2014 - REVISION SUMMARY CHANGE FORM							Service	ATA:00
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
	PROC. REF: RCF FA2M								
FA2M-141217C	REVIEW FALCON 2000 - MAINTENANCE MANUAL DOCUMENTATION DISCREPANCIES 1-238850492 AND 1-239637769 - REVISION SUMMARY CHANGE FORM							Service	ATA:00
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
	PROC. REF: RCF FA2M								
FA2M-150708	REVIEW DASSAULT AVIATION FALCON 2000 SMM REVISION G & H, DATED MAR-15-2015							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF FA2M								
FA2M-151021	REVIEW FALCON 2000 MPD REVISION DATED 21 OCT 2015							Service	ATA:00
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
FA2M-151203	REVIEW SUPPLEMENTAL MAINTENANCE MANUAL CHAPTER 05 FOR FALCON 2000 REVISION NO. I, DATED AUGUST 27/2015-CAMP CHANGE FORM							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF FA2M								
FA2M-160427	REVIEW FA2M MPD REV 6 - SUMMARY CHANGE FORM							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF FA2M								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 00 - INFORMATION									
FA2M-160627	REVIEW AMM REVISION 36 DATED APR 20/2016							Service ATA:00	
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
FA2M-161021	REVIEW MPD REVISION 7 DATED SEPTEMBER 2016							Service ATA:00	
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
FA2M-170222A	REVIEW MPD REVISION 8 DATED DECEMBER 2016							Service ATA:00	
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
FA2M-170222B	REVIEW CHANGES TO 5-40 FROM MPD REVISION 8 DATED DECEMBER 2016							Service ATA:00	
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
FA2M-171101	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 9 DATED NOVEMBER 2017							Service ATA:00	
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF FA2M									
FA2M-171101A	REVIEW MAINTENANCE MANUAL CHAPTER 5-40 AIRWORTHINESS LIMITATIONS - REVISION 19 - NOVEMBER 2017							Service ATA:00	
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
FA2M-171101L	REVIEW DASSAULT FALCON 2000 MPD REVISION 9 + ALD 05-40 REV 19 DATED NOV, 2017 (LIGHT RSCF FOR TRANSITION)							Service ATA:00	
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
FA2M-180205	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCY (DD) 1-309445121							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-180322	REVIEW DOCUMENT DISCREPANCIES DD 1-305056891, 1-309702391, 1-310213413, 1-306775364, AND 1-307191003							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: MPD FA2M			
FA2M-180409	REVIEW FALCON 2000 DOCUMENT DISCREPANCY 1-311025631							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-180612	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCIES (DD) RESPONSE DATE 12-JUN-2018							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: RCF FA2M, RCF FA2M			
FA2M-181101	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 10 - NOVEMBER 2018							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-181101A	REVIEW MAINTENANCE MANUAL CHAPTER 5-40-00 REVISION 20 - NOVEMBER 2018							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
					PROC. REF: RCF FA2M			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
FA2M-190412								Service ATA:00
	MOS/MSC	01-Mar-00	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
					PROC. REF: RCF FA2M			
FA2M-190808								Service ATA:00
	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCY (DD) 1-345369346							REQUIREMENT CHANGE FORMS
	MOS/MSC		-					
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-191201								Service ATA:00
	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 11 - DECEMBER 2019							REQUIREMENT CHANGE FORMS
	MOS/MSC		-					
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-191201A								Service ATA:00
	REVIEW MAINTENANCE MANUAL CHAPTER 5-40 REVISION 21 - DECEMBER 2019							REQUIREMENT CHANGE FORMS
	MOS/MSC		-					
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-200401								Service ATA:00
	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 11-01 - APRIL 2020							REQUIREMENT CHANGE FORMS
	MOS/MSC		-					
	HRS							
	AFL							
					PROC. REF: RCF FA2M			
FA2M-200610								Service ATA:00
	REVIEW TASK 71-20-02-250-801 TOLERANCE CORRECTION							REQUIREMENT CHANGE FORMS
	MOS/MSC		-					
	HRS							
	AFL							
					PROC. REF: RCF FA2M			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
FA2M-200612	REVIEW TASK 28-00-00-290-801-02 TOLERANCE CORRECTION							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
				PROC. REF: RCF FA2M				
FA2M-201101	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 12 - NOVEMBER 2020							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
				PROC. REF: RCF FA2M				
FA2M-STORAGE	REVIEW STORAGE / RETURN TO SERVICE OF AIRCRAFT REQUIREMENTS							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
				PROC. REF: RCF FA2M				
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-05	12M/800FH INSPECTION							Package ATA:05
	MOS	27-Dec-23	12 (+1m)		27-Dec-24	27-Jan-25	265 d (+31)	
	HRS	14292.8	800 (+40)		15092.8	15132.8	738.4 (+40)	
	AFL	9471						
				PROC. REF: MPD 05-10-00				PKG:5
05-08-00-200-800-06	24M/1600FH INSPECTION							Package ATA:05
	MOS	27-Dec-23	24 (+1m)	Adj -164d	16-Jul-25	16-Aug-25	466 d (+31)	
	HRS	14292.8	1600 (+40)		15892.8	15932.8	1538.4 (+40)	
	AFL	9471						
				PROC. REF: MPD 05-10-00				PKG:6
05-08-00-200-800-07	36M/2400FH INSPECTION							Package ATA:05
	MOS	05-May-22	36 (+1m)	Adj -271d	07-Aug-24	07-Sep-24	123 d (+31)	
	HRS	13592.3	2400 (+40)		15992.3	16032.3	1637.9 (+40)	
	AFL	9008						
				PROC. REF: MPD 05-10-00				PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-15	12M INSPECTION							Package ATA:05
	MOS	14-Feb-24	12 (+1m)		14-Feb-25	14-Mar-25	314 d (+28)	
	HRS	14354.4						
	AFL	9502						
				PROC. REF: MPD 05-10-00				PKG:15
05-08-00-200-800-16	24M INSPECTION							Package ATA:05
	MOS	27-Dec-23	24 (+1m)	Adj -164d	16-Jul-25	16-Aug-25	466 d (+31)	
	HRS	14292.8						
	AFL	9471						
				PROC. REF: MPD 05-10-00				PKG:16
05-08-00-200-800-17	36M INSPECTION							Package ATA:05
	MOS	05-May-22	36 (+1m)		05-May-25	05-Jun-25	394 d (+31)	
	HRS	11761.3						
	AFL	7947						
				PROC. REF: MPD 05-10-00				PKG:17
05-08-00-200-800-21	1B INSPECTION							Package ATA:05
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)	Adj -231	14961.3	15001.3	606.9 (+40)	
	AFL	9008						
				PROC. REF: MPD 05-10-00				PKG:21
05-08-00-200-800-22	2B INSPECTION							Package ATA:05
	MOS	05-May-22						
	HRS	13592.3	3200 (+40)	Adj -231	16561.3	16601.3	2206.9 (+40)	
	AFL	9008						
				PROC. REF: MPD 05-10-00				PKG:22
05-08-00-200-800-23	3B INSPECTION							Package ATA:05
	MOS	05-May-22						
	HRS	13592.3	4800 (+40)	Adj -231	18161.3	18201.3	3806.9 (+40)	
	AFL	9008						
				PROC. REF: MPD 05-10-00				PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-31	1C INSPECTION							Package ATA:05
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	
	HRS	11761.3						
	AFL	7947	3750		11697		2195	
				PROC. REF: MPD 05-10-00				PKG:31
05-08-00-200-800-32	2C INSPECTION							Package ATA:05
	MOS	16-Apr-13	144 (+2m)		16-Apr-25	16-Jun-25	375 d (+61)	
	HRS	9087.6						
	AFL	6131	7500		13631		4129	
				PROC. REF: MPD 05-10-00				PKG:32
05-08-00-200-800-33	3C INSPECTION							Package ATA:05
	MOS	16-Jul-19	216 (+2m)		16-Jul-37	16-Sep-37	4849 d (+62)	
	HRS	11761.3						
	AFL	7947	11250		19197		9695	
				PROC. REF: MPD 05-10-00				PKG:33
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 24.160	AFL							
				PROC. REF: AMM 05-50-00-100-801				
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 09.010	AFL							
				PROC. REF: AMM 05-50-00-200-801				
05-50-00-200-802-01	CHECK AFTER HAILSTORM							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 51.050	AFL							
				PROC. REF: AMM 05-50-00-200-802				
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 51.040	AFL							
				PROC. REF: AMM 05-50-00-200-803				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 32.840	AFL								
PROC. REF: AMM 05-50-00-200-804									
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 51.030	AFL								
PROC. REF: AMM 05-50-00-200-805									
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00-200-806									
05-50-00-200-809-01	INSPECTION AFTER SLAT OPERATION IN OVERSPEED CONDITION							Service	ATA:05
	MOS/MSC	28-Jul-10	A/R						
	HRS	7497.6							
WC#: 57.200	AFL	5028							
PROC. REF: AMM 05-50-00-200-809									
05-50-00-200-810-01	INSPECTION AFTER FLAP OPERATION IN OVERSPEED CONDITION							Service	ATA:05
	MOS/MSC	28-Jul-10	A/R						
	HRS	7497.6							
WC#: 57.210	AFL	5028							
PROC. REF: AMM 05-50-00-200-810									
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 53.420	AFL								
PROC. REF: AMM 05-50-00-200-812									
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING - CHECK AFTER WHEEL SHOCK AT TAKE-OFF OR LANDING							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00-200-813									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-200-817-01	CHECK AFTER COLLISION WITH FOREIGN OBJECT							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-50-00-200-817								
05-50-00-200-822-01	OPERATION TO BE PERFORMED AFTER VMO/MMO EXCEEDANCE							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-50-00-200-822								
05-50-00-200-823-01	CHECK OF THE SLATS AFTER OVERHEATING - LH WING							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-50-00-200-823								
05-50-00-200-823-02	CHECK OF THE SLATS AFTER OVERHEATING - RH WING							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-50-00-200-823								
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-50-00-620-801								
05-50-00-620-801-02 ^U	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTIONS AND ANTI-CORROSION TREATMENTS AT MEDIUM TIME INTERVALS							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 05.030	AFL								
	PROC. REF: AMM 05-50-00-620-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 51.070	AFL								
PROC. REF: AMM 05-50-00-620-804									
05-50-00-620-805-01	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION - CRITERIA TO DEFINE A/C AT RISK OF FUEL CONTAMINATION							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-620-805									
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-620-805									
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION							Service	ATA:05
	MOS/MSC	20-Aug-13	A/R						
	HRS	9263.5							
WC#: 21.410	AFL	6253							
PROC. REF: AMM 05-50-00-700-801									
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 20.010	AFL								
PROC. REF: SL 20-350, AMM 05-50-00-700-803									
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 32.830	AFL								
PROC. REF: AMM 05-50-00-700-806									
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 32.810	AFL								
PROC. REF: AMM 05-50-00-700-807									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 32.800	AFL								
PROC. REF: AMM 05-50-00-700-808									
05-50-00-700-810-01	CHECK AFTER SAND CONDITION - CHECKS AFTER EACH FLIGHT THROUGH SAND							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-810									
05-50-00-700-810-02	CHECK AFTER SAND CONDITION - FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLIGHT THROUGH SAND							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-810									
05-50-00-700-810-03	CHECK AFTER SAND CONDITION - PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-810									
05-50-00-700-810-04	CHECK AFTER SAND CONDITION - INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-810									
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-818									
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-822									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-700-822-02	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-822									
05-50-00-700-822-03	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-822									
05-50-00-700-822-04	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-822									
05-50-00-700-822-05	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA							Service	ATA:05
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00-700-822									
05-50-00-730-801-01	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - FILTER CLOGGING							Service	ATA:05
	MOS/MSC	06-Jan-17	A/R						
	HRS	10786							
WC#: 29.260	AFL	7286							
PROC. REF: AMM 05-50-00-730-801									
05-50-00-730-801-02	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - PUMP FAILURE							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
WC#: 29.270	AFL								
PROC. REF: AMM 05-50-00-730-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00-730-802									
05-50-00-910-801-01 ^S	AIRCRAFT CHECK FLIGHT							Service	ATA:05
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 05.020	AFL	7947	3750						
PROC. REF: AMM 05-50-00-910-801									
PKG:31									
05-60-00-200-801-01	BASIC INSPECTION							Service	ATA:05
	MOS	24-Oct-23	12 (+1m)		24-Oct-24	24-Nov-24	201 d (+31)		
	HRS	14220.4	400 (+40)	Adj -59.1	14561.3	14601.3	206.9 (+40)		
WC#: 05.010	AFL	9426							
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801									
05-60-00-200-801-03	BASIC INSPECTION - GROUND SERVICING CHECKS							Service	ATA:05
	MOS	24-Oct-23	12 (+1m)		24-Oct-24	24-Nov-24	201 d (+31)		
	HRS	14220.4	400 (+40)		14620.4	14660.4	266 (+40)		
WC#: 05.010	AFL	9426							
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801									
05-60-00-200-801-04	BASIC INSPECTION - CHECK OF MAGNETIC INDICATORS							Service	ATA:05
	DAYS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
WC#: 05.010	AFL	7323							
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801									
05-60-00-200-801-07	BASIC INSPECTION - CABIN WARNING TEST							Service	ATA:05
	MOS	24-Oct-23	12 (+1m)		24-Oct-24	24-Nov-24	201 d (+31)		
	HRS	14220.4	400 (+40)		14620.4	14660.4	266 (+40)		
WC#: 05.010	AFL	9426							
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801									
05-60-00-200-801-07A	PERFORM BASIC INSPECTION - CABIN WARNING TEST (MANDATORY 5-40)							Service	ATA:05
	MOS	24-Oct-23						MANDATORY 5-40	
	HRS	14220.4	650		14870.4		516		
WC#: 05.010	AFL	9426							
PROC. REF: AMM 05-60-00-200-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050A20 ^U	PERFORM POST FLIGHT INSPECTION							Service	ATA:05
	MOS/MSC	30-Jan-24	A/R						
	HRS	14354.4							
	AFL	9502							
057110	NO. 1 ENGINE - 200 HOUR ROUTINE INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12270.6	200 (+10%)		(12470.6) 14492.8	12490.6	138.4 (+20)		
	ENC	8203							
				PROC. REF: LMM 05-21-00				PKG:1	
057110	NO. 2 ENGINE - 200 HOUR ROUTINE INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12429.6	200 (+10%)		(12629.6) 14492.7	12649.6	138.3 (+20)		
	ENC	8337							
				PROC. REF: LMM 05-21-00				PKG:1	
057115	NO. 1 ENGINE - 400 HOUR ROUTINE INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)		(12670.6) 14692.8	12710.6	338.4 (+40)		
	ENC	8203							
								PKG:3	
057115	NO. 2 ENGINE - 400 HOUR ROUTINE INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)		(12829.6) 14692.7	12869.6	338.3 (+40)		
	ENC	8337							
								PKG:3	
057120	NO. 1 ENGINE - 600 HOUR MINOR INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12270.6	600 (+50)		(12870.6) 14892.8	12920.6	538.4 (+50)		
	ENC	8203							
				PROC. REF: LMM 05-21-00				PKG:2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057120	NO. 2 ENGINE - 600 HOUR MINOR INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12429.6	600 (+50)		(13029.6) 14892.7	13079.6	538.3 (+50)		
	ENC	8337							
				PROC. REF: LMM 05-21-00				PKG:2	
057125	NO. 1 ENGINE - 800 HOUR MINOR INSPECTION							Package	ATA:05
	MOS	28-Sep-22							
	HRS	11745.4	800 (+50)		(12545.4) 14567.6	12595.4	213.2 (+50)		
	ENC	7866							
								PKG:4	
057125	NO. 2 ENGINE - 800 HOUR MINOR INSPECTION							Package	ATA:05
	MOS	28-Dec-23							
	HRS	12429.6	800 (+50)		(13229.6) 15092.7	13279.6	738.3 (+50)		
	ENC	8337							
								PKG:4	
057130	NO. 1 ENGINE - 1200 HOUR UNDER COWL INSPECTION							Package	ATA:05
	MOS	19-Dec-23							
	HRS	12270.6	1200 (+50)		(13470.6) 15492.8	13520.6	1138.4 (+50)		
	ENC	8203							
								PKG:5	
057130	NO. 2 ENGINE - 1200 HOUR UNDER COWL INSPECTION							Package	ATA:05
	MOS	19-Dec-23							
	HRS	12429.6	1200 (+50)		(13629.6) 15492.7	13679.6	1138.3 (+50)		
	ENC	8337							
								PKG:5	
057135	NO. 1 ENGINE - 1600 HR BOROSCOPE INSPECTION							Package	ATA:05
	MOS	20-Aug-19							
	HRS	10645.5	1600 (+50)		(12245.5) 14267.7	12295.5	OVD		
	ENC	7219							
								PKG:6	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057135	NO. 2 ENGINE - 1600 HR BOROSCOPE INSPECTION							Package ATA:05
	MOS	19-Dec-23						
	HRS	12429.6	1600 (+50)		(14029.6) 15892.7	14079.6	1538.3 (+50)	
	ENC	8337						
								PKG:6
057140	NO. 1 ENGINE - 1600 HOUR UNDER COWL INSPECTION							Package ATA:05
	MOS/MSC	01-Aug-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: LMM 05-21-00								PKG:7
057140	NO. 2 ENGINE - 1600 HOUR UNDER COWL INSPECTION							Package ATA:05
	MOS/MSC	01-Jul-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: LMM 05-21-00								PKG:7
20-31-00-910-801-02	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - ANTI-ICING TREATMENT							Service ATA:05
	MOS/MSC	01-Mar-00	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-31-00-910-801								
32-42-05-780-801-02 ^S	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (110GC)							Service ATA:05
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8	1600 (+40)					
WC#: 05.010	AFL	9471						
PROC. REF: MPD 05-10-00, AMM 32-42-05-780-801								PKG:6
ATA 08 - LEVELING AND WEIGHING								
08-10-00-910-801-01	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON WHEELS							Service ATA:08
	MOS	10-Jan-23	36		10-Jan-26		644 d	
	HRS	13859.4						
	AFL	9175						
PROC. REF: AMM 08-10-00-910-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 09 - TOWING AND TAXING									
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT							Service	ATA:09
	MOS/MSC	28-Nov-14	A/R						
	HRS	10116.4							
WC#: 09.020	AFL	6829							
PROC. REF: AMM 09-10-00-910-810									
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV									
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS							Service	ATA:10
	MOS/MSC		A/R						
	HRS								
WC#: 10.020	AFL								
PROC. REF: AMM 10-10-00-200-801									
10-10-00-550-801-09 ^U	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PRE-STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 8 WEEKS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
10-10-00-550-801-11	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-12	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - ADDITIONAL OPERATIONS FOR STORAGE FROM 2 TO 12 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-13	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A PERIOD OF 12 TO 18 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-14	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY MONTH							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV									
10-10-00-550-801-15	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 2 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-16	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 6 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-17	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AT THE END OF THE 2 MONTHS OR LESS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-10-00-550-801-18	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS							Service	ATA:10
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 20.050	AFL	0							
PROC. REF: AMM 10-10-00-550-801									
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL							Service	ATA:10
	MOS/MSC		A/R						
	HRS								
WC#: 10.010	AFL								
PROC. REF: AMM 10-20-00-910-802									
ATA 11 - PLACARDS AND MARKINGS									
11-00-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE INTERNAL AND EXTERNAL MARKINGS AND PLACARDS							Service	ATA:11
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 11-00-00-210-801, SMM 11-90-01									
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT							Service	ATA:20
	MOS/MSC		A/R						
	HRS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
WC#: 51.060		AFL		PROC. REF: AMM 20-30-00-330-801				
20-31-00-100-801-01 ^U	CLEANING OF THE AIRCRAFT EXTERIOR							Service ATA:20
	MOS/MSC	08-Oct-14	A/R					
	HRS	10013.7						
	AFL	6764						
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR							Service ATA:20
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
WC#: 20.040		AFL		PROC. REF: SL 20-318, AMM 20-31-00-140-801				
20-31-00-910-801-01	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - DE-ICING TREATMENT							Service ATA:20
	MOS/MSC	A/R						
	HRS							
WC#: 20.030		AFL		PROC. REF: SL 20-625, AMM 20-31-00-910-801				
20-32-00-360-803-01	PROVISIONAL REPAIR OF LEAKY SCREWS OR RIVETS ON FUEL TANKS							Service ATA:20
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-32-00-360-803								
20-32-00-910-802-01	ACCEPTANCE CRITERIA FOR HYDRAULIC LEAKS							Service ATA:20
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-32-00-910-802								
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS							Service ATA:20
	MOS/MSC	01-Mar-00	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-33-00-300-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-41-00-910-801								
20-60-00-370-813-01	APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS							Service	ATA:20
	MOS/MSC		A/R						
	HRS								
WC#: 20.020	AFL								
	PROC. REF: SL 20-615, AMM 20-60-00-370-813								
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (5GA)							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (10GA)							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (5GA3)							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (10GA3)							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (5GB)							Service	ATA:20
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 20-60-00-370-816								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-20-01-350-801-01		RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L110HD)						Service	ATA:21
PN:2744A010100	MOS	16-Jul-19					OVERHAUL		
SN:00425	HRS	11761.3	4500 (+3%)		16261.3	16396.3	1906.9 (+135)		
WC#: 21.030	AFL	7947							
PROC. REF: AMM 21-20-01-350-801									
21-20-01-350-801-02		RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R110HD)						Service	ATA:21
PN:2744A010100	MOS	16-Jul-19					OVERHAUL		
SN:00427	HRS	11761.3	4500 (+3%)		16261.3	16396.3	1906.9 (+135)		
WC#: 21.030	AFL	7947							
PROC. REF: AMM 21-20-01-350-801									
21-20-01-350-802-01		RESTORATION OF THE FLOW LIMITERS (FUNCTIONAL TEST / SERVICING) - LH FLOW LIMITER (L110HD)						Service	ATA:21
PN:2744A010100	MOS/MSC	20-Apr-10	O/C						
SN:00425	HRS	7299.5							
WC#: 21.030	AFL	4889							
PROC. REF: AMM 21-20-01-350-802									
21-20-01-350-802-02		RESTORATION OF THE FLOW LIMITERS (FUNCTIONAL TEST / SERVICING) - RH FLOW LIMITER (R110HD)						Service	ATA:21
PN:2744A010100	MOS/MSC	20-Apr-10	O/C						
SN:00427	HRS	7299.5							
WC#: 21.030	AFL	4889							
PROC. REF: AMM 21-20-01-350-802									
21-20-01-900-801-01		REMOVAL / INSTALLATION OF THE FLOW LIMITERS - LH FLOW LIMITER (L110HD)						Component	ATA:21
PN:2744A010100	MOS/MSC	20-Apr-10	O/C	TSN 0					
SN:00425	HRS	7299.5		TSN 0					
WC#: 21.030	AFL	4889		TSN 0					
PROC. REF: AMM 21-20-01-900-801									
21-20-01-900-801-02		REMOVAL / INSTALLATION OF THE FLOW LIMITERS - RH FLOW LIMITER (R110HD)						Component	ATA:21
PN:2744A010100	MOS/MSC	20-Apr-10	O/C	TSN 0					
SN:00427	HRS	7299.5		TSN 0					
WC#: 21.030	AFL	4889		TSN 0					
PROC. REF: AMM 21-20-01-900-801									
21-22-19-900-801-01		REMOVAL / INSTALLATION OF THE GASPER PRESSURE CONTROL VALVE - GASPER PRESSURE CONTROL VALVE (130HD)						Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.270	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-28-00-710-801-01 ^S		OPERATIONAL TEST OF THE EFIS VENTILATION SYSTEM						Service	ATA:21
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 21.010	AFL	9008							
PROC. REF: AMM 21-28-00-710-801								PKG:21	
21-30-00-790-801-01		GROUND CHECK OF CABIN SEALING						Service	ATA:21
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 21-30-00-790-801									
21-30-00-790-802-01 ^S		IN-FLIGHT CHECK OF CABIN SEALING						Service	ATA:21
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 21.120	AFL	9008							
PROC. REF: AMM 21-30-00-790-802								PKG:21	
21-30-00-790-803-01		PRESSURIZATION LEAK TEST WITH EXTERNAL SOURCE OF AIR						Service	ATA:21
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 21-30-00-790-803									
21-30-01-900-801-01		REMOVAL / INSTALLATION OF THE AUTOMATIC PRESSURIZATION CONTROLLER - CPC (50HP)						Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.210	AFL	0		TSN 0					
PROC. REF: AMM 21-30-01-900-801									
21-30-09-720-801-01		FUNCTIONAL TEST OF THE ALTITUDE ALERT OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (150HP)						Service	ATA:21
PN:3311AJ61	MOS	21-Dec-23							
SN:762	HRS	14292.8	4000 (+3%)		18292.8	18412.8	3938.4 (+120)		
WC#: 21.190	AFL	9471							
PROC. REF: AMM 21-30-09-720-801									
21-30-09-900-801-01		REMOVAL / INSTALLATION OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (150HP)						Component	ATA:21
PN:3311AJ61	MOS/MSC	21-Dec-23	O/C						
SN:762	HRS	14292.8							
WC#: 21.190	AFL	9471							
PROC. REF: AMM 21-30-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-00-720-801-01^S FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PNEUMATIC ACTUATOR (230HD) Service ATA:21								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 21.150	AFL	9008						
PROC. REF: AMM 21-31-00-720-801								PKG:21
21-31-00-720-801-02^S FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - OVERPRESSURE CHECK VALVE (240HD) Service ATA:21								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 21.150	AFL	9008						
PROC. REF: AMM 21-31-00-720-801								PKG:21
21-31-01-720-801-01^S FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM Service ATA:21								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 21.020	AFL	9008						
PROC. REF: AMM 21-31-01-720-801								PKG:21
21-31-09-350-801-01 RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (250HD) Service ATA:21								
PN:AE1103A01	MOS/MSC	20-May-10	N/A					
SN:00817	HRS	7358.1						
WC#: 21.040	AFL	4931						
PROC. REF: AMM 21-31-09-350-801								
21-31-09-900-801-01 REMOVAL / INSTALLATION OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (250HD) Component ATA:21								
PN:AE1103A01	MOS/MSC	20-May-10	O/C	TSN 0				
SN:00817	HRS	7358.1		TSN 0				
WC#: 21.040	AFL	4931		TSN 0				
PROC. REF: AMM 21-31-09-900-801								
21-32-00-710-801-01^S OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM Service ATA:21								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 21.130	AFL	9008						
PROC. REF: AMM 21-32-00-710-801								PKG:21
21-32-00-710-802-01^S OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY Service ATA:21								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 21.140	AFL	9008						
PROC. REF: AMM 21-32-00-710-802								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-00-790-801-01^S LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L110FE) Service ATA:21								
	MOS	27-Dec-23	24 (+1m)					RVSM
	HRS	14292.8						
WC#: 21.405	AFL	9471						
PROC. REF: AMM 21-32-00-790-801						PKG:16		
21-32-00-790-801-02^S LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R110FE) Service ATA:21								
	MOS	27-Dec-23	24 (+1m)					RVSM
	HRS	14292.8						
	AFL	9471						
PROC. REF: AMM 21-32-00-790-801						PKG:16		
21-32-00-790-801-03^S LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STAND-BY STATIC PRESSURE PROBE (L900FE) Service ATA:21								
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
	AFL	9471						
PROC. REF: AMM 21-32-00-790-801						PKG:16		
21-32-00-790-801-04^S LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STAND-BY STATIC PRESSURE PROBE (R900FE) Service ATA:21								
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
	AFL	9471						
PROC. REF: AMM 21-32-00-790-801						PKG:16		
21-32-06-200-801-01 INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF ELECTROPNEUMATIC VALVE (70HP) Service ATA:21								
PN:2097M041301	MOS	19-Jan-23						
SN:02609	HRS	13859.4	1640 (+3%)		15499.4	15548.6	1145 (+49.2)	
WC#: 21.160	AFL	9175						
PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-02 INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF PNEUMATIC VALVE (80HP) Service ATA:21								
PN:2099N041301	MOS	19-Jan-23						
SN:125	HRS	13859.4	1640 (+3%)		15499.4	15548.6	1145 (+49.2)	
WC#: 21.170	AFL	9175						
PROC. REF: AMM 21-32-06-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-32-06-200-801-03	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF ELECTROPNEUMATIC VALVE (70HP)							Service	ATA:21
PN:2097M041301	MOS	19-Jan-23							
SN:02609	HRS	13859.4	1640		15499.4		1145		
WC#: 21.160	AFL	9175							
PROC. REF: AMM 21-32-06-200-801									
21-32-06-200-801-03A	INSPECTION/CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)							Service	ATA:21
PN:2097M041301	MOS	19-Jan-23						MANDATORY 5-40	
SN:02609	HRS	13859.4	1640		15499.4		1145		
WC#: 21.160	AFL	9175							
PROC. REF: AMM 21-32-06-200-801									
21-32-06-200-801-04	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF PNEUMATIC VALVE (80HP)							Service	ATA:21
PN:2099N041301	MOS	19-Jan-23							
SN:125	HRS	13859.4	1640		15499.4		1145		
WC#: 21.170	AFL	9175							
PROC. REF: AMM 21-32-06-200-801									
21-32-06-200-801-04A	INSPECTION/CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)							Service	ATA:21
PN:2099N041301	MOS	19-Jan-23						MANDATORY 5-40	
SN:125	HRS	13859.4	1640		15499.4		1145		
WC#: 21.170	AFL	9175							
PROC. REF: AMM 21-32-06-200-801									
21-32-06-200-801-05	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (975HP) AND (976HP)							Service	ATA:21
	MOS	19-Jan-23							
	HRS	13859.4	1640 (+40)		15499.4	15539.4	1145 (+40)		
WC#: 21.160	AFL	9175							
PROC. REF: AMM 21-32-06-200-801									
21-32-06-200-801-05A	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINE (MANDATORY 5-40)							Service	ATA:21
	MOS	26-Sep-16						MANDATORY 5-40	
	HRS	10749.4	7500		18249.4		3895		
WC#: 21.160	AFL	7265							
PROC. REF: AMM 21-32-06-200-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-32-06-720-801-01		FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - ELECTROPNEUMATIC VALVE (70HP)						Service	ATA:21
PN:2097M041301	MOS	19-Jan-23							
SN:02609	HRS	13859.4	4840 (+3%)		18699.4	18844.6	4345 (+145.2)		
WC#: 21.160	AFL	9175							
PROC. REF: AMM 21-32-06-720-801									
21-32-06-720-801-01A		FUNCTIONAL TEST ELECTROPNEUMATIC VALVE (MANDATORY 5-40)						Service	ATA:21
PN:2097M041301	MOS	10-Sep-15						MANDATORY 5-40	
SN:02609	HRS	10489.8	7500		17989.8		3635.4		
WC#: 21.160	AFL	7089							
PROC. REF: AMM 21-32-06-720-801									
21-32-06-720-801-02		FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - PNEUMATIC VALVE (80HP)						Service	ATA:21
PN:2099N041301	MOS	19-Jan-23							
SN:125	HRS	13859.4	4840 (+3%)		18699.4	18844.6	4345 (+145.2)		
WC#: 21.170	AFL	9175							
PROC. REF: AMM 21-32-06-720-801									
21-32-06-720-801-02A		FUNCTIONAL TEST PNEUMATIC VALVE (MANDATORY 5-40)						Service	ATA:21
PN:2099N041301	MOS	10-Sep-15						MANDATORY 5-40	
SN:125	HRS	10489.8	7500		17989.8		3635.4		
WC#: 21.170	AFL	7089							
PROC. REF: AMM 21-32-06-720-801									
21-32-06-720-802-01 ^S		FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - ELECTROPNEUMATIC VALVE (70HP)						Service	ATA:21
	MOS	01-Mar-00	72 (+2m)						
	HRS	0							
	AFL	0	3750						
PROC. REF: AMM 21-32-06-720-802									
PKG:31									
21-32-06-720-802-02 ^S		FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - PNEUMATIC VALVE (80HP)						Service	ATA:21
	MOS	01-Mar-00	72 (+2m)						
	HRS	0							
	AFL	0	3750						
PROC. REF: AMM 21-32-06-720-802									
PKG:31									
21-32-06-900-801-01		REMOVAL / INSTALLATION OF THE ELECTROPNEUMATIC VALVE - ELECTROPNEUMATIC VALVE (70HP)						Component	ATA:21
PN:2097M041301	MOS/MSC	19-Jan-23	O/C	TSN 180					
SN:02609	HRS	13859.4		TSN 3228					
WC#: 21.160	AFL	9175		TSN 2361					
PROC. REF: AMM 21-32-06-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-32-06-900-802-01		REMOVAL / INSTALLATION OF THE PNEUMATIC VALVE - PNEUMATIC VALVE (80HP)					Component	ATA:21	
PN:2099N041301	MOS/MSC	19-Jan-23	O/C	TSR 1					
SN:125	HRS	13859.4		TSO 1558, TSR 0					
WC#: 21.170	AFL	9175		TSO 849, TSR 0					
PROC. REF: AMM 21-32-06-900-802									
21-32-41-200-801-01 ^S		INSPECTION OF THE NICOTINE FILTER CARTRIDGE - CABIN AIR FILTER (90HP)					Service	ATA:21	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 21.180	AFL	7947	3750						
PROC. REF: AMM 21-32-41-200-801									
21-51-13-900-801-01		REMOVAL / INSTALLATION OF THE RECIRCULATION VALVE - RECIRCULATION VALVE (220HD)					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.080	AFL	0		TSN 0					
PROC. REF: AMM 21-51-13-900-801									
21-52-05-350-801-01		RESTORATION OF THE TURBOCOOLER (OVERHAUL) - TURBOCOOLER (10HF)					Service	ATA:21	
PN:3511A020000AMDTB	MOS/MSC		N/A						
SN:00181	HRS								
WC#: 21.250	AFL								
PROC. REF: AMM 21-52-05-350-801									
21-52-05-610-801-01		TURBOCOOLER OIL SERVICING - TURBOCOOLER (10HF)					Service	ATA:21	
	MOS/MSC	23-Aug-07	N/A						
	HRS	5545.2							
WC#: 21.250	AFL	3737							
PROC. REF: AMM 21-52-05-610-801									
21-52-05-700-801-01		TURBOCOOLER OIL LEVEL CHECK - TURBOCOOLER (10HF)					Service	ATA:21	
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: AMM 21-52-05-700-801									
21-52-05-900-801-01		REMOVAL / INSTALLATION OF THE TURBOCOOLER - TURBOCOOLER (10HF)					Component	ATA:21	
PN:3511A020000AMDTB	MOS/MSC	20-May-16	O/C	TSO 11					
SN:00181	HRS	10730.7		TSO 0					
WC#: 21.250	AFL	7258		TSO 0					
PROC. REF: AMM 21-52-05-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-52-09-900-803-01		REMOVAL / INSTALLATION OF THE DUAL HEAT EXCHANGER - DUAL HEAT EXCHANGER (20HF)					Component	ATA:21	
PN:11-811528-3	MOS/MSC	08-Jul-22	O/C	TSR 8					
SN:E0515	HRS	13652.4		TSR 0					
WC#: 21.290	AFL	9039		TSR 0					
PROC. REF: AMM 21-52-09-900-803									
21-52-11-900-801-01		REMOVAL / INSTALLATION OF THE JET PUMP VALVE - JET PUMP VALVE (215HF)					Component	ATA:21	
PN:BYLB52232	MOS/MSC	26-Feb-03	O/C	TSN 0					
SN:23	HRS	1190.8		TSN 0					
WC#: 21.330	AFL	879		TSN 0					
PROC. REF: AMM 21-52-11-900-801									
21-52-13-100-801-01 ^S		CLEANING OF THE CONDENSER - CONDENSER (30HF)					Service	ATA:21	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 21.300	AFL	7947	3750						
PROC. REF: AMM 21-52-13-100-801									
21-52-13-900-801-01		REMOVAL / INSTALLATION OF THE CONDENSER - CONDENSER (30HF)					Component	ATA:21	
PN:11-881528	MOS/MSC	09-Mar-10	O/C	TSR 0					
SN:E0383	HRS	7238.9		TSR 0					
WC#: 21.300	AFL	4855		TSR 0					
PROC. REF: AMM 21-52-13-900-801									
21-52-18-100-801-01		CLEANING OF THE WATER SEPARATOR FILTER - WATER SEPARATOR FILTER (40HF1)					Service	ATA:21	
	MOS	08-Sep-22	24 (+1m)		08-Sep-24	08-Oct-24	155 d (+30)		
	HRS	13765.9	1200 (+40)	Adj -12.4	14953.5	14993.5	599.1 (+40)		
WC#: 21.260	AFL	9108							
PROC. REF: AMM 21-52-18-100-801									
21-52-33-900-801-01		REMOVAL / INSTALLATION OF THE TURBINE TEMPERATURE CONTROL VALVE - TURBINE TEMPERATURE CONTROL VALVE (120HF)					Component	ATA:21	
PN:785894-7	MOS/MSC	08-Apr-21	O/C	TSR 0					
SN:01970	HRS	12782.6		TSR 0					
WC#: 21.310	AFL	8523		TSR 0					
PROC. REF: AMM 21-52-33-900-801									
21-52-39-900-801-01		REMOVAL / INSTALLATION OF THE TURBINE TEMPERATURE SENSORS - TURBINE TEMPERATURE SENSOR (135HF)					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.320	AFL	0		TSN 0					
PROC. REF: AMM 21-52-39-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-52-39-900-801-02		REMOVAL / INSTALLATION OF THE TURBINE TEMPERATURE SENSORS - TURBINE TEMPERATURE SENSOR (136HF)					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.320	AFL	0		TSN 0					
PROC. REF: AMM 21-52-39-900-801									
21-52-45-900-801-01		REMOVAL / INSTALLATION OF THE COMPRESSOR OUTLET OVERHEAT SENSOR - COMPRESSOR OVERHEAT SENSOR (140HF)					Component	ATA:21	
PN:RP161-00	MOS/MSC	03-May-06	O/C	TSN 0					
SN:2789	HRS	4346		TSN 0					
WC#: 21.320	AFL	2979		TSN 0					
PROC. REF: AMM 21-52-45-900-801									
21-52-73-100-801-01 ^S		CLEANING OF THE TURBOCOOLER AIR RETURN INLET GRID					Service	ATA:21	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 21.400	AFL	9471							
PROC. REF: AMM 21-52-73-100-801									
21-52-75-960-801-01A		DISCARD DOWNSTREAM TURBOCOOLER CONDITIONING PIPE (MANDATORY 5-40)					Service	ATA:21	PKG:16
PN:F2MA721540A3	MOS/MSC	01-Oct-04	O/C						
SN:LF49/95	HRS	2789.2							
WC#: 21.390	AFL	1963							
PROC. REF: AMM 21-52-75-960-801									
21-60-00-900-801-01		REMOVAL / INSTALLATION OF THE CABIN TEMPERATURE SENSOR - CABIN TEMPERATURE SENSOR (140HN)					Component	ATA:21	
PN:785895	MOS/MSC	13-Oct-06	O/C	TSN 0					
SN:864	HRS	4862.4		TSN 0					
WC#: 21.380	AFL	3308		TSN 0					
PROC. REF: AMM 21-60-00-900-801									
21-61-02-900-801-01		REMOVAL / INSTALLATION OF THE AIR CONDITIONING COMPUTER - AIR CONDITIONING COMPUTER (115HN)					Component	ATA:21	
PN:785893-6	MOS/MSC	09-Jul-15	O/C	TSR 0					
SN:0236	HRS	10384.8		TSR 0					
WC#: 21.360	AFL	7018		TSR 0					
PROC. REF: AMM 21-61-02-900-801									
21-63-02-900-801-01		REMOVAL / INSTALLATION OF THE COCKPIT HOT TEMPERATURE VALVE - COCKPIT HOT TEMPERATURE CONTROL VALVE (R105HN)					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.350	AFL	0		TSN 0					
PROC. REF: AMM 21-63-02-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
21-63-03-900-801-01		REMOVAL / INSTALLATION OF THE COCKPIT COLD TEMPERATURE VALVE - COCKPIT COLD TEMPERATURE CONTROL VALVE (R100HN)						Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.350	AFL	0		TSN 0					
PROC. REF: AMM 21-63-03-900-801									
21-64-02-900-801-01		REMOVAL / INSTALLATION OF THE CABIN HOT TEMPERATURE VALVE - CABIN HOT TEMPERATURE CONTROL VALVE (L105HN)						Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.340	AFL	0		TSN 0					
PROC. REF: AMM 21-64-02-900-801									
21-64-03-900-801-01		REMOVAL / INSTALLATION OF THE CABIN COLD TEMPERATURE VALVE - CABIN COLD TEMPERATURE CONTROL VALVE (L100HN)						Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.340	AFL	0		TSN 0					
PROC. REF: AMM 21-64-03-900-801									
21-71-01-350-801-01		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - OZONE CONVERTER (L1HX)						Service	ATA:21
PN:41098001	MOS	02-Jun-14							
SN:7341	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 36.010	AFL	6566							
PROC. REF: AMM 21-71-01-350-801									
21-71-01-350-801-02		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - OZONE CONVERTER (R1HX)						Service	ATA:21
PN:41098001	MOS	02-Jun-14							
SN:7342	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 36.010	AFL	6566							
PROC. REF: AMM 21-71-01-350-801									
21-71-01-900-801-01		REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - OZONE CONVERTER (L1HX)						Component	ATA:21
PN:41098001	MOS/MSC	02-Jun-14	O/C	TSN 7					
SN:7341	HRS	9733.1		TSN 0					
WC#: 36.010	AFL	6566		TSN 0					
PROC. REF: AMM 21-71-01-900-801									
21-71-01-900-801-02		REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - OZONE CONVERTER (R1HX)						Component	ATA:21
PN:41098001	MOS/MSC	02-Jun-14	O/C	TSN 7					
SN:7342	HRS	9733.1		TSN 0					
WC#: 36.010	AFL	6566		TSN 0					
PROC. REF: AMM 21-71-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
212801	LH COOLING UNIT CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.050	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212806	RH COOLING UNIT CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.050	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212816	LH HOT AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212821	RH HOT AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212826	LH COLD AIR DISTRIBUTION CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.070	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212831	RH COLD AIR DISTRIBUTION CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.070	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
212841	RECIRCULATION CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 21.090	AFL	0			TSN 0				
PROC. REF: AMM 21-51-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
212846		NOSE CONE PNEUMATIC ACTUATOR					Component	ATA:21	
PN:7021-200	MOS/MSC	17-Dec-08	O/C						
SN:C47724	HRS	6549.1							
WC#: 21.100	AFL	4386							
PROC. REF: GENERIC NO REF									
212851		NOSE CONE THERMOSTAT					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
213811		NOSE CONE OVERPRESSURE CHECK VALVE					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
213841		NO. 1 ENGINE LOW PRESSURE AIR CHECK VALVE					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.230	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
213851		NO. 2 ENGINE LOW PRESSURE AIR CHECK VALVE					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.230	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
213861		APU LOW PRESSURE AIR CHECK VALVE					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.230	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
213871		PRESSURIZATION JET-PUMP					Component	ATA:21	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.240	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
215801	COLD AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.280	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
215806	DOWNSTREAM TURBOCOOLER CONDITIONING PIPE							Component	ATA:21
PN:F2MA721540A3	MOS/MSC	01-Oct-04	O/C	TSR 0					
SN:LF49/95	HRS	2789.2		TSR 0					
WC#: 21.390	AFL	1963		TSR 0					
PROC. REF: GENERIC NO REF									
215831	HIGH PRESSURE WATER SEPARATOR							Component	ATA:21
PN:SP0500C01	MOS/MSC	06-May-08	O/C						
SN:00379	HRS	6152.6							
WC#: 21.260	AFL	4109							
PROC. REF: GENERIC NO REF									
216851	CABIN DUCT TEMPERATURE (L120HN) SENSOR							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.370	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
216861	COCKPIT DUCT TEMPERATURE (R120HN) SENSOR							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.370	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
216866	CABIN DUCT TEMPERATURE (121HN) SENSOR							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.415	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
216881	COCKPIT TEMPERATURE SENSOR							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.380	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 21 - AIR CONDITIONING									
216891	CABIN TEMPERATURE INDICATOR							Component	ATA:21
PN:5318-221-80-10	MOS/MSC	05-Dec-03	O/C	TSR 0					
SN:408	HRS	1998.3		TSR 0					
WC#: 21.380	AFL	1413		TSR 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-01	REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - CABIN PRESSURE MANUAL CONTROLLER (60HP)							Component	ATA:21
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.220	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 22 - AUTO FLIGHT									
22-10-00-710-801-01 ^S	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)							Service	ATA:22
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 22.010	AFL	9471							
PROC. REF: AMM 22-10-00-710-801									
22-10-02-900-802-01	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL COMPUTER (FCC) - FCC 1 (L145CA)							Component	ATA:22
PN:822-0327-508	MOS/MSC	16-Mar-24	O/C						
SN:H88J	HRS	14354.4							
WC#: 22.050	AFL	9502							
PROC. REF: AMM 22-10-02-900-802									
22-10-02-900-802-02	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL COMPUTER (FCC) - FCC 2 (R145CA)							Component	ATA:22
PN:822-0327-508	MOS/MSC	16-Mar-24	O/C						
SN:1619	HRS	14354.4							
WC#: 22.050	AFL	9502							
PROC. REF: AMM 22-10-02-900-802									
22-10-05-720-801-01 ^S	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)							Service	ATA:22
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 22.020	AFL	6131	7500						
PROC. REF: AMM 22-10-05-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-10-05-720-801-02 ^S FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA) Service ATA:22								
	MOS	29-Aug-23	144 (+2m)					
	HRS	14127.2						
WC#: 22.030	AFL	9364	7500					
PROC. REF: AMM 22-10-05-720-801								PKG:32
22-10-05-900-801-01 REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA) Component ATA:22								
PN:622-4404-102	MOS/MSC	02-Sep-14	O/C					
SN:150C	HRS	9929.2						
WC#: 22.020	AFL	6700						
PROC. REF: AMM 22-10-05-900-801								
22-10-05-900-801-02 REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA) Component ATA:22								
PN:622-4404-102	MOS/MSC	29-Aug-23	O/C					
SN:3XGM	HRS	14127.2						
WC#: 22.030	AFL	9364						
PROC. REF: AMM 22-10-05-900-801								
22-10-07-700-801-01 ^S CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - AILERON SERVOMOTOR CABLE (10CA) Service ATA:22								
	MOS	16-Apr-13	144 (+2m)					
	HRS	9087.6						
WC#: 22.020	AFL	6131	7500					
PROC. REF: AMM 22-10-07-700-801								PKG:32
22-10-07-700-801-02 ^S CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - ELEVATOR SERVOMOTOR CABLE (5CA) Service ATA:22								
	MOS	16-Apr-13	144 (+2m)					
	HRS	9087.6						
WC#: 22.030	AFL	6131	7500					
PROC. REF: AMM 22-10-07-700-801								PKG:32
22-10-13-700-801-01 CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - AILERON SERVOMOTOR CAPSTAN (11CA) Service ATA:22								
	MOS	20-Dec-23						
	HRS	14292.8	14000 (+3%)		28292.8	28712.8	13938.4 (+420)	
WC#: 22.060	AFL	9471						
PROC. REF: AMM 22-10-13-700-801								
22-10-13-700-801-02 CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - ELEVATOR SERVOMOTOR CAPSTAN (6CA) Service ATA:22								
	MOS	19-Dec-23						
	HRS	14292.8	14000 (+3%)		28292.8	28712.8	13938.4 (+420)	
WC#: 22.060	AFL	9471						
PROC. REF: AMM 22-10-13-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 22 - AUTO FLIGHT									
22-13-01-350-801-01		RESTORATION OF THE YAW DAMPER ACTUATOR (OVERHAUL) - YAW DAMPER LINEAR ACTUATOR (220CA)							Service ATA:22
PN:822-1794-001	MOS	05-May-22						OVERHAUL	
SN:4PX43	HRS	13592.3	3000		16592.3		2237.9		
WC#: 22.040	AFL	9008							
PROC. REF: AMM 22-13-01-350-801									
22-13-01-350-801-01A		RESTORATION YAW DAMPER ACTUATOR (MANDATORY 5-40)							Service ATA:22
PN:822-1794-001	MOS	05-May-22						MANDATORY 5-40	
SN:4PX43	HRS	13592.3	3000		16592.3		2237.9		
WC#: 22.040	AFL	9008							
PROC. REF: AMM 22-13-01-350-801									
22-13-01-900-801-01		REMOVAL / INSTALLATION OF THE YAW DAMPER ACTUATOR - YAW DAMPER ACTUATOR (220CA)							Component ATA:22
PN:822-1794-001	MOS/MSC	05-May-22	H/T						
SN:4PX43	HRS	13592.3							
WC#: 22.040	AFL	9008							
PROC. REF: AMM 22-13-01-900-801									
22-15-00-720-801-01 ^S		FUNCTIONAL TEST OF MACH TRIM							Service ATA:22
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 22.080	AFL	9008							
PROC. REF: AMM 22-15-00-720-801									
PKG:21									
221801		AUTOPILOT AILERON CONTROL SERVOMOTOR SUPPORT							Component ATA:22
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.060	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05-900-801									
221802		AUTOPILOT ELEVATOR CONTROL SERVOMOTOR SUPPORT							Component ATA:22
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.060	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05-900-801									
ATA 23 - COMMUNICATIONS									
23-11-00-710-802-01		OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 1 SYSTEM							Service ATA:23
	MOS/MSC	20-Jul-14	O/C						
	HRS	9833.8							
	AFL	6636							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 23 - COMMUNICATIONS									
PROC. REF: AMM 23-11-00-710-802									
23-11-00-710-802-02	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 2 SYSTEM							Service	ATA:23
	MOS/MSC	20-Jul-14	O/C						
	HRS	9833.8							
	AFL	6636							
PROC. REF: AMM 23-11-00-710-802									
23-11-00-710-802-03	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 3 SYSTEM (A/C WITH VHF 3)							Service	ATA:23
	MOS/MSC	20-Jul-14	O/C						
	HRS	9833.8							
	AFL	6636							
PROC. REF: AMM 23-11-00-710-802									
23-11-05-900-801-01	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 1 ANTENNA							Component	ATA:23
PN:S65-8280-10	MOS/MSC	20-Jul-14	O/C	TSN 0					
SN:310-24784	HRS	9833.8		TSN 0					
WC#: 23.020	AFL	6636		TSN 0					
PROC. REF: AMM 23-11-05-900-801									
23-11-05-900-801-02	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 2 ANTENNA							Component	ATA:23
PN:S65-8280-10	MOS/MSC	01-Oct-23	O/C	TSN 0					
SN:857-861	HRS	14171.3		TSN 0					
WC#: 23.020	AFL	9397		TSN 0					
PROC. REF: AMM 23-11-05-900-801									
23-60-00-760-801-01 ^S	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS							Service	ATA:23
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 23.070	AFL	9008							
PROC. REF: AMM 23-60-00-760-801									
23-81-01-900-801-01	REMOVAL / INSTALLATION OF THE RADIO TUNING UNIT (RTU) - RTU 1 (L230RC)							Component	ATA:23
PN:822-0730-334	MOS/MSC	14-Dec-04	O/C	TSR 0					
SN:3GUM	HRS	2914.5		TSR 0					
WC#: 23.040	AFL	2035		TSR 0					
PROC. REF: AMM 23-81-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 23 - COMMUNICATIONS									
23-81-01-900-801-02		REMOVAL / INSTALLATION OF THE RADIO TUNING UNIT (RTU) - RTU 2 (R230RC)					Component	ATA:23	
PN:822-0730-334	MOS/MSC	20-Oct-10	O/C						
SN:888	HRS	7625.5							
WC#: 23.040	AFL	5112							
PROC. REF: AMM 23-81-01-900-801									
231801		HF ANTENNA					Component	ATA:23	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
231831		NO. 1 VHF TRANSCEIVER					Component	ATA:23	
PN:822-1115-001	MOS/MSC	29-Sep-23	O/C	TSO 0					
SN:1925	HRS	14169		TSO 0					
WC#: 23.030	AFL	9395		TSO 0					
PROC. REF: GENERIC NO REF									
231841		NO. 2 VHF TRANSCEIVER					Component	ATA:23	
PN:822-1115-021	MOS/MSC	29-Sep-23	O/C						
SN:010V	HRS	14169							
WC#: 23.030	AFL	9395							
PROC. REF: GENERIC NO REF									
231871		HF TRANSCEIVER					Component	ATA:23	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
231876		HF COUPLER AMPLIFIER					Component	ATA:23	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
233A16 ^U		AIRSHOW (DIU) DIGITAL INTERFACE UNIT					Component	ATA:23	
PN:920050	MOS/MSC	27-Jul-21	O/C						
SN:1530	HRS	12963.9							
	AFL	8644							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-20-05-710-801-01 ^S		OPERATIONAL TEST OF THE GROUND FAULT INTERRUPTER (GFI)						Service	ATA:24
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 24-20-05-710-801, SMM 24-90-01								PKG:21	
24-30-00-710-801-01 ^S		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS						Service	ATA:24
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 24.030	AFL	9008							
PROC. REF: AMM 24-30-00-710-801								PKG:21	
24-30-00-710-801-01A		OPERATIONAL TEST OF VOLTAGE MONITORING CIRCUITS (MANDATORY 5-40)						Service	ATA:24
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
PROC. REF: AMM 24-30-00-710-801									
24-31-01-350-801-01		RESTORATION OF THE DC GENERATORS (OVERHAUL) - DC GENERATOR 1 (L100PC)						Service	ATA:24
PN:12800-2-1	MOS	16-Jul-19						OVERHAUL	
SN:1017	HRS	11761.3	3240 (+3%)		15001.3	15098.5	646.9 (+97.2)		
WC#: 24.070	AFL	7947							
PROC. REF: AMM 24-31-01-350-801									
24-31-01-350-801-02		RESTORATION OF THE DC GENERATORS (OVERHAUL) - DC GENERATOR 2 (R100PC)						Service	ATA:24
PN:12800-2-1	MOS	16-Jul-19						OVERHAUL	
SN:1545	HRS	11761.3	3240 (+3%)		15001.3	15098.5	646.9 (+97.2)		
WC#: 24.070	AFL	7947							
PROC. REF: AMM 24-31-01-350-801									
24-31-01-900-801-01		REMOVAL / INSTALLATION OF THE DC GENERATORS - DC GENERATOR 1 (L100PC)						Component	ATA:24
PN:12800-2-1	MOS/MSC	16-Jul-19	H/T	TSO 91					
SN:1017	HRS	11761.3		TSN 10275.2, TSO 3275.2					
WC#: 24.070	AFL	7947		TSO 2240					
PROC. REF: AMM 24-31-01-900-801									
24-31-01-900-801-02		REMOVAL / INSTALLATION OF THE DC GENERATORS - DC GENERATOR 2 (R100PC)						Component	ATA:24
PN:12800-2-1	MOS/MSC	16-Jul-19	H/T	TSO 143					
SN:1545	HRS	11761.3		TSO 6220.4					
WC#: 24.070	AFL	7947		TSO 4215					
PROC. REF: AMM 24-31-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-31-09-900-801-01		REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - APU GCU (70KA)					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.110	AFL	0		TSN 0					
PROC. REF: AMM 24-31-09-900-801									
24-31-09-900-801-02		REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 1 (L130PC)					Component	ATA:24	
PN:12900-6	MOS/MSC	22-Sep-06	O/C	TSR 0					
SN:1918	HRS	4778.9		TSR 0					
WC#: 24.110	AFL	3262		TSR 0					
PROC. REF: AMM 24-31-09-900-801									
24-31-09-900-801-03		REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 2 (R130PC)					Component	ATA:24	
PN:12900-6	MOS/MSC	15-Jan-10	O/C	TSR 0					
SN:2165	HRS	7185.3		TSR 0					
WC#: 24.110	AFL	4827		TSR 0					
PROC. REF: AMM 24-31-09-900-801									
24-32-00-710-802-01		CHECK OF THE BATTERY REVERSE CURRENT PROTECTION					Service	ATA:24	
	MOS	17-Apr-13							
	HRS	9087.6	7500		16587.6		2233.2		
WC#: 24.060	AFL	6131							
PROC. REF: AMM 24-32-00-710-802									
24-32-00-710-802-01A		CHECK OF THE BATTERY REVERSE CURRENT PROTECTION (MANDATORY 5-40)					Service	ATA:24	
	MOS	17-Apr-13						MANDATORY 5-40	
	HRS	9087.6	7500		16587.6		2233.2		
WC#: 24.060	AFL	6131							
PROC. REF: AMM 24-32-00-710-802									
24-32-01-350-801-01		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY (150PC)					Service	ATA:24	
PN:405CH10	MOS	28-Dec-23	33 (+2m)		28-Sep-26	28-Nov-26	905 d (+61)	OVERHAUL	
SN:S06469	HRS	14292.8	1700 (+3%)		15992.8	16043.8	1638.4 (+51)		
WC#: 24.050	AFL	9471							
PROC. REF: AMM 24-32-01-350-801									
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY (150PC)					Service	ATA:24	
PN:405CH10	MOS	28-Dec-23	17 (+1m)		28-May-25	28-Jun-25	417 d (+31)		
SN:S06469	HRS	14292.8	850 (+10%)		15142.8	15227.8	788.4 (+85)		
WC#: 24.050	AFL	9471							
PROC. REF: AMM 24-32-01-700-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-32-01-700-802-01		REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY (150PC)						Service	ATA:24
PN:405CH10	MOS/MSC		N/A						
SN:S06469	HRS								
WC#: 24.050	AFL								
PROC. REF: AMM 24-32-01-700-802									
24-32-01-900-801-01		REMOVAL / INSTALLATION OF THE MAIN BATTERY - BATTERY (150PC)						Component	ATA:24
PN:405CH10	MOS/MSC	28-Dec-23	O/C	TSO 47					
SN:S06469	HRS	14292.8		TSO 1429.2					
WC#: 24.050	AFL	9471		TSO 897					
PROC. REF: AMM 24-32-01-900-801									
24-32-01-960-801-01		DISCARD OF THE MAIN LEAD / ACID BATTERY - BATTERY (150PC)						Service	ATA:24
PN:405CH10	MOS/MSC		O/C						
SN:S06469	HRS								
WC#: 24.050	AFL								
PROC. REF: AMM 24-32-01-960-801									
24-32-09-610-801-01		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY INSTRUMENTS BATTERY (330NH)						Service	ATA:24
PN:804747	MOS	02-May-23	12 (+3%)		02-May-24	13-May-24	26 d (+11)		
SN:2945	HRS	13952.4							
WC#: 34.140	AFL	9231							
PROC. REF: AMM 24-32-09-610-801									
24-32-09-610-801-02		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP)						Service	ATA:24
PN:135687	MOS	02-May-23	12 (+3%)		02-May-24	13-May-24	26 d (+11)		
SN:2221	HRS	13952.4							
WC#: 34.150	AFL	9231							
PROC. REF: AMM 24-32-09-610-801									
24-32-09-610-801-03		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)						Service	ATA:24
PN:804747	MOS	02-May-23	12 (+3%)		02-May-24	13-May-24	26 d (+11)		
SN:2959	HRS	13952.4							
WC#: 34.150	AFL	9231							
PROC. REF: AMM 24-32-09-610-801									
24-32-09-610-801-04		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)						Service	ATA:24
PN:135687	MOS	06-Dec-23	12 (+3%)		06-Dec-24	17-Dec-24	244 d (+11)		
SN:4212	HRS	14292.8							
WC#: 34.160	AFL	9471							
PROC. REF: AMM 24-32-09-610-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-710-802-01 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - STAND-BY INSTRUMENTS BATTERY (330NH) Service ATA:24								
PN:804747	MOS/MSC	02-May-23	N/A					
SN:2945	HRS	13952.4						
WC#: 34.140	AFL	9231						
PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-02 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP) Service ATA:24								
PN:135687	MOS/MSC	02-May-23	N/A					
SN:2221	HRS	13952.4						
WC#: 34.150	AFL	9231						
PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-03 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP) Service ATA:24								
PN:804747	MOS/MSC	02-May-23	N/A					
SN:2959	HRS	13952.4						
WC#: 34.150	AFL	9231						
PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-04 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP) Service ATA:24								
PN:135687	MOS/MSC	06-Dec-23	N/A					
SN:4212	HRS	14292.8						
WC#: 34.160	AFL	9471						
PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-05 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - AUXILIARY BATTERY (R710PE) Service ATA:24								
PN:PN	MOS/MSC	01-Mar-00	N/A					
SN:NOT INSTALLED	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-710-802, CMM 24-30-08								
24-32-09-720-801-01 CAPACITY TESTING OF THE STAND-BY BATTERIES - STAND-BY INSTRUMENTS BATTERY (330NH) Service ATA:24								
PN:804747	MOS/MSC	02-May-23	N/A					
SN:2945	HRS	13952.4						
	AFL	9231						
PROC. REF: AMM 24-32-09-720-801								
24-32-09-720-801-02 CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP) Service ATA:24								
PN:135687	MOS/MSC	02-May-23	N/A					
SN:2221	HRS	13952.4						
	AFL	9231						
PROC. REF: AMM 24-32-09-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-32-09-720-801-03		CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)							Service ATA:24
PN:804747	MOS/MSC	02-May-23	N/A						
SN:2959	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 24-32-09-720-801									
24-32-09-720-801-04		CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)							Service ATA:24
PN:135687	MOS/MSC	06-Dec-23	N/A						
SN:4212	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 24-32-09-720-801									
24-32-09-720-801-05		CAPACITY TESTING OF THE STAND-BY BATTERIES - AUXILIARY BATTERY (R710PE)							Service ATA:24
PN:PN	MOS/MSC	01-Mar-00	N/A						
SN:NOT INSTALLED	HRS	0							
WC#: 23.080	AFL	0							
PROC. REF: AMM 24-32-09-720-801, CMM 24-30-08									
24-32-09-900-801-01		REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - STAND-BY INSTRUMENTS BATTERY (330NH)							Component ATA:24
PN:804747	MOS/MSC	02-May-23	O/C		TSO 0				
SN:2945	HRS	13952.4			TSO 0				
WC#: 34.140	AFL	9231			TSO 0				
PROC. REF: AMM 24-32-09-900-801									
24-32-09-900-801-02		REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP)							Component ATA:24
PN:135687	MOS/MSC	02-May-23	O/C		TSO 0				
SN:2221	HRS	13952.4			TSO 0				
WC#: 34.150	AFL	9231			TSO 0				
PROC. REF: AMM 24-32-09-900-801									
24-32-09-900-801-03		REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)							Component ATA:24
PN:804747	MOS/MSC	02-May-23	O/C		TSO 0				
SN:2959	HRS	13952.4			TSO 0				
WC#: 34.150	AFL	9231			TSO 0				
PROC. REF: AMM 24-32-09-900-801									
24-32-09-900-801-04		REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)							Component ATA:24
PN:135687	MOS/MSC	06-Dec-23	O/C		TSO 0				
SN:4212	HRS	14292.8			TSO 0				
WC#: 34.160	AFL	9471			TSO 0				
PROC. REF: AMM 24-32-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-32-09-900-801-05		REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - AUXILIARY BATTERY (R710PE)					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:NOT INSTALLED	HRS	0		TSN 0					
WC#: 23.080	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
24-32-09-960-801-01		REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - STAND-BY INSTRUMENTS BATTERY (330NH)					Service	ATA:24	
PN:804747	MOS/MSC	02-May-23	O/C						
SN:2945	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 24-32-09-960-801									
24-32-09-960-801-02		REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 1 STAND-BY BATTERY (195NP)					Service	ATA:24	
PN:135687	MOS/MSC	02-May-23	O/C						
SN:2221	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 24-32-09-960-801									
24-32-09-960-801-03		REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 2 STAND-BY BATTERY (295NP)					Service	ATA:24	
PN:804747	MOS/MSC	02-May-23	O/C						
SN:2959	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 24-32-09-960-801									
24-32-09-960-801-05		REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 3 STAND-BY BATTERY (95NP)					Service	ATA:24	
PN:135687	MOS/MSC	06-Dec-23	O/C						
SN:4212	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 24-32-09-960-801									
24-32-09-960-802-01		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - STAND-BY INSTRUMENTS BATTERY (330NH)					Service	ATA:24	
PN:804747	MOS/MSC	02-May-23	N/A						
SN:2945	HRS	13952.4							
WC#: 34.140	AFL	9231							
PROC. REF: AMM 24-32-09-960-802									
24-32-09-960-802-02		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 1 STAND-BY BATTERY (195NP)					Service	ATA:24	
PN:135687	MOS/MSC	02-May-23	N/A						
SN:2221	HRS	13952.4							
WC#: 34.150	AFL	9231							
PROC. REF: AMM 24-32-09-960-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-960-802-03 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 2 STAND-BY BATTERY (295NP) Service ATA:24								
PN:804747	MOS/MSC	02-May-23	N/A					
SN:2959	HRS	13952.4						
WC#: 34.150	AFL	9231						
PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-04 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 3 STAND-BY BATTERY (95NP) Service ATA:24								
PN:135687	MOS/MSC	06-Dec-23	N/A					
SN:4212	HRS	14292.8						
WC#: 34.160	AFL	9471						
PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-05 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - AUXILIARY BATTERY (R710PE) Service ATA:24								
PN:PN	MOS/MSC	01-Mar-00	N/A					
SN:NOT INSTALLED	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-960-802								
24-33-01-350-801-01 RESTORATION OF THE APU STARTER-GENERATOR (OVERHAUL) - APU STARTER-GENERATOR (30KA) Service ATA:24								
PN:8060-160	MOS	15-Jun-22						OVERHAUL
SN:3508	HRS	13630.3						
WC#: 24.040	AFL	9028						
	APH	11344	1240 (+3%)	Adj .02	12584.02	12621.22	645 (+37.2)	
PROC. REF: AMM 24-33-01-350-801								
24-33-01-900-801-01 REMOVAL / INSTALLATION OF THE APU STARTER-GENERATOR - APU STARTER-GENERATOR (30KA) Component ATA:24								
PN:8060-160	MOS/MSC	15-Jun-22	H/T	TSN 0				
SN:3508	HRS	13630.3		TSN 0				
WC#: 24.040	AFL	9028		TSN 0				
	APH	11344	0	TSN 0, Adj .02				
PROC. REF: AMM 24-33-01-900-801								
24-33-05-220-803-01 CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (30KA) Service ATA:24								
PN:8060-160	MOS/MSC	15-Jun-22	N/A					
SN:3508	HRS	13630.3						
	AFL	9028						
PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-33-05-220-804-01 CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - APU STARTER-GENERATOR (30KA) Service ATA:24								
PN:8060-160	MOS/MSC	15-Jun-22	N/A					
SN:3508	HRS	13630.3						
	AFL	9028						
	APH	11344		Adj .02				
PROC. REF: AMM 24-33-05-220-804								
24-33-05-220-805-01 CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - APU STARTER-GENERATOR (30KA) Service ATA:24								
PN:8060-160	MOS	20-Dec-23						
SN:3508	HRS	14292.8						
	AFL	9471						
	APH	11915	150		12065	12095	126 (+30)	
PROC. REF: AMM 24-33-05-220-805								
24-33-05-960-801-01 REPLACEMENT OF THE APU STARTER-GENERATOR BRUSHES Service ATA:24								
PN:8060-160	MOS/MSC	15-Jun-22	O/C					
SN:3508	HRS	13630.3						
	AFL	9028						
	APH	11344	0	Adj .02				
PROC. REF: AMM 24-33-05-960-801								
24-40-00-720-801-01^S FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB - GROUND POWER UNIT PROTECTION PCB (504PG) Service ATA:24								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 24.120	AFL	9008						
PROC. REF: AMM 24-40-00-720-801								
24-41-00-720-801-01^S FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE FUNCTION Service ATA:24								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 24-41-00-720-801								
24-41-00-720-801-02^S FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF SAFETY DEVICES Service ATA:24								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 24-41-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
24-61-01-900-801-01		REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOXES - LH MAIN ELECTRICAL BOX (10PZ)					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.010	AFL	0		TSN 0					
PROC. REF: AMM 24-61-01-900-801									
24-61-01-900-801-02		REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOXES - RH MAIN ELECTRICAL BOX (20PZ)					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.010	AFL	0		TSN 0					
PROC. REF: AMM 24-61-01-900-801									
24-63-09-720-801-01 ^S		FUNCTIONAL TEST OF THE ENGINE STARTING PRINTED CIRCUIT BOARD - LH ENGINE STARTING PCB (L15EX)					Service	ATA:24	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 80.030	AFL	9008							
PROC. REF: AMM 24-63-09-720-801									
24-63-09-720-801-02 ^S		FUNCTIONAL TEST OF THE ENGINE STARTING PRINTED CIRCUIT BOARD - RH ENGINE STARTING PCB (R15EX)					Service	ATA:24	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 80.030	AFL	9008							
PROC. REF: AMM 24-63-09-720-801									
24-63-13-710-801-01 ^S		OPERATIONAL TEST OF THE DOME LIGHT PCB - DOME LIGHT PCB (515LS)					Service	ATA:24	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 24.140	AFL	9008							
PROC. REF: AMM 24-63-13-710-801									
24-90-01-900-801-01		GROUND FAULT (GFI) INTERRUPTER					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
243805		LH ALTERNATOR AIR-INTAKE DUCT					Component	ATA:24	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
243806	RH ALTERNATOR AIR-INTAKE DUCT							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.130	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
243811	MAIN SUPPLY BATTERY BLOWER							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.020	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
243821	LH DC VOLTMETER							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.080	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
243831	RH DC VOLTMETER							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.080	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
243841	LH DC AMMETER							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.090	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
243851	RH DC AMMETER							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.090	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
244801	GROUND POWER RECEPTACLE							Component	ATA:24
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 24.120	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-00-01-200-801-01 INSPECTION OF THE ONBOARD KIT Service ATA:25								
	MOS/MSC	08-Feb-17	O/C					
	HRS	10863.8						
WC#: 25.035	AFL	7323						
PROC. REF: AMM 25-00-01-200-801								
25-00-05-200-801-01 ^S INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSSES AND SAFETY BELTS Service ATA:25								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
WC#: 25.010	AFL	7947	3750					
PROC. REF: AMM 25-00-05-200-801								
PKG:31								
25-00-09-200-801-01 ^U CHECK OF THE CLOSING AND SEALING OF TRASH CANS Service ATA:25								
	MOS/MSC	08-Sep-22	O/C					
	HRS	13765.9						
WC#: 25.032	AFL	9108						
PROC. REF: GENERIC NO REF								
25-11-01-900-801-01 REMOVAL / INSTALLATION OF THE PILOT SEATS - LH PILOT SEAT (L2MG) Component ATA:25								
PN:1421310-15	MOS/MSC	28-Feb-07	O/C					
SN:131	HRS	5187.3		TSN 5871.8				
WC#: 25.020	AFL	3511		TSN 3991				
PROC. REF: AMM 25-11-01-900-801								
25-11-01-900-801-02 REMOVAL / INSTALLATION OF THE PILOT SEATS - RH PILOT SEAT (R2MG) Component ATA:25								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01-900-801								
25-11-13-640-801-01 ^S GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG) Service ATA:25								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 25.030	AFL	9008						
PROC. REF: AMM 25-11-13-640-801								
PKG:21								
25-11-13-640-801-02 ^S GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG) Service ATA:25								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 25.030	AFL	9008						
PROC. REF: AMM 25-11-13-640-801								
PKG:21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-11-19-960-801-01 ^S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG)							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-11-19-960-801							PKG:31	
25-11-19-960-801-02 ^S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG)							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-11-19-960-801							PKG:31	
25-11-25-200-801-01 ^S	INSPECTION OF THE PILOT SEAT ROLLER PINS - LH PILOT SEAT (L2MG)							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 25.110	AFL	7947	3750						
	PROC. REF: AMM 25-11-25-200-801							PKG:31	
25-11-25-200-801-02 ^S	INSPECTION OF THE PILOT SEAT ROLLER PINS - RH PILOT SEAT (R2MG)							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-11-25-200-801							PKG:31	
25-12-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT - THIRD CREW MEMBER SEAT (M1001MP)							Service	ATA:25
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
	PROC. REF: AMM 25-12-00-210-801, SMM 25-90-01							PKG:5	
25-20-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - PASSENGER DOOR ASSIST HANDLE							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-20-00-210-801, SMM 25-90-07							PKG:31	
25-20-00-210-801-02	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - AFT LAVATORY ASSIST HANDLE							Service	ATA:25
	MOS/MSC		N/A						
	HRS								
	AFL								
	PROC. REF: AMM 25-20-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-20-00-220-801-04	INSPECTION / TEST OF THE WASTE CONTAINERS - INSPECTION / TEST OF WASTE CONTAINERS							Service	ATA:25
	MOS	08-Sep-22							
	HRS	13765.9	1000	Adj -9.8	14756.1		401.7		
	AFL	9108							
	PROC. REF: AMM 25-20-00-220-801, SMM 25-90-17								
25-20-00-220-802-01 ^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-20-00-220-802, SMM 25-90-09								
25-20-00-220-802-02 ^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF THE POP OUT WORK SURFACE							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-20-00-220-802, SMM 25-90-25								
25-20-00-220-802-05 ^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - OPERATIONAL TEST OF TAMBOUR DOOR POWER CUT OFF FUNCTION							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-20-00-220-802, SMM 25-90-13								
25-21-00-220-801-01 ^S	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE SINGLE AND DOUBLE SEATS							Service	ATA:25
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 25-21-00-220-801, SMM 25-90-03								
25-21-00-220-801-02 ^S	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE DIVAN							Service	ATA:25
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 25-21-00-220-801, SMM 25-90-05								
25-22-01-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-22-01-210-801, SMM 25-90-27								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-22-01-210-801-02 ^U	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLE IN FRONT OF EMERGENCY EXIT							Service	ATA:25
	MOS/MSC	16-Jul-19	O/C						
	HRS	11761.3							
	AFL	7947							
	PROC. REF: SMM 25-90-27								
25-22-05-220-802-01 ^S	DETAILED INSPECTION OF THE DINING TABLE							Service	ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 25-22-05-220-802, SMM 25-90-29								
	PKG:31								
25-23-61-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE TRACKING MAGAZINE RACK - INSPECTION OF THE TRACKING MAGAZINE RACK							Service	ATA:25
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
	AFL	9471							
	PROC. REF: AMM 25-23-61-210-801, SMM 25-90-39								
	PKG:6								
25-30-16-900-801-01	COFFEE MAKER							Component	ATA:25
PN:HFE96-28B	MOS/MSC	02-Dec-15	O/C						
SN:01172AT	HRS	10579							
	AFL	7153							
	PROC. REF: AMM 25-33-00-900-801								
25-30-33-900-801-01	CONVECTION OVEN							Component	ATA:25
PN:1539-IM-OH	MOS/MSC	06-Jun-04	O/C	TSR 0					
SN:97-4-22842	HRS	2424.3		TSR 0					
	AFL	1715		TSR 0					
	PROC. REF: AMM 25-33-00-900-801								
25-33-09-210-801-01	INSPECTION OF THE COFFEE MAKER / ESPRESSO MACHINE							Service	ATA:25
	MOS/MSC	02-Dec-15	A/R						
	HRS	10579							
	AFL	7153							
	PROC. REF: AMM 25-33-09-210-801								
25-33-17-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN							Service	ATA:25
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 25-33-17-210-801, SMM 25-90-19								
	PKG:7								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-33-17-710-801-01		OPERATIONAL TEST OF THE MICROWAVE OVEN DOOR ELECTRICAL POWER CUT-OFF FUNCTION							Service ATA:25
PN:R26ST	MOS/MSC		N/A						
SN:080873512	HRS	0							
	AFL								
PROC. REF: AMM 25-33-17-710-801									
25-60-00-200-801-02 ^S		INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT							Service ATA:25
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 25.040	AFL	9471							
PROC. REF: AMM 25-60-00-200-801									
PKG:16									
25-60-00-200-801-03		INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT							Service ATA:25
	MOS/MSC	27-Dec-23	DUE						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 25-60-00-200-801									
25-60-01-900-801-01		NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT							Component ATA:25
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-00-900-801									
25-60-01-900-801-02		NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT							Component ATA:25
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-00-900-801									
25-61-00-200-881-01		INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)							Service ATA:25
	MOS	26-May-23	12		26-May-24		50 d	MANDATORY	
	HRS	13996.4							
	AFL	9265							
PROC. REF: FAR 91.207									
25-61-00-710-801-01		OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM- CHECK OF ELT 96/97 UNIT CONTROLS							Service ATA:25
	MOS/MSC	20-May-16	O/C						
	HRS	10730.7							
WC#: 25.100	AFL	7258							
PROC. REF: AMM 25-61-00-710-801, AMM 25-61-00-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-00-710-801-02^S OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM- CHECK OF ELT 96/97/ADT 406 COCKPIT CONTROLS								
	MOS	16-Jul-19	36 (+1m)					Service ATA:25
	HRS	11761.3						
	AFL	7947						
PROC. REF: AMM 25-61-00-710-801, AMM 25-61-00-710-801								PKG:17
25-61-00-710-801-03 OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT 96/97/ADT 406								
	MOS	19-Jan-23	36 (+1m)	Adj -187d	16-Jul-25	16-Aug-25	466 d (+31)	Service ATA:25
	HRS	13859.4						
	AFL	9175						
PROC. REF: AMM 25-61-00-710-801, AMM 25-61-00-710-801								
25-61-00-710-801-04 OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - OPERATIONAL TEST OF ELT 90/91								
	MOS/MSC	20-May-16	N/A					Service ATA:25
	HRS	10730.7						
	AFL	7258						
PROC. REF: AMM 25-61-00-710-801								
25-61-01-710-801-01 OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) G-SWITCH - ELT (32RB)								
PN:01N65900	MOS	26-May-23	60 (+3%)		26-May-28	20-Jul-28	1511 d (+55)	Service ATA:25
SN:07452196	HRS	13996.4						
	AFL	9265						
PROC. REF: AMM 25-61-01-710-801, AMM 25-61-01-710-801								
25-61-01-900-802-01 REMOVAL / INSTALLATION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) ADT 406 - ELT (32RB)								
PN:01N65900	MOS/MSC	26-May-23	O/C	TSR 85				Component ATA:25
SN:07452196	HRS	13996.4		TSR 3265.7				
WC#: 25.100	AFL	9265		TSR 2007				
PROC. REF: AMM 25-61-01-900-803, AMM 25-61-01-900-804, AMM 25-61-01-900-802								
25-61-13-200-801-01 VISUAL INSPECTION OF THE ELT BATTERY PACK (JOLLIET JE2) - ELT (32RB)								
	MOS/MSC	01-Mar-00	O/C					Service ATA:25
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-61-13-200-801								
25-61-13-200-802-01 VISUAL INSPECTION OF THE ELT BATTERY PACKS (ELT 90 / 91 OR ELT 96 / 97) - ELT (32RB)								
	MOS/MSC	26-May-23	O/C					Service ATA:25
	HRS	13996.4						
	AFL	9265						
PROC. REF: AMM 25-61-13-200-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-13-200-803-01 VISUAL INSPECTION OF ELT BATTERY PACK (ELT ADT 406) - ELT (32RB) Service ATA:25								
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-61-13-200-803								
25-61-13-960-801-01 DISCARD OF THE ELT BATTERY PACKS - ELT (32RB) Service ATA:25								
PN:01N65900	MOS/MSC	26-May-23	DUE		29-Feb-28 (M)		1424 d	LIFE LIMIT
SN:07452196	HRS	13996.4						
WC#: 25.100	AFL	9265						
PROC. REF: AMM 25-61-13-960-801								
25-62-00-900-801-01 REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1) Component ATA:25								
PN:DK120	MOS/MSC	19-Jan-23	O/C					
SN:SC45445	HRS	13859.4						
WC#: 25.100	AFL	9175						
PROC. REF: AMM 25-62-00-900-801								
25-62-00-900-801-02 REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1) OR (715FZ1) Component ATA:25								
PN:DK120/90	MOS/MSC	19-Jan-23	O/C					
SN:AT49143	HRS	13859.4						
WC#: 25.100	AFL	9175						
PROC. REF: AMM 25-62-00-900-801								
25-62-01-720-801-01 FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1) Service ATA:25								
PN:DK120	MOS	19-Jan-23	25 (+3%)		19-Feb-25	12-Mar-25	319 d (+21)	
SN:SC45445	HRS	13859.4						
WC#: 25.100	AFL	9175						
PROC. REF: AMM 25-62-01-720-801								
25-62-01-720-801-02 FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1) OR (715FZ1) Service ATA:25								
PN:DK120/90	MOS	19-Jan-23	25 (+3%)		19-Feb-25	12-Mar-25	319 d (+21)	
SN:AT49143	HRS	13859.4						
WC#: 25.100	AFL	9175						
PROC. REF: AMM 25-62-01-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-62-05-960-801-01	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR UNDERWATER LOCATOR BEACON (10FZ1)							Service	ATA:25
PN:DK120	MOS/MSC	19-Jan-23	DUE		31-Oct-29 (M)		2034 d	LIFE LIMIT	
SN:SC45445	HRS	13859.4							
WC#: 25.100	AFL	9175							
PROC. REF: AMM 25-62-05-960-801									
25-62-05-960-801-02	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR UNDERWATER LOCATOR BEACON (130FZ1)							Service	ATA:25
PN:DK120/90	MOS/MSC	19-Jan-23	DUE		31-Oct-29 (M)		2034 d	LIFE LIMIT	
SN:AT49143	HRS	13859.4							
WC#: 25.100	AFL	9175							
PROC. REF: AMM 25-62-05-960-801									
25-63-00-350-801-01	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - PILOT EVAS UNIT (L9510MP)							Service	ATA:25
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-00-350-801									
25-63-00-350-801-02	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - COPILOT EVAS UNIT (R9510MP)							Service	ATA:25
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-00-350-801									
25-63-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - PILOT EVAS UNIT (L9510MP)							Service	ATA:25
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: AMM 25-63-00-710-801									
25-63-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - COPILOT EVAS UNIT (R9510MP)							Service	ATA:25
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: AMM 25-63-00-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-63-01-960-801-01		DISCARD OF THE EVAS BATTERY - PILOT EVAS UNIT (L9510MP)						Service	ATA:25
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-01-960-801									
25-63-01-960-801-02		DISCARD OF THE EVAS BATTERY - COPILOT EVAS UNIT (R9510MP)						Service	ATA:25
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 25-63-01-960-801									
25-64-13-200-801-01		INSPECT NO. 1 LIFE RAFT						Service	ATA:25
PN:913FAUL-J301101	MOS	15-May-23	36 (+3%)		15-May-26	17-Jun-26	769 d (+33)		
SN:9UL-00152	HRS	13972.9							
WC#: 25.090	AFL	9253							
PROC. REF: AMM 25-64-13-200-801									
25-64-13-200-801-01		INSPECT NO. 2 LIFE RAFT						Service	ATA:25
PN:913FAUL-J301101	MOS	15-May-23	36 (+3%)		15-May-26	17-Jun-26	769 d (+33)		
SN:9UL-00396	HRS	13972.9							
WC#: 25.090	AFL	9253							
PROC. REF: AMM 25-64-13-200-801									
25-64-13-350-801-01		RESTORATION NO. 1 LIFE RAFT (OVERHAUL)						Service	ATA:25
PN:913FAUL-J301101	MOS	15-May-23	60 (+3%)		15-May-28	09-Jul-28	1500 d (+55)		
SN:9UL-00152	HRS	13972.9							
	AFL	9253							
PROC. REF: AMM 25-64-13-350-801									
25-64-13-350-801-01		RESTORATION NO. 2 LIFE RAFT (OVERHAUL)						Service	ATA:25
PN:913FAUL-J301101	MOS	15-May-23	60 (+3%)		15-May-28	09-Jul-28	1500 d (+55)		
SN:9UL-00396	HRS	13972.9							
	AFL	9253							
PROC. REF: AMM 25-64-13-350-801									
25-64-13-790-801-01S ^U		INSPECTION/HYDROSTATIC TEST NO. 1 LIFE RAFT						Service	ATA:25
PN:913FAUL-J301101	MOS	15-May-23	60		15-May-28		1500 d		
SN:9UL-00152	HRS	13972.9							
	AFL	9253							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-64-13-790-801-02S ^U		INSPECTION/HYDROSTATIC TEST NO. 2 LIFE RAFT							Service ATA:25
PN:913FAUL-J301101	MOS	15-May-23	60		15-May-28		1500 d		
SN:9UL-00396	HRS	13972.9							
	AFL	9253							
PROC. REF: GENERIC NO REF									
25-64-13-900-801-01		NO. 1 LIFE RAFT							Component ATA:25
PN:913FAUL-J301101	MOS/MSC	15-May-23	O/C						
SN:9UL-00152	HRS	13972.9							
WC#: 25.090	AFL	9253							
PROC. REF: GENERIC NO REF									
25-64-13-900-801-01		NO. 2 LIFE RAFT							Component ATA:25
PN:913FAUL-J301101	MOS/MSC	15-May-23	O/C						
SN:9UL-00396	HRS	13972.9							
WC#: 25.090	AFL	9253							
PROC. REF: GENERIC NO REF									
25-64-13-960-801-01		DISCARD OF THE LIFE RAFT - NO. 1 LIFE RAFT (15ME)							Service ATA:25
PN:913FAUL-J301101	MOS/MSC		O/C						
SN:9UL-00152	HRS								
	AFL								
PROC. REF: AMM 25-64-13-960-801									
25-64-13-960-801-01		DISCARD OF THE LIFE RAFT - NO. 2 LIFE RAFT (15ME)							Service ATA:25
PN:913FAUL-J301101	MOS/MSC		O/C						
SN:9UL-00396	HRS								
	AFL								
PROC. REF: AMM 25-64-13-960-801									
25-64-17-350-802-01		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME)							Service ATA:25
PN:P01074-101C	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:18061180092	HRS	13592.3							
WC#: 25.045	AFL	9008							
PROC. REF: AMM 25-64-17-350-802									
25-64-17-350-802-02		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME)							Service ATA:25
PN:P01074-101C	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:18061180065	HRS	13592.3							
WC#: 25.046	AFL	9008							
PROC. REF: AMM 25-64-17-350-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-802-03 RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME)								
PN:P01074-101C	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:18061180061	HRS	13592.3						
WC#: 25.047	AFL	9008						
PROC. REF: AMM 25-64-17-350-802								
25-64-17-350-803-01 RESTORATION NO. 01 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080009	HRS	13592.3						
WC#: 25.050	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION NO. 02 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080004	HRS	13592.3						
WC#: 25.050	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION NO. 03 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080008	HRS	13592.3						
WC#: 25.060	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION NO. 04 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080002	HRS	13592.3						
WC#: 25.060	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION NO. 05 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080011	HRS	13592.3						
WC#: 25.070	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION NO. 06 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL
SN:20101080014	HRS	13592.3						
WC#: 25.070	AFL	9008						
PROC. REF: AMM 25-64-17-350-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-64-17-350-803-01		RESTORATION NO. 07 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)						Service	ATA:25
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:20101080017	HRS	13592.3							
WC#: 25.080	AFL	9008							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-01		RESTORATION NO. 08 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)						Service	ATA:25
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:20101080015	HRS	13592.3							
WC#: 25.080	AFL	9008							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-01		RESTORATION NO. 09 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)						Service	ATA:25
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:20101080020	HRS	13592.3							
WC#: 25.081	AFL	9008							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-01		RESTORATION NO. 10 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)						Service	ATA:25
PN:P01074-103	MOS	05-May-22	60		05-May-27		1124 d	OVERHAUL	
SN:20101080002	HRS	13592.3							
WC#: 25.081	AFL	9008							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-01		RESTORATION NO. 11 PASSENGER LIFE VEST						Service	ATA:25
PN:P0640-103	MOS	02-Aug-21	60		02-Aug-26		848 d	OVERHAUL	
SN:B62474	HRS	12985							
WC#: 25.082	AFL	8657							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-01		RESTORATION NO. 12 PASSENGER LIFE VEST						Service	ATA:25
PN:P0640-103	MOS	02-Aug-21	60		02-Aug-26		848 d	OVERHAUL	
SN:C83812	HRS	12985							
WC#: 25.082	AFL	8657							
PROC. REF: AMM 25-64-17-350-803									
25-64-17-350-803-13		RESTORATION NO. 1 INFANT LIFE VEST (OVERHAUL OR DISCARD)						Service	ATA:25
PN:P0640-113	MOS	02-Aug-21	60		02-Aug-26		848 d	OVERHAUL	
SN:10021750007	HRS	12985							
	AFL	8657							
PROC. REF: AMM 25-64-17-350-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-64-17-900-802-01		PILOT LIFE VEST						Component	ATA:25
PN:P01074-101C	MOS/MSC	27-Nov-23	O/C	TSN 65					
SN:18061180092	HRS	14292.8		TSN 700.5					
WC#: 25.045	AFL	9471		TSN 463					
PROC. REF: GENERIC NO REF									
25-64-17-900-802-02		COPILOT LIFE VEST						Component	ATA:25
PN:P01074-101C	MOS/MSC	27-Nov-23	O/C						
SN:18061180065	HRS	14292.8							
WC#: 25.046	AFL	9471							
PROC. REF: GENERIC NO REF									
25-64-17-900-802-03		THIRD CREW MEMBER LIFE VEST						Component	ATA:25
PN:P01074-101C	MOS/MSC	27-Nov-23	O/C	TSN 65					
SN:18061180061	HRS	14292.8		TSN 700.5					
WC#: 25.047	AFL	9471		TSN 463					
PROC. REF: GENERIC NO REF									
25-64-17-900-803-01		NO. 01 PASSENGER LIFE VEST						Component	ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0	01-Oct-25 (M)		543 d		
SN:20101080009	HRS	13592.3		TSN 0					
WC#: 25.050	AFL	9008		TSN 0					
PROC. REF: GENERIC NO REF									
25-64-17-900-803-01		NO. 02 PASSENGER LIFE VEST						Component	ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0					
SN:20101080004	HRS	13592.3		TSN 0					
WC#: 25.050	AFL	9008		TSN 0					
PROC. REF: GENERIC NO REF									
25-64-17-900-803-01		NO. 03 PASSENGER LIFE VEST						Component	ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0	01-Oct-25 (M)		543 d		
SN:20101080008	HRS	13592.3		TSN 0					
WC#: 25.060	AFL	9008		TSN 0					
PROC. REF: GENERIC NO REF									
25-64-17-900-803-01		NO. 04 PASSENGER LIFE VEST						Component	ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0					
SN:20101080002	HRS	13592.3		TSN 0					
WC#: 25.060	AFL	9008		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-900-803-01		NO. 05 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0	01-Oct-25 (M)		543 d	
SN:20101080011	HRS	13592.3		TSN 0				
WC#: 25.070	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 06 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	05-May-22	O/C	TSN 0				
SN:20101080014	HRS	13592.3		TSN 0				
WC#: 25.070	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 07 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	05-May-22	O/C	TSN 0				
SN:20101080017	HRS	13592.3		TSN 0				
WC#: 25.080	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 08 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	05-May-22	O/C	TSN 0				
SN:20101080015	HRS	13592.3		TSN 0				
WC#: 25.080	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 09 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	01-Oct-20	O/C	TSN 0				
SN:20101080020	HRS	13592.3		TSN 0				
WC#: 25.081	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 10 PASSENGER LIFE VEST						Component ATA:25
PN:P01074-103	MOS/MSC	05-May-22	O/C	TSN 0				
SN:20101080002	HRS	13592.3		TSN 0				
WC#: 25.081	AFL	9008		TSN 0				
PROC. REF: GENERIC NO REF								
25-64-17-900-803-01		NO. 11 PASSENGER LIFE VEST						Component ATA:25
PN:P0640-103	MOS/MSC	28-Nov-14	O/C	TSO 0				
SN:B62474	HRS	3368		TSO 0				
WC#: 25.082	AFL	2336		TSO 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
25-64-17-900-803-01		NO. 12 PASSENGER LIFE VEST							Component ATA:25
PN:P0640-103	MOS/MSC	10-Sep-15	O/C		TSO 1				
SN:C83812	HRS	10489.8			TSO 0				
WC#: 25.082	AFL	7089			TSO 0				
PROC. REF: GENERIC NO REF									
25-64-17-900-804-01		NO. 1 INFANT LIFE VEST							Component ATA:25
PN:P0640-113	MOS/MSC	02-Aug-21	O/C						
SN:10021750007	HRS	12985							
	AFL	8657							
PROC. REF: GENERIC NO REF									
25-90-01-900-801-03		THIRD CREW MEMBER SEAT							Component ATA:25
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
25-90-11-200-801-01S ^{U S}		INSPECTION OF THE DRAWER SLIDE ASSEMBLY(S)							Service ATA:25
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: SMM 25-90-11									
25-90-19-900-801-01		MICROWAVE OVEN							Component ATA:25
PN:R26ST	MOS/MSC	03-Jan-18	O/C		TSN 0				
SN:080873512	HRS	11613.8			TSN 0				
	AFL				TSN 0				
PROC. REF: AMM 25-33-00-900-801									
251811		PILOT SEAT ACTUATOR							Component ATA:25
PN:142500-1	MOS/MSC	23-Oct-07	O/C		TSN 0				
SN:UNKNOWN	HRS	5738.8			TSN 0				
WC#: 25.030	AFL	3854			TSN 0				
PROC. REF: AMM 25-11-13-900-801									
251812		COPILOT SEAT ACTUATOR							Component ATA:25
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 25.030	AFL	0			TSN 0				
PROC. REF: AMM 25-11-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
253A00 ^U		MED-AIR FIRST AID KIT						Component	ATA:25
PN:AFAK 1.0	MOS/MSC	28-Mar-23	O/C	TSO 0				CUSTOMER CODE	
SN:032012023	HRS	13908.8		TSO 0					
	AFL	9201		TSO 0					
253A01 ^U		RESTORE MED-AIR FIRST AID KIT						Service	ATA:25
PN:AFAK 1.0	MOS	28-Mar-23	12		28-Mar-24		OVD		
SN:032012023	HRS	13908.8							
	AFL	9201							
256E01 ^U		RENEW ELT BEACON NOAA 406 MHZ REGISTRATION						Service	ATA:25
	MOS	01-Mar-00	24		25-May-25 (M)		414 d		
	HRS	0							
	AFL	0							
256E03 ^U		REGISTRATION NO. 3 ELT BEACON NOAA 406 MHZ						Service	ATA:25
	MOS		24		25-May-25 (M)		414 d		
	HRS								
	AFL								
256E04 ^U		REGISTRATION NO. 2 ELT BEACON NOAA 406 MHZ						Service	ATA:25
	MOS	25-May-23	24		25-May-25		414 d		
	HRS	14292.8							
	AFL	9471							
256K01 ^U		FIRST AID KIT						Component	ATA:25
PN:500939	MOS/MSC	28-Mar-22	O/C						
SN:032012023	HRS	13540.6							
	AFL	8975							
256K06 ^U		INSPECT/RECERTIFY FIRST AID KIT						Service	ATA:25
PN:500939	MOS	02-May-23	12		02-May-24		26 d		
SN:032012023	HRS	13952.4							
	AFL	9231							
259A06 ^U		COCKPIT VOICE RECORDER CONTROL BOX						Component	ATA:25
PN:F2MA600313110B2	MOS/MSC	08-Feb-17	O/C	TSR 5					
SN:86	HRS	10863.8							
	AFL	7323							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
33-50-05-350-802-02		RESTORATION OF THE MAGLITE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (R702LC)						Service	ATA:25
PN:P2-07-0011-500	MOS/MSC	N/A							
SN:061123021	HRS								
	AFL								
PROC. REF: AMM 33-50-05-350-802, SMM 25-90-43									
ATA 26 - FIRE PROTECTION									
26-10-00-720-801-01		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L5WG)						Service	ATA:26
PN:360112290040017	MOS	16-Apr-13							
SN:244858	HRS	9087.6	7500 (+3%)		16587.6	16812.6	2233.2 (+225)		
WC#: 26.010	AFL	6131							
PROC. REF: AMM 26-10-00-720-801									
26-10-00-720-801-02		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (R5WG)						Service	ATA:26
PN:360112290040017	MOS	27-Aug-18							
SN:270902-270906	HRS	11709.3	7500 (+3%)		19209.3	19434.3	4854.9 (+225)		
WC#: 26.010	AFL	7915							
PROC. REF: AMM 26-10-00-720-801									
26-10-00-720-801-03		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - APU FIRE DETECTOR (10WG)						Service	ATA:26
PN:PN	MOS	22-Nov-13							
SN:UNKNOWN	HRS	9419.6							
WC#: 26.020	AFL	6356							
	APH	8265	5000 (+3%)	Adj 3125.02	16390.02	16540.02	4451 (+150)		
PROC. REF: AMM 26-10-00-720-801									
26-10-17-720-801-01 ^S		FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - LH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR (L110WG)						Service	ATA:26
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
PROC. REF: AMM 26-10-17-720-801									
26-10-17-720-801-01A		FUNCTIONAL TEST OF THE LH MAIN LANDING GEAR COMPARTMENT PIN POINT FIRE DETECTOR (MANDATORY 5-40)						Service	ATA:26
	MOS	05-May-22							
	HRS	13592.3	20000		33592.3		19237.9	MANDATORY 5-40	
	AFL	9008							
PROC. REF: AMM 26-10-17-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-10-17-720-801-02 ^S	FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - RH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR (R110WG)							Service	ATA:26
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
PROC. REF: AMM 26-10-17-720-801								PKG:22	
26-10-17-720-801-02A	FUNCTIONAL TEST OF THE RH MAIN LANDING GEAR COMPARTMENT PIN POINT FIRE DETECTOR (MANDATORY 5-40)							Service	ATA:26
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	20000		33592.3		19237.9		
	AFL	9008							
PROC. REF: AMM 26-10-17-720-801									
26-10-19-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L5WG)							Component	ATA:26
PN:360112290040017	MOS/MSC	17-May-12	O/C						
SN:244858	HRS	8600.3							
WC#: 26.010	AFL	5785							
PROC. REF: AMM 26-10-19-900-801									
26-10-19-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (R5WG)							Component	ATA:26
PN:360112290040017	MOS/MSC	16-Aug-18	O/C	TSN 0					
SN:270902-270906	HRS	11709.3		TSN 0					
WC#: 26.010	AFL	7915		TSN 0					
PROC. REF: AMM 26-10-19-900-801									
26-10-19-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - APU FIRE DETECTOR (10WG)							Component	ATA:26
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.020	AFL	0		TSN 0					
PROC. REF: AMM 26-10-19-900-801									
26-10-19-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - LH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR (L110WG)							Component	ATA:26
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.050	AFL	0		TSN 0					
PROC. REF: AMM 26-10-19-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-10-19-900-801-05	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - RH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR (R110WG)							Component	ATA:26
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 26.050	AFL	0	TSN 0						
PROC. REF: AMM 26-10-19-900-801									
26-10-21-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR - SMOKE DETECTOR (210WG)							Component	ATA:26
PN:DF2220	MOS/MSC	20-May-16	O/C	TSR 2					
SN:580	HRS	10730.7	TSR 0						
WC#: 26.030	AFL	7258	TSR 0						
PROC. REF: AMM 26-10-21-900-801									
26-10-29-720-801-01 ^S	FUNCTIONAL TEST OF THE OVERHEAT PROBE - OVERHEAT PROBE (120WG)							Service	ATA:26
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 26.170	AFL	9008							
PROC. REF: AMM 26-10-29-720-801									
26-20-00-760-801-01	INSULATION TEST OF APU AND ENGINE EXTINGUISHER PERCUSSION CIRCUITS - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L10WB)							Service	ATA:26
PN:861375	MOS/MSC	16-Jul-19	O/C						
SN:UNKNOWN	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 26-20-00-760-801									
26-20-00-760-801-02	INSULATION TEST OF APU AND ENGINE EXTINGUISHER PERCUSSION CIRCUITS - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (R10WB)							Service	ATA:26
PN:861375	MOS/MSC	02-May-23	O/C						
SN:NSN	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 26-20-00-760-801									
26-20-00-760-801-03	INSULATION TEST OF APU AND ENGINE EXTINGUISHER PERCUSSION CIRCUITS - APU PERCUSSION CARTRIDGE (11WB)							Service	ATA:26
PN:861375	MOS/MSC	02-May-23	O/C						
SN:NSN	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 26-20-00-760-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-00-760-801-04	INSULATION TEST OF APU AND ENGINE EXTINGUISHER PERCUSSION CIRCUITS - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (L20WB)							Service	ATA:26
PN:861385	MOS/MSC	14-Jan-21	O/C						
SN:NSN	HRS								
	AFL								
PROC. REF: AMM 26-20-00-760-801									
26-20-00-760-801-05	INSULATION TEST OF APU AND ENGINE EXTINGUISHER PERCUSSION CIRCUITS - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (R20WB)							Service	ATA:26
PN:M861385	MOS/MSC	06-Dec-23	O/C						
SN:NA	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 26-20-00-760-801									
26-20-01-760-801-01 ^S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH 1" SWITCH/LIGHT (310WG4)							Service	ATA:26
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 26.080	AFL	7947	3750						
PROC. REF: AMM 26-20-01-760-801									
26-20-01-760-801-02 ^S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH 2" SWITCH/LIGHT (310WG5)							Service	ATA:26
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 26-20-01-760-801									
26-20-01-760-801-03 ^S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH 1" SWITCH/LIGHT (310WG11)							Service	ATA:26
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 26.090	AFL	7947	3750						
PROC. REF: AMM 26-20-01-760-801									
26-20-01-760-801-04 ^S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH 2" SWITCH/LIGHT (310WG12)							Service	ATA:26
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 26-20-01-760-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-01-760-801-05^S CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - APU "DISCH 1" SWITCH/LIGHT (310WG8)								
	MOS	16-Jul-19	72 (+2m)					Service ATA:26
	HRS	11761.3						
WC#: 26.100	AFL	7947	3750					
PROC. REF: AMM 26-20-01-760-801						PKG:31		
26-20-01-900-801-01 REMOVAL / INSTALLATION OF THE FIRE CONTROL PANEL - FIRE CONTROL PANEL (310WG)								
PN:6100-02	MOS/MSC	29-Aug-18	O/C					Component ATA:26
SN:147	HRS							
WC#: 26.060	AFL							
PROC. REF: AMM 26-20-01-900-801								
26-20-09-220-801-01 WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (L30WB)								
PN:861630	MOS	02-May-23	12 (+1m)		02-May-24	02-Jun-24	26 d (+31)	Service ATA:26
SN:25784	HRS							
WC#: 26.080	AFL							
PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-02 WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (R30WB)								
PN:861630	MOS	02-May-23	12 (+1m)		02-May-24	02-Jun-24	26 d (+31)	Service ATA:26
SN:55415	HRS							
WC#: 26.090	AFL							
		WeightCheck Date : 02-May-23						PROC. REF: AMM 26-20-09-220-801
26-20-09-220-801-03 WEIGHING OF THE FIRE EXTINGUISHERS - APU FIRE EXTINGUISHER (35WB)								
PN:861630	MOS	02-May-23	12 (+1m)		02-May-24	02-Jun-24	26 d (+31)	Service ATA:26
SN:53916	HRS							
WC#: 26.100	AFL							
PROC. REF: AMM 26-20-09-220-801								
26-20-09-350-801-01 RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE FIRE EXTINGUISHER (L30WB)								
PN:861630	MOS	16-Jul-19	60		16-Jul-24		101 d	Service ATA:26
SN:25784	HRS							MANDATORY
WC#: 26.080	AFL							
PROC. REF: AMM 26-20-09-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-09-350-801-02	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE FIRE EXTINGUISHER (R30WB)							Service	ATA:26
PN:861630	MOS	01-Dec-21	60		01-Dec-26 (M)		969 d	MANDATORY	
SN:55415	HRS								
WC#: 26.090	AFL								
PROC. REF: AMM 26-20-09-350-801									
26-20-09-350-801-03	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU FIRE EXTINGUISHER (35WB)							Service	ATA:26
PN:861630	MOS	16-Jul-19	60		16-Jul-24		101 d	MANDATORY	
SN:53916	HRS								
WC#: 26.100	AFL								
PROC. REF: AMM 26-20-09-350-801									
26-20-09-900-801-01	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (L30WB)							Component	ATA:26
PN:861630	MOS/MSC	02-May-23	H/T	TSO 117					
SN:25784	HRS	13952.4		TSO 4688.9					
WC#: 26.080	AFL	9231		TSO 2978					
PROC. REF: AMM 26-20-09-900-801									
26-20-09-900-801-02	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE FIRE EXTINGUISHER (R30WB)							Component	ATA:26
PN:861630	MOS/MSC	02-May-23	H/T	TSO 66					
SN:55415	HRS	13952.4		TSO 2842.9					
WC#: 26.090	AFL	9231		TSO 1743					
PROC. REF: AMM 26-20-09-900-801									
26-20-09-900-801-03	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - APU FIRE EXTINGUISHER (35WB)							Component	ATA:26
PN:861630	MOS/MSC	02-May-23	H/T						
SN:53916	HRS	13952.4							
WC#: 26.100	AFL	9231							
PROC. REF: AMM 26-20-09-900-801									
26-20-12-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L40WB)							Component	ATA:26
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.130	AFL	0		TSN 0					
PROC. REF: AMM 26-20-12-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-12-900-801-02		REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 2 SHUTTLE VALVE (R40WB)					Component	ATA:26	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.130	AFL	0		TSN 0					
PROC. REF: AMM 26-20-12-900-801									
26-20-12-960-801-01		DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L40WB)					Service	ATA:26	
PN:PN	MOS/MSC	01-Mar-00	A/R					REPLACE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 26-20-12-960-801									
26-20-12-960-801-02		DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 2 SHUTTLE VALVE (R40WB)					Service	ATA:26	
PN:PN	MOS/MSC	01-Mar-00	A/R					REPLACE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 26-20-12-960-801									
26-20-13-900-802-01		REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L10WB)					Component	ATA:26	
PN:861375	MOS/MSC	02-May-23	H/T						
SN:UNKNOWN	HRS	13952.4							
	AFL	9231							
PROC. REF: AMM 26-20-13-900-802									
26-20-13-900-802-02		REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (R10WB)					Component	ATA:26	
PN:861375	MOS/MSC	02-May-23	H/T	TSN 0					
SN:NSN	HRS	13952.4		TSN 0					
	AFL	9231		TSN 0					
PROC. REF: AMM 26-20-13-900-802									
26-20-13-900-802-03		REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (L20WB)					Component	ATA:26	
PN:861385	MOS/MSC	14-Jan-21	H/T	TSN 0					
SN:NSN	HRS			TSN 0					
	AFL	8426		TSN 0					
PROC. REF: AMM 26-20-13-900-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-13-900-802-04		REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (R20WB)					Component	ATA:26	
PN:M861385	MOS/MSC	06-Dec-23	H/T	TSN 0					
SN:NA	HRS	14292.8		TSN 0					
	AFL	9471		TSN 0					
PROC. REF: AMM 26-20-13-900-802									
26-20-13-900-802-05		REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (11WB)					Component	ATA:26	
PN:861375	MOS/MSC	02-May-23	H/T	TSN 0					
SN:NSN	HRS	13952.4		TSN 0					
	AFL	9231		TSN 0					
PROC. REF: AMM 26-20-13-900-802									
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L10WB)					Service	ATA:26	
PN:861375	MOS	16-Jul-19	60		16-Jul-24		101 d	SCRAP	
SN:UNKNOWN	HRS								
WC#: 26.080	AFL								
PROC. REF: AMM 26-20-13-960-801									
26-20-13-960-801-01M		DISCARD NO. 1 ENGINE FIRST-SHOOT PERCUSSION RED (L10WB) CARTRIDGE (LIFE LIMIT)					Service	ATA:26	
PN:861375	MOS	01-Oct-18	84		01-Oct-25		543 d	LIFE LIMIT	
SN:UNKNOWN	HRS								
WC#: 26.080	AFL								
PROC. REF: AMM 26-20-13-960-801									
26-20-13-960-801-02		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (R10WB)					Service	ATA:26	
PN:861375	MOS	02-May-23	60		02-May-28		1487 d	SCRAP	
SN:NSN	HRS								
WC#: 26.090	AFL								
PROC. REF: AMM 26-20-13-960-801									
26-20-13-960-801-02M		DISCARD NO. 1 ENGINE SECOND-SHOOT PERCUSSION RED (R10WB) CARTRIDGE (LIFE LIMIT)					Service	ATA:26	
PN:861375	MOS	31-Dec-21	84		31-Dec-28		1730 d	LIFE LIMIT	
SN:NSN	HRS								
WC#: 26.090	AFL								
PROC. REF: AMM 26-20-13-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-03 DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (L20WB) Service ATA:26								
PN:861385	MOS	14-Jan-21	60		14-Jan-26		648 d	SCRAP
SN:NSN	HRS							
WC#: 26.080	AFL							
Installation Date: : 14-Jan-21 PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-03M DISCARD NO. 2 ENGINE SECOND-SHOOT PERCUSSION GREEN (L20WB) CARTRIDGE (LIFE LIMIT) Service ATA:26								
PN:861385	MOS	22-Apr-20	84		22-Apr-27		1111 d	LIFE LIMIT
SN:NSN	HRS							
WC#: 26.080	AFL							
Manufacture Date:: 22-Apr-20 PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-04 DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (R20WB) Service ATA:26								
PN:M861385	MOS	06-Dec-23	60		06-Dec-28		1705 d	SCRAP
SN:NA	HRS							
WC#: 26.090	AFL							
PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-04M DISCARD NO. 2 ENGINE FIRST-SHOOT PERCUSSION GREEN (R20WB) CARTRIDGE (LIFE LIMIT) Service ATA:26								
PN:M861385	MOS	07-Sep-18	84		07-Sep-25		519 d	LIFE LIMIT
SN:NA	HRS							
WC#: 26.090	AFL							
PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-05 DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (11WB) Service ATA:26								
PN:861375	MOS	02-May-23	60		02-May-28		1487 d	SCRAP
SN:NSN	HRS							
WC#: 26.100	AFL							
PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-05M DISCARD APU PERCUSSION RED (11WB) CARTRIDGE (LIFE LIMIT) Service ATA:26								
PN:861375	MOS	31-Dec-21	84		31-Dec-28		1730 d	LIFE LIMIT
SN:NSN	HRS							
WC#: 26.100	AFL							
PROC. REF: AMM 26-20-13-960-801								
26-20-15-720-801-01 WEIGH COCKPIT PORTABLE EXTINGUISHER Service ATA:26								
PN:898052	MOS	15-Sep-22	24 (+3%)		15-Sep-24	06-Oct-24	162 d (+21)	
SN:A30842796	HRS							
	AFL							
PROC. REF: AMM 26-20-15-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-15-720-801-02		WEIGH FORWARD EXTINGUISHER						Service	ATA:26
PN:898052	MOS	15-Sep-22	24 (+3%)		15-Sep-24	06-Oct-24	162 d (+21)		
SN:X-456906	HRS								
	AFL								
PROC. REF: AMM 26-20-15-720-801									
26-20-15-720-801-03		WEIGH AFT CABIN EXTINGUISHER						Service	ATA:26
PN:898052	MOS	15-Sep-22	24 (+3%)		15-Sep-24	06-Oct-24	162 d (+21)		
SN:Y-626151	HRS								
	AFL								
PROC. REF: AMM 26-20-15-720-801									
26-20-15-720-801-04		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - PORTABLE FIRE EXTINGUISHER 4 (110WB4)						Service	ATA:26
PN:PN	MOS/MSC	01-Mar-00	N/A						
SN:UNKNOWN	HRS	0							
WC#: 26.160	AFL	0							
PROC. REF: AMM 26-20-15-720-801									
26-20-15-790-801-01		HYDROSTATIC TEST COCKPIT PORTABLE EXTINGUISHER						Service	ATA:26
PN:898052	MOS	24-Feb-21	144 (+3%)		24-Feb-33	03-Jul-33	3246 d (+129)		
SN:A30842796	HRS								
	AFL								
PROC. REF: AMM 26-20-15-790-801									
26-20-15-790-801-02		HYDROSTATIC TEST FORWARD EXTINGUISHER						Service	ATA:26
PN:898052	MOS	15-Sep-22	144 (+3%)		15-Sep-34	24-Jan-35	3814 d (+131)		
SN:X-456906	HRS								
	AFL								
PROC. REF: AMM 26-20-15-790-801									
26-20-15-790-801-03		HYDROSTATIC TEST AFT CABIN EXTINGUISHER						Service	ATA:26
PN:898052	MOS	01-Feb-15	144 (+3%)		01-Feb-27	10-Jun-27	1031 d (+129)		
SN:Y-626151	HRS								
	AFL								
PROC. REF: AMM 26-20-15-790-801									
26-20-15-790-801-04		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - PORTABLE FIRE EXTINGUISHER 4 (110WB4)						Service	ATA:26
PN:PN	MOS/MSC	01-Mar-00	N/A						
SN:UNKNOWN	HRS	0							
WC#: 26.160	AFL	0							
PROC. REF: AMM 26-20-15-790-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
26-20-19-720-801-01		WEIGHING OF THE DISPOSABLE FIRE EXTINGUISHER - DISPOSABLE FIRE EXTINGUISHER (L7513ME)							Service ATA:26
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 26-20-19-720-801, SMM 26-90-01									
26-90-01-900-801-01		DISPOSABLE FIRE EXTINGUISHER							Component ATA:26
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: GENERIC NO REF									
262081		FORWARD EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	15-Sep-22	H/T		TSN 171				
SN:X-456906	HRS	13776.5			TSN 3516.7				
	AFL	9117			TSN 2186				
PROC. REF: GENERIC NO REF									
262082		AFT CABIN EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	15-Sep-22	H/T		TSN 107, TSR 77				
SN:Y-626151	HRS	13776.5			TSN 3286.7, TSR 3045.8				
	AFL	9117			TSN 2028, TSR 1859				
PROC. REF: GENERIC NO REF									
262083		COCKPIT PORTABLE EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	15-Sep-22	H/T		TSN 91				
SN:A30842796	HRS	13776.5							
	AFL	9117							
PROC. REF: GENERIC NO REF									
262084		PORTABLE FIRE EXTINGUISHER NO. 4 (110WB4)							Component ATA:26
PN:PN	MOS/MSC	01-Mar-00	N/A		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 26.160	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
ATA 27 - FLIGHT CONTROLS									
27-00-00-220-801-01A		INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY 5-40)							Service ATA:27
	MOS	27-Dec-23						MANDATORY 5-40	
	HRS	14292.8	4000		18292.8		3938.4		
WC#: 27.495	AFL	9471							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
PROC. REF: AMM 27-00-00-220-801									
27-00-00-640-801-01 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - LH AILERON SERVO-ACTUATOR (30CR)							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-801									
PKG:32									
27-00-00-640-801-02 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (40CR)							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-801									
PKG:32									
27-00-00-640-801-03 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (10CL)							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.025	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-801									
PKG:32									
27-00-00-640-801-04 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (10CP)							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.025	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-801									
PKG:32									
27-00-00-640-802-01 ^S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS - IN PRESSURIZED AREA							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.030	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-802									
PKG:32									
27-00-00-640-802-02 ^S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS - IN NON-PRESSURIZED AREA							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.030	AFL	6131	7500						
PROC. REF: AMM 27-00-00-640-802									
PKG:32									
27-00-00-640-805-01 ^U	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION							Service	ATA:27
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 27.045	AFL	6131							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-00-00-640-805-02 ^U	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR GREASING OF BEARINGS							Service	ATA:27
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 27.045	AFL	6131							
27-00-00-640-805-03 ^S	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - INSPECTION AND GREASING OF BEARINGS OF THE LH ROLL PRESSURE SEALED BOX							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-640-805								PKG:32
27-00-00-640-805-04 ^S	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - INSPECTION AND GREASING OF BEARINGS OF THE RH ROLL PRESSURE SEALED BOX							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-640-805								PKG:32
27-00-00-640-805-05 ^S	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - INSPECTION AND GREASING OF BEARINGS OF THE YAW PRESSURE SEALED BOX							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-640-805								PKG:32
27-00-00-640-805-06 ^S	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - INSPECTION AND GREASING OF BEARINGS OF THE PITCH PRESSURE SEALED BOX							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-640-805								PKG:32
27-00-00-710-801-01 ^S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 1							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.005	AFL	9008							
	PROC. REF: AMM 27-00-00-710-801								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-00-00-710-801-01A	OPERATIONAL TEST NO. 1 OF THE HYDRAULIC SYSTEM 1 FLIGHT CONTROLS (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1650		15242.3		887.9		
WC#: 27.005	AFL	9008							
PROC. REF: AMM 27-00-00-710-801									
27-00-00-710-801-02 ^S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 2							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.005	AFL	9008							
PROC. REF: AMM 27-00-00-710-801									
27-00-00-710-801-02A	OPERATIONAL TEST NO. 2 OF THE HYDRAULIC SYSTEM 2 FLIGHT CONTROLS (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1650		15242.3		887.9		
WC#: 27.005	AFL	9008							
PROC. REF: AMM 27-00-00-710-801									
27-00-00-710-802-01 ^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL TRIM							Service	ATA:27
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 27.010	AFL	7947	3750						
PROC. REF: AMM 27-00-00-710-802									
27-00-00-710-802-02 ^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL EMERGENCY TRIM							Service	ATA:27
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 27.010	AFL	7947	3750						
PROC. REF: AMM 27-00-00-710-802									
27-00-00-710-802-03 ^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - YAW TRIM							Service	ATA:27
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 27.010	AFL	7947	3750						
PROC. REF: AMM 27-00-00-710-802									
27-00-00-710-803-01	OPERATIONAL TEST OF THE SERVO-ACTUATOR ACCUMULATOR MONITORING LOGIC							Service	ATA:27
	MOS	07-Feb-24	12 (+1m)		07-Feb-25	07-Mar-25	307 d (+28)		
	HRS	14354.4	400 (+40)		14754.4	14794.4	400 (+40)		
WC#: 27.455	AFL	9502							
PROC. REF: AMM 27-00-00-710-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-00-00-720-804-01 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								PKG:32
27-00-00-720-804-01A	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU (MANDATORY 5-40)							Service	ATA:27
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	10000		19087.6		4733.2		
	AFL	6131							
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-02 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - FUNCTIONAL TEST OF LH ROLL AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								PKG:32
27-00-00-720-804-03 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								PKG:32
27-00-00-720-804-03A	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU (MANDATORY 5-40)							Service	ATA:27
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	10000		19087.6		4733.2		
	AFL	6131							
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-04 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - FUNCTIONAL TEST OF RH ROLL AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								PKG:32
27-00-00-720-804-05 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF YAW AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-00-00-720-804-05A	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF YAW AAFU (MANDATORY 5-40)							Service	ATA:27
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	10000		19087.6		4733.2		
	AFL	6131							
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-06 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - FUNCTIONAL TEST OF YAW AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-07 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF PITCH AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-07A	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - INSPECTION OF PITCH AAFU (MANDATORY 5-40)							Service	ATA:27
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	10000		19087.6		4733.2		
	AFL	6131							
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-720-804-08 ^S	CHECK OF THE AUXILIARY AFU'S FOR NON-DISCONNECTION - FUNCTIONAL TEST OF PITCH AAFU							Service	ATA:27
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
	PROC. REF: AMM 27-00-00-720-804								
27-00-00-790-803-01 ^S	CHECK OF THE SERVO-ACTUATOR INTERNAL DAMPING - LH AILERON SERVO-ACTUATOR (30CR)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								
27-00-00-790-803-01A	CHECK OF THE LH AILERON SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-00-00-790-803-02 ^S	CHECK OF THE SERVO-ACTUATOR INTERNAL DAMPING - RH AILERON SERVO-ACTUATOR (40CR)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								PKG:21
27-00-00-790-803-02A	CHECK OF THE RH AILERON SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								
27-00-00-790-803-03 ^S	CHECK OF THE SERVO-ACTUATOR INTERNAL DAMPING - RUDDER SERVO-ACTUATOR (10CL)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.035	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								PKG:21
27-00-00-790-803-03A	CHECK RUDDER SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
WC#: 27.035	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								
27-00-00-790-803-04 ^S	CHECK OF THE SERVO-ACTUATOR INTERNAL DAMPING - ELEVATOR SERVO-ACTUATOR (10CP)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.035	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								PKG:21
27-00-00-790-803-04A	CHECK ELEVATOR SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
WC#: 27.035	AFL	9008							
	PROC. REF: AMM 27-00-00-790-803, AMM 27-00-00-790-803								
27-12-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (30CR)							Component	ATA:27
PN:103151-03	MOS/MSC	19-Aug-11	O/C						
SN:248	HRS	8123							
WC#: 27.130	AFL	5461							
	PROC. REF: AMM 27-12-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-12-01-900-801-02		REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (40CR)					Component	ATA:27	
PN:103151-04	MOS/MSC	10-Mar-21	O/C						
SN:227	HRS	12694							
WC#: 27.130	AFL	8476							
PROC. REF: AMM 27-12-01-900-801									
27-13-01-640-806-01 ^S		LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA - LH WING					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-13-01-640-806									
PKG:31									
27-13-01-640-806-02 ^S		LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA - RH WING					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-13-01-640-806									
PKG:31									
27-13-01-640-807-01 ^S		GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-13-01-640-807									
PKG:31									
27-13-01-640-808-01 ^S		GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA - LH WING					Service	ATA:27	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 27-13-01-640-808									
PKG:16									
27-13-01-640-808-02 ^S		GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA - RH WING					Service	ATA:27	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 27-13-01-640-808									
PKG:16									
27-14-01-350-801-01		RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (60CR)					Service	ATA:27	
PN:021057-37	MOS	16-Apr-13	144 (+3%)		16-Apr-25	25-Aug-25	375 d (+131)		
SN:8961	HRS	9087.6							
WC#: 27.105	AFL	6131							
PROC. REF: AMM 27-14-01-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-14-01-900-801-01		REMOVAL / INSTALLATION OF THE ROLL TRIM ACTUATOR - ROLL TRIM ACTUATOR (60CR)					Component	ATA:27	
PN:021057-37	MOS/MSC	16-Apr-13	O/C	TSR 0					
SN:8961	HRS	9087.6		TSR 0					
WC#: 27.105	AFL	6131		TSR 0					
PROC. REF: AMM 27-14-01-900-801									
27-14-03-350-801-01		RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (95CR)					Service	ATA:27	
PN:021127-01	MOS	16-Apr-13	144 (+3%)		16-Apr-25	25-Aug-25	375 d (+131)		
SN:715	HRS	9087.6							
WC#: 27.110	AFL	6131							
PROC. REF: AMM 27-14-03-350-801									
27-14-03-900-801-01		REMOVAL / INSTALLATION OF THE EMERGENCY ROLL TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (95CR)					Component	ATA:27	
PN:021127-01	MOS/MSC	16-Apr-13	O/C						
SN:715	HRS	9087.6		TSN 9561					
WC#: 27.110	AFL	6131		TSN 5849					
PROC. REF: AMM 27-14-03-900-801									
27-14-05-720-801-01 ^S		FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS - ROLL TRIM RELAY BOX (502CR)					Service	ATA:27	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.095	AFL	6131	7500						
PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801									
27-14-05-720-801-01A		FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS (MANDATORY 5-40)					Service	ATA:27	
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	20000		29087.6		14733.2		
WC#: 27.095	AFL	6131							
PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801									
27-15-01-640-801-01 ^S		PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS					Service	ATA:27	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.090	AFL	6131	7500						
PROC. REF: AMM 27-15-01-640-801									
27-15-01-720-801-01 ^S		FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (50CR)					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 27.090	AFL	7947	3750						
PROC. REF: AMM 27-15-01-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-15-01-900-801-01		REMOVAL / INSTALLATION OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (50CR)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.090	AFL	0		TSN 0					
PROC. REF: AMM 27-15-01-900-801									
27-15-05-350-801-01		RESTORATION OF THE ROLL MAIN AFU (FUNCTIONAL TEST / SERVICING) - ROLL MAIN AFU (65CR)					Service	ATA:27	
PN:105124	MOS	06-Dec-12	144 (+3%)		06-Dec-24	15-Apr-25	244 d (+130)		
SN:391	HRS								
WC#: 27.115	AFL								
PROC. REF: AMM 27-15-05-350-801									
27-15-05-900-801-01		REMOVAL / INSTALLATION OF THE ROLL MAIN AFU - ROLL MAIN AFU (65CR)					Component	ATA:27	
PN:105124	MOS/MSC	16-Apr-13	O/C	TSR 0					
SN:391	HRS	9087.6		TSN 9561, TSR 0					
WC#: 27.115	AFL	6131		TSN 5849, TSR 0					
PROC. REF: AMM 27-15-05-900-801									
27-15-07-640-801-01 ^S		PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L66CR)					Service	ATA:27	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.480	AFL	6131	7500						
PROC. REF: AMM 27-15-07-640-801									
27-15-07-640-801-02 ^S		PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R66CR)					Service	ATA:27	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
PROC. REF: AMM 27-15-07-640-801									
27-15-07-900-801-01		LH ROLL (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.120	AFL	0		TSN 0					
PROC. REF: AMM 27-15-07-900-801									
27-15-07-900-801-01		RH ROLL (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.120	AFL	0		TSN 0					
PROC. REF: AMM 27-15-07-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-22-01-900-801-01		REMOVAL / INSTALLATION OF THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (10CL)					Component	ATA:27	
PN:103145-01	MOS/MSC	04-May-17	O/C	TSR 0					
SN:147	HRS	10936.2		TSR 0					
WC#: 27.170	AFL	7365		TSR 0					
PROC. REF: AMM 27-22-01-900-801									
27-23-01-640-806-01 ^S		LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-23-01-640-806									
PKG:31									
27-23-01-640-807-01 ^S		GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-23-01-640-807									
PKG:31									
27-23-01-640-808-01 ^S		GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA					Service	ATA:27	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 27-23-01-640-808									
PKG:16									
27-24-01-350-801-01		RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (30CL)					Service	ATA:27	
PN:021057-36	MOS	02-May-23	144 (+3%)		02-May-35	11-Sep-35	4043 d (+132)		
SN:15196	HRS	13952.4							
WC#: 27.170	AFL	9231							
PROC. REF: AMM 27-24-01-350-801									
27-24-01-900-801-01		REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW MAIN AFU (15CL)					Component	ATA:27	
PN:105125-01	MOS/MSC	16-Apr-13	O/C	TSR 0					
SN:416	HRS	9087.6		TSR 0					
WC#: 27.165	AFL	6131		TSR 0					
PROC. REF: AMM 27-24-01-900-801									
27-24-01-900-801-02		REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW TRIM ACTUATOR (30CL)					Component	ATA:27	
PN:021057-36	MOS/MSC	02-May-23	O/C						
SN:15196	HRS	13952.4							
WC#: 27.170	AFL	9231							
PROC. REF: AMM 27-24-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-24-05-720-802-01^S FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS								
	MOS	16-Apr-13	144 (+2m)					Service ATA:27
	HRS	9087.6						
WC#: 27.160	AFL	6131	7500					
PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802								PKG:32
27-24-05-720-802-01A FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS (MANDATORY 5-40)								
	MOS	16-Apr-13						Service ATA:27
	HRS	9087.6	20000		29087.6		14733.2	MANDATORY 5-40
WC#: 27.160	AFL	6131						
PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802								
27-25-05-350-801-01 RESTORATION OF THE YAW MAIN AFU (FUNCTIONAL TEST / SERVICING) - YAW MAIN AFU (15CL)								
PN:105125-01	MOS	10-Oct-12	144 (+3%)		10-Oct-24	18-Feb-25	187 d (+131)	Service ATA:27
SN:416	HRS							
WC#: 27.165	AFL							
PROC. REF: AMM 27-25-05-350-801								
27-25-07-350-801-01 RESTORATION OF THE YAW AUXILIARY AFU (FUNCTIONAL TEST / SERVICING) - YAW AAFU (20CL)								
PN:105070-06	MOS	16-Apr-13	144 (+3%)		16-Apr-25	25-Aug-25	375 d (+131)	Service ATA:27
SN:1257	HRS	9087.6						
WC#: 27.165	AFL	6131						
PROC. REF: AMM 27-25-07-350-801								
27-25-07-900-801-01 REMOVAL / INSTALLATION OF THE YAW AUXILIARY AFU - YAW AAFU (20CL)								
PN:105070-06	MOS/MSC	16-Apr-13	O/C	TSR 0				Component ATA:27
SN:1257	HRS	9087.6		TSR 0				
WC#: 27.165	AFL	6131		TSR 0				
PROC. REF: AMM 27-25-07-900-801								
27-31-01-640-801-01^S GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (10CR)								
	MOS	16-Apr-13	144 (+2m)					Service ATA:27
	HRS	9087.6						
	AFL	6131	7500					
PROC. REF: AMM 27-31-01-640-801								PKG:32
27-31-01-640-801-02^S GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (20CR)								
	MOS	16-Apr-13	144 (+2m)					Service ATA:27
	HRS	9087.6						
	AFL	6131	7500					
PROC. REF: AMM 27-31-01-640-801								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-31-01-900-801-01		REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (10CR)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.125	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01-900-801									
27-31-01-900-801-02		REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (20CR)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.125	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01-900-801									
27-32-01-900-801-01		REMOVAL / INSTALLATION OF THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (10CP)					Component	ATA:27	
PN:103144-02	MOS/MSC	16-Apr-13	O/C	TSR 0					
SN:8	HRS	9087.6		TSR 0					
WC#: 27.215	AFL	6131		TSR 0					
PROC. REF: AMM 27-32-01-900-801									
27-33-01-640-806-01 ^S		LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA					Service	ATA:27	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-33-01-640-806									
27-33-01-640-807-01 ^S		GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA					Service	ATA:27	PKG:31
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 27-33-01-640-807									
27-35-00-720-801-01 ^S		FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.200	AFL	9008							
PROC. REF: AMM 27-35-00-720-801									
27-35-01-640-801-01 ^S		PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (30CP)					Service	ATA:27	
PN:PN	MOS	16-Apr-13	144 (+2m)						
SN:UNKNOWN	HRS	9087.6							
WC#: 27.195	AFL	6131	7500						
PROC. REF: AMM 27-35-01-640-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-35-01-900-801-01		REMOVAL / INSTALLATION OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (30CP)					Component	ATA:27	
PN:221150M02	MOS/MSC	21-Nov-15	O/C	TSR 0					
SN:145	HRS	10579		TSR 0					
WC#: 27.195	AFL	7153		TSR 0					
PROC. REF: AMM 27-35-01-900-801, AMM 27-35-01-900-801									
27-35-05-350-801-01		RESTORATION OF THE PITCH MAIN AFU (FUNCTIONAL TEST / SERVICING) - PITCH MAIN AFU (15CP)					Service	ATA:27	
PN:105122-06	MOS	06-Mar-14	144 (+3%)		06-Mar-26	15-Jul-26	699 d (+131)		
SN:559	HRS								
WC#: 27.205	AFL								
PROC. REF: AMM 27-35-05-350-801									
27-35-05-710-801-01 ^S		TEST OF THE ELECTRICAL HEATING OF PITCH MAIN AFU - PITCH MAIN AFU (15CP)					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.460	AFL	9008							
PROC. REF: AMM 27-35-05-710-801									
27-35-05-900-801-01		REMOVAL / INSTALLATION OF THE PITCH MAIN AFU - PITCH MAIN AFU (15CP)					Component	ATA:27	
PN:105122-06	MOS/MSC	02-Jun-14	O/C	TSR 3					
SN:559	HRS	9733.1		TSR 0					
WC#: 27.205	AFL	6566		TSR 0					
PROC. REF: AMM 27-35-05-900-801									
27-35-07-350-801-01		RESTORATION OF THE PITCH AUXILIARY AFU (DISCARD OF BUSHINGS 1050450002) - PITCH AAFU (20CP)					Service	ATA:27	
PN:PN	MOS/MSC	11-May-07	N/A						
SN:UNKNOWN	HRS	5260.1							
WC#: 27.210	AFL	3550							
PROC. REF: AMM 27-35-07-350-801									
27-35-07-350-801-01A		RESTORATION PITCH AUXILIARY (AFU) ARTIFICIAL FEEL UNIT (DISCARD OF BUSHINGS 1050450002) (MANDATORY 5-40)					Service	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
WC#: 27.210	AFL	0							
PROC. REF: AMM 27-35-07-350-801									
27-35-07-640-801-01 ^S		PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (20CP)					Service	ATA:27	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 27.210	AFL	6131	7500						
PROC. REF: AMM 27-35-07-640-801									

PKG:21

PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-35-07-900-801-01		REMOVAL / INSTALLATION OF THE PITCH AUXILIARY AFU - PITCH AAFU (20CP)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.210	AFL	0		TSN 0					
PROC. REF: AMM 27-35-07-900-801									
27-40-00-720-801-01 ^S		FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 27-40-00-720-801									
PKG:21									
27-40-01-210-802-01		VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (210CH)					Service	ATA:27	
PN:021121-12	MOS	16-Jul-19	72 (+3%)		16-Jul-25	20-Sep-25	466 d (+66)		
SN:731	HRS	11761.3							
WC#: 27.260	AFL	7947	3750 (+3%)		11697	11809.5	2195 (+112.5)		
PROC. REF: AMM 27-40-01-210-802									
27-40-01-350-801-01		RESTORATION OF THE HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT) - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (210CH)					Service	ATA:27	
PN:021121-12	MOS	16-Apr-13	144 (+3%)		16-Apr-25	25-Aug-25	375 d (+131)		
SN:731	HRS	9087.6							
WC#: 27.260	AFL	6131	7500 (+3%)		13631	13856	4129 (+225)		
PROC. REF: AMM 27-40-01-350-801									
27-40-01-350-801-01A		RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT)(MANDATORY 5-40)					Service	ATA:27	
PN:021121-12	MOS	16-Apr-13						MANDATORY 5-40	
SN:731	HRS	9087.6							
	AFL	6131	7725		13856		4354		
PROC. REF: AMM 27-40-01-350-801									
27-40-01-640-802-01 ^S		GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (210CH)					Service	ATA:27	
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
WC#: 27.235	AFL	9471							
PROC. REF: AMM 27-40-01-640-802									
PKG:5									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40-01-720-801-01^S MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - NORMAL ELECTRIC MOTOR (210CHA)								
	MOS	05-May-22						Service ATA:27
	HRS	13592.3	1600 (+40)					
WC#: 27.280	AFL	9008						
					PROC. REF: AMM 27-40-01-720-801			PKG:21
27-40-01-720-801-02^S MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - EMERGENCY ELECTRIC MOTOR (210CHB)								
	MOS	05-May-22						Service ATA:27
	HRS	13592.3	1600 (+40)					
WC#: 27.280	AFL	9008						
					PROC. REF: AMM 27-40-01-720-801			PKG:21
27-40-01-900-801-01 REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (210CH)								
PN:021121-12	MOS/MSC	16-Apr-13	H/T		TSR 0			Component ATA:27
SN:731	HRS	9087.6			TSN 9561, TSR 0			
WC#: 27.260	AFL	6131			TSN 5849, TSR 0			
					PROC. REF: AMM 27-40-01-900-801			
27-40-03-100-801-01 CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR MOTORS - NORMAL ELECTRIC MOTOR (210CHA)								
	MOS/MSC	16-Apr-13	N/A					Service ATA:27
	HRS	9087.6						
WC#: 27.265	AFL	6131						
					PROC. REF: AMM 27-40-03-100-801			
27-40-05-900-801-01 REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER POSITION REPEATER BOX - HORIZONTAL STABILIZER POSITION REPEATER BOX (320CH)								
PN:016095-02	MOS/MSC	18-Feb-14	O/C					Component ATA:27
SN:194	HRS	9548.1						
WC#: 27.275	AFL	6444						
					PROC. REF: AMM 27-40-05-900-801			
27-40-15-710-801-01^S OPERATIONAL TEST OF THE RELAY IN THE HORIZONTAL STABILIZER EMERGENCY CONTROL BOX								
	MOS	16-Apr-13	144 (+2m)					Service ATA:27
	HRS	9087.6						
WC#: 27.270	AFL	6131	7500					
					PROC. REF: AMM 27-40-15-710-801			PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-40-15-710-801-01A	OPERATIONAL TEST OF THE RELAY IN THE HORIZONTAL STABILIZER EMERGENCY CONTROL BOX (MANDATORY 5-40)							Service	ATA:27
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6	16000		25087.6		10733.2		
WC#: 27.270	AFL	6131							
PROC. REF: AMM 27-40-15-710-801									
27-40-17-720-801-01 ^S	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HORIZONTAL STABILIZER RELAY BOX (500CH)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	4800 (+40)						
WC#: 27.255	AFL	9008							
PROC. REF: AMM 27-40-17-720-801									
27-40-17-720-801-01A	FUNCTIONAL TEST HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)							Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	5000		18592.3		4237.9		
WC#: 27.255	AFL	9008							
PROC. REF: AMM 27-40-17-720-801									
27-50-00-640-801-01 ^S	GREASING / LUBRICATION OF FLAP MECHANISMS							Service	ATA:27
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 27.290	AFL	9471							
PROC. REF: AMM 27-50-00-640-801									
27-50-00-710-801-01	OPERATIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM							Service	ATA:27
	MOS/MSC	10-Sep-15	O/C						
	HRS	10489.8							
WC#: 27.305	AFL	7089							
PROC. REF: AMM 27-50-00-710-801									
27-50-00-720-801-01 ^S	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM - USING THE HYDRAULIC GPU							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+50)						
	AFL	9008							
PROC. REF: AMM 27-50-00-720-801									
27-50-00-720-802-01	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM							Service	ATA:27
	MOS	07-Feb-24	12 (+1m)		07-Feb-25	07-Mar-25	307 d (+28)		
	HRS	14354.4	400 (+40)		14754.4	14794.4	400 (+40)		
WC#: 27.295	AFL	9502							
PROC. REF: AMM 27-50-00-720-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-50-00-720-802-01A	FUNCTIONAL TEST OF FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)							Service	ATA:27
	MOS	07-Feb-24						MANDATORY 5-40	
	HRS	14354.4	450		14804.4		450		
WC#: 27.295	AFL	9502							
PROC. REF: AMM 27-50-00-720-802									
27-50-00-720-803-01 ^S	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 27-50-00-720-803									
27-51-01-900-801-01	REMOVAL / INSTALLATION OF THE SLATS / FLAPS CONTROL BOX - SLATS/FLAPS CONTROL BOX (50CZ)							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.100	AFL	0		TSN 0					
PROC. REF: AMM 27-51-01-900-801									
27-52-01-900-801-01	REMOVAL / INSTALLATION OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (10CF)							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.325	AFL	0		TSN 0					
PROC. REF: AMM 27-52-01-900-801									
27-52-13-200-801-01 ^S	CHECK / GREASING OF FLAP CONTROL ROD SPLINES							Service	ATA:27
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 27.320	AFL	7947	3750						
PROC. REF: AMM 27-52-13-200-801									
27-53-01-220-801-01	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (40CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
WC#: 27.290	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									
27-53-01-220-801-02	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-220-801-03	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L20CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									
27-53-01-220-801-04	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R20CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									
27-53-01-220-801-05	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									
27-53-01-220-801-06	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (30CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-220-801									
27-53-01-350-801-01	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (40CF)							Service	ATA:27
PN:1-5319-3	MOS	04-Apr-11							
SN:6028	HRS	7883.8							
WC#: 27.310	AFL	5278	4500		9778		276		
PROC. REF: AMM 27-53-01-350-801									
27-53-01-350-801-01A	RESTORATION LH OUTBOARD FLAP SCREWJACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)							Service	ATA:27
PN:1-5319-3	MOS	04-Apr-11						MANDATORY 5-40	
SN:6028	HRS	7883.8							
WC#: 27.310	AFL	5278	4500		9778		276		
PROC. REF: AMM 27-53-01-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-801-02 RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP LATERAL SCREW JACK (L25CF) Service ATA:27								
PN:5318-3	MOS	13-May-15						
SN:2407	HRS	10259.8						
WC#: 27.315	AFL	6931	3500		10431		929	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-02A RESTORATION LH INBOARD LATERAL FLAP SCREWJACK ACTUATOR (OVERHAUL) (MANDATORY 5-40) Service ATA:27								
PN:5318-3	MOS	13-May-15						MANDATORY 5-40
SN:2407	HRS	10259.8						
WC#: 27.315	AFL	6931	3500		10431		929	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-03 RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP CENTER SCREW JACK (L20CF) Service ATA:27								
PN:5318-3	MOS	05-May-22						
SN:8185	HRS	13592.3						
WC#: 27.470	AFL	9008	3500		12508		3006	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-03A RESTORATION LH INBOARD CENTRAL FLAP SCREWJACK ACTUATOR (OVERHAUL) (MANDATORY 5-40) Service ATA:27								
PN:5318-3	MOS	05-May-22						MANDATORY 5-40
SN:8185	HRS	13592.3						
WC#: 27.470	AFL	9008	3500		12508		3006	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-04 RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP CENTER SCREW JACK (R20CF) Service ATA:27								
PN:5318-3	MOS	05-May-22						
SN:8184	HRS	13592.3						
WC#: 27.470	AFL	9008	3500		12508		3006	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-04A RESTORATION RH INBOARD FLAP CENTRAL SCREWJACK ACTUATOR (OVERHAUL) (MANDATORY 5-40) Service ATA:27								
PN:5318-3	MOS	05-May-22						MANDATORY 5-40
SN:8184	HRS	13592.3						
WC#: 27.470	AFL	9008	3500		12508		3006	
PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-05 RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP LATERAL SCREW JACK (R25CF) Service ATA:27								
PN:5318-3	MOS	05-May-22						
SN:7289	HRS	13592.3						
WC#: 27.315	AFL	9008	3500		12508		3006	
PROC. REF: AMM 27-53-01-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-350-801-05A		RESTORATION RH INBOARD FLAP LATERAL SCREWJACK ACTUATOR (MANDATORY 5-40)							Service ATA:27
PN:5318-3	MOS	05-May-22						MANDATORY 5-40	
SN:7289	HRS	13592.3							
WC#: 27.315	AFL	9008	3500		12508		3006		
PROC. REF: AMM 27-53-01-350-801									
27-53-01-350-801-06		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH OUTBOARD FLAP SCREW JACK (30CF)							Service ATA:27
PN:2-5319-3	MOS	13-May-15							
SN:659	HRS	10259.8							
WC#: 27.310	AFL	6931	4500		11431		1929		
PROC. REF: AMM 27-53-01-350-801									
27-53-01-350-801-06A		RESTORATION RH OUTBOARD FLAP SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)							Service ATA:27
PN:2-5319-3	MOS	13-May-15						MANDATORY 5-40	
SN:659	HRS	10259.8							
WC#: 27.310	AFL	6931	4500		11431		1929		
PROC. REF: AMM 27-53-01-350-801									
27-53-01-350-802-01		UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (40CF)							Service ATA:27
PN:1-5319-3	MOS/MSC	04-Apr-11	N/A						
SN:6028	HRS	7883.8							
	AFL	5278							
PROC. REF: AMM 27-53-01-350-802									
27-53-01-350-802-01A		UPGRADE LH OUTBOARD FLAP SCREWJACK ACTUATOR (MANDATORY 5-40-30)							Service ATA:27
PN:1-5319-3	MOS/MSC	04-Apr-11	N/A					MANDATORY 5-40	
SN:6028	HRS	7883.8							
	AFL	5278							
PROC. REF: AMM 27-53-01-350-802									
27-53-01-350-802-02		UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)							Service ATA:27
PN:5318-3	MOS/MSC		N/A						
SN:2407	HRS								
	AFL								
PROC. REF: AMM 27-53-01-350-802									
27-53-01-350-802-02A		UPGRADE LH INBOARD LATERAL FLAP SCREWJACK ACTUATOR (MANDATORY 5-40-30)							Service ATA:27
	MOS/MSC		N/A					MANDATORY 5-40	
	HRS								
	AFL								
PROC. REF: AMM 27-53-01-350-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-802-03 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L20CF) Service ATA:27								
PN:5318-3	MOS/MSC	05-May-22	N/A					
SN:8185	HRS	13592.3						
	AFL	9008						
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-03A UPGRADE LH INBOARD CENTRAL FLAP SCREWJACK ACTUATOR (MANDATORY 5-40-30) Service ATA:27								
PN:5318-3	MOS/MSC		N/A					MANDATORY 5-40
SN:8185	HRS							
	AFL							
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-04 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R20CF) Service ATA:27								
PN:5318-3	MOS/MSC	05-May-22	N/A					
SN:8184	HRS	13592.3						
	AFL	9008						
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-04A UPGRADE RH INBOARD FLAP CENTRAL SCREWJACK ACTUATOR (MANDATORY 5-40-30) Service ATA:27								
PN:5318-3	MOS/MSC		N/A					MANDATORY 5-40
SN:8184	HRS							
	AFL							
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-05 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R25CF) Service ATA:27								
PN:5318-3	MOS/MSC	05-May-22	N/A					
SN:7289	HRS	13592.3						
	AFL	9008						
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-05A UPGRADE RH INBOARD FLAP LATERAL SCREWJACK ACTUATOR (MANDATORY 5-40-30) Service ATA:27								
PN:5318-3	MOS/MSC		N/A					MANDATORY 5-40
SN:7289	HRS							
	AFL							
PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-06 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (30CF) Service ATA:27								
PN:2-5319-3	MOS/MSC		N/A					
SN:659	HRS							
	AFL							
PROC. REF: AMM 27-53-01-350-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-350-802-06A	UPGRADE RH OUTBOARD FLAP SCREW JACK ACTUATOR (MANDATORY 5-40-30)							Service	ATA:27
	MOS/MSC		N/A					MANDATORY 5-40	
	HRS								
	AFL								
								PROC. REF: AMM 27-53-01-350-802	
27-53-01-640-803-01	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (40CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
								PROC. REF: AMM 27-53-01-640-803	
27-53-01-640-803-02	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
								PROC. REF: AMM 27-53-01-640-803	
27-53-01-640-803-03	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L20CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
								PROC. REF: AMM 27-53-01-640-803	
27-53-01-640-803-04	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R20CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
								PROC. REF: AMM 27-53-01-640-803	
27-53-01-640-803-05	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
								PROC. REF: AMM 27-53-01-640-803	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-640-803-06	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (30CF)							Service	ATA:27
	MOS	13-Nov-23	8 (+1m)	Adj -3d	10-Jul-24	10-Aug-24	95 d (+31)		
	HRS	14262.6							
	AFL	9450	400		9850		348		
PROC. REF: AMM 27-53-01-640-803									
27-53-01-720-803-01	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (40CF)							Service	ATA:27
PN:1-5319-3	MOS	24-Oct-23							
SN:6028	HRS	14220.4	450		14670.4		316		
WC#: 27.310	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-01A	CHECK LH OUTBOARD FLAP SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service	ATA:27
PN:1-5319-3	MOS	24-Oct-23						MANDATORY 5-40	
SN:6028	HRS	14220.4	450		14670.4		316		
WC#: 27.310	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-02	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)							Service	ATA:27
PN:5318-3	MOS	24-Oct-23							
SN:2407	HRS	14220.4	450		14670.4		316		
WC#: 27.315	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-02A	CHECK LH INBOARD LATERAL FLAP SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service	ATA:27
PN:5318-3	MOS	24-Oct-23						MANDATORY 5-40	
SN:2407	HRS	14220.4	450		14670.4		316		
WC#: 27.315	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-03	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L20CF)							Service	ATA:27
PN:5318-3	MOS	05-May-22							
SN:8185	HRS	13592.3							
WC#: 27.470	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-720-803-03A		CHECK LH INBOARD CENTRAL FLAP SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:5318-3	MOS	05-May-22						MANDATORY 5-40	
SN:8185	HRS	13592.3							
WC#: 27.470	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-04		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R20CF)							Service ATA:27
PN:5318-3	MOS	05-May-22							
SN:8184	HRS	13592.3							
WC#: 27.470	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-04A		CHECK RH INBOARD FLAP CENTRAL SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:5318-3	MOS	05-May-22						MANDATORY 5-40	
SN:8184	HRS	13592.3							
WC#: 27.470	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-05		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)							Service ATA:27
PN:5318-3	MOS	05-May-22							
SN:7289	HRS	13592.3							
WC#: 27.315	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-05A		CHECK RH INBOARD FLAP LATERAL SCREWJACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:5318-3	MOS	05-May-22						MANDATORY 5-40	
SN:7289	HRS	13592.3							
WC#: 27.315	AFL	9008	T:3000		12008		2506		
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-06		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (30CF)							Service ATA:27
PN:2-5319-3	MOS	24-Oct-23							
SN:659	HRS	14220.4	450		14670.4		316		
WC#: 27.310	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									
27-53-01-720-803-06A		CHECK RH OUTBOARD FLAP SCREW JACK ACTUATOR SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY 5-40)							Service ATA:27
PN:2-5319-3	MOS	24-Oct-23						MANDATORY 5-40	
SN:659	HRS	14220.4	450		14670.4		316		
WC#: 27.310	AFL	9426							
PROC. REF: AMM 27-53-01-720-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-900-803-01		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (40CF)					Component	ATA:27	
PN:1-5319-3	MOS/MSC	04-Apr-11	O/C	TSN 0					
SN:6028	HRS	7883.8		TSN 0					
WC#: 27.310	AFL	5278		TSN 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-900-803-02		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)					Component	ATA:27	
PN:5318-3	MOS/MSC	13-May-15	O/C	TSO 3					
SN:2407	HRS	10259.8		TSO 0					
WC#: 27.315	AFL	6931		TSO 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-900-803-03		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L20CF)					Component	ATA:27	
PN:5318-3	MOS/MSC	05-May-22	O/C	TSN 0					
SN:8185	HRS	13592.3		TSN 0					
WC#: 27.470	AFL	9008		TSN 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-900-803-04		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R20CF)					Component	ATA:27	
PN:5318-3	MOS/MSC	05-May-22	O/C	TSN 0					
SN:8184	HRS	13592.3		TSN 0					
WC#: 27.470	AFL	9008		TSN 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-900-803-05		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)					Component	ATA:27	
PN:5318-3	MOS/MSC	05-May-22	O/C	TSN 0					
SN:7289	HRS	13592.3		TSN 0					
WC#: 27.315	AFL	9008		TSN 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-900-803-06		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (30CF)					Component	ATA:27	
PN:2-5319-3	MOS/MSC	13-May-15	O/C	TSN 123, TSO 1					
SN:659	HRS	10259.8		TSN 7063, TSO 0					
WC#: 27.310	AFL	6931		TSN 4140, TSO 0					
PROC. REF: AMM 27-53-01-900-803									
27-53-01-960-801-01		DISCARD OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (40CF)					Service	ATA:27	
PN:1-5319-3	MOS	04-Apr-11					LIFE LIMIT		
SN:6028	HRS	7883.8							
WC#: 27.310	AFL	5278	16000		21278		11776		
PROC. REF: AMM 27-53-01-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-53-01-960-801-02		DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L25CF)						Service	ATA:27
PN:5318-3	MOS	13-May-15						LIFE LIMIT	
SN:2407	HRS	10259.8		TAC 5620					
WC#: 27.315	AFL	6931	15000	TAC 0	18572		9070		
PROC. REF: AMM 27-53-01-960-801									
27-53-01-960-801-03		DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L20CF)						Service	ATA:27
PN:5318-3	MOS	05-May-22						LIFE LIMIT	
SN:8185	HRS	13592.3							
WC#: 27.470	AFL	9008	15000		24008		14506		
PROC. REF: AMM 27-53-01-960-801									
27-53-01-960-801-04		DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R20CF)						Service	ATA:27
PN:5318-3	MOS	05-May-22						LIFE LIMIT	
SN:8184	HRS	13592.3							
WC#: 27.470	AFL	9008	15000		24008		14506		
PROC. REF: AMM 27-53-01-960-801									
27-53-01-960-801-05		DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R25CF)						Service	ATA:27
PN:5318-3	MOS	05-May-22						LIFE LIMIT	
SN:7289	HRS	13592.3							
WC#: 27.315	AFL	9008	15000		24008		14506		
PROC. REF: AMM 27-53-01-960-801									
27-53-01-960-801-06		DISCARD OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (30CF)						Service	ATA:27
PN:2-5319-3	MOS	13-May-15						LIFE LIMIT	
SN:659	HRS	10259.8		TAC 7063					
WC#: 27.310	AFL	6931	16000	TAC 0	18791		9289		
PROC. REF: AMM 27-53-01-960-801									
27-60-00-710-803-01 ^S		OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES						Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 27.350	AFL	9008							
PROC. REF: AMM 27-60-00-710-803									
27-61-01-720-801-01 ^S		FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE MICROSWITCH (L130CD)						Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.345	AFL	9008							
PROC. REF: AMM 27-61-01-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-61-01-720-801-02 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE MICROSWITCH (L120CD)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
					PROC. REF: AMM 27-61-01-720-801			PKG:22	
27-61-01-720-801-03 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE MICROSWITCH (L110CD)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
					PROC. REF: AMM 27-61-01-720-801			PKG:22	
27-61-01-720-801-04 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE MICROSWITCH (R110CD)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
					PROC. REF: AMM 27-61-01-720-801			PKG:22	
27-61-01-720-801-05 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE MICROSWITCH (R120CD)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
					PROC. REF: AMM 27-61-01-720-801			PKG:22	
27-61-01-720-801-06 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE MICROSWITCH (R130CD)							Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
					PROC. REF: AMM 27-61-01-720-801			PKG:22	
27-61-01-900-801-01	LEFT OUTBOARD AIRBRAKE MICROSWITCH							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
					PROC. REF: GENERIC NO REF				
27-61-01-900-801-02	LEFT CENTER AIRBRAKE MICROSWITCH							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
					PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-61-01-900-801-03		LEFT INBOARD AIRBRAKE MICROSWITCH					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
27-61-01-900-801-04		RIGHT INBOARD AIRBRAKE MICROSWITCH					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
27-61-01-900-801-05		RIGHT CENTER AIRBRAKE MICROSWITCH					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
27-61-01-900-801-06		RIGHT OUTBOARD AIRBRAKE MICROSWITCH					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
27-62-01-900-801-01		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30CD)					Component	ATA:27	
PN:106091-07	MOS/MSC	18-Feb-20	O/C	TSR 0					
SN:5385	HRS	12088.7		TSN 11942.3, TSR 0					
WC#: 27.355	AFL	8133		TSN 8052, TSR 0					
PROC. REF: AMM 27-62-01-900-801									
27-62-01-900-801-02		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L20CD)					Component	ATA:27	
PN:106091-08	MOS/MSC	18-Feb-20	O/C	TSR 0					
SN:5397	HRS	12088.7		TSN 11942.3, TSR 0					
WC#: 27.355	AFL	8133		TSN 8052, TSR 0					
PROC. REF: AMM 27-62-01-900-801									
27-62-01-900-801-03		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L10CD)					Component	ATA:27	
PN:106091-09	MOS/MSC	20-Dec-19	O/C	TSO 0					
SN:3224	HRS	11942.3		TSO 0					
WC#: 27.355	AFL	8052		TSO 0					
PROC. REF: AMM 27-62-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-62-01-900-801-04		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R10CD)						Component	ATA:27
PN:106091-09	MOS/MSC	18-Feb-20	O/C	TSR 0					
SN:5408	HRS	12088.7		TSN 11955.5, TSR 0					
WC#: 27.360	AFL	8133		TSN 8058, TSR 0					
PROC. REF: AMM 27-62-01-900-801									
27-62-01-900-801-05		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R20CD)						Component	ATA:27
PN:106091-08	MOS/MSC	18-Feb-20	O/C	TSR 0					
SN:5396	HRS	12088.7		TSN 11955.5, TSR 0					
WC#: 27.360	AFL	8133		TSN 8058, TSR 0					
PROC. REF: AMM 27-62-01-900-801									
27-62-01-900-801-06		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30CD)						Component	ATA:27
PN:106091-07	MOS/MSC	18-Feb-20	O/C	TSR 0					
SN:5386	HRS	12088.7		TSN 11955.5, TSR 0					
WC#: 27.360	AFL	8133		TSN 8058, TSR 0					
PROC. REF: AMM 27-62-01-900-801									
27-80-00-710-804-02		OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - EMERGENCY MODE						Service	ATA:27
	MOS	07-Aug-18							
	HRS	11704.7	10000 (+40)	Adj -1704.7	20000	20040	5645.6 (+40)		
	AFL	7913							
PROC. REF: AMM 27-80-00-710-804									
27-80-00-710-806-01		OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS - LH AOA SENSOR (L10CM)						Service	ATA:27
	MOS/MSC	10-Sep-15	O/C						
	HRS	10489.8							
	AFL	7089							
PROC. REF: AMM 27-80-00-710-806									
27-80-00-710-806-02		OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS - RH AOA SENSOR (R10CM)						Service	ATA:27
	MOS/MSC	10-Sep-15	O/C						
	HRS	10489.8							
	AFL	7089							
PROC. REF: AMM 27-80-00-710-806									
27-80-00-710-807-02 ^S		OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - LH SOLENOID (S1)						Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 27-80-00-710-807									

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-80-00-710-807-03 ^S		OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - RH SOLENOID (S2)						Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 27-80-00-710-807								PKG:21	
27-80-00-720-801-02 ^S		FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE						Service	ATA:27
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 27-80-00-720-801								PKG:21	
27-80-00-720-801-02A		FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE (MANDATORY 5-40)						Service	ATA:27
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
PROC. REF: AMM 27-80-00-720-801									
27-80-01-900-801-01		REMOVAL / INSTALLATION OF THE OUTBOARD SLAT MANIFOLD - OUTBOARD SLAT MANIFOLD (30CM)						Component	ATA:27
PN:108143-01	MOS/MSC	16-Apr-13	O/C		TSR 0				
SN:224	HRS	9087.6			TSN 9966, TSR 0				
WC#: 27.420	AFL	6131			TSN 6159, TSR 0				
PROC. REF: AMM 27-80-01-900-801									
27-80-05-900-801-01		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH SLAT INBOARD ACTUATOR (L440CM)						Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.430	AFL	0			TSN 0				
PROC. REF: AMM 27-80-05-900-801									
27-80-05-900-801-02		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH SLAT INBOARD ACTUATOR (R440CM)						Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.435	AFL	0			TSN 0				
PROC. REF: AMM 27-80-05-900-801									
27-80-05-900-801-03		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH SLAT OUTBOARD ACTUATOR (L430CM)						Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.430	AFL	0			TSN 0				
PROC. REF: AMM 27-80-05-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
27-80-05-900-801-04		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH SLAT OUTBOARD ACTUATOR (R430CM)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.435	AFL	0		TSN 0					
PROC. REF: AMM 27-80-05-900-801									
27-80-05-900-801-05		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH SLAT EMERGENCY ACTUATOR (L450CM)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.440	AFL	0		TSN 0					
PROC. REF: AMM 27-80-05-900-801									
27-80-05-900-801-06		REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH SLAT EMERGENCY ACTUATOR (R450CM)					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.440	AFL	0		TSN 0					
PROC. REF: AMM 27-80-05-900-801									
27-80-17-720-801-01 ^S		FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH SLAT EXTENDED MICROSWITCH (L210CM)					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.405	AFL	9008							
PROC. REF: AMM 27-80-17-720-801									
PKG:22									
27-80-17-720-801-02 ^S		FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH SLAT RETRACTED MICROSWITCH (L220CM)					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.405	AFL	9008							
PROC. REF: AMM 27-80-17-720-801									
PKG:22									
27-80-17-720-801-03 ^S		FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH SLAT EXTENDED MICROSWITCH (R210CM)					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.405	AFL	9008							
PROC. REF: AMM 27-80-17-720-801									
PKG:22									
27-80-17-720-801-04 ^S		FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH SLAT RETRACTED MICROSWITCH (R220CM)					Service	ATA:27	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 27.405	AFL	9008							
PROC. REF: AMM 27-80-17-720-801									
PKG:22									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
270811	PILOT PEDAL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
270816	COPILOT PEDAL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
270831	PILOT PEDAL ADJUSTMENT ROD BOX							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.070	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
270841	COPILOT PEDAL ADJUSTMENT ROD BOX							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.070	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
271851	LH AILERON NO.1 SYSTEM SERVO ACTUATOR ACCUMULATOR							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.135	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
271856	LH AILERON NO.2 SYSTEM SERVO ACTUATOR ACCUMULATOR							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.135	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
271861	RH AILERON NO.1 SYSTEM SERVO ACTUATOR ACCUMULATOR							Component	ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 27.140	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
271866		RH AILERON NO.2 SYS SERVO ACTUATOR ACCUMULATOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.140	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
273806		ELEVATOR ARTHUR CONTROL BOX					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.220	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
273816		PITCH FEEL SERVO VALVE					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.225	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
275801		LH FLAP DUAL TRANSFER GEARBOX					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.330	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
275811		RH FLAP DUAL TRANSFER GEARBOX					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.330	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
275821		LH FLAP POSITION TRANSMITTER					Component	ATA:27	
PN:1-4414-2	MOS/MSC	28-Jul-15	O/C	TSR 0					
SN:7267	HRS	10421		TSR 0					
WC#: 27.335	AFL	7045		TSR 0					
PROC. REF: GENERIC NO REF									
275831		RH FLAP POSITION TRANSMITTER					Component	ATA:27	
PN:2-4414-2	MOS/MSC	28-Jul-15	O/C	TSR 0					
SN:518	HRS	10421		TSR 0					
WC#: 27.335	AFL	7045		TSR 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
276801		AIRBRAKE/EMERGENCY SLATS MANIFOLD					Component		ATA:27
PN:71365-1	MOS/MSC	10-Nov-21	O/C						
SN:0174	HRS	13181.1							
WC#: 27.365	AFL	8779							
PROC. REF: GENERIC NO REF									
276806		AIRBRAKE PRESSURE HOLDING VALVE					Component		ATA:27
PN:D25AB1704	MOS/MSC	02-Jul-07	O/C						
SN:65	HRS	5430.8							
WC#: 27.370	AFL	3666							
PROC. REF: AMM 27-62-03-900-801									
276811		AIRBRAKE PRESSURE GAUGE					Component		ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.375	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
276816		HYDRAULIC AIRBRAKE CHARGING VALVE					Component		ATA:27
PN:MS28889-2	MOS/MSC	24-Jul-07	O/C	TSN 0					
SN:NSN	HRS	5502.2		TSN 0					
WC#: 27.380	AFL	3708		TSN 0					
PROC. REF: GENERIC NO REF									
276821		LH OUTBOARD AIRBRAKE RESTRICTOR					Component		ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.385	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
276826		LH MIDDLE AIRBRAKE RESTRICTOR					Component		ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.385	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
276831		LH INBOARD AIRBRAKE RESTRICTOR					Component		ATA:27
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.385	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 27 - FLIGHT CONTROLS									
276836		RH INBOARD AIRBRAKE RESTRICTOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.390	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
276841		RH MIDDLE AIRBRAKE RESTRICTOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.390	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
276846		RH OUTBOARD AIRBRAKE RESTRICTOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.390	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
278841		LH SLAT EMERGENCY ACTUATOR ONE-WAY RESTRICTOR VALVE					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.445	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
278846		RH SLAT EMERGENCY ACTUATOR ONE-WAY RESTRICTOR VALVE					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.445	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
278851		LH SLAT ACTUATOR ADJUSTABLE RESTRICTOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
278856		RH SLAT ACTUATOR ADJUSTABLE RESTRICTOR					Component	ATA:27	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-00-00-280-801-01 ^S	FUEL CONTAMINATION DETECTION TEST							Service	ATA:28
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
WC#: 28.140	AFL	9471							
	PROC. REF: AMM 28-00-00-280-801								PKG:5
28-00-00-290-801-01 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH FEEDER TANK							Service	ATA:28
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 28-00-00-290-801								PKG:7
28-00-00-290-801-02 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH FEEDER TANK							Service	ATA:28
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 28-00-00-290-801								PKG:7
28-00-00-290-801-03	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH CENTER-WING TANK							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-04	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH CENTER-WING TANK							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-05 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH WING TANK							Service	ATA:28
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 28-00-00-290-801								PKG:7
28-00-00-290-801-06 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH WING TANK							Service	ATA:28
	MOS	05-May-22	36 (+1m)						
	HRS	13592.3	2400 (+40)						
	AFL	9008							
	PROC. REF: AMM 28-00-00-290-801								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803								
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803								
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803								
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803								
28-00-00-910-803-05 ^U	DECONTAMINATION OF THE FUEL SYSTEMS - INSPECTION OF FEEDER TANKS							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803								
28-00-00-910-803-07 ^U	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING OF FUEL TANKS							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS							Service	ATA:28
	MOS/MSC		A/R						
	HRS								
WC#: 28.420	AFL								
PROC. REF: AMM 28-00-00-910-804									
28-10-00-280-801-01 ^S	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES							Service	ATA:28
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 28.020	AFL	6131	7500						
PROC. REF: AMM 28-10-00-280-801									
28-21-01-900-801-01	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - LH NORMAL BOOSTER PUMP (L30QD)							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.250	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01-900-801									
28-21-01-900-801-02	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - RH NORMAL BOOSTER PUMP (R30QD)							Component	ATA:28
PN:226165-1	MOS/MSC	27-Aug-19	O/C						
SN:154	HRS	11800.9							
WC#: 28.250	AFL	7971							
PROC. REF: AMM 28-21-01-900-801									
28-21-04-900-801-01	REMOVAL / INSTALLATION OF THE BOOSTER PUMP CANISTERS - LH NORMAL BOOSTER PUMP CANISTER (L31QD)							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.280	AFL	0		TSN 0					
PROC. REF: AMM 28-21-04-900-801									
28-21-04-900-801-02	REMOVAL / INSTALLATION OF THE BOOSTER PUMP CANISTERS - RH NORMAL BOOSTER PUMP CANISTER (R31QD)							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.280	AFL	0		TSN 0					
PROC. REF: AMM 28-21-04-900-801									
28-21-13-710-801-01 ^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - LH ENGINE FUEL SHUT-OFF VALVE (L20QD)							Service	ATA:28
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 76.030	AFL	7947	3750						
PROC. REF: AMM 28-21-13-710-801									

PKG:32

PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-13-710-801-02^S OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - RH ENGINE FUEL SHUT-OFF VALVE (R20QD)								
	MOS	16-Jul-19	72 (+2m)					Service ATA:28
	HRS	11761.3						
WC#: 76.030	AFL	7947	3750					
PROC. REF: AMM 28-21-13-710-801								
28-21-13-720-801-01 FUNCTIONAL TEST OF THE THERMAL EXPANSION SYSTEM OF THE FUEL SHUT-OFF VALVES - LH ENGINE FUEL SHUT-OFF VALVE (L20QD)								
PN:B97-31-652	MOS	02-Jun-14						Service ATA:28
SN:20156	HRS	9733.1	10000 (+3%)		19733.1	20033.1	5378.7 (+300)	
WC#: 28.270	AFL	6566						
PROC. REF: AMM 28-21-13-720-801								
28-21-13-720-801-02 FUNCTIONAL TEST OF THE THERMAL EXPANSION SYSTEM OF THE FUEL SHUT-OFF VALVES - RH ENGINE FUEL SHUT-OFF VALVE (R20QD)								
PN:B97-31-652	MOS	02-Jun-14						Service ATA:28
SN:20154	HRS	9733.1	10000 (+3%)		19733.1	20033.1	5378.7 (+300)	
WC#: 28.270	AFL	6566						
PROC. REF: AMM 28-21-13-720-801								
28-21-13-900-801-01 NO. 1 ENGINE FUEL SHUTOFF VALVE								
PN:B97-31-652	MOS/MSC	02-Jun-14	O/C	TSN 197, TSR 4				Component ATA:28
SN:20156	HRS	9733.1		TSN 10156, TSR 0				
WC#: 76.030	AFL	6566		TSR 0				
PROC. REF: AMM 28-21-13-900-803								
28-21-13-900-801-02 NO. 2 ENGINE FUEL SHUTOFF VALVE								
PN:B97-31-652	MOS/MSC	02-Jun-14	O/C	TSN 197, TSR 4				Component ATA:28
SN:20154	HRS	9733.1		TSN 10156, TSR 0				
WC#: 76.030	AFL	6566		TSR 0				
PROC. REF: AMM 28-21-13-900-803								
28-21-13-900-802-01 REMOVAL / INSTALLATION OF THE ENGINE FUEL SHUT-OFF VALVE ACTUATORS - LH ENGINE FUEL SHUT-OFF VALVE ACTUATOR (L20QD1)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:28
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-13-900-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-13-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE FUEL SHUT-OFF VALVE ACTUATORS - RH ENGINE FUEL SHUT-OFF VALVE ACTUATOR (R20QD1)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0	TSN 0					
	AFL	0	TSN 0					
PROC. REF: AMM 28-21-13-900-802								
28-21-17-790-801-01	SEALING TEST OF THE APU FUEL SHUT-OFF VALVE - APU SHUT-OFF VALVE (10QD2)						Service	ATA:28
	MOS/MSC	22-Nov-13	C/C					
	HRS	9419.6						
WC#: 49.185	AFL	6356						
PROC. REF: AMM 28-21-17-790-801								
28-21-25-710-801-01 ^S	OPERATIONAL TEST OF THE CROSSFEED UNITS						Service	ATA:28
	MOS	05-May-22	36 (+1m)					
	HRS	13592.3	2400 (+40)					
WC#: 28.240	AFL	9008						
PROC. REF: AMM 28-21-25-710-801								
28-21-25-900-801-01	REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - LH CROSSFEED UNIT (400QS)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0	TSN 0					
WC#: 28.270	AFL	0	TSN 0					
PROC. REF: AMM 28-21-25-900-801								
28-21-25-900-801-02	REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - RH CROSSFEED UNIT (410QS)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0	TSN 0					
WC#: 28.270	AFL	0	TSN 0					
PROC. REF: AMM 28-21-25-900-801								
28-21-27-900-801-01	REMOVAL / INSTALLATION OF THE CROSSFEED UNIT ELECTRICAL ACTUATORS - LH CROSSFEED UNIT ACTUATOR (400QS1)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0	TSN 0					
WC#: 28.260	AFL	0	TSN 0					
PROC. REF: AMM 28-21-27-900-801								
28-21-27-900-801-02	REMOVAL / INSTALLATION OF THE CROSSFEED UNIT ELECTRICAL ACTUATORS - RH CROSSFEED UNIT ACTUATOR (410QS1)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0	TSN 0					
	AFL	0	TSN 0					
PROC. REF: AMM 28-21-27-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-21-29-100-801-01 ^S	CLEANING OF THE CROSSFEED UNIT FILTERS - LH CROSSFEED UNIT FILTER							Service	ATA:28
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
				PROC. REF: AMM 28-21-29-100-801				PKG:5	
28-21-29-100-801-02 ^S	CLEANING OF THE CROSSFEED UNIT FILTERS - RH CROSSFEED UNIT FILTER							Service	ATA:28
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
				PROC. REF: AMM 28-21-29-100-801				PKG:5	
28-22-01-900-801-01	REMOVAL / INSTALLATION OF THE TANK INTERCONNECTION VALVE - TANKS INTERCONNECTION VALVE (370QS)							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.220	AFL	0		TSN 0					
				PROC. REF: AMM 28-22-01-900-801					
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
				PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP							Service	ATA:28
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
				PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING							Service	ATA:28
	MOS/MSC	10-Sep-15	O/C						
	HRS	10489.8							
	AFL	7089							
				PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-05	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY							Service	ATA:28
	MOS	07-Feb-24	2 (+5d)		07-Apr-24	12-Apr-24	1 d (+5)		
	HRS	14354.4							
	AFL	9502							
				PROC. REF: AMM 28-30-00-680-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service	ATA:28
	MOS	07-Feb-24	2 (+5d)		07-Apr-24	12-Apr-24	1 d (+5)		
	HRS	14354.4							
	AFL	9502							
PROC. REF: AMM 28-30-00-680-804									
28-30-01-900-801-01		REMOVAL / INSTALLATION OF THE DEFUELING MANIFOLD - DEFUELING MANIFOLD (10QD)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
28-30-11-900-801-01		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH WING TANK SUMP DRAIN VALVE (L30QS)						Component	ATA:28
PN:142D12-1	MOS/MSC	28-Nov-14	O/C						
SN:J18503	HRS	10116.4							
WC#: 28.370	AFL	6829							
PROC. REF: AMM 28-30-11-900-801									
28-30-11-900-801-02		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH WING TANK SUMP DRAIN VALVE (R30QS)						Component	ATA:28
PN:142D12-1	MOS/MSC	11-May-07	O/C	TSN 0					
SN:C81132	HRS	5260.1		TSN 0					
WC#: 28.370	AFL	3550		TSN 0					
PROC. REF: AMM 28-30-11-900-801									
28-30-11-900-801-03		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK SUMP DRAIN VALVE (L40QS)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.380	AFL	0		TSN 0					
PROC. REF: AMM 28-30-11-900-801									
28-30-11-900-801-04		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK REAR SUMP DRAIN VALVE (R40QS)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.380	AFL	0		TSN 0					
PROC. REF: AMM 28-30-11-900-801									
28-30-11-900-801-05		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK FRONT SUMP DRAIN VALVE (R45QS1)						Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.390	AFL	0		TSN 0					
PROC. REF: AMM 28-30-11-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-30-11-900-801-06		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH FEEDER TANK SUMP DRAIN VALVE (R45QS2)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.390	AFL	0		TSN 0					
PROC. REF: AMM 28-30-11-900-801									
28-30-11-900-801-07		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH CENTERWING TANK SUMP DRAIN VALVE (430QS)					Component	ATA:28	
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
WC#: 28.400	AFL								
PROC. REF: AMM 28-30-11-900-801									
28-30-11-960-801-01		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH WING TANK SUMP DRAIN VALVE (L30QS)					Service	ATA:28	
PN:142D12-1	MOS/MSC	28-Nov-14	O/C						
SN:J18503	HRS	10116.4							
	AFL	6829							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-801-02		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH WING TANK SUMP DRAIN VALVE (R30QS)					Service	ATA:28	
PN:142D12-1	MOS/MSC	01-Mar-00	O/C						
SN:C81132	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-801-03		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH FEEDER TANK SUMP DRAIN VALVE (L40QS)					Service	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-801-04		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH CENTERWING TANK REAR SUMP DRAIN VALVE (R40QS)					Service	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-801-05		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH CENTERWING TANK FRONT SUMP DRAIN VALVE (R45QS1)					Service	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-30-11-960-801-06		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH FEEDER TANK SUMP DRAIN VALVE (R45QS2)					Service	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-801-07		REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH CENTERWING TANK SUMP DRAIN VALVE (430QS)					Service	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-801									
28-30-11-960-802-01		DISCARD OF THE FUEL DRAIN CAPS					Service	ATA:28	
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-30-11-960-802									
28-41-00-720-801-01 ^S		FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM - LH INDICATOR					Service	ATA:28	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
PROC. REF: AMM 28-41-00-720-801									
28-41-00-720-801-02 ^S		FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM - RH INDICATOR					Service	ATA:28	PKG:22
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
	AFL	9008							
PROC. REF: AMM 28-41-00-720-801									
28-41-01-900-801-01		REMOVAL / INSTALLATION OF THE FUEL QUANTITY MANAGEMENT COMPUTER (FQMC) - FQMC (70QJ)					Component	ATA:28	
PN:736659-12	MOS/MSC	31-May-17	O/C	TSR 0					
SN:0309	HRS	10979.9		TSR 0					
WC#: 28.360	AFL	7397		TSR 0					
PROC. REF: AMM 28-41-01-900-801									
28-41-05-900-801-01		REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH FEEDER TANK GAUGE (L50QJ)					Component	ATA:28	
PN:768-343-1	MOS/MSC	02-Nov-07	O/C	TSR 0					
SN:131	HRS	5765.5		TSR 0					
WC#: 28.310	AFL	3864		TSR 0					
PROC. REF: AMM 28-41-05-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-05-900-801-02 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH FEEDER TANK GAUGE (R50QJ)								Component ATA:28
PN:768-343-1	MOS/MSC	11-Jan-07	O/C					
SN:328	HRS	5070.2						
WC#: 28.310	AFL	3433						
PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-03 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH CENTERWING TANK GAUGE (L60QJ)								Component ATA:28
PN:768-342-3	MOS/MSC	15-Jun-22	O/C	TSN 0				
SN:518	HRS	13630.3		TSN 0				
WC#: 28.320	AFL	9028		TSN 0				
PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-04 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH CENTERWING TANK GAUGE (R60QJ)								Component ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.320	AFL	0		TSN 0				
PROC. REF: AMM 28-41-05-900-801								
28-41-09-900-801-01 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING INBOARD TANK GAUGE (L20QJ)								Component ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.300	AFL	0		TSN 0				
PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-02 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING INBOARD TANK GAUGE (R20QJ)								Component ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.330	AFL	0		TSN 0				
PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-03 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING CENTER TANK GAUGE (L30QJ)								Component ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.300	AFL	0		TSN 0				
PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-04 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING CENTER TANK GAUGE (R30QJ)								Component ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.330	AFL	0		TSN 0				
PROC. REF: AMM 28-41-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-41-09-900-801-05		REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING OUTBOARD TANK GAUGE (L40QJ)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.300	AFL	0		TSN 0					
PROC. REF: AMM 28-41-09-900-801									
28-41-09-900-801-06		REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING OUTBOARD TANK GAUGE (R40QJ)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.330	AFL	0		TSN 0					
PROC. REF: AMM 28-41-09-900-801									
28-43-01-720-801-01 ^S		FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE SENSOR (25QJ)					Service	ATA:28	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 28.410	AFL	7947	3750						
PROC. REF: AMM 28-43-01-720-801									
PKG:31									
28-50-09-900-801-01		REMOVAL / INSTALLATION OF THE REFUELING VALVES AND CHECK VALVES - LH ELECTRICAL REFUELING VALVE (L70QS)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.040	AFL	0		TSN 0					
PROC. REF: AMM 28-50-09-900-801									
28-50-09-900-801-02		REMOVAL / INSTALLATION OF THE REFUELING VALVES AND CHECK VALVES - RH ELECTRICAL REFUELING VALVE (R70QS)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.040	AFL	0		TSN 0					
PROC. REF: AMM 28-50-09-900-801									
28-50-09-900-801-03		REMOVAL / INSTALLATION OF THE REFUELING VALVES AND CHECK VALVES - LH TANKS CHECK VALVE (L80QS)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
28-50-09-900-801-04		REMOVAL / INSTALLATION OF THE REFUELING VALVES AND CHECK VALVES - RH TANKS CHECK VALVE (R80QS)					Component	ATA:28	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-70-05-790-801-01		SEALING TEST OF THE NON-RETURN VALVE OF THE PRESSURE REDUCER - PRESSURE REDUCING VALVE (210QD)						Service	ATA:28
PN:B14DE2080	MOS	05-May-22							
SN:1103	HRS	13592.3	7500 (+3%)		21092.3	21317.3	6737.9 (+225)		
WC#: 28.170	AFL	9008							
PROC. REF: AMM 28-70-05-790-801									
28-70-05-900-801-01		REMOVAL / INSTALLATION OF THE PRESSURE REDUCING VALVE - PRESSURE REDUCING VALVE (210QD)						Component	ATA:28
PN:B14DE2080	MOS/MSC	05-May-22	O/C						
SN:1103	HRS	13592.3							
WC#: 28.170	AFL	9008							
PROC. REF: AMM 28-70-05-900-801									
28-70-09-350-801-01		RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - LH VALVE BOX (L260QD)						Service	ATA:28
PN:B04BA1006	MOS	02-Jun-14							
SN:1031	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 28.180	AFL	6566							
PROC. REF: AMM 28-70-09-350-801									
28-70-09-350-801-02		RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - RH VALVE BOX (R260QD)						Service	ATA:28
PN:B04BA1006	MOS	02-Jun-14							
SN:838	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 28.180	AFL	6566							
PROC. REF: AMM 28-70-09-350-801									
28-70-09-900-801-01		REMOVAL / INSTALLATION OF THE VALVE BOXES - LH VALVE BOX (L260QD)						Component	ATA:28
PN:B04BA1006	MOS/MSC	02-Jun-14	O/C	TSR 5					
SN:1031	HRS	9733.1		TSR 0					
WC#: 28.180	AFL	6566		TSR 0					
PROC. REF: AMM 28-70-09-900-801									
28-70-09-900-801-02		REMOVAL / INSTALLATION OF THE VALVE BOXES - RH VALVE BOX (R260QD)						Component	ATA:28
PN:B04BA1006	MOS/MSC	02-Jun-14	O/C	TSR 5					
SN:838	HRS	9733.1		TSR 0					
WC#: 28.180	AFL	6566		TSR 0					
PROC. REF: AMM 28-70-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
28-70-13-350-801-01	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L80QD)							Service	ATA:28
PN:B06GA1052-1	MOS/MSC	13-May-15	O/C						
SN:5830	HRS	10259.8							
	AFL	6931							
PROC. REF: AMM 28-70-13-350-801									
28-70-13-350-801-02	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R80QD)							Service	ATA:28
PN:B06GA1052-1	MOS/MSC	02-Jun-14	O/C						
SN:5335	HRS	9733.1							
	AFL	6566							
PROC. REF: AMM 28-70-13-350-801									
28-70-13-720-802-01	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L80QD)							Service	ATA:28
PN:B06GA1052-1	MOS	13-May-15							
SN:5830	HRS	10259.8	5000 (+3%)		15259.8	15409.8	905.4 (+150)		
WC#: 28.150	AFL	6931							
PROC. REF: AMM 28-70-13-720-802									
28-70-13-720-802-02	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R80QD)							Service	ATA:28
PN:B06GA1052-1	MOS	02-Jun-14							
SN:5335	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 28.150	AFL	6566							
PROC. REF: AMM 28-70-13-720-802									
28-70-13-900-801-01	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L80QD)							Component	ATA:28
PN:B06GA1052-1	MOS/MSC	13-May-15	O/C	TSN 1					
SN:5830	HRS	10259.8		TSN 0					
WC#: 28.150	AFL	6931		TSN 0					
PROC. REF: AMM 28-70-13-900-801									
28-70-13-900-801-02	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R80QD)							Component	ATA:28
PN:B06GA1052-1	MOS/MSC	02-Jun-14	O/C	TSN 1					
SN:5335	HRS	9733.1		TSN 0					
WC#: 28.150	AFL	6566		TSN 0					
PROC. REF: AMM 28-70-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-17-130-801-01^S CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - FUEL PRESSURIZATION FILTER (90QD) Service ATA:28								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 28.120	AFL	9008						
PROC. REF: AMM 28-70-17-130-801								PKG:21
28-70-17-700-801-01^S CHECK OF FUEL PRESSURIZATION NON-RETURN VALVES FOR JAMMING - LH FUEL NON RETURN VALVE (L60QD) Service ATA:28								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
	AFL	7947	3750					
PROC. REF: AMM 28-70-17-700-801								PKG:31
28-70-17-700-801-02^S CHECK OF FUEL PRESSURIZATION NON-RETURN VALVES FOR JAMMING - RH FUEL NON RETURN VALVE (R60QD) Service ATA:28								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
	AFL	7947	3750					
PROC. REF: AMM 28-70-17-700-801								PKG:31
28-70-21-900-801-01 REMOVAL / INSTALLATION OF THE VENT VALVES - LH VENT VALVE (L355QS) Component ATA:28								
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 28.070	AFL	0			TSN 0			
PROC. REF: AMM 28-70-21-900-801								
28-70-21-900-801-02 REMOVAL / INSTALLATION OF THE VENT VALVES - RH VENT VALVE (R355QS) Component ATA:28								
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 28.070	AFL	0			TSN 0			
PROC. REF: AMM 28-70-21-900-801								
281801 REFUELING FILLER CONNECTOR Component ATA:28								
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 28.030	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
281826 FUELING PANEL Component ATA:28								
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 28.060	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
281831	FUELING MANIFOLD							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281851	LH WING OUTBOARD JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.080	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281856	RH WING OUTBOARD JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.080	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281861	LH WING TANK CENTRAL JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.090	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281866	RH WING TANK CENTRAL JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.090	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281871	LH WING INBOARD JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.100	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
281876	RH WING INBOARD JET-PUMP							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.110	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
281881		LEFT WING CENTER JET-PUMP					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
281886		RIGHT WING CENTER JET-PUMP					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
282806		LH FUEL NON-RETURN VALVE					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
282811		RH FUEL NON-RETURN VALVE					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
282816		FUEL PRESSURIZATION AIR FILTER					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.210	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
285801		FUEL PRESSURE GAUGE					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.340	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
285806		NO. 1 ENGINE FUEL PRESSURE SWITCH					Component		ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.350	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
285811	NO. 2 ENGINE FUEL PRESSURE SWITCH							Component	ATA:28
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.350	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 29 - HYDRAULIC POWER									
29-00-00-280-801-01	SAMPLING OF THE HYDRAULIC FLUID - HYDRAULIC SYSTEM 1							Service	ATA:29
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 29-00-00-280-801									
29-00-00-280-801-02	SAMPLING OF THE HYDRAULIC FLUID - HYDRAULIC SYSTEM 2							Service	ATA:29
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 29-00-00-280-801									
29-10-00-720-801-01 ^S	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 1							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 29.030	AFL	7947	3750						
PROC. REF: AMM 29-10-00-720-801									
29-10-00-720-801-02 ^S	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 2							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 29.030	AFL	7947	3750						
PROC. REF: AMM 29-10-00-720-801									
29-11-01-350-801-01	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - ENGINE 1 HYDRAULIC SYSTEM 1 PUMP (L10GP)							Service	ATA:29
PN:3031749-001	MOS	03-Feb-21						OVERHAUL	
SN:MX648524	HRS	12626.1	4000 (+3%)		16626.1	16746.1	2271.7 (+120)		
WC#: 29.050	AFL	8442							
PROC. REF: AMM 29-11-01-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-01-350-801-02 RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - ENGINE 2 HYDRAULIC SYSTEM 1 PUMP (R10GP) Service ATA:29								
PN:3031749-001	MOS	05-May-22						OVERHAUL
SN:MX697613	HRS	13592.3	4000 (+3%)		17592.3	17712.3	3237.9 (+120)	
WC#: 29.050	AFL	9008						
PROC. REF: AMM 29-11-01-350-801								
29-11-01-350-801-03 RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - ENGINE 2 HYDRAULIC SYSTEM 2 PUMP (5GP) Service ATA:29								
PN:3031749-001	MOS	30-Aug-22						OVERHAUL
SN:MX635244	HRS	13743.8	4000 (+3%)		17743.8	17863.8	3389.4 (+120)	
WC#: 29.060	AFL	9097						
PROC. REF: AMM 29-11-01-350-801								
29-11-01-900-801-01 REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - ENGINE 1 HYDRAULIC SYSTEM 1 PUMP (L10GP) Component ATA:29								
PN:3031749-001	MOS/MSC	03-Feb-21	H/T	TSO 0				
SN:MX648524	HRS	12626.1		TSO 0				
WC#: 29.050	AFL	8442		TSO 0				
PROC. REF: AMM 29-11-01-900-801								
29-11-01-900-801-02 REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - ENGINE 2 HYDRAULIC SYSTEM 1 PUMP (R10GP) Component ATA:29								
PN:3031749-001	MOS/MSC	05-May-22	H/T					
SN:MX697613	HRS	13592.3						
WC#: 29.050	AFL	9008						
PROC. REF: AMM 29-11-01-900-801								
29-11-01-900-801-03 REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - ENGINE 2 HYDRAULIC SYSTEM 2 PUMP (5GP) Component ATA:29								
PN:3031749-001	MOS/MSC	30-Aug-22	H/T	TSO 0				
SN:MX635244	HRS	13743.8		TSO 0				
WC#: 29.060	AFL	9097		TSO 0				
PROC. REF: AMM 29-11-01-900-801								
29-11-21-900-801-01 REMOVAL / INSTALLATION OF THE HYDRAULIC MANIFOLD PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML) Component ATA:29								
PN:AAB019-81D9A	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-21-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-11-21-900-801-02		REMOVAL / INSTALLATION OF THE HYDRAULIC MANIFOLD PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)					Component	ATA:29	
PN:AAB019-81D9A	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-11-21-900-801									
29-11-21-900-801-03		REMOVAL / INSTALLATION OF THE HYDRAULIC MANIFOLD PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)					Component	ATA:29	
PN:AAB019-81D9A	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-11-21-900-801									
29-11-25-900-801-01		REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 1 SYSTEM 1 PUMP PRESSURE SWITCH (L30GJ)					Component	ATA:29	
PN:15H0088PH	MOS/MSC	11-Sep-19	O/C	TSN 0					
SN:5490	HRS	11769.9		TSN 0					
WC#: 29.180	AFL	7953		TSN 0					
PROC. REF: AMM 29-11-25-900-801									
29-11-25-900-801-02		REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 2 SYSTEM 2 PUMP PRESSURE SWITCH (35GJ)					Component	ATA:29	
PN:15H0088PH	MOS/MSC	11-Sep-19	O/C	TSN 0					
SN:5489	HRS	11769.9		TSN 0					
WC#: 29.190	AFL	7953		TSN 0					
PROC. REF: AMM 29-11-25-900-801									
29-11-25-900-801-03		REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 2 SYSTEM 1 PUMP PRESSURE SWITCH (R30GJ)					Component	ATA:29	
PN:15H0088PH	MOS/MSC	27-Jan-13	O/C	TSN 0					
SN:3695	HRS	9067.3		TSN 0					
WC#: 29.180	AFL	6120		TSN 0					
PROC. REF: AMM 29-11-25-900-801									
29-11-25-960-801-01		DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 1 SYSTEM 1 PUMP PRESSURE SWITCH (L30GJ)					Service	ATA:29	
PN:15H0088PH	MOS/MSC	11-Sep-19	O/C						
SN:5490	HRS	11769.9							
WC#: 29.180	AFL	7953							
PROC. REF: AMM 29-11-25-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-25-960-801-02 DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 2 SYSTEM 1 PUMP PRESSURE SWITCH (R30GJ) Service ATA:29								
PN:15H0088PH	MOS/MSC	27-Jan-13	O/C					
SN:3695	HRS	9067.3						
WC#: 29.180	AFL	6120						
PROC. REF: AMM 29-11-25-960-801								
29-11-25-960-801-03 DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - ENGINE 2 SYSTEM 2 PUMP PRESSURE SWITCH (35GJ) Service ATA:29								
PN:15H0088PH	MOS/MSC	11-Sep-19	O/C					
SN:5489	HRS	11769.9						
WC#: 29.190	AFL	7953						
PROC. REF: AMM 29-11-25-960-801								
29-12-05-710-801-01 OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 1 HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (30GPB) Service ATA:29								
	MOS	30-Jan-24	12 (+1m)		30-Jan-25	28-Feb-25	299 d (+29)	
	HRS	14354.4	400 (+40)	Adj -2	14752.4	14792.4	398 (+40)	
	AFL	9502						
PROC. REF: AMM 29-12-05-710-801								
29-12-05-710-801-01A OPERATIONAL TEST OF THE NO.1 ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40) Service ATA:29								
	MOS	30-Jan-24						MANDATORY 5-40
	HRS	14354.4	450		14804.4		450	
	AFL	9502						
PROC. REF: AMM 29-12-05-710-801								
29-12-05-710-801-02 OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (30GPC) Service ATA:29								
	MOS	30-Jan-24	12 (+1m)		30-Jan-25	28-Feb-25	299 d (+29)	
	HRS	14354.4	400 (+40)		14754.4	14794.4	400 (+40)	
	AFL	9502						
PROC. REF: AMM 29-12-05-710-801								
29-12-05-710-801-02A OPERATIONAL TEST OF THE NO.2 ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40) Service ATA:29								
	MOS	30-Jan-24						MANDATORY 5-40
	HRS	14354.4	450		14804.4		450	
	AFL	9502						
PROC. REF: AMM 29-12-05-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-12-05-710-801-03	OPERATIONAL TEST OF THE HYDRAULIC SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM 2 SHUT-OFF VALVE (40GPB)							Service	ATA:29
	MOS	30-Jan-24	12 (+1m)		30-Jan-25	28-Feb-25	299 d (+29)		
	HRS	14354.4	400 (+40)	Adj -2	14752.4	14792.4	398 (+40)		
	AFL	9502							
PROC. REF: AMM 29-12-05-710-801									
29-12-05-710-801-03A	OPERATIONAL TEST OF THE NO.2 ENGINE HYDRAULIC SYSTEM 2 SHUT-OFF VALVE (MANDATORY 5-40)							Service	ATA:29
	MOS	30-Jan-24						MANDATORY 5-40	
	HRS	14354.4	450		14804.4		450		
	AFL	9502							
PROC. REF: AMM 29-12-05-710-801									
29-13-09-960-801-01 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 1 HYDRAULIC SYSTEM 1 DELIVERY FILTER (P11) (300GP1)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 29-13-09-960-801									
PKG:31									
29-13-09-960-801-02 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 2 HYDRAULIC SYSTEM 1 DELIVERY FILTER (P12) (300GP2)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 29-13-09-960-801									
PKG:31									
29-13-09-960-801-03 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 1 HYDRAULIC SYSTEM 1 RETURN FILTER (CD12) (300GP3)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 29-13-09-960-801									
PKG:31									
29-13-09-960-801-04 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 2 HYDRAULIC SYSTEM 1 RETURN FILTER (CD11) (300GP4)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 29-13-09-960-801									
PKG:31									
29-13-09-960-801-05 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC SYSTEM 1 GENERAL RETURN FILTER (RET) (300GP5)							Service	ATA:29
	MOS	16-Nov-22	72 (+2m)						
	HRS	13854.5							
	AFL	9172	3750						
PROC. REF: AMM 29-13-09-960-801									
PKG:31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-13-09-960-801-06 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 2 HYDRAULIC SYSTEM 2 DELIVERY FILTER (P2) (320GP1)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 29-13-09-960-801							PKG:31	
29-13-09-960-801-07 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - ENGINE 2 HYDRAULIC SYSTEM 2 RETURN FILTER (CD2) (320GP2)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 29-13-09-960-801							PKG:31	
29-13-09-960-801-08 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC SYSTEM 2 GENERAL RETURN FILTER (RET) (320GP3)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 29-13-09-960-801							PKG:31	
29-13-09-960-801-09 ^S	REPLACEMENT OF THE HYDRAULIC FILTERS - STAND-BY PUMP DELIVERY FILTER (ST-BY) (320GP4)							Service	ATA:29
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 29-13-09-960-801							PKG:31	
29-14-01-610-801-01	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (30GP)							Service	ATA:29
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 29-14-01-610-801								
29-14-01-610-801-02	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (40GP)							Service	ATA:29
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 29-14-01-610-801								
29-14-01-680-801-01	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (30GP)							Service	ATA:29
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 29.080	AFL	6131							
	PROC. REF: AMM 29-14-01-680-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-14-01-680-801-02	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (40GP)							Service	ATA:29
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 29.080	AFL	6131							
PROC. REF: AMM 29-14-01-680-801									
29-14-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (30GP)							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.070	AFL	0		TSN 0					
PROC. REF: AMM 29-14-01-900-801									
29-14-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (40GP)							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.070	AFL	0		TSN 0					
PROC. REF: AMM 29-14-01-900-801									
29-14-11-780-801-01	CHECK OF THE HYDRAULIC SYSTEM 1 ACCUMULATOR CAPACITY - SYSTEM 1 HYDRAULIC ACCUMULATOR (L150GP)							Service	ATA:29
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 29.250	AFL	6131							
PROC. REF: AMM 29-14-11-780-801									
29-14-11-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 HYDRAULIC ACCUMULATOR (L150GP)							Component	ATA:29
PN:60967-1	MOS/MSC	19-Aug-11	O/C						
SN:EFS1361	HRS	8123							
WC#: 29.040	AFL	5461							
PROC. REF: AMM 29-14-11-900-801									
29-14-11-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 HYDRAULIC ACCUMULATOR (R150GP)							Component	ATA:29
PN:60967-1	MOS/MSC	12-Apr-09	O/C						
SN:TRS-2600	HRS	6726.6							
WC#: 29.040	AFL	4514							
PROC. REF: AMM 29-14-11-900-801									
29-15-01-130-801-01 ^S	CLEANING OF THE PRESSURIZATION AIR FILTER OF THE HYDRAULIC RESERVOIR - HYDRAULIC RESERVOIRS PRESSURIZATION FILTER (250GP)							Service	ATA:29
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 29.010	AFL	9008							
PROC. REF: AMM 29-15-01-130-801									

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-20-00-720-801-02		FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 2						Service	ATA:29
	MOS	11-Dec-23							
	HRS	14292.8	5000 (+40)	Adj -205.2	19087.6	19127.6	4733.2 (+40)		
	AFL	9471							
PROC. REF: AMM 29-20-00-720-801									
29-20-01-900-801-01		REMOVAL / INSTALLATION OF THE STAND-BY ELECTRIC PUMP - STANDBY ELECTRIC PUMP (10GS)						Component	ATA:29
PN:42032	MOS/MSC	02-Jun-14	O/C						
SN:AB773	HRS	9733.1							
WC#: 29.130	AFL	6566							
PROC. REF: AMM 29-20-01-900-801									
29-20-03-220-801-01		CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (10GS)						Service	ATA:29
PN:42032	MOS	02-Jun-14							
SN:AB773	HRS	9733.1	5000 (+3%)		14733.1	14883.1	378.7 (+150)		
WC#: 29.130	AFL	6566							
PROC. REF: AMM 29-20-03-220-801									
29-20-03-720-801-01		FUNCTIONAL TEST OF THE STANDBY ELECTRIC PUMP MOTOR - STANDBY ELECTRIC PUMP (10GS)						Service	ATA:29
PN:42032	MOS/MSC	02-Jun-14	O/C						
SN:AB773	HRS	9733.1							
WC#: 29.130	AFL	6566							
PROC. REF: AMM 29-20-03-720-801									
29-20-05-900-801-01		REMOVAL / INSTALLATION OF THE STANDBY PUMP SELECTOR VALVE - STANDBY PUMP SELECTOR VALVE (20GS)						Component	ATA:29
PN:B94A13-205	MOS/MSC	12-Nov-21	O/C						
SN:A09655	HRS	13187.6							
WC#: 29.160	AFL	8784							
PROC. REF: AMM 29-20-05-900-801									
29-20-07-900-801-01		REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L30GS)						Component	ATA:29
PN:15H0091PH	MOS/MSC	11-Sep-19	O/C	TSN 0					
SN:3186	HRS	11769.9		TSN 0					
WC#: 29.150	AFL	7953		TSN 0					
PROC. REF: AMM 29-20-07-900-801									
29-20-07-900-801-02		REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R30GS)						Component	ATA:29
PN:15H0091PH	MOS/MSC	27-Jul-22	O/C	TSN 0					
SN:4061	HRS	13675.4		TSN 0					
WC#: 29.150	AFL	9059		TSN 0					
PROC. REF: AMM 29-20-07-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
29-20-07-960-801-01		DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L30GS)					Service	ATA:29	
PN:15H0091PH	MOS/MSC	11-Sep-19	O/C						
SN:3186	HRS	11769.9							
WC#: 29.150	AFL	7953							
PROC. REF: AMM 29-20-07-960-801									
29-20-07-960-801-02		DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R30GS)					Service	ATA:29	
PN:15H0091PH	MOS/MSC	27-Jul-22	O/C						
SN:4061	HRS	13675.4							
WC#: 29.150	AFL	9059							
PROC. REF: AMM 29-20-07-960-801									
29-30-05-900-801-01		REMOVAL / INSTALLATION OF THE HYDRAULIC MANIFOLD PRESSURE SENSORS - SYSTEM 1 PRESSURE SENSOR (L10GJ)					Component	ATA:29	
PN:64279-530-2	MOS/MSC	21-May-13	O/C	TSR 0					
SN:4669	HRS	9131.5		TSR 0					
WC#: 29.170	AFL	6158		TSR 0					
PROC. REF: GENERIC NO REF									
29-30-05-900-801-02		REMOVAL / INSTALLATION OF THE HYDRAULIC MANIFOLD PRESSURE SENSORS - SYSTEM 2 PRESSURE SENSOR (R10GJ)					Component	ATA:29	
PN:64279-530-2	MOS/MSC	06-Oct-17	O/C	TSN 0					
SN:6647	HRS	11164.8		TSN 0					
WC#: 29.170	AFL	7535		TSN 0					
PROC. REF: GENERIC NO REF									
291801		HYDRAULIC SYSTEM PRESSURE REDUCER					Component	ATA:29	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291811		HYDRAULIC SYSTEM SOLENOID SHUT-OFF VALVE					Component	ATA:29	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291821		NO.1 SYSTEM ACCUMULATOR PRESSURE GAUGE					Component	ATA:29	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
291831	NO.2 SYSTEM ACCUMULATOR PRESSURE GAUGE							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291841	NO.1 HYDRAULIC SYSTEM MANIFOLD							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291851	NO.2 HYDRAULIC SYSTEM MANIFOLD							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291856	HYDRAULIC TANK AIR FILTER							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
291861	NO.1 HYDRAULIC SYSTEM RESERVOIR GAUGE							Component	ATA:29
PN:768345-1	MOS/MSC	22-Nov-13	O/C	TSR 0					
SN:0306	HRS	9419.6		TSR 0					
WC#: 29.220	AFL	6356		TSR 0					
PROC. REF: GENERIC NO REF									
291862	LEFT ENGINE NO.1 HYDRAULIC SYSTEM SHUT-OFF VALVE							Component	ATA:29
PN:D09BB1002	MOS/MSC	21-Feb-20	O/C	TSO 0					
SN:277	HRS	12088.7		TSO 0					
WC#: 29.230	AFL	8133		TSO 0					
PROC. REF: GENERIC NO REF									
291863	RIGHT ENGINE NO.1 HYDRAULIC SYSTEM SHUT-OFF VALVE							Component	ATA:29
PN:D09BB1002	MOS/MSC	21-Feb-20	O/C	TSO 0					
SN:252	HRS	12088.7		TSO 0					
WC#: 29.230	AFL	8133		TSO 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 29 - HYDRAULIC POWER									
291871	NO.2 HYDRAULIC SYSTEM RESERVOIR GAUGE							Component	ATA:29
PN:768345-2	MOS/MSC	02-Dec-15	O/C	TSR 0					
SN:0892	HRS	10579		TSR 0					
WC#: 29.220	AFL	7153		TSR 0					
PROC. REF: GENERIC NO REF									
291872	RIGHT ENGINE NO.2 HYDRAULIC SYSTEM SHUT-OFF VALVE							Component	ATA:29
PN:D09BB1002	MOS/MSC	21-Feb-20	O/C	TSO 0					
SN:512	HRS	12088.7		TSO 0					
WC#: 29.230	AFL	8133		TSO 0					
PROC. REF: GENERIC NO REF									
292810	STAND-BY HYDRAULIC PUMP							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
293851	NO.1 SYSTEM RESERVOIR HYDRAULIC PRESSURE SWITCH							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
293861	NO.2 SYSTEM RESERVOIR PRESSURE SWITCH							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
293871	FLAP HYDRAULIC SUPPLY FLOW LIMITER							Component	ATA:29
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.240	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 30 - ICE AND RAIN PROTECTION									
30-11-09-350-801-01	RESTORATION OF THE OUTBOARD SLAT TELESCOPIC DUCTS (OVERHAUL) - LH TELESCOPIC DUCT (30DL)							Service	ATA:30
PN:5035-600	MOS/MSC	05-May-22	N/A						
SN:891	HRS	13592.3							
WC#: 30.020	AFL	9008							
PROC. REF: AMM 30-11-09-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-09-350-801-01A RESTORATION LH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL) (MANDATORY 5-40) Service ATA:30								
PN:5035-600	MOS/MSC	05-May-22	N/A					
SN:891	HRS	13592.3						
WC#: 30.020	AFL	9008						
PROC. REF: AMM 30-11-09-350-801								
30-11-09-350-801-02 RESTORATION OF THE OUTBOARD SLAT TELESCOPIC DUCTS (OVERHAUL) - RH TELESCOPIC DUCT (40DL) Service ATA:30								
PN:5035-700	MOS/MSC	22-Nov-13	N/A					
SN:302	HRS	9419.6						
WC#: 30.020	AFL	6356						
PROC. REF: AMM 30-11-09-350-801								
30-11-09-350-801-02A RESTORATION RH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL) (MANDATORY 5-40) Service ATA:30								
PN:5035-700	MOS/MSC	22-Nov-13	N/A					
SN:302	HRS	9419.6						
WC#: 30.020	AFL	6356						
PROC. REF: AMM 30-11-09-350-801								
30-11-09-720-801-01 FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (30DL) Service ATA:30								
PN:5035-600	MOS	05-May-22						
SN:891	HRS	13592.3	2480 (+3%)		16072.3	16146.7	1717.9 (+74.4)	
WC#: 30.020	AFL	9008	2000 (+3%)		11008	11068	1506 (+60)	
PROC. REF: AMM 30-11-09-720-801								
30-11-09-720-801-02 FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (40DL) Service ATA:30								
PN:5035-700	MOS	05-May-22						
SN:302	HRS	13592.3	1240 (+3%)		14832.3	14869.5	477.9 (+37.2)	
WC#: 30.020	AFL	9008	1000 (+3%)		10008	10038	506 (+30)	
PROC. REF: AMM 30-11-09-720-801								
30-11-09-900-801-01 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (30DL) Component ATA:30								
PN:5035-600	MOS/MSC	22-Nov-13	O/C					
SN:891	HRS	9419.6						
WC#: 30.020	AFL	6356						
PROC. REF: AMM 30-11-09-900-801								
30-11-09-900-801-02 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (40DL) Component ATA:30								
PN:5035-700	MOS/MSC	22-Nov-13	O/C					
SN:302	HRS	9419.6						
WC#: 30.020	AFL	6356						
PROC. REF: AMM 30-11-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 30 - ICE AND RAIN PROTECTION									
30-11-11-280-801-01	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE							Service	ATA:30
	MOS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
	AFL	7323							
	PROC. REF: AMM 30-11-11-280-801								
30-11-11-280-801-02	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE							Service	ATA:30
	MOS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
	AFL	7323							
	PROC. REF: AMM 30-11-11-280-801								
30-11-17-200-801-01 ^S	INSPECTION OF THE WING ANTI-ICING SYSTEM COUPLINGS							Service	ATA:30
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 30.010	AFL	7947	3750						
	PROC. REF: AMM 30-11-17-200-801							PKG:31	
30-12-01-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING VALVE - WING ANTI-ICING VALVE (20DL)							Component	ATA:30
PN:BYLB52188-6	MOS/MSC	03-Dec-10	O/C						
SN:274	HRS	7703.1							
WC#: 30.150	AFL	5161							
	PROC. REF: AMM 30-12-01-900-801								
30-20-00-710-801-01 ^S	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 1							Service	ATA:30
	MOS	28-Feb-23							
	HRS	13865.3	1600 (+40)						
WC#: 30.040	AFL	9179							
	PROC. REF: AMM 30-20-00-710-801							PKG:21	
30-20-00-710-801-02 ^S	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 2							Service	ATA:30
	MOS	28-Feb-23							
	HRS	13865.3	1600 (+40)						
WC#: 30.040	AFL	9179							
	PROC. REF: AMM 30-20-00-710-801							PKG:21	
30-20-01-700-801-01	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - LH ENGINE AIR INTAKE ANTI-ICING VALVE (L10DN)							Service	ATA:30
PN:C142268-3	MOS	24-Jan-18							
SN:427	HRS	11316.5	5000 (+3%)		16316.5	16466.5	1962.1 (+150)		
WC#: 30.050	AFL	7622							
	PROC. REF: AMM 30-20-01-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 30 - ICE AND RAIN PROTECTION									
30-20-01-700-801-02		FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - RH ENGINE AIR INTAKE ANTI-ICING VALVE (R10DN)					Service	ATA:30	
PN:C142268-3	MOS	05-May-22							
SN:612	HRS	13592.3	5000 (+3%)		18592.3	18742.3	4237.9 (+150)		
WC#: 30.050	AFL	9008							
PROC. REF: AMM 30-20-01-700-801									
30-20-01-900-801-01		REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - LH ENGINE AIR INTAKE ANTI-ICING VALVE (L10DN)					Component	ATA:30	
PN:C142268-3	MOS/MSC	24-Jan-18	O/C	TSR 0					
SN:427	HRS	11316.5		TSR 0					
WC#: 30.050	AFL	7622		TSR 0					
PROC. REF: GENERIC NO REF									
30-20-01-900-801-02		REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - RH ENGINE AIR INTAKE ANTI-ICING VALVE (R10DN)					Component	ATA:30	
PN:C142268-3	MOS/MSC	13-Nov-10	O/C	TSR 0					
SN:612	HRS	7688.8		TSR 0					
WC#: 30.050	AFL	5148		TSR 0					
PROC. REF: GENERIC NO REF									
30-30-00-710-801-01 ^S		OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM					Service	ATA:30	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 30.080	AFL	9008							
PROC. REF: AMM 30-30-00-710-801									
30-41-00-200-801-01 ^S		INSPECTION OF THE WINDSHIELD HEATING SYSTEM CONNECTORS					Service	ATA:30	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 30-41-00-200-801									
30-41-00-710-801-01 ^S		OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM					Service	ATA:30	
	MOS	05-May-22							
	HRS	13592.3	4800 (+40)						
WC#: 30.130	AFL	9008							
PROC. REF: AMM 30-41-00-710-801									
30-41-01-900-801-01		REMOVAL / INSTALLATION OF THE WINDSHIELD RESISTOR BOXES - LH WINDSHIELD RESISTOR BOX (L503DG)					Component	ATA:30	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-41-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 30 - ICE AND RAIN PROTECTION									
30-41-01-900-801-02		REMOVAL / INSTALLATION OF THE WINDSHIELD RESISTOR BOXES - RH WINDSHIELD RESISTOR BOX (R503DG)					Component	ATA:30	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-41-01-900-801									
30-43-05-900-801-01		REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - LH WINDSHIELD WIPER MOTOR (10DG)					Component	ATA:30	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.090	AFL	0		TSN 0					
PROC. REF: AMM 30-43-05-900-801									
30-43-05-900-801-02		REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - RH WINDSHIELD WIPER MOTOR (15DG)					Component	ATA:30	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.090	AFL	0		TSN 0					
PROC. REF: AMM 30-43-05-900-801									
30-43-09-220-801-01		CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - LH WINDSHIELD WIPER MOTOR (10DG)					Service	ATA:30	
PN:PN	MOS	01-Mar-00							
SN:UNKNOWN	HRS	0	15000 (+3%)		15000	15450	645.6 (+450)		
WC#: 30.090	AFL	0							
PROC. REF: AMM 30-43-09-220-801									
30-43-09-220-801-02		CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - RH WINDSHIELD WIPER MOTOR (15DG)					Service	ATA:30	
PN:PN	MOS	01-Mar-00							
SN:UNKNOWN	HRS	0	15000 (+3%)		15000	15450	645.6 (+450)		
WC#: 30.090	AFL	0							
PROC. REF: AMM 30-43-09-220-801									
30-90-00-710-801-01 ^S		OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM					Service	ATA:30	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 30.140	AFL	9008							
PROC. REF: AMM 30-90-00-710-801									
301801		LH WING ANTI-ICING PRESSURE SWITCH					Component	ATA:30	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301811 RH WING ANTI-ICING PRESSURE SWITCH Component ATA:30								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
302801 LH ENGINE ANTI-ICING LOW PRESSURE SWITCH Component ATA:30								
PN:8G1199-5	MOS/MSC	11-Jun-08	O/C	TSO 0				
SN:2928	HRS	6227.8		TSO 0				
WC#: 30.060	AFL	4154		TSO 0				
PROC. REF: GENERIC NO REF								
302811 RH ENGINE ANTI-ICING LOW PRESSURE SWITCH Component ATA:30								
PN:8G1199-5	MOS/MSC	23-Oct-07	O/C					
SN:0090	HRS	5738.8						
WC#: 30.060	AFL	3854						
PROC. REF: GENERIC NO REF								
302821 LH ENGINE ANTI-ICING HIGH PRESSURE SWITCH Component ATA:30								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
302831 RH ENGINE ANTI-ICING HIGH PRESSURE SWITCH Component ATA:30								
PN:8G1340-4	MOS/MSC	01-May-04	O/C	TSN 0				
SN:490	HRS	2335.4		TSN 0				
WC#: 30.070	AFL	1653		TSN 0				
PROC. REF: GENERIC NO REF								
304801 PILOT WINDSHIELD HEATING REGULATOR Component ATA:30								
PN:AV30559060030-1	MOS/MSC	23-Sep-05	O/C					
SN:722	HRS	3830						
WC#: 30.100	AFL	2634						
PROC. REF: GENERIC NO REF								
304811 COPILOT WINDSHIELD HEATING REGULATOR Component ATA:30								
PN:AV30559060030-1	MOS/MSC	23-Sep-05	O/C					
SN:723	HRS	3830						
WC#: 30.100	AFL	2634						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 30 - ICE AND RAIN PROTECTION									
304821	REAR WINDOW HEATING REGULATOR							Component	ATA:30
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
304831	LATERAL WINDOW HEATING REGULATOR							Component	ATA:30
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-11-01-900-801-01	REMOVAL / INSTALLATION OF THE OVERHEAD PANEL - OVERHEAD PANEL (180PC)							Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.115	AFL	0		TSN 0					
PROC. REF: AMM 31-11-01-900-801									
31-11-47-900-801-01	OVERHEAD PANEL "BAT" (145PC) MAGNETIC SWITCH							Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
31-11-47-900-801-03	OVERHEAD PANEL "GEN 1" (L140PC) MAGNETIC SWITCH							Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
31-11-47-900-801-04	OVERHEAD PANEL "GEN 2" (R140PC) MAGNETIC SWITCH							Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-11-47-900-801-05		OVERHEAD PANEL "APU" (135PC) MAGNETIC SWITCH							Component ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
31-21-05-900-801-01		PILOT CLOCK							Component ATA:31
PN:M877-24HR	MOS/MSC	21-Sep-12	O/C						
SN:11116	HRS	8893							
WC#: 31.020	AFL	5992							
PROC. REF: GENERIC NO REF									
31-21-05-900-801-02		COPILOT CLOCK							Component ATA:31
PN:M877-24HR	MOS/MSC	21-Sep-12	O/C						
SN:11117	HRS	8893							
WC#: 31.020	AFL	5992							
PROC. REF: GENERIC NO REF									
31-21-05-960-801-01		REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (L10FS) BATTERY							Service ATA:31
PN:M877-24HR	MOS	05-May-22	25		05-Jun-24		60 d	LIFE LIMIT	
SN:11116	HRS	13592.3							
WC#: 31.020	AFL	9008							
PROC. REF: AMM 31-21-05-960-801									
31-21-05-960-801-02		REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (R10FS) BATTERY							Service ATA:31
PN:M877-24HR	MOS	05-May-22	25		05-Jun-24		60 d	LIFE LIMIT	
SN:11117	HRS	13592.3							
WC#: 31.020	AFL	9008							
PROC. REF: AMM 31-21-05-960-801									
31-31-00-710-802-01 ^S		OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM							Service ATA:31
	MOS	16-Jul-19	36 (+1m)						
	HRS	11761.3							
WC#: 31.110	AFL	7947							
PROC. REF: AMM 31-31-00-710-802									
31-31-00-720-801-01		FUNCTIONAL TEST OF THE 88-PARAMETER FDR - FDR (715FZ)							Service ATA:31
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
WC#: 31.130	AFL	0							
PROC. REF: AMM 31-31-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-00-720-802-01 FUNCTIONAL TEST OF THE 57-PARAMETER FDR - FDR (715FZ) Service ATA:31								
	MOS/MSC	21-Sep-12	A/R					
	HRS	8893						
WC#: 31.130	AFL	5992						
PROC. REF: AMM 31-31-00-720-802								
31-31-00-720-803-01 FUNCTIONAL TEST OF THE 32-PARAMETER FDR - FDR (715FZ) Service ATA:31								
	MOS/MSC	20-May-16	O/C					
	HRS	10730.7						
WC#: 31.170	AFL	7258						
PROC. REF: AMM 31-31-00-720-803, AMM 31-31-00-720-803								
31-31-00-970-801-01 DOWNLOAD OF THE FLIGHT DATA RECORDER (FDR) - FDR (715FZ) Service ATA:31								
	MOS/MSC	13-May-15	A/R					
	HRS	10259.8						
WC#: 31.110	AFL	6931						
PROC. REF: AMM 31-31-00-970-801								
31-31-09-710-801-01 OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (40FZ) Service ATA:31								
PN:PN-UNKNOWN	MOS	28-Nov-14	240 (+3%)		28-Nov-34	04-Jul-35	3888 d (+218)	
SN:4504	HRS	10116.4						
WC#: 31.080	AFL	6829						
PROC. REF: AMM 31-31-09-710-801								
31-31-09-710-801-02 OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (190FZ) OR (714FZ) Service ATA:31								
PN:PN-UNKNOWN	MOS	28-Nov-14	240 (+3%)		28-Nov-34	04-Jul-35	3888 d (+218)	
SN:4524	HRS	10116.4						
WC#: 31.080	AFL	6829						
PROC. REF: AMM 31-31-09-710-801								
31-31-09-900-801-01 REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (40FZ) Component ATA:31								
PN:PN-UNKNOWN	MOS/MSC	17-Dec-08	O/C					
SN:4504	HRS	6549.1						
WC#: 31.080	AFL	4386						
PROC. REF: AMM 31-31-09-900-801								
31-31-09-900-801-02 REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (190FZ) OR (714FZ) Component ATA:31								
PN:PN-UNKNOWN	MOS/MSC	17-Dec-08	O/C					
SN:4524	HRS	6549.1						
WC#: 31.080	AFL	4386						
PROC. REF: AMM 31-31-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-31-900-801-01 REMOVAL / INSTALLATION OF THE FLIGHT DATA RECORDER (FDR) - FDR (130FZ)								
PN:980-4710-001	MOS/MSC	27-Oct-14	O/C	TSR 0				Component ATA:31
SN:0256	HRS	10050.6		TSR 0				
WC#: 31.110	AFL	6787		TSR 0				
PROC. REF: AMM 31-31-31-900-801								
31-31-33-900-801-01 REMOVAL / INSTALLATION / ADJUSTMENT OF THE FDR FLIGHT CONTROL SURFACE POSITION SENSORS - LH ROLL CONTROL SURFACE POSITION SENSOR (201FZ)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-33-900-801								
31-31-33-900-801-02 REMOVAL / INSTALLATION / ADJUSTMENT OF THE FDR FLIGHT CONTROL SURFACE POSITION SENSORS - RH ROLL CONTROL SURFACE POSITION SENSOR (202FZ)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-33-900-801								
31-31-33-900-801-03 REMOVAL / INSTALLATION / ADJUSTMENT OF THE FDR FLIGHT CONTROL SURFACE POSITION SENSORS - PITCH CONTROL SURFACE POSITION SENSOR (203FZ)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-33-900-801								
31-31-33-900-801-04 REMOVAL / INSTALLATION / ADJUSTMENT OF THE FDR FLIGHT CONTROL SURFACE POSITION SENSORS - YAW CONTROL SURFACE POSITION SENSOR (204FZ)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-33-900-801								
31-31-37-900-801-01 REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - PITCH CONTROL POSITION POTENTIOMETER (160FZ)								
PN:1002000M00	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-37-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-37-900-801-02	REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - YAW CONTROL POSITION POTENTIOMETER (170FZ)						Component	ATA:31
PN:1002000M00	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-37-900-801								
31-31-37-900-801-03	REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - ROLL CONTROL POSITION POTENTIOMETER (180FZ)						Component	ATA:31
PN:1002000M00	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-37-900-801								
31-31-38-900-801-01	REMOVAL / INSTALLATION OF THE FDR ACCELEROMETER - ACCELEROMETER (150FZ)						Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.160	AFL	0		TSN 0				
PROC. REF: AMM 31-31-38-900-801								
31-31-50-350-801-01	RESTORATION OF THE COCKPIT VOICE RECORDER (OVERHAUL) - CVR (10FZ)						Service	ATA:31
PN:980-6023-002	MOS/MSC	26-Aug-11	O/C					
SN:11365	HRS	8142.2						
WC#: 31.100	AFL	5473						
PROC. REF: AMM 31-31-50-350-801								
31-31-50-710-801-01 ^S	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM - CVR (10FZ)						Service	ATA:31
	MOS	16-Jul-19	36 (+1m)					
	HRS	11761.3						
WC#: 31.100	AFL	7947						
PROC. REF: AMM 31-31-50-710-801								
31-31-50-720-801-01 ^U	FUNCTIONAL TEST OF THE COCKPIT VOICE (CVR) RECORDER						Service	ATA:31
	MOS/MSC	21-Sep-12	O/C					
	HRS	8893						
WC#: 31.125	AFL	5992						
PROC. REF: GENERIC NO REF								

PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-50-970-801-01 DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) - CVR (10FZ) Service ATA:31								
	MOS/MSC	13-May-15	O/C					
	HRS	10259.8						
	AFL	6931						
PROC. REF: AMM 31-31-50-970-801								
31-31-51-900-801-01 REMOVAL / INSTALLATION OF THE COCKPIT VOICE RECORDER (CVR) - CVR (10FZ) Component ATA:31								
PN:980-6023-002	MOS/MSC	26-Aug-11	O/C	TSN 0				
SN:11365	HRS	8142.2		TSN 0				
WC#: 31.100	AFL	5473		TSN 0				
PROC. REF: AMM 31-31-51-900-801								
31-31-56-960-801-01 REPLACEMENT OF THE CVR TAPE - CVR (10FZ) Service ATA:31								
	MOS/MSC		N/A					
	HRS							
WC#: 31.100	AFL							
PROC. REF: AMM 31-31-56-960-801								
31-32-00-970-801-01 DOWNLOAD OF THE QUICK ACCESS RECORDER (QAR) - QAR (720FZ) Service ATA:31								
	MOS/MSC		O/C					
	HRS							
WC#: 31.150	AFL							
PROC. REF: AMM 31-32-00-970-801, AMM 31-32-00-970-801								
31-32-01-900-801-01 REMOVAL / INSTALLATION OF THE QUICK ACCESS RECORDER (QAR) - QAR (720FZ) Component ATA:31								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 31.150	AFL							
PROC. REF: AMM 31-32-01-900-801, AMM 31-32-01-900-801								
31-32-05-960-801-01 REPLACEMENT OF THE QUICK ACCESS RECORDER (QAR) BATTERY - QAR (720FZ) BATTERY Service ATA:31								
PN:PN	MOS/MSC		N/A					
SN:NOT INSTALLED	HRS							
WC#: 31.150	AFL							
PROC. REF: AMM 31-32-05-960-801, AMM 31-32-05-960-801								
31-52-00-710-801-01^S OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY Service ATA:31								
	MOS	05-May-22	36 (+1m)					
	HRS	13592.3	2400 (+40)					
WC#: 31.010	AFL	9008						
PROC. REF: AMM 31-52-00-710-801								

PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-52-03-900-801-01		REMOVAL / INSTALLATION OF THE WARNING PANEL LIGHTS						Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.070	AFL	0		TSN 0					
PROC. REF: AMM 31-52-03-900-801									
31-54-00-720-801-01		FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: ALARM TEST						Service	ATA:31
	MOS	21-Dec-23							
	HRS	14292.8	700	Adj -160.6	14832.2		477.8		
WC#: 31.030	AFL	9471							
PROC. REF: AMM 31-54-00-720-801									
31-54-00-720-801-01A		FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: ALARM TEST (MANDATORY 5-40)						Service	ATA:31
	MOS	21-Dec-23						MANDATORY 5-40	
	HRS	14292.8	700		14992.8		638.4		
WC#: 31.030	AFL	9471							
PROC. REF: AMM 31-54-00-720-801									
31-54-00-720-802-01 ^S		FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST						Service	ATA:31
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 31.140	AFL	9008							
PROC. REF: AMM 31-54-00-720-802									
31-55-00-720-801-01 ^S		FUNCTIONAL TEST OF THE LANDING SAFETIES						Service	ATA:31
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 31.040	AFL	9008							
PROC. REF: AMM 31-55-00-720-801									
31-56-00-900-801-01		REMOVAL / INSTALLATION OF THE AUDIO WARNING UNIT						Component	ATA:31
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
31-60-00-710-801-01 ^S		OPERATIONAL TEST OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED)						Service	ATA:31
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 31.050	AFL	9008							
PROC. REF: AMM 31-60-00-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-60-51-900-801-01 REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 1 (30EA)								
PN:C14000BC04	MOS/MSC	02-May-18	O/C					Component ATA:31
SN:1141	HRS	11576.3						
WC#: 31.060	AFL	7811						
PROC. REF: AMM 31-60-51-900-801								
31-60-51-900-801-02 REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 2 (40EA)								
PN:C14000DB06	MOS/MSC	28-Mar-23	O/C					Component ATA:31
SN:263	HRS	13908.8						
WC#: 31.060	AFL	9201						
PROC. REF: AMM 31-60-51-900-801								
31-60-51-900-801-03 REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 3 (50EA)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:31
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.060	AFL	0		TSN 0				
PROC. REF: AMM 31-60-51-900-801								
ATA 32 - LANDING GEAR								
32-00-00-700-801-01 CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (5GM)								
	MOS/MSC	16-Apr-13	O/C					Service ATA:32
	HRS	9087.6						
WC#: 32.190	AFL	6131						
PROC. REF: AMM 32-00-00-700-801								
32-00-00-700-801-02 CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (120GM)								
	MOS/MSC	09-Dec-20	O/C					Service ATA:32
	HRS							
WC#: 32.220	AFL	8406						
PROC. REF: AMM 32-00-00-700-801								
32-00-00-700-801-03 CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (130GM)								
	MOS/MSC	09-Dec-20	O/C					Service ATA:32
	HRS							
WC#: 32.220	AFL	8406						
PROC. REF: AMM 32-00-00-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-00-00-780-801-01		CHECK OF LANDING GEAR AND L/G DOOR OPERATING PRESSURES						Service	ATA:32
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-00-00-780-801									
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND MLG DOOR						Service	ATA:32
	MOS	29-Sep-23	8 (+1m)	Adj -10d	19-May-24	19-Jun-24	43 d (+31)		
	HRS	14169							
	AFL	9395	400		9795		293		
PROC. REF: AMM 32-10-00-640-801									
32-10-00-640-801-02		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND MLG DOOR						Service	ATA:32
	MOS	29-Sep-23	8 (+1m)	Adj -10d	19-May-24	19-Jun-24	43 d (+31)		
	HRS	14169							
	AFL	9395	400		9795		293		
PROC. REF: AMM 32-10-00-640-801									
32-11-00-220-801-01		DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (5GA)						Service	ATA:32
PN:D23345000-8	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
SN:B76	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-11-00-220-801									
32-11-00-220-801-02		DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (10GA)						Service	ATA:32
PN:D23346000-8	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
SN:B76	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-11-00-220-801									
32-11-00-350-801-01		RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (5GA)						Service	ATA:32
PN:D23345000-8	MOS	22-Mar-12	144 (+3%)		22-Mar-24	31-Jul-24	TOL (+116 d)	OVERHAUL	
SN:B76	HRS	8486.2							
	AFL	5707	6000		11707		2205		
PROC. REF: AMM 32-11-00-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-11-00-350-801-02		RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (10GA)						Service	ATA:32
PN:D23346000-8	MOS	22-Mar-12	144 (+3%)		22-Mar-24	31-Jul-24	TOL (+116 d)	OVERHAUL	
SN:B76	HRS	8486.2							
	AFL	5707	6000		11707		2205		
PROC. REF: AMM 32-11-00-350-801									
32-11-00-700-802-01		CHECK AND ADJUSTMENT OF THE AXIAL PLAY TORQUE LINKS OF THE MAIN LANDING GEARS (MLG) - LH MLG LEG (5GA)						Service	ATA:32
PN:D23345000-8	MOS	07-Aug-18	72 (+3%)		20-Mar-24 (M)	24-May-24	TOL (+48 d)		
SN:B76	HRS	11704.7							
	AFL	7913	3000 (+3%)		10913	11003	1411 (+90)		
PROC. REF: AMM 32-11-00-700-802									
32-11-00-700-802-02		CHECK AND ADJUSTMENT OF THE AXIAL PLAY TORQUE LINKS OF THE MAIN LANDING GEARS (MLG) - RH MLG LEG (10GA)						Service	ATA:32
PN:D23346000-8	MOS	07-Aug-18	72 (+3%)		20-Mar-24 (M)	24-May-24	TOL (+48 d)		
SN:B76	HRS	11704.7							
	AFL	7913	3000 (+3%)		10913	11003	1411 (+90)		
PROC. REF: AMM 32-11-00-700-802									
32-11-00-900-801-01		REMOVAL / INSTALLATION OF THE MLG LEGS - LH MLG LEG (5GA)						Component	ATA:32
PN:D23345000-8	MOS/MSC	22-Mar-12	H/T						
SN:B76	HRS	8486.2							
WC#: 32.020	AFL	5707							
PROC. REF: AMM 32-11-00-900-801									
32-11-00-900-801-02		REMOVAL / INSTALLATION OF THE MLG LEGS - RH MLG LEG (10GA)						Component	ATA:32
PN:D23346000-8	MOS/MSC	22-Mar-12	H/T						
SN:B76	HRS	8486.2							
WC#: 32.030	AFL	5707							
PROC. REF: AMM 32-11-00-900-801									
32-11-00-960-801-01		REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (5GA)						Service	ATA:32
PN:D23345000-8	MOS	22-Mar-12						LIFE LIMIT	
SN:B76	HRS	8486.2							
	AFL	5707	20000		25707		16205		
PROC. REF: AMM 32-11-00-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-960-801-01A REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITEDPARTS) - LH MLG LEG (5GA)								
PN:D23345000-8	MOS	22-Mar-12						Service ATA:32
SN:B76	HRS	8486.2						MANDATORY 5-40
	AFL	5707	20000		25707		16205	
PROC. REF: AMM 32-11-00-960-801								
32-11-00-960-801-02 REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (10GA)								
PN:D23346000-8	MOS	22-Mar-12						Service ATA:32
SN:B76	HRS	8486.2						LIFE LIMIT
	AFL	5707	20000		25707		16205	
PROC. REF: AMM 32-11-00-960-801								
32-11-00-960-801-02A REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITEDPARTS) - RH MLG LEG (10GA)								
PN:D23346000-8	MOS	22-Mar-12						Service ATA:32
SN:B76	HRS	8486.2						MANDATORY 5-40
	AFL	5707	20000		25707		16205	
PROC. REF: AMM 32-11-00-960-801								
32-11-05-610-801-01 SERVICING OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER								
	MOS/MSC	01-Mar-00	O/C					Service ATA:32
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-05-610-801								
32-11-05-610-801-02 SERVICING OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER								
	MOS/MSC	01-Mar-00	O/C					Service ATA:32
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-05-610-801								
32-11-05-780-801-01^S CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (5GA3)								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.020	AFL	9008						
PROC. REF: AMM 32-11-05-780-801								
32-11-05-780-801-02^S CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (10GA3)								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.030	AFL	9008						
PROC. REF: AMM 32-11-05-780-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-05-900-801-01 REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (5GA3) Component ATA:32								
PN:D23365000-4	MOS/MSC	22-Mar-12	H/T					
SN:B77	HRS	8486.2						
WC#: 32.020	AFL	5707						
PROC. REF: AMM 32-11-05-900-801								
32-11-05-900-801-02 REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (10GA3) Component ATA:32								
PN:D23366000-4	MOS/MSC	22-Mar-12	H/T					
SN:B77	HRS	8486.2						
WC#: 32.030	AFL	5707						
PROC. REF: AMM 32-11-05-900-801								
32-11-21-900-801-01 REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - LH MLG BRACE STRUT ACTUATOR (40GA) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
PROC. REF: AMM 32-11-21-900-801								
32-11-21-900-801-02 REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - RH MLG BRACE STRUT ACTUATOR (45GA) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
PROC. REF: AMM 32-11-21-900-801								
32-11-25-220-801-01 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA) Service ATA:32								
	MOS		72 (+8m)		22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	
	HRS							
	AFL							
PROC. REF: AMM 32-11-25-220-801								
32-11-25-220-801-02 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA) Service ATA:32								
	MOS		72 (+8m)		22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	
	HRS							
	AFL							
PROC. REF: AMM 32-11-25-220-801								
32-11-25-220-801-03 DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA) Service ATA:32								
	MOS		72 (+8m)		22-Mar-24 (M)	22-Nov-24	TOL (+230 d)	
	HRS							
	AFL							
PROC. REF: AMM 32-11-25-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)							Service	ATA:32
	MOS		72 (+8m)		22-Mar-24 (M)	22-Nov-24	TOL (+230 d)		
	HRS								
	AFL								
PROC. REF: AMM 32-11-25-220-801									
32-11-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG FRONT BALL-JOINT BEARING (L90GA)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-11-25-900-801									
32-11-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG REAR BALL-JOINT BEARING (L100GA)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-11-25-900-801									
32-11-25-900-801-03	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-11-25-900-801									
32-11-25-900-801-04	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG REAR BALL-JOINT BEARING (R100GA)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-11-25-900-801									
32-12-17-900-801-01	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - LH MLG UPLOCK BOX (120GM)							Component	ATA:32
PN:C24244007-3	MOS/MSC	09-Dec-20	O/C						
SN:H0825	HRS	12515.4							
WC#: 32.220	AFL	8406							
PROC. REF: AMM 32-12-17-900-801									
32-12-17-900-801-02	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - RH MLG UPLOCK BOX (130GM)							Component	ATA:32
PN:C24245007-3	MOS/MSC	09-Dec-20	O/C						
SN:Y00024	HRS	12515.4							
WC#: 32.220	AFL	8406							
PROC. REF: AMM 32-12-17-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-12-25-900-801-01 REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - LH MLG MAIN DOOR ACTUATOR (L50GA) Component ATA:32								
PN:VN1031-2	MOS/MSC	08-Sep-07	O/C	TSR 0				
SN:1353	HRS	5598.6		TSR 0				
WC#: 32.050	AFL	3768		TSR 0				
PROC. REF: AMM 32-12-25-900-801								
32-12-25-900-801-02 REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - RH MLG MAIN DOOR ACTUATOR (R50GA) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.050	AFL	0		TSN 0				
PROC. REF: AMM 32-12-25-900-801								
32-12-29-900-801-01 REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - LH MLG DOOR LATCH (L170GM) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-12-29-900-801-02 REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - RH MLG DOOR LATCH (R170GM) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-20-00-640-801-01 LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS Service ATA:32								
	MOS	29-Sep-23	8 (+1m)	Adj -10d	19-May-24	19-Jun-24	43 d (+31)	
	HRS	14169						
WC#: 32.070	AFL	9395	400		9795		293	
PROC. REF: AMM 32-20-00-640-801								
32-21-00-220-801-01 DETAILED INSPECTION OF THE NLG LEG - NLG LEG (5GB) Service ATA:32								
PN:D23332000-4	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)	
SN:B163	HRS	11761.3						
	AFL	7947						
PROC. REF: AMM 32-21-00-220-801								
32-21-00-350-801-01 RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (5GB) Service ATA:32								
PN:D23332000-4	MOS	30-Jan-15	144 (+3%)		30-Jan-27	08-Jun-27	1029 d (+129)	OVERHAUL
SN:B163	HRS	10131.5						
	AFL	6839	6000		12839		3337	
PROC. REF: AMM 32-21-00-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-00-900-801-01 REMOVAL / INSTALLATION OF THE NLG LEG - NLG LEG (5GB)								Component ATA:32
PN:D23332000-4	MOS/MSC	30-Jan-15	H/T	TSO 0				
SN:B163	HRS	10131.5		TSO 0				
WC#: 32.080	AFL	6839		TSO 0				
PROC. REF: AMM 32-21-00-900-801								
32-21-00-960-801-01 REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (5GB)								Service ATA:32
PN:D23332000-4	MOS							LIFE LIMIT
SN:B163	HRS							
	AFL		20000		26839 (M)		17337	
PROC. REF: AMM 32-21-00-960-801								
32-21-00-960-801-01A REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITEDPARTS) - NLG LEG (5GB)								Service ATA:32
PN:D23332000-4	MOS							MANDATORY 5-40
SN:B163	HRS							
	AFL		20000		26839 (M)		17337	
PROC. REF: AMM 32-21-00-960-801								
32-21-01-610-801-01 SERVICING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER								Service ATA:32
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-21-01-610-801								
32-21-01-780-801-01 ^S CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (5GB5)								Service ATA:32
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 32.110	AFL	9008						
PROC. REF: AMM 32-21-01-780-801								
32-21-01-780-802-01 CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE - NLG SHOCK ABSORBER								Service ATA:32
	MOS/MSC	10-Sep-15	N/A					
	HRS	10489.8						
WC#: 32.720	AFL	7089						
PROC. REF: AMM 32-21-01-780-802								
32-21-01-900-801-01 REMOVAL / INSTALLATION OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (5GB5)								Component ATA:32
PN:D23367000-1	MOS/MSC	21-Sep-12	H/T	TSO 0				
SN:B128	HRS	8893		TSO 0				
WC#: 32.080	AFL	5992		TSO 0				
PROC. REF: AMM 32-21-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-21-09-220-801-01	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING							Service	ATA:32
	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-21-09-220-801									
32-21-09-220-801-02	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING							Service	ATA:32
	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-21-09-220-801									
32-21-09-220-801-03	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING							Service	ATA:32
	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-21-09-220-801									
32-21-09-220-801-04	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING							Service	ATA:32
	MOS	16-Jul-19	72 (+8m)		16-Jul-25	16-Mar-26	466 d (+243)		
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 32-21-09-220-801									
32-21-09-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG DRAG BRACE BALL-JOINT BEARING							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-21-09-900-801									
32-21-09-900-801-02	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG DRAG BRACE BALL-JOINT BEARING							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-21-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-09-900-801-03 REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG LEG BALL-JOINT BEARING								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-09-900-801								
32-21-09-900-801-04 REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG LEG BALL-JOINT BEARING								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-09-900-801								
32-22-01-350-801-01 RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (20GB)								
PN:GA62269	MOS	19-Jan-23	144 (+3%)		19-Jan-35	28-May-35	3940 d (+129)	Service OVERHAUL ATA:32
SN:649	HRS	13859.4						
WC#: 32.080	AFL	9175	6000		15175		5673	
PROC. REF: AMM 32-22-01-350-801								
32-22-01-900-801-01 REMOVAL / INSTALLATION OF THE NLG DRAG BRACE - NLG DRAG BRACE (20GB)								
PN:D23334000-1	MOS/MSC	20-Apr-10	O/C					Component ATA:32
SN:245	HRS	7299.5						
WC#: 32.080	AFL	4889						
PROC. REF: AMM 32-22-01-900-801								
32-22-13-900-801-01 REMOVAL / INSTALLATION OF THE NLG ACTUATOR - NLG LEG ACTUATOR (10GB)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
PROC. REF: AMM 32-22-13-900-801								
32-22-17-900-801-01 REMOVAL / INSTALLATION OF THE NLG UPLOCK BOX - NLG UPLOCK BOX (5GM)								
PN:C24245006-3	MOS/MSC	03-Dec-10	O/C					Component ATA:32
SN:H1310	HRS	7703.1						
WC#: 32.190	AFL	5161						
PROC. REF: AMM 32-22-17-900-801								
32-30-00-720-801-01^S FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - NORMAL OPERATION								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.140	AFL	9008						
PROC. REF: AMM 32-30-00-720-801								

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30-00-720-801-02^S FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - HYDRAULIC EMERGENCY OPERATION								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.140	AFL	9008						
PROC. REF: AMM 32-30-00-720-801								PKG:21
32-30-00-720-801-03^S FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - MECHANICAL EMERGENCY OPERATION								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.140	AFL	9008						
PROC. REF: AMM 32-30-00-720-801								PKG:21
32-30-13-900-801-01 REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY SELECTOR VALVE - L/G NORMAL/EMERGENCY SELECTOR VALVE (140GM)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.230	AFL	0		TSN 0				
PROC. REF: AMM 32-30-13-900-801								
32-31-00-700-801-01^S CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND								
	MOS	05-May-22						Service ATA:32
	HRS	13592.3	1600 (+40)					
WC#: 32.170	AFL	9008						
PROC. REF: AMM 32-31-00-700-801								PKG:21
32-31-01-900-801-01 REMOVAL / INSTALLATION OF THE LANDING GEAR CONTROL LEVER - L/G CONTROL LEVER (100GM)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.210	AFL	0		TSN 0				
PROC. REF: AMM 32-31-01-900-801								
32-31-17-900-801-02 REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR HYDRAULIC SUPPLY UNIT SOLENOID VALVES - L/G EXTENSION SOLENOID VALVE (150GM1E)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.240	AFL	0		TSN 0				
PROC. REF: AMM 32-31-17-900-801								
32-32-00-640-801-01^S SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL								
	MOS	27-Dec-23	24 (+1m)					Service ATA:32
	HRS	14292.8						
WC#: 32.160	AFL	9471						
PROC. REF: AMM 32-32-00-640-801								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-00-640-801-02^S SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE								
	MOS	27-Dec-23	24 (+1m)					Service ATA:32
	HRS	14292.8						
	AFL	9471						
					PROC. REF: AMM 32-32-00-640-801			PKG:16
32-32-00-640-801-03^S SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS								
	MOS	27-Dec-23	24 (+1m)					Service ATA:32
	HRS	14292.8						
	AFL	9471						
					PROC. REF: AMM 32-32-00-640-801			PKG:16
32-32-00-640-801-04^S SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE								
	MOS	27-Dec-23	24 (+1m)					Service ATA:32
	HRS	14292.8						
	AFL	9471						
					PROC. REF: AMM 32-32-00-640-801			PKG:16
32-32-00-700-801-01 CHECK AFTER LANDING GEAR EMERGENCY EXTENSION								
	MOS/MSC		A/R					Service ATA:32
	HRS							
WC#: 32.820	AFL							
					PROC. REF: AMM 32-32-00-700-801			
32-32-05-900-801-01 REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - RH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (260GM)								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
					PROC. REF: GENERIC NO REF			
32-32-05-900-801-02 REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - LH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (261GM)								
PN:4806567	MOS/MSC	03-Dec-10	O/C					Component ATA:32
SN:15191	HRS	7703.1						
WC#: 32.290	AFL	5161						
					PROC. REF: GENERIC NO REF			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-17-640-801-01 ^S	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENSION CONTROL						Service	ATA:32
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
WC#: 32.150	AFL	9471						
					PROC. REF: AMM 32-32-17-640-801		PKG:16	
32-32-17-640-801-02 ^S	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS						Service	ATA:32
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
	AFL	9471						
					PROC. REF: AMM 32-32-17-640-801		PKG:16	
32-32-17-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (250GM)						Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.180	AFL	0		TSN 0				
					PROC. REF: AMM 32-32-17-900-801			
32-40-00-780-801-01 ^S	CHECK OF BRAKING PRESSURES - SYSTEM 1						Service	ATA:32
	MOS	05-May-22						
	HRS	13592.3	3200 (+40)					
WC#: 32.380	AFL	9008						
					PROC. REF: AMM 32-40-00-780-801		PKG:22	
32-40-00-780-801-02 ^S	CHECK OF BRAKING PRESSURES - SYSTEM 2						Service	ATA:32
	MOS	05-May-22						
	HRS	13592.3	3200 (+40)					
WC#: 32.380	AFL	9008						
					PROC. REF: AMM 32-40-00-780-801		PKG:22	
32-41-00-220-801-01 ^S	DETAILED INSPECTION OF THE BRAKE LINKAGE CONTROL						Service	ATA:32
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
WC#: 32.420	AFL	9471						
					PROC. REF: AMM 32-41-00-220-801		PKG:16	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-02-900-801-01 REMOVAL / INSTALLATION OF THE BSCU - BSCU 1 (L240GC)								Component ATA:32
PN:C203470060700	MOS/MSC	06-Jul-22	O/C	TSN 0				
SN:UNKNOWN	HRS							
WC#: 32.530	AFL							
PROC. REF: AMM 32-41-02-900-801								
32-41-02-900-801-02 REMOVAL / INSTALLATION OF THE BSCU - BSCU 2 (R240GC)								Component ATA:32
PN:C203470060700	MOS/MSC	24-Apr-23	O/C					
SN:285	HRS	13947.1						
WC#: 32.530	AFL	9228						
PROC. REF: AMM 32-41-02-900-801								
32-41-05-900-801-01 REMOVAL / INSTALLATION OF THE BRAKE PEDAL POSITION TRANSDUCERS - LH BRAKE PEDALS POSITION TRANSMITTER (5GC)								Component ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.360	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05-900-801								
32-41-05-900-801-02 REMOVAL / INSTALLATION OF THE BRAKE PEDAL POSITION TRANSDUCERS - RH BRAKE PEDALS POSITION TRANSMITTER (10GC)								Component ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.360	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05-900-801								
32-41-07-610-801-01 ^S SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS								Service ATA:32
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
WC#: 32.430	AFL	7947	3750					
PROC. REF: AMM 32-41-07-610-801								
32-41-09-720-801-01 FUNCTIONAL TEST OF THE HYDRAULIC FUSES - LH HYDRAULIC FUSE (L415GC)								Service ATA:32
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
WC#: 32.710	AFL	0						
PROC. REF: AMM 32-41-09-720-801								
32-41-09-720-801-02 FUNCTIONAL TEST OF THE HYDRAULIC FUSES - RH HYDRAULIC FUSE (R415GC)								Service ATA:32
	MOS/MSC	01-Mar-00	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-41-09-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-41-17-900-801-01		REMOVAL / INSTALLATION OF THE BRAKE SHUT-OFF VALVES - SYSTEM 1 BRAKE SHUT-OFF VALVE (L245GC)					Component	ATA:32	
PN:65670-2	MOS/MSC	26-Apr-06	O/C	TSR 0					
SN:2461AR	HRS	4330.2		TSR 0					
WC#: 32.540	AFL	2967		TSR 0					
PROC. REF: AMM 32-41-17-900-801									
32-41-17-900-801-02		REMOVAL / INSTALLATION OF THE BRAKE SHUT-OFF VALVES - SYSTEM 2 BRAKE SHUT-OFF VALVE (R245GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.540	AFL	0		TSN 0					
PROC. REF: AMM 32-41-17-900-801									
32-41-37-900-801-01		SYSTEM NO. 1 BRAKE FILTER					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.570	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
32-41-37-900-801-02		SYSTEM NO. 2 BRAKE FILTER					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.570	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
32-41-37-900-801-03		PARKING BRAKE (450GC) FILTER					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.780	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
32-41-37-900-801-04		PARKING BRAKE (460GC) FILTER					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.790	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
32-41-37-960-801-01 ^S		REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - SYSTEM 1 BRAKE FILTER (L410GC)					Service	ATA:32	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 32.390	AFL	9008							
PROC. REF: AMM 32-41-37-960-801									

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-37-960-801-02^S REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - SYSTEM 2 BRAKE FILTER (R410GC) Service ATA:32								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 32.390	AFL	9008						
PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-37-960-801-03^S REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - PARKING BRAKE FILTER (450GC) Service ATA:32								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 32.390	AFL	9008						
PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-37-960-801-04^S REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - PARKING BRAKE FILTER (460GC) Service ATA:32								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-49-900-801-01 REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L260GC) Component ATA:32								
PN:C20345000	MOS/MSC	18-Aug-21	O/C					
SN:UNKNOWN	HRS	12985						
WC#: 32.400	AFL	8657						
PROC. REF: AMM 32-41-49-900-801								
32-41-49-900-801-02 REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L265GC) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.400	AFL	0		TSN 0				
PROC. REF: AMM 32-41-49-900-801								
32-41-49-900-801-03 REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R265GC) Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0		TSN 0				
PROC. REF: AMM 32-41-49-900-801								
32-41-49-900-801-04 REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R260GC) Component ATA:32								
PN:C20345000	MOS/MSC	15-Apr-11	O/C					
SN:01956	HRS	7895						
WC#: 32.410	AFL	5286						
PROC. REF: AMM 32-41-49-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-41-57-900-801-01 ^U		LH SYSTEM NO.1 BRAKE SERVOVALVE					Component	ATA:32	
PN:C20103510-1	MOS/MSC	31-May-11	O/C						
SN:01475	HRS	7981.4							
WC#: 32.650	AFL	5353							
32-41-57-900-801-01		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH SYSTEM 1 BRAKE SERVOVALVE (L250GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.550	AFL	0		TSN 0					
PROC. REF: AMM 32-41-57-900-801									
32-41-57-900-801-02		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH SYSTEM 1 BRAKE SERVOVALVE (R250GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.550	AFL	0		TSN 0					
PROC. REF: AMM 32-41-57-900-801									
32-41-57-900-801-02 ^U		RH SYSTEM NO.1 BRAKE SERVOVALVE					Component	ATA:32	
PN:C20103510-1	MOS/MSC	13-May-11	O/C	TSR 0					
SN:189	HRS	7936.7		TSR 0					
WC#: 32.650	AFL	5323		TSR 0					
32-41-57-900-801-03 ^U		LH SYSTEM NO.2 BRAKE SERVOVALVE					Component	ATA:32	
PN:C20103510-1	MOS/MSC	15-Nov-06	O/C						
SN:631	HRS	4940							
WC#: 32.660	AFL	3347							
32-41-57-900-801-03		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH SYSTEM 2 BRAKE SERVOVALVE (L251GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.560	AFL	0		TSN 0					
PROC. REF: AMM 32-41-57-900-801									
32-41-57-900-801-04		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH SYSTEM 2 BRAKE SERVOVALVE (R251GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.560	AFL	0		TSN 0					
PROC. REF: AMM 32-41-57-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-57-900-801-04 ^U RH SYSTEM NO.2 BRAKE SERVOVALVE								Component ATA:32
PN:C20103510-1	MOS/MSC	15-Nov-06	O/C					
SN:634	HRS	4940						
WC#: 32.660	AFL	3347						
32-42-00-610-801-01 SERVICING OF THE PARK BRAKE CONTROL								Service ATA:32
	MOS/MSC	08-Feb-17	O/C					
	HRS	10863.8						
WC#: 32.450	AFL	7323						
PROC. REF: AMM 32-42-00-610-801								
32-42-00-720-801-01 ^S FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - CHECK OF THE PARK BRAKE SYSTEM HYDRAULIC CAPACITY								Service ATA:32
	MOS	05-May-22						
	HRS	13592.3	3200 (+40)					
WC#: 32.370	AFL	9008						
PROC. REF: AMM 32-42-00-720-801								
32-42-00-720-801-01A FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - CHECK OF THE PARK BRAKE SYSTEM HYDRAULIC CAPACITY (MANDATORY 5-40)								Service ATA:32
	MOS/MSC	05-May-22	N/A					
	HRS	13592.3						
	AFL	9008						
PROC. REF: AMM 32-42-00-720-801								
32-42-00-720-801-02 ^S FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - CHECK OF THE PARK BRAKE PRESSURES								Service ATA:32
	MOS	05-May-22						
	HRS	13592.3	3200 (+40)					
WC#: 32.380	AFL	9008						
PROC. REF: AMM 32-42-00-720-801								
32-42-01-900-801-01 REMOVAL / INSTALLATION OF THE PARK BRAKE SELECTOR VALVE - PARK BRAKE SELECTOR VALVE (30GC)								Component ATA:32
PN:70012-21	MOS/MSC	07-May-09	O/C	TSN 0				
SN:836	HRS	6757		TSN 0				
WC#: 32.480	AFL	4535		TSN 0				
PROC. REF: AMM 32-42-01-900-801								
32-42-05-720-801-02 ^U FUNCTIONAL CHECK OF PARK BRAKE ACCUMULATOR CAPACITY (A/C WITHOUT SB F2000-193)								Service ATA:32
	MOS/MSC	10-Sep-15	O/C					
	HRS	10489.8						
	AFL	7089						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-42-05-780-801-02A	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (110GC) (MANDATORY 5-40)							Service	ATA:32
	MOS	27-Dec-23						MANDATORY 5-40	
	HRS	14292.8	2000		16292.8		1938.4		
	AFL	9471							
PROC. REF: AMM 32-42-05-780-801									
32-42-05-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR - PARK BRAKE ACCUMULATOR (110GC)							Component	ATA:32
PN:60967-1	MOS/MSC	20-Mar-09	O/C	TSO 0					
SN:EFS1069	HRS	6685.9		TSO 0					
WC#: 32.510	AFL	4485		TSO 0					
PROC. REF: AMM 32-42-05-900-801									
32-42-05-900-802-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR SWITCH - PARK BRAKE PRESSURE SWITCH (150GC)							Component	ATA:32
PN:7G1052-1	MOS/MSC	20-Mar-09	O/C	TSN 0					
SN:236	HRS	6685.9		TSN 0					
WC#: 32.605	AFL	4485		TSN 0					
PROC. REF: AMM 32-42-05-900-802									
32-42-13-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE FLEXIBLE CONTROL - PARK BRAKE FLEXIBLE CONTROL (190GC)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.440	AFL	0		TSN 0					
PROC. REF: AMM 32-42-13-900-801									
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES							Service	ATA:32
	MOS/MSC	30-Mar-21	O/C						
	HRS	12756.1							
	AFL	8509							
PROC. REF: AMM 32-44-00-220-801									
32-44-00-250-801-01	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG OUTBOARD WHEEL (L225GC)							Service	ATA:32
PN:C20384200MIC	MOS	05-Jul-23							
SN:00952	HRS	14049.3							
WC#: 32.300	AFL	9307	400 (+3%)		9707	9807	205 (+100)		
PROC. REF: AMM 32-44-00-250-801									
32-44-00-250-801-02	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG INBOARD WHEEL (L220GC)							Service	ATA:32
PN:C20384200	MOS	29-Aug-23							
SN:00800	HRS	14127.2							
WC#: 32.310	AFL	9364	400 (+3%)		9764	9864	262 (+100)		
PROC. REF: AMM 32-44-00-250-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R220GC)						Service	ATA:32
PN:C20384200MIC	MOS	05-Jul-23							
SN:00466	HRS	14049.3							
WC#: 32.320	AFL	9307	400 (+3%)		9707	9807	205 (+100)		
PROC. REF: AMM 32-44-00-250-801									
32-44-00-250-801-04		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R225GC)						Service	ATA:32
PN:C20384200MIC	MOS	10-Oct-23							
SN:01309	HRS	14192							
WC#: 32.330	AFL	9411	400 (+3%)		9811	9911	309 (+100)		
PROC. REF: AMM 32-44-00-250-801									
32-44-00-250-801-05		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L300GC)						Service	ATA:32
PN:C20383000MIC	MOS	21-Jul-23							
SN:00185	HRS	14071.9							
WC#: 32.340	AFL	9326	500 (+3%)		9826	9841	324 (+15)		
PROC. REF: AMM 32-44-00-250-801									
32-44-00-250-801-06		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R300GC)						Service	ATA:32
PN:C20383000	MOS	21-Jul-23							
SN:F133	HRS	14071.9							
WC#: 32.350	AFL	9326	500 (+3%)		9826	9841	324 (+15)		
PROC. REF: AMM 32-44-00-250-801									
32-44-00-780-801-01		PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES						Service	ATA:32
	MOS	07-Feb-24	2 (+5d)		07-Apr-24	12-Apr-24	1 d (+5)		
	HRS	14354.4							
	AFL	9502							
PROC. REF: AMM 32-44-00-780-801									
32-44-01-900-801-01		REMOVAL / INSTALLATION OF THE NLG WHEELS - LH NLG WHEEL (L300GC)						Component	ATA:32
PN:C20383000MIC	MOS/MSC	21-Jul-23	O/C	TSO 0					
SN:00185	HRS	14071.9		TSO 0					
WC#: 32.340	AFL	9326		TSO 0					
PROC. REF: AMM 32-44-01-900-801									
32-44-01-900-801-02		REMOVAL / INSTALLATION OF THE NLG WHEELS - RH NLG WHEEL (R300GC)						Component	ATA:32
PN:C20383000	MOS/MSC	21-Jul-23	O/C	TSO 0					
SN:F133	HRS	14071.9		TSO 0					
WC#: 32.350	AFL	9326		TSO 0					
PROC. REF: AMM 32-44-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-05-900-801-01 REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - LH NOSE WHEEL TIRE (L310GC)								Component ATA:32
PN:M08301IND03	MOS/MSC	21-Jul-23	O/C	TSN 0				
SN:2224T094	HRS	14071.9		TSN 0				
WC#: 32.340	AFL	9326		TSN 0				
PROC. REF: AMM 32-44-05-900-801								
32-44-05-900-801-02 REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - RH NLG WHEEL TIRE (R310GC)								Component ATA:32
PN:M08301IND03	MOS/MSC	21-Jul-23	O/C	TSN 0				
SN:2032T208	HRS	14071.9		TSN 0				
WC#: 32.350	AFL	9326		TSN 0				
PROC. REF: AMM 32-44-05-900-801								
32-44-09-900-801-01 REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L225GC)								Component ATA:32
PN:C20384200MIC	MOS/MSC	05-Jul-23	O/C	TSO 0				
SN:00952	HRS	14049.3		TSO 0				
WC#: 32.300	AFL	9307		TSO 0				
PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-02 REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L220GC)								Component ATA:32
PN:C20384200	MOS/MSC	29-Aug-23	O/C	TSO 0				
SN:00800	HRS	14127.2		TSO 0				
WC#: 32.310	AFL	9364		TSO 0				
PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-03 REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R220GC)								Component ATA:32
PN:C20384200MIC	MOS/MSC	05-Jul-23	O/C	TSO 0				
SN:00466	HRS	14049.3		TSO 0				
WC#: 32.320	AFL	9307		TSO 0				
PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-04 REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R225GC)								Component ATA:32
PN:C20384200MIC	MOS/MSC	10-Oct-23	O/C	TSO 0				
SN:01309	HRS	14192		TSO 0				
WC#: 32.330	AFL	9411		TSO 0				
PROC. REF: AMM 32-44-09-900-801								
32-44-13-900-801-01 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH OUTBOARD MAIN WHEEL TIRE (L235GC)								Component ATA:32
PN:M15101-01	MOS/MSC	05-Jul-23	O/C	TSN 0				
SN:2353K107	HRS	14049.3		TSN 0				
WC#: 32.300	AFL	9307		TSN 0				
PROC. REF: AMM 32-44-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-13-900-801-02 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH INBOARD MAIN WHEEL TIRE (L230GC)								Component ATA:32
PN:M15101-01	MOS/MSC	29-Aug-23	O/C	TSN 0				
SN:2238K116	HRS	14127.2		TSN 0				
WC#: 32.310	AFL	9364		TSN 0				
PROC. REF: AMM 32-44-13-900-801								
32-44-13-900-801-03 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH INBOARD MAIN WHEEL TIRE (R230GC)								Component ATA:32
PN:M15101-01	MOS/MSC	05-Jul-23	O/C	TSN 0				
SN:2363K126	HRS	14049.3		TSN 0				
WC#: 32.320	AFL	9307		TSN 0				
PROC. REF: AMM 32-44-13-900-801								
32-44-13-900-801-04 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH OUTBOARD MAIN WHEEL TIRE (R235GC)								Component ATA:32
PN:M15101-01	MOS/MSC	10-Oct-23	O/C	TSN 0				
SN:2238K106	HRS	14192		TSN 0				
WC#: 32.330	AFL	9411		TSN 0				
PROC. REF: AMM 32-44-13-900-801								
32-44-15-900-801-01 LH OUTBOARD MAIN LANDING GEAR (MLG) FLANGE								Component ATA:32
PN:PN	MOS/MSC	25-Mar-14	O/C	TSN 0				
SN:UNKNOWN	HRS	9616.2		TSN 0				
WC#: 32.300	AFL	6496		TSN 0				
PROC. REF: GENERIC NO REF								
32-44-15-900-801-02 LH INBOARD MAIN LANDING GEAR (MLG) FLANGE								Component ATA:32
PN:PN	MOS/MSC	25-Mar-14	O/C	TSN 0				
SN:UNKNOWN	HRS	9616.2		TSN 0				
WC#: 32.310	AFL	6496		TSN 0				
PROC. REF: GENERIC NO REF								
32-44-15-900-801-03 RH INBOARD MAIN LANDING GEAR (MLG) FLANGE								Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	23-Jun-21	O/C					
SN:UNKNOWN	HRS	12897.5						
WC#: 32.320	AFL	8599						
PROC. REF: GENERIC NO REF								
32-44-15-900-801-04 RH OUTBOARD MAIN LANDING GEAR (MLG) FLANGE								Component ATA:32
PN:PN	MOS/MSC	24-Oct-13	O/C	TSN 0				
SN:UNKNOWN	HRS	9359.5		TSN 0				
WC#: 32.330	AFL	6319		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-44-15-960-801-01		REPLACEMENT OF THE MLG WHEEL FLANGES - LH MLG OUTBOARD WHEEL (L225GC)							Service ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-01A		REPLACEMENT OF THE MLG WHEEL FLANGES							Service ATA:32
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-02		REPLACEMENT OF THE MLG WHEEL FLANGES - LH MLG INBOARD WHEEL (L220GC)							Service ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-02A		REPLACEMENT OF THE MLG WHEEL FLANGES							Service ATA:32
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-03		REPLACEMENT OF THE MLG WHEEL FLANGES - RH MLG INBOARD WHEEL (R220GC)							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	23-Jun-21	O/C						
SN:UNKNOWN	HRS	12897.5							
	AFL	8599							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-03A		REPLACEMENT OF THE MLG WHEEL FLANGES							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	23-Jun-21	O/C						
SN:UNKNOWN	HRS	12897.5							
	AFL	8599							
PROC. REF: AMM 32-44-15-960-801									
32-44-15-960-801-04		REPLACEMENT OF THE MLG WHEEL FLANGES - RH MLG OUTBOARD WHEEL (R225GC)							Service ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-44-15-960-801-04A		REPLACEMENT OF THE MLG WHEEL FLANGES						Service	ATA:32
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-44-15-960-801									
32-44-17-350-801-01		RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG OUTBOARD BRAKE (L215GC)						Service	ATA:32
PN:C20382100	MOS/MSC	05-May-22	A/R				OVERHAUL		
SN:00282	HRS	13592.3							
WC#: 32.460	AFL	9008							
PROC. REF: AMM 32-44-17-350-801									
32-44-17-350-801-02		RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG INBOARD BRAKE (L210GC)						Service	ATA:32
PN:C20382100	MOS/MSC	05-May-22	A/R				OVERHAUL		
SN:00349	HRS	13592.3							
WC#: 32.460	AFL	9008							
PROC. REF: AMM 32-44-17-350-801									
32-44-17-350-801-03		RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG INBOARD BRAKE (R210GC)						Service	ATA:32
PN:C20382100	MOS/MSC	01-Jun-22	A/R				OVERHAUL		
SN:00664	HRS	13608							
WC#: 32.470	AFL	9016							
PROC. REF: AMM 32-44-17-350-801									
32-44-17-350-801-04		RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG OUTBOARD BRAKE (R215GC)						Service	ATA:32
PN:C20382100	MOS/MSC	05-May-22	A/R				OVERHAUL		
SN:00833	HRS	13592.3							
WC#: 32.470	AFL	9008							
PROC. REF: AMM 32-44-17-350-801									
32-44-17-900-801-01		REMOVAL / INSTALLATION OF THE BRAKES - LH MLG OUTBOARD BRAKE (L215GC)						Component	ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C						
SN:00282	HRS	13592.3							
WC#: 32.460	AFL	9008							
PROC. REF: AMM 32-44-17-900-801									
32-44-17-900-801-02		REMOVAL / INSTALLATION OF THE BRAKES - LH MLG INBOARD BRAKE (L210GC)						Component	ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C						
SN:00349	HRS	13592.3							
WC#: 32.460	AFL	9008							
PROC. REF: AMM 32-44-17-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-17-900-801-03 REMOVAL / INSTALLATION OF THE BRAKES - RH MLG INBOARD BRAKE (R210GC)								Component ATA:32
PN:C20382100	MOS/MSC	01-Jun-22	O/C	TSN 0				
SN:00664	HRS	13608		TSN 0				
WC#: 32.470	AFL	9016		TSN 0				
PROC. REF: AMM 32-44-17-900-801								
32-44-17-900-801-04 REMOVAL / INSTALLATION OF THE BRAKES - RH MLG OUTBOARD BRAKE (R215GC)								Component ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C					
SN:00833	HRS	13592.3						
WC#: 32.470	AFL	9008						
PROC. REF: AMM 32-44-17-900-801								
32-44-17-960-801-01 DISCARD OF THE BRAKES - LH MLG OUTBOARD BRAKE (L215GC)								Service ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C					
SN:00282	HRS	13592.3						
WC#: 32.460	AFL	9008						
PROC. REF: AMM 32-44-17-960-801								
32-44-17-960-801-02 DISCARD OF THE BRAKES - LH MLG INBOARD BRAKE (L210GC)								Service ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C					
SN:00349	HRS	13592.3						
WC#: 32.460	AFL	9008						
PROC. REF: AMM 32-44-17-960-801								
32-44-17-960-801-03 DISCARD OF THE BRAKES - RH MLG INBOARD BRAKE (R210GC)								Service ATA:32
PN:C20382100	MOS/MSC	01-Jun-22	O/C					
SN:00664	HRS	13608						
WC#: 32.470	AFL	9016						
PROC. REF: AMM 32-44-17-960-801								
32-44-17-960-801-04 DISCARD OF THE BRAKES - RH MLG OUTBOARD BRAKE (R215GC)								Service ATA:32
PN:C20382100	MOS/MSC	05-May-22	O/C					
SN:00833	HRS	13592.3						
WC#: 32.470	AFL	9008						
PROC. REF: AMM 32-44-17-960-801								
32-44-18-960-801-01 REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG OUTBOARD BRAKE (L215GC) SEAL								Service ATA:32
PN:C20382100	MOS/MSC	05-May-22	A/R					
SN:00282	HRS	13592.3						
WC#: 32.460	AFL	9008						
PROC. REF: AMM 32-44-18-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-44-18-960-801-02		REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG INBOARD BRAKE (L210GC) SEAL					Service	ATA:32	
PN:C20382100	MOS/MSC	05-May-22	A/R						
SN:00349	HRS	13592.3							
WC#: 32.460	AFL	9008							
PROC. REF: AMM 32-44-18-960-801									
32-44-18-960-801-03		REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG INBOARD BRAKE (R210GC) SEAL					Service	ATA:32	
PN:C20382100	MOS/MSC	01-Jun-22	A/R						
SN:00664	HRS	13608							
WC#: 32.470	AFL	9016							
PROC. REF: AMM 32-44-18-960-801									
32-44-18-960-801-04		REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG OUTBOARD BRAKE (R215GC) SEAL					Service	ATA:32	
PN:C20382100	MOS/MSC	05-May-22	A/R						
SN:00833	HRS	13592.3							
WC#: 32.470	AFL	9008							
PROC. REF: AMM 32-44-18-960-801									
32-44-21-900-801-01		REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - UPPER SWIVEL COUPLING (L100GC) / (R100GC) / (L101GC) / (R101GC)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.500	AFL	0		TSN 0					
PROC. REF: AMM 32-44-21-900-801									
32-44-21-900-801-02		REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - LOWER SWIVEL COUPLING (L102GC) / (R102GC) / (L103GC) / (R103GC)					Component	ATA:32	
PN:A101-24660	MOS/MSC	22-Nov-13	O/C						
SN:H0769	HRS	9419.6							
WC#: 32.500	AFL	6356							
PROC. REF: AMM 32-44-21-900-801									
32-50-00-710-801-01 ^S		OPERATIONAL TEST OF THE STEERING CONTROL SYSTEM					Service	ATA:32	
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 32.670	AFL	7947	3750						
PROC. REF: AMM 32-50-00-710-801									
32-50-01-900-801-01		REMOVAL / INSTALLATION OF THE NLG WHEEL STEERING REPEATER BOX - NOSE WHEEL STEERING POSITION SENSOR (5GB2)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-50-13-900-801-01		REMOVAL / INSTALLATION OF THE STEERING SERVOVALVE - STEERING SERVOVALVE (5GB1)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-13-900-801									
32-61-49-900-801-01		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH BRACE ACTUATOR MONITORING PROXIMITY SWITCH (40GAA)					Component	ATA:32	
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0					
SN:01327	HRS	8486.2		TSN 0					
	AFL	5707		TSN 0					
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-02		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH BRACE ACTUATOR CONTROL PROXIMITY SWITCH (40GAB)					Component	ATA:32	
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0					
SN:01312	HRS	8486.2		TSN 0					
	AFL	5707		TSN 0					
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-03		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH BRACE ACTUATOR MONITORING PROXIMITY SWITCH (45GAA)					Component	ATA:32	
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0					
SN:01309	HRS	8486.2		TSN 0					
	AFL	5707		TSN 0					
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-04		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH BRACE ACTUATOR CONTROL PROXIMITY SWITCH (45GAB)					Component	ATA:32	
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0					
SN:01315	HRS	8486.2		TSN 0					
	AFL	5707		TSN 0					
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-05		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG UPLOCK BOX PROXIMITY SWITCH (120GM1)					Component	ATA:32	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-49-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-61-49-900-801-06	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG UPLOCK BOX PROXIMITY SWITCH (130GM1)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-07	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG DOOR LATCH CONTROL PROXIMITY SWITCH (L170GM1)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-08	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG DOOR LATCH MONITORING PROXIMITY SWITCH (L170GM2)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-09	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG DOOR LATCH CONTROL PROXIMITY SWITCH (R170GM1)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-10	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG DOOR LATCH MONITORING PROXIMITY SWITCH (R170GM2)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-11	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG INBOARD PROXIMITY SWITCH (5GAB)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-49-900-801-12	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG OUTBOARD PROXIMITY SWITCH (5GAD)						Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-13	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG INBOARD PROXIMITY SWITCH (10GAB)						Component	ATA:32
PN:84738722	MOS/MSC	29-Dec-17	O/C	TSN 0				
SN:34704	HRS	11289.8		TSN 0				
	AFL	7604		TSN 0				
PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-14	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG OUTBOARD PROXIMITY SWITCH (10GAD)						Component	ATA:32
PN:D22884000-1	MOS/MSC	13-Oct-09	O/C	TSR 0				
SN:U156	HRS	6998.8		TSR 0				
	AFL	4706		TSR 0				
PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-15	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NOSE GEAR DRAG BRACE MONITORING PROXIMITY SWITCH (20GBA)						Component	ATA:32
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0				
SN:01307	HRS	8486.2		TSN 0				
	AFL	5707		TSN 0				
PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-16	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NOSE GEAR DRAG BRACE CONTROL PROXIMITY SWITCH (20GBB)						Component	ATA:32
PN:D23336000-2	MOS/MSC	22-Mar-12	O/C	TSN 0				
SN:01333	HRS	8486.2		TSN 0				
	AFL	5707		TSN 0				
PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-17	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG UPLOCK BOX CONTROL PROXIMITY SWITCH (5GM1)						Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-61-49-900-801-18	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG UPLOCK BOX MONITORING PROXIMITY SWITCH (5GM2)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-19	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG LH PROXIMITY SWITCH (5GBC)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-20	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG RH PROXIMITY SWITCH (5GBD)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-21	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LH MAIN DOOR PROXIMITY SWITCH (L100GB)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
32-61-49-900-801-22	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG RH MAIN DOOR PROXIMITY SWITCH (R100GB)							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 32-61-49-900-801									
321811	LEFT MLG DOOR EXTENSION ACTUATOR RESTRICTOR VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.055	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321816 RIGHT MLG DOOR EXTENSION ACTUATOR RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.055	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
321821 LEFT MLG DOOR RETRACTION ACTUATOR RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.065	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
321826 RIGHT MLG DOOR RETRACTION ACTUATOR RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.065	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
322806 NLG DRAG BRACE HYDRAULIC SWIVEL COUPLING Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
322810 NOSE LANDING GEAR TELESCOPIC YOKE ASSEMBLY Component ATA:32								
PN:GA62269	MOS/MSC	19-Jan-23	O/C	TSO 0				
SN:649	HRS	13859.4		TSO 0				
WC#: 32.080	AFL	9175		TSO 0				
PROC. REF: GENERIC NO REF								
323806 LEFT MAIN LANDING GEAR EXTENSION RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323811 RIGHT MAIN LANDING GEAR EXTENSION RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323851 NOSE LANDING GEAR EXTENSION RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323856 NOSE LANDING GEAR RETRACTION RESTRICTOR VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323861 MAIN LANDING GEAR HYD PROTECTION SYSTEM CHECK VALVE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323866 LANDING GEAR EMERGENCY HYDRAULIC EXTENSION HANDLE Component ATA:32								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324033 LH SYSTEM NO.1 BRAKE PRESSURE SWITCH Component ATA:32								
PN:1203P0224	MOS/MSC	22-Mar-12	O/C	TSN 0				
SN:0179	HRS	8486.2		TSN 0				
WC#: 32.580	AFL	5707		TSN 0				
PROC. REF: GENERIC NO REF								
324034 RH SYSTEM NO.1 BRAKE PRESSURE SWITCH Component ATA:32								
PN:7G1042	MOS/MSC	22-Nov-13	O/C	TSN 0				
SN:1920	HRS	9419.6		TSN 0				
WC#: 32.580	AFL	6356		TSN 0				
PROC. REF: GENERIC NO REF								
324041 LH SYSTEM NO.2 BRAKE PRESSURE SWITCH Component ATA:32								
PN:7G1042	MOS/MSC	20-Apr-10	O/C	TSN 0				
SN:1599	HRS	7299.5		TSN 0				
WC#: 32.590	AFL	4889		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
324042		RH SYSTEM NO.2 BRAKE PRESSURE SWITCH					Component		ATA:32
PN:7G1042	MOS/MSC	20-Apr-10	O/C	TSN 0					
SN:1600	HRS	7299.5		TSN 0					
WC#: 32.590	AFL	4889		TSN 0					
PROC. REF: GENERIC NO REF									
324043		NO. 1 BRAKE TEST PRESSURE SWITCH					Component		ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.600	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324044		NO. 2 BRAKE TEST PRESSURE SWITCH					Component		ATA:32
PN:7G1104	MOS/MSC	20-Apr-06	O/C	TSN 0					
SN:182	HRS	4313.9		TSN 0					
WC#: 32.600	AFL	2960		TSN 0					
PROC. REF: GENERIC NO REF									
324807		PARKING BRAKE DISTRIBUTOR CHECK VALVE					Component		ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.480	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324809		LEFT BRAKE SYSTEM SHUTTLE VALVE					Component		ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.490	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324812		RIGHT BRAKE SYSTEM SHUTTLE VALVE					Component		ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.490	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324815		PARK BRAKE SYSTEM THERMAL VALVE					Component		ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.490	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
324825	PARKING BRAKE ACCUMULATOR CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.510	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324827	BRAKE ACCUMULATOR PRESSURE GAUGE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.520	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324860	LEFT SYSTEM NO.1 BRAKE CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.610	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324863	RIGHT SYSTEM NO.1 BRAKE CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.610	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324866	LEFT SYSTEM NO.2 BRAKE CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.620	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324869	RIGHT SYSTEM NO.2 BRAKE CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.620	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
324872	LEFT SYSTEM NO.1 BRAKE RESTRICTOR							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.630	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
324875	RIGHT SYSTEM NO.1 BRAKE RESTRICTOR							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.630	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
324878	LEFT SYSTEM NO.2 BRAKE RESTRICTOR							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.640	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
324881	RIGHT SYSTEM NO.2 BRAKE RESTRICTOR							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.640	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
325801	NOSE GEAR STEERING SOLENOID VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.680	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
325803	NOSE GEAR STEERING CHECK VALVE							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.680	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
325806	NOSE GEAR CONTROL STEERING WHEEL							Component	ATA:32
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.680	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									
ATA 33 - LIGHTS									
33-10-07-900-801-01	REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - PILOT DOME LIGHT (L31LE)							Component	ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 33.220	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
33-10-07-900-801-02		REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - COPILOT DOME LIGHT (R31LE)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.220	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-01		PILOT GLARESHIELD FLUORESCENT TUBE					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-02		COPILOT GLARESHIELD FLUORESCENT TUBE					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-03		PILOT GLARESHIELD UPPER ELECTRO-LUMINESCENT LIGHT STRIP RAMP					Component	ATA:33	
PN:251TZ01Y00	MOS/MSC	26-Jan-08	O/C	TSN 0					
SN:250	HRS	5938.5		TSN 0					
	AFL	3970		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-04		COPILOT GLARESHIELD ELECTRO-LUMINESCENT LIGHT STRIP					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-05		PILOT GLARESHIELD BOTTOM ELECTRO-LUMINESCENT LIGHT STRIP RAMP					Component	ATA:33	
PN:240TZ01Y00	MOS/MSC	26-Jan-08	O/C	TSN 0					
SN:309	HRS	5938.5		TSN 0					
	AFL	3970		TSN 0					
PROC. REF: GENERIC NO REF									
33-10-09-900-801-06		COPILOT GLARESHIELD BOTTOM ELECTRO-LUMINESCENT LIGHT STRIP					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
33-10-09-960-801-01	REPLACEMENT OF THE GLARESHIELD LIGHTS - PILOT GLARESHIELD FLUORESCENT TUBE (50LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-09-960-801-02	REPLACEMENT OF THE GLARESHIELD LIGHTS - COPILOT GLARESHIELD FLUORESCENT TUBE (60LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-09-960-801-03	REPLACEMENT OF THE GLARESHIELD LIGHTS - PILOT GLARESHIELD ELECTRO-LUMINESCENT LIGHT STRIP (L70LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-09-960-801-04	REPLACEMENT OF THE GLARESHIELD LIGHTS - COPILOT GLARESHIELD ELECTRO-LUMINESCENT LIGHT STRIP (R70LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-09-960-801-05	REPLACEMENT OF THE GLARESHIELD LIGHTS - PILOT GLARESHIELD ELECTRO-LUMINESCENT LIGHT STRIP (L75LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-09-960-801-06	REPLACEMENT OF THE GLARESHIELD LIGHTS - COPILOT GLARESHIELD ELECTRO-LUMINESCENT LIGHT STRIP (R75LC)							Service	ATA:33
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 33-10-09-960-801								
33-10-17-900-801-01	REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - LH CIRCUIT BREAKER PANEL SPOTLIGHT (L40LC)							Component	ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.030	AFL	0		TSN 0					
	PROC. REF: AMM 33-10-17-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
33-10-17-900-801-02		REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - RH CIRCUIT BREAKER PANEL SPOTLIGHT (R40LC)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.030	AFL	0		TSN 0					
PROC. REF: AMM 33-10-17-900-801									
33-20-00-200-801-01		INSPECTION OF "ALC" LIGHTING TUBES					Service	ATA:33	
	MOS	27-Nov-23	12 (+1m)		27-Nov-24	27-Dec-24	235 d (+30)		
	HRS	14292.8	400 (+40)		14692.8	14732.8	338.4 (+40)		
WC#: 33.250	AFL	9471							
PROC. REF: AMM 33-20-00-200-801									
33-40-00-720-801-01 ^S		FUNCTIONAL TEST OF THE EXTERIOR LIGHTS WITH LED TECHNOLOGY - TAXI LIGHT (100LX)					Service	ATA:33	
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 33-40-00-720-801									
33-40-01-900-801-01		REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - LH NAVIGATION LIGHT (15LX) OR (15LX) / (28L) OR (15LX) / (565LX)					Component	ATA:33	
PN:2LA006615-22	MOS/MSC	31-Dec-20	O/C						
SN:N/A	HRS	12553.5							
	AFL	8426							
PROC. REF: AMM 33-40-01-900-801									
33-40-01-900-801-02		REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - RH NAVIGATION LIGHT (10LX) OR (10LX) / (29L) OR (10LX) / (566LX)					Component	ATA:33	
PN:PN-UNKNOWN	MOS/MSC	20-Oct-10	O/C						
SN:UNKNOWN	HRS	7625.5							
	AFL	5112							
PROC. REF: AMM 33-40-01-900-801									
33-40-07-900-801-01		REMOVAL / INSTALLATION OF THE WHITE REAR NAVIGATION / ANTI-COLLISION LIGHT - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (40LX)					Component	ATA:33	
PN:6480651	MOS/MSC	30-Sep-16	O/C	TSN 0					
SN:332	HRS	10749.4		TSN 0					
WC#: 33.260	AFL	7265		TSN 0					
PROC. REF: AMM 33-40-07-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
33-40-09-900-802-01		REMOVAL / INSTALLATION OF UPPER ANTI-COLLISION LIGHT - UPPER ANTI-COLLISION LIGHT (4LX)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
33-40-31-960-801-01		REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - FLASH TUBE OF LH WING WHITE ANTI-COLLISION LIGHT (L210LX)					Component	ATA:33	
PN:39-28-21	MOS/MSC	16-Jan-14	O/C	TSN 0					
SN:3396	HRS	9510.9		TSN 0					
WC#: 33.160	AFL	6418		TSN 0					
PROC. REF: AMM 33-40-31-960-801									
33-40-31-960-801-02		REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - FLASH TUBE OF RH WHITE WING ANTI-COLLISION LIGHT (R210LX)					Component	ATA:33	
PN:6480701	MOS/MSC	28-Dec-23	O/C						
SN:207	HRS	14292.8							
WC#: 33.160	AFL	9471							
PROC. REF: AMM 33-40-31-960-801									
33-40-37-900-801-01		REMOVAL / INSTALLATION OF THE LANDING LIGHTS - LH LANDING LIGHT (L70LX)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.130	AFL	0		TSN 0					
PROC. REF: AMM 33-40-37-900-801									
33-40-37-900-801-02		REMOVAL / INSTALLATION OF THE LANDING LIGHTS - RH LANDING LIGHT (R70LX)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.130	AFL	0		TSN 0					
PROC. REF: AMM 33-40-37-900-801									
33-40-41-900-801-01		REMOVAL / INSTALLATION OF THE TAXI LIGHT - TAXI LIGHT (100LX)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.150	AFL	0		TSN 0					
PROC. REF: AMM 33-40-41-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
33-40-41-960-801-01		REPLACEMENT OF THE TAXI LIGHT BULB - TAXI LIGHT (100LX)					Service	ATA:33	
PN:PN	MOS/MSC	27-Oct-22	O/C						
SN:UNKNOWN	HRS	13832.6							
	AFL	9154							
PROC. REF: AMM 33-40-41-960-801									
33-40-65-900-801-01		LH WING ANTICOLLISION LIGHT POWER SUPPLY BOX					Component	ATA:33	
PN:6480702	MOS/MSC	16-Jan-14	O/C	TSN 0					
SN:441	HRS	9510.9		TSN 0					
WC#: 33.170	AFL	6418		TSN 0					
PROC. REF: AMM 33-40-65-960-801									
33-40-65-900-801-02		RH WING ANTICOLLISION LIGHT POWER SUPPLY BOX					Component	ATA:33	
PN:6480702	MOS/MSC	28-Dec-23	O/C	TSN 0					
SN:0988	HRS	14292.8		TSN 0					
WC#: 33.170	AFL	9471		TSN 0					
PROC. REF: AMM 33-40-65-960-801									
33-50-00-710-804-01 ^S		OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EMERGENCY LIGHTING SYSTEM					Service	ATA:33	
	MOS	05-May-22							
	HRS	13592.3	4800 (+40)						
	AFL	9008							
PROC. REF: AMM 33-50-00-710-804									
33-50-00-720-801-01 ^U		FUNCTIONAL TEST NO. 1 EMERGENCY (EPS1) POWER SUPPLY					Service	ATA:33	PKG:23
PN:D734-02-001	MOS/MSC	20-May-16	O/C						
SN:3408	HRS	10730.7							
WC#: 33.200	AFL	7258							
PROC. REF: GENERIC NO REF									
33-50-00-720-801-02 ^U		FUNCTIONAL TEST NO. 2 EMERGENCY (EPS2) POWER SUPPLY					Service	ATA:33	
PN:D734-02-001	MOS/MSC	11-Aug-22	O/C						
SN:3407	HRS	13706.6							
WC#: 33.200	AFL	9084							
PROC. REF: GENERIC NO REF									
33-50-00-720-801-03 ^U		FUNCTIONAL TEST NO. 3 EMERGENCY (EPS3) POWER SUPPLY					Service	ATA:33	
PN:D734-02-001	MOS/MSC	19-Jan-23	O/C						
SN:3430	HRS	13859.4							
WC#: 33.210	AFL	9175							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-05-350-801-01 RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (L702LC) Service ATA:33								
PN:P2-07-0005-120	MOS/MSC		N/A					
SN:N/A	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-801, SMM 25-90-51								
33-50-05-350-801-02 RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (R702LC) Service ATA:33								
PN:P2-07-0011-500	MOS/MSC		N/A					
SN:061123021	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-801, SMM 25-90-51								
33-50-05-350-802-01 RESTORATION OF THE MAGLITE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (L702LC) Service ATA:33								
PN:P2-07-0005-120	MOS/MSC		N/A					
SN:N/A	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-802, SMM 25-90-43								
33-50-05-350-803-01 RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (L702LC) Service ATA:33								
PN:P2-07-0005-120	MOS/MSC		N/A					
SN:N/A	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-803								
33-50-05-350-803-02 RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (R702LC) Service ATA:33								
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-803								
33-50-05-900-801-01 REMOVAL / INSTALLATION OF THE RECHARGEABLE FLASHLIGHT BASES - FLASHLIGHT (L702LC) Component ATA:33								
PN:P2-07-0005-120	MOS/MSC	15-Jun-22	O/C	TSN 0				
SN:N/A	HRS	13630.3		TSN 0				
	AFL	9028		TSN 0				
PROC. REF: AMM 33-50-05-900-801								
33-50-05-900-801-02 REMOVAL / INSTALLATION OF THE RECHARGEABLE FLASHLIGHT BASES - FLASHLIGHT (R702LC) Component ATA:33								
PN:P2-07-0011-500	MOS/MSC	11-Oct-06	O/C	TSN 0				
SN:061123021	HRS	4932.4		TSN 0				
	AFL	3341		TSN 0				
PROC. REF: AMM 33-50-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-05-960-801-01 DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - LH FLASHLIGHT BATTERY (9610ME) Service ATA:33								
PN:P2-07-0005-120	MOS	08-Sep-22	60 (+3%)		08-Sep-27	01-Nov-27	1250 d (+54)	
SN:N/A	HRS	13765.9						
	AFL	9108						
PROC. REF: AMM 33-50-05-960-801, SMM 25-90-49								
33-50-05-960-801-02 DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - RH FLASHLIGHT BATTERY (9620ME) Service ATA:33								
PN:P2-07-0011-500	MOS	27-May-21	60 (+3%)		27-May-26	21-Jul-26	781 d (+55)	
SN:061123021	HRS	12863.6						
	AFL	8574						
PROC. REF: AMM 33-50-05-960-801, SMM 25-90-49								
33-50-33-610-801-01 SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 1 (5LE) Service ATA:33								
PN:D734-02-001	MOS/MSC	14-Jan-21	O/C					
SN:3408	HRS							
WC#: 33.200	AFL	8426						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-02 SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 2 (10LE) Service ATA:33								
PN:D734-02-001	MOS/MSC	11-Aug-22	O/C					
SN:3407	HRS	13706.6						
WC#: 33.200	AFL	9084						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-03 SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 3 (15LE) Service ATA:33								
PN:D734-02-001	MOS/MSC	19-Jan-23	O/C					
SN:3430	HRS	13859.4						
WC#: 33.210	AFL	9175						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-900-801-01 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 1 (5LE) Component ATA:33								
PN:D734-02-001	MOS/MSC	10-Sep-15	O/C	TSR 1				
SN:3408	HRS	10489.8		TSR 0				
WC#: 33.200	AFL	7089		TSR 0				
PROC. REF: AMM 33-50-33-900-801								
33-50-33-900-801-02 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 2 (10LE) Component ATA:33								
PN:D734-02-001	MOS/MSC	11-Aug-22	O/C	TSR 84				
SN:3407	HRS	13706.6		TSR 3216.8				
WC#: 33.200	AFL	9084		TSR 1995				
PROC. REF: AMM 33-50-33-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-33-900-801-03 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 3 (15LE)								Component ATA:33
PN:D734-02-001	MOS/MSC	19-Jan-23	O/C	TSR 89				
SN:3430	HRS	13859.4		TSR 3369.6				
WC#: 33.210	AFL	9175		TSR 2086				
PROC. REF: AMM 33-50-33-900-801								
33-50-37-900-801-01 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 1 (5LE) BATTERY PACK								Component ATA:33
PN:C734-01-030	MOS/MSC	28-Oct-22	O/C	TSN 0				
SN:CF33808/41/21	HRS	13832.6		TSN 0				
	AFL	9154		TSN 0				
PROC. REF: AMM 33-50-37-900-801								
33-50-37-900-801-02 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 2 (10LE) BATTERY PACK								Component ATA:33
PN:AD-C734-01-030	MOS/MSC	01-Oct-23	O/C	TSN 0				
SN:295096	HRS	14169		TSN 0				
	AFL	9395		TSN 0				
PROC. REF: AMM 33-50-37-900-801								
33-50-37-900-801-03 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 3 (15LE) BATTERY PACK								Component ATA:33
PN:C734-01-030	MOS/MSC	19-Jan-23	O/C	TSN 0				
SN:295098	HRS	13859.4		TSN 0				
	AFL	9175		TSN 0				
PROC. REF: AMM 33-50-37-900-801								
33-50-37-960-802-01 DISCARD OF THE EPS BATTERY PACKS - EPS 1 (5LE) BATTERY PACK								Service ATA:33
PN:C734-01-030	MOS	28-Oct-22	25		28-Nov-24		236 d	LIFE LIMIT
SN:CF33808/41/21	HRS	13832.6						
WC#: 33.200	AFL	9154						
PROC. REF: AMM 33-50-37-960-802								
33-50-37-960-802-02 DISCARD OF THE EPS BATTERY PACKS - EPS 2 (10LE) BATTERY PACK								Service ATA:33
PN:AD-C734-01-030	MOS	01-Oct-23	25		01-Nov-25		574 d	LIFE LIMIT
SN:295096	HRS	14169						
WC#: 33.200	AFL	9395						
PROC. REF: AMM 33-50-37-960-802								
33-50-37-960-802-03 DISCARD OF THE EPS BATTERY PACKS - EPS 3 (15LE) BATTERY PACK								Service ATA:33
PN:C734-01-030	MOS	19-Jan-23	25		19-Feb-25		319 d	LIFE LIMIT
SN:295098	HRS	13859.4						
WC#: 33.210	AFL	9175						
PROC. REF: AMM 33-50-37-960-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331811 PILOT READING LIGHT DIMMER BOX								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.020	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
331816 COPILOT READING LIGHT DIMMER BOX								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.020	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
331841 SHIELD LIGHTING POWER SUPPLY								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.050	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
331856 PILOT INSTRUMENT LIGHTING TRANSFORMER								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.060	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
331861 COPILOT INSTRUMENT LIGHTING TRANSFORMER								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.060	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
333801 AFT SERVICING COMPARTMENT CEILING LIGHT								Component ATA:33
PN:15-0254-3	MOS/MSC	04-Jul-08	O/C		TSN 0			
SN:020117067	HRS	6259.8			TSN 0			
WC#: 33.070	AFL	4184			TSN 0			
PROC. REF: GENERIC NO REF								
333811 BAGGAGE COMPARTMENT CEILING LIGHT								Component ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.070	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
333821	FORWARD SERVICING COMPARTMENT CEILING LIGHT							Component	ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
333841	BAGGAGE COMPARTMENT DOOR FLOODLIGHT							Component	ATA:33
PN:32-24-2	MOS/MSC	25-Oct-05	O/C	TSN 0					
SN:11-02	HRS	3949.4		TSN 0					
WC#: 33.080	AFL	2706		TSN 0					
PROC. REF: GENERIC NO REF									
333861	NOSE CONE INSPECTION LIGHT							Component	ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
334821	REAR NAVIGATION/ANTICOLLISION LIGHT POWER SUPPLY							Component	ATA:33
PN:6480702	MOS/MSC	29-Nov-16	O/C	TSN 0					
SN:680	HRS	10759.2		TSN 0					
WC#: 33.120	AFL	7272		TSN 0					
PROC. REF: GENERIC NO REF									
334826	FIN RED ANTICOLLISION LIGHT POWER SUPPLY							Component	ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
334841	LEFT LANDING LIGHT LENS ASSEMBLY							Component	ATA:33
PN:SPSF900-12-1-0	MOS/MSC	16-Apr-13	O/C	TSN 0					
SN:8813	HRS	9087.6		TSN 0					
WC#: 33.140	AFL	6131		TSN 0					
PROC. REF: GENERIC NO REF									
334846	RIGHT LANDING LIGHT LENS ASSEMBLY							Component	ATA:33
PN:SPSF900-11-1-0	MOS/MSC	16-Apr-13	O/C	TSN 0					
SN:8490	HRS	9087.6		TSN 0					
WC#: 33.140	AFL	6131		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
334851 ^U		LH NAVIGATION LIGHT ASSEMBLY					Component		ATA:33
PN:4137-01	MOS/MSC	09-Mar-10	O/C	TSN 0					
SN:NSN	HRS	7238.9		TSN 0					
WC#: 33.110	AFL	4855		TSN 0					
334851		LH NAVIGATION LIGHT FAIRING					Component		ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM GENERIC									
334852 ^U		RH NAVIGATION LIGHT ASSEMBLY					Component		ATA:33
PN:PN-UNKNOWN	MOS/MSC	20-Oct-10	O/C						
SN:UNKNOWN	HRS	7625.5							
WC#: 33.110	AFL	5112							
334852		RH NAVIGATION LIGHT FAIRING					Component		ATA:33
PN:PN	MOS								
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM GENERIC									
334876		LEFT WING ICE DETECTION LIGHT					Component		ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.180	AFL	0		TSN 0					
PROC. REF: AMM 33-40-45-900-801									
334881		RIGHT WING ICE DETECTION LIGHT					Component		ATA:33
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.180	AFL	0		TSN 0					
PROC. REF: AMM 33-40-45-900-801									
334C02 ^U		BELLY STROBE LIGHT ASSEMBLY					Component		ATA:33
PN:39-59-2	MOS/MSC	13-Oct-16	O/C						
SN:629	HRS	10749.4							
	AFL	7265							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334C51^U CHECK STROBE LIGHT INTENSITY Service ATA:33								
	MOS	07-Feb-24	12		07-Feb-25		307 d	
	HRS	14354.4						
	AFL	9502						
335851 EVACUATION LIGHT Component ATA:33								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335861 OUTSIDE EMERGENCY EXIT LIGHT Component ATA:33								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335871 FRAME 4/5 PASSENGER DOOR SPOTLIGHT Component ATA:33								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335881 FRAME 6/7 PASSENGER DOOR SPOTLIGHT Component ATA:33								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33A4851^U PULSE LIGHT BOX Component ATA:33								
PN:FE892-02	MOS/MSC	27-Jul-21	O/C	TSN 0				
SN:2509	HRS	12963.9		TSN 0				
	AFL	8644		TSN 0				
33A4852^U REMOVE AND REPLACE PULSE LIGHT BOX PULSE LIGHT BOX Service ATA:33								
PN:FE892-02	MOS/MSC	27-Jul-21	A/R					
SN:2509	HRS	12963.9						
	AFL	8644						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
34-00-00-900-803-46		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - PILOT READING LIGHT (L10LC)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-47		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - COPILOT READING LIGHT (R10LC)					Component	ATA:33	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 34 - NAVIGATION									
34-00-00-900-803-02		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - GUIDANCE PANEL CONTROLLER (150CA)					Component	ATA:34	
PN:822-0385-002	MOS/MSC	07-Jun-11	O/C	TSO 0					
SN:30F8W	HRS	7999.2		TSO 0					
WC#: 22.050	AFL	5367		TSO 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-03		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - BATTERY TEMPERATURE INDICATOR (270PC)					Component	ATA:34	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-06		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - TRIM POSITION INDICATOR (20CZ)					Component	ATA:34	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-07		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - CONFIGURATION PANEL (30CZ)					Component	ATA:34	
PN:206TS04Y12	MOS/MSC	21-Sep-12	O/C	TSR 0					
SN:1210	HRS	8893		TSR 0					
WC#: 27.055	AFL	5992		TSR 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-00-00-900-803-10 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - STAND-BY ALTIMETER (330FE) Component ATA:34								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 34.100	AFL							
PROC. REF: GENERIC NO REF								
34-00-00-900-803-11 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - STAND-BY MACH AIRSPEED INDICATOR (340FE) Component ATA:34								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 34.110	AFL							
PROC. REF: GENERIC NO REF								
34-00-00-900-803-21 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - DCP 1 (L370NH) Component ATA:34								
PN:822-0321-008	MOS/MSC	05-Jan-17	O/C	TSR 0				
SN:4C8R	HRS	10786		TSR 0				
WC#: 34.260	AFL	7286		TSR 0				
PROC. REF: GENERIC NO REF								
34-00-00-900-803-22 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - DCP 2 (R370NH) Component ATA:34								
PN:822-0321-008	MOS/MSC	20-May-16	O/C	TSO 4				
SN:1NW6D	HRS	10730.7		TSO 0				
WC#: 34.260	AFL	7258		TSO 0				
PROC. REF: GENERIC NO REF								
34-00-00-900-803-23 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - RSP 1 (L362NH) Component ATA:34								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
34-00-00-900-803-24 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - RSP 2 (R362NH) Component ATA:34								
PN:822-0273-002	MOS/MSC	16-Jan-20	O/C	TSR 6				
SN:221	HRS	12017.2		TSR 0				
WC#: 34.250	AFL	8091		TSR 0				
PROC. REF: GENERIC NO REF								
34-00-00-900-803-25 REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - AIRBRAKE/TAIPLANE/TRIM CONTROL BOX (10CZ) Component ATA:34								
PN:013015-18	MOS/MSC	08-Aug-09	O/C	TSR 0				
SN:1939	HRS	6940.9		TSR 0				
WC#: 27.050	AFL	4664		TSR 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-00-00-900-803-29		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - ICS 1 (L10RL)					Component	ATA:34	
PN:990-3333-264	MOS/MSC	25-Sep-11	O/C						
SN:9912163	HRS	8214.3							
WC#: 23.060	AFL	5517							
PROC. REF: GENERIC NO REF									
34-00-00-900-803-32		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - ICS 2 (R10RL)					Component	ATA:34	
PN:990-3333-264	MOS/MSC	20-Feb-15	O/C						
SN:01100011856	HRS	10153.1							
WC#: 23.060	AFL	6855							
PROC. REF: GENERIC NO REF									
34-00-00-900-803-33		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - HF 2 CONTROLLER (R170RC)					Component	ATA:34	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-48		REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - STAND-BY COMPASS (10NH)					Component	ATA:34	
PN:KCA0105W	MOS/MSC	26-Feb-11	O/C	TSN 0					
SN:BC5550209	HRS	7837.7		TSN 0					
WC#: 34.180	AFL	5247		TSN 0					
PROC. REF: GENERIC NO REF									
34-01-00-720-801-01 ^S		FUNCTIONAL TEST OF THE EFIS SYSTEM - PFD 1 (L360NH)					Service	ATA:34	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 34.010	AFL	9471							
PROC. REF: AMM 34-01-00-720-801									
PKG:16									
34-01-00-720-801-02 ^S		FUNCTIONAL TEST OF THE EFIS SYSTEM - PFD 2 (R360NH)					Service	ATA:34	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 34-01-00-720-801									
PKG:16									
34-01-00-720-801-03 ^S		FUNCTIONAL TEST OF THE EFIS SYSTEM - MFD 1 (L361NH)					Service	ATA:34	
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 34-01-00-720-801									
PKG:16									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-01-00-720-801-04 ^S		FUNCTIONAL TEST OF THE EFIS SYSTEM - MFD 2 (R361NH)						Service	ATA:34
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 34-01-00-720-801								PKG:16	
34-01-13-900-801-01		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 1 (L360NH)						Component	ATA:34
PN:622-9978-122	MOS/MSC	16-Jan-20	O/C						
SN:129VP	HRS	12071.2							
WC#: 34.230	AFL	8091							
PROC. REF: AMM 34-01-13-900-801									
34-01-13-900-801-02		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 2 (R360NH)						Component	ATA:34
PN:622-9978-122	MOS/MSC	18-Aug-20	O/C	TSO 0					
SN:1PC2	HRS	12328.2		TSO 0					
WC#: 34.230	AFL	8286		TSO 0					
PROC. REF: AMM 34-01-13-900-801									
34-01-13-900-801-03		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 1 (L361NH)						Component	ATA:34
PN:622-9978-122	MOS/MSC	08-Jan-20	O/C	TSO 0					
SN:129VP	HRS	11999.5		TSO 0					
WC#: 34.240	AFL	8078		TSO 0					
PROC. REF: AMM 34-01-13-900-801									
34-01-13-900-801-04		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 2 (R361NH)						Component	ATA:34
PN:622-9978-122	MOS/MSC	27-Nov-19	O/C						
SN:1BV6	HRS	11891.6		TSR 27.9					
WC#: 34.240	AFL	8026		TSR 19					
PROC. REF: AMM 34-01-13-900-801									
34-01-25-710-801-05		OPERATIONAL TEST OF THE EFIS FANS - EFIS FANS						Service	ATA:34
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 34-01-25-710-801									
34-03-01-900-801-01		REMOVAL / INSTALLATION OF THE DIGITAL DISTANCE RADIO MAGNETIC INDICATOR (DDRMI) - DDRMI (110NH)						Component	ATA:34
PN:520-3020-005	MOS/MSC	22-Oct-14	O/C	TSR 0					
SN:16953	HRS	10045.3		TSR 0					
	AFL	6783		TSR 0					
PROC. REF: AMM 34-03-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-00-720-801-01^S FUNCTIONAL TEST OF THE AIR DATA SYSTEM								
	MOS	27-Dec-23	24 (+1m)					Service ATA:34
	HRS	14292.8						
WC#: 34.030	AFL	9471						
PROC. REF: AMM 34-10-00-720-801								PKG:16
34-10-01-900-801-01 REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (120FE)								
PN:102AU1CK	MOS/MSC	11-Aug-22	O/C					Component ATA:34
SN:A90400	HRS	13706.6						
WC#: 34.090	AFL	9084						
PROC. REF: AMM 34-10-01-900-801								
34-10-11-720-801-01^S CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (L10CM)								
	MOS	05-May-22						Service ATA:34
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 34-10-11-720-801								PKG:21
34-10-11-720-801-02^S CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (R10CM)								
	MOS	05-May-22						Service ATA:34
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 34-10-11-720-801								PKG:21
34-10-11-900-801-01 REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - LH AOA SENSOR (L10CM)								
PN:861CAU2	MOS/MSC	25-Sep-09	O/C	TSR 0				Component ATA:34
SN:0203A	HRS	6976.6		TSR 0				
WC#: 27.425	AFL	4688		TSR 0				
PROC. REF: AMM 34-10-11-900-801								
34-10-11-900-801-02 REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - RH AOA SENSOR (R10CM)								
PN:861CAU2	MOS/MSC	08-Sep-09	O/C	TSN 0				Component ATA:34
SN:0016A	HRS	6962		TSN 0				
WC#: 27.425	AFL	4679		TSN 0				
PROC. REF: AMM 34-10-11-900-801								
34-11-00-680-801-01^S DRAINING OF THE TOTAL / STATIC PRESSURE SYSTEM - DRAINING PITOT/STATIC LINES								
	MOS	27-Dec-23	24 (+1m)					Service ATA:34
	HRS	14292.8						
WC#: 34.480	AFL	9471						
PROC. REF: AMM 34-11-00-680-801								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-11-00-790-801-01	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT STATIC AIR PRESSURE SYSTEM							Service	ATA:34
	MOS/MSC	19-Aug-11	A/R						
	HRS	8123							
WC#: 34.550	AFL	5461							
PROC. REF: AMM 34-11-00-790-801									
34-11-01-200-801-01	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - LH TOTAL PRESSURE PROBE (L100FE)							Service	ATA:34
	MOS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
WC#: 34.060	AFL	7323							
PROC. REF: AMM 34-11-01-200-801									
34-11-01-200-801-02	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - RH TOTAL PRESSURE PROBE (R100FE)							Service	ATA:34
	MOS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
	AFL	7323							
PROC. REF: AMM 34-11-01-200-801									
34-11-01-200-801-03	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - STAND-BY TOTAL PRESSURE PROBE (105FE)							Service	ATA:34
	MOS/MSC	08-Feb-17	O/C						
	HRS	10863.8							
	AFL	7323							
PROC. REF: AMM 34-11-01-200-801									
34-11-01-900-801-01	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - LH TOTAL PRESSURE PROBE (L100FE)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.070	AFL	0		TSN 0					
PROC. REF: AMM 34-11-01-900-801									
34-11-01-900-801-02	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - RH TOTAL PRESSURE PROBE (R100FE)							Component	ATA:34
PN:50520	MOS/MSC	25-Apr-09	O/C						
SN:4039	HRS	6732.2							
WC#: 34.070	AFL	4518							
PROC. REF: AMM 34-11-01-900-801									
34-11-01-900-801-03	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - STAND-BY TOTAL PRESSURE PROBE (105FE)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.070	AFL	0		TSN 0					
PROC. REF: AMM 34-11-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-05-900-801-01 REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L110FE) Component ATA:34								
PN:C16778AA	MOS/MSC	04-Nov-20	O/C					
SN:1434	HRS	12473.8						
WC#: 34.080	AFL	8378						
PROC. REF: AMM 34-11-05-900-801, AMM 34-11-05-900-801								
34-11-05-900-801-02 REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R110FE) Component ATA:34								
PN:C16778AA	MOS/MSC	04-Nov-20	O/C	TSN 0				
SN:1242	HRS	12473.8		TSN 0				
WC#: 34.080	AFL	8378		TSN 0				
PROC. REF: AMM 34-11-05-900-801, AMM 34-11-05-900-801								
34-11-05-900-802-01 REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - PILOT STAND-BY STATIC PRESSURE PROBE (L900FE) Component ATA:34								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-05-900-802								
34-11-05-900-802-02 REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - COPILOT STAND-BY STATIC PRESSURE PROBE (R900FE) Component ATA:34								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-05-900-802								
34-14-01-700-881-01 TEST NO. 1 AIR DATA (ADC) COMPUTER (FAR 91.411) Service ATA:34								
PN:PN-UNKNOWN	MOS	19-Dec-23	24		19-Dec-25		622 d	MANDATORY
SN:YX5G	HRS							
WC#: 34.050	AFL							
PROC. REF: FAR 91.411								
34-14-01-700-881-02 TEST NO. 2 AIR DATA (ADC) COMPUTER (FAR 91.411) Service ATA:34								
PN:822-0374-439	MOS	19-Dec-23	24		19-Dec-25		622 d	MANDATORY
SN:25UC	HRS							
WC#: 34.050	AFL							
PROC. REF: FAR 91.411								
34-14-01-900-801-01 REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (L320FE) Component ATA:34								
PN:PN-UNKNOWN	MOS/MSC	08-Jan-06	O/C	TSO 0				
SN:YX5G	HRS	4641.5		TSO 0				
WC#: 34.050	AFL	3170		TSO 0				
PROC. REF: AMM 34-14-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-14-01-900-801-02		REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (R320FE)					Component	ATA:34	
PN:822-0374-439	MOS/MSC	29-Dec-11	O/C						
SN:25UC	HRS	8367.12							
WC#: 34.050	AFL	5617							
PROC. REF: AMM 34-14-01-900-801									
34-15-02-700-881-01		TEST STAND-BY ALTIMETER (FAR 91.411)					Service	ATA:34	
PN:PN	MOS/MSC	19-May-20	N/A						
SN:NOT INSTALLED	HRS	12158.5							
WC#: 34.100	AFL	8174							
PROC. REF: FAR 91.411									
34-16-00-720-801-01		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L320FE)					Service	ATA:34	
PN:PN-UNKNOWN	MOS	19-Dec-23	12 (+3%)		19-Dec-24	30-Dec-24	257 d (+11)		
SN:YX5G	HRS	14292.8							
WC#: 34.050	AFL	9471							
PROC. REF: AMM 34-16-00-720-801									
34-16-00-720-801-02		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R320FE)					Service	ATA:34	
PN:822-0374-439	MOS	19-Dec-23	12 (+3%)		19-Dec-24	30-Dec-24	257 d (+11)		
SN:25UC	HRS	14292.8							
WC#: 34.050	AFL	9471							
PROC. REF: AMM 34-16-00-720-801									
34-16-00-720-801-03		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY ALTIMETER (330FE)					Service	ATA:34	
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
WC#: 34.100	AFL								
PROC. REF: AMM 34-16-00-720-801									
34-16-00-720-801-04		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY MACH AIRSPEED INDICATOR (340FE)					Service	ATA:34	
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
WC#: 34.110	AFL								
PROC. REF: AMM 34-16-00-720-801									
34-16-00-720-801-05		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADU (470FE)					Service	ATA:34	
PN:27100-01-01	MOS	19-Dec-23	24 (+3%)		19-Dec-25	10-Jan-26	622 d (+22)		
SN:M018275	HRS	14292.8							
WC#: 34.510	AFL	9471							
PROC. REF: AMM 34-16-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-00-710-801-01 ^S OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 1 (151NP) Service ATA:34								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
WC#: 34.420	AFL	9008						
PROC. REF: AMM 34-21-00-710-801								PKG:21
34-21-00-710-801-02 ^S OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 2 (250NP) Service ATA:34								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 34-21-00-710-801								PKG:21
34-21-00-710-801-03 OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 3 (51NP) Service ATA:34								
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 34-21-00-710-801								
34-21-00-710-801-04 ^S OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - AHC (710NP) Service ATA:34								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 34-21-00-710-801								PKG:21
34-21-01-900-801-01 REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) AND ATTITUDE AND HEADING COMPUTER (AHC) - IRU 1 (150NP) OR (151NP) Component ATA:34								
PN:HG2001GD03	MOS/MSC	18-Aug-05	O/C					
SN:00053410	HRS	3686.2						
WC#: 34.410	AFL	2545						
PROC. REF: AMM 34-21-01-900-801								
34-21-01-900-801-02 REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) AND ATTITUDE AND HEADING COMPUTER (AHC) - IRU 2 (250NP) Component ATA:34								
PN:HG2001GD03	MOS/MSC	18-Aug-05	O/C					
SN:00043303	HRS	3686.2						
WC#: 34.410	AFL	2545						
PROC. REF: AMM 34-21-01-900-801								
34-21-01-900-801-03 REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) AND ATTITUDE AND HEADING COMPUTER (AHC) - IRU 3 (51NP) Component ATA:34								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 34.415	AFL							
PROC. REF: AMM 34-21-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-21-01-900-801-04		REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) AND ATTITUDE AND HEADING COMPUTER (AHC) - AHC (710NP)					Component	ATA:34	
PN:622-9336-400	MOS/MSC	11-Oct-17	O/C	TSR 0					
SN:2130	HRS	11173.5		TSR 0					
WC#: 34.210	AFL	7541		TSR 0					
PROC. REF: AMM 34-21-01-900-801									
34-21-13-100-801-01 ^S		CLEANING / REPLACEMENT OF THE IRU FAN FILTERS					Service	ATA:34	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 34.410	AFL	9008							
PROC. REF: AMM 34-21-13-100-801									
PKG:22									
34-22-00-710-801-01 ^S		OPERATIONAL TEST OF THE ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS)					Service	ATA:34	
	MOS	05-May-22							
	HRS	13592.3	3200 (+40)						
WC#: 34.120	AFL	9008							
PROC. REF: AMM 34-22-00-710-801									
PKG:22									
34-23-00-720-801-01		FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - ADU (470FE)					Service	ATA:34	
PN:27100-01-01	MOS	05-May-22	24 (+3%)		05-May-24	27-May-24	29 d (+22)		
SN:M018275	HRS	13592.3							
	AFL	9008							
PROC. REF: AMM 34-23-00-720-801									
34-23-00-720-801-02		FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - SFD (320NH1)					Service	ATA:34	
PN:39204-00-01	MOS	05-May-22	24 (+3%)		05-May-24	27-May-24	29 d (+22)		
SN:M017055	HRS	13592.3							
	AFL	9008							
PROC. REF: AMM 34-23-00-720-801									
34-23-00-720-801-03 ^U		FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - STAND-BY HORIZON					Service	ATA:34	
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
34-23-00-820-801-01		CALIBRATION OF THE STAND-BY HORIZON - STAND-BY HORIZON (320NH)					Service	ATA:34	
PN:PN-UNKNOWN	MOS/MSC	10-Nov-06	C/C						
SN:3509	HRS	4932.4							
WC#: 34.170	AFL	3341							
PROC. REF: AMM 34-23-00-820-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-23-00-900-801-01		REMOVAL / INSTALLATION OF THE STAND-BY HORIZON - STAND-BY HORIZON (320NH)					Component	ATA:34	
PN:PN-UNKNOWN	MOS/MSC	10-Nov-06	O/C						
SN:3509	HRS	4932.4							
WC#: 34.170	AFL	3341							
PROC. REF: AMM 34-23-00-900-801									
34-23-01-900-801-01		REMOVAL / INSTALLATION OF THE SECONDARY FLIGHT DISPLAY (SFD) - SFD (320NH1)					Component	ATA:34	
PN:39204-00-01	MOS/MSC	30-Aug-13	O/C	TSR 0					
SN:M017055	HRS	9280.8		TSR 0					
WC#: 34.490	AFL	6264		TSR 0					
PROC. REF: AMM 34-23-01-900-801									
34-23-05-700-881-01		TEST SECONDARY FLIGHT DISPLAY (SFD) DATA UNIT (FAR 91.411)					Service	ATA:34	
PN:27100-01-01	MOS	05-May-22	24		05-May-24		29 d	MANDATORY	
SN:M018275	HRS	13592.3							
WC#: 34.510	AFL	9008							
PROC. REF: FAR 91.411									
34-23-05-900-801-01		REMOVAL / INSTALLATION OF THE SECONDARY FLIGHT DISPLAY AIR DATA UNIT (ADU) - ADU (470FE)					Component	ATA:34	
PN:27100-01-01	MOS/MSC	20-May-16	O/C						
SN:M018275	HRS	10730.7							
WC#: 34.510	AFL	7258							
PROC. REF: AMM 34-23-05-900-801									
34-25-00-820-801-01		COMPENSATION OF STAND-BY COMPASS					Service	ATA:34	
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 34-25-00-820-801									
34-31-00-710-801-01		OPERATIONAL TEST OF THE HEAD-UP GUIDANCE SYSTEM (HGS)					Service	ATA:34	
	MOS/MSC		O/C						
	HRS								
WC#: 34.530	AFL								
PROC. REF: AMM 34-31-00-710-801									
34-31-00-720-801-01		FUNCTIONAL TEST OF THE HGS DUAL POWER SUPPLY					Service	ATA:34	
	MOS/MSC		N/A						
	HRS								
WC#: 34.040	AFL								
PROC. REF: AMM 34-31-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-31-00-720-801-01A	FUNCTIONAL TEST FUNCTIONAL TEST OF THE HGS DUAL POWER SUPPLY (MANDATORY 5-40)							Service	ATA:34
	MOS/MSC		N/A						
	HRS								
WC#: 34.040	AFL								
PROC. REF: AMM 34-31-00-720-801									
34-31-01-900-801-01	REMOVAL / INSTALLATION OF THE HGS OVERHEAD UNIT - OHU (215NH)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-01-900-801									
34-31-05-900-801-01	REMOVAL / INSTALLATION OF THE HGS COMBINER - HGS COMBINER (221NH)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-05-900-801									
34-31-09-900-801-01	REMOVAL / INSTALLATION OF THE HGS COMPUTER - HGS COMPUTER (211NH)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-09-900-801									
34-31-17-900-801-01	REMOVAL / INSTALLATION OF THE HGS CONTROL PANEL - HGS CONTROL PANEL (225NH)							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-17-900-801									
34-41-01-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR RECEIVER / TRANSMITTER / ANTENNA ASSEMBLY - WEATHER RADAR RECEIVER / TRANSMITTER/ ANTENNA (210NP)							Component	ATA:34
PN:622-8441-003	MOS/MSC	14-Apr-12	O/C	TSR 0					
SN:2235	HRS	8522.6		TSR 0					
WC#: 34.290	AFL	5731		TSR 0					
PROC. REF: AMM 34-41-01-900-801									
34-41-13-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR CONTROL PANEL - WEATHER RADAR CONTROL PANEL (L220NP)							Component	ATA:34
PN:622-9932-002	MOS/MSC	24-Apr-04	O/C	TSO 0					
SN:1250X	HRS	2327.5		TSO 0					
WC#: 34.292	AFL	1647		TSO 0					
PROC. REF: AMM 34-41-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-42-00-710-801-01		OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (20NL)					Service	ATA:34
PN:622-2855-011	MOS/MSC	28-May-21	O/C					
SN:441Y	HRS	12868.6						
	AFL	8576						
PROC. REF: AMM 34-42-00-710-801								
34-42-00-710-801-02		OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (50NL)					Service	ATA:34
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
	AFL							
PROC. REF: AMM 34-42-00-710-801								
34-42-01-900-801-01		REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER AND CONVERTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (20NL)					Component	ATA:34
PN:622-2855-011	MOS/MSC	28-May-21	O/C					
SN:441Y	HRS	12868.6						
WC#: 34.295	AFL	8576						
PROC. REF: AMM 34-42-01-900-801								
34-42-01-900-801-02		REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER AND CONVERTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (50NL)					Component	ATA:34
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
	AFL							
PROC. REF: AMM 34-42-01-900-801								
34-42-01-900-801-03		REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER AND CONVERTER - RADIO ALTIMETER CONVERTER (21NL)					Component	ATA:34
PN:622-7209-002	MOS/MSC	28-Dec-23	O/C					
SN:1RG1	HRS	14292.8						
WC#: 34.280	AFL	9471						
PROC. REF: AMM 34-42-01-900-801								
34-42-09-900-801-01		REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 TRANSMITTER ANTENNA (10NL)					Component	ATA:34
PN:S67-2002-13	MOS/MSC	20-Jul-14	O/C					
SN:545-5487	HRS	9833.8						
WC#: 34.270	AFL	6636						
PROC. REF: AMM 34-42-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-42-09-900-801-02		REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 RECEIVER ANTENNA (11NL)						Component	ATA:34
PN:S67-2002-13	MOS/MSC	20-Jul-14	O/C						
SN:545-5486	HRS	9833.8							
WC#: 34.270	AFL	6636							
PROC. REF: AMM 34-42-09-900-801									
34-44-01-900-801-01		REMOVAL / INSTALLATION OF THE TCAS TRANSCEIVER - TCAS TRANSCEIVER (350NP)						Component	ATA:34
PN:822-1294-032	MOS/MSC	05-Apr-22	O/C						
SN:158955	HRS	13556.3							
	AFL	8984							
PROC. REF: AMM 34-44-01-900-801									
34-51-01-820-801-01		CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L210NR)						Service	ATA:34
PN:622-7194-201	MOS	05-May-22	24 (+3%)		05-May-24	27-May-24	29 d (+22)		
SN:4CDU	HRS	13592.3							
WC#: 34.340	AFL	9008							
PROC. REF: AMM 34-51-01-820-801									
34-51-01-820-801-02		CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R210NR)						Service	ATA:34
PN:622-7194-201	MOS	05-May-22	24 (+3%)		05-May-24	27-May-24	29 d (+22)		
SN:4AMH	HRS	13592.3							
WC#: 34.340	AFL	9008							
PROC. REF: AMM 34-51-01-820-801									
34-51-05-900-801-01		REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - LH VOR/LOC ANTENNA (L230NR)						Component	ATA:34
PN:DMN4-45-3	MOS/MSC	16-Apr-13	O/C	TSN 0					
SN:12773	HRS	9087.6		TSN 0					
WC#: 34.330	AFL	6131		TSN 0					
PROC. REF: AMM 34-51-05-900-801									
34-51-05-900-801-02		REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - RH VOR/LOC ANTENNA (R230NR)						Component	ATA:34
PN:DMN4-45-3	MOS/MSC	16-Apr-13	O/C	TSN 0					
SN:12774	HRS	9087.6		TSN 0					
WC#: 34.330	AFL	6131		TSN 0					
PROC. REF: AMM 34-51-05-900-801									
34-51-17-900-801-01		REMOVAL / INSTALLATION OF THE MARKER ANTENNA - MARKER ANTENNA (260NR) .						Component	ATA:34
PN:S35-1000-1	MOS/MSC	07-Oct-11	O/C	TSN 0					
SN:101-6878	HRS	8225.6		TSN 0					
WC#: 34.370	AFL	5529		TSN 0					
PROC. REF: AMM 34-51-17-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-52-05-900-801-01		REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 1 ANTENNA (L330NR)					Component	ATA:34	
PN:DMNI50-2-2	MOS/MSC	07-Oct-11	O/C	TSN 0					
SN:126436	HRS	8225.6		TSN 0					
WC#: 34.400	AFL	5529		TSN 0					
PROC. REF: AMM 34-52-05-900-801									
34-52-05-900-801-02		REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 2 ANTENNA (R330NR)					Component	ATA:34	
PN:DMNI50-2-2	MOS/MSC	07-Oct-11	O/C	TSN 0					
SN:126991	HRS	8225.6		TSN 0					
WC#: 34.400	AFL	5529		TSN 0					
PROC. REF: AMM 34-52-05-900-801									
34-54-00-700-881-01		TEST NO. 1 AIR TRAFFIC CONTROL (ATC) TRANSPONDER (FAR 91.413)					Service	ATA:34	
PN:622-9210-008	MOS	19-Dec-23	24		19-Dec-25		622 d	MANDATORY	
SN:7516	HRS	14292.8							
WC#: 34.300	AFL	9471							
PROC. REF: FAR 91.413									
34-54-00-700-881-02		TEST NO. 2 AIR TRAFFIC CONTROL (ATC) TRANSPONDER (FAR 91.413)					Service	ATA:34	
PN:622-9210-007	MOS	19-Dec-23	24		19-Dec-25		622 d	MANDATORY	
SN:02KC	HRS								
WC#: 34.300	AFL								
PROC. REF: FAR 91.413									
34-54-00-720-802-01		FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS					Service	ATA:34	
PN:622-9210-008	MOS	19-Dec-23	24 (+3%)		19-Dec-25	10-Jan-26	622 d (+22)		
SN:7516	HRS	14292.8							
WC#: 34.300	AFL	9471							
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802									
34-54-00-720-802-02		FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS					Service	ATA:34	
PN:622-9210-007	MOS	19-Dec-23	24 (+3%)		19-Dec-25	10-Jan-26	622 d (+22)		
SN:02KC	HRS	14292.8							
WC#: 34.300	AFL	9471							
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802									
34-54-05-900-801-01		REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 UPPER ANTENNA (L330NP)					Component	ATA:34	
PN:DMNI50-2-2	MOS/MSC	07-Oct-11	O/C	TSN 0					
SN:126989	HRS	8225.6		TSN 0					
WC#: 34.310	AFL	5529		TSN 0					
PROC. REF: AMM 34-54-05-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-54-05-900-801-02		REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 UPPER ANTENNA (R330NP)					Component	ATA:34	
PN:DMNI50-2-2	MOS/MSC	07-Oct-11	O/C	TSN 0					
SN:126990	HRS	8225.6		TSN 0					
WC#: 34.310	AFL	5529		TSN 0					
PROC. REF: AMM 34-54-05-900-801									
34-54-05-900-801-03		REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 LOWER ANTENNA (L331NP)					Component	ATA:34	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.320	AFL	0		TSN 0					
PROC. REF: AMM 34-54-05-900-801									
34-54-05-900-801-04		REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 LOWER ANTENNA (R331NP)					Component	ATA:34	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.320	AFL	0		TSN 0					
PROC. REF: AMM 34-54-05-900-801									
34-58-01-710-881-01		CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)					Service	ATA:34	
	DAYS/MSC	01-Mar-00	A/R					MANDATORY	
	HRS	0							
WC#: 34.345	AFL	0							
PROC. REF: FAR 91.171									
34-61-01-900-801-01		REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 1 (L110NG)					Component	ATA:34	
PN:822-0868-057	MOS/MSC	02-Jun-21	O/C	TSR 1					
SN:1259	HRS	12876.6		TSR 0					
WC#: 34.540	AFL	8581		TSR 0					
PROC. REF: AMM 34-61-01-900-801									
34-61-01-900-801-02		REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 2 (R110NG)					Component	ATA:34	
PN:822-1354-102	MOS/MSC	23-Feb-22	O/C						
SN:4DCB	HRS	13478.6							
WC#: 34.540	AFL	8935							
PROC. REF: AMM 34-61-01-900-801									
34-61-01-900-801-03		REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 3 (L146NG)					Component	ATA:34	
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
WC#: 34.540	AFL								
PROC. REF: AMM 34-61-01-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
34-61-09-960-801-01		REPLACEMENT OF THE CONTROL DISPLAY UNIT BATTERY - CDU 3 (740NG) (OPTIONAL)							Service ATA:34
PN:822-1354-102	MOS/MSC		N/A						
SN:1119F	HRS								
	AFL								
PROC. REF: AMM 34-61-09-960-801									
34-90-10-900-801-01		HONEYWELL FMS CONTROL DISPLAY (CDU) UNIT							Component ATA:34
PN:822-1354-102	MOS/MSC	10-Feb-15	O/C	TSO 0					
SN:1119F	HRS	10150.3		TSO 0					
	AFL	6852		TSO 0					
PROC. REF: GENERIC NO REF									
340121 ^U		REPLACE (MDC) MAINTENANCE DIAGNOSTIC COMPUTER INTERNAL BATTERY							Service ATA:34
PN:622-9818-213	MOS/MSC	09-Jan-24	O/C						
SN:5FXD	HRS	14319.6							
WC#: 34.210	AFL	9484							
PROC. REF: GENERIC NO REF									
341091 ^U		REPLACE NO. 1 AIR DATA (ADC) COMPUTER BATTERY							Service ATA:34
PN:PN-UNKNOWN	MOS/MSC	05-May-22	O/C						
SN:YX5G	HRS	13592.3							
WC#: 34.050	AFL	9008							
PROC. REF: GENERIC NO REF									
341092 ^U		REPLACE NO. 2 AIR DATA (ADC) COMPUTER BATTERY							Service ATA:34
PN:822-0374-439	MOS/MSC		O/C						
SN:25UC	HRS								
WC#: 34.050	AFL								
PROC. REF: GENERIC NO REF									
342011		NO. 1 AHRS - (ECU) EXTERNAL COMPENSATION/(CCU) COMPENSATION AND CONTROL UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
342012		NO. 2 AHRS - (ECU) EXTERNAL COMPENSATION/(CCU) COMPENSATION AND CONTROL UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342121^U REPLACE NO. 1 (AHC) ATTITUDE AND HEADING REFERENCE COMPUTER BATTERY Service ATA:34								
PN:622-9336-400	MOS/MSC		O/C					
SN:2130	HRS							
WC#: 34.210	AFL							
PROC. REF: GENERIC NO REF								
342122^U REPLACE NO. 2 (AHC) ATTITUDE AND HEADING REFERENCE COMPUTER BATTERY Service ATA:34								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 34.210	AFL							
PROC. REF: GENERIC NO REF								
342831 (IAP) INTEGRATED AVIONICS PROCESSOR Component ATA:34								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342841 (DAU) DATA ACQUISITION UNIT Component ATA:34								
PN:822-0320-003	MOS/MSC	28-Sep-09	O/C					
SN:111J	HRS	6978.6						
WC#: 34.200	AFL	4690						
PROC. REF: GENERIC NO REF								
342842 LH UPPER (1A) I/O CONCENTRATOR Component ATA:34								
PN:622-9814-634	MOS/MSC	11-May-07	O/C					
SN:468X	HRS	5260.1						
WC#: 34.450	AFL	3550						
PROC. REF: GENERIC NO REF								
342843 LH LOWER (1B) I/O CONCENTRATOR Component ATA:34								
PN:622-9814-634	MOS/MSC	11-May-07	O/C					
SN:485R	HRS	5260.1						
WC#: 34.450	AFL	3550						
PROC. REF: GENERIC NO REF								
342844 RH UPPER (2B) I/O CONCENTRATOR Component ATA:34								
PN:622-9814-634	MOS/MSC	11-May-07	O/C					
SN:485P	HRS	5260.1						
WC#: 34.460	AFL	3550						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342845 RH LOWER (2A) I/O CONCENTRATOR								Component ATA:34
PN:622-9814-632	MOS/MSC	14-Dec-04	O/C		TSR 0			
SN:485T	HRS	2914.5			TSR 0			
WC#: 34.460	AFL	2035			TSR 0			
PROC. REF: GENERIC NO REF								
342847 (DBU) DATA BASE UNIT								Component ATA:34
PN:822-2215-002	MOS/MSC	18-Feb-14	O/C		TSO 0			
SN:30GYP	HRS	9548.1			TSO 0			
WC#: 34.520	AFL	6444			TSO 0			
PROC. REF: GENERIC NO REF								
342850 NO. 2 (AHC) ATTITUDE AND HEADING REFERENCE COMPUTER								Component ATA:34
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 34.210	AFL							
PROC. REF: GENERIC NO REF								
342852 NO. 1 ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS) FLUX VALVE								Component ATA:34
PN:622-8154-001	MOS/MSC	04-Dec-06	O/C		TSN 0			
SN:32718	HRS	4979.5			TSN 0			
WC#: 34.220	AFL	3377			TSN 0			
PROC. REF: GENERIC NO REF								
342854 NO. 2 ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS) FLUX VALVE								Component ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0			
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.220	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
344806 NO. 1 AIR TRAFFIC CONTROL (ATC) TRANSPONDER								Component ATA:34
PN:622-9210-008	MOS/MSC	05-May-22	O/C					
SN:7516	HRS	13592.3						
WC#: 34.300	AFL	9008						
PROC. REF: GENERIC NO REF								
344811 NO. 2 AIR TRAFFIC CONTROL (ATC) TRANSPONDER								Component ATA:34
PN:622-9210-007	MOS/MSC	05-May-22	O/C					
SN:02KC	HRS	13592.3						
WC#: 34.300	AFL	9008						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
345801	NO. 1 ADF RECEIVER							Component	ATA:34
PN:622-7382-101	MOS/MSC	18-Nov-09	O/C						
SN:4ANK	HRS	7066.1							
WC#: 34.350	AFL	4752							
PROC. REF: GENERIC NO REF									
345806	NO. 2 ADF RECEIVER							Component	ATA:34
PN:622-7382-101	MOS/MSC	18-Nov-09	O/C						
SN:3TYA	HRS	7066.1							
WC#: 34.350	AFL	4752							
PROC. REF: GENERIC NO REF									
345811	NO. 1 ADF LOOP ANTENNA							Component	ATA:34
PN:622-7383-001	MOS/MSC	11-Dec-23	O/C	TSN 0					
SN:4KDD4N	HRS	14292.8		TSN 0					
WC#: 34.360	AFL	9471		TSN 0					
PROC. REF: GENERIC NO REF									
345816	NO. 2 ADF LOOP ANTENNA							Component	ATA:34
PN:622-7383-001	MOS/MSC	13-May-15	O/C	TSN 0					
SN:49Y9V	HRS	10259.8		TSN 0					
WC#: 34.360	AFL	6931		TSN 0					
PROC. REF: GENERIC NO REF									
345836	GLIDE SLOPE ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.380	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
345841	NO. 1 DME TRANSCEIVER							Component	ATA:34
PN:622-7309-101	MOS/MSC	29-Oct-01	O/C	TSO 0					
SN:24B8	HRS	294.7		TSO 0					
WC#: 34.390	AFL	198		TSO 0					
PROC. REF: GENERIC NO REF									
345846	NO. 2 DME TRANSCEIVER							Component	ATA:34
PN:622-7309-101	MOS/MSC	15-Nov-10	O/C	TSO 0					
SN:1PMH	HRS	7690.7		TSO 0					
WC#: 34.390	AFL	5150		TSO 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
345861		NO. 1 VOR/ILS/MARKER RECEIVER					Component		ATA:34
PN:622-7194-201	MOS/MSC	20-May-16	O/C						
SN:4CDU	HRS	10730.7							
WC#: 34.340	AFL	7258							
PROC. REF: GENERIC NO REF									
345866		NO. 2 VOR/ILS/MARKER RECEIVER					Component		ATA:34
PN:622-7194-201	MOS/MSC	20-May-16	O/C						
SN:4AMH	HRS	10730.7							
WC#: 34.340	AFL	7258							
PROC. REF: GENERIC NO REF									
345A03^U		UPDATE FMS NAV DATABASE					Service		ATA:34
	DAYS	14-Feb-24	30		15-Mar-24		OVD		
	HRS	14354.4							
	AFL	9502							
346121^U		REPLACE NO. 1 FLIGHT MANAGEMENT (FMC) COMPUTER BATTERY					Service		ATA:34
PN:822-0868-057	MOS/MSC	02-Jun-21	O/C						
SN:1259	HRS	12876.6							
WC#: 34.540	AFL	8581							
PROC. REF: GENERIC NO REF									
346122^U		REPLACE NO. 2 FLIGHT MANAGEMENT (FMC) COMPUTER BATTERY					Service		ATA:34
PN:822-1354-102	MOS/MSC		O/C						
SN:4DCB	HRS								
WC#: 34.540	AFL								
PROC. REF: GENERIC NO REF									
346123^U		REPLACE NO. 3 FLIGHT MANAGEMENT (FMC) COMPUTER BATTERY					Service		ATA:34
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
WC#: 34.540	AFL								
PROC. REF: GENERIC NO REF									
349806		NO. 1 INERTIAL REFERENCE SYSTEM (IRS) MODE SELECT (MSU) UNIT					Component		ATA:34
PN:CG1042AB03	MOS/MSC	27-Feb-09	O/C	TSR 0					
SN:97112233	HRS	6660.3		TSR 0					
WC#: 34.430	AFL	4463		TSR 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 34 - NAVIGATION									
349816	NO. 2 INERTIAL REFERENCE SYSTEM (IRS) MODE SELECT (MSU) UNIT							Component	ATA:34
PN:CG1042AB03	MOS/MSC	06-Apr-06	O/C	TSR 0					
SN:1167	HRS	4265.6		TSR 0					
WC#: 34.430	AFL	2928		TSR 0					
PROC. REF: GENERIC NO REF									
349826	NO. 3 INERTIAL REFERENCE SYSTEM (IRS) MODE SELECT (MSU) UNIT							Component	ATA:34
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.430	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 35 - OXYGEN									
34-00-00-900-803-31	REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - LH PILOT OXYGEN MASK BOX (L20WH)							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
34-00-00-900-803-36	REMOVAL / INSTALLATION OF THE COCKPIT EQUIPMENT - RH PILOT OXYGEN MASK BOX (R20WH)							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
35-10-05-350-801-01	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L10WH1)							Service	ATA:35
PN:MC10-12-101	MOS	15-Jun-22	72 (+3%)		15-Jun-28	19-Aug-28	1531 d (+65)	OVERHAUL	
SN:2700	HRS	13630.3							
WC#: 35.020	AFL	9028							
PROC. REF: AMM 35-10-05-350-801									
35-10-05-350-801-02	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R10WH1)							Service	ATA:35
PN:MC10-12-152	MOS	15-Jun-22	72 (+3%)		15-Jun-28	19-Aug-28	1531 d (+65)	OVERHAUL	
SN:SE18552	HRS	13788.2							
WC#: 35.020	AFL	9127							
PROC. REF: AMM 35-10-05-350-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-10-05-350-801-03 RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - THIRD CREW MEMBER OXYGEN MASK (M10WH1) Service ATA:35								
PN:MC10-12-152	MOS	30-Jan-24	72 (+3%)		30-Jan-30	03-Apr-30	2125 d (+63)	OVERHAUL
SN:116000	HRS	14354.4						
WC#: 35.020	AFL	9502						
PROC. REF: AMM 35-10-05-350-801								
35-10-05-710-801-01 ^S OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L10WH1) Service ATA:35								
	MOS	07-Feb-24	12 (+1m)					
	HRS	14354.4						
WC#: 35.020	AFL	9502						
PROC. REF: AMM 35-10-05-710-801								
35-10-05-710-801-02 ^S OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R10WH1) Service ATA:35								
	MOS	07-Feb-24	12 (+1m)					
	HRS	14354.4						
WC#: 35.020	AFL	9502						
PROC. REF: AMM 35-10-05-710-801								
35-10-05-710-801-03 ^S OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (M10WH1) Service ATA:35								
	MOS	07-Feb-24	12 (+1m)					
	HRS	14354.4						
WC#: 35.020	AFL	9502						
PROC. REF: AMM 35-10-05-710-801								
35-10-05-900-801-01 REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L10WH1) Component ATA:35								
PN:MC10-12-101	MOS/MSC	15-Jun-22	O/C	TSO 0				
SN:2700	HRS	13630.3		TSO 0				
WC#: 35.020	AFL	9028		TSO 0				
PROC. REF: AMM 35-10-05-900-801								
35-10-05-900-801-02 REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R10WH1) Component ATA:35								
PN:MC10-12-152	MOS/MSC	05-Oct-22	O/C	TSO 0				
SN:SE18552	HRS	13788.2		TSO 0				
WC#: 35.020	AFL	9127		TSO 0				
PROC. REF: AMM 35-10-05-900-801								
35-10-05-900-801-03 REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (M10WH1) Component ATA:35								
PN:MC10-12-152	MOS/MSC	30-Jan-24	O/C	TSO 0				
SN:116000	HRS	14354.4		TSO 0				
WC#: 35.020	AFL	9502		TSO 0				
PROC. REF: AMM 35-10-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20-00-210-801-01^S GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS AND SMOKE MASKS Service ATA:35								
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
WC#: 35.160	AFL	9471						
PROC. REF: AMM 35-20-00-210-801								PKG:16
35-20-00-720-801-01^S FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM Service ATA:35								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 35-20-00-720-801, AMM 35-20-00-720-801								PKG:21
35-20-00-720-801-01A FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM (MANDATORY 5-40) Service ATA:35								
	MOS	05-May-22						MANDATORY 5-40
	HRS	13592.3	1740		15332.3		977.9	
WC#: 35.040	AFL	9008						
PROC. REF: AMM 35-20-00-720-801, AMM 35-20-00-720-801								
35-20-01-350-801-01 RESTORATION OF THE PASSENGER OXYGEN CONTROLLER (OVERHAUL) - PASSENGER OXYGEN CONTROLLER (10WJ) Service ATA:35								
PN:RCA74-03	MOS	16-Jul-19	72 (+3%)		16-Jul-25	20-Sep-25	466 d (+66)	OVERHAUL
SN:1026	HRS	11761.3						
WC#: 35.050	AFL	7947						
PROC. REF: AMM 35-20-01-350-801								
35-20-01-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN CONTROLLER Component ATA:35								
PN:RCA74-03	MOS/MSC	16-Jul-19	H/T	TSO 0				
SN:1026	HRS	11761.3		TSN 6752.7, TSO 0				
WC#: 35.050	AFL	7947		TSN 4311, TSO 0				
PROC. REF: AMM 35-20-01-900-801, AMM 35-20-01-900-801								
35-20-09-900-801-01 NO. 01 PASSENGER OXYGEN MASK Component ATA:35								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.070	AFL	0		TSN 0				
PROC. REF: AMM 35-20-09-900-801								
35-20-09-900-801-01 NO. 02 PASSENGER OXYGEN MASK Component ATA:35								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.070	AFL	0		TSN 0				
PROC. REF: AMM 35-20-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
35-20-09-900-801-01	NO. 03 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.070	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 04 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.080	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 05 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.080	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 06 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.080	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 07 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.090	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 08 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.090	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 09 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.090	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
35-20-09-900-801-01	NO. 10 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.100	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 11 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.100	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 12 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.100	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 13 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.105	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 14 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.105	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 15 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.100	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									
35-20-09-900-801-01	NO. 16 PASSENGER OXYGEN MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.170	AFL	0		TSN 0					
PROC. REF: AMM 35-20-09-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
35-21-05-210-801-01 ^S	INSPECTION OF THE RILSAN TUBE ASSEMBLY							Service	ATA:35
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 35-21-05-210-801, SMM 35-90-01								PKG:21	
35-21-20-900-801-01	FIRST AID OXYGEN CYLINDER							Component	ATA:35
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: GENERIC NO REF									
35-30-01-960-801-01	DISCARD OF THE SMOKE HOOD - SMOKE HOOD (5WK)							Service	ATA:35
PN:802300-14	MOS	20-Mar-22	120		20-Mar-32		2905 d	LIFE LIMIT	
SN:E22030732	HRS								
WC#: 35.110	AFL								
PROC. REF: AMM 35-30-01-960-801									
35-30-05-210-801-01	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (10WK)							Service	ATA:35
PN:56009M6A-FF30A	MOS	27-Nov-23	12 (+3%)		27-Nov-24	07-Dec-24	235 d (+10)		
SN:ST68537	HRS	14292.8							
WC#: 35.140	AFL	9471							
PROC. REF: AMM 35-30-05-210-801									
35-30-05-350-801-01	RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (10WK)							Service	ATA:35
PN:56009M6A-FF30A	MOS	26-Aug-20	60 (+3%)		26-Aug-25	20-Oct-25	507 d (+55)	OVERHAUL	
SN:ST68537	HRS								
WC#: 35.140	AFL								
PROC. REF: AMM 35-30-05-350-801									
35-30-05-610-801-01	REFILLING OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (10WK)							Service	ATA:35
PN:56009M6A-FF30A	MOS/MSC	02-Aug-21	O/C						
SN:ST68537	HRS	12985							
	AFL	8657							
PROC. REF: AMM 35-30-05-610-801									
35-30-05-960-801-01	DISCARD OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (10WK)							Service	ATA:35
PN:56009M6A-FF30A	MOS/MSC	02-Aug-21	N/A						
SN:ST68537	HRS	12985							
	AFL	8657							
PROC. REF: AMM 35-30-05-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-30-09-100-801-01 CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (10WK) Service ATA:35								
PN:5600-9M6A-FF30A	MOS/MSC	20-May-16	O/C					
SN:P06050592	HRS	10730.7						
WC#: 35.140	AFL	7258						
PROC. REF: AMM 35-30-09-100-801								
35-30-09-350-801-01 RESTORATION OF THE SMOKE MASKS (OVERHAUL) - SMOKE MASK (730WJ) Service ATA:35								
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 35.110	AFL							
PROC. REF: AMM 35-30-09-350-801								
35-40-01-720-801-01 FUNCTIONAL TEST OF THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY - OXYGEN CYLINDER (10WY) Service ATA:35								
PN:176219-115	MOS	15-Jun-22	60 (+3%)		15-Jun-27	08-Aug-27	1165 d (+54)	
SN:541024406	HRS							
	AFL							
PROC. REF: AMM 35-40-01-720-801								
35-40-01-790-801-01^U HYDROSTATIC TEST OXYGEN CYLINDER Service ATA:35								
PN:176219-115	MOS/MSC	15-Jun-22	O/C					
SN:541024406	HRS	13630.3						
WC#: 35.010	AFL	9028						
PROC. REF: GENERIC NO REF								
35-40-01-900-801-01 REMOVAL / INSTALLATION OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (10WY) Component ATA:35								
PN:176219-115	MOS/MSC	15-Jun-22	H/T	TSO 0				
SN:541024406	HRS	13630.3		TSO 0				
WC#: 35.010	AFL	9028		TSO 0				
PROC. REF: AMM 35-40-01-900-801								
35-40-01-960-801-01 DISCARD OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (10WY) Service ATA:35								
PN:176219-115	MOS	01-Mar-22	180		01-Mar-37		4712 d	LIFE LIMIT
SN:541024406	HRS							
WC#: 35.010	AFL							
PROC. REF: AMM 35-40-01-960-801								
35-40-05-720-801-01^U FUNCTIONAL TEST OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE Service ATA:35								
	MOS/MSC	21-Sep-12	O/C					
	HRS	8893						
WC#: 35.010	AFL	5992						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
350801	OXYGEN CYLINDER PRESSURE GUAGE							Component	ATA:35
PN:172200-01	MOS/MSC	31-Mar-08	O/C						
SN:1738	HRS	6066.9							
WC#: 35.150	AFL	4053							
PROC. REF: GENERIC NO REF									
353004	NO. 1 PORTABLE OXYGEN BOTTLE MASK							Component	ATA:35
PN:5600-9M6A-FF30A	MOS/MSC	22-Mar-12	O/C	TSN 0					
SN:P06050592	HRS	8486.1		TSN 0					
WC#: 35.140	AFL	5707		TSN 0					
PROC. REF: GENERIC NO REF									
353801	SMOKE HOOD							Component	ATA:35
PN:802300-14	MOS/MSC	05-May-22	O/C						
SN:E22030732	HRS	13592.3							
	AFL	9008							
PROC. REF: GENERIC NO REF									
353851	NO. 1 PORTABLE OXYGEN BOTTLE							Component	ATA:35
PN:56009M6A-FF30A	MOS/MSC	02-Aug-21	H/T	TSO 0					
SN:ST68537	HRS	12985		TSO 0					
WC#: 35.140	AFL	8657		TSO 0					
PROC. REF: GENERIC NO REF									
354801	SMOKE MASK							Component	ATA:35
PN:PN	MOS/MSC	01-Sep-15	O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: GENERIC NO REF									
ATA 36 - PNEUMATIC									
36-10-00-790-801-01	LEAK CHECK OF THE BLEED AIR SYSTEM AFTER COMPONENT INSTALLATION							Service	ATA:36
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-00-790-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 36 - PNEUMATIC									
36-10-05-200-801-01 ^S	INSPECTION OF THE BLEED AIR CHECK VALVES - LH ENGINE BLEED CHECK VALVE (L20HU)							Service	ATA:36
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 36.040	AFL	7947	3750						
PROC. REF: AMM 36-10-05-200-801								PKG:31	
36-10-05-200-801-02 ^S	INSPECTION OF THE BLEED AIR CHECK VALVES - RH ENGINE BLEED CHECK VALVE (R20HU)							Service	ATA:36
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 36.040	AFL	7947	3750						
PROC. REF: AMM 36-10-05-200-801								PKG:31	
36-10-05-200-801-03 ^S	INSPECTION OF THE BLEED AIR CHECK VALVES - APU CHECK VALVE (130KH)							Service	ATA:36
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 36.040	AFL	7947	3750						
PROC. REF: AMM 36-10-05-200-801								PKG:31	
36-10-05-200-801-03A	INSPECT OF THE APU CHECK VALVE (MANDATORY 5-40)							Service	ATA:36
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3	7500		19261.3		4906.9		
WC#: 36.040	AFL	7947							
PROC. REF: AMM 36-10-05-200-801									
36-10-21-710-802-01 ^S	OPERATIONAL TEST OF THE FEEDER ISOLATION VALVE							Service	ATA:36
	DAYS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 05.010	AFL	9008							
PROC. REF: MPD 05-10-00, AMM 36-10-21-710-802								PKG:21	
36-10-21-710-802-01A	OPERATIONAL TEST OF THE FEEDER ISOLATION VALVE (MANDATORY 5-40)							Service	ATA:36
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	2500		16092.3		1737.9		
	AFL	9008							
PROC. REF: AMM 36-10-21-710-802									
361061	LH ENGINE BLEED AIR CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 36.030	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 36 - PNEUMATIC									
361062	RH ENGINE BLEED AIR CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
361063	APU CHECK VALVE							Component	ATA:36
PN:CYLB51161-2	MOS/MSC	17-Oct-19	O/C	TSR 0					
SN:2634	HRS	11823.8		TSR 0					
WC#: 36.030	AFL	7985		TSR 0					
PROC. REF: GENERIC NO REF									
361801	FEEDER ISOLATION VALVE							Component	ATA:36
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
361811	LEFT ENGINE BLEED AIR VALVE							Component	ATA:36
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
361821	RIGHT ENGINE BLEED AIR VALVE							Component	ATA:36
PN:BYLB51994	MOS/MSC	20-Dec-02	O/C	TSN 0					
SN:82	HRS	1098.4		TSN 0					
WC#: 36.060	AFL	806		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 38 - WATER/WASTE									
38-00-00-610-801-01 ^S	SERVICING OF THE WATER SYSTEM							Service	ATA:38
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 38.030	AFL	9471							
PROC. REF: AMM 38-00-00-610-801									
PKG:16									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 38 - WATER/WASTE									
38-00-00-900-801-01		REMOVAL / INSTALLATION OF THE FULL LIGHT INHIBITION MICROSWITCH - FULL LIGHT INHIBITION MICROSWITCH (260MT) / (713MT)					Component	ATA:38	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-00-00-900-801									
38-10-00-210-801-01 ^S		DETAILED INSPECTION OF WATER SYSTEM COMPONENTS					Service	ATA:38	
	MOS	16-Jul-19	72 (+2m)		16-Jul-25 (M)	16-Sep-25	466 d (+62)		
	HRS	11761.3							
	AFL	7947	3750		11697 (M)		2195		
PROC. REF: AMM 38-10-00-210-801									
PKG:31									
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION					Service	ATA:38	
	MOS	08-Feb-24	6 (+1m)		08-Aug-24	08-Sep-24	124 d (+31)		
	HRS	14354.4							
WC#: 38.010	AFL	9502							
PROC. REF: AMM 38-10-00-670-801									
38-10-00-720-801-01		FUNCTIONAL TEST OF THE WATER SUPPLY SYSTEM					Service	ATA:38	
	MOS/MSC	31-May-13	O/C						
	HRS	9143							
	AFL	6168							
PROC. REF: AMM 38-10-00-720-801									
38-13-09-900-801-01		REMOVAL / INSTALLATION OF THE REAR WATER HEATER - REAR WATER HEATER (22MT)					Component	ATA:38	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-13-09-900-801									
38-13-09-900-802-01		REMOVAL / INSTALLATION OF THE FORWARD WATER HEATER - GALLEY WATER HEATER (724MT)					Component	ATA:38	
PN:8921082G6	MOS/MSC	13-May-15	O/C	TSN 0					
SN:N1428808	HRS	10259.8		TSN 0					
	AFL	6931		TSN 0					
PROC. REF: AMM 38-13-09-900-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38-13-55-710-801-01 OPERATIONAL TEST OF THE LAVATORY WATER SOLENOID / PAD Service ATA:38								
	MOS/MSC	08-Feb-17	O/C					
	HRS	10863.8						
	AFL	7323						
PROC. REF: AMM 38-13-55-710-801, SMM 38-90-17								
38-15-01-710-801-01^S OPERATIONAL TEST OF THE UV STERILIZER - AFT VANITY UV STERILIZER (743MT) Service ATA:38								
	MOS	16-Apr-13	72 (+2m)					
	HRS	9087.6						
	AFL	6131	3750					
PROC. REF: AMM 38-15-01-710-801								
38-15-09-900-801-01 REMOVAL / INSTALLATION OF THE UV LAMP - UV LAMP (9870MT) Component ATA:38								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-15-09-900-801								
38-15-09-960-801-01 REPLACEMENT OF THE UV LAMP - UV LAMP (9870MT) Service ATA:38								
PN:PN	MOS	05-May-22						
SN:UNKNOWN	HRS	13592.3	3000 (+3%)		16592.3	16682.3	2237.9 (+90)	
	AFL	9008						
PROC. REF: AMM 38-15-09-960-801								
38-15-17-100-801-01 CLEANING OF THE UV STERILIZER QUARTZ SLEEVE - QUARTZ SLEEVE (9890MT) Service ATA:38								
	MOS/MSC	16-Jul-19	N/A					
	HRS	11761.3						
	AFL	7947						
PROC. REF: AMM 38-15-17-100-801								
38-30-00-710-801-01 OPERATIONAL TEST OF THE DRAIN MAST ANTI-ICING SYSTEM Service ATA:38								
	MOS/MSC	01-Mar-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 38-30-00-710-801								
38-30-01-900-801-01 REMOVAL / INSTALLATION OF THE REAR DRAIN MAST - REAR DRAIN MAST (25MT) Component ATA:38								
PN:MAT-200506-A	MOS/MSC	10-Sep-15	O/C	TSN 0				
SN:AEK16-01	HRS	10489.8		TSN 0				
	AFL	7089		TSN 0				
PROC. REF: AMM 38-30-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38-31-01-900-801-01 REMOVAL / INSTALLATION OF THE FRONT DRAIN MAST - FRONT DRAIN MAST (26MT)								Component ATA:38
PN:MAT-302706-A	MOS/MSC	18-Aug-10	O/C					
SN:467	HRS	7529.1						
WC#: 38.020	AFL	5053						
PROC. REF: AMM 38-31-01-900-801								
38-31-13-960-801-01 REPLACEMENT OF THE GALLEY WATER FILTER								Service ATA:38
	MOS/MSC	03-Oct-22	O/C					
	HRS	13788.2						
	AFL	9127						
PROC. REF: AMM 38-31-13-960-801								
38-31-17-200-801-01 ^S INSPECTION OF THE DRAIN BOX - DRAIN BOX (905MD)								Service ATA:38
	MOS	16-Jul-19	72 (+2m)		16-Jul-25 (M)	16-Sep-25	466 d (+62)	
	HRS	11761.3						
WC#: 38.040	AFL	7947	3750		11697 (M)		2195	
PROC. REF: AMM 38-31-17-200-801								
38-34-17-210-801-01 ^S GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL - FORWARD TOILET DRAIN CONTROL (525MD)								Service ATA:38
	MOS	08-Sep-22	36 (+1m)					
	HRS	13765.9						
	AFL	9108						
PROC. REF: AMM 38-34-17-210-801								
38-34-21-210-801-01 ^S GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL - AFT TOILET DRAIN CONTROL (102MN)								Service ATA:38
	MOS	16-Jul-19	36 (+1m)					
	HRS	11761.3						
	AFL	7947						
PROC. REF: AMM 38-34-21-210-801								
38-90-01-200-802-01S ^S INSPECTION METALLIC WATER TANK FOR CORROSION AND PITTING								Service ATA:38
	MOS	16-Jul-19	72 (+2m)		16-Jul-25 (M)	16-Sep-25	466 d (+62)	
	HRS	11761.3						
	AFL	7947	3750		11697 (M)		2195	
PROC. REF: SMM 38-90-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 45 - CENTRAL MAINT SYSTEM								
45-10-02-900-801-01	REMOVAL / INSTALLATION OF THE MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE - MAINTENANCE AND DIAGNOSTIC COMPUTER (355NH)						Component	ATA:45
PN:622-9818-213	MOS/MSC	09-Jan-24	O/C					
SN:5FXD	HRS	14319.6						
WC#: 34.210	AFL	9484						
PROC. REF: AMM 45-10-02-900-801								
45-20-00-910-801-01	USE OF THE MAINTENANCE PC						Service	ATA:45
	MOS/MSC		A/R					
	HRS							
WC#: 45.030	AFL							
PROC. REF: AMM 45-20-00-910-801								
45-30-00-910-801-01	USE OF THE HAND HELD TESTER						Service	ATA:45
	MOS/MSC		A/R					
	HRS							
WC#: 45.020	AFL							
PROC. REF: AMM 45-30-00-910-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 46 - INFORMATION SYSTEMS									
46-20-02-720-801-01		FUNCTIONAL TEST OF THE EDU BATTERIES - LH EDU (L7101NS)						Service	ATA:46
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 46-20-02-720-801, SMM 46-90-03									
46-20-02-720-801-02		FUNCTIONAL TEST OF THE EDU BATTERIES - RH EDU (R7101NS)						Service	ATA:46
PN:PN	MOS/MSC		N/A						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: AMM 46-20-02-720-801, SMM 46-90-03									
46-90-03-900-801-01		PILOT ELECTRONIC FLIGHT BAG (EFB) UNIT						Component	ATA:46
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: GENERIC NO REF									
46-90-03-900-801-02		COPILOT ELECTRONIC FLIGHT BAG (EFB) UNIT						Component	ATA:46
PN:PN	MOS/MSC		O/C						
SN:NOT INSTALLED	HRS								
	AFL								
PROC. REF: GENERIC NO REF									
ATA 49 - AIRBORNE AUXILIARY POWER									
49-10-05-220-801-01		APU - DETAILED INSPECTION COMPRESSOR ROTOR						Service	ATA:49
PN:3822281-1	MOS/MSC	19-Oct-13	O/C						
SN:011365104520	HRS	8265							
	APUS	8850							
49-10-05-960-801-01		APU - DISCARD OF THE APU COMPRESSOR ROTOR - AUXILIARY POWER UNIT (10KA)						Service	ATA:49
PN:3822281-1	MOS						LIFE LIMIT		
SN:011365104520	HRS		100000		100000 (M)		88110		
	APUS		100000		100000 (M)		85870		
PROC. REF: AMM 49-10-05-960-801									
49-10-09-960-801-01		APU - DISCARD OF THE APU TURBINE ROTOR - AUXILIARY POWER UNIT (10KA)						Service	ATA:49
PN:3615880-1	MOS	19-Oct-13					LIFE LIMIT		
SN:970134508884	HRS	8265	10000		18265		6375		
	APUS	8850	10000		18850		4720		
PROC. REF: AMM 49-10-09-960-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
49-20-00-220-801-01	APU - DETAILED INSPECTION OF THE APU HOT SECTION							Service	ATA:49
	MOS/MSC	27-Jun-13	O/C						
	HRS	8232							
	APUS	8790							
	PROC. REF: GENERIC NO REF								
49-31-07-960-801-01	APU - REPLACEMENT OF THE APU FUEL FILTER							Service	ATA:49
	MOS	08-Sep-22							
	HRS	11414	1000 (+3%)		12414	12444	524 (+30)		
	APUS	13380							
	PROC. REF: MM 49-30-52, AMM 49-31-07-960-801, AMM 49-31-07-960-801, AMM 49-31-07-960-801, AMM 49-31-07-960-801, AMM 49-31-07-960-801								
49-31-09-200-801-01	APU - CHECK OF THE FLOW RATE OF THE APU FUEL NOZZLE							Service	ATA:49
	MOS	01-Oct-13							
	HRS	8265	4500 (+3%)		12765	12900	875 (+135)		
	APUS	8850							
	PROC. REF: MM 49-20-00, AMM 49-31-09-200-801								
49-41-04-220-801-01	APU - DETAILED INSPECTION 9 O'CLOCK IGNITER PLUG							Service	ATA:49
PN:3888002-5	MOS	08-Sep-22							
SN:N/A	HRS	11414	750 (+3%)		12164	12186.5	274 (+22.5)		
	APUS	13380							
	PROC. REF: MM 49-40-33, AMM 49-41-04-220-801								
49-41-04-220-801-02	APU - DETAILED INSPECTION 5 O'CLOCK IGNITER PLUG (IF INSTALLED)							Service	ATA:49
PN:CH34549	MOS	19-Jan-23							
SN:NA	HRS	11535	750 (+3%)		12285	12307.5	395 (+22.5)		
	APUS	13561							
	PROC. REF: MM 49-40-33								
49-41-04-900-801-01	APU - 9 O'CLOCK IGNITER PLUG							Component	ATA:49
PN:3888002-5	MOS/MSC	08-Sep-22	O/C	TSN 114					
SN:N/A	HRS	11414		TSN 3268					
	APUS	13380		TSN 4714					
49-41-04-900-801-02	APU - 5 O'CLOCK IGNITER PLUG							Component	ATA:49
PN:CH34549	MOS/MSC	19-Jan-23	O/C						
SN:NA	HRS	11535							
	APUS	13561							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49-41-04-960-801-01 APU - REPLACE 9 O'CLOCK IGNITER PLUG Service ATA:49								
PN:3888002-5	MOS/MSC	18-Mar-13	O/C					
SN:N/A	HRS	8146						
	APUS	8666						
PROC. REF: MM 49-40-33								
49-41-04-960-801-02 APU - REPLACE 5 O'CLOCK IGNITER PLUG Service ATA:49								
PN:CH34549	MOS/MSC		O/C					
SN:NA	HRS							
	APUS							
PROC. REF: MM 49-40-33								
49-50-01-900-802-02 REMOVAL / INSTALLATION OF THE APU AIR INLET DOOR AND DOOR ACTUATOR - APU DOOR ACTUATOR (10KH) Component ATA:49								
PN:221400M04	MOS/MSC	09-Nov-17	O/C					
SN:388	HRS							
WC#: 49.190	AFL							
PROC. REF: AMM 49-50-01-900-802								
49-52-01-710-801-01^S OPERATIONAL TEST OF THE APU BLEED AIR VALVE CLOSURE WHEN ENGINE BLEED AIR VALVES ARE FAILED OPEN - APU BLEED AIR VALVE (9KA) Service ATA:49								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
WC#: 36.020	AFL	7947	3750					
PROC. REF: AMM 49-52-01-710-801								
49-52-01-710-801-01A OPERATIONAL TEST OF THE APU BLEED AIR VALVE CLOSURE WHEN ENGINE BLEED AIR VALVES ARE FAILED OPEN (MANDATORY 5-40) Service ATA:49								
	MOS	16-Jul-19						MANDATORY 5-40
	HRS	11761.3	7500		19261.3		4906.9	
WC#: 36.020	AFL	7947						
PROC. REF: AMM 49-52-01-710-801								
49-90-00-280-801-01 APU - SPECTROMETRIC ANALYSIS OF APU OIL AND OIL FILTER (SOAP) Service ATA:49								
	MOS	08-Sep-22						
	HRS	11414	500 (+3%)		11914	11929	24 (+15)	
	APUS	13380						
PROC. REF: AMM 49-90-00-280-801, AMM 49-90-00-280-801, AMM 49-90-00-280-801, AMM 49-90-00-280-801, AMM 49-90-00-280-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
49-91-00-610-802-01	APU - REPLACEMENT OF THE APU OIL							Service	ATA:49
	MOS/MSC	05-Jun-18	O/C						
	HRS	9865							
	APUS	11320							
PROC. REF: MM 49-20-00, AMM 49-91-00-610-802									
49-91-01-220-801-01	APU - INSPECTION OF THE APU MAGNETIC DRAIN PLUG							Service	ATA:49
	MOS	19-Jan-23							
	HRS	11535	750 (+3%)	Adj -54	12231	12253.5	341 (+22.5)		
	APUS	13561							
PROC. REF: MM 49-90-46, AMM 49-91-01-220-801									
49-91-04-960-801-01	APU - REPLACEMENT OF THE APU OIL FILTER ELEMENT							Service	ATA:49
	MOS/MSC	08-Sep-22	O/C						
	HRS	11414							
	APUS	13380							
PROC. REF: MM 49-90-47, AMM 49-91-04-960-801									
491010	APU - TURBINE ROTOR							Component	ATA:49
PN:3615880-1	MOS/MSC	19-Oct-13	O/C	TSR 0					
SN:970134508884	HRS	8265		TSR 0					
	APUS	8850		TSR 0					
491020	APU - COMPRESSOR ROTOR							Component	ATA:49
PN:3822281-1	MOS/MSC	19-Oct-13	O/C	TSR 0					
SN:011365104520	HRS	8265		TSR 0					
	APUS	8850		TSR 0					
491122	APU - FUEL SHUTOFF VALVE							Component	ATA:49
PN:692545-18	MOS/MSC	30-Jan-08	O/C						
SN:1218	HRS								
	APUS								
PROC. REF: MM 49-30-54									
491134	APU CONTROLLER COMPUTER							Component	ATA:49
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.205	AFL	0		TSN 0					
	APH		0	Adj 3125.02					
PROC. REF: EMM 49-60-46									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
492005	APU - PLAIN, ENCASED SEAL (COMPRESSOR INLET ASSEMBLY)							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492007	APU - CASE ASSY							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-01	APU - NO. 1 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-02	APU - NO. 2 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-03	APU - NO. 3 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-04	APU - NO. 4 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-05	APU - NO. 5 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-06	APU - NO. 6 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
492011-07	APU - NO. 7 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-08	APU - NO. 8 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-09	APU - NO. 9 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-10	APU - NO. 10 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-11	APU - NO. 11 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-12	APU - NO. 12 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-13	APU - NO. 13 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-14	APU - NO. 14 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
492011-15	APU - NO. 15 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-16	APU - NO. 16 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-17	APU - NO. 17 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-18	APU - NO. 18 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-19	APU - NO. 19 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-20	APU - NO. 20 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-21	APU - NO. 21 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-22	APU - NO. 22 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
492011-23	APU - NO. 23 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492011-24	APU - NO. 24 VANE ASSEMBLY SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492012	APU - CONTAINMENT RING							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492016	APU - GAS TURBING ENGINE POWER SECTION ASSEMBLY							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492017	APU - SEAL SET, GENERATOR, MATCHED							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492019	APU - COMPRESSOR CASE ASSEMBLY (MATCHED SET)							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492030	APU - PLANET SPUR GEAR SET							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492031	APU - ANNULAR BALL BEARING							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
492040	APU - SEAL SET, COMPRESSOR, MATCHED							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492050	APU - CYLINDRICAL ROLLER BEARING							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
493010	APU - FUEL CONTROL							Component	ATA:49
PN:3882730-8	MOS/MSC	27-Jun-13	O/C	TSR 0					
SN:25345	HRS	8232		TSR 0					
	APUS	8790		TSR 0					
					PROC. REF: MM 49-30-52				
493011	APU - FUEL CONTROL TORQUE MOTOR							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
493012	APU - VALVE AND SLEEVE SET ASSEMBLY							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
493030	APU - ORIFICE FITTING							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
					PROC. REF: MM 49-30-56				
493060	APU - CONTROLLER							Component	ATA:49
PN:2118844	MOS/MSC	28-Apr-10	O/C						
SN:UNKNOWN	HRS	6221							
	APUS	6382							
					PROC. REF: MM 49-60-46				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
493070	APU - LOAD CONTROL VALVE							Component	ATA:49
PN:109812-14	MOS/MSC	30-Jan-15	O/C						
SN:2866	HRS	8801							
	APUS	9720							
PROC. REF: MM 49-50-33									
494010	APU - IGNITION UNIT							Component	ATA:49
PN:3876280-4	MOS/MSC	26-Apr-21	O/C						
SN:J11050484	HRS	10795		TSO 2253					
	APUS			TSO 3190					
PROC. REF: MM 49-40-32									
495033	APU - ELECTRO-MAGNETIC CONTROL VALVE							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
495042	APU - P3 PRESSURE SENOR							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: MM 49-50-42									
495050	APU - P2 PRESSURE SENSOR							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
495090	APU - MODULATING DIFFUSER VANE ACTUATOR							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
496010	APU - LINEAR TRANSDUCER							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
497010 APU - MOTIONAL PICK UP TRANSDUCER Component ATA:49								
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: MM 49-60-43								
497020 APU - IMMERSION THERMOCOUPLE Component ATA:49								
PN:3876003-3	MOS/MSC	04-Feb-06	O/C	TSN 0				
SN:062021900446	HRS	2896		TSN 0				
	APUS	2767		TSN 0				
PROC. REF: MM 49-60-45								
497030 APU - HOURMETER Component ATA:49								
PN:3888126-1	MOS/MSC	09-Feb-11	O/C	TSN 0				
SN:NSN	HRS			TSN 0				
	APUS			TSN 0				
PROC. REF: MM 49-70-41								
499001 APU - ACCESSORY DRIVE GEARBOX ASSEMBLY Component ATA:49								
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
499010 APU - OIL ROTARY PUMP Component ATA:49								
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: MM 49-90-51								
499050 APU - OIL PRESSURE REGULATOR VALVE Component ATA:49								
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: MM 49-90-52								
499060 APU - HIGH OIL TEMPERATURE SENSOR Component ATA:49								
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: MM 49-60-46								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 49 - AIRBORNE AUXILIARY POWER									
499070	APU - LOW OIL PRESSURE SWITCH							Component	ATA:49
PN:3876001-8	MOS/MSC	16-Aug-07	O/C	TSN 0					
SN:06824	HRS	4260		TSN 0					
	APUS	4146		TSN 0					
PROC. REF: MM 49-60-43									
499080	APU - OIL LEVEL DETECTOR							Component	ATA:49
PN:722446	MOS/MSC	14-Sep-07	O/C	TSN 0					
SN:633	HRS			TSN 0					
	APUS			TSN 0					
499901	APU - FORGING							Component	ATA:49
PN:PN	MOS/MSC	26-Oct-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
49APU1	APU							Component	ATA:49
PN:3800548-2	MOS/MSC	15-Jun-22	E/C						
SN:P-324	HRS	13630.3							
WC#: 49.APU1	AFL	9028							
PROC. REF: AMM 49-10-01-900-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
51-00-00-200-801-01 ^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 12 M OR 800 FH INSPECTION							Service	ATA:51
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
					PROC. REF: AMM 51-00-00-200-801			PKG:5	
51-00-00-200-802-01 ^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 24 M OR 1600 FH INSPECTION							Service	ATA:51
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
	AFL	9471							
					PROC. REF: AMM 51-00-00-200-802			PKG:6	
51-00-00-200-803-01 ^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 1C INSPECTION							Service	ATA:51
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
					PROC. REF: AMM 51-00-00-200-803			PKG:31	
51-00-00-200-804-01 ^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 2C INSPECTION							Service	ATA:51
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
					PROC. REF: AMM 51-00-00-200-804			PKG:32	
ATA 52 - DOORS									
52-00-00-200-801-01 ^S	INSPECTION / CHECK OF THE DOORS SEALS - PASSENGER							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.120	AFL	7947	3750						
					PROC. REF: AMM 52-00-00-200-801			PKG:31	
52-00-00-200-801-02 ^S	INSPECTION / CHECK OF THE DOORS SEALS - BAGGAGE COMPARTMENT							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.120	AFL	7947	3750						
					PROC. REF: AMM 52-00-00-200-801			PKG:31	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-00-00-200-801-03 ^S INSPECTION / CHECK OF THE DOORS SEALS - FORWARD SERVICING COMPARTMENT Service ATA:52								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
WC#: 53.120	AFL	7947	3750					
PROC. REF: AMM 52-00-00-200-801								PKG:31
52-00-00-200-801-04 ^S INSPECTION / CHECK OF THE DOORS SEALS - AFT SERVICING COMPARTMENT Service ATA:52								
	MOS	16-Jul-19	72 (+2m)					
	HRS	11761.3						
WC#: 53.120	AFL	7947	3750					
PROC. REF: AMM 52-00-00-200-801								PKG:31
52-00-00-640-801-01 ^S LUBRICATION OF SERVICE DOORS Service ATA:52								
	MOS	07-Feb-24	12 (+1m)					
	HRS	14354.4						
WC#: 52.010	AFL	9502						
PROC. REF: AMM 52-00-00-640-801								PKG:15
52-10-00-220-801-01 DETAILED INSPECTION OF THE PASSENGER DOOR COUNTERBALANCING SYSTEM Service ATA:52								
	MOS/MSC		O/C					
	HRS							
WC#: 52.030	AFL							
PROC. REF: AMM 52-10-00-220-801								
52-10-00-610-801-01 ^S SERVICING OF THE PASSENGER DOOR Service ATA:52								
	MOS	10-Sep-15	36 (+1m)					
	HRS	10489.8						
WC#: 52.020	AFL	7089						
PROC. REF: AMM 52-10-00-610-801								PKG:17
52-10-00-610-802-01 ^S SERVICING OF THE PASSENGER DOOR SAFETY CATCH Service ATA:52								
	MOS	08-Feb-17	36 (+1m)					
	HRS	10863.8						
	AFL	7323						
PROC. REF: AMM 52-10-00-610-802								PKG:17
52-10-00-640-801-01 ^S LUBRICATION OF THE ROLLERS OF THE PASSENGER DOOR LOWER MECHANISM Service ATA:52								
	MOS	22-Nov-13	144 (+2m)					
	HRS	9419.6						
WC#: 52.035	AFL	6356	7500					
PROC. REF: AMM 52-10-00-640-801								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-00-720-801-01 ^S FUNCTIONAL TEST OF THE PASSENGER DOOR Service ATA:52								
	MOS	16-Apr-13	72 (+2m)					
	HRS	9087.6						
WC#: 52.020	AFL	6131	3750					
PROC. REF: AMM 52-10-00-720-801								PKG:31
52-10-01-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER DOOR - PASSENGER DOOR (PAX) Component ATA:52								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.020	AFL	0		TSN 0				
PROC. REF: AMM 52-10-01-900-801								
52-10-03-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (10MA1) Component ATA:52								
PN:222900-1M03	MOS/MSC	16-Jul-19	O/C	TSN 0				
SN:2965	HRS	11761.3		TSN 0				
WC#: 52.035	AFL	7947		TSN 0				
PROC. REF: AMM 52-10-03-900-801								
52-10-03-960-801-01 DISCARD OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (10MA1) Service ATA:52								
PN:222900-1M03	MOS	16-Jul-19	60		16-Jul-24		101 d	LIFE LIMIT
SN:2965	HRS	11761.3						
WC#: 52.035	AFL	7947						
PROC. REF: AMM 52-10-03-960-801								
52-10-09-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER DOOR REDUCING GEAR MOTOR - PASSENGER DOOR REDUCING GEAR MOTOR (50MA) Component ATA:52								
PN:222200-1M01	MOS/MSC	11-Feb-12	O/C					
SN:660	HRS	8422.1						
WC#: 52.030	AFL	5663						
PROC. REF: AMM 52-10-09-900-801								
52-10-11-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER DOOR COUNTERBALANCING LEAF-SPRING ACTUATOR - PASSENGER DOOR COUNTERBALANCING ACTUATOR (10MA) Component ATA:52								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.030	AFL	0		TSN 0				
PROC. REF: AMM 52-10-11-900-801								
52-10-19-900-801-01 REMOVAL / INSTALLATION OF THE PASSENGER DOOR HANDRAIL Component ATA:52								
PN:FGFB295007D2	MOS/MSC	31-Dec-12	O/C	TSR 0				
SN:09071112109	HRS	9044.7		TSR 0				
	AFL	6101		TSR 0				
PROC. REF: AMM 52-10-19-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 52 - DOORS									
52-20-00-610-801-01 ^S	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN							Service	ATA:52
	MOS	27-Dec-23	24						
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 52-20-00-610-801							PKG:16	
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)							Service	ATA:52
	MOS	27-Dec-23	24		27-Dec-25		630 d	MANDATORY 5-40	
	HRS	14292.8							
WC#: 52.040	AFL	9471							
	PROC. REF: AMM 52-20-00-610-801								
52-20-00-610-801-02 ^S	SERVICING OF THE EMERGENCY EXIT DOOR							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 52.040	AFL	9471							
	PROC. REF: AMM 52-20-00-610-801							PKG:16	
52-20-00-710-801-01 ^S	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE							Service	ATA:52
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 52.040	AFL	9008							
	PROC. REF: AMM 52-20-00-710-801							PKG:21	
52-20-01-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY EXIT DOOR							Component	ATA:52
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.040	AFL	0		TSN 0					
	PROC. REF: AMM 52-20-01-900-801								
52-30-00-610-801-01 ^S	SERVICING OF THE BAGGAGE COMPARTMENT DOOR - BAGGAGE COMPARTMENT DOOR (900MC)							Service	ATA:52
	MOS	16-Jul-19	36 (+1m)						
	HRS	11761.3							
WC#: 52.050	AFL	7947							
	PROC. REF: AMM 52-30-00-610-801							PKG:17	
52-30-00-710-801-01 ^S	CHECK OF THE BAGGAGE COMPARTMENT DOOR MECHANISM							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 52.060	AFL	7947	3750						
	PROC. REF: AMM 52-30-00-710-801							PKG:31	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 52 - DOORS									
52-30-01-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR							Component	ATA:52
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.050	AFL	0		TSN 0					
PROC. REF: AMM 52-30-01-900-801									
52-40-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE ACCESS PANELS AND DOORS							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 52.090	AFL	9471							
PROC. REF: AMM 52-40-00-210-801									
52-41-07-610-801-01 ^S	SERVICING OF THE NLG WELL CEILING DOOR							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 52.100	AFL	9471							
PROC. REF: AMM 52-41-07-610-801									
52-50-00-710-801-01 ^S	INSPECTION / TEST OF THE BLOWOUT DOORS / PANELS							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 52-50-00-710-801									
52-54-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVIDERS AND BULKHEADS							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 52-54-00-210-801, SMM 52-90-05									
52-54-05-210-801-02 ^S	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM							Service	ATA:52
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 52-54-05-210-801, SMM 52-90-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 52 - DOORS									
52-54-05-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER - INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
	AFL	9471							
				PROC. REF: AMM 52-54-05-210-802				PKG:6	
52-60-01-610-801-01 ^S	SERVICING OF THE FORWARD SERVICING COMPARTMENT DOOR							Service	ATA:52
	MOS	10-Sep-15	36 (+1m)						
	HRS	10489.8							
WC#: 52.070	AFL	7089							
				PROC. REF: AMM 52-60-01-610-801				PKG:17	
52-60-09-610-801-01 ^S	SERVICING OF THE AFT SERVICING COMPARTMENT DOOR							Service	ATA:52
	MOS	16-Jul-19	36 (+1m)						
	HRS	11761.3							
WC#: 52.080	AFL	7947							
				PROC. REF: AMM 52-60-09-610-801				PKG:17	
52-70-00-710-802-01 ^S	OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - PASSENGER							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 52.120	AFL	9471							
				PROC. REF: AMM 52-70-00-710-802				PKG:6	
52-70-00-710-802-02 ^S	OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - EMERGENCY EXIT							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 52.120	AFL	9471							
				PROC. REF: AMM 52-70-00-710-802				PKG:6	
52-70-00-710-802-03 ^S	OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - BAGGAGE COMPARTMENT							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 52.120	AFL	9471							
				PROC. REF: AMM 52-70-00-710-802				PKG:6	
52-70-00-710-802-04 ^S	OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - FORWARD SERVICING COMPARTMENT							Service	ATA:52
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 52.120	AFL	9471							
				PROC. REF: AMM 52-70-00-710-802				PKG:6	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-70-00-710-802-05^S OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - AFT SERVICING COMPARTMENT								
	MOS	27-Dec-23	24 (+1m)					Service ATA:52
	HRS	14292.8	1600 (+40)					
WC#: 52.120	AFL	9471						
PROC. REF: AMM 52-70-00-710-802								PKG:6
52-70-00-710-802-06^S OPERATIONAL TEST OF THE DOOR INDICATING SYSTEM - FORWARD LAVATORY SERVICE DOOR								
	MOS	27-Dec-23	24 (+1m)					Service ATA:52
	HRS	14292.8	1600 (+40)					
WC#: 52.120	AFL	9471						
PROC. REF: AMM 52-70-00-710-802								PKG:6
523801 FORWARD SERVICING COMPARTMENT DOOR								
PN:F2MA259003411	MOS/MSC	10-Sep-15	O/C					Component ATA:52
SN:UNKNOWN	HRS	10489.8						
WC#: 52.070	AFL	7089						
PROC. REF: GENERIC NO REF								
523806 AFT SERVICING COMPARTMENT DOOR								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:52
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 53 - FUSELAGE								
53-00-00-200-803-01 INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 - GENERAL VISUAL INSPECTION								
	MOS	01-Mar-00						Service ATA:53
	HRS	0						
WC#: 53.150	AFL	0	T:11250		11250		1748	
PROC. REF: AMM 53-00-00-200-803								
53-00-00-200-803-01A GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 (MANDATORY 5-40)								
	MOS	01-Mar-00						Service ATA:53
	HRS	0						MANDATORY 5-40
WC#: 53.150	AFL	0	T:11250		11250		1748	
PROC. REF: AMM 53-00-00-200-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-00-00-200-803-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 - DETAILED INSPECTION IN SPECIFIC AREAS							Service	ATA:53
	MOS	01-Mar-00							
	HRS	0							
WC#: 53.435	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 53-00-00-200-803									
53-00-00-200-803-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 (MANDATORY 5-40)							Service	ATA:53
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
WC#: 53.435	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 53-00-00-200-803									
53-00-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 53.010	AFL	9471							
PROC. REF: AMM 53-00-00-210-801									
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-00-00-210-801									
53-00-00-220-801-01 ^S	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.425	AFL	7947	3750						
PROC. REF: AMM 53-00-00-220-801									
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-00-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-00-00-370-802-01 ^U	RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN NLG AND MLG BAYS - RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN NLG BAY							Service	ATA:53
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF									
53-00-00-370-802-02 ^U	RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN NLG AND MLG BAYS - RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN LH MLG BAY							Service	ATA:53
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF									
53-00-00-370-802-03 ^U	RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN NLG AND MLG BAYS - RENEWAL OF THE CORROSION INHIBITOR COMPOUND IN RH MLG BAY							Service	ATA:53
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF									
53-10-00-200-808-01 ^S	INSPECTION OF THE NLG BAY							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 53.110	AFL	9502							
PROC. REF: AMM 53-10-00-200-808									
53-10-00-200-808-01C	INSPECTION OF THE NLG BAY (CPCP)							Service	ATA:53
	MOS	27-Dec-23	12 (+1m)		27-Dec-24	27-Jan-25	265 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-10-00-200-808									
53-10-00-200-810-01	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - GENERAL VISUAL INSPECTION OF SKIN							Service	ATA:53
	MOS	06-Sep-17							
	HRS	11110.8							
WC#: 53.140	AFL	7501	3750		11251		1749		
PROC. REF: AMM 53-10-00-200-810									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)							Service	ATA:53
	MOS	06-Sep-17						MANDATORY 5-40	
	HRS	11110.8							
WC#: 53.140	AFL	7501	3750		11251		1749		
PROC. REF: AMM 53-10-00-200-810									
53-10-00-200-810-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - DETAILED INSPECTION IN SPECIFIC AREAS							Service	ATA:53
	MOS	01-Mar-00							
	HRS	0							
WC#: 53.430	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 53-10-00-200-810									
53-10-00-200-810-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4(MANDATORY 5-40)							Service	ATA:53
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
WC#: 53.430	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 53-10-00-200-810									
53-10-00-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 53.0301	AFL	9471							
PROC. REF: AMM 53-10-00-210-802									
53-10-00-220-801-01 ^S	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN THE PROBE AREAS							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)					RVSM	
	HRS	14292.8							
WC#: 53.155	AFL	9471							
PROC. REF: AMM 53-10-00-220-801									
53-10-00-220-802-01 ^S	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.0302	AFL	7947	3750						
PROC. REF: AMM 53-10-00-220-802									
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-10-00-220-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-10-01-250-801-01	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP							Service	ATA:53
	MOS	16-Apr-13							
	HRS	9087.6							
WC#: 53.190	AFL	6131	T:7500		13631		4129		
PROC. REF: AMM 53-10-01-250-801									
53-10-03-220-801-03 ^S	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS							Service	ATA:53
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
PROC. REF: AMM 53-10-03-220-801									
53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)							Service	ATA:53
	MOS	16-Apr-13	144 (+2m)		16-Apr-25	16-Jun-25	375 d (+61)	CPCP	
	HRS	9087.6							
	AFL	6131							
PROC. REF: AMM 53-10-03-220-801									
53-10-03-250-801-01	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.180	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-10-03-250-801									
53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.180	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-10-03-250-801									
53-10-33-220-802-01	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS							Service	ATA:53
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 53.220	AFL	6131							
PROC. REF: AMM 53-10-33-220-802									
53-10-33-220-802-01C	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)							Service	ATA:53
	MOS/MSC	16-Apr-13	N/A						
	HRS	9087.6							
	AFL	6131							
PROC. REF: AMM 53-10-33-220-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-10-39-220-801-01 ^S	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.200	AFL	7947	3750						
PROC. REF: AMM 53-10-39-220-801								PKG:31	
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-10-39-220-801									
53-10-39-220-802-01 ^S	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service	ATA:53
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 53.230	AFL	6131	7500						
PROC. REF: AMM 53-10-39-220-802								PKG:32	
53-10-39-220-802-01A	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 53.230	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-10-39-220-802									
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service	ATA:53
	MOS	16-Apr-13	144 (+2m)		16-Apr-25	16-Jun-25	375 d (+61)	CPCP	
	HRS	9087.6							
	AFL	6131							
PROC. REF: AMM 53-10-39-220-802									
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR - FITTING							Service	ATA:53
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 53.350	AFL	6131							
PROC. REF: AMM 53-10-41-220-801									
53-10-41-220-801-01A	DETAILED INSPECTION OF ATTACHMENT FITTING OF NOSE LANDING GEAR ACTUATOR (MANDATORY 5-40)							Service	ATA:53
	MOS/MSC	16-Apr-13	O/C					MANDATORY 5-40	
	HRS	9087.6							
WC#: 53.350	AFL	6131							
PROC. REF: AMM 53-10-41-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-41-220-801-02^S DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR - VERTICAL PANEL SUPPORTING THE FITTING								
	MOS	16-Jul-19	72 (+2m)					Service ATA:53
	HRS	11761.3						
WC#: 53.360	AFL	7947	3750					
PROC. REF: AMM 53-10-41-220-801								PKG:31
53-10-41-220-801-02A DETAILED INSPECTION OF THE VERTICAL PANEL SUPPORTING ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)								
	MOS	16-Jul-19						Service ATA:53
	HRS	11761.3						MANDATORY 5-40
WC#: 53.360	AFL	7947	3750		11697		2195	
PROC. REF: AMM 53-10-41-220-801								
53-11-00-210-801-01^S GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA								
	MOS	27-Dec-23	24 (+1m)					Service ATA:53
	HRS	14292.8						
WC#: 53.0201	AFL	9471						
PROC. REF: AMM 53-11-00-210-801								PKG:16
53-11-00-210-801-01C GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)								
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	Service ATA:53
	HRS	14292.8						CPCP
	AFL	9471						
PROC. REF: AMM 53-11-00-210-801								
53-11-00-220-802-01 DETAILED INSPECTION OF THE IAPS SUPPORT IN THE NOSE CONE								
	MOS/MSC	01-Mar-00	O/C					Service ATA:53
	HRS	0						
WC#: 53.370	AFL	0						
PROC. REF: AMM 53-11-00-220-802								
53-11-00-760-801-01^S CHECK OF THE NOSE CONE ELECTRICAL BONDING								
	MOS	27-Dec-23	24 (+1m)					Service ATA:53
	HRS	14292.8						
WC#: 53.380	AFL	9471						
PROC. REF: AMM 53-11-00-760-801								PKG:16
53-11-01-900-801-01 REMOVAL / INSTALLATION OF THE NOSE CONE								
PN:FGFB208D2	MOS/MSC	10-Sep-15	O/C	TSR 0				Component ATA:53
SN:BZ80	HRS	10489.8		TSR 0				
	AFL	7089		TSR 0				
PROC. REF: AMM 53-11-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-11-09-900-801-01	REMOVAL / INSTALLATION OF THE RADOME							Component	ATA:53
PN:FGFB207D1	MOS/MSC	18-Apr-13	O/C						
SN:266	HRS	9087.6		TSN 2031.7					
	AFL	6131		TSN 1356					
PROC. REF: AMM 53-11-09-900-801									
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.405	AFL	7947	7500		15443 (M)		5941		
PROC. REF: AMM 53-11-21-960-801									
53-30-00-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 53.0401	AFL	9471							
PROC. REF: AMM 53-30-00-210-802									
53-30-00-220-801-01 ^S	DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.0402	AFL	7947	3750						
PROC. REF: AMM 53-30-00-220-801									
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-30-00-220-801									
53-30-00-220-801-02 ^S	DETAILED INSPECTION OF THE PASSENGER CABIN - ABOVE THE FLOOR							Service	ATA:53
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 53.0402	AFL	6131	7500						
PROC. REF: AMM 53-30-00-220-801									
53-30-00-250-801-01	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES							Service	ATA:53
	MOS	16-Apr-13							
	HRS	9087.6							
WC#: 53.170	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-00-250-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-30-00-250-801-01A	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 53.170	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-00-250-801									
53-30-00-250-802-01	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS							Service	ATA:53
	MOS	16-Apr-13							
	HRS	9087.6							
WC#: 53.160	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-00-250-802									
53-30-00-250-802-01A	EDDY-CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 53.160	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-00-250-802									
53-30-21-250-801-01	EDDY CURRENT INSPECTION AT FRAME 21							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.240	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-21-250-801									
53-30-26-220-801-01	DETAILED INSPECTION AT FRAME 26 - STIFFENER 9							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.280	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-220-801									
53-30-26-220-801-01A	DETAILED INSPECTION AT FRAME 26 - STIFFENER 9 (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.280	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-220-801									
53-30-26-220-801-02	DETAILED INSPECTION AT FRAME 26 - STIFFENER 17 WEB FRAME							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.290	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-30-26-220-801-02A	DETAILED INSPECTION AT FRAME 26 - STIFFENER 17 WEB FRAME(MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.290	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-220-801									
53-30-26-250-801-01	EDDY CURRENT INSPECTION AT FRAME 26 - VERTICAL BEAMS							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.250	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-250-801									
53-30-26-250-801-01A	EDDY-CURRENT INSPECTION AT FRAME 26 - VERTICAL BEAMS (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.250	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-250-801									
53-30-26-250-801-02	EDDY CURRENT INSPECTION AT FRAME 26 - STIFFENER 17							Service	ATA:53
	MOS	16-Apr-13							
	HRS	9087.6							
WC#: 53.260	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-26-250-801									
53-30-26-250-801-02A	EDDY-CURRENT INSPECTION AT FRAME 26 - STIFFENER 17 (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 53.260	AFL	6131	3750		9881		379		
PROC. REF: AMM 53-30-26-250-801									
53-30-26-250-801-03	EDDY CURRENT INSPECTION AT FRAME 26 - KEEL BEAM FLANGE CONNECTION							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.270	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-250-801									
53-30-26-250-801-03A	EDDY-CURRENT INSPECTION AT FRAME 26 - KEEL BEAM FLANGE CONNECTION (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.270	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-30-26-250-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-30-27-220-801-01	DETAILED INSPECTION OF THE FASTENERS AT FRAME 27							Service	ATA:53
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 53.375	AFL	0							
	PROC. REF: AMM 53-30-27-220-801								
53-40-00-200-804-01 ^S	INSPECTION OF THE MLG BAYS - LH MLG BAY							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 53.100	AFL	9502							
	PROC. REF: AMM 53-40-00-200-804								PKG:15
53-40-00-200-804-01C	INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service	ATA:53
	MOS	27-Dec-23	12 (+1m)		27-Dec-24	27-Jan-25	265 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 53-40-00-200-804								
53-40-00-200-804-02 ^S	INSPECTION OF THE MLG BAYS - RH MLG BAY							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 53.100	AFL	9502							
	PROC. REF: AMM 53-40-00-200-804								PKG:15
53-40-00-200-804-02C	INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service	ATA:53
	MOS	27-Dec-23	12 (+1m)		27-Dec-24	27-Jan-25	265 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 53-40-00-200-804								
53-40-00-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 53.0601	AFL	9471							
	PROC. REF: AMM 53-40-00-210-802								PKG:16
53-40-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 53-40-00-210-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-40-00-220-801-01 ^S	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.0602	AFL	7947	3750						
PROC. REF: AMM 53-40-00-220-801								PKG:31	
53-40-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-40-00-220-801									
53-40-00-220-802-01 ^S	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.050	AFL	7947	3750						
PROC. REF: AMM 53-40-00-220-802								PKG:31	
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 53-40-00-220-802									
53-41-00-220-801-01 ^S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								PKG:16	
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING (CPCP)							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801									
53-41-00-220-801-02 ^S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								PKG:16	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING (CPCP)							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-220-802-01 ^S	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.130	AFL	7947	3750						
	PROC. REF: AMM 53-41-00-220-802								
53-41-00-220-802-01A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.130	AFL	7947	7500		15447		5945		
	PROC. REF: AMM 53-41-00-220-802								
53-41-00-220-802-02 ^S	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 53-41-00-220-802								
53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
	AFL	7947	7500		15447		5945		
	PROC. REF: AMM 53-41-00-220-802								
53-41-00-620-802-01 ^U	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH WING UPPER ROOT BOLT RECESSES							Service	ATA:53
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 57.120	AFL	6131							
	PROC. REF: GENERIC NO REF								
53-41-00-620-802-02 ^U	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING UPPER ROOT BOLT RECESSES							Service	ATA:53
	MOS/MSC	16-Apr-13	O/C						
	HRS	9087.6							
WC#: 57.130	AFL	6131							
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-41-01-640-801-01 ^S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.020	AFL	7947	3750						
PROC. REF: AMM 53-41-01-640-801								PKG:31	
53-41-01-640-801-02 ^S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - RH LINK ROD							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.020	AFL	7947	3750						
PROC. REF: AMM 53-41-01-640-801								PKG:31	
53-50-00-210-804-01 ^S	GENERAL VISUAL INSPECTION OF THE AFT SERVICING COMPARTMENT							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 53.0901	AFL	9502							
PROC. REF: AMM 53-50-00-210-804								PKG:15	
53-50-00-210-804-01C	GENERAL VISUAL INSPECTION OF THE AFT SERVICING COMPARTMENT (CPCP)							Service	ATA:53
	MOS	27-Dec-23	12 (+1m)		27-Dec-24	27-Jan-25	265 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-50-00-210-804									
53-50-00-210-805-02 ^S	GENERAL VISUAL INSPECTION OF THE FORWARD SERVICING COMPARTMENT							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
	AFL	9502							
PROC. REF: AMM 53-50-00-210-805								PKG:15	
53-50-00-210-806-01 ^S	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 53.0701	AFL	9471							
PROC. REF: AMM 53-50-00-210-806								PKG:16	
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 53-50-00-210-806									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-50-00-210-807-01 ^S	GENERAL VISUAL INSPECTION OF THE APU AREA							Service	ATA:53
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 53.410	AFL	9502							
	PROC. REF: AMM 53-50-00-210-807								PKG:15
53-50-00-220-803-01 ^S	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.0702	AFL	7947	3750						
	PROC. REF: AMM 53-50-00-220-803								PKG:31
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
	PROC. REF: AMM 53-50-00-220-803								
53-50-00-220-804-01 ^S	DETAILED INSPECTION OF THE FORWARD SERVICING COMPARTMENT							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.0802	AFL	7947	3750						
	PROC. REF: AMM 53-50-00-220-804								PKG:31
53-50-23-250-802-01	EDDY CURRENT INSPECTION OF THE BAGGAGE COMPARTMENT SKIN PANELS AROUND DOOR LOWER ROUNDED ANGLE AT FRAME 23							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.210	AFL	7947	3750		11697		2195		
	PROC. REF: AMM 53-50-23-250-802								
53-50-23-250-802-01A	EDDY-CURRENT INSPECTION OF BAGGAGE COMPARTMENT SKIN PANELS AROUND DOOR LOWER ROUNDED ANGLES AT FRAME 23 (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.210	AFL	7947	3750		11697		2195		
	PROC. REF: AMM 53-50-23-250-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-50-30-250-801-01	EDDY-CURRENT INSPECTION AT FRAME 30							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.300	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-30-250-801									
53-50-30-250-801-01A	EDDY-CURRENT INSPECTION AT FRAME 30 (MANDATORY 05-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.300	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-30-250-801									
53-50-33-250-801-01	EDDY-CURRENT INSPECTION AT FRAME 33							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.310	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-33-250-801									
53-50-33-250-801-01A	EDDY-CURRENT INSPECTION AT FRAME 33 (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.310	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-33-250-801									
53-50-43-250-801-01	EDDY-CURRENT INSPECTION OF THE LOWER FIN FRONT SPAR FLANGES							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.320	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-43-250-801									
53-50-43-250-801-01A	EDDY-CURRENT INSPECTION OF LOWER FIN FRONT SPAR FLANGES (MANDATORY 5-40)							Service	ATA:53
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 53.320	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-43-250-801									
53-50-45-250-801-01	EDDY-CURRENT INSPECTION OF THE FIN STUB REAR SPAR							Service	ATA:53
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 53.330	AFL	7947	3750		11697		2195		
PROC. REF: AMM 53-50-45-250-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
53-50-47-220-801-01 ^S	DETAILED INSPECTION OF LOWER FIN DOOR FRAME SKIN							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 53.340	AFL	7947	3750						
	PROC. REF: AMM 53-50-47-220-801								PKG:31
53-60-00-760-801-01 ^S	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING							Service	ATA:53
	MOS	16-Jul-19	36 (+1m)						
	HRS	11761.3							
WC#: 53.390	AFL	7947							
	PROC. REF: AMM 53-60-00-760-801								PKG:17
53-80-00-200-801-01 ^S	CHECK OF THE FUSELAGE CONDENSATION AND STREAM WATER DRAINS							Service	ATA:53
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 51.010	AFL	9471							
	PROC. REF: AMM 53-80-00-200-801								PKG:16
53-80-09-710-801-01 ^S	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS - STRUCTURE AUTOMATIC DRAIN (L10SX)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 51.020	AFL	7947	3750						
	PROC. REF: AMM 53-80-09-710-801								PKG:31
53-80-09-710-801-02 ^S	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS - STRUCTURE AUTOMATIC DRAIN (R10SX)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 53-80-09-710-801								PKG:31
53-80-09-710-801-03 ^S	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS - FUEL AUTOMATIC DRAIN (70QD)							Service	ATA:53
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
	PROC. REF: AMM 53-80-09-710-801								PKG:31
536401	APU FIREWALL ASSEMBLY							Component	ATA:53
PN:F2MA258501419	MOS/MSC	16-Apr-13	O/C		TSN 0				
SN:324	HRS	9087.6			TSN 0				
WC#: 53.400	AFL	6131			TSN 0				
	PROC. REF: AMM 53-76-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 54 - NACELLES/PYLONS									
54-00-00-210-810-01	GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (L5EZ)							Service	ATA:54
	MOS	28-Feb-23	24 (+1m)		28-Feb-25	31-Mar-25	328 d (+31)		
	HRS	13865.3	800 (+40)		14665.3	14705.3	310.9 (+40)		
WC#: 54.010	AFL	9179							
PROC. REF: AMM 54-00-00-210-810									
54-00-00-210-810-01C	GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (L5EZ) (CPCP)							Service	ATA:54
	MOS	28-Feb-23	24 (+1m)		28-Feb-25	31-Mar-25	328 d (+31)	CPCP	
	HRS	13865.3							
	AFL	9179							
PROC. REF: AMM 54-00-00-210-810									
54-00-00-210-810-02	GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (R5EZ)							Service	ATA:54
	MOS	28-Feb-23	24 (+1m)		28-Feb-25	31-Mar-25	328 d (+31)		
	HRS	13865.3	800 (+40)		14665.3	14705.3	310.9 (+40)		
WC#: 54.010	AFL	9179							
PROC. REF: AMM 54-00-00-210-810									
54-00-00-210-810-02C	GENERAL VISUAL INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (R5EZ) (CPCP)							Service	ATA:54
	MOS	28-Feb-23	24 (+1m)		28-Feb-25	31-Mar-25	328 d (+31)	CPCP	
	HRS	13865.3							
	AFL	9179							
PROC. REF: AMM 54-00-00-210-810									
54-00-00-220-801-01 ^S	DETAILED INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (L5EZ)							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)						
	HRS	13865.3							
WC#: 54.020	AFL	9179	7500						
PROC. REF: AMM 54-00-00-220-801									
54-00-00-220-801-01C	DETAILED INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 1 (CPCP)							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)		28-Feb-35	30-Apr-35	3980 d (+61)	CPCP	
	HRS	13865.3							
	AFL	9179							
PROC. REF: AMM 54-00-00-220-801									
54-00-00-220-801-02 ^S	DETAILED INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (R5EZ)							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)						
	HRS	13865.3							
WC#: 54.020	AFL	9179	7500						
PROC. REF: AMM 54-00-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 54 - NACELLES/PYLONS									
54-00-00-220-801-02C	DETAILED INSPECTION OF THE ENGINE NACELLES AND PYLONS - ENGINE 2 (CPCP)							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)		28-Feb-35	30-Apr-35	3980 d (+61)	CPCP	
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 54-00-00-220-801								
54-11-00-610-801-01 ^S	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 (L5EZ)							Service	ATA:54
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 54.050	AFL	9471							
	PROC. REF: AMM 54-11-00-610-801								
54-11-00-610-801-02 ^S	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 (R5EZ)							Service	ATA:54
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 54.050	AFL	9471							
	PROC. REF: AMM 54-11-00-610-801								
54-11-00-760-801-01 ^S	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING - ENGINE 1							Service	ATA:54
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 54.065	AFL	9471							
	PROC. REF: AMM 54-11-00-760-801								
54-11-00-760-801-02 ^S	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING - ENGINE 2							Service	ATA:54
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 54.065	AFL	9471							
	PROC. REF: AMM 54-11-00-760-801								
54-14-01-210-802-01	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER POD FAIRINGS - ENGINE 1 THRUST REVERSER							Service	ATA:54
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 78.090	AFL	0							
	PROC. REF: AMM 54-14-01-210-802								
54-14-01-210-802-01A	GENERAL VISUAL INSPECTION OF THE NO.1 ENGINE THRUST REVERSER POD FAIRINGS (MANDATORY 5-40)							Service	ATA:54
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 78.090	AFL	0							
	PROC. REF: AMM 54-14-01-210-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 54 - NACELLES/PYLONS									
54-14-01-210-802-02	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER POD FAIRINGS - ENGINE 2 THRUST REVERSER							Service	ATA:54
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 78.090	AFL	0							
PROC. REF: AMM 54-14-01-210-802									
54-14-01-210-802-02A	GENERAL VISUAL INSPECTION OF THE NO.2 ENGINE THRUST REVERSER POD FAIRINGS (MANDATORY 5-40)							Service	ATA:54
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
WC#: 78.090	AFL	0							
PROC. REF: AMM 54-14-01-210-802									
54-41-00-280-801-01 ^U	SPECIAL DETAILED INSPECTION OF THE INNER FACE OF THE ENGINE AIR INTAKE							Service	ATA:54
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
54-41-00-280-801-02 ^S	SPECIAL DETAILED INSPECTION OF THE INNER FACE OF THE ENGINE AIR INTAKE - ENGINE 1							Service	ATA:54
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 54-41-00-280-801									
54-41-00-280-801-03 ^S	SPECIAL DETAILED INSPECTION OF THE INNER FACE OF THE ENGINE AIR INTAKE - ENGINE 2							Service	ATA:54
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 54-41-00-280-801									
54-50-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE ENGINE PYLON UPPER SKIN PANEL - ENGINE 1							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)						
	HRS	13865.3							
	AFL	9179	7500						
PROC. REF: AMM 54-50-00-210-801									
54-50-00-210-801-01A	GENERAL VISUAL INSPECTION OF THE NO. 1 ENGINE PYLON UPPER SKIN PANEL (MANDATORY 5-40)							Service	ATA:54
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
PROC. REF: AMM 54-50-00-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 54 - NACELLES/PYLONS									
54-50-00-210-801-02 ^S	GENERAL VISUAL INSPECTION OF THE ENGINE PYLON UPPER SKIN PANEL - ENGINE 2							Service	ATA:54
	MOS	28-Feb-23	144 (+2m)						
	HRS	13865.3							
	AFL	9179	7500						
	PROC. REF: AMM 54-50-00-210-801								PKG:32
54-50-00-210-801-02A	GENERAL VISUAL INSPECTION OF THE NO. 2 ENGINE PYLON UPPER SKIN PANEL (MANDATORY 5-40)							Service	ATA:54
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 54-50-00-210-801								
ATA 55 - STABILIZERS									
55-00-00-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 55.0101	AFL	9471							
	PROC. REF: AMM 55-00-00-210-802								PKG:16
55-00-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS (CPCP)							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 55-00-00-210-802								
55-00-00-220-802-01 ^S	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS							Service	ATA:55
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 55.0102	AFL	7947	3750						
	PROC. REF: AMM 55-00-00-220-802								PKG:31
55-00-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS (CPCP)							Service	ATA:55
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
	PROC. REF: AMM 55-00-00-220-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 55 - STABILIZERS									
55-00-00-760-801-01 ^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 55.110	AFL	9471							
				PROC. REF: AMM 55-00-00-760-801				PKG:16	
55-00-00-760-801-02 ^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 55.090	AFL	9471							
				PROC. REF: AMM 55-00-00-760-801				PKG:16	
55-00-00-760-801-03 ^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 55.100	AFL	9471							
				PROC. REF: AMM 55-00-00-760-801				PKG:16	
55-10-00-220-801-01 ^S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE							Service	ATA:55
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
				PROC. REF: AMM 55-10-00-220-801				PKG:32	
55-10-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)							Service	ATA:55
	MOS	16-Apr-13	144 (+2m)		16-Apr-25	16-Jun-25	375 d (+61)	CPCP	
	HRS	9087.6							
	AFL	6131							
				PROC. REF: AMM 55-10-00-220-801					
55-10-00-220-802-01 ^S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS							Service	ATA:55
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
	AFL	6131	7500						
				PROC. REF: AMM 55-10-00-220-802				PKG:32	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 55 - STABILIZERS									
55-10-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP)							Service	ATA:55
	MOS	16-Apr-13	144 (+2m)		16-Apr-25	16-Jun-25	375 d (+61)	CPCP	
	HRS	9087.6							
	AFL	6131							
	PROC. REF: AMM 55-10-00-220-802								
55-10-00-270-801-01	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS							Service	ATA:55
	MOS	01-Mar-00	T:288 (+2m)		01-Mar-24	01-May-24	TOL (+25 d)		
	HRS	0							
WC#: 55.020	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 55-10-00-270-801								
55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY 5-40)							Service	ATA:55
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
WC#: 55.020	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 55-10-00-270-801								
55-10-00-640-802-01 ^S	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK AND ACTUATOR UPPER HINGE - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (210CH)							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 27.245	AFL	9471							
	PROC. REF: AMM 55-10-00-640-802							PKG:16	
55-10-03-640-801-01 ^S	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM							Service	ATA:55
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 55.050	AFL	9471							
	PROC. REF: AMM 55-10-03-640-801							PKG:16	
55-10-31-220-801-01 ^S	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS							Service	ATA:55
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 55.080	AFL	7947	3750						
	PROC. REF: AMM 55-10-31-220-801							PKG:31	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 55 - STABILIZERS									
55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)							Service	ATA:55
	MOS	16-Jul-19						MANDATORY 5-40	
	HRS	11761.3							
WC#: 55.080	AFL	7947	3750		11697		2195		
PROC. REF: AMM 55-10-31-220-801									
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS							Service	ATA:55
	MOS	19-Jan-23	36 (+1m)		19-Jan-26	19-Feb-26	653 d (+31)		
	HRS	13859.4	600 (+40)	Adj -3.2	14456.2	14496.2	101.8 (+40)		
WC#: 27.230	AFL	9175							
PROC. REF: AMM 55-10-33-640-801									
55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE							Service	ATA:55
	MOS	01-Mar-00							
	HRS	0							
WC#: 55.030	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-10-39-220-801									
55-10-39-220-801-01A	NON DESTRUCTIVE CHECK OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE (MANDATORY 5-40)							Service	ATA:55
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
WC#: 55.030	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-10-39-220-801									
55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE							Service	ATA:55
	MOS	01-Mar-00							
	HRS	0							
WC#: 55.030	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-10-39-220-801									
55-10-39-220-801-02A	NON DESTRUCTIVE CHECK OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE (MANDATORY 5-40)							Service	ATA:55
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
WC#: 55.030	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-10-39-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 55 - STABILIZERS									
55-20-01-900-801-01		REMOVAL / INSTALLATION OF THE ELEVATORS - LH ELEVATOR					Component	ATA:55	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-20-01-900-801									
55-20-01-900-801-02		REMOVAL / INSTALLATION OF THE ELEVATORS - RH ELEVATOR					Component	ATA:55	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-20-01-900-801									
55-20-03-640-801-01 ^S		LUBRICATION OF THE ELEVATOR BEARINGS					Service	ATA:55	
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 55.060	AFL	6131	7500						
PROC. REF: AMM 55-20-03-640-801									
55-20-03-640-802-01 ^S		LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES					Service	ATA:55	
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 27.175	AFL	9502							
PROC. REF: AMM 55-20-03-640-802									
55-20-05-640-801-01 ^S		LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND U-JOINTS					Service	ATA:55	
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
WC#: 27.240	AFL	9471							
PROC. REF: AMM 55-20-05-640-801									
55-30-00-270-801-01		ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS					Service	ATA:55	
	MOS	01-Mar-00	T:288 (+2m)		01-Mar-24	01-May-24	TOL (+25 d)		
	HRS	0							
WC#: 55.040	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-30-00-270-801									
55-30-00-270-801-01A		ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY 5-40)					Service	ATA:55	
	MOS	01-Mar-00					MANDATORY 5-40		
	HRS	0							
WC#: 55.040	AFL	0	T:11250		11250		1748		
PROC. REF: AMM 55-30-00-270-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 55 - STABILIZERS									
55-40-05-640-801-01 ^S		LUBRICATION OF THE RUDDER BEARINGS						Service	ATA:55
	MOS	16-Apr-13	144 (+2m)						
	HRS	9087.6							
WC#: 55.070	AFL	6131	7500						
PROC. REF: AMM 55-40-05-640-801								PKG:32	
55-40-05-640-802-01 ^S		LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES						Service	ATA:55
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 27.145	AFL	9502							
PROC. REF: AMM 55-40-05-640-802								PKG:15	
ATA 56 - WINDOWS									
56-10-01-900-801-01		REMOVAL / INSTALLATION OF THE WINDSHIELDS - PILOT WINDSHIELD (10SA)						Component	ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 56.030	AFL	0			TSN 0				
PROC. REF: AMM 56-10-01-900-801									
56-10-01-900-801-02		REMOVAL / INSTALLATION OF THE WINDSHIELDS - COPILOT WINDSHIELD (20SA)						Component	ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 56.030	AFL	0			TSN 0				
PROC. REF: AMM 56-10-01-900-801									
56-10-01-900-801-03		REMOVAL / INSTALLATION OF THE WINDSHIELDS - FRONT WINDSHIELD (5SA)						Component	ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 56.030	AFL	0			TSN 0				
PROC. REF: AMM 56-10-01-900-801									
56-10-07-900-801-02		REMOVAL / INSTALLATION OF THE RH LATERAL WINDOW - RH LATERAL WINDOW (40SA)						Component	ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 56.020	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-09-640-801-01 ^S LUBRICATION OF THE OPENING WINDOW MECHANISM - LH OPENING WINDOW (30SA) Service ATA:56								
	MOS	27-Dec-23	24 (+1m)					
	HRS	14292.8						
WC#: 56.010	AFL	9471						
PROC. REF: AMM 56-10-09-640-801								PKG:16
56-10-09-900-801-01 REMOVAL / INSTALLATION OF THE OPENING WINDOW - LH OPENING WINDOW (30SA) Component ATA:56								
PN:SPSF900-4-6-1	MOS/MSC	18-Nov-09	O/C					
SN:2034	HRS	7066.1						
WC#: 56.010	AFL	4752						
PROC. REF: AMM 56-10-09-900-801								
56-10-11-900-801-01 REMOVAL / INSTALLATION OF THE REAR WINDOWS - LH REAR WINDOW (60SA) Component ATA:56								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 56-10-11-900-801								
56-10-11-900-801-02 REMOVAL / INSTALLATION OF THE REAR WINDOWS - RH REAR WINDOW (65SA) Component ATA:56								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 56-10-11-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 1 LEFT PASSENGER CABIN WINDOW Component ATA:56								
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				
SN:19817	HRS	6805.3		TSN 0				
WC#: 56.050	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 1 RIGHT PASSENGER CABIN WINDOW Component ATA:56								
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				
SN:19820	HRS	6805.3		TSN 0				
WC#: 56.090	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 10 LEFT PASSENGER CABIN WINDOW Component ATA:56								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.080	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 10 RIGHT PASSENGER CABIN WINDOW								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:56
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.120	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 2 LEFT PASSENGER CABIN WINDOW								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:56
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 2 RIGHT PASSENGER CABIN WINDOW								
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				Component ATA:56
SN:19824	HRS	6805.3		TSN 0				
WC#: 56.090	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 3 LEFT PASSENGER CABIN WINDOW								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:56
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 3 RIGHT PASSENGER CABIN WINDOW								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:56
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.090	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 4 LEFT PASSENGER CABIN WINDOW								
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				Component ATA:56
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.060	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 4 RIGHT PASSENGER CABIN WINDOW								
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				Component ATA:56
SN:19823	HRS	6805.3		TSN 0				
WC#: 56.100	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 5 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.060	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 5 RIGHT PASSENGER CABIN WINDOW								Component ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.100	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 6 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				
SN:19819	HRS	6805.3		TSN 0				
WC#: 56.060	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 6 RIGHT PASSENGER CABIN WINDOW								Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				
SN:19822	HRS	6805.3		TSN 0				
WC#: 56.100	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 7 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0				
SN:19821	HRS	6805.3		TSN 0				
WC#: 56.070	AFL	4571		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 7 RIGHT PASSENGER CABIN WINDOW								Component ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.110	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01 REMOVAL / INSTALLATION OF THE NO. 8 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.070	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 56 - WINDOWS									
56-20-05-900-801-01	REMOVAL / INSTALLATION OF THE NO. 8 RIGHT PASSENGER CABIN WINDOW							Component	ATA:56
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0					
SN:19825	HRS	6805.3		TSN 0					
WC#: 56.110	AFL	4571		TSN 0					
PROC. REF: AMM 56-20-05-900-801									
56-20-05-900-801-01	REMOVAL / INSTALLATION OF THE NO. 9 LEFT PASSENGER CABIN WINDOW							Component	ATA:56
PN:SPSF2M8-3-0	MOS/MSC	18-Jun-09	O/C	TSN 0					
SN:19818	HRS	6805.3		TSN 0					
WC#: 56.070	AFL	4571		TSN 0					
PROC. REF: AMM 56-20-05-900-801									
56-20-05-900-801-01	REMOVAL / INSTALLATION OF THE NO. 9 RIGHT PASSENGER CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 56.110	AFL	0		TSN 0					
PROC. REF: AMM 56-20-05-900-801									
ATA 57 - WINGS									
57-00-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 57.0101	AFL	9471							
PROC. REF: AMM 57-00-00-210-801									
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 57-00-00-210-801									
57-00-00-210-801-02 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 57.0101	AFL	9471							
PROC. REF: AMM 57-00-00-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)		27-Dec-25	27-Jan-26	630 d (+31)	CPCP	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-03 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING ANTI-ICING SYSTEM							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-03A	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING ANTI-ICING SYSTEM (MANDATORY 5-40)							Service	ATA:57
	MOS	27-Dec-23	26		27-Feb-26		692 d	FDBCK	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING ANTI-ICING SYSTEM							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04A	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING ANTI-ICING SYSTEM (MANDATORY 5-40)							Service	ATA:57
	MOS	27-Dec-23	26		27-Feb-26		692 d	FDBCK	
	HRS	14292.8							
	AFL	9471							
	PROC. REF: AMM 57-00-00-210-801								
57-00-00-220-802-01 ^S	DETAILED INSPECTION OF THE WINGS - LH WING							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.0102	AFL	7947	3750						
	PROC. REF: AMM 57-00-00-220-802								
57-00-00-220-802-01C	DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
	PROC. REF: AMM 57-00-00-220-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-00-00-220-802-02 ^S	DETAILED INSPECTION OF THE WINGS - RH WING							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.0102	AFL	7947	3750						
PROC. REF: AMM 57-00-00-220-802								PKG:31	
57-00-00-220-802-02C	DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 57-00-00-220-802									
57-00-00-760-801-01 ^S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH SIDE WING MOVABLE SURFACE							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 57-00-00-760-801								PKG:16	
57-00-00-760-801-02 ^S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH SIDE WING MOVABLE SURFACE							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 57-00-00-760-801								PKG:16	
57-00-01-900-801-01	REMOVAL / INSTALLATION OF THE WINGS - LH WING							Component	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-00-01-900-801									
57-00-01-900-801-02	REMOVAL / INSTALLATION OF THE WINGS - RH WING							Component	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-00-01-900-801									
57-10-00-290-801-01 ^S	BORESCOPE INSPECTION OF THE WING TANKS							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 57-10-00-290-801								PKG:31	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)		16-Jul-25	16-Sep-25	466 d (+62)	CPCP	
	HRS	11761.3							
	AFL	7947							
	PROC. REF: AMM 57-10-00-290-801								
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-01-210-801								
57-10-01-210-801-01A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-01-210-801								
57-10-01-210-801-02	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-01-210-801								
57-10-01-210-801-02A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-01-210-801								
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-14-220-801-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-801-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-220-802								
57-10-14-250-801-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-14-250-801-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-801-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-801-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-802								
57-10-14-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-802								
57-10-14-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-802								
57-10-14-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-14-250-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-02	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-02A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-802								
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-802								
57-10-15-220-802-02	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-15-220-802-02A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-220-802								
57-10-15-250-801-01	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-01A	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-02	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-02A	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-10-15-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-803-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING							Service	ATA:57
	MOS	01-Mar-00							
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)							Service	ATA:57
	MOS	01-Mar-00						MANDATORY 5-40	
	HRS	0							
	AFL	0	T:11250		11250		1748		
	PROC. REF: AMM 57-10-15-250-803								
57-41-13-640-801-01 ^S	LUBRICATION OF THE SLAT MECHANISMS							Service	ATA:57
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 27.395	AFL	9471							
	PROC. REF: AMM 57-41-13-640-801								

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-45-13-220-801-01 ^S	DETAILED INSPECTION OF THE SLAT CASINGS - INSPECTION OF LH OUTBOARD SLAT CASINGS AT TRACKS 6 AND 8							Service	ATA:57
	MOS	01-Mar-00	144 (+2m)						
	HRS	0							
	AFL	0	7500						
	PROC. REF: AMM 57-45-13-220-801							PKG:32	
57-45-13-220-801-02 ^S	DETAILED INSPECTION OF THE SLAT CASINGS - INSPECTION OF RH OUTBOARD SLAT CASINGS AT TRACKS 6 AND 8							Service	ATA:57
	MOS	01-Mar-00	144 (+2m)						
	HRS	0							
	AFL	0	7500						
	PROC. REF: AMM 57-45-13-220-801							PKG:32	
57-45-13-280-801-01 ^U	CONDUCTIVITY CHECK OF THE SLATS							Service	ATA:57
	MOS/MSC	01-Mar-00	O/C						
	HRS	0							
	AFL	0							
	PROC. REF: GENERIC NO REF								
57-45-13-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - LH OUTBOARD SLAT							Component	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
	PROC. REF: AMM 57-45-13-900-801								
57-45-13-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - RH OUTBOARD SLAT							Component	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
	PROC. REF: AMM 57-45-13-900-801								
57-45-13-960-801-01	REPLACEMENT OF THE OUTBOARD SLATS - LH OUTBOARD SLAT							Service	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
	PROC. REF: AMM 57-45-13-960-801								
57-45-13-960-801-02	REPLACEMENT OF THE OUTBOARD SLATS - RH OUTBOARD SLAT							Service	ATA:57
PN:PN	MOS/MSC	01-Mar-00	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
	PROC. REF: AMM 57-45-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-45-25-250-801-01	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 5 AND 10							Service	ATA:57
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 57.220	AFL	7947	7500		15447		5945		
PROC. REF: AMM 57-45-25-250-801									
57-55-00-700-801-01 ^S	CHECK OF THE FLAP LATERAL CLEARANCE							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.150	AFL	7947	3750						
PROC. REF: AMM 57-55-00-700-801									
57-55-07-220-801-01 ^S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - LH WING							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.060	AFL	7947	3750						
PROC. REF: AMM 57-55-07-220-801									
57-55-07-220-801-02 ^S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - RH WING							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.060	AFL	7947	3750						
PROC. REF: AMM 57-55-07-220-801									
57-55-11-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 57-55-11-210-801									
57-55-13-640-801-01 ^S	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - LH WING							Service	ATA:57
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
PROC. REF: AMM 57-55-13-640-801									
57-55-13-640-801-02 ^S	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - RH WING							Service	ATA:57
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
	AFL	9471							
PROC. REF: AMM 57-55-13-640-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-55-21-250-801-01	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5							Service	ATA:57
	MOS	16-Jul-19							
	HRS	11761.3							
WC#: 57.080	AFL	7947	3750		11697		2195		
PROC. REF: AMM 57-55-21-250-801									
57-55-21-250-801-01A	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)							Service	ATA:57
	MOS	16-Jul-19							
	HRS	11761.3							
	AFL	7947	4770		12717		3215		
PROC. REF: AMM 57-55-21-250-801									
57-60-05-640-801-01 ^S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.090	AFL	7947	3750						
PROC. REF: AMM 57-60-05-640-801									
57-60-05-640-801-02 ^S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS							Service	ATA:57
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 57.090	AFL	7947	3750						
PROC. REF: AMM 57-60-05-640-801									
57-60-05-640-802-01 ^S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON							Service	ATA:57
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
	AFL	9502							
PROC. REF: AMM 57-60-05-640-802									
57-60-05-640-802-02 ^S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON							Service	ATA:57
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
	AFL	9502							
PROC. REF: AMM 57-60-05-640-802									
57-70-03-640-801-01 ^S	LUBRICATION OF THE AIRBRAKE HINGES							Service	ATA:57
	MOS	07-Feb-24	12 (+1m)						
	HRS	14354.4							
WC#: 27.340	AFL	9502							
PROC. REF: AMM 57-70-03-640-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 71 - POWER PLANT									
71-00-00-100-801-01	ENGINE CLEANING - ENGINE 1 (L5EZ)							Service	ATA:71
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 71-00-00-100-801								
71-00-00-100-801-02	ENGINE CLEANING - ENGINE 2 (R5EZ)							Service	ATA:71
	MOS/MSC	01-Mar-00	A/R						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 71-00-00-100-801								
71-00-00-910-802-01	ENGINE INSPECTION RUN-UP - ENGINE 1 (L5EZ)							Service	ATA:71
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 71-00-00-910-802								
71-00-00-910-802-02	ENGINE INSPECTION RUN-UP - ENGINE 2 (R5EZ)							Service	ATA:71
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 71-00-00-910-802								
71-00-00-910-803-01	END OF INSPECTION RUN-UP - ENGINE 1 (L5EZ)							Service	ATA:71
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 71-00-00-910-803								
71-00-00-910-803-02	END OF INSPECTION RUN-UP - ENGINE 2 (R5EZ)							Service	ATA:71
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
	AFL	9179							
	PROC. REF: AMM 71-00-00-910-803								
71-20-02-250-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE FRONT MOUNTS AND FITTINGS - ENGINE 1 FRONT MOUNT ASSEMBLY (L10EZ)							Service	ATA:71
	MOS	16-Apr-13	216 (+3%)		16-Apr-31	30-Oct-31	2566 d (+197)		
	HRS	9087.6							
WC#: 54.030	AFL	6131	3750		9881		379		
	PROC. REF: AMM 71-20-02-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-02-250-801-01A SPECIAL DETAILED INSPECTION OF THE NO.1 ENGINE FRONT MOUNTS AND FITTINGS (MANDATORY 5-40)								
	MOS	16-Apr-13						Service ATA:71
	HRS	9087.6						MANDATORY 5-40
WC#: 54.030	AFL	6131	3750		9881		379	
PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-02 SPECIAL DETAILED INSPECTION OF THE ENGINE FRONT MOUNTS AND FITTINGS - ENGINE 2 FRONT MOUNT ASSEMBLY (R10EZ)								
	MOS	29-Oct-14	216 (+3%)		29-Oct-32	13-May-33	3128 d (+196)	Service ATA:71
	HRS	10116.65						
WC#: 54.030	AFL	6829	3750		10579		1077	
PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-02A SPECIAL DETAILED INSPECTION OF THE NO.2 ENGINE FRONT MOUNTS AND FITTINGS (MANDATORY 5-40)								
	MOS	29-Oct-14						Service ATA:71
	HRS	10116.65						MANDATORY 5-40
WC#: 54.030	AFL	6829	3750		10579		1077	
PROC. REF: AMM 71-20-02-250-801								
71-20-02-900-801-01 REMOVAL / INSTALLATION OF THE ENGINE FRONT MOUNTS - ENGINE 1 FRONT MOUNT ASSEMBLY (L10EZ)								
PN:3051040-5	MOS/MSC	23-Nov-12	O/C					Component ATA:71
SN:018-019031-00130	HRS							
WC#: 54.030	AFL							
PROC. REF: AMM 71-20-02-900-801								
71-20-02-900-801-02 REMOVAL / INSTALLATION OF THE ENGINE FRONT MOUNTS - ENGINE 2 FRONT MOUNT ASSEMBLY (R10EZ)								
PN:3051040-4	MOS/MSC	04-Sep-09	O/C					Component ATA:71
SN:0428-6847-4-04028-124	HRS	7030.4		TSN 5132.6				
WC#: 54.030	AFL	4768		TSN 3382				
PROC. REF: AMM 71-20-02-900-801								
71-20-07-250-801-01 SPECIAL DETAILED INSPECTION OF THE ENGINE REAR MOUNTS - ENGINE 1 REAR MOUNT								
	MOS	16-Apr-13						Service ATA:71
	HRS	9087.6						
WC#: 54.040	AFL	6131	3750		9881		379	
PROC. REF: AMM 71-20-07-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 71 - POWER PLANT									
71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION OF THE NO.1 ENGINE REAR MOUNTS (MANDATORY 5-40)							Service	ATA:71
	MOS	16-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 54.040	AFL	6131	3750		9881		379		
PROC. REF: AMM 71-20-07-250-801									
71-20-07-250-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE REAR MOUNTS - ENGINE 2 REAR MOUNT							Service	ATA:71
	MOS	17-Apr-13							
	HRS	9087.6							
WC#: 54.040	AFL	6131	3750		11250 (M)		1748		
PROC. REF: AMM 71-20-07-250-801									
71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION OF THE NO.2 ENGINE REAR MOUNTS (MANDATORY 5-40)							Service	ATA:71
	MOS	17-Apr-13						MANDATORY 5-40	
	HRS	9087.6							
WC#: 54.040	AFL	6131	3750		11250 (M)		1748		
PROC. REF: AMM 71-20-07-250-801									
710031 ^U	PERFORM ENGINE CHECK FLIGHT							Service	ATA:71
	MOS/MSC	01-Mar-00	E/C						
	HRS	0							
WC#: 71.090	AFL	0							
PROC. REF: GENERIC NO REF									
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3050000-5	MOS/MSC	28-Feb-23	E/C						
SN:P105362	HRS	13865.3							
WC#: 71.EN1	AFL	9179							
PROC. REF: AMM 71-00-01-900-801									
71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3050000-5	MOS/MSC	28-Feb-23	E/C						
SN:P105414	HRS	13865.3							
WC#: 71.EN2	AFL	9179							
PROC. REF: AMM 71-00-01-900-801									
ATA 72 - ENGINE									
720010	NO. 1 ENGINE - PERFORM ENGINE (MPI) MIDPOINT INSPECTION							Service	ATA:72
	MOS	13-Aug-19							
	HRS	10645.5	2500 (+50)		(13145.5) 15167.7	13195.5	813.3 (+50)		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
	ENC	7219							
PROC. REF: LMM 72-00-00									
720010	NO. 2 ENGINE - PERFORM ENGINE (MPI) MIDPOINT INSPECTION							Service	ATA:72
	MOS	14-Jun-19							
	HRS	10816	2500 (+50)		(13316) 15179.1	13366	824.7 (+50)		
	ENC	7355							
PROC. REF: LMM 72-00-00									
720020	NO. 1 ENGINE - PERFORM ENGINE (CZI) CORE ZONE INSPECTION							Service	ATA:72
	MOS	26-Nov-12							
	HRS	8078	5000 (+50)		(13078) 15100.2	13128	745.8 (+50)		
	ENC	5537							
PROC. REF: LMM 72-00-00									
720020	NO. 2 ENGINE - PERFORM ENGINE (CZI) CORE ZONE INSPECTION							Service	ATA:72
	MOS	26-Feb-13							
	HRS	8388.8	5000 (+50)		(13388.8) 15251.9	13438.8	897.5 (+50)		
	ENC	5734							
PROC. REF: LMM 72-00-00									
720030 ^S	NO. 1 ENGINE - FUNCTIONAL CHECK OF OVERSPEED SYSTEM							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)						
	ENC	8203							
PROC. REF: LMM 72-00-00									
720030 ^S	NO. 2 ENGINE - FUNCTIONAL CHECK OF OVERSPEED SYSTEM							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
PROC. REF: LMM 72-00-00									
720040 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF DEFERRED TIME LIMITED DISPATCH FAULT MESSAGES							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)						
	ENC	8203							
PROC. REF: LMM 72-00-00									

PKG:3 ,4 ,6,7,5

PKG:3 ,4 ,6,7,5

PKG:3 ,4 ,6,7,5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
720040 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF DEFERRED TIME LIMITED DISPATCH FAULT MESSAGES							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
					PROC. REF: LMM 72-00-00			PKG:3 ,4 ,6,7,5	
720050 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF FIRE ZONE 1 FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)						
	ENC	8203							
					PROC. REF: LMM 72-00-00, LMM CFE-2007-EIT-002			PKG:3 ,4 ,6,7,5	
720050 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF FIRE ZONE 1 FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
					PROC. REF: LMM 72-00-00, LMM CFE-2007-EIT-002			PKG:3 ,4 ,6,7,5	
720060 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF UNDER COWL AREA (FIRE ZONE 2) FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	19-Dec-23							
	HRS	12270.6	1200 (+50)						
	ENC	8203							
					PROC. REF: GENERIC NO REF, LMM CFE-2007-EIT-002, LMM 72-00-00			PKG:5,7	
720060 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF UNDER COWL AREA (FIRE ZONE 2) FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	19-Dec-23							
	HRS	12429.6	1200 (+50)						
	ENC	8337							
					PROC. REF: GENERIC NO REF, LMM CFE-2007-EIT-002, LMM 72-00-00			PKG:5,7	
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE							Service	ATA:72
	MOS/MSC	20-Aug-10	O/C						
	HRS	6721							
	ENC	4583							
					PROC. REF: LMM 72-00-00				
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE							Service	ATA:72
	MOS/MSC	01-Jul-00	O/C						
	HRS	0							
	ENC	0							
					PROC. REF: LMM 72-00-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service	ATA:72
	MOS/MSC	20-Aug-10	O/C						
	HRS	6721							
	ENC	4583							
	PROC. REF: LMM 72-00-00								
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service	ATA:72
	MOS/MSC	01-Jul-00	O/C						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE							Service	ATA:72
	MOS/MSC	26-Nov-12	O/C						
	HRS	8078							
	ENC	5537							
	PROC. REF: LMM 72-00-00								
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE							Service	ATA:72
	MOS/MSC	01-Jul-00	O/C						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721004	NO. 1 ENGINE - SPECIAL(UNSCHEDULED) AND SCHEDULED INSPECTIONS							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721004	NO. 2 ENGINE - SPECIAL(UNSCHEDULED) AND SCHEDULED INSPECTIONS							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721005	NO. 1 ENGINE - INSPECT ENGINES THAT HAVE OPERATED ABOVE THE TEMPATURE LIMITS (OVERTEMPERATURE)							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
721005	NO. 2 ENGINE - INSPECT ENGINES THAT HAVE OPERATED ABOVE THE TEMPATURE LIMITS (OVERTEMPERATURE)							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721006	NO. 1 ENGINE - INSPECT ENGINES THAT HAVE OPERATED ABOVE SPEED LIMITS							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721006	NO. 2 ENGINE - INSPECT ENGINES THAT HAVE OPERATED ABOVE SPEED LIMITS							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721007	NO. 1 ENGINE - INSPECT ENGINES THAT SHOW HOT-SECTION DISTRESS (BURN-OUTS)							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721007	NO. 2 ENGINE - INSPECT ENGINES THAT SHOW HOT-SECTION DISTRESS (BURN-OUTS)							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721008	NO. 1 ENGINE - INSPECT ENGINES AFTER THE AIRCRAFT HAS BEEN HIT BY LIGHTNING							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721008	NO. 2 ENGINE - INSPECT ENGINES AFTER THE AIRCRAFT HAS BEEN HIT BY LIGHTNING							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
721009	NO. 1 ENGINE - INSPECT ENGINES AFTER A VG SYSTEM MALFUNCTION OR A COMPLESSOR STALL							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721009	NO. 2 ENGINE - INSPECT ENGINES AFTER A VG SYSTEM MALFUNCTION OR A COMPLESSOR STALL							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721010	NO. 1 ENGINE - INSPECT ENGINES FOR METAL CONTAMINATION OF OIL SYSTEM							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721010	NO. 2 ENGINE - INSPECT ENGINES FOR METAL CONTAMINATION OF OIL SYSTEM							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721011	NO. 1 ENGINE - INSPECT ENGINES OPERATED WITH LOW OR NO OIL PRESSURE INDICATION							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721011	NO. 2 ENGINE - INSPECT ENGINES OPERATED WITH LOW OR NO OIL PRESSURE INDICATION							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721012	NO. 1 ENGINE - INSPECT ENGINES THAT HAVE INGESTED VOLCANIC ASH							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
721012	NO. 2 ENGINE - INSPECT ENGINES THAT HAVE INGESTED VOLCANIC ASH							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721013	NO. 1 ENGINE - INSPECT ENGINES OPERATED AT VIBRATION LEVELS BEYOND THE ALLOWED LIMITS LISTED IN TESTING							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721013	NO. 2 ENGINE - INSPECT ENGINES OPERATED AT VIBRATION LEVELS BEYOND THE ALLOWED LIMITS LISTED IN TESTING							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721014	NO. 1 ENGINE - INSPECT ENGINES IMMERSSED IN SALT WATER OR EXPOSED TO FIRE EXINGUISHING MATERIAL							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721014	NO. 2 ENGINE - INSPECT ENGINES IMMERSSED IN SALT WATER OR EXPOSED TO FIRE EXINGUISHING MATERIAL							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721015	NO. 1 ENGINE - INSPECT ENGINES FOR FOD THAT HAVE BIRD STRICKES OR INGEST FOREIGN OBJECTS							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721015	NO. 2 ENGINE - INSPECT ENGINES FOR FOD THAT HAVE BIRD STRICKES OR INGEST FOREIGN OBJECTS							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
721016	NO. 1 ENGINE - LUBE OIL PRESSURE SENSOR INSPECTION							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721016	NO. 2 ENGINE - LUBE OIL PRESSURE SENSOR INSPECTION							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721017	NO. 1 ENGINE - COMPRESSOR VANE ACTUATING ASSEMBLY TO STATOR VANE SPINDLE INSPECTION							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721017	NO. 2 ENGINE - COMPRESSOR VANE ACTUATING ASSEMBLY TO STATOR VANE SPINDLE INSPECTION							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721018	NO. 1 ENGINE - GEARBOX RIGID COUPLING SHAFT INSPECTION							Service	ATA:72
	MOS/MSC	01-Aug-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
721018	NO. 2 ENGINE - GEARBOX RIGID COUPLING SHAFT INSPECTION							Service	ATA:72
	MOS/MSC	01-Jul-00	A/R						
	HRS	0							
	ENC	0							
	PROC. REF: LMM 72-00-00								
722010	NO. 1 ENGINE - NO.1 ROLLER BEARING							Component	ATA:72
PN:3050714-1	MOS/MSC	17-Dec-05	O/C						
SN:991991407939	HRS				TSN 3929.4				
	ENC				TSN 2774				
	PROC. REF: GENERIC NO REF, LMM 72-71-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
722010	NO. 2 ENGINE - NO.1 ROLLER BEARING							Component	ATA:72
PN:3050714-1	MOS/MSC	18-May-06	O/C						
SN:001991411835	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
PROC. REF: GENERIC NO REF, LMM 72-71-02									
722020	NO. 1 ENGINE - NO.2 BALL BEARING							Component	ATA:72
PN:3050114-1	MOS/MSC	17-Dec-05	O/C						
SN:991991407885	HRS			TSN 3929.4					
	ENC			TSN 2774					
PROC. REF: GENERIC NO REF									
722020	NO. 2 ENGINE - NO.2 BALL BEARING							Component	ATA:72
PN:3050701-5	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:00P10835	HRS			TSO 0					
	ENC			TSO 0					
PROC. REF: GENERIC NO REF									
722030	NO. 1 ENGINE - NO.2 AFT ROLLER BEARING							Component	ATA:72
PN:3050738-1	MOS/MSC	17-Dec-05	O/C						
SN:991991415006	HRS			TSN 3929.4					
	ENC			TSN 2774					
PROC. REF: GENERIC NO REF									
722030	NO. 2 ENGINE - NO.2 AFT ROLLER BEARING							Component	ATA:72
PN:3050738-1	MOS/MSC	18-May-06	O/C						
SN:001991408919	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
PROC. REF: GENERIC NO REF									
722040	NO. 1 ENGINE - FAN SPINNER ASSEMBLY							Component	ATA:72
PN:3050223-1	MOS	26-Nov-12		TSO 0				LIFE LIMIT	
SN:06278300002	HRS	8078		TSN 2417, TSO 0					
	ENC	5537	24000	TSN 1567, TSO 0	(27970) 29238		19736		
PROC. REF: LMM 72-70-01, LMM 72-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
722040	NO. 2 ENGINE - FAN SPINNER ASSEMBLY							Component	ATA:72
PN:3050223-1	MOS	11-Jul-07		TSN 0, TSO 0				LIFE LIMIT	
SN:042784300029	HRS	5048.2		TSN 0, TSO 0					
	ENC	3400	24000	TSN 0, TSO 0	(27400) 28534		19032		
PROC. REF: LMM 72-70-01, LMM 72-70-01									
722050	NO. 1 ENGINE - FAN ROTOR ASSEMBLY							Component	ATA:72
PN:3050753-2	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:980322902434	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
PROC. REF: GENERIC NO REF, LMM 72-70-02, LMM 72-70-02									
722050	NO. 2 ENGINE - FAN ROTOR ASSEMBLY							Component	ATA:72
PN:3050753-2	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:000322901304	HRS			TSN 8388.8, TSO 0					
	ENC			TSN 5734, TSO 0					
PROC. REF: GENERIC NO REF, LMM 72-70-02, LMM 72-70-02									
722060	NO. 1 ENGINE - FAN ROTOR DISK							Component	ATA:72
PN:3050745-2	MOS	11-May-07		TSO 0				LIFE LIMIT	
SN:980322902434	HRS	5142.6		TSN 5710.6, TSO 0					
	ENC	3555	24000	TSN 3648, TSO 0	(23907) 25175		15673		
PROC. REF: GENERIC NO REF, LMM 72-70-02, LMM 72-71-02									
722060	NO. 2 ENGINE - FAN ROTOR DISK							Component	ATA:72
PN:3050745-2	MOS	18-May-06		TSO 0				LIFE LIMIT	
SN:000322901304	HRS	3932		TSN 3932.9, TSO 0					
	ENC	2683	24000	TSN 2683, TSO 0	(24000) 25134		15632		
PROC. REF: GENERIC NO REF, LMM 72-70-02, LMM 72-71-02									
722065	NO. 1 ENGINE - INSPECT FAN ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
722065	NO. 2 ENGINE - INSPECT FAN ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
722070	NO. 1 ENGINE - FAN STUB SHAFT							Component	ATA:72
PN:3050708-4	MOS/MSC	17-Dec-05	O/C						
SN:982517402484	HRS			TSN 3929.4					
	ENC			TSN 2774					
				PROC. REF: LMM 72-50-04, LMM 72-50-04					
722070	NO. 2 ENGINE - FAN STUB SHAFT							Component	ATA:72
PN:3050708-4	MOS/MSC	18-May-06	O/C						
SN:002512300028	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
				PROC. REF: LMM 72-50-04, LMM 72-50-04					
722080	NO. 1 ENGINE - CORE MODULE							Component	ATA:72
PN:6091T09G01	MOS/MSC	22-Dec-05	O/C						
SN:800461	HRS			TSN 3929.4					
	ENC			TSN 2774					
				PROC. REF: GENERIC NO REF					
722080	NO. 2 ENGINE - CORE MODULE							Component	ATA:72
PN:6091T09G01	MOS/MSC	18-May-06	O/C						
SN:800511	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
				PROC. REF: GENERIC NO REF					
722090	NO. 1 ENGINE - NO.3 BALL BEARING							Component	ATA:72
PN:5123T93P02	MOS/MSC	17-Dec-05	O/C						
SN:FCAB6474	HRS			TSN 3929.4					
	ENC			TSN 2774					
				PROC. REF: GENERIC NO REF					
722090	NO. 2 ENGINE - NO.3 BALL BEARING							Component	ATA:72
PN:5123T93P03	MOS/MSC	27-Feb-13	O/C	TSN 0					
SN:TBCKT323	HRS			TSN 0					
	ENC			TSN 0					
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723010	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T68G11	MOS	31-May-03						LIFE LIMIT	
SN:GLHK61DP	HRS	1884		TSN 1884					
	ENC	1374	20000	TSN 1374	(20000) 21268		11766		
PROC. REF: GENERIC NO REF									
723010	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T68G11	MOS	18-May-06						LIFE LIMIT	
SN:GLHK692C	HRS	3932		TSN 3932.9					
	ENC	2683	20000	TSN 2683	(20000) 21134		11632		
PROC. REF: GENERIC NO REF									
723011	NO. 1 ENGINE - INSPECT FIRST STAGE COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723011	NO. 2 ENGINE - INSPECT FIRST STAGE COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
723015 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE ACTUATING ASSEMBLIES OF INLET, STAGE 1 AND STAGE 2,GUIDE VANES FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)						
	ENC	8203							
PROC. REF: LMM 72-00-00									
723015 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE ACTUATING ASSEMBLIES OF INLET, STAGE 1 AND STAGE 2,GUIDE VANES FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723020	NO. 1 ENGINE - STAGE 2/3 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T71P06	MOS	26-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN32755	HRS	8078		TSN 0					
	ENC	5537	10000	TSN 0	(15537) 16805		7303		
PROC. REF: GENERIC NO REF									
723020	NO. 2 ENGINE - STAGE 2/3 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T71P06	MOS	28-Feb-13		TSN 0				LIFE LIMIT	
SN:PUN32634	HRS	8388.8		TSN 0					
	ENC	5734	10000	TSN 0	(15734) 16868		7366		
PROC. REF: GENERIC NO REF									
723025	NO. 1 ENGINE - INSPECT STAGE 2/3 COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723025	NO. 2 ENGINE - INSPECT STAGE 2/3 COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
723030	NO. 1 ENGINE - STAGE 4/5 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T74P09	MOS	26-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN32806	HRS	8078		TSN 0					
	ENC	5537	5200	TSN 0	(10737) 12005		2503		
PROC. REF: GENERIC NO REF									
723030	NO. 2 ENGINE - STAGE 4/5 COMPRESSOR ROTOR BLISK							Component	ATA:72
PN:6079T74P09	MOS	19-Dec-08		TSN 0				LIFE LIMIT	
SN:PUN24896	HRS	5955		TSN 0					
	ENC	4018	5200	TSN 0	(9218) 10352		850		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723035	NO. 1 ENGINE - INSPECT STAGE 4/5 COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723035	NO. 2 ENGINE - INSPECT STAGE 4/5 COMPRESSOR ROTOR BLISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
723040	NO. 1 ENGINE - CENTRIFUGAL COMPRESSOR IMPELLER							Component	ATA:72
PN:6079T77P07	MOS	05-Mar-13		TSN 0				LIFE LIMIT	
SN:PUN32467	HRS	8078		TSN 0					
	ENC	5537	5300	TSN 0	(10837) 12105		2603		
PROC. REF: GENERIC NO REF									
723040	NO. 2 ENGINE - CENTRIFUGAL COMPRESSOR IMPELLER							Component	ATA:72
PN:6079T77P07	MOS	28-Feb-13						LIFE LIMIT	
SN:PUN23577	HRS	8388.8		TSN 2433.2					
	ENC	5734	5300	TSN 1716	(9318) 10452		950		
PROC. REF: GENERIC NO REF									
723045	NO. 1 ENGINE - INSPECT CENTRIFUGAL COMPRESSOR IMPELLER							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723045	NO. 2 ENGINE - INSPECT CENTRIFUGAL COMPRESSOR IMPELLER							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
723050	NO. 1 ENGINE - IMPELLER SHAFT							Component	ATA:72
PN:6079T80P07	MOS	26-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN32593	HRS	8078		TSN 0					
	ENC	5537	7100	TSN 0	(12637) 13905		4403		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723050	NO. 2 ENGINE - IMPELLER SHAFT							Component	ATA:72
PN:6079T80P07	MOS	28-Feb-13		TSN 0				LIFE LIMIT	
SN:PUN32546	HRS	8388.8		TSN 0					
	ENC	5734	7100	TSN 0	(12834) 13968		4466		
PROC. REF: GENERIC NO REF									
723055	NO. 1 ENGINE - INSPECT IMPELLER SHAFT							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723055	NO. 2 ENGINE - INSPECT IMPELLER SHAFT							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
723060	NO. 1 ENGINE - TIE ROD							Component	ATA:72
PN:5087T75P01	MOS	26-Nov-12						LIFE LIMIT	
SN:BCM61740	HRS	8078		TSN 4682.5					
	ENC	5537	30000	TSN 2148	(33389) 34657		25155		
PROC. REF: GENERIC NO REF									
723060	NO. 2 ENGINE - TIE ROD							Component	ATA:72
PN:5127T26P02	MOS	28-Feb-13		TSN 0				LIFE LIMIT	
SN:FBKCM019	HRS	8388.8		TSN 0					
	ENC	5734	5000	TSN 0	(10734) 11868		2366		
PROC. REF: GENERIC NO REF									
723061	NO. 1 ENGINE - INSPECT TIE ROD							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
723061	NO. 2 ENGINE - INSPECT TIE ROD							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723065	NO. 1 ENGINE - AIR TUBE							Component	ATA:72
PN:5087T83P01	MOS/MSC	17-Dec-05	O/C						
SN:PUN14123	HRS				TSN 3929.4				
	ENC				TSN 2774				
PROC. REF: GENERIC NO REF									
723065	NO. 2 ENGINE - AIR TUBE							Component	ATA:72
PN:5087T83P01	MOS/MSC	18-May-06	O/C						
SN:PUN14954	HRS	3932			TSN 3932.9				
	ENC	2683			TSN 2683				
PROC. REF: GENERIC NO REF									
723070	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component	ATA:72
PN:6079T99G09	MOS/MSC	26-Nov-12	O/C		TSR 0				
SN:GGAEB461	HRS	8078			TSR 0				
	ENC	5537			TSR 0				
PROC. REF: GENERIC NO REF, LMM 72-30-10, LMM 72-30-10									
723070	NO. 2 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component	ATA:72
PN:6079T99G09	MOS/MSC	27-Feb-13	O/C		TSR 0				
SN:GGAEB511	HRS				TSR 0				
	ENC				TSR 0				
PROC. REF: GENERIC NO REF, LMM 72-30-10, LMM 72-30-10									
723080	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) STATOR ASSEMBLY							Component	ATA:72
PN:5087T42G10	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:GGAED461	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									
723080	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) STATOR ASSEMBLY							Component	ATA:72
PN:5087T42G10	MOS/MSC	15-Nov-12	O/C						
SN:GGAEC511	HRS	8388.4							
	ENC	5734							
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									
723090	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLY							Component	ATA:72
PN:6083T73G15	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:GGAEC461	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
723090	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLY							Component	ATA:72
PN:6083T73G15	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:GGAECS11	HRS			TSN 8388.8, TSO 0					
	ENC			TSN 5734, TSO 0					
PROC. REF: GENERIC NO REF									
724010	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) INNER CASE							Component	ATA:72
PN:6083T14G06	MOS/MSC	05-Nov-12	O/C						
SN:UNKNOWN	HRS	8078							
	ENC	5537							
PROC. REF: GENERIC NO REF									
724010	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) INNER CASE							Component	ATA:72
PN:6083T14G06	MOS/MSC	15-Nov-12	O/C						
SN:UNKNOWN	HRS	8388.4							
	ENC	5734							
PROC. REF: GENERIC NO REF									
724020	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE (HPT) BLADE SET							Component	ATA:72
PN:3056T86P01	MOS	05-Mar-13						LIFE LIMIT	
SN:NCE570DH	HRS	8078	5000	TSN 0	(13078)		745.8		
	ENC	5537		TSN 0	15100.2				
PROC. REF: GENERIC NO REF									
724020	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE (HPT) BLADE SET							Component	ATA:72
PN:3056T86P01	MOS	15-Nov-12						LIFE LIMIT	
SN:NCE334JY	HRS	8388.8	5000	TSN 0	(13388.8)		897.5		
	ENC	5734		TSN 0	15251.9				
PROC. REF: GENERIC NO REF									
724030	NO. 1 ENGINE - STAGE 2 HIGH PRESSURE TURBINE (HPT) BLADE SET							Component	ATA:72
PN:6077T08P06	MOS	31-Aug-19						LIFE LIMIT	
SN:CAV626647	HRS	10645.5	6000	TSN 0	(16645.5)		4313.3		
	ENC	7219		TSN 0	18667.7				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
724030	NO. 2 ENGINE - STAGE 2 HIGH PRESSURE TURBINE (HPT) BLADE SET							Component	ATA:72
PN:6077T08P06	MOS	14-Jun-19		TSN 0				LIFE LIMIT	
SN:NCE328JU	HRS	10816	6000	TSN 0	(16816) 18679.1		4324.7		
	ENC	7355		TSN 0					
PROC. REF: GENERIC NO REF									
724040	NO. 1 ENGINE - COMBUSTION CASE							Component	ATA:72
PN:5083T09G08	MOS/MSC	17-Dec-05	O/C						
SN:GEVEW5CR	HRS			TSN 3929.4					
	ENC			TSN 2774					
PROC. REF: GENERIC NO REF									
724040	NO. 2 ENGINE - COMBUSTION CASE							Component	ATA:72
PN:5083T09G08	MOS/MSC	18-May-06	O/C						
SN:GEVEWHYP	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
PROC. REF: GENERIC NO REF									
724041	NO. 1 ENGINE - INLET FAN HOUSING							Component	ATA:72
PN:PN	MOS/MSC	01-Aug-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REF, LMM 72-20-01, LMM 72-20-01									
724041	NO. 2 ENGINE - INLET FAN HOUSING							Component	ATA:72
PN:PN	MOS/MSC	01-Jul-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REF, LMM 72-20-01, LMM 72-20-01									
724050	NO. 1 ENGINE - COMBUSTION LINER							Component	ATA:72
PN:4106T97G02	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:GGM900JC	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
PROC. REF: GENERIC NO REF									
724050	NO. 2 ENGINE - COMBUSTION LINER							Component	ATA:72
PN:4106T97G02	MOS/MSC	27-Feb-13	O/C	TSN 0					
SN:GGM9H8J0	HRS			TSN 0					
	ENC			TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
724060	NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY							Component	ATA:72
PN:5087T17G02	MOS/MSC	17-Dec-05	O/C						
SN:GATCYKJ9	HRS			TSN 3929.4					
	ENC			TSN 2774					
PROC. REF: GENERIC NO REF									
724060	NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY							Component	ATA:72
PN:5087T17G02	MOS/MSC	18-May-06	O/C						
SN:GATD0MON	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
PROC. REF: GENERIC NO REF									
724070	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY							Component	ATA:72
PN:5088T20G05	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:GGAEA461	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
PROC. REF: GENERIC NO REF									
724070	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY							Component	ATA:72
PN:5088T20G10	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:GGAEA511	HRS			TSN 8388.8, TSO 0					
	ENC			TSN 5734, TSO 0					
PROC. REF: GENERIC NO REF									
725010 ^S	NO. 1 ENGINE - BORESCOPE INTERNAL COMPONENTS							Service	ATA:72
	MOS	20-Aug-19							
	HRS	10645.5	1600 (+50)						
	ENC	7219							
PROC. REF: LMM 72-00-00									
725010 ^S	NO. 2 ENGINE - BORESCOPE INTERNAL COMPONENTS							Service	ATA:72
	MOS	19-Dec-23							
	HRS	12429.6	1600 (+50)						
	ENC	8337							
PROC. REF: LMM 72-00-00									
725020	NO. 1 ENGINE - STAGE 1 FORWARD HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:5087T76P01	MOS	05-Nov-12						LIFE LIMIT	
SN:PUN14055	HRS	8078		TSN 8078					
	ENC	5537	9700	TSN 5537	(9700) 10968		1466		
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725020	NO. 2 ENGINE - STAGE 1 FORWARD HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:5087T76P01	MOS	15-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN31166	HRS	8388.8		TSN 0					
	ENC	5734	9700	TSN 0	(15434) 16568		7066		
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									
725025	NO. 1 ENGINE - INSPECT HPT1 FORWARD COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725025	NO. 2 ENGINE - INSPECT HPT1 FORWARD COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725030	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE (HPT) DISK							Component	ATA:72
PN:5127T27P01	MOS	31-Aug-19		TSN 0				LIFE LIMIT	
SN:CAV62839	HRS	10645.5		TSN 0					
	ENC	7219	3950	TSN 0	(11169) 12437		2935		
PROC. REF: GENERIC NO REF									
725030	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE (HPT) DISK							Component	ATA:72
PN:5127T27P01	MOS	15-Nov-12		TSN 0				LIFE LIMIT	
SN:NCE334JY	HRS	8388.8		TSN 0					
	ENC	5734	3950	TSN 0	(9684) 10818		1316		
PROC. REF: GENERIC NO REF									
725035	NO. 1 ENGINE - INSPECT HPT1 DISK							Service	ATA:72
PN:5127T27P01	MOS/MSC	31-Aug-19	C/C						
SN:CAV62839	HRS	10645.5							
	ENC	7219							
725035	NO. 2 ENGINE - INSPECT HPT1 DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725040	NO. 1 ENGINE - STAGE 1 AFT HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:6083T38P08	MOS/MSC	05-Nov-12	O/C						
SN:NCE959AK	HRS	8078		TSN 4148.6					
	ENC	5537		TSN 2763					
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									
725040	NO. 2 ENGINE - STAGE 1 AFT HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:6083T38P08	MOS/MSC	15-Nov-12	O/C						
SN:NCE076BJ	HRS	8388.8		TSN 4455.9					
	ENC	5734		TSN 3051					
PROC. REF: GENERIC NO REF, LMM 72-50-08, LMM 72-50-08									
725045	NO. 1 ENGINE - INSPECT HPT1 AFT COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725045	NO. 2 ENGINE - INSPECT HPT1 AFT COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725050	NO. 1 ENGINE - TURBINE ROTOR INTERSTAGE SEAL							Component	ATA:72
PN:4106T90P01	MOS	05-Nov-12					LIFE LIMIT		
SN:BIW01AE7	HRS	8078		TSN 2257					
	ENC	5537	4600	TSN 1562	(8575) 9843		341		
PROC. REF: GENERIC NO REF									
725050	NO. 2 ENGINE - TURBINE ROTOR INTERSTAGE SEAL							Component	ATA:72
PN:4106T90P01	MOS	15-Nov-12		TSN 0			LIFE LIMIT		
SN:TMT2TD44	HRS	8388.8		TSN 0					
	ENC	5734	4600	TSN 0	(10334) 11468		1966		
PROC. REF: GENERIC NO REF									
725055	NO. 1 ENGINE - INSPECT (HPT) TURBINE ROTOR INTERSTAGE SEAL							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725055	NO. 2 ENGINE - INSPECT (HPT) TURBINE ROTOR INTERSTAGE SEAL							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725060	NO. 1 ENGINE - STAGE 2 HIGH PRESSURE TURBINE (HPT) DISK							Component	ATA:72
PN:5127T28P01	MOS	31-Aug-19		TSN 0				LIFE LIMIT	
SN:CAV62647	HRS	10645.5		TSN 0					
	ENC	7219	3950	TSN 0	(11169) 12437		2935		
PROC. REF: GENERIC NO REF									
725060	NO. 2 ENGINE - STAGE 2 HIGH PRESSURE TURBINE (HPT) DISK							Component	ATA:72
PN:5127T28P01	MOS	15-Nov-12		TSN 0				LIFE LIMIT	
SN:NCE328JU	HRS	8388.8		TSN 0					
	ENC	5734	3950	TSN 0	(9684) 10818		1316		
PROC. REF: GENERIC NO REF									
725065	NO. 1 ENGINE - INSPECT HPT2 DISK							Service	ATA:72
PN:5127T28P01	MOS/MSC	31-Aug-19	C/C						
SN:CAV62647	HRS	10645.5							
	ENC	7219							
725065	NO. 2 ENGINE - INSPECT HPT2 DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725070	NO. 1 ENGINE - STAGE 2 AFT HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:6083T39P05	MOS	05-Nov-12						LIFE LIMIT	
SN:NCE2223J	HRS	8078		TSN 8078					
	ENC	5537	10000	TSN 5537	(10000) 11268		1766		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725070	NO. 2 ENGINE - STAGE 2 AFT HIGH PRESSURE TURBINE (HPT) COOLING PLATE							Component	ATA:72
PN:6083T39P05	MOS	15-Nov-12		TSN 0				LIFE LIMIT	
SN:NCE732FB	HRS	8388.8		TSN 0					
	ENC	5734	10000	TSN 0	(15734) 16868		7366		
PROC. REF: GENERIC NO REF									
725075	NO. 1 ENGINE - INSPECT HPT2 AFT COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725075	NO. 2 ENGINE - INSPECT HPT2 AFT COOLING PLATE							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725080	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE (HPT) SHAFT							Component	ATA:72
PN:5087T15P05	MOS	05-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN32087	HRS	8078		TSN 0					
	ENC	5537	6200	TSN 0	(11737) 13005		3503		
PROC. REF: GENERIC NO REF									
725080	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE (HPT) SHAFT							Component	ATA:72
PN:5087T15P05	MOS	15-Nov-12		TSN 0				LIFE LIMIT	
SN:PUN32092	HRS	8388.8		TSN 0					
	ENC	5734	6200	TSN 0	(11934) 13068		3566		
PROC. REF: GENERIC NO REF									
725085	NO. 1 ENGINE - INSPECT HPT REAR SHAFT							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725085	NO. 2 ENGINE - INSPECT HPT REAR SHAFT							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725090	NO. 1 ENGINE - TIE ROD LOCKNUT							Component	ATA:72
PN:5087T92P01	MOS	30-Jan-06						LIFE LIMIT	
SN:TEJ36439	HRS	3929.4		TSN 3929.4					
	ENC	2774	10000	TSN 2774	(10000) 11268		1766		
PROC. REF: GENERIC NO REF									
725090	NO. 2 ENGINE - TIE ROD LOCKNUT							Component	ATA:72
PN:5087T92P01	MOS	18-May-06						LIFE LIMIT	
SN:TEJ47553	HRS	3932		TSN 3932.9					
	ENC	2683	10000	TSN 2683	(10000) 11134		1632		
PROC. REF: GENERIC NO REF									
725091	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050549-3	MOS	30-Jan-06						LIFE LIMIT	
SN:99533220610	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									
725091	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050549-3	MOS	18-May-06						LIFE LIMIT	
SN:995332201399	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									
725092	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050547-2	MOS	30-Jan-06						LIFE LIMIT	
SN:995332200660	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									
725092	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050547-2	MOS	18-May-06						LIFE LIMIT	
SN:995332201507	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725093	NO. 1 ENGINE - INSPECT TIE ROD LOCKNUT							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725093	NO. 2 ENGINE - INSPECT TIE ROD LOCKNUT							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725096	NO. 1 ENGINE - INSPECT LPT1 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725096	NO. 2 ENGINE - INSPECT LPT1 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725097	NO. 1 ENGINE - INSPECT LPT2 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725097	NO. 2 ENGINE - INSPECT LPT2 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725110	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050545-3	MOS	30-Jan-06						LIFE LIMIT	
SN:995332200642	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725110	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE (LPT) ROTOR DISK							Component	ATA:72
PN:3050545-3	MOS	18-May-06						LIFE LIMIT	
SN:995332201528	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									
725115	NO. 1 ENGINE - INSPECT LPT3 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725115	NO. 2 ENGINE - INSPECT LPT3 ROTOR DISK							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725120	NO. 1 ENGINE - STAGE 1/2 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050548-2	MOS	30-Jan-06						LIFE LIMIT	
SN:990316000587	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									
725120	NO. 2 ENGINE - STAGE 1/2 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050548-4	MOS	18-May-06						LIFE LIMIT	
SN:000316000701	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									
725125	NO. 1 ENGINE - INSPECT STAGE 1/2 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725125	NO. 2 ENGINE - INSPECT STAGE 1/2 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725130	NO. 1 ENGINE - STAGE 2/3 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050546-3	MOS	30-Jan-06		TSN 0				LIFE LIMIT	
SN:050316000371	HRS	3929.4		TSN 0					
	ENC	2774	25000	TSN 0	(27774) 29042		19540		
PROC. REF: GENERIC NO REF									
725130	NO. 2 ENGINE - STAGE 2/3 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050546-3	MOS	18-May-06		TSN 3932.9				LIFE LIMIT	
SN:000316001168	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									
725135	NO. 1 ENGINE - INSPECT STAGE 2/3 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725135	NO. 2 ENGINE - INSPECT STAGE 2/3 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725140	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050807-1	MOS	30-Jan-06						LIFE LIMIT	
SN:99230400165	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									
725140	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Component	ATA:72
PN:3050807-1	MOS	18-May-06		TSN 0				LIFE LIMIT	
SN:051686801425	HRS	3932		TSN 0					
	ENC	2683	25000	TSN 0	(27683) 28817		19315		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725145	NO. 1 ENGINE - INSPECT STAGE 1 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725145	NO. 2 ENGINE - INSPECT STAGE 1 LOW PRESSURE TURBINE (LPT) ROTATING AIR SEAL							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725150	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) STUB SHAFT							Component	ATA:72
PN:3050867-2	MOS	30-Jan-06						LIFE LIMIT	
SN:980322903301	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									
725150	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) STUB SHAFT							Component	ATA:72
PN:3050867-2	MOS	19-Dec-08		TSN 0				LIFE LIMIT	
SN:060322903547	HRS	5955		TSN 0					
	ENC	4018	25000	TSN 0	(29018) 30152		20650		
PROC. REF: GENERIC NO REF									
725155	NO. 1 ENGINE - INSPECT LP STUB SHAFT							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725155	NO. 2 ENGINE - INSPECT LP STUB SHAFT							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725160	NO. 1 ENGINE - 2ND/3RD LOW PRESSURE TURBINE (LPT) COUPLER SHAFT							Component	ATA:72
PN:3050583-6	MOS	30-Jan-06						LIFE LIMIT	
SN:990316000412	HRS	3929.4		TSN 3929.4					
	ENC	2774	25000	TSN 2774	(25000) 26268		16766		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725160	NO. 2 ENGINE - 2ND/3RD LOW PRESSURE TURBINE (LPT) COUPLER SHAFT							Component	ATA:72
PN:3050583-6	MOS	18-May-06						LIFE LIMIT	
SN:000316000090	HRS	3932		TSN 3932.9					
	ENC	2683	25000	TSN 2683	(25000) 26134		16632		
PROC. REF: GENERIC NO REF									
725165	NO. 1 ENGINE - INSPECT COUPLER SHAFT							Service	ATA:72
	MOS/MSC	01-Aug-00	C/C						
	HRS	0							
	ENC	0							
725165	NO. 2 ENGINE - INSPECT COUPLER SHAFT							Service	ATA:72
	MOS/MSC	01-Jul-00	C/C						
	HRS	0							
	ENC	0							
725170	NO. 1 ENGINE - LOW PRESSURE (LP) SHAFT							Component	ATA:72
PN:3050882-1	MOS/MSC	27-Jun-10	O/C	TSO 0					
SN:6-04733-132	HRS			TSN 4889.1, TSO 0					
	ENC			TSN 2576, TSO 0					
PROC. REF: GENERIC NO REF									
725170	NO. 2 ENGINE - LOW PRESSURE (LP) SHAFT							Component	ATA:72
PN:3050882-1	MOS/MSC	19-Dec-08	O/C	TSO 0					
SN:970473300003	HRS	5955		TSN 3998, TSO 0					
	ENC	4018		TSO 0					
PROC. REF: GENERIC NO REF									
725180	NO. 1 ENGINE - TOWER SHAFT ROLLER BEARING							Component	ATA:72
PN:3050182-2	MOS/MSC	17-Dec-05	O/C						
SN:981991421617	HRS			TSN 3929.4					
	ENC			TSN 2774					
PROC. REF: GENERIC NO REF									
725180	NO. 2 ENGINE - TOWER SHAFT ROLLER BEARING							Component	ATA:72
PN:3050182-2	MOS/MSC	18-May-06	O/C						
SN:001991411809	HRS	3932		TSN 3932.9					
	ENC	2683		TSN 2683					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725190	NO. 1 ENGINE - TOWER SHAFT DUPLEX BALL BEARING							Component	ATA:72
PN:3051357-1	MOS/MSC	14-Jul-09	O/C		TSN 0				
SN:080233010333	HRS				TSN 0				
	ENC				TSN 0				
PROC. REF: GENERIC NO REF									
725190	NO. 2 ENGINE - TOWER SHAFT DUPLEX BALL BEARING							Component	ATA:72
PN:3051357-1	MOS/MSC	27-Feb-13	O/C		TSN 0				
SN:12-151725-07855	HRS				TSN 0				
	ENC				TSN 0				
PROC. REF: GENERIC NO REF									
725210	NO. 1 ENGINE - NO.4 ROLLER BEARING							Component	ATA:72
PN:3050855-1	MOS/MSC	22-Dec-05	O/C		TSN 0				
SN:051991418477	HRS				TSN 0				
	ENC				TSN 0				
PROC. REF: GENERIC NO REF									
725210	NO. 2 ENGINE - NO.4 ROLLER BEARING							Component	ATA:72
PN:3050855-1	MOS/MSC	18-May-06	O/C						
SN:031991407830	HRS	3932			TSN 1934.6				
	ENC	2683			TSN 1270				
PROC. REF: GENERIC NO REF									
725220	NO. 1 ENGINE - NO.5 ROLLER BEARING							Component	ATA:72
PN:3050595-1	MOS/MSC	30-Jan-06	O/C						
SN:991991402768	HRS				TSN 3929.4				
	ENC				TSN 2774				
PROC. REF: GENERIC NO REF									
725220	NO. 2 ENGINE - NO.5 ROLLER BEARING							Component	ATA:72
PN:3050595-1	MOS/MSC	18-May-06	O/C						
SN:001991411777	HRS	3932			TSN 3932.9				
	ENC	2683			TSN 2683				
PROC. REF: GENERIC NO REF									
725230	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050526-8	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:995332200610	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
725230	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050526-8	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:975332201149	HRS			TSN 4134.7, TSO 0					
	ENC			TSN 2689, TSO 0					
PROC. REF: GENERIC NO REF									
725240	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050518-4	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:995332200660	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
PROC. REF: GENERIC NO REF									
725240	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050518-4	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:995332201507	HRS			TSN 8388.8, TSO 0					
	ENC			TSN 5734, TSO 0					
PROC. REF: GENERIC NO REF									
725250	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050509-4	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:995332200642	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
PROC. REF: GENERIC NO REF									
725250	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY							Component	ATA:72
PN:3050509-4	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:975332200599	HRS			TSN 4134.7, TSO 0					
	ENC			TSN 2689, TSO 0					
PROC. REF: GENERIC NO REF									
725260	NO. 1 ENGINE - DETAILED INSPECTION OF THE GENERATOR RIGID COUPLING SHAFT							Service	ATA:72
	MOS/MSC	22-Nov-13	O/C						
	HRS	8410							
	ENC	5762							
PROC. REF: LMM 72-00-60									
725260 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE GENERATOR RIGID COUPLING SHAFT							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
PROC. REF: LMM 72-00-60									

PKG:3 ,4 ,6,7,5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
726010	NO. 1 ENGINE - ACCESSORY GEARBOX							Component	ATA:72
PN:3050601-4	MOS/MSC	26-Nov-12	O/C	TSR 0					
SN:1272	HRS	8078		TSR 0					
	ENC	5537		TSR 0					
PROC. REF: LMM 72-00-60, LMM 72-00-60									
726010	NO. 2 ENGINE - ACCESSORY GEARBOX							Component	ATA:72
PN:3050601-4	MOS/MSC	19-Dec-08	O/C	TSR 0					
SN:1470	HRS	5955		TSR 0					
	ENC	4018		TSR 0					
PROC. REF: LMM 72-00-60, LMM 72-00-60									
727010	NO. 1 ENGINE - DETAILED INSPECTION OF FAIRING CORE MOUNT BRACKETS FOR CONDITION AND SECURITY							Service	ATA:72
	MOS/MSC	28-Feb-23	O/C						
	HRS	11842.8							
	ENC	7911							
PROC. REF: LMM 72-70-08									
727010 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF FAIRING CORE MOUNT BRACKETS FOR CONDITION AND SECURITY							Service	ATA:72
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
PROC. REF: LMM 72-70-08									
ATA 73 - ENGINE FUEL AND CONTROL									
73-20-05-710-801-01 ^S	OPERATIONAL TEST OF THE HMU - LH ENGINE HMU (L5EZ5)							Service	ATA:73
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 71.050	AFL	9008							
PROC. REF: AMM 73-20-05-710-801									
73-20-05-710-801-01A	OPERATIONAL TEST OF THE LH ENGINE HYDROMECHANICAL UNIT (HMU) (MANDATORY 5-40)							Service	ATA:73
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
WC#: 71.050	AFL	9008							
PROC. REF: AMM 73-20-05-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 73 - ENGINE FUEL AND CONTROL									
73-20-05-710-801-02 ^S	OPERATIONAL TEST OF THE HMU - RH ENGINE HMU (R5EZ5)							Service	ATA:73
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 73-20-05-710-801								PKG:21	
73-20-05-710-801-02A	OPERATIONAL TEST OF THE RH ENGINE HYDROMECHANICAL UNIT (HMU) (MANDATORY 5-40)							Service	ATA:73
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
PROC. REF: AMM 73-20-05-710-801									
73-40-00-700-801-01	INDICATION TEST OF APR							Service	ATA:73
	MOS	15-Jan-24	12 (+1m)		15-Jan-25	15-Feb-25	284 d (+31)		
	HRS	14325.5	400 (+40)		14725.5	14765.5	371.1 (+40)		
WC#: 71.040	AFL	9488							
PROC. REF: AMM 73-40-00-700-801									
73-40-00-700-801-01A	TEST OF THE AUTOMATIC POWER RESERVE (APR) INDICATION (MANDATORY 5-40)							Service	ATA:73
	MOS	15-Jan-24						MANDATORY 5-40	
	HRS	14325.5	450		14775.5		421.1		
WC#: 71.040	AFL	9488							
PROC. REF: AMM 73-40-00-700-801									
73-40-00-710-801-01 ^S	OPERATIONAL TEST OF APR							Service	ATA:73
	MOS	28-Feb-23							
	HRS	13865.3	1600 (+40)						
WC#: 71.070	AFL	9179							
PROC. REF: AMM 73-40-00-710-801								PKG:21	
73-40-00-710-801-01A	OPERATIONAL TEST OF THE AUTOMATIC POWER RESERVE (APR) (MANDATORY 5-40)							Service	ATA:73
	MOS	28-Feb-23						MANDATORY 5-40	
	HRS	13865.3	1800		15665.3		1310.9		
WC#: 71.070	AFL	9179							
PROC. REF: AMM 73-40-00-710-801									
73-40-00-710-802-01	OPERATIONAL TEST OF THE ENGINE SHUT-DOWN BY OVERSPEED PROTECTION							Service	ATA:73
	MOS/MSC	28-Feb-23	O/C						
	HRS	13865.3							
WC#: 71.030	AFL	9179							
PROC. REF: AMM 73-40-00-710-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 73 - ENGINE FUEL AND CONTROL									
730010		NO. 1 ENGINE - FUEL FLOW TRANSMITTER						Component	ATA:73
PN:3051203-1	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:8413	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: LMM 73-30-01, LMM 73-30-01									
730010		NO. 2 ENGINE - FUEL FLOW TRANSMITTER						Component	ATA:73
PN:3051203-1	MOS/MSC	27-Feb-13	O/C		TSO 0				
SN:W8959	HRS				TSO 0				
	ENC				TSO 0				
PROC. REF: LMM 73-30-01, LMM 73-30-01									
731010		NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER						Component	ATA:73
PN:3051200-1	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:992409400338	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: LMM 73-10-05, LMM 73-10-05									
731010		NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER						Component	ATA:73
PN:3051200-1	MOS/MSC	27-Feb-13	O/C		TSO 0				
SN:972409400163	HRS				TSO 0				
	ENC				TSO 0				
PROC. REF: LMM 73-10-05, LMM 73-10-05									
732010		NO. 1 ENGINE - (HMU) HYDROMECHANICAL UNIT						Component	ATA:73
PN:5085T40G04	MOS/MSC	26-Nov-12	O/C		TSO 0				
SN:BECH0726	HRS	8078			TSO 0				
	ENC	5537			TSO 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01									
732010		NO. 2 ENGINE - (HMU) HYDROMECHANICAL UNIT						Component	ATA:73
PN:5085T40G04	MOS/MSC	27-Feb-13	O/C		TSR 0				
SN:BECH1006	HRS				TSR 0				
	ENC				TSR 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01									
732020^S		NO. 1 ENGINE - DISCARD FUEL FILTER ELEMENT						Service	ATA:73
	MOS	28-Dec-23							
	HRS	12270.6	600 (+50)						
	ENC	8203							
PROC. REF: LMM 73-21-01, LMM 73-21-01									

PKG:2 ,5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 73 - ENGINE FUEL AND CONTROL									
732020 ^S	NO. 2 ENGINE - DISCARD FUEL FILTER ELEMENT							Service	ATA:73
	MOS	28-Dec-23							
	HRS	12429.6	600 (+50)						
	ENC	8337							
	PROC. REF: LMM 73-21-01, LMM 73-21-01								PKG:2 ,5
732030 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF HMU FOR CONDITION AND SECURITY							Service	ATA:73
	MOS	28-Dec-23							
	HRS	12270.6	400 (+10%)						
	ENC	8203							
	PROC. REF: LMM 72-00-00								PKG:3 ,4 ,6,7,5
732030 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF HMU FOR CONDITION AND SECURITY							Service	ATA:73
	MOS	28-Dec-23							
	HRS	12429.6	400 (+10%)						
	ENC	8337							
	PROC. REF: LMM 72-00-00								PKG:3 ,4 ,6,7,5
ATA 74 - IGNITION									
740010	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG							Component	ATA:74
PN:4095T13P04	MOS/MSC	28-Sep-22	O/C						
SN:UNKNOWN	HRS	11745.4							
	ENC	7866							
	PROC. REF: LMM 74-20-02								
740010	NO. 2 ENGINE - 4 O'CLOCK IGNITER PLUG							Component	ATA:74
PN:4095T13P04	MOS/MSC	11-Dec-23	O/C	TSN 0					
SN:N/A	HRS	12429.6		TSN 0					
	ENC	8337		TSN 0					
	PROC. REF: LMM 74-20-02								
740020 ^S	NO. 1 ENGINE - DETAILED INSPECTION 4 O'CLOCK IGNITER PLUG FOR CONDITION AND SECURITY							Service	ATA:74
PN:4095T13P04	MOS	28-Sep-22							
SN:UNKNOWN	HRS	11745.4	800 (+50)						
	ENC	7866							
	PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:4 ,6,7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
740020 ^{U S} NO. 2 ENGINE - DETAILED INSPECTION 4 O'CLOCK IGNITER PLUG FOR CONDITION AND SECURITY								Service ATA:74
PN:4095T13P04	MOS		28-Dec-23					
SN:N/A	HRS		12429.6			800 (+50)		
	ENC		8337					
PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:4 ,6,7
740030 NO. 1 ENGINE - 8 O'CLOCK IGNITER PLUG								Component ATA:74
PN:4095T13P04	MOS/MSC		28-Sep-22	O/C	TSN 0			
SN:UNLRC649	HRS		11745.4		TSN 0			
	ENC		7866		TSN 0			
PROC. REF: LMM 74-20-02								
740030 NO. 2 ENGINE - 8 O'CLOCK IGNITER PLUG								Component ATA:74
PN:4095T13P04	MOS/MSC		11-Dec-23	O/C	TSN 99			
SN:N/A	HRS		12429.6		TSN 2761.5			
	ENC		8337		TSN 1739			
PROC. REF: LMM 74-20-02								
740040 ^S NO. 1 ENGINE - DETAILED INSPECTION 8 O'CLOCK IGNITER PLUG FOR CONDITION AND SECURITY								Service ATA:74
PN:4095T13P04	MOS		28-Sep-22					
SN:UNLRC649	HRS		11745.4			800 (+50)		
	ENC		7866					
PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:4 ,6,7
740040 ^{U S} NO. 2 ENGINE - DETAILED INSPECTION 8 O'CLOCK IGNITER PLUG FOR CONDITION AND SECURITY								Service ATA:74
PN:4095T13P04	MOS		28-Dec-23					
SN:N/A	HRS		12429.6			800 (+50)		
	ENC		8337					
PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:4 ,6,7
741010 NO. 1 ENGINE - IGNITION EXCITER								Component ATA:74
PN:3051402-2	MOS/MSC		22-Dec-12	O/C	TSO 0			
SN:000218019264	HRS				TSO 0			
	ENC				TSO 0			
PROC. REF: LMM 74-10-01, LMM 74-10-01								
741010 NO. 2 ENGINE - IGNITION EXCITER								Component ATA:74
PN:3051402-2	MOS/MSC		08-Feb-12	O/C	TSN 0			
SN:080218092859	HRS		7911.6		TSN 0			
	ENC		5364		TSN 0			
PROC. REF: LMM 74-10-01, LMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 74 - IGNITION									
742010	NO. 1 ENGINE - 4 O'CLOCK IGNITION LEAD							Component	ATA:74
PN:PN	MOS/MSC	01-Aug-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	ENC	0			TSN 0				
PROC. REF: LMM 74-20-10, LMM 74-20-01									
742010	NO. 2 ENGINE - 4 O'CLOCK IGNITION LEAD							Component	ATA:74
PN:PN	MOS/MSC	01-Jul-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	ENC	0			TSN 0				
PROC. REF: LMM 74-20-10, LMM 74-20-01									
742020	NO. 1 ENGINE - 8 O'CLOCK IGNITION LEAD							Component	ATA:74
PN:PN	MOS/MSC	01-Aug-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	ENC	0			TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01									
742020	NO. 2 ENGINE - 8 O'CLOCK IGNITION LEAD							Component	ATA:74
PN:PN	MOS/MSC	01-Jul-00	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	ENC	0			TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 75 - AIR									
753010	NO. 1 ENGINE - START BLEED VALVE							Component	ATA:75
PN:3051350-4	MOS/MSC	26-Nov-12	O/C	TSR 0					
SN:050437400493	HRS	8078		TSR 0					
	ENC	5537		TSR 0					
PROC. REF: LMM 75-30-04, LMM 75-30-04									
753010	NO. 2 ENGINE - START BLEED VALVE							Component	ATA:75
PN:3051350-4	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:050437400507	HRS			TSO 0					
	ENC			TSO 0					
PROC. REF: LMM 75-30-04, LMM 75-30-04									
753020	NO. 1 ENGINE - START BLEED VALVE ACTUATOR							Component	ATA:75
PN:3051205-2	MOS/MSC	26-Nov-12	O/C	TSR 0					
SN:BE CJ5348	HRS	8078		TSR 0					
	ENC	5537		TSR 0					
PROC. REF: LMM 75-30-01, LMM 75-30-01									
753020	NO. 2 ENGINE - START BLEED VALVE ACTUATOR							Component	ATA:75
PN:3051205-2	MOS/MSC	27-Feb-13	O/C	TSR 0					
SN:BE CJ5470	HRS			TSR 0					
	ENC			TSR 0					
PROC. REF: LMM 75-30-01, LMM 75-30-01									
753030	NO. 1 ENGINE - (VGA) VARIABLE GEOMETRIC ACTUATOR							Component	ATA:75
PN:5077T99P03	MOS/MSC	26-Nov-12	O/C	TSR 0					
SN:BECH5040	HRS	8078		TSR 0					
	ENC	5537		TSR 0					
PROC. REF: LMM 75-30-10, LMM 75-30-10									
753030	NO. 2 ENGINE - (VGA) VARIABLE GEOMETRIC ACTUATOR							Component	ATA:75
PN:5077T99P03	MOS/MSC	27-Feb-13	O/C	TSR 0					
SN:BECH5054	HRS			TSR 0					
	ENC			TSR 0					
PROC. REF: LMM 75-30-10, LMM 75-30-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 76 - ENGINE CONTROLS									
76-10-01-900-801-01		REMOVAL / INSTALLATION OF THE THROTTLE CONTROL UNIT - THROTTLE CONTROL UNIT (10EC)					Component	ATA:76	
PN:221900-1M07	MOS/MSC	18-Apr-12	O/C	TSR 0					
SN:103	HRS	8538.7		TSR 0					
WC#: 76.020	AFL	5738		TSR 0					
PROC. REF: AMM 76-10-01-900-801									
76-10-13-900-801-01		REMOVAL / INSTALLATION OF THE ENGINE FUEL SWITCHES - "FUEL ENG 1" SWITCH (L502EF)					Component	ATA:76	
PN:412UZ01G	MOS/MSC	09-May-18	O/C	TSN 0					
SN:N/A	HRS	11576.3		TSN 0					
	AFL	7811		TSN 0					
PROC. REF: AMM 76-10-13-900-801									
76-10-13-900-801-02		REMOVAL / INSTALLATION OF THE ENGINE FUEL SWITCHES - "FUEL ENG 2" SWITCH (R502EF)					Component	ATA:76	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-13-900-801									
760010		NO. 1 ENGINE - FADEC A (FULL AUTHORITY DIGITAL ELECTRONIC CONTROL) UNIT					Component	ATA:76	
PN:64547-2118996-027	MOS/MSC	20-Jan-12	O/C						
SN:ATUA0657	HRS								
	ENC								
PROC. REF: LMM 76-10-05									
760010		NO. 2 ENGINE - FADEC A (FULL AUTHORITY DIGITAL ELECTRONIC CONTROL) UNIT					Component	ATA:76	
PN:4106T48P19	MOS/MSC	27-Feb-13	O/C						
SN:ATUA0449	HRS								
	ENC								
PROC. REF: LMM 76-10-05									
760020		NO. 1 ENGINE - FADEC B (FULL AUTHORITY DIGITAL ELECTRONIC CONTROL) UNIT					Component	ATA:76	
PN:4106T48P19	MOS/MSC	25-Nov-12	O/C						
SN:ATUA0562	HRS	8078							
	ENC	5537							
PROC. REF: LMM 76-10-05, LMM 76-10-05									
760020		NO. 2 ENGINE - FADEC B (FULL AUTHORITY DIGITAL ELECTRONIC CONTROL) UNIT					Component	ATA:76	
PN:4106T48P19	MOS/MSC	19-Dec-08	O/C						
SN:ATUA0807	HRS	5955							
	ENC	4018							
PROC. REF: LMM 76-10-05, LMM 76-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-30-01-900-801-01 REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC (20EA)								Component ATA:77
PN:5010-825-00-14	MOS/MSC	28-Nov-05	O/C					
SN:282	HRS	4011.7						
WC#: 77.040	AFL	2746						
PROC. REF: GENERIC NO REF								
771010 NO. 1 ENGINE - PERMANENT MAGNETIC STATOR								Component ATA:77
PN:3051401-1	MOS/MSC	26-Nov-12	O/C	TSO 0				
SN:991959200159	HRS	8078		TSO 0				
	ENC	5537		TSO 0				
PROC. REF: LMM 77-10-02								
771010 NO. 2 ENGINE - PERMANENT MAGNETIC STATOR								Component ATA:77
PN:3051401-1	MOS/MSC	27-Feb-13	O/C	TSO 0				
SN:001959200193	HRS			TSO 0				
	ENC			TSO 0				
PROC. REF: LMM 77-10-02								
771020 NO. 1 ENGINE - PERMANENT MAGNETIC ROTOR								Component ATA:77
PN:PN	MOS/MSC	01-Aug-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-10-02, LMM 77-10-02								
771020 NO. 2 ENGINE - PERMANENT MAGNETIC ROTOR								Component ATA:77
PN:PN	MOS/MSC	01-Jul-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-10-02, LMM 77-10-02								
772000 ^S NO. 1 ENGINE - DETAILED INSPECTION OF WIRING HARNESSSES FOR CONDITION AND SECURITY								Service ATA:77
	MOS	28-Dec-23						
	HRS	12270.6	400 (+10%)					
	ENC	8203						
PROC. REF: LMM 72-00-00								
772000 ^S NO. 2 ENGINE - DETAILED INSPECTION OF WIRING HARNESSSES FOR CONDITION AND SECURITY								Service ATA:77
	MOS	28-Dec-23						
	HRS	12429.6	400 (+10%)					
	ENC	8337						
PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 77 - ENGINE INDICATING									
773801	NO. 1 ENGINE VIBRATION SENSOR							Component	ATA:77
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
773811	NO. 2 ENGINE VIBRATION SENSOR							Component	ATA:77
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
ATA 78 - EXHAUST									
78-30-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 1 THRUST REVERSER							Service	ATA:78
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 78.010	AFL	9471							
PROC. REF: AMM 78-30-00-210-801									
78-30-00-210-801-02 ^S	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 2 THRUST REVERSER							Service	ATA:78
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8	1600 (+40)						
WC#: 78.010	AFL	9471							
PROC. REF: AMM 78-30-00-210-801									
78-30-00-720-801-01 ^S	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN							Service	ATA:78
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
	AFL	7947	3750						
PROC. REF: AMM 78-30-00-720-801									
78-31-00-220-801-01 ^S	DETAILED INSPECTION OF THE THRUST REVERSER LOCKING SYSTEM - ENGINE 1 THRUST REVERSER							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 78.180	AFL	9008							
PROC. REF: AMM 78-31-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 78 - EXHAUST									
78-31-00-220-801-02 ^S	DETAILED INSPECTION OF THE THRUST REVERSER LOCKING SYSTEM - ENGINE 2 THRUST REVERSER							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
WC#: 78.180	AFL	9008							
PROC. REF: AMM 78-31-00-220-801								PKG:21	
78-31-00-280-801-01 ^S	SPECIAL DETAILED INSPECTION OF THRUST REVERSER DOOR HINGE FITTINGS AND LINK RODS - ENGINE 1 THRUST REVERSER							Service	ATA:78
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 78.170	AFL	7947	3750						
PROC. REF: AMM 78-31-00-280-801								PKG:31	
78-31-00-280-801-02 ^S	SPECIAL DETAILED INSPECTION OF THRUST REVERSER DOOR HINGE FITTINGS AND LINK RODS - ENGINE 2 THRUST REVERSER							Service	ATA:78
	MOS	16-Jul-19	72 (+2m)						
	HRS	11761.3							
WC#: 78.170	AFL	7947	3750						
PROC. REF: AMM 78-31-00-280-801								PKG:31	
78-31-00-640-802-01	GREASING OF THE THRUST REVERSER DOOR HINGE BOLTS							Service	ATA:78
	MOS	06-Dec-23	12 (+1m)		06-Dec-24	06-Jan-25	244 d (+31)		
	HRS	14292.8	400 (+40)	Adj -131.5	14561.3	14601.3	206.9 (+40)		
	AFL	9471							
PROC. REF: AMM 78-31-00-640-802									
78-31-00-640-803-01 ^S	GREASING OF THE LINK ROD HINGE BOLTS AND DOOR LATCH HOOKS - LINK ROD HINGE BOLTS							Service	ATA:78
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
WC#: 78.050	AFL	9471							
PROC. REF: AMM 78-31-00-640-803								PKG:16	
78-31-00-640-803-02 ^S	GREASING OF THE LINK ROD HINGE BOLTS AND DOOR LATCH HOOKS - DOOR LATCH HOOKS							Service	ATA:78
	MOS	27-Dec-23	24 (+1m)						
	HRS	14292.8							
	AFL	9471							
PROC. REF: AMM 78-31-00-640-803								PKG:16	
78-31-13-210-801-01	GENERAL VISUAL INSPECTION OF THE MAIN THRUST REVERSER ACTUATORS - ENGINE 1 TR INBOARD ACTUATOR (L195ER1)							Service	ATA:78
	MOS/MSC	04-Sep-19	O/C						
	HRS	11761.3							
	AFL	7947							
PROC. REF: AMM 78-31-13-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 78 - EXHAUST									
78-31-13-210-801-02	GENERAL VISUAL INSPECTION OF THE MAIN THRUST REVERSER ACTUATORS - ENGINE 1 TR OUTBOARD ACTUATOR (L195ER2)							Service	ATA:78
	MOS/MSC	23-Sep-05	O/C						
	HRS	3830							
	AFL	2634							
PROC. REF: AMM 78-31-13-210-801									
78-31-13-210-801-03	GENERAL VISUAL INSPECTION OF THE MAIN THRUST REVERSER ACTUATORS - ENGINE 2 TR INBOARD ACTUATOR (R195ER1)							Service	ATA:78
	MOS/MSC	30-May-08	O/C						
	HRS	6210.5							
	AFL	4141							
PROC. REF: AMM 78-31-13-210-801									
78-31-13-210-801-04	GENERAL VISUAL INSPECTION OF THE MAIN THRUST REVERSER ACTUATORS - ENGINE 2 TR OUTBOARD ACTUATOR (R195ER2)							Service	ATA:78
	MOS/MSC	03-Jun-05	O/C						
	HRS	3410.8							
	AFL	2366							
PROC. REF: AMM 78-31-13-210-801									
78-31-13-900-801-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 1 TR INBOARD ACTUATOR (L195ER1)							Component	ATA:78
PN:F2MA581717-015	MOS/MSC	04-Sep-19	O/C		TSO 0				
SN:6207	HRS	11761.3			TSO 0				
WC#: 78.110	AFL	7947			TSO 0				
PROC. REF: AMM 78-31-13-900-801									
78-31-13-900-801-02	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 1 TR OUTBOARD ACTUATOR (L195ER2)							Component	ATA:78
PN:F2MA581717-015	MOS/MSC	30-May-08	O/C		TSN 0				
SN:5497	HRS	6210.5			TSN 0				
WC#: 78.110	AFL	4141			TSN 0				
PROC. REF: AMM 78-31-13-900-801									
78-31-13-900-801-03	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 2 TR INBOARD ACTUATOR (R195ER1)							Component	ATA:78
PN:F2MA581717-015	MOS/MSC	23-Sep-05	O/C		TSR 0				
SN:5482	HRS	3830			TSR 0				
WC#: 78.120	AFL	2634			TSR 0				
PROC. REF: AMM 78-31-13-900-801									
78-31-13-900-801-04	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 2 TR OUTBOARD ACTUATOR (R195ER2)							Component	ATA:78
PN:F2MA581717-011	MOS/MSC	03-Jun-05	O/C		TSR 0				
SN:5196	HRS	3410.8			TSR 0				
WC#: 78.120	AFL	2366			TSR 0				
PROC. REF: AMM 78-31-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-31-13-960-801-01 DISCARD OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 1 TR INBOARD ACTUATOR (L195ER1) Service ATA:78								
PN:F2MA581717-015	MOS/MSC	04-Sep-19	O/C					
SN:6207	HRS	11761.3						
WC#: 78.110	AFL	7947						
PROC. REF: AMM 78-31-13-960-801								
78-31-13-960-801-02 DISCARD OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 1 TR OUTBOARD ACTUATOR (L195ER2) Service ATA:78								
PN:F2MA581717-015	MOS/MSC	30-May-08	O/C					
SN:5497	HRS	6210.5						
WC#: 78.110	AFL	4141						
PROC. REF: AMM 78-31-13-960-801								
78-31-13-960-801-03 DISCARD OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 2 TR INBOARD ACTUATOR (R195ER1) Service ATA:78								
PN:F2MA581717-015	MOS/MSC	23-Sep-05	O/C					
SN:5482	HRS	3830						
WC#: 78.120	AFL	2634						
PROC. REF: AMM 78-31-13-960-801								
78-31-13-960-801-04 DISCARD OF THE THRUST REVERSER DOOR ACTUATORS - ENGINE 2 TR OUTBOARD ACTUATOR (R195ER2) Service ATA:78								
PN:F2MA581717-011	MOS/MSC	03-Jun-05	O/C					
SN:5196	HRS	0						
WC#: 78.120	AFL	2366						
PROC. REF: AMM 78-31-13-960-801								
78-32-00-760-801-01^S TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - RELAY PCB (413JE) Service ATA:78								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 78-32-00-760-801								
78-32-00-760-801-01A TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - RELAY PCB (MANDATORY 5-40) Service ATA:78								
	MOS	05-May-22						MANDATORY 5-40
	HRS	13592.3	1800		15392.3		1037.9	
	AFL	9008						
PROC. REF: AMM 78-32-00-760-801								
78-32-00-760-801-02^S TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - PCB (414JE) Service ATA:78								
	MOS	05-May-22						
	HRS	13592.3	1600 (+40)					
	AFL	9008						
PROC. REF: AMM 78-32-00-760-801								

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 78 - EXHAUST									
78-32-00-760-801-02A	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - PCB (MANDATORY 5-40)							Service	ATA:78
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	1800		15392.3		1037.9		
	AFL	9008							
PROC. REF: AMM 78-32-00-760-801									
78-32-00-760-801-03 ^S	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - LH TRCU (L40ER)							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 78-32-00-760-801									
78-32-00-760-801-03A	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - LH TRCU (MANDATORY 5-40)							Service	ATA:78
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	2670		16262.3		1907.9		
	AFL	9008							
PROC. REF: AMM 78-32-00-760-801									
78-32-00-760-801-04 ^S	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - RH TRCU (R40ER)							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 78-32-00-760-801									
78-32-00-760-801-04A	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT - RH TRCU (MANDATORY 5-40)							Service	ATA:78
	MOS	05-May-22						MANDATORY 5-40	
	HRS	13592.3	2670		16262.3		1907.9		
	AFL	9008							
PROC. REF: AMM 78-32-00-760-801									
78-32-09-780-801-01 ^S	CHECK OF THE THRUST REVERSER ACCUMULATOR CAPACITY - LH TR ACCUMULATOR (L120ER)							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 78-32-09-780-801									
78-32-09-780-801-02 ^S	CHECK OF THE THRUST REVERSER ACCUMULATOR CAPACITY - RH TR ACCUMULATOR (R120ER)							Service	ATA:78
	MOS	05-May-22							
	HRS	13592.3	1600 (+40)						
	AFL	9008							
PROC. REF: AMM 78-32-09-780-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 78 - EXHAUST									
78-32-09-900-801-01		REMOVAL / INSTALLATION OF THE THRUST REVERSER HYDRAULIC ACCUMULATOR - LH TR ACCUMULATOR (L120ER)					Component	ATA:78	
PN:60967-1	MOS/MSC	17-Dec-08	O/C						
SN:EFS1623	HRS	6549.1							
WC#: 78.150	AFL	4386							
PROC. REF: AMM 78-32-09-900-801									
78-32-09-900-801-02		REMOVAL / INSTALLATION OF THE THRUST REVERSER HYDRAULIC ACCUMULATOR - RH TR ACCUMULATOR (R120ER)					Component	ATA:78	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.150	AFL	0		TSN 0					
PROC. REF: AMM 78-32-09-900-801									
78-32-45-900-801-01		REMOVAL / INSTALLATION OF THE THRUST REVERSER CONTROL UNIT (TRCU) - LH TRCU (L40ER)					Component	ATA:78	
PN:DS232-67	MOS/MSC	12-Sep-15	O/C	TSR 0					
SN:295	HRS	10492.7		TSR 0					
	AFL	7091		TSR 0					
PROC. REF: AMM 78-32-45-900-801									
78-32-45-900-801-02		REMOVAL / INSTALLATION OF THE THRUST REVERSER CONTROL UNIT (TRCU) - RH TRCU (R40ER)					Component	ATA:78	
PN:DS232-67	MOS/MSC	30-Aug-21	O/C						
SN:304	HRS	13039.3							
	AFL	8686							
PROC. REF: AMM 78-32-45-900-801									
783811		LH INBOARD THRUST REVERSER LATCH ACTUATOR ASSEMBLY					Component	ATA:78	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.130	AFL	0		TSN 0					
PROC. REF: AMM 78-32-25-900-801									
783812		RH INBOARD THRUST REVERSER LATCH ACTUATOR ASSEMBLY					Component	ATA:78	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.140	AFL	0		TSN 0					
PROC. REF: AMM 78-32-25-900-801									
783813		LH OUTBOARD THRUST REVERSER LATCH ACTUATOR ASSEMBLY					Component	ATA:78	
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.130	AFL	0		TSN 0					
PROC. REF: AMM 78-32-25-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 78 - EXHAUST									
783814	RH OUTBOARD THRUST REVERSER LATCH ACTUATOR ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.140	AFL	0		TSN 0					
PROC. REF: AMM 78-32-25-900-801									
783831	LH THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:F2MA581792007	MOS/MSC	02-Aug-21	O/C						
SN:A30040130	HRS	12985							
WC#: 78.180	AFL	8657							
PROC. REF: GENERIC NO REF									
783832	RH THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:F2MA581792007	MOS/MSC	02-Aug-21	O/C						
SN:A30040340	HRS	12985							
WC#: 78.180	AFL	8657							
PROC. REF: GENERIC NO REF									
ATA 79 - OIL									
79-30-01-900-801-01	REMOVAL / INSTALLATION / CALIBRATION OF ENGINE OIL LEVEL GAUGES - LH ENGINE OIL GAUGE (L20EL)							Component	ATA:79
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.070	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01-900-801									
79-30-01-900-801-02	REMOVAL / INSTALLATION / CALIBRATION OF ENGINE OIL LEVEL GAUGES - RH ENGINE OIL GAUGE (R20EL)							Component	ATA:79
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.070	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01-900-801									
790010 ^S	NO. 1 ENGINE - DISCARD ENGINE OIL							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12270.6	600 (+50)						
	ENC	8203							
PROC. REF: LMM 72-00-00									
								PKG:2 ,5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
790010 ^S	NO. 2 ENGINE - DISCARD ENGINE OIL							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12429.6	600 (+50)						
	ENC	8337							
					PROC. REF: LMM 72-00-00			PKG:2 ,5	
790020 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF MAGNETIC CHIP DETECTOR FOR CONDITION AND SECURITY							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12270.6	600 (+50)						
	ENC	8203							
					PROC. REF: LMM 79-30-02, LMM 79-30-02, LMM 72-00-00			PKG:2 ,5	
790020 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF MAGNETIC CHIP DETECTOR FOR CONDITION AND SECURITY							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12429.6	600 (+50)						
	ENC	8337							
					PROC. REF: LMM 79-30-02, LMM 79-30-02, LMM 72-00-00			PKG:2 ,5	
790030 ^S	NO. 1 ENGINE - VISUALLY CHECK OIL LEVEL							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12270.6	200 (+10%)						
	ENC	8203							
					PROC. REF: GENERIC NO REF, LMM 72-00-00			PKG:1 ,2 ,5,3 ,4 ,6,7	
790030 ^S	NO. 2 ENGINE - VISUALLY CHECK OIL LEVEL							Service	ATA:79
	MOS	28-Dec-23							
	HRS	12429.6	200 (+10%)						
	ENC	8337							
					PROC. REF: GENERIC NO REF, LMM 72-00-00			PKG:1 ,2 ,5,3 ,4 ,6,7	
792010	NO. 1 ENGINE - OIL SURFACE TYPE COOLER							Component	ATA:79
PN:160450-2	MOS/MSC	26-Nov-12	O/C		TSR 0				
SN:49-361	HRS	8078			TSR 0				
	ENC	5537			TSR 0				
					PROC. REF: LMM 79-20-08, LMM 79-20-08				
792010	NO. 2 ENGINE - OIL SURFACE TYPE COOLER							Component	ATA:79
PN:160450-2	MOS/MSC	27-Feb-13	O/C		TSR 0				
SN:45-152	HRS				TSR 0				
	ENC				TSR 0				
					PROC. REF: LMM 79-20-08, LMM 79-20-08				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
792020	NO. 1 ENGINE - OIL FILTER AND REGULATOR ADAPTER							Component	ATA:79
PN:3050603-1	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:0006451C0479	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
792020	NO. 2 ENGINE - OIL FILTER AND REGULATOR ADAPTER							Component	ATA:79
PN:3050603-1	MOS/MSC	27-Feb-13	O/C	TSR 0					
SN:060645105628	HRS			TSR 0					
	ENC			TSR 0					
792030	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE							Component	ATA:79
PN:160448-2	MOS/MSC	26-Nov-12	O/C	TSR 0					
SN:18-280	HRS	8078		TSR 0					
	ENC	5537		TSR 0					
	PROC. REF: LMM 79-20-08								
792030	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE							Component	ATA:79
PN:160448-2	MOS/MSC	27-Feb-13	O/C	TSR 0					
SN:487	HRS			TSR 0					
	ENC			TSR 0					
	PROC. REF: LMM 79-20-08								
792040	NO. 1 ENGINE - OIL PUMP							Component	ATA:79
PN:3050635-3	MOS/MSC	26-Nov-12	O/C	TSO 0					
SN:98-14057-110	HRS	8078		TSO 0					
	ENC	5537		TSO 0					
	PROC. REF: LMM 79-20-04, LMM 79-20-04								
792040	NO. 2 ENGINE - OIL PUMP							Component	ATA:79
PN:3050635-3	MOS/MSC	27-Feb-13	O/C	TSO 0					
SN:96-14057-118	HRS			TSO 0					
	ENC			TSO 0					
	PROC. REF: LMM 79-20-04, LMM 79-20-04								
793010	NO. 1 ENGINE - DISCARD OIL FILTER ELEMENT							Service	ATA:79
	MOS	28-Dec-23						SERVICE LIFE LIMIT	
	HRS	12270.6	300 (+10%)		(12570.6) 14592.8	12600.6	238.4 (+30)		
	ENC	8203							
	PROC. REF: LMM 79-20-01, LMM 79-20-01								
	PKG:1 ,2 ,5,3 ,4 ,6,7								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
793010	NO. 2 ENGINE - DISCARD OIL FILTER ELEMENT							Service	ATA:79
	MOS	28-Dec-23						SERVICE LIFE LIMIT	
	HRS	12429.6	300 (+10%)		(12729.6) 14592.7	12759.6	238.3 (+30)		
	ENC	8337							
PROC. REF: LMM 79-20-01, LMM 79-20-01								PKG:1 ,2 ,5,3 ,4 ,6,7	
793030	NO. 1 ENGINE - MAGNETIC CHIP DETECTOR							Component	ATA:79
PN:3051356-1	MOS/MSC	22-Apr-13	O/C	TSN 44					
SN:082017900107	HRS	8087.9		TSN 1721.6					
	ENC	5541		TSN 1179					
PROC. REF: GENERIC NO REF									
793030	NO. 2 ENGINE - MAGNETIC CHIP DETECTOR							Component	ATA:79
PN:3051356-1	MOS/MSC	14-Apr-17	O/C						
SN:UNKNOWN	HRS	10154.5							
	ENC	6931							
PROC. REF: GENERIC NO REF									
ATA 80 - STARTING									
80-10-05-610-801-01 ^S	ENGINE PNEUMATIC STARTER OIL CHANGE - LH ENGINE PNEUMATIC STARTER (L10EX)							Service	ATA:80
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
WC#: 80.010	AFL	9471							
PROC. REF: AMM 80-10-05-610-801								PKG:5	
80-10-05-610-801-02 ^S	ENGINE PNEUMATIC STARTER OIL CHANGE - RH ENGINE PNEUMATIC STARTER (R10EX)							Service	ATA:80
	MOS	27-Dec-23	12 (+1m)						
	HRS	14292.8	800 (+40)						
WC#: 80.010	AFL	9471							
PROC. REF: AMM 80-10-05-610-801								PKG:5	
80-10-05-700-801-01	OIL LEVEL CHECK OF THE ENGINE PNEUMATIC STARTER - LH ENGINE PNEUMATIC STARTER (L10EX)							Service	ATA:80
	MOS	13-Nov-23							
	HRS	14262.6	200 (+10%)		14462.6	14482.6	108.2 (+20)		
	AFL	9450							
PROC. REF: AMM 80-10-05-700-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 2000 Serial: 139 RegNo: N26NJ HRS: 14354.4 AFL: 9502 As Of: 16-Mar-2024

06-Apr-2024 11:18 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 80 - STARTING									
80-10-05-700-801-02	OIL LEVEL CHECK OF THE ENGINE PNEUMATIC STARTER - RH ENGINE PNEUMATIC STARTER (R10EX)							Service	ATA:80
	MOS	13-Nov-23							
	HRS	14262.6	200 (+10%)		14462.6	14482.6	108.2 (+20)		
	AFL	9450							
PROC. REF: AMM 80-10-05-700-801									
80-10-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC STARTERS - LH ENGINE PNEUMATIC STARTER (L10EX)							Component	ATA:80
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 80.010	AFL	0		TSN 0					
PROC. REF: AMM 80-10-05-900-801									
80-10-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC STARTERS - RH ENGINE PNEUMATIC STARTER (R10EX)							Component	ATA:80
PN:3505656-6	MOS/MSC	11-May-07	O/C	TSO 0					
SN:248	HRS	5260.1		TSO 0					
WC#: 80.010	AFL	3550		TSO 0					
PROC. REF: AMM 80-10-05-900-801									
80-10-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC STARTER CONTROL VALVES - LH ENGINE STARTING VALVE (L20EX)							Component	ATA:80
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 80.020	AFL	0		TSN 0					
PROC. REF: AMM 80-10-13-900-801									
80-10-13-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC STARTER CONTROL VALVES - RH ENGINE STARTING VALVE (R20EX)							Component	ATA:80
PN:PN	MOS/MSC	01-Mar-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 80.020	AFL	0		TSN 0					
PROC. REF: AMM 80-10-13-900-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task