

Phone: +1-912-298-1300
Fax: 1-912-963-0265/1-800-944-1775
Analyst: Ralph Moose

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		GULFSTREAM AEROSPACE CORPORATION G550	5124	08 Dec 2023	6181.2	1568
Engine	1	ROLLS-ROYCE DERBY PLC BR700-710C4- 11 (G550)	15351	08 Dec 2023	6181.2	1568
Engine	2	ROLLS-ROYCE DERBY PLC BR700-710C4- 11 (G550)	15350	08 Dec 2023	6181.2	1568
APU		HONEYWELL RE220 (G550)	P-447	08 Dec 2023	4190.5	0

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

01 - Watch List											
010010	Service Center Maintenance Induction Checklist	HRS		130.8				6050.4			0
		AFL		29				1539			0
		MOS		10.1				27 Feb 2023			
		MSC					O/C				
Airframe											

05 - Time Limits/Maintenance Checks											
055007	Hard or Overweight Landing - Inspection	HRS		6181.2				0			0
		AFL		1568				0			0
		MOS		208.3				21 Aug 2006			
		MSC					O/C				
Airframe											
055019	Aircraft Residual Deicing / Anti-Icing Fluid - Inspection / Cleaning	HRS		6181.2				0			0
		AFL		1568				0			0
		MOS		208.3				21 Aug 2006			
		MSC					O/C				
Airframe											

08 - Leveling and Weighing											
----------------------------	--	--	--	--	--	--	--	--	--	--	--

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
080001	Weight & Balance Aircraft		HRS		347.1			5834.1			0
			AFL		75			1493			0
			MOS		19.1		36	27 May 2022	27 May 2025	27 Jun 2025	
Airframe			[MOS: +1m/-1m]								
11 - Placards and Markings											
111111	Exterior Strip and Paint		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC O/C								
12 - Servicing											
121010	Pre-Postflight Inspection		HRS		648.85			5532.35			0
			AFL		141			1427			0
			MOS		37.7			06 Nov 2020			
Airframe			MSC O/C								
121400	No. 1 Engine - AIR Turbine Starter Oil - Change		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
Engine			[HRS: +50/-50]								
Notes: PN: 3505934-8 SN: 019-29CD.											
121400 (121401)	No. 2 Engine - AIR Turbine Starter Oil - Change		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			ENC		29			1539			0
			MOS		8.6			09 Apr 2023			
Engine			[HRS: +50/-50]								
Notes: PN: 3505934-8 SN: 0606-17 13.											
121500	Hydraulic System Reservoir (Left) - Servicing		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3			21 Apr 2021			
Airframe			MSC O/C								
121501	Hydraulic System Reservoir (Right) - Servicing		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3			21 Apr 2021			
Airframe			MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
123300	Nose Tire Assembly - Servicing		HRS		347.8			5833.4			0
			AFL		77			1491			0
			MOS		19.1			25 May 2022			
	Airframe		MSC					O/C			
123301	Main Tire Assembly - Servicing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.8			03 May 2023			
	Airframe		MSC					O/C			
20 - Standard Practices - Airframe											
200001	Preflight - Inspection		HRS		648.85			5532.35			0
			AFL		141			1427			0
			MOS		37.7			06 Nov 2020			
	Airframe		MSC					O/C			
200091	Pre Maintenance Checklist		HRS		0			6181.2			0
			AFL		0			1568			0
			MOS		.5			14 Dec 2023			
	Airframe		MSC					O/C			
200092	Post Maintenance Checklist		HRS		0			6181.2			0
			AFL		0			1568			0
			MOS		.4			18 Dec 2023			
	Airframe		MSC					O/C			
200093	Post Maintenance - Servicing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
	Airframe		MSC					O/C			
21 - AIR Conditioning											
210001	AIR Conditioning System - Functional Check		HRS		57.2			6124			0
			AFL		10			1558			0
			MOS		3.3			21 Sep 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212101	Cabin Silencer (Upper) - Removal / Installation		HRS		6181.2			0			0
	1159AC50153-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
212102	Cockpit Silencer - Removal / Installation		HRS		6181.2			0			0
	1159AC50153-7	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
212103	Pack Inlet Valve (Left) - Removal / Installation		HRS		6167			14.2			0
	396610-6	951	AFL		1560			8			0
			MOS		203.3			20 Jan 2007			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
212104	Pack Inlet Valve (Right) - Removal / Installation		HRS		6167			14.2			0
	396610-6	950	AFL		1560			8			0
			MOS		203.3			20 Jan 2007			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
212105	Cold AIR Manifold - Removal / Installation		HRS		6181.2			0			0
	1159AC50103-27	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STANLEY AVIATION CORPORATION
	Airframe		MSC					O/C			
212106	Hot AIR Manifold - Removal / Installation		HRS		6181.2			0			0
	1159AC50103-27	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STANLEY AVIATION CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212110	Pack Inlet Valve (Left) - Inflight Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
Notes: -6 VALVES INSTALLED											
212112	Pack Inlet Valve (Right) - Inflight Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
Notes: -6 VALVES INSTALLED											
212201	Ram AIR Check Valve - Removal / Installation		HRS		1245.7			4935.5			0
	3202776-1	1039	AFL		296			1272			0
			MOS		66.2			22 Jun 2018			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
212202	Ram AIR Check Valve - Detailed Inspection		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
			AFL		296			1272			0
			MOS		66.2			22 Jun 2018			
	Airframe		[HRS: +50/-50]								
Notes: PN: 3202776-1 SN: <NONE>.											
212204	Ram AIR Exhaust (Left) - Removal / Installation		HRS		6181.2			0			0
	3202776-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
212205	Ram AIR Exhaust (Right) - Removal / Installation		HRS		6181.2			0			0
	3202776-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212401	Cockpit Airflow Control Valve - Removal / Installation		HRS		6181.2			0			0
	BYLB-52588	324	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			SMITHS AEROSPACE, INC.
	Airframe		MSC					O/C			
212502	Electronic Equipment Rack Cooling FANS (Right) - Removal / Installation		HRS		6181.2			0			0
	011587502	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AMETEK
	Airframe		MSC					O/C			
212509	Personal Services Unit Cooling Fan - Removal / Installation		HRS		6181.2			0			0
	011990500	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AMETEK
	Airframe		MSC					O/C			
212510	Aft Equipment Cooling Fan - Removal / Installation		HRS		6181.2			0			0
	011586501	106034277	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AMETEK
	Airframe		MSC					O/C			
212511	CRT Display FANS/Filter-Clean		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
212512	Fan , Aux Avionics Cooling		HRS		6181.2			0			0
	8124K	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HYDRA- ELECTRIC COMPANY
	Airframe		MSC					O/C			
212513	Electronic Equipment Rack Cooling FANS (Left) - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212514	Electronic Equipment Rack Cooling FANS (Right) - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
212517	Detector, Aft Eer Low Speed		HRS		6181.2			0			0
	035640501	E06134245	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AMETEK
			MSC					O/C			
Airframe											
212530	Fan, Pedestalcooling -OPS Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
212531	Radio Rack Cooling Fan (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
212532	Radio Rack Cooling Fan (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
213001	Cabin Pressurization Control - System Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
213006	Cabin Pressure Controller - Removal / Installation		HRS		6181.2			0			0
	2119146-4	14-B0040	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
			MSC					O/C			
Airframe											
213007	Cabin Pressurization Selector Panel - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2118936-1	93-B0179	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213008	Cabin Pressurization Control Panel - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2119144-X	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								
Airframe											
213009	Cabin Pressurization Controller - System Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
213011	Outflow Valve - Removal / Installation		HRS		6181.2			0			0
	103878-1	66-A0216	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC								
Airframe											
213015	Pressure Relief Valve - Removal / Installation		HRS		6181.2			0			0
	103832-2	56-C0250	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								
Airframe											
213101	Outflow Valve - Cleaning / Painting		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
213301	Decompression Advisory System - Functional Test		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			AFL		150			1418			0
			MOS		44.4			16 Apr 2020			
			[HRS: +50/-50]								
Airframe											
213302	Differential Pressure Limiter Valve (Primary) - Functional Check		HRS		1476.7		2500	4704.5	7204.5	7254.5	0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213303	Differential Pressure Limiter Valve (Secondary) -		HRS		1476.7		2500	4704.5	7204.5	7254.5	0
	Functional Check		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		[HRS: +50/-50]								
213304	Differential Pressure Limiter Valve (Negative) - Functional		HRS		1476.7		2500	4704.5	7204.5	7254.5	0
	Check		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		[HRS: +50/-50]								
213305	Baggage Compartment Shut-Off Valve and Reset Switch -		HRS		1476.7		2500	4704.5	7204.5	7254.5	0
	Operational Test		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		[HRS: +50/-50]								
213306	Baggage Compartment Decompression Warning Circuit -		HRS		6181.2			0			0
	Operational Test		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
			[HRS: +50/-50]								
213307	Baggage Compartment Ventilation Check Valve - Detailed		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
	Inspection		AFL		296			1272			0
			MOS		66.1			25 Jun 2018			
	Airframe		[HRS: +50/-50]								
213308	Pressure Relief Valve Remote AIR Filter - Detailed		HRS		1476.7		2500	4704.5	7204.5	7254.5	0
	Inspection		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		[HRS: +50/-50]								
213309	Remote AIR Filter - Removal / Installation		HRS		3856.1			2325.1			0
	147240-1	NSN	AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC				O/C				A.S.A.P. TECHNOLOGIES INC.
			[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213310	Baggage Compartment Decompression Switch - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P20M-H23	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PRECISION SENSORS INC
			MSC								
Airframe											
213311	Baggage Compartment Ventilation Check Valve - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3202776-1	1032	MOS		66.1			25 Jun 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
213312	Pressure Relief Valve - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
213313	Baggage Compartment Shutoff Valve Reset Switch - Removal Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	MS24523-30	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELECTRO ENTERPRISES INC
			MSC								
Airframe											
213314	Baggage Compartment Shutoff Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	632-758	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
213401	Cabin Pressure Indicator (No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	789537-1-2	0537	MOS		208.3			21 Aug 2006			INTERTECHNIQUE
			MSC								E
Airframe											
213402	Cabin Pressure Indicator (No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	40123486	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213403	Cabin Pressure Acquisition Module - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	789538-1-2	0455	MOS		208.3			21 Aug 2006			INTERTECHNIQU
			MSC					O/C			E
Airframe											
213404	Indicator, Cabin Pressure #3		HRS		6181.2			0			0
	720-15900-105		AFL		1568			0			0
		SN-UNKNOWN	MOS		208.3			21 Aug 2006			KOLLSMAN, INC.
			MSC					O/C			
Airframe											
213405	Valve, S/O Cbn Press Indicator		HRS		6181.2			0			0
	02C74T01		AFL		1568			0			0
		SN-UNKNOWN	MOS		208.3			21 Aug 2006			NEWARK
			MSC					O/C			ELECTRONICS
Airframe											
215101	AIR Conditioning Controller (Left) - Removal /		HRS		57.2			6124			0
	Installation		AFL		10			1558			0
	1151582-6	010C-1049	MOS		3.3			21 Sep 2023			
			MSC					O/C			
Airframe											
215102	AIR Conditioning Controller (Right) - Removal /		HRS		57.2			6124			0
	Installation		AFL		10			1558			0
	1151582-6	1151582-02340	MOS		3.3			21 Sep 2023			
			MSC					O/C			
Airframe											
215103	Pack Outlet Temperature Sensor (Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1151834-1	04048	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			ASCA INC.
Airframe											
215104	Pack Outlet Temperature Sensor (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1151834-1	04051	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			ASCA INC.
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215105	Compressor Outlet Temperature Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1150124-2	1150124-06313	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC				O/C				ASCA INC.
Airframe											
215106	Compressor Outlet Temperature Sensor (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1150124-2	1150124-06314	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC				O/C				ASCA INC.
Airframe											
215201	AIR Conditioning Pack (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2215080-3	882	MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
215202	AIR Conditioning Pack (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2215080-3	883	MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
215203	Primary / Secondary Heat Exchanger (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341140-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GENERAL
			MSC				O/C				DYNAMICS
Airframe											
215204	Primary / Secondary Heat Exchanger (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341140-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GENERAL
			MSC				O/C				DYNAMICS
Airframe											
215205	AIR Cycle Machine (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2205590-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC				O/C				ENGINES
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215206	AIR Cycle Machine (Right) - Removal / Installation		HRS		6181.2			0			0
	2205590-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC								ENGINES SYSTEMS & SERVICE
215207	Low Limit Valve (Left) - Removal / Installation		HRS	TSN:10	6171.2			10			0
	3291284-1	885	AFL	TSN:7	1561			7			0
			MOS		203.4			16 Jan 2007			GENERAL
	Airframe		MSC								DYNAMICS AVIATIONS SERVICES
215208	Low Limit Valve (Right) - Removal / Installation		HRS	TSN:10	6171.2			10			0
	3291284-1	884	AFL	TSN:7	1561			7			0
			MOS		203.4			16 Jan 2007			GENERAL
	Airframe		MSC								DYNAMICS AVIATIONS SERVICES
215213	Turbine Inlet Temperature Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
	1150124-2	06375	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC								ASCA INC.
215214	Turbine Inlet Temperature Sensor (Right) - Removal / Installation		HRS		6181.2			0			0
	1150124-2	06317	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC								ASCA INC.
215215	Reheater / Condenser (Left) - Removal / Installation		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL
	Airframe		MSC								DYNAMICS AVIATIONS SERVICES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215216	Reheater / Condenser (Right) - Removal / Installation		HRS		6181.2			0			0
	2341142-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
215217	Servo Pressure Regulator (Left) - Removal / Installation		HRS		6181.2			0			0
	3215634-1	2031	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
215218	Servo Pressure Regulator (Right) - Removal / Installation		HRS		6181.2			0			0
	3215634-1	2032	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
215219	Water Extractor (Left) - Removal / Installation		HRS		6181.2			0			0
	2341144-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
215220	Water Extractor (Right) - Removal / Installation		HRS		6181.2			0			0
	2341144-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215221	Compressor Bypass Check Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3202782-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
215222	Compressor Bypass Check Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3202782-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
215223	Water Extractor Aspirator Line and Nozzle (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
215224	Water Extractor Aspirator Line and Nozzle (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
215225	Strainer, L Ecs H2O Extr-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
215226	Strainer, R Ecs H2O Extr-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
215227	Primary / Secondary Heat Exchanger (Left) - Detailed Inspection		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215228	Primary / Secondary Heat Exchanger (Right) - Detailed Inspection		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC							O/C	
Airframe											
215229	Primary / Secondary Heat Exchangers (Left Secondary, Sb-2215080-21-2768) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341682-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC							O/C	
Airframe											
215230	Primary / Secondary Heat Exchangers (Right, Secondary, Sb-2215080-21-2768) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341682-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC							O/C	
Airframe											
215231	Primary / Secondary Heat Exchangers (Left, Primary, Sb-2215080-21-2768) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341680-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
215232	Primary / Secondary Heat Exchangers (Right, Primary, Sb-2215080-21-2768) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2341680-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
215233	Honeywell Sb 2215080-21-2768		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
215234	Rhs Ecs Distribution Duct		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215237	Water Extractor Strainer (Left) - Removal / Installation		HRS		6181.2			0			0
	1159ACM50843-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
215240	Water Extractor Strainer (Right) - Removal / Installation		HRS		6181.2			0			0
	1159ACM50843-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
215301	Valve, Bag Comp Cooling Supply		HRS		6181.2			0			0
	FYLB52635	331	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
216101	Zone Trim AIR Valve (Cockpit) - Removal / Installation		HRS		1509			4672.2			0
	3291268-4	461	AFL		359			1209			0
			MOS		77.7			06 Jul 2017			GULFSTREAM -
	Airframe		MSC					O/C			LGB
216102	Zone Trim AIR Valve (Forward Cabin) - Removal / Installation		HRS	TSN:618.9	665.8			5515.4			0
			AFL	TSN:156	150			1418			0
	3291268-4	1609	MOS	TSN:27	43.2			23 May 2020			N/A
	Airframe		MSC					O/C			
216103	Zone Trim AIR Valve (Aft Cabin) - Removal / Installation		HRS		665.8			5515.4			0
	3291268-4	1441	AFL		150			1418			0
			MOS		43			28 May 2020			
	Airframe		MSC					O/C			
216104	Overheat Thermostats Zone Supply (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	129740-1-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ENGINES SYSTEMS & SERVICE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216105	Overheat Thermostats Zone Supply (Forward Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	129740-1-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ENGINES SYSTEMS & SERVICE
216106	Overheat Thermostats Zone Supply (Aft Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	129740-1-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ENGINES SYSTEMS & SERVICE
216107	AIR Supply / Zone Trim AIR Check Valve (Left Cold AIR Manifold) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
216108	AIR Supply / Zone Trim AIR Check Valve (Right Cold AIR Manifold) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
216109	Temperature Control Rheostat (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151502-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ASCA INC.
216113	AIR Supply and Zone Trim AIR Check Valves (Left Hot AIR Manifold) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3202760-1	1007	MOS		65.5			12 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			ENGINES SYSTEMS & SERVICE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216114	AIR Supply and Zone Trim AIR Check Valve (Right Hot AIR Manifold) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3202760-1	1006	MOS		65.5			12 Jul 2018			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
216115	AIR Supply and Zone Trim AIR Check Valve (Left Cold AIR Manifold) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3202758-1	849	MOS		65.5			12 Jul 2018			CRISSAIR INC
			MSC								
Airframe											
216116	AIR Supply and Zone Trim AIR Check Valve (Right Cold AIR Manifold) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3202758-1	848	MOS		65.5			12 Jul 2018			CRISSAIR INC
			MSC								
Airframe											
216117	AIR Supply / Zone Trim AIR Check Valve (Left Hot AIR Manifold) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
Airframe											
216118	AIR Supply / Zone Trim AIR Check Valve (Right Hot AIR Manifold) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
Airframe											
216119	Low Speed Warning Detector (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	035640501	SN-UNKNOWN	MOS		208.3			21 Aug 2006			AMETEK
			MSC								
Airframe											
216120	Low Speed Warning Detector (Forward Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	035640501	E05503083	MOS		208.3			21 Aug 2006			AMETEK
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216121	Low Speed Warning Detector (Aft Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	035640501	E05332092	MOS		208.3			21 Aug 2006			AMETEK
			MSC								O/C
Airframe											
216122	Detector, L Pdb Low Speed		HRS		6181.2			0			0
			AFL		1568			0			0
	035850500	SN-UNKNOWN	MOS		208.3			21 Aug 2006			AMETEK
			MSC								O/C
Airframe											
216123	Detector, Bagg Compt Low Speed		HRS		6181.2			0			0
			AFL		1568			0			0
	035850500	SN-UNKNOWN	MOS		208.3			21 Aug 2006			AMETEK
			MSC								O/C
Airframe											
216201	Cabin / Cockpit Temperature Indication - Functional Test		HRS		69.6			6111.6			0
			AFL		14			1554			0
			MOS		3.8			04 Sep 2023			
			MSC								O/C
Airframe											
216401	Cabin / Cockpit Temperature Indicator (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	789575-1	0504	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								O/C
Airframe											
216402	Cabin / Cockpit Temperature Indicator (Forward Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	789575-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								O/C
Airframe											
216403	Cabin / Cockpit Temperature Indicator (Aft Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	789575-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								O/C
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216404	Zone Supply Temperature Sensor (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								ASCA INC.
Airframe											
216405	Zone Supply Temperature Sensor (Forward Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	1151834-04023	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								ASCA INC.
Airframe											
216406	Zone Supply Temperature Sensor (Aft Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	1151834-04021	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								ASCA INC.
Airframe											
216407	Zone Temperature Sensor (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								ASCA INC.
Airframe											
216408	Zone Temperature Sensor (Fwd Cabin) - Removal / Installation		HRS		69.6			6111.6			0
			AFL		14			1554			0
	1151834-1	1151834-04021	MOS		3.8			04 Sep 2023			
			MSC								
Airframe											
216409	Zone Temperature Sensor (Aft Cabin) - Removal / Installation		HRS		69.6			6111.6			0
			AFL		14			1554			0
	1151834-1	1151834-04023	MOS		3.8			04 Sep 2023			
			MSC								
Airframe											
216410	Zone Temperature Sensor Fan (Cockpit) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	011590500	SN-UNKNOWN	MOS		208.3			21 Aug 2006			MPC PRODUCTS
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216411	Zone Temperature Sensor Fan (Fwd Cabin) - Removal / Installation		HRS		5164.7			1016.5			0
			AFL		1254			314			0
	011590500	105447825	MOS		176.2			23 Apr 2009			MPC PRODUCTS
			MSC								
Airframe											
216412	Zone Temperature Sensor Fan (Aft Cabin) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	011590500	SN-UNKNOWN	MOS		208.3			21 Aug 2006			MPC PRODUCTS
			MSC								
Airframe											
217001	Ozone Converter (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAC501-1	6764	MOS		208.3			21 Aug 2006			COX & COMPANY INC
			MSC								
Airframe											
217002	Ozone Converter (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAC501-1	6763	MOS		208.3			21 Aug 2006			COX & COMPANY INC
			MSC								
Airframe											
217003	Ozone Converter (Left) - Functional Test		HRS		6181.2		10000	0	10000	10050	0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe	[HRS: +50/-50]										
Notes: PN: 1159SCAC501-1 SN: 6764.											
217004	Ozone Converter (Right) - Functional Test		HRS		6181.2		10000	0	10000	10050	0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe	[HRS: +50/-50]										
Notes: PN: 1159SCAC501-1 SN: 6763.											
22 - Auto Flight											
221001	Flight Guidance Panel - Removal / Installation		HRS		44.7			6136.5			0
			AFL		7			1561			0
	7021852-901	09010765	MOS		2.6			10 Oct 2023			N/A
			MSC								
Airframe	O/C										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
221002	Autopilot - Operational Test		HRS		934.6			5246.6			0
			AFL		222			1346			0
			MOS		55.2			23 May 2019			
	Airframe		MSC					O/C			
Notes: SWAPPED											
221201	Aileron Servo No. 1 - Removal / Installation		HRS		6181.2			0			0
	6256-164	495	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
221202	Aileron Servo No. 2 - Removal / Installation		HRS		6181.2			0			0
	6256-164	496	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
221203	Aileron Servo Bracket Assembly No. 1 - Removal / Installation		HRS		6181.2			0			0
	6256-151-1	1509	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221204	Aileron Servo Bracket Assembly No. 2 - Removal / Installation		HRS		6181.2			0			0
	6256-151-1	1508	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221205	Lane A1 Aiop Module - Removal / Installation		HRS		2860.1			3321.1			0
	7029305-1902	13062240	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			
221206	Lane B1 Aiop Module - Removal / Installation		HRS	TSN:1925.5	955.3			5225.9			0
	7028432-1902	1306G528	AFL	TSN:489	227			1341			0
			MOS	TSN:69	55.2			23 May 2019			HONEYWELL
	Airframe		MSC					O/C			
Notes: SWAPPED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
221207	Lane A2 Aiop Module - Removal / Installation		HRS		2860.1			3321.1			0
	7029305-1902	13062252	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			
221208	Lane B2 Aiop Module - Removal / Installation		HRS	TSN:1925.5	955.3			5225.9			0
	7028432-1902	1306G501	AFL	TSN:489	227			1341			0
			MOS	TSN:69	55.2			23 May 2019			HONEYWELL
	Airframe		MSC					O/C			
221301	Elevator Autopilot Servo No. 1 - Removal / Installation		HRS		6181.2			0			0
	6256-162	581	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221302	Elevator Autopilot Servo No. 2 - Removal / Installation		HRS		6181.2			0			0
	6256-162	591	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221303	Elevator Autopilot Servo Bracket Assembly No. 1 - Removal / Installation		HRS		6181.2			0			0
	6256-151-1	1506	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221304	Elevator Autopilot Servo Bracket Assembly No. 2 - Removal / Installation		HRS		6181.2			0			0
	6256-151-1	1507	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
221305	Elevator Trim Servo - Removal / Installation		HRS		5725.3			455.9			0
	7000260-503	05081366	AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
	Airframe		MSC					O/C			
221306	Elevator Trim Servo Bracket - Removal / Installation		HRS		5725.3			455.9			0
	7000261-604	00020960	AFL		1438			130			0
			MOS		191.3			21 Jan 2008			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
223002	Auto Throttle Disconnect Switch - Removal / Installation		HRS		6181.2			0			0
	X	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
223003	Takeoff / Go Around Switch - Removal / Installation		HRS		6181.2			0			0
	X	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
223005	Auto Throttle - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
23 - Communications											
230005	Avionics Ramp Check		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		95.1			27 Jan 2016			
	Airframe		MSC					O/C			
230102	Airshow Mounting Kit		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
231003	VHF Antenna No. 1 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	DM-C50-22-1	1437	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.8			04 Jul 2018			
	Airframe		MSC					O/C			
231004	VHF Antenna No. 2 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	DM-C50-22-1	1454	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.8			04 Jul 2018			
	Airframe		MSC					O/C			
231005	Transceiver, #3 VHF Comm		HRS		4830.6			1350.6			0
	7026203-813	06120282	AFL		1172			396			0
			MOS		167.5			15 Jan 2010			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231006	VHF Antenna No. 3 - Removal / Installation		HRS	TSN:231	1245.7			4935.5			0
	DM C50-22-1	4240	AFL	TSN:54	296			1272			0
			MOS	TSN:12	65.8			04 Jul 2018			AIL SYSTEMS INC.
	Airframe		MSC					O/C			
231010	VHF Voice Communications - Operational Test		HRS		1244.1			4937.1			0
			AFL		295			1273			0
			MOS		65.4			18 Jul 2018			
	Airframe		MSC					O/C			
231015	VHF Data Radio - Return to Service Test		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		MSC					O/C			
231101	High Frequency Receiver / Transmitter No. 1 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	822-0102-001	2895	MOS		208.3			21 Aug 2006			ROCKWELL COLLINS
	Airframe		MSC					O/C			
231102	High Frequency Receiver / Transmitter No. 2 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	822-0102-001	2878	MOS		208.3			21 Aug 2006			ROCKWELL COLLINS
	Airframe		MSC					O/C			
231105	HF Antenna Coupler No. 1 - Removal / Installation		HRS		4830.6			1350.6			0
			AFL		1172			396			0
	622-8114-002	6483	MOS		167.5			15 Jan 2010			ROCKWELL COLLINS
	Airframe		MSC					O/C			
231106	HF Antenna Coupler No. 2 - Removal / Installation		HRS		4831.2			1350			0
			AFL		1172			396			0
	622-8114-002	6561	MOS		167.5			15 Jan 2010			ROCKWELL COLLINS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231108	Airshow 4000 Sys Components - Gvi		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
Notes: 232166											
231110	HF Antenna - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159CS52061-411	GA0318	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7.1			25 May 2023			N/A
	Airframe		MSC					O/C			
231112	HF Antenna - Continuity Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
	Airframe		MSC					O/C			
231114	HF Dual Coupler Mounting Tray - Removal / Installation		HRS	TSN:425	4830.6			1350.6			0
	622-8124-001	2994	AFL	TSN:116	1172			396			0
			MOS	TSN:12	167.5			15 Jan 2010			ROCKWELL COLLINS
	Airframe		MSC					O/C			
231120	HF Voice Communication - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC					O/C			
231121	HF Antenna Adapter - Removal / Installation		HRS		6181.2			0			0
	822-0089-001	920	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROCKWELL COLLINS
	Airframe		MSC					O/C			
231201	AIR Radio Telecommunications Unit #1 Radio Telephone -		HRS	TSN:3363.9	130.8			6050.4			0
	Removal / Installation		AFL	TSN:829	29			1539			0
	724855-804	MSA6174	MOS	TSN:132	7.3			21 May 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231202	Duplexer, #1 Radio Phone 800MZ		HRS		6181.2			0			0
	620317-2	02724	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231203	Antenna, Radio Telephone 800MZ		HRS		2860.1			3321.1			0
	S65-5366-890L	268-3864	AFL		711			857			0
			MOS		124.5			15 Aug 2013			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
231204	Cdbr, #1 Radio Telephone 800MZ		HRS		6181.2			0			0
	724864-801	MSW1007	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231205	Cdbr, #2 Radio Telephone 800MZ		HRS		6173.3			7.9			0
	902205-803	MSR8948	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231206	Cdbr, #3 Radio Telephone 800MZ		HRS		6173.3			7.9			0
	902205-803	MSR8968	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231207	Cdbr-2, #1 Radio Telephone 800		HRS		6181.2			0			0
	902205-803	MSR8988	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231208	Cdbr-2, #2 Radio Telephone 800		HRS		6173.3			7.9			0
	902205-803	MSR8942	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TELEDYNE
	Airframe		MSC					O/C			CONTROLS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231209	CAS, #1 Radio Telephone 800MZ		HRS		6181.2			0			0
	725256-801	MSL5344	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231212	Handset, Crew Rest		HRS		6173.3			7.9			0
	938810A-C	2609002	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
231213	Handset, #1 Cabin 800MZ		HRS		6173.3			7.9			0
	725729-807WH	51769	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
231214	Handset, #2 Cabin 800MZ		HRS		6173.3			7.9			0
	725729-807WH	51867	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
231215	Handset, #3 Cabin 800MZ		HRS		6173.3			7.9			0
	725729-807WH	51925	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
231216	Handset, #4 Cabin 800MZ		HRS		6173.3			7.9			0
	725729-815WH	MX51534	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
231218	Aiu, #1 Radio Telephone 800MZ		HRS		6151.5			29.7			0
	724986-802	MSM3313	AFL		1555			13			0
			MOS		202.5			14 Feb 2007			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231220	Cdb, #4 Radio Telephone 800MZ		HRS		6173.3			7.9			0
	902205-803	MSR8950	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TELEDYNE
	Airframe		MSC					O/C			CONTROLS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231222	Tray, #1 Artu		HRS		6181.2			0			0
	724868-802	MST9168	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE
	Airframe		MSC					O/C			CONTROLS
231241	Voice / Data Radio Module No. 1 - Removal / Installation		HRS		1852.8			4328.4			0
	7026201-813	1502C168	AFL		444			1124			0
			MOS		87.7			06 Sep 2016			
	Airframe		MSC					O/C			
231244	Voice / Data Radio Module No. 2 - Removal / Installation		HRS		1830.1			4351.1			0
	7026201-813	1505C397	AFL		441			1127			0
			MOS		87.5			12 Sep 2016			HONEYWELL
	Airframe		MSC					O/C			
231301	HF Antenna Coupler (No. 1) - Servicing		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
231302	HF Antenna Coupler (No. 2) - Servicing		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
231501	Transceiver Unit, Iridium Sys		HRS		6151.5			29.7			0
	500616-2	3338	AFL		1555			13			0
			MOS		202.5			14 Feb 2007			HONEYWELL
	Airframe		MSC					O/C			
231502	Dual Channel Satellite Antenna (Aircell) - Removal / Installation		HRS	TSN:4927.6	1245.7			4935.5			0
			AFL	TSN:1266	296			1272			0
	S67-1575-109	145078	MOS	TSN:138	65.8			04 Jul 2018			
	Airframe		MSC					O/C			
231505	# 2 Iridium Handset		HRS		6173.3			7.9			0
	500040-00-32	0806-2603	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ICG
	Airframe		MSC					O/C			

Notes: CAMP 231500

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231530	SATCOM Antenna - Removal / Installation		HRS		130.8			6050.4			0
	806-10-0001	0P000162	AFL		29			1539			0
			MOS		7.1			25 May 2023			N/A
	Airframe		MSC							O/C	
Notes: CAM 232101											
231531	Diplexer / Low Noise Amplifier - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	804-10-0011	1706110	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7			28 May 2023			N/A
	Airframe		MSC							O/C	
Notes: CAMP 232113											
232102	Satellite Data Unit - Removal / Installation		HRS		1616.1			4565.1			0
	7516118-27011	67000587	AFL		390			1178			0
	A,C,D	A-D,M	MOS		81.2			24 Mar 2017			HONEYWELL
	Airframe		MSC							O/C	
232103	High Power Amplifier - Removal / Installation		HRS		4692.4			1488.8			0
	7516250-60050	00112040	AFL		1142			426			0
	A-G	A-G	MOS		165.2			22 Mar 2010			HONEYWELL
	Airframe		MSC							O/C	
232104	Unit, SATCOM Radio Freq (Rfu)		HRS		6181.2			0			0
	7516240-60050	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC							O/C	
232111	Radome, SATCOM		HRS	TSN:5507.5	665.8			5515.4			0
	5052-100	051	AFL	TSN:1412	150			1418			0
			MOS	TSN:161	43.3			20 May 2020			
	Airframe		MSC							O/C	
232112	Fairing, SATCOM		HRS	TSN:5507.5	665.8			5515.4			0
	5052-101	055	AFL	TSN:1412	150			1418			0
			MOS	TSN:161	43.5			13 May 2020			
	Airframe		MSC							O/C	
232115	Control Unit, SAT Tv Antenna		HRS		6181.2			0			0
	401/262	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232126	Stabilizer, SATCOM		HRS		6181.2			0			0
	81821/ACA	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
232131	Airshow Touchscreen Remote - Visual Check (RF/IF)		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-9	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: -1m]								
232133	SATCOM System - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
232134	Magnastar MCS-7000 - Visual Inspection, Above Floor		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1	-8	24	27 May 2023	31 May 2025*	30 Jun 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: THIS ITEM HAS BEEN ENTERED OUT OF ORDER.											
232135	Magnastar MCS-7000 - Functional Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-15	24	02 Jun 2023	31 May 2025*	30 Jun 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
232146	Securaplane 500 Above Floor - Visual Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: 237229											
232151	Securaplane 500 Wiring Under Cabin Floor - Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232165	Airshow 4000 System - Functional Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
232166	Airshow 4000 Wiring Under Floor - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1	-89	192	26 May 2023	28 Feb 2039*	31 Mar 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
232223	Printer, Cabin		HRS		6173.3			7.9			0
	MFC420CN	M5F259080	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC O/C								
232245	Securaplane DMC57-1 UHF Antenna-Visual Insp		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		202.1			26 Feb 2007			
	Airframe										
232250	Panel, R/H Bbml Maintenance		HRS		6173.3			7.9			0
	GC544280033-01	00047	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC O/C								
232251	Server, Bbml Advanced Cabin		HRS		3856.1			2325.1			0
	ACS-02-001	00062	AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC O/C								
Notes: CAMP 232254											
232252	Unit, Bbml LAN Switching		HRS		6173.3			7.9			0
	MSU-01-001	00324	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC O/C								
232253	Point, Bbml Wireless Access #1		HRS	TSN:5507.5	665.8			5515.4			0
	GC514280075-01	00301	AFL	TSN:1412	150			1418			0
			MOS	TSN:160	44			30 Apr 2020			N/A
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232259	Transceiver/Router, Bbml Integrated		HRS		130.8			6050.4			0
	1054023	41-100270	AFL		29			1539			0
			MOS		7.1			27 May 2023			N/A
	Airframe		MSC							O/C	
232260	Antenna, Bbml Skylink		HRS		3521.5			2659.7			0
	1000009	00-119	AFL		865			703			0
			MOS		140.7			07 Apr 2012			FINISHMASTER INC.
	Airframe		MSC							O/C	
232261	Unit, Bbml Antenna Control		HRS	TSN:4530.9	130.8			6050.4			0
	1007783	00-10081	AFL	TSN:1107	29			1539			0
			MOS	TSN:158	7.1			27 May 2023			N/A
	Airframe		MSC							O/C	
232265	Data Port W/Cover, Bbml		HRS		6173.3			7.9			0
	106084-1	1371006	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC							O/C	
232266	Hard Drive, Bbml		HRS		6173.3			7.9			0
	GC544280022-01	00035	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC							O/C	
233004	AMP, PA / Chime		HRS		6173.3			7.9			0
	990-1254-068	06060028968	AFL		1564			4			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC							O/C	
233007	Rack, PA AMP		HRS		6173.3			7.9			0
	622-1195-001	28VOC	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC							O/C	
233011	Speaker, Cabin PA #1		HRS		6173.3			7.9			0
	DT-PA2N	062147030	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM DALLAS
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233012	Speaker, Cabin PA #2		HRS		6173.3			7.9			0
	DT-PA2N	062147029	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
233013	Speaker, Cabin PA #3		HRS		6173.3			7.9			0
	DT-PA2N	062147001	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
233014	Speaker, Cabin PA #4		HRS		6173.3			7.9			0
	DT-PA2N	062147004	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
233015	Speaker, Cabin PA #5		HRS		6173.3			7.9			0
	DT-PA2N	062147032	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
233018	Box, AREA Distribution		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC					O/C			
233019	Box, Decoder Digitl Intrfc #1		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		44.9			31 Mar 2020			
	Airframe		MSC					O/C			
233020	Box, Decoder Digitl Intrfc #2		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45			30 Mar 2020			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233021	Box, Decoder Digitl Intrfc #3		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC					O/C			
233022	Box, Decoder Digitl Intrfc #4		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC					O/C			
233023	Box, Decoder Digitl Intrfc #5		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC					O/C			
233052	Video Control Unit		HRS		6173.3			7.9			0
	100-2415-01	1466	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			INSIGHT DIRECT,INC
	Airframe		MSC					O/C			
233056	AMP, #1 Speaker		HRS		1912.4			4268.8			0
	105210-0001	100769	AFL		474			1094			0
			MOS		100.5			12 Aug 2015			BOSE
	Airframe		MSC					O/C			
233057	AMP, #2 Speaker		HRS		6181.2			0			0
	180806	100710	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			BOSE
	Airframe		MSC					O/C			
233061	Compact Disc Player (No. 1) - Final Phase Removal / Installation		HRS		6173.3			7.9			0
	866-3210-1-1	206370219	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TELEVISION CENTER SERVICE CO. INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233078	Remote, #1 Cabin		HRS		6173.3			7.9			0
	2507-1-002-2507-138-279	206410312	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233079	Remote, #2 Cabin		HRS		6173.3			7.9			0
	2507-1-002-2507-138-279	206410313	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233084	Digital Video Disc Player (No. 1) - Final Phase Removal / Installation		HRS	TSN:5124.8	130.8			6050.4			0
			AFL	TSN:1259	29			1539			0
	866-0027-004	004771	MOS	TSN:172	6.9			02 Jun 2023			N/A
	Airframe		MSC					O/C			
233089	Digital Video Disc Player (No. 2) - Final Phase Removal / Installation		HRS		3856.1			2325.1			0
			AFL		950			618			0
	866-0027-004	004855	MOS		148.5			12 Aug 2011			J R MUSIC WORLD
	Airframe		MSC					O/C			
233101	Monitor, #1 Lh Seat		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
233102	Monitor, #1 Rh Seat		HRS		6173.3			7.9			0
	7000-061	0609J049	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN PRODUCTS
	Airframe		MSC					O/C			
233103	Monitor, #2 L/H Seat		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233104	Monitor, #2 R/H Seat		HRS		6173.3			7.9			0
	7000-061	0609J065	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN
	Airframe		MSC					O/C			PRODUCTS
233111	Monitor, Crew Rest / Work Sta		HRS		6173.3			7.9			0
	7000-060	0609J062	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233112	Monitor, Credenza		HRS	TSN:535	130.8			6050.4			0
	1901-201	20030002	AFL	TSN:121	29			1539			0
			MOS	TSN:38	6.9			02 Jun 2023			N/A
	Airframe		MSC					O/C			
233118	Monitor, Lcd		HRS		6173.3			7.9			0
	7000-060	0609J056	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233135	Amplifier, Tv/Video		HRS		6173.3			7.9			0
	MSM2925-01-1	070600145	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			STAGE FRONT
	Airframe		MSC					O/C			PRESENTATION SYSTEMS
233160	Monitor, Lh Aft Cabin Bulkhead		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		44.9			02 Apr 2020			
	Airframe		MSC					O/C			
233161	Monitor, Rh Aft Cabin Bulkhead		HRS		665.8			5515.4			0
	1901-201	20030003	AFL		150			1418			0
			MOS	TSN:2	44			29 Apr 2020			ROSEN AVIATION
	Airframe		MSC					O/C			
233162	Monitor, Lh Fwd Cabin Bulkhead		HRS	TSN:3551	2622.3			3558.9			0
	2710-1-1702	206380344	AFL	TSN:903	659			909			0
			MOS	TSN:85	118.5			14 Feb 2014			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233163	Monitor, Rh Fwd Cabin Bulkhead		HRS		665.8			5515.4			0
	1901-201	20030001	AFL		150			1418			0
			MOS	TSN:2	44			29 Apr 2020			ROSEN AVIATION
	Airframe		MSC								
233169	Box, Encoder Digitl Intrfc #1		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC								
233170	Box, Encoder Digitl Intrfc #2		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45			30 Mar 2020			
	Airframe		MSC								
233171	Box, Encoder Digitl Intrfc #3		HRS		665.8			5515.4			0
	PN	NOT INSTALLED	AFL		150			1418			0
			MOS		45			30 Mar 2020			
	Airframe		MSC								
233192	Avds Node Box - No. 1 - (Audio Visual Distribution System)		HRS		665.8			5515.4			0
	100-0074-27	156517N0001	AFL		150			1418			0
			MOS	TSN:17	43.5			15 May 2020			N/A
	Airframe		MSC								
233193	Avds Node Box - No. 2 - (Audio Visual Distribution System)		HRS		665.8			5515.4			0
	100-0074-84	165283N0001	AFL		150			1418			0
			MOS	TSN:2	43.7			07 May 2020			INNOVATIVE ADVANTAGE
	Airframe		MSC								
233202	Camera, Fwd Looking		HRS		6151.5			29.7			0
	100-1056-02	1482	AFL		1555			13			0
			MOS		202.5			12 Feb 2007			THALES AVIONICS CANADA INC.
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233203	Camera, Aft Looking		HRS		6151.5			29.7			0
	100-1056-02	0601256	AFL		1555			13			0
			MOS		202.5			12 Feb 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
233204	Camera, Down Looking		HRS		6173.3			7.9			0
	100-1054-02	1402	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GENERAL
	Airframe		MSC					O/C			DYNAMICS AVIATIONS SERVICES
233219	Controller, Airshow Primary J6		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
233223	Controller, Airshow		HRS		1035.1			5146.1			0
	925000-100	D01001444	AFL		242			1326			0
			MOS		58.2			23 Feb 2019			ROCKWELL
	Airframe		MSC					O/C			COLLINS AIRSHOW SYSTEMS
233251	Subwoofer, #1		HRS	TSN:6042.5	130.8			6050.4			0
	DT-AUS-4MSG	061143013	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			31 May 2023			N/A
	Airframe		MSC					O/C			
233252	Subwoofer, #2		HRS	TSN:6042.5	130.8			6050.4			0
	DT-AUS-4MSG	061143014	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			31 May 2023			N/A
	Airframe		MSC					O/C			
233253	Subwoofer, #3		HRS	TSN:6042.5	130.8			6050.4			0
	DT-AUS-4MSG	061143015	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			31 May 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233254	Subwoofer, #4		HRS	TSN:6042.5	130.8			6050.4			0
	DT-AUS-4MSG4	061143016	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			31 May 2023			N/A
	Airframe		MSC					O/C			
233261	Module, Cabin Management		HRS		6181.2			0			0
	1944-1-8/1644-512-20	206150112	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
233262	Monitor Controller (No.1)		HRS		665.8			5515.4			0
	0700-105	20030202	AFL		150			1418			0
			MOS	TSN:2	43.7			07 May 2020			ROSEN AVIATION
	Airframe		MSC					O/C			
233263	Monitor Controller (No.2)		HRS		665.8			5515.4			0
	0700-105	20030203	AFL		150			1418			0
			MOS	TSN:2	43.7			07 May 2020			ROSEN AVIATION
	Airframe		MSC					O/C			
233267	Monitor Controller (No.3)		HRS		665.8			5515.4			0
	0700-105	20040034	AFL		150			1418			0
			MOS	TSN:1	43.7			07 May 2020			ROSEN AVIATION
	Airframe		MSC					O/C			
233301	Speaker, #1 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271018	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233302	Speaker, #2 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271019	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233303	Speaker, #3 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271020	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233304	Speaker, #4 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062272001	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233305	Speaker, #5 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062272002	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233306	Speaker, #6 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	62271013	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233307	Speaker, #7 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271014	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233308	Speaker, #8 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271015	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233309	Speaker, #9 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271016	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233310	Speaker, #10 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-A8GAK	062271017	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			BOSE
	Airframe		MSC					O/C			
233311	Speaker, #11 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-PA2N8	062641003	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233312	Speaker, #12 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-PA2N8	062641002	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233313	Speaker, #13 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-PA2N8	062641006	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233314	Speaker, #14 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-PA2N8	062641029	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233315	Speaker, #15 Cbn Entertainment		HRS		6173.3			7.9			0
	DT-PA2N8	062641005	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
233445	Cabin Entertainment Video - Final Phase Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
233511	Receptacle, Monitor Lh #1		HRS		6173.3			7.9			0
	0100-002	0605K111	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN AVIATION DISPLAYS, LLC
	Airframe		MSC					O/C			
233512	Receptacle, Monitor Rh #1		HRS		6173.3			7.9			0
	0100-002	0605K114	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN AVIATION DISPLAYS, LLC
	Airframe		MSC					O/C			
233513	Receptacle, Monitor Lh #2		HRS		6173.3			7.9			0
	0100-002	0605K112	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN AVIATION DISPLAYS, LLC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233514	Receptacle, Monitor Rh #2		HRS		6173.3			7.9			0
	0100-002	0605K116	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN AVIATION
	Airframe		MSC					O/C			DISPLAYS, LLC
233515	Receptacle, Monitor Lh #3		HRS		6173.3			7.9			0
	0100-002	0605K113	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ROSEN AVIATION
	Airframe		MSC					O/C			DISPLAYS, LLC
235003	Network / Audio Interface Module No. 1 (Left) - Removal / Installation		HRS		1245.7			4935.5			0
	7517964-918	4050543	AFL		296			1272			0
			MOS		65.4			17 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			
235004	Network / Audio Interface Module No. 2 (Right) - Removal / Installation		HRS		1244.1			4937.1			0
	7517964-918	09096711	AFL		295			1273			0
			MOS		65.4			18 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			
235005	Audio Control Panel No. 1 - Removal / Installation		HRS		4025.3			2155.9			0
	7511900-90302	04091010	AFL		980			588			0
			MOS		152.1			26 Apr 2011			HONEYWELL
	Airframe		MSC					O/C			
235006	Audio Control Panel No. 2 - Removal / Installation		HRS		3856.1			2325.1			0
	7511900-90302	04020653	AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC					O/C			
235007	Audio Control Panel No. 3 - Removal / Installation		HRS		3521.5			2659.7			0
	7511900-90302	04050783	AFL		865			703			0
			MOS		141.5			14 Mar 2012			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235010	Audio Integrating System - Operational Check		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC							O/C	
235012	Modular Radio System - Return to Service Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC							O/C	
235013	Modular Radio Cabinet (Left) - Removal / Installation		HRS		5725.3			455.9			0
	7026240-902	07081269	AFL		1438			130			0
			MOS		191.7			07 Jan 2008			
	Airframe		MSC							O/C	
235016	Modular Radio Cabinet (Right) - Removal / Installation		HRS		6181.2			0			0
	7517959-904	06061972	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC							O/C	
235301	Oxygen Mask Microphone (Pilot) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
	Airframe		MSC							O/C	
235302	Oxygen Mask Microphone (Copilot) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
	Airframe		MSC							O/C	
235303	Oxygen Mask Microphone (Observer) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
	Airframe		MSC							O/C	
235304	Oxygen Mask Microphone (Auxiliary) - Operational Test		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.3			20 Aug 2015			
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235305	Microphone, Pilot Hand		HRS		6181.2			0			0
	602FTR	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
235306	Microphone, COPILOT Hand		HRS		6181.2			0			0
	602FTR	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
235307	Microphone, Observer Hand		HRS		6181.2			0			0
	602FTR	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
236001	L Wing Static Wicks / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236002	R Wing Static Wicks / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236003	L Horizontal Stabilizer Static Wick / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236004	R Horizontal Stabilizer Static Wick / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236005	Vertical Stabilizer Static Wick / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236006	Tail Cone Static Wick / Bonding - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-8	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
236011	Static Wick (Left Wing No. 1) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236012	Static Wick (Left Wing No. 2) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236013	Static Wick (Left Wing No. 3) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236014	Static Wick (Right Wing No. 1) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236015	Static Wick (Right Wing No. 2) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236016	Static Wick (Right Wing No. 3) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
Airframe			MSC				O/C				
236017	Static Wick (Left Horizontal Stabilizer No. 1) - Removal / Installation		HRS		6181.2			0			0
	FON9-1481-0IT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236018	Static Wick (Left Horizontal Stabilizer No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236019	Static Wick (Left Horizontal Stabilizer No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236020	Static Wick (Right Horizontal Stabilizer No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236021	Static Wick (Right Horizontal Stabilizer No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236022	Static Wick (Right Horizontal Stabilizer No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236023	Static Wick (Center Horizontal Stabilizer) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
236024	Static Wick (Tail Cone No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAW20A1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			CHELTON INC
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236025	Static Wick (Tail Cone No. 2) - Removal / Installation		HRS		6181.2			0			0
	GAW20A1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
	Airframe		MSC					O/C			
237001	Cockpit Voice Recorder Unit - Removal / Installation		HRS		665.8			5515.4			0
	2100-1020-00	000255435	AFL		150			1418			0
			MOS		44.9			02 Apr 2020			
	Airframe		MSC					O/C			
237002	Cockpit Voice Recorder Control Panel - Removal / Installation		HRS		6181.2			0			0
	S151-0020-00	000391296	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			L3
	Airframe		MSC					O/C			COMMUNICATIO NS
237003	Cockpit Voice Recorder Cockpit AREA Microphone - Removal / Installation		HRS		6181.2			0			0
	5055-0067-01	000359800	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
237004	Cockpit Voice Recorder - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
237005	Cvr Monitoring - Flight Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
237012	Cockpit Voice Recorder Underwater Locator Beacon (DK120 or DK120/90) - Battery Discard		HRS		1247.7			4933.5			0
	DK120/90	AT111803	AFL		298			1270			0
			MOS	TSN:1	66.5			15 Jun 2018	02 May 2024		
	Airframe		MSC					DUE			EXPIRATION
							[End Of Month Item]				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	TSN:1	66.5		O/C	15 Jun 2018			Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237013	Cockpit Voice Recorder Underwater Locator Beacon - Removal / Installation		HRS		1247.7			4933.5			0
	DK120/90	AT111803	AFL		298			1270			0
			MOS	TSN:1	66.5			15 Jun 2018			
Airframe											
237014	Cockpit Voice Recorder Underwater Locator Beacon - Battery Replacement		HRS		1247.7			4933.5			0
	DK120/90	AT111803	AFL		298			1270			0
			MOS	TSN:1	66.5			15 Jun 2018			
Airframe											
237016	Cockpit Voice Recorder Underwater Locator Beacon - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	13	24	18 Mar 2023	31 Mar 2025*	30 Apr 2025	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
237018	Cockpit Voice Recorder Underwater Locator Beacon - Switch Cleaning (DK100 / DK120)		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	13	24	18 Mar 2023	31 Mar 2025*	30 Apr 2025	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
237020	Cockpit Voice Recorder Impact Switch - Functional Check		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.4		84	18 Jun 2018	20 May 2024		
[End Of Month Item]											
Airframe											
237021	Cockpit Voice Recorder Impact Switch - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	1159SCAV402-2	2318	AFL	TSN:1272	296			1272			0
			MOS	TSN:142	66.4			18 Jun 2018			DAVTRON INC
[End Of Month Item]											
Airframe											
237022	Inverter, Ckpt Voice Recorder		HRS		6181.2			0			0
	8300-A140-01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237203	Ultra High Frequency Antenna - Final Phase Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	DMC57-1	8953	MOS		203.7			08 Jan 2007			AIL SYSTEMS INC.
			MSC								
Airframe											
237204	Indicator, Security Sys Alarm		HRS		6173.3			7.9			0
	100-0651-01	0804	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			SECURAPLANE
			MSC								
Airframe											
237205	Panel, Security Sys Solar		HRS		6173.3			7.9			0
	443-0101-01	C10211152282141	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			PEAK TECHNOLOGIES, INC.
			MSC								
Airframe											
237207	Passive Infrared Sensor (Forward Nose Wheel Well) - Final Phase Removal / Installation		HRS		6173.3			7.9			0
	100-0401-11	3654	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237208	Passive Infrared Sensor (Aft Nose Wheel Well) - Final Phase Removal / Installation		HRS		6173.3			7.9			0
	100-0401-11	3653	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237209	Passive Infrared Sensor (Left Main Gear Wheel Well) - Final Phase Removal / Installation		HRS		6173.3			7.9			0
	100-0401-11	3629	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237210	Passive Infrared Sensor (Right Main Gear Wheel Well) - Final Phase Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	100-0401-11	3652	MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC					O/C			
Airframe											
237213	Transceiver, Security System		HRS		6173.3			7.9			0
			AFL		1562			6			0
	444EX600	0723	MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC					O/C			
Airframe											
237214	Battery Pack - 550 (No. 1) - Final Phase Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	PN	NOT INSTALLED	MOS		9.2			22 Mar 2023			
			MSC					O/C			
Airframe											
237222	Aircraft Security - Final Phase Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
237223	Control Display Unit (Cdu)		HRS		6173.3			7.9			0
			AFL		1562			6			0
	100-0106-01	0715	MOS		203.7			08 Jan 2007			SECURAPLANE TECHNOLOGIES, LLC
			MSC					O/C			
Airframe											
237225	Pir-375 Sensors - Clean (Wheel Well)		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		-7	12	18 Mar 2023	31 Mar 2024*	
Airframe											
											[End Of Month Item]

Notes: 237238

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)							Manufacturer
											Date Type
237227	Securaplane 500 Battery Module Bp-550-Replacement		HRS		1245.7			4935.5			0
	100-1032-01	5764	AFL		296			1272			0
			MOS		66.1			27 Jun 2018			
	Airframe		MSC					O/C			
Notes: 237239											
237228	Securaplane 500 Security System-Func Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6		24	11 Mar 2022	31 Mar 2024		
	Airframe							[End Of Month Item]			
Notes: 237236											
237234	Securaplane Rad-04, Handheld Transceiver - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	444-EX600	0723	MOS	TSN:177	31.3			19 May 2021			N/A
	Airframe		MSC					O/C			
237240	Securaplane 500 Security System Wiring and		HRS		130.8			6050.4			0
	Components-Inspection		AFL		29			1539			0
			MOS		6.9	-96	192	02 Jun 2023	28 Feb 2039*		
	Airframe							[End Of Month Item]			
Notes: 237230											
238005	RF Detector #1		HRS		6173.3			7.9			0
	DBD01-001	00341	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
238006	RF Detector #2		HRS		6173.3			7.9			0
	DBD01-001	00342	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
238007	RF Detector #3		HRS		6173.3			7.9			0
	DBD01-001	00347	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
239199	Software Update (SATCOM)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
24 - Electrical Power											
240101	Emergency Battery (Left) - Removal / Installation		HRS		129.3			6051.9			0
	1159SCAV524-3	P0993	AFL		28			1540			0
			MOS		6.8			04 Jun 2023			N/A
	Airframe		MSC					O/C			
240102	Emergency Battery (Right) - Removal / Installation		HRS		321.8			5859.4			0
	1159SCAV524-3	P3876	AFL		68			1500			0
			MOS		18			28 Jun 2022			
	Airframe		MSC					O/C			
240103	Emergency Battery (Forward) - Removal / Installation		HRS		392.4			5788.8			0
	1159SCAV524-3	P2795	AFL		88			1480			0
			MOS		21.6			11 Mar 2022			
	Airframe		MSC					O/C			
240104	Emergency Battery (Aft) - Removal / Installation		HRS		392.4			5788.8			0
	1159SCAV524-3	P4798	AFL		88			1480			0
			MOS		22.2			23 Feb 2022			
	Airframe		MSC					O/C			
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 240114, SO 9-27-17											
240106	L Emergency Battery - Bite / Battery Level Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
240107	R Emergency Battery - Bite / Battery Level Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
240108	Fwd Emergency Battery - Bite / Battery Level Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
240109	Aft Emergency Battery - Bite / Battery Level Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
240111	Emergency Battery Pack (Left) - Restore		HRS		130.8			6050.4			0
	102-1103-01	220908-36	AFL		29			1539			0
			MOS		9.5		48	15 Mar 2023	31 Mar 2027		
Airframe			[End Of Month Item]								
Notes: PART OF S/N: P2881											
240112	Emergency Battery Pack (Right) - Restore		HRS		609.87			5571.33			0
	102-1103-01	200928-39	AFL		126			1442			0
			MOS		33.5		48	15 Mar 2021	31 Mar 2025	30 Apr 2025	
Airframe			[End Of Month Item]								
240113	Emergency Battery Pack (Forward) - Restore		HRS		392.4			5788.8			0
	102-1103-01	030420-17	AFL		88			1480			0
			MOS		21.6		48	11 Mar 2022	31 Mar 2026		
Airframe			[End Of Month Item]								
240114	Emergency Battery Pack (Aft) - Restore		HRS		597.1			5584.1			0
	102-1103-01	210309-39	AFL		124			1444			0
			MOS	TSN:1	29.6		48	10 Jul 2021	30 Jun 2025		
Airframe			[End Of Month Item]								
Notes: PART OF S/N: P-4798											
240121	Emergency Battery Power System (Left) - Operational		HRS		129.3			6051.9			0
	Test		AFL		28			1540			0
			MOS		6.8		12	04 Jun 2023	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
240122	Emergency Battery Power System (Right) - Operational		HRS		130.8			6050.4			0
	Test		AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
240123	Emergency Battery Power System (Forward) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
240124	Emergency Battery Power System (Aft) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
241005	L Idg AIR Cooled Oil Cooler - Removal / Installation		HRS		6181.2			0			0
	50028001-11	50028-1133	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
241006	R Idg AIR Cooled Oil Cooler - Removal / Installation		HRS		6181.2			0			0
	50028001-11	50028-1146	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
242001	Tail Compartment AC Feeder Cables - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
242005	Standby Electrical Power System - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	22	24	11 Mar 2022	30 Apr 2024*	31 May 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
242100	Engine Alternating Current Generation - Operational Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.1			26 May 2020			
			MSC					O/C			
Airframe											
242101	Adaptor, L Eng Generator Qad		HRS		6181.2			0			0
	1159SCAV500-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			HAMILTON SUNDSTRAND
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242102	Adaptor, R Eng Generator Qad		HRS		6181.2			0			0
	1159SCAV500-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
242103	L Idg - Removal / Installation		HRS		6181.2			0			0
	1159SCAV500-3	0789	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
242104	R Idg - Removal / Installation		HRS		6181.2			0			0
	1159SCAV500-3	0788	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
242105	Integrated Drive Generator Oil Scavenge Filter (Left) - Removal / Installation		HRS		665.8			5515.4			0
	5905018	NSN	AFL		150			1418			0
			MOS	TSN:2	43			29 May 2020			
	Airframe		MSC					O/C			
242106	Integrated Drive Generator Oil Scavenge Filter (Right) - Removal / Installation		HRS		6181.2			0			0
	AC-F451F-16	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242109	Integrated Drive Generator (Left) - Oil Level Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
	Airframe		MSC					O/C			
242110	Integrated Drive Generator (Right) - Oil Level Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242111	Integrated Drive Generator (Left) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCAV500-3 SN: <NONE>. WO SC13165											
242112	Integrated Drive Generator (Right) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCAV500-3 SN: <NONE>. WO SC13165											
242113	Integrated Drive Generator Disconnect System (Left) - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.4		50	16 May 2023	31 Jul 2027	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
242114	Integrated Drive Generator Disconnect System (Right) - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.4		50	16 May 2023	31 Jul 2027	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
242115	Integrated Drive Generator (Left) - Servicing		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCAV500-3 SN: <NONE>. WO SC13165											
242116	Integrated Drive Generator (Right) - Servicing		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCAV500-3 SN: <NONE>. WO SC13165											
242117	Integrated Drive Generator Oil Scavenger Filter (Left) - Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43			29 May 2020			
Airframe			MSC O/C HAMILTON SUNDSTRAND								
Notes: PN: 5905018 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242118	Integrated Drive Generator Oil Scavenger Filter (Right) - Inspection		HRS		2622.3			3558.9			0
			AFL		659			909			0
			MOS		118.5			14 Feb 2014			HAMILTON
			MSC							O/C	SUNDSTRAND
Airframe											
Notes: PN: 5905018 SN: <NONE>.											
242123	Integrated Drive Generator (Left) - Oil System Filling		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
			MSC							O/C	
Airframe											
Notes: PN: 1159SCAV500-3 SN: 0789. FREQUENCY ONLY FOR A/C NOT HAVE MOD 5 INPUT SHAFT/SEAL (MOD 5 CUT IN A/C 5001)											
242126	Integrated Drive Generator (Right) - Oil System Filling		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC							O/C	
Airframe											
Notes: FREQUENCY ONLY FOR A/C NOT HAVE MOD 5 INPUT SHAFT/SEAL (MOD 5 CUT IN A/C 5001)											
242141	Integrated Drive Generator Oil Scavenger Filter		HRS		130.8			6050.4			0
	Differential Pressure Indicator (Left) - Inspection		AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
			MSC							O/C	
Airframe											
242142	Integrated Drive Generator Oil Scavenger Filter		HRS		130.8			6050.4			0
	Differential Pressure Indicator (Right) - Inspection		AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
			MSC							O/C	
Airframe											
242200	APU AC Generation Sys-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
242201	APU Generator - Removal / Installation		HRS	TSN:535.7	3320.4			2860.8			0
	1159SCAV501-1	0485	AFL	TSN:129	821			747			0
			MOS	TSN:12	136.4			16 Aug 2012			HAMILTON
			MSC							O/C	SUNDSTRAND
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242202	APU Gcu - Removal / Installation		HRS		6181.2			0			0
	1702787B	0568	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
242203	APU CTA - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU
	Airframe		MSC					O/C			E
242204	APU AC Contactor - Removal / Installation		HRS		6181.2			0			0
	1C121	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242205	Idg. Oil APU - Service		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242206	APU AC Generation System - Operational Check		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC					O/C			
242300	Emergency Inverter-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242301	Emergency Inverter - Removal / Installation		HRS		129.3			6051.9			0
	6431200-7	G22-10463	AFL		28			1540			0
			MOS	TSN:6	6.8			04 Jun 2023			N/A
	Airframe		MSC					O/C			
242302	E Inverter OPS Check		HRS		129.3			6051.9			0
			AFL		28			1540			0
			MOS		6.8			04 Jun 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242400	Hyd Motor AC Gen Sys-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242401	Hydraulic Motor Generator - Removal / Installation		HRS		2728.2			3453			0
	1159SCAV522-3	F9911284	AFL		681			887			0
			MOS		121.7			08 Nov 2013			EATON
	Airframe		MSC					O/C			AEROSPACE
242402	Hmg Gcu - Removal / Installation		HRS		6181.2			0			0
	1159SCAV523-1	G0620762	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			SECURAPLANE
	Airframe		MSC					O/C			TECHNOLOGIES, LLC
242404	Hydraulic Motor Generator Current Transformer Assembly		HRS		6181.2			0			0
	- Removal / Installation		AFL		1568			0			0
	1159SCAV504-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
242405	Hmg Contactors - Removal / Installation		HRS		6181.2			0			0
	1C121	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242406	Standby Junction and Relay Panel - Removal / Installation		HRS		6181.2			0			0
	PN		AFL		1568			0			0
		SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242601	Electrical Power Control Switch - Removal / Installation		HRS		6181.2			0			0
	PN		AFL		1568			0			0
		SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242603	L Idg Gcu - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	1702787B	0584	AFL	TSN:1418	150			1418			0
			MOS	TSN:166	43.1			26 May 2020			N/A
	Airframe		MSC					O/C			
242604	R Idg Gcu - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	1702787B	0497	AFL	TSN:1418	150			1418			0
			MOS	TSN:166	43.1			26 May 2020			N/A
	Airframe		MSC					O/C			
242700	60 HZ Power Generation System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
			[End Of Month Item]								
242701	Converter (400 to 60 HZ) - Removal / Installation		HRS		6181.2			0			0
	1-002-0102-1723	HT000958	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AVIONIC INSTRUMENTS INC
	Airframe		MSC					O/C			
242712	Splitter, HI Speed Data RX #1		HRS		6181.2			0			0
	7519349-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242714	Splitter, HI Speed Data RX #2		HRS		6181.2			0			0
	7519349-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
242722	60 Hertz Cabin Pressure Switch - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		72	26 Feb 2007 30 Sep 2028 31 Oct 2028			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
243001	Main Battery (Left) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCAV519-1	090520005733B	AFL		29			1539			0
			MOS		9.4			16 Mar 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243002	Main Battery (Right) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCAV519-1	098337	AFL		29			1539			0
			MOS		9.4			16 Mar 2023			N/A
	Airframe		MSC					O/C			
243003	L Main Battery Charger - Removal / Installation		HRS		1889.3			4291.9			0
	1159SCAV520-7	289534-1386	AFL		454			1114			0
			MOS		89.5			15 Jul 2016			UNISON INDUSTRIES
	Airframe		MSC					O/C			
243004	R Main Battery Charger - Removal / Installation		HRS	TSN:332.4	1889.3			4291.9			0
	1159SB57520-11	245992-312	AFL	TSN:130	454			1114			0
			MOS		89.5			15 Jul 2016			UNISON INDUSTRIES
	Airframe		MSC					O/C			
243005	L Main Battery Hall Effect Sensor - Removal / Installation		HRS		6181.2			0			0
	1159SCAV507-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ELDEC CORP
	Airframe		MSC					O/C			
243006	R Main Battery Hall Effect Sensor - Removal / Installation		HRS		4187.8			1993.4			0
	1159SCAV507-3	208240210	AFL		1016			552			0
			MOS		155.3			21 Jan 2011			ELDEC CORP
	Airframe		MSC					O/C			
243007	Main Battery Contactor (Left) - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
243008	Main Battery Contactor (Right) - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
243009	L Main Battery Charger Contactor - Removal / Installation		HRS		6181.2			0			0
	642CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243010	R Main Battery Charger Contactor - Removal / Installation		HRS		6181.2			0			0
	642CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
243011	L Main Battery - Capacity Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	7	12	16 Mar 2023	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: PN: 1159SCAV519-1 SN: 098337.											
243012	R Main Battery - Capacity Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	7	12	16 Mar 2023	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: PN: 1159SCAV519-1 SN: 090520005733B.											
243013	L Main Battery Service and Electrolyte Level - Check		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
	Airframe		MSC					O/C			
243014	R Main Battery Service and Electrolyte Level - Check		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
	Airframe		MSC					O/C			
243015	Main Battery - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
	Airframe		MSC					O/C			
243017	Probe, #1 Battery Temperature		HRS		6181.2			0			0
	P600-14B	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FOXTRONICS INC
	Airframe		MSC					O/C			
243018	Probe, #2 Battery Temperature		HRS		6181.2			0			0
	P600-14B	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FOXTRONICS INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243020	Tail Compartment Dc Feeder Cables - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
243100	L Main Tru - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	B1996	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
Airframe			MSC				O/C				
Notes: CAMP 243301											
243101	L Essential Tru - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	B1995	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
Airframe			MSC				O/C				
Notes: CAMP 243302											
243102	R Main Tru - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	B1998	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
Airframe			MSC				O/C				
Notes: CAMP 243303											
243103	R Essential Tru - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	B1999	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
Airframe			MSC				O/C				
Notes: CAMP 243304											
243104	Auxiliary Tru - Removal / Installation		HRS		6181.2			0			0
	1159SCAV508-3	B1997	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
Airframe			MSC				O/C				
Notes: CAMP 243305											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243105	L Main Tru Hall Effect Sensor (Fwd) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV507-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELDEC CORP
			MSC								
Airframe											
243106	L Essential Tru Hall Effect Sensor (Middle) - Removal / Installation		HRS		5255.6			925.6			0
			AFL		1288			280			0
	1159SCAV507-3	368TF	MOS		179.1			26 Jan 2009			ELDEC CORP
			MSC								
Airframe											
243107	R Main Tru Hall Effect Sensor - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV507-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELDEC CORP
			MSC								
Airframe											
243108	R Essential Tru Hall Effect Sensor - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV507-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELDEC CORP
			MSC								
Airframe											
243109	Auxiliary Tru Hall Effect Sensor (Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV507-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELDEC CORP
			MSC								
Airframe											
243703	Control Unit, L Dc Bus Power		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV503-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											
243704	Control Unit, R Dc Bus Power		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV503-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243801	Battery Volt / AMP Meter - Removal / Installation		HRS		130.8			6050.4			0
	789550-2-1	0722	AFL		29			1539			0
			MOS		6.9			01 Jun 2023			N/A
	Airframe		MSC								
244200	External AC Power System - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC								
244201	External AC Power CTA - Removal / Installation		HRS		6181.2			0			0
	1159SCAV504-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC								
244202	External AC Power Contactor - Removal / Installation		HRS		6181.2			0			0
	870CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC								
244299	Receptacle, External Dc Power		HRS		6181.2			0			0
	1159SCAV200-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC								
244300	External Dc Power System - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC								
244301	External Dc Power Contactor - Removal / Installation		HRS		6181.2			0			0
	870CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC								
244302	External Dc Power Hall Effect Sensor - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV507-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ELDEC CORP
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
244401	Ground Fault Circuit Interrupt - Removal / Installation		HRS		6181.2			0			0
	X	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
244402	Ground Power AC Contactor - Removal / Installation		HRS		6181.2			0			0
	890CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			DONGHIA TEXTILE CORP INC
	Airframe		MSC					O/C			
244403	Ground Power Dc Contactor - Removal / Installation		HRS		6181.2			0			0
	890CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			DONGHIA TEXTILE CORP INC
	Airframe		MSC					O/C			
244431	Controller, #1 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14890706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244432	Controller, #2 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14900706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244433	Controller, #3 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14910706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244434	Controller, #4 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14920706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
244435	Controller, #5 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14930706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244436	Controller, #6 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14940706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244437	Controller, #7 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14950706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244438	Controller, #8 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14960706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244439	Controller, #9 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14970706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244440	Controller, #10 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14980706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244441	Controller, #11 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	14990706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
244442	Controller, #12 50HZ AC Power		HRS		6173.3			7.9			0
	106075-1	15000706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245005	AC Load Distribution System - Operational Check		HRS		129.3			6051.9			0
			AFL		28			1540			0
			MOS		6.8			04 Jun 2023			
	Airframe		MSC							O/C	
245101	Left Power Distribution Box - Removal / Installation		HRS		129.3			6051.9			0
	1703230	0198	AFL		28			1540			0
			MOS		6.8			04 Jun 2023			N/A
	Airframe		MSC							O/C	
245102	Right Power Distribution Box - Removal / Installation		HRS		129.3			6051.9			0
	1703232	0201	AFL		28			1540			0
			MOS		6.8			04 Jun 2023			N/A
	Airframe		MSC							O/C	
245103	Main AC Contactor (Left) - Removal / Installation		HRS		6181.2			0			0
	9100A01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC							O/C	
245104	Main AC Contactor (Right) - Removal / Installation		HRS		6181.2			0			0
	9100A01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC							O/C	
245105	AC Cross-Tie Contactor (Left) - Removal / Installation		HRS		6181.2			0			0
	900CA01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC							O/C	
245106	AC Cross-Tie Contactor (Right) - Removal / Installation		HRS		6181.2			0			0
	900CA01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC							O/C	
245107	Main Tru AC Contactor (Left) - Removal / Installation		HRS		6181.2			0			0
	IC121-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245108	Main Tru AC Contactor (Right) - Removal / Installation		HRS		6181.2			0			0
	IC121-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
245109	L Pdb Essential AC Contactor - Removal / Installation		HRS		6181.2			0			0
	IC121-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
245110	R Pdb Essential AC Contactor - Removal / Installation		HRS		6181.2			0			0
	IC121-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
245111	Contactor, Cabin 60 HZ Power		HRS		6181.2			0			0
	96210080	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
245121	Left Power Distribution Box Mounting Tray - Removal / Installation		HRS		6181.2			0			0
	1703237A	0188	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
245122	Right Power Distribution Box Mounting Tray - Removal / Installation		HRS		6181.2			0			0
	1703239A	0189	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
245301	Gfci - 60 HZ Power #1		HRS		6173.3			7.9			0
	106072-1	9451106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245302	Gfci - 60 HZ Power #2		HRS		6173.3			7.9			0
	106072-1	9441106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245303	Gfci - 60 HZ Power #3		HRS		6173.3			7.9			0
	106072-1	9461106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245304	Gfci - 60 HZ Power #4		HRS		6173.3			7.9			0
	106072-1	9471106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245306	Gfci-60 HZ Power #6		HRS		6181.2			0			0
	106072-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245307	Gfci-60 HZ Power #7		HRS		6181.2			0			0
	106072-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245308	Gfci-60 HZ Power #8		HRS		6181.2			0			0
	106072-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245309	Gfci-60 HZ Power #9		HRS		6181.2			0			0
	106072-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245310	Gfci-60 HZ Power #10		HRS		6181.2			0			0
	106072-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245321	Outlet Assy, # 1 50 HZ		HRS		6173.3			7.9			0
	106185-2	881106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245322	Outlet Assy, # 2 50 HZ		HRS		6173.3			7.9			0
	106185-2	891106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245323	Outlet Assy, # 3 50 HZ		HRS		6173.3			7.9			0
	106185-2	901106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245324	Outlet Assy, # 4 50 HZ		HRS		6173.3			7.9			0
	106185-2	941106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245325	Outlet Assy, # 5 50 HZ		HRS		6173.3			7.9			0
	106185-2	921106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245326	Outlet Assy, # 6 50 HZ		HRS		6173.3			7.9			0
	106185-2	931106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245327	Outlet Assy, # 7 50 HZ		HRS		6173.3			7.9			0
	106185-2	951106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245328	Outlet Assy, # 8 50 HZ		HRS		6173.3			7.9			0
	106185-2	961106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245329	Outlet Assy, # 9 50 HZ		HRS		6173.3			7.9			0
	106185-2	971106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245330	Outlet Assy, # 10 50 HZ		HRS		6173.3			7.9			0
	106185-2	981106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245331	Outlet Assy, # 11 50 HZ		HRS		6173.3			7.9			0
	106185-2	991106	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
245370	Controller, #1 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245371	Controller, #2 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245372	Controller, #3 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Contin Controls
	Airframe		MSC					O/C			
245373	Controller, #4 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245374	Controller, #5 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245375	Controller, #6 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245376	Controller, #7 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245377	Controller, #8 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245378	Controller, #9 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245379	Controller, #10 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245380	Controller, #11 60 HZ AC Power		HRS		6181.2			0			0
	106075-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			Mid Cont Controls
	Airframe		MSC					O/C			
245523	60HZ Outlet, Credenza - Removal / Installation		HRS		665.8			5515.4			0
	106394-2-3	371118	AFL		150			1418			0
			MOS	TSN:18	44			30 Apr 2020			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS, INC.
246001	L Bpcu - Removal / Installation		HRS		6181.2			0			0
	1702789A	0378	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
246002	R Bpcu - Removal / Installation		HRS		6181.2			0			0
	1702789A	0353	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
246005	Direct Current Load Distribution System - Operational Check		HRS		129.3			6051.9			0
			AFL		28			1540			0
			MOS		6.8			04 Jun 2023			
			MSC							O/C	
Airframe											
246010	Ground Service Bus - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC							O/C	
Airframe											
246011	L Main Dc Contactor - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
			MSC							O/C	
Airframe											
246012	R Main Dc Contactor - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
			MSC							O/C	
Airframe											
246013	L Main Dc Cross-Tie Contactor - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
			MSC							O/C	
Airframe											
246014	R Main Dc Cross-Tie Contactor - Removal / Installation		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
			MSC							O/C	
Airframe											
246016	R Ground Service Bus Contactor - Removal / Installation		HRS		6181.2			0			0
	870CC01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
246017	Contactor, L Pdb Ledc		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
246018	Contactor, R Pdb Redc		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
246201	Contactor, L Pdb Ledcb		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
246202	Contactor, R Pdb Redcb		HRS		6181.2			0			0
	220CC02	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ECE
	Airframe		MSC					O/C			
246401	Relay, Gnd Srvc Bus Time Delay		HRS		6181.2			0			0
	TRDU24A2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			IN-FAB PRO, INV.
	Airframe		MSC					O/C			
248020	E System Controller		HRS		6181.2			0			0
	2052-1-8	205290117	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ELECTRO ENTERPRISES INC
	Airframe		MSC					O/C			
25 - Equipment/Furnishings											
250005	Jack, Aircraft Axle		HRS		6173.3			7.9			0
	2-7830-0110	1827060605	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TRONAIR INC
	Airframe		MSC					O/C			
250010	Towbar, Aircraft		HRS		6181.2			0			0
	WYG45XLT	4291	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AERO WELD INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
250015	Ladder		HRS		5725.3			455.9			0
	1159SCB750-1	00110	AFL		1438			130			0
			MOS		191.3			21 Jan 2008			CARBIS
	Airframe		MSC					O/C			LADDERS
251001	Pilot Seat - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159SCF513-23	46466	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	7.1			26 May 2023			
	Airframe		MSC					O/C			
251002	Copilot Seat - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159SCF513-24	46470	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	7.1			26 May 2023			
	Airframe		MSC					O/C			
251003	Observer Seat - Removal / Installation		HRS	TSN:5859.9	321.8			5859.4			0
	1159SCF501-1	186-1425	AFL	TSN:1500	68			1500			0
			MOS	TSN:191	17.9			01 Jul 2022			
	Airframe		MSC					O/C			
251006	Crew Seats Inertia Reel (Pilot) - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
251007	Crew Seats Inertia Reel (Copilot) - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
251008	Crew Seats Inertia Reel (Observer) - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
251011	Crew Seat Tracks (Pilot) - Lubrication		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251012	Crew Seat Tracks (Copilot) - Lubrication		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
251013	Crew Seat Track (Observer) - Lubrication		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
251016	Crew Seat Restraints (Pilot) - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
251017	Crew Seat Restraints (Copilot) - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
251018	Crew Seat Restraints (Observer) - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
251021	Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18		48	28 Jun 2022	30 Jun 2026	31 Jul 2026	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
251022	Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18		48	28 Jun 2022	30 Jun 2026	31 Jul 2026	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
251023	Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.9	-6	48	01 Jul 2022	30 Jun 2026*	31 Jul 2026	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251101	Glareshield (Cockpit)		HRS		6181.2			0			0
	1159FP40014-S803	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
251110	Sunshade Assembly, Cockpit (Left)		HRS		130.8			6050.4			0
	1-6112-200G	105216	AFL		29			1539			0
			MOS	TSN:4	6.9			02 Jun 2023			N/A
	Airframe		MSC					O/C			
251111	Sunshade Assembly, Cockpit (Right)		HRS		467.9			5713.3			0
	1-6111-200G	2118	AFL		100			1468			0
			MOS		25.6			11 Nov 2021			
	Airframe		MSC					O/C			
251401	Rack, Electronic Equipment (Left)		HRS		6181.2			0			0
	37-811-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
251501	Rack, Electronic Equipment (Right)		HRS		6181.2			0			0
	37-812-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
252001	Cabin Full Size Single Seat (Left No. 1) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.524.01-7008A	060828-05	MOS	TSN:198	4.1			25 Aug 2023			
	Airframe		MSC					O/C			
252002	Cabin Full Size Single Seat (Left No. 2) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.524.01-7005B	060828-02	MOS	TSN:198	4.1			25 Aug 2023			
	Airframe		MSC					O/C			
252006	Cabin Full Size Single Seat (Right No. 1) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.524.01-7007B	060828-04	MOS	TSN:198	4.1			25 Aug 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252007	Cabin Full Size Single Seat (Right No. 2) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.524.01-70A	060828-01	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252011	Cabin Double Seat (Aft Facing No. 1) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.525.01-(4007A)	060828-06	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252013	Cabin Double Seat (Forward Facing No. 1) - Final Phase		HRS	TSN:6098.5	74.8			6106.4			0
	Removal / Installation		AFL	TSN:1545	17			1551			0
	2524.525.01-4002B	060828-07	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252015	Divan, Four Place (No. 1)		HRS	TSN:6098.5	74.8			6106.4			0
	2523.700.01-(03)		AFL	TSN:1545	17			1551			0
		060629-19	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252016	Divan, Four Place (No. 2)		HRS	TSN:6098.5	74.8			6106.4			0
	2523.700.01-(03)		AFL	TSN:1545	17			1551			0
		060828-09	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252017	Two Place Divan (Left No. 1) - Final Phase Removal /		HRS	TSN:6098.5	74.8			6106.4			0
	Installation		AFL	TSN:1545	17			1551			0
	2523.700.01-(04)	060828-10	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											
252018	Two Place Divan (Left No. 2) - Final Phase Removal /		HRS	TSN:6098.5	74.8			6106.4			0
	Installation		AFL	TSN:1545	17			1551			0
	2523.700.01-(04)	060828-11	MOS	TSN:198	4.1			25 Aug 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252021	Shade, Window (Left, No. 1)		HRS		145			6036.2			0
	ATG-WS-2008	0167-104	AFL		32			1536			0
			MOS		10.5			14 Feb 2023			
	Airframe		MSC						O/C		
252022	Shade, Window (Left, No. 2)		HRS	TSN:6042.5	130.8			6050.4			0
	ATG-WS-2004	0359-102	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
252023	Shade, Window (Left, No. 3)		HRS	TSN:6042.5	130.8			6050.4			0
	ATG-WS-2004	0359-103	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
252024	Shade, Window (Left, No. 4)		HRS		130.8			6050.4			0
	ATG-WS-2008	022-109	AFL		29			1539			0
			MOS		6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
252025	Shade, Window (Left, No. 5)		HRS	TSN:6050.4	130.8			6050.4			0
	ATG-WS-2008	0359-107	AFL	TSN:1539	29			1539			0
			MOS	TSN:194	6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
252026	Shade, Window (Left, No. 6)		HRS		145			6036.2			0
	ATG-WS-2008	024-502	AFL		32			1536			0
			MOS		10.5			14 Feb 2023			
	Airframe		MSC						O/C		
252027	Shade, Window (Right, No. 1)		HRS		6173.3			7.9			0
	ATG-WS-2002	0359-901	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC						O/C		
252028	Shade, Window (Right, No. 2)		HRS		6173.3			7.9			0
	ATG-WS-2002	0359-902	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC						O/C		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252029	Shade, Window (Right, No. 3)		HRS	TSN:6042.5	130.8			6050.4			0
	ATG-WS-2004	0359-106	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
252030	Shade, Window (Right, No. 4)		HRS		6173.3			7.9			0
	ATG-WS-2004	0359-107	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC						O/C		
252031	Shade, Window (Right, No. 5)		HRS	TSN:6098.5	74.8			6106.4			0
	ATG-WS-2004	0359-108	AFL	TSN:1545	17			1551			0
			MOS	TSN:198	4.1			25 Aug 2023			
	Airframe		MSC						O/C		
252032	Shade, Window (Right, No. 6)		HRS		6173.3			7.9			0
	ATG-WS-2005	0359-503	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC						O/C		
252033	Shade, Window (Left, No. 7)		HRS		665.8			5515.4			0
	ATG-WS-2009	0359-502	AFL		150			1418			0
			MOS		43			28 May 2020			
	Airframe		MSC						O/C		
252034	Shade, Window (Right, No. 7)		HRS		665.8			5515.4			0
	ATG-WS-2009	0359-504	AFL		150			1418			0
			MOS		43			28 May 2020			
	Airframe		MSC						O/C		
252051	Conference Table Lift - Final Phase Removal / Installation		HRS	TSN:6106.4	74.8			6106.4			0
	PN	SN-UNKNOWN	AFL	TSN:1551	17			1551			0
			MOS	TSN:204	4.1			25 Aug 2023			
	Airframe		MSC						O/C		
252070	Supplemental Floor Heater No. 1 - Removal / Installation		HRS	TSN:923.9	321.8			5859.4			0
	NPN PROVIDED	NSN PROVIDED	AFL	TSN:228	68			1500			0
			MOS	TSN:48	17.9			01 Jul 2022			
	Airframe		MSC						O/C		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252101	Passenger Seats Attachments and Locking - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
252102	Passenger Seats Restraints - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
252103	Passenger Seats and Seat Tracks - Lubrication		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18			28 Jun 2022			
			MSC					O/C			
Airframe											
252104	Passenger Seats Inertia Reels - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
252105	Seat, Flight Attendant		HRS	TSN:6098.5	74.8			6106.4			0
	2524.524.01-226B	060828-03	AFL	TSN:1545	17			1551			0
			MOS	TSN:198	4.1			25 Aug 2023			
			MSC					O/C			
Airframe											
252471	Window Shade (Left #4) - Operational Test (Elite)		HRS		584			5597.2			0
			AFL		123			1445			0
			MOS		28.3			19 Aug 2021			
			MSC					O/C			
Airframe											
252501	Table, Forward (Left)		HRS	TSN:6042.5	130.8			6050.4			0
	53775-25	25235	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			02 Jun 2023			N/A
			MSC					O/C			
Airframe											
252502	Table, Forward (Right)		HRS	TSN:6042.5	130.8			6050.4			0
	53775-25	23547	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	7			30 May 2023			N/A
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252503	Table, Mid (Left)		HRS	TSN:6042.5	130.8			6050.4			0
	53775-16	25606	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	7			30 May 2023			N/A
	Airframe		MSC						O/C		
252504	Table, Mid (Right)		HRS		6173.3			7.9			0
	70221-18H	25710	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			ENFLITE, INC.
	Airframe		MSC						O/C		
252510	Pocket Door Assembly (No. 1)		HRS		6173.3			7.9			0
	42300-230R-029	26193	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			SHORELINE MARINE
	Airframe		MSC						O/C		
252558	Exit Sign, Lh Mid Cabin Bulkhead		HRS		130.8			6050.4			0
	BC1-0002-022	N/A	AFL		29			1539			0
			MOS	TSN:1	6.8			03 Jun 2023			N/A
	Airframe		MSC						O/C		
253010	Microwave Oven - Final Phase Removal / Installation		HRS	TSN:6042.5	130.8			6050.4			0
	R21HT	23009	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	7			30 May 2023			N/A
	Airframe		MSC						O/C		
253011	Oven (Galley) {No. 1}		HRS		130.8			6050.4			0
	2510-0069-03	225047601	AFL		29			1539			0
			MOS		8.1			27 Apr 2023			N/A
	Airframe		MSC						O/C		
253017	Coffeemaker (No. 1) - Final Phase Removal / Installation		HRS	TSN:6042.5	130.8			6050.4			0
	400-1794-02	06-09-39704	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.9			02 Jun 2023			N/A
	Airframe		MSC						O/C		
253018	Coffeemaker (No. 2) - Final Phase Removal / Installation		HRS		6181.2			0			0
	400-2195-01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC						O/C		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
253029	Refrigerator		HRS	TSN:6042.5	130.8			6050.4			0
	DA1200CSU-GA44	CSU-0276	AFL	TSN:1533	29			1539			0
			MOS	TSN:195	8.1			27 Apr 2023			N/A
	Airframe		MSC					O/C			
253201	Espresso Machine		HRS	TSN:6042.5	130.8			6050.4			0
	3510-0066-01	245651403	AFL	TSN:1533	29			1539			0
			MOS	TSN:196	6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			
254030	Stowage Compartment Latch - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	20	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024			
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
Notes: THIS FREQUENCY IS REQUIRED PER ICA GC52801A444 FOR A/C 5124											
254101	Lavatory Compartment - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
256006	Goggles, Crew Smoke (Pilot)		HRS		6181.2			0			0
	MXP210-00	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
	Airframe		MSC					O/C			
256007	Goggles, Crew Smoke (Copilot)		HRS		6181.2			0			0
	MXP210-00	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
	Airframe		MSC					O/C			
256008	Goggles, Crew Smoke (Observer)		HRS		6181.2			0			0
	MXP210-00	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU E
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256009	Goggles, CSO (Communications Stations)		HRS		6181.2			0			0
	MXP210-00	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			INTERTECHNIQU
	Airframe		MSC					O/C			E
256011	Crew Smoke Goggles (Pilot) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		30	-5	36	30 Jun 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
256012	Crew Smoke Goggles (Copilot) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		30	-5	36	30 Jun 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
256013	Crew Smoke Goggles (Observer) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		30	-5	36	30 Jun 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
256017	FIRE / Crash Axe - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3		12	19 Mar 2023	31 Mar 2024	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
256019	EVAS System (Left) - Periodic Inspection		HRS		57.2			6124			0
			AFL		10			1558			0
			MOS		3.5		3	12 Sep 2023	31 Dec 2023	31 Jan 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: PN: 107STC-049 SN: <NONE>.											
256020	EVAS System (Right) - Periodic Inspection		HRS		57.2			6124			0
			AFL		10			1558			0
			MOS		3.5		3	12 Sep 2023	31 Dec 2023	31 Jan 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: PN: 107STC-050 SN: <NONE>.											
256021	Emergency Vision Assurance System (EVAS) {Left}		HRS		404.7			5776.5			0
	107STC-049	0003Q10P	AFL		92			1476			0
			MOS		22.7			07 Feb 2022			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256022	Emergency Vision Assurance System (EVAS) {Right}		HRS		404.7			5776.5			0
	107STC-050	0001S07P	AFL		92			1476			0
			MOS		22.7			07 Feb 2022			N/A
	Airframe		MSC					O/C			
256023	EVAS System (Left) - Rebuild		HRS	TSN:4927.6	1245.7			4935.5			0
	107STC-049	0003Q10P	AFL	TSN:1266	296			1272			0
			MOS	TSN:138	65.6		120	10 Jul 2018	31 Oct 2026	31 Jan 2027	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
Notes: REBUILD DUE +/- 3 MONTHS OF OCTOBER 2026											
256024	EVAS System (Right) - Rebuild		HRS		1245.7			4935.5			0
	107STC-050	0001S07P	AFL		296			1272			0
			MOS		65.6		120	10 Jul 2018	31 Jul 2028	31 Oct 2028	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
Notes: REBUILD DUE +/- 3 MONTHS OF JULY 2028											
256025	Ditching Line - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2		48	23 Apr 2023	30 Apr 2027	31 May 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256038	EVAS System (Left) - Biennial Inspection		HRS		404.7			5776.5			0
			AFL		92			1476			0
			MOS		22.7	52	24	07 Feb 2022	31 Mar 2024*	30 Jun 2024	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
Notes: PN: 107STC-049 SN: 0003Q10P. 256027											
256039	EVAS System (Right) - Biennial Inspection		HRS		404.7			5776.5			0
			AFL		92			1476			0
			MOS		22.7	52	24	07 Feb 2022	31 Mar 2024*	30 Jun 2024	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
Notes: PN: 107STC-050 SN: 0001S07P. 256028											
256041	No. 1 First AID Kit		HRS		347.8			5833.4			0
	AESPS02	PS-AAV	AFL		77			1491			0
			MOS		19.1			25 May 2022			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256043	First AID Kit (No. 1) - Detailed Inspection		HRS		96.5			6084.7			0
			AFL		22			1546			0
			MOS		5.7	-7	12	07 Jul 2023	30 Jun 2024*	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: AFAK 1.0 SN: <NONE>.											
256045	First AID Kit (No. 1) Time Limited Supplies - Discard		HRS		96.5			6084.7			0
	AESPS02	PS-AAV	AFL	TSN:55	22			1546			0
			MOS	TSN:14	5.7	12	12	07 Jul 2023	31 May 2024*		
Airframe			[End Of Month Item]								
256061	Flashlight (No. 1) - Removal / Installation		HRS	TSN:3725.3	130.8			6050.4			0
	106-000-646	32560711	AFL	TSN:921	29			1539			0
			MOS	TSN:139	9.5			14 Mar 2023			
Airframe			MSC				O/C				
256062	Flashlight (No. 2) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	106-000-646	32487243	AFL	TSN:1539	29			1539			0
			MOS	TSN:198	9.4			18 Mar 2023			
Airframe			MSC				O/C				
256063	Flashlight (No. 3) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	106-000-646	32576530	AFL	TSN:1539	29			1539			0
			MOS	TSN:198	9.4			18 Mar 2023			
Airframe			MSC				O/C				
256064	Flashlight (No. 4) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	R1019	D3044043161	AFL	TSN:1539	29			1539			0
			MOS	TSN:198	9.5			14 Mar 2023			
Airframe			MSC				O/C				
256071	Flashlight (No. 1) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	4	12	14 Mar 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256072	Flashlight (No. 2) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256073	Flashlight (No. 3) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		12	18 Mar 2023	31 Mar 2024	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256074	Flashlight (No. 4) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	4	12	14 Mar 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256101	Battery, Flashlight (No. 1)		HRS		1889.4			4291.8			0
	ARXX235	NSN	AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
Airframe			MSC				O/C				
256102	Battery, Flashlight (No. 2)		HRS		1889.4			4291.8			0
	ARXX235	NSN	AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
Airframe			MSC				O/C				
256103	Battery, Flashlight (No. 3)		HRS		1889.4			4291.8			0
	ARXX235	NSN	AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
Airframe			MSC				O/C				
256104	Battery, Flashlight (No. 4)		HRS		1889.4			4291.8			0
	LR20	NSN	AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
Airframe			MSC				O/C				
256201	Life Vest(S) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-73	12	31 May 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256202	Life Raft(S) (No. 1) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-81	12	31 May 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256203	Life Raft(S) (No. 2) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-81	12	31 May 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256211	Life Vest (No. 1) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1828850	AFL		29			1539			0
			MOS	TSN:134	6.9			31 May 2023			
Airframe			MSC				O/C				
256212	Life Vest (No. 2) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1832872	AFL		29			1539			0
			MOS		6.9			31 May 2023			
Airframe			MSC				O/C				
256213	Life Vest (No. 3) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1896586	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
Airframe			MSC				O/C				
256214	Life Vest (No. 4) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1828851	AFL		29			1539			0
			MOS		6.9			31 May 2023			
Airframe			MSC				O/C				
256215	Life Vest (No. 5) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1896606	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
Airframe			MSC				O/C				
256216	Life Vest (No. 6) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1896592	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
Airframe			MSC				O/C				
256217	Life Vest (No. 7) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1828861	AFL	TSN:792	29			1539			0
			MOS	TSN:134	6.9			31 May 2023			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256218	Life Vest (No. 8) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1896590	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
	Airframe		MSC					O/C			
256219	Life Vest (No. 9) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1828933	AFL	TSN:792	29			1539			0
			MOS	TSN:134	6.9			31 May 2023			
	Airframe		MSC					O/C			
256220	Life Vest (No. 10) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1828955	AFL	TSN:792	29			1539			0
			MOS	TSN:134	6.9			31 May 2023			
	Airframe		MSC					O/C			
256221	Life Vest (No. 11) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1896597	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
	Airframe		MSC					O/C			
256222	Life Vest (No. 12) - Removal / Installation		HRS	TSN:3189.6	130.8			6050.4			0
	63600-105	L1900158	AFL	TSN:792	29			1539			0
			MOS	TSN:130	6.9			31 May 2023			
	Airframe		MSC					O/C			
256223	Life Vest (No. 13) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1828910	AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
256224	Life Vest (No. 14) - Removal / Installation		HRS		130.8			6050.4			0
	63600-105	L1896591	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
	Airframe		MSC					O/C			
256225	Life Vest (No. 15) - Removal / Installation		HRS		130.8			6050.4			0
	63600-505	L1896596	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256226	Life Vest (No. 16) - Removal / Installation		HRS		130.8			6050.4			0
	63600-505	L1896589	AFL	TSN:792	29			1539			0
			MOS	TSN:131	6.9			31 May 2023			
	Airframe		MSC					O/C			
256250	Life Vest (Pilot) - Removal / Installation		HRS	TSN:1758.6	130.8			6050.4			0
	63600-505	L2440537	AFL	TSN:425	29			1539			0
			MOS	TSN:110	6.9			31 May 2023			
	Airframe		MSC					O/C			
256251	Life Vest (Copilot) - Removal / Installation		HRS		130.8			6050.4			0
	63600-505	L1732733	AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
256252	Life Vest (Observer) - Removal / Installation		HRS		130.8			6050.4			0
	63600-505	L1732730	AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
256253	Life Vest (Crew Member) - Removal / Installation		HRS		130.8			6050.4			0
	63600-505	L1732729	AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
256260	Life Raft (No. 1) - Removal / Installation		HRS		130.8			6050.4			0
	1320FAUL-6J0-1-100	13UL-00674	AFL		29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			
256261	Life Raft (No. 2) - Removal / Installation		HRS		130.8			6050.4			0
	1320FAUL-6J0-1-100	13UL-00675	AFL		29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			
256270	Life Raft (No. 1) - Restore		HRS		597.1			5584.1			0
	1320FAUL-6J0-1-100	13UL-00674	AFL		124			1444			0
			MOS		31.3		36	19 May 2021 31 May 2024			
	Airframe		[End Of Month Item]								EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256271	Life Raft (No. 2) - Restore		HRS		597.1			5584.1			0
	1320FAUL-6J0-1-100	13UL-00675	AFL		124			1444			0
			MOS		31.3		36	19 May 2021	31 May 2024		
Airframe	[End Of Month Item]										EXPIRATION
256281	Protective Breathing Equipment (No. 1) - Removal /		HRS	TSN:1758.6	130.8			6050.4			0
	Installation		AFL	TSN:425	29			1539			0
	MR-10039N	E1601226	MOS	TSN:83	9.3			19 Mar 2023			
			MSC							O/C	
Airframe											
256282	Protective Breathing Equipment (No. 1) - Detailed		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		9.3		12	19 Mar 2023	31 Mar 2024	30 Apr 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
Notes: PN: MR-10039N SN: <NONE>. WO SC13165											
256283	Protective Breathing Equipment (No. 1) - Discard		HRS		1889.4			4291.8			0
	MR-10039N	E1601226	AFL		454			1114			0
			MOS	TSN:3	89.4		126	18 Jul 2016	31 Oct 2026		
Airframe	[End Of Month Item]										GULFSTREAM SAV COMPLETION IPTS EXPIRATION
Notes: TRACKING ACCORDING TO REENROLLMENT PAPERWORK, SO 7-26-16											
256284	Protective Breathing Equipment (No. 2) - Removal /		HRS	TSN:6039.6	130.8			6050.4			0
	Installation		AFL	TSN:1522	29			1539			0
	MR-10039N	E1601205	MOS	TSN:201	6.8			03 Jun 2023			N/A
			MSC							O/C	
Airframe											
256285	Protective Breathing Equipment (No. 2) - Detailed		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		6.8	-76	12	03 Jun 2023	31 Mar 2024*	30 Apr 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
Notes: PN: MR-10039N SN: <NONE>. WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Manufacturer
											Date Type
256286	Protective Breathing Equipment (No. 2) - Discard				HRS			4281			0
	MR-10039N	E1601205			AFL			1097			0
					MOS		126	03 Jun 2016	22 Oct 2026		GULFSTREAM SAV COMPLETION IPTS EXPIRATION
Airframe					[End Of Month Item]						
Notes: UPDATED NEXT DUE REFERENCING REMOVAL/INSTALLATION CMP CARD 256284 STATING NEXT DUE IS 10/2026											
256301	Emergency Locator Transmitter - Removal / Installation				HRS	TSN:630		6050.4			0
	453-5000-999	210-11764			AFL	TSN:146		1539			0
					MOS	TSN:42		16 Mar 2023			N/A
Airframe					MSC		O/C				
256302	Emergency Locator Transmitter Batteries - Discard				HRS			5225.9			0
	452-0133	381325-032			AFL			1341			0
		V134B			MOS	TSN:2	60	30 May 2019	26 Mar 2024		ARTEX SUPPLY INC EXPIRATION
Airframe					[End Of Month Item]						
256303	Emergency Locator Transmitter Antenna - Removal / Installation				HRS	TSN:4935.5		4935.5			0
	110-337	124360			AFL	TSN:1272		1272			0
					MOS	TSN:143		04 Jul 2018			ARTEX AIRCRAFT SUPPLIES
Airframe					MSC		O/C				
256306	Emergency Locator Transmitter - Operational Test (FAR 91.207)				HRS			6050.4			0
					AFL			1539			0
					MOS		12	16 Mar 2023	31 Mar 2024		
Airframe					[End Of Month Item]						
256307	Emergency Locator Transmitter / Navigation Interface Unit - Removal / Installation				HRS			0			0
	453-6500	05478			AFL			0			0
		V002B			MOS			21 Aug 2006			ARTEX AIRCRAFT SUPPLIES
Airframe					MSC		O/C				
256311	Emergency Locator Transmitter - Operational Check				HRS			6050.4			0
					AFL			1539			0
					MOS			16 Mar 2023			
Airframe					MSC		O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256401	Defibrillator		HRS		6173.3			7.9			0
	M3861A-ABA	1006216366	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
256402	Battery, Defibrillator - Change		HRS		145			6036.2			0
	989803136291	LOT 97068P	AFL		32			1536			0
			MOS		10.5			14 Feb 2023	30 Apr 2027		
	Airframe		MSC					DUE			
Notes: BATTERY EXP DATE: 04/30/2027.											
256404	Defibrillator Battery - Inspect / Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-84	12	03 Jun 2023	31 Mar 2024*		
	Airframe							[End Of Month Item]			
Notes: PN: 989803136291 SN: <NONE>.											
256406	Defibrillator Electrode Pads - Discard (SET No. 1)		HRS		115.4			6065.8			0
	FR2 (M3713A)	LOT 020722-03	AFL		24			1544			0
			MOS		6.6			09 Jun 2023	31 Jan 2024		
	Airframe		MSC					DUE			EXPIRATION
256451	Defibrillator - General Visual Inspection		HRS		10.8			6170.4			0
			AFL		2			1566			0
			MOS		.8	-2	1	03 Dec 2023	01 Jan 2024*		
	Airframe		MSC					-			
Notes: PN: 502861 SN: 1006216366.											
256700	Life Vest (No. 1) - Restore		HRS	TSN:5788.8	392.4			5788.8			0
	63600-105	L1828850	AFL	TSN:1480	88			1480			0
			MOS	TSN:1466	21.6		120	11 Mar 2022	08 Mar 2032		
	Airframe							[End Of Month Item]			EXPIRATION
256701	Life Vest (No. 2) - Restore		HRS		392.4			5788.8			0
	63600-105	L1832872	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
	Airframe							[End Of Month Item]			EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256702	Life Vest (No. 3) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1896586	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256703	Life Vest (No. 4) - Restore		HRS		392.4			5788.8			0
	63600-105	L1828851	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
Airframe											EXPIRATION
256704	Life Vest (No. 5) - Restore		HRS		347.8			5833.4			0
	63600-105	L1896606	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256705	Life Vest (No. 6) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1896592	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256706	Life Vest (No. 7) - Restore		HRS		392.4			5788.8			0
	63600-105	L1828861	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
Airframe											EXPIRATION
256707	Life Vest (No. 8) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1896590	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256708	Life Vest (No. 9) - Restore		HRS		392.4			5788.8			0
	63600-105	L1858933	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
Airframe											EXPIRATION
256709	Life Vest (No. 10) - Restore		HRS		392.4			5788.8			0
	63600-105	L1828955	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
Airframe											EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256710	Life Vest (No. 11) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1896597	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256711	Life Vest (No. 12) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1900158	AFL	TSN:1491	77			1491			0
			MOS	TSN:1468	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256712	Life Vest (No. 13) - Restore		HRS		392.4			5788.8			0
	63600-105	L1828910	AFL		88			1480			0
			MOS		21.6		120	11 Mar 2022	08 Mar 2032		
Airframe											EXPIRATION
256713	Life Vest (No. 14) - Restore		HRS	TSN:5833.4	347.8			5833.4			0
	63600-105	L1896591	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256714	Life Vest (No. 15) - Restore		HRS		347.8			5833.4			0
	63600-105	L1896596	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256715	Life Vest (No. 16) - Restore		HRS		347.8			5833.4			0
	63600-105	L1896589	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1		120	25 May 2022	18 May 2032		
Airframe											EXPIRATION
256726	Life Vest (Pilot) - Restore		HRS		1889.4			4291.8			0
	63600-505	L2440537	AFL		454			1114			0
			MOS	TSN:28	89.4		120	18 Jul 2016	30 Mar 2024		
Airframe											EXPIRATION
256727	Life Vest (Copilot) - Restore		HRS		597.1			5584.1			0
	63600-505	L1732733	AFL		124			1444			0
			MOS		29.6		120	09 Jul 2021	31 Jul 2031		
Airframe											EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256728	Life Vest (Observer) - Restore		HRS		597.1			5584.1			0
	63600-505	L1732730	AFL		124			1444			0
			MOS		29.6		120	09 Jul 2021	31 Jul 2031		
	Airframe		[End Of Month Item]								EXPIRATION
256729	Life Vest (Crew Member) - Restore		HRS		597.1			5584.1			0
	63600-505	L1732729	AFL		124			1444			0
			MOS		29.6		120	09 Jul 2021	31 Jul 2031		
	Airframe		[End Of Month Item]								EXPIRATION
26 - FIRE Protection											
260301	Baggage Compartment Smoke Evacuation Valve -		HRS		1245.7			4935.5			0
	Operational Test		AFL		296			1272			0
			MOS		66.3		72	21 Jun 2018	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
260302	Smoke Evacuation Valve - Removal / Installation		HRS		6181.2			0			0
	B-43YF2-RD-SS	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GE
	Airframe		MSC				O/C				POLYMERSHAPE S
261101	Equipment Overheat Thermal Switch (Leer, 056S4) -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	GAS850-DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
261102	Equipment Overheat Thermal Switch (Leer, 056S5) -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261103	Equipment Overheat Thermal Switch (Leer, 056S6) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
Airframe			MSC				O/C				
261104	Equipment Overheat Thermal Switch (Left Shelf No. 4) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
Airframe			MSC				O/C				
261105	Equipment Overheat Thermal Switch (Reer, 056S20) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
Airframe			MSC				O/C				
261106	Equipment Overheat Thermal Switch (Reer, 056S21) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
Airframe			MSC				O/C				
261107	Equipment Overheat Thermal Switch (Right Shelf No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261108	Equipment Overheat Thermal Switch (Right Shelf No. 4) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC					O/C			
Airframe											
261109	Equipment Overheat Thermal Switch (Leer) - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
261110	Equipment Overheat Thermal Switch (Reer) - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
261145	Engine FIRE and Heat Sensing (Left) - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
261146	Engine FIRE and Heat Sensing (Right) - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
261147	FIRE Detection Link Harness (Between RAIL 1 and RAIL 2, Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	X	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
261148	FIRE Detection Link Harness (Between RAIL 1 and RAIL 2, Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	X	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261149	Core Engine FIRE Detection Sensors (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ARG10094	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
261150	Core Engine FIRE Detection Sensors (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ARG10094	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
261151	FIRE Detection RAIL Assembly No. 5 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-196	06-03-7846	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC						O/C		
Airframe											
261152	FIRE Detection RAIL Assembly No. 5 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-196	05-09-7378	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC						O/C		
Airframe											
261155	FIRE Detection RAIL Assembly No. 2 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-201	06-06-8007	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC						O/C		
Airframe											
261156	FIRE Detection RAIL Assembly No. 2 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-201	06-06-8010	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261157	FIRE Detection RAIL Assembly No. 3 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-198	06-03-7859	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261158	FIRE Detection RAIL Assembly No. 3 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	51291-198	06-06-7999	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261201	FIRE Detection Control Box (Left Engine) - Removal / Installation		HRS	TSN:1344.9	1044.7			5136.5			0
			AFL	TSN:360	245			1323			0
	51653-154	3044	MOS	TSN:56	58.6			11 Feb 2019			KIDDE AEROSPACE
			MSC					O/C			
Airframe											
261202	FIRE Detection Control Box (Right Engine) - Removal / Installation		HRS		1035.1			5146.1			0
			AFL		242			1326			0
	51653-274	02095	MOS	TSN:7	57.7			07 Mar 2019			KIDDE AEROSPACE
			MSC					O/C			
Airframe											
261203	Pylon Thermal Switch (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261204	Pylon Thermal Switch (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261205	Pylon Thermal Switch (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261206	Pylon Thermal Switch (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261207	Pylon Thermal Switch (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261208	Pylon Thermal Switch (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261209	Pylon Thermal Switch (Left) - Functional Test		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
261210	Pylon Thermal Switch (Right) - Functional Test		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
261211	FIRE Detection Control Box (Left Engine) - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											
261212	FIRE Detection Control Box (Right Engine) - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261301	APU FIRE Detection Loop - Removal / Installation		HRS		2078.3			4102.9			0
	6360-12-1000/450-7	200886	AFL		510			1058			0
			MOS		148.5			12 Aug 2011			MEGGITT
	Airframe		MSC					O/C			SAFETY SYSTEMS
261302	APU (FIRE) Shut-Down Circuit - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
261305	APU Compartment FIRE Detect Loop - Operational Test		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
	Airframe							[HRS: +50/-50]			
261401	Equipment Overheat Thermal Switch (Baggage Electronic		HRS		6181.2			0			0
	Equipment Rack, 056S8) - Removal / Installation		AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
261402	Equipment Overheat Thermal Switch (Baggage Electronic		HRS		6181.2			0			0
	Equipment Rack, 056S9) - Removal / Installation		AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
261403	Equipment Overheat Thermal Switch (Left Aft Floor,		HRS		6181.2			0			0
	056S12) - Removal / Installation		AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261404	Equipment Overheat Thermal Switch (Left Aft Floor, 056S13) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261405	Equipment Overheat Thermal Switch (Left Aft Floor, 056S14) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261406	Equipment Overheat Thermal Switch (Center Aft Floor, 056S15) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261407	Equipment Overheat Thermal Switch (Right Aft Floor, 056S16) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261408	Equipment Overheat Thermal Switch (Aft Equipment, 056S10) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261409	Equipment Overheat Thermal Switch (Aft Equipment, 056S11) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261410	Equipment Overheat Thermal Switch (Right Aft Floor, 056S27) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261411	Equipment Overheat Thermal Switch (Right Aft Floor, 056S28) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261412	Equipment Overheat Thermal Switch (Center Aft Floor, 056S29) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
261413	Equipment Overheat Thermal Switch (Forward Floor, 056S24) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261414	Equipment Overheat Thermal Switch (Forward Floor, 056S25) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261415	Equipment Overheat Thermal Switch (Forward Floor, 056S26) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261416	Equipment Overheat Thermal Switch (Forward Floor, 056S30) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC					O/C			COMMERCIAL ELECTRONICS SYSTEMS
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261417	Equipment Overheat Thermal Switch (Forward Floor, 056S31) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC								
Airframe											
261418	Aft Equipment Overheat Thermal Switches - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-10	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
261419	Baggage Compartment Below Floor Overheat Thermal Switch - Functional Test		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
261503	Smoke Detection Unit (Baggage Compartment) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	72130001-006	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
261601	FIRE Detection and Indication - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
Airframe											
262020	Engine FIRE Bottle (Left) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	33800100-1	55255D1	MOS		87.9			31 Aug 2016			PACIFIC SCIENTIFIC CO
			MSC								
Airframe											
262021	Engine FIRE Bottle (Left) - (Hydrostatic) Functional Test		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		92.1			27 Apr 2016			
			MSC								
Airframe											

Notes: PN: 33800100-1 SN: 55255D1. TRACKING ACCORDING TO REENROLLMENT PAPERWORK, SO 7-26-16

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262025	Engine FIRE Bottle (Right) - Removal / Installation		HRS		1864.9			4316.3			0
	33800100-1	55753D1	AFL		445			1123			0
			MOS		87.9			31 Aug 2016			PACIFIC
	Airframe		MSC					O/C			SCIENTIFIC CO
262026	Engine FIRE Bottle (Right) - (Hydrostatic) Functional Test		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		92.1			27 Apr 2016			
	Airframe		MSC					O/C			
Notes: PN: 33800100-1 SN: 55753D1. TRACKING ACCORDING TO REENROLLMENT PAPERWORK, SO 7-26-16											
262101	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Removal / Installation		HRS		665.8			5515.4			0
	35201023-1	NSN	AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
	Airframe		MSC					O/C			
262102	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	35201023-1	NSN	AFL	TSN:1418	150			1418			0
			MOS	TSN:164	45.1			27 Mar 2020			
	Airframe		MSC					O/C			
262105	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.1		120	27 Mar 2020	31 Mar 2030	30 Apr 2030	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: INITIAL DUE 10 YEARS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 10 YEARS THEREAFTER, OR 10 YEARS SINCE LAST ACCOMPLISHMENT OF ENGINE FIRE EXTINGUISHING SHUTTLE VALVE (DOUBLE CHECK VALVE TEE) - FUNCTIONAL TEST CODE 262105. AIRCRAFT BEYOND 9 YEARS S											
262106	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.1		120	27 Mar 2020	31 Mar 2030	30 Apr 2030	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: INITIAL DUE 10 YEARS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 10 YEARS THEREAFTER, OR 10 YEARS SINCE LAST ACCOMPLISHMENT OF ENGINE FIRE EXTINGUISHING SHUTTLE VALVE (DOUBLE CHECK VALVE TEE) - FUNCTIONAL TEST CODE 262106. AIRCRAFT BEYOND 9 YE											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262108	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1836UG	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262109	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1836UG	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262133, SO 9-6-16											
262110	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1136UG	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262111	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1136UG	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262128, SO 9-6-16											
262112	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1709UB	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262113	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1709UB	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262129, SO 9-6-16											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262114	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1139UG	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262115	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1139UG	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262131, SO 9-6-16											
262116	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1698UB	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262117	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1698UB	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262132, SO 9-6-16											
262118	Engine FIRE Bottle Cartridge (Left Bottle, APU / Spare Squib, Service Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1841UG	MOS		87.9		120	31 Aug 2016	31 Aug 2026		PACIFIC SCIENTIFIC CO
Airframe											
262119	Engine FIRE Bottle Cartridge (Left Bottle, APU / Spare Squib, Manufacturers Life) - Discard		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1841UG	MOS		87.9		180	31 Aug 2016	31 Aug 2031		PACIFIC SCIENTIFIC CO MANUFACTURE
Airframe											
Notes: UPDATED REFERENCING COMPLIANCE AND CERTIFICATION TAG ATTACHED TO CODE 262130, SO 9-6-16											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262120	Engine FIRE Pull Handle (Left) - Removal / Installation		HRS		6181.2			0			0
	24293-1	201	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ESTERLINE
	Airframe		MSC					O/C			MASON
Notes: CAMP CODE 262103											
262121	Engine FIRE Pull Handle (Right) - Removal / Installation		HRS		6181.2			0			0
	24293-2	198	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			JANCO
	Airframe		MSC					O/C			CORPORATION
Notes: CAMP CODE 262104											
262122	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (Left Engine) - Functional Check		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	-14	36	02 Jul 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
262123	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (Right Engine) - Functional Check		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	-14	36	02 Jul 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
262124	Engine FIRE Bottle Pressure Switch (Left) - Operational Test		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.5		60	15 Mar 2021	31 Mar 2026	30 Apr 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: NO INFORMATION SUPPLIED GPL 21/5/15											
262125	Engine FIRE Bottle Pressure Switch (Right) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1	22	60	27 May 2023	30 Jun 2028*	31 Jul 2028	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262126	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (APU) - Functional Check		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	-14	36	02 Jul 2021	30 Jun 2024*	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
262128	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1136UG	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											
262129	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1709UB	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											
262130	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1841UG	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											
262131	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903876	1139UG	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											
262132	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903931	1698UB	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											
262133	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Removal / Installation		HRS		1864.9			4316.3			0
			AFL		445			1123			0
	30903852	1836UG	MOS		87.9			31 Aug 2016			PACIFIC
			MSC					O/C			SCIENTIFIC CO
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)							Manufacturer
											Date Type
262137	Engine FIRE Bottle Low Pressure Switch (Functional Check) (Left) - Restore		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3	3536		21 Aug 2006	30 Apr 2026*		
			MSC							O/C	
Airframe		[End Of Month Item]									
Notes: ACCOMPLISH AT 120 MONTHS SINCE NEW OR ACCOMPLISHMENT OF LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, CODE 262021 AND EVERY 120 MONTHS THEREAFTER.											
262138	Engine FIRE Bottle Low Pressure Switch (Functional Check) (Right) - Restore		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3	3536		21 Aug 2006	30 Apr 2026*		
			MSC							O/C	
Airframe		[End Of Month Item]									
Notes: ACCOMPLISH AT 120 MONTHS SINCE NEW OR ACCOMPLISHMENT OF LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, CODE 262026 AND EVERY 120 MONTHS THEREAFTER.											
262139	Engine FIRE Bottle (Left) - Weight Check		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.5	42	60	15 Mar 2021	30 Apr 2026*	31 May 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
Notes: ACCOMPLISH AT 5 YEARS SINCE LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, CODE 262021. AIRCRAFT BEYOND 48 MONTHS SINCE LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30 AND E											
262140	Engine FIRE Bottle (Right) - Weight Check		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.5	42	60	15 Mar 2021	30 Apr 2026*	31 May 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
Notes: ACCOMPLISH AT 5 YEARS SINCE LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, CODE 262026. AIRCRAFT BEYOND 48 MONTHS SINCE LAST ENGINE FIRE BOTTLE - (HYDROSTATIC) FUNCTIONAL TEST, ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30 AND E											
262510	Portable Water FIRE Extinguisher (Forward Cabin) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	892480	6198	MOS		6.8			03 Jun 2023			N/A
			MSC							O/C	
Airframe											
262511	Portable Water FIRE Extinguisher (Forward Cabin) - Restore		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		96			28 Dec 2015			
			MSC							O/C	OVERHAUL
Airframe											
Notes: PN: 892480 SN: 20808.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)							Manufacturer
											Date Type
262512	Portable Water FIRE Extinguisher (Forward Cabin) -		HRS		130.8			6050.4			0
	(Proof Pressure Test) Functional Test		AFL		29			1539			0
			MOS		6.8		60	03 Jun 2023	31 Mar 2028		
			[End Of Month Item]								
Airframe											
Notes: PN: 892480 SN: <NONE>.											
262513	Portable Water FIRE Extinguisher (Forward Cabin) -		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		7.1			27 May 2023			
			MSC				O/C				
Airframe											
Notes: PN: 892480 SN: <NONE>.											
262548	Extinguisher, Bbml Server		HRS		6173.6			7.6			0
	A800100-2	SN-UNKNOWN	AFL		1562			6			0
			MOS	TSN:6	202.7			06 Feb 2007			
			MSC				O/C				
Airframe											
262549	Extinguisher, Credenza FIRE		HRS		597.1			5584.1			0
	A825100-4	SN-UNKNOWN	AFL		124			1444			0
			MOS		31.3			20 May 2021			N/A
			MSC				O/C				
Airframe											
262560	Trash Receptacle Enclosure (Aft Lavatory) - Detailed		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		6.8	-76	12	03 Jun 2023	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262561	Trash Receptacle Enclosure (Forward Lavatory) - Detailed		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		6.8	-76	12	03 Jun 2023	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262563	Trash Receptacle Enclosure (Forward Galley / Annex) -		HRS		130.8			6050.4			0
	Detailed Inspection		AFL		29			1539			0
			MOS		6.8	-76	12	03 Jun 2023	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item] [MOS: +1m/-1m]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262569	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Credenza) - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3		60	20 May 2021	31 May 2026	30 Jun 2026	
Airframe											WEIGHT CHECK
Notes: 262696 - NOT INSTALLED											
262582	Trash Receptacle FIRE Extinguisher Nozzles (Credenza) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-14	12	03 Jun 2023	20 May 2024*	20 Jun 2024	
Airframe											
Notes: 262694 - N/A IAW WO GEKBR002											
262600	Portable Halon FIRE Extinguisher (Cockpit) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	898052	X-658389	MOS	TSN:183	9.3			19 Mar 2023			N/A
			MSC								O/C
Airframe											
262601	Portable Halon FIRE Extinguisher (Cockpit) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3		12	19 Mar 2023	31 Mar 2024	30 Apr 2024	
Airframe											
Notes: PN: 898052 SN: X-658389.											
262602	Portable Halon FIRE Extinguisher (Cockpit) - Weight Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3	-24	12	19 Mar 2023	29 Feb 2024*	31 Mar 2024	
Airframe											WEIGHT CHECK
Notes: PN: 898052 SN: X-658389.											
262603	Portable Halon FIRE Extinguisher (Cockpit, Hydrostatic) - Functional Test		HRS		955.3			5225.9			0
			AFL		227			1341			0
			MOS		54.6			10 Jun 2019			
			MSC								O/C
Airframe											HYDRO CHECK
Notes: PN: 898052 SN: X-658389.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262610	Portable Halon FIRE Extinguisher (Forward Cabin) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	C354TS	H-35486522	MOS	TSN:15	6.8			03 Jun 2023			N/A
			MSC								
Airframe											
262611	Portable Halon FIRE Extinguisher (Forward Cabin) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3		12	19 Mar 2023	31 Mar 2024	30 Apr 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
Notes: PN: 100-9750 SN: <NONE>. 262621											
262612	Portable Halon FIRE Extinguisher (Forward Cabin) - Weight Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3	-24	12	19 Mar 2023	29 Feb 2024*	31 Mar 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
Notes: PN: 100-9750 SN: <NONE>.											
262613	Portable Halon FIRE Extinguisher (Foward Cabin, Hydrostatic) - Functional Test		HRS		1414.1			4767.1			0
			AFL		332			1236			0
			MOS		73.7		144	07 Nov 2017	30 Nov 2029		
	[End Of Month Item]										
Airframe											
Notes: PN: 100-9750 SN: X-101558.											
262614	Portable Halon FIRE Extinguisher (Forward Cabin) - Final Phase Restore		HRS		130.8			6050.4			0
			AFL		29			1539			0
	C354TS	H-35486522	MOS	TSN:4	6.8		72	03 Jun 2023	28 Feb 2029		N/A
	[End Of Month Item]										
Airframe											
Notes: FOR CASP/FLAG P/N 100-9750											
262630	Portable Halon FIRE Extinguisher (Aft Lavatory) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	C354TS	H-35486504	MOS	TSN:15	6.8			03 Jun 2023			N/A
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262631	Portable Halon FIRE Extinguisher (Aft Lavatory) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-76	12	03 Jun 2023	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: 100-9750 SN: <NONE>.											
262632	Portable Halon FIRE Extinguisher (Aft Lavatory) - Weight Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-94	12	03 Jun 2023	29 Feb 2024*	31 Mar 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: 100-9750 SN: <NONE>.											
262633	Portable Halon FIRE Extinguisher (Aft Lavatory, Hydrostatic) - Functional Test		HRS		1414.1			4767.1			0
			AFL		332			1236			0
			MOS		73.7		144	07 Nov 2017	30 Nov 2029		
			[End Of Month Item]								
Airframe											
Notes: PN: 100-9750 SN: X-101555.											
262634	Portable Halon FIRE Extinguisher (Aft Lavatory) - Final Phase Restore		HRS		130.8			6050.4			0
			AFL		29			1539			0
	C354TS	H-35486504	MOS	TSN:4	6.8		72	03 Jun 2023	28 Feb 2029		N/A
			[End Of Month Item]								
Airframe											
27 - Flight Controls											
270005	Aileron and Rudder Trim Control Head / Secondary Control Rods - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	528401-9	625	MOS		208.3			21 Aug 2006			MAIN SOLUTIONS
			MSC					O/C			
Airframe											
270995	Lateral Control System Rigging from Control Wheels to Wing Rear Beam Station 125		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
270998	Lateral Control System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271001	Aileron Trim Tab - Removal / Installation		HRS		6181.2			0			0
	1159CSH55300-5	0318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271002	Trim Tab Actuator (Aileron) - Removal / Installation		HRS		6181.2			0			0
	1159SCC100-25	01470	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271003	Cable, Ail Trim UPR (Wing)		HRS		6181.2			0			0
	NAS313C17-5252	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
271004	Cable, Ail Trim Lower (Wing)		HRS		6181.2			0			0
	NAS313C16-5197	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
271005	Cable, Ail Trim Lh-Fuselage		HRS		6181.2			0			0
	1159SCC562-129	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271006	Cable, Ail Trim Rh-Fuselage		HRS		6181.2			0			0
	1159SCC562-127	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271008	Aileron Trim Tab Actuator / Linkage - General Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271009	Aileron Rigging (Wing Rear Beam Station 125 to Outboard)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271010	Aileron Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271011	Aileron Control and Trim Cables In Main Wheel Wells / Wing Trailing Edge - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271012	Lateral Control System - Friction Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
			MSC					O/C			
Airframe											
271013	Aileron Input Control ROD Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	A-UV04-403	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271014	Aileron Input Control ROD Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	A-GUV04-403	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
											VOUGHT AIRCRAFT INDUSTRIES INC.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271021	Aileron Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	1159CS55004-5	0318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271022	Aileron Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
	1159CS55005-1	0318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
271023	Aileron Primary Pressure Seals - Removal / Installation		HRS		6181.2			0			0
	1159C50020-3/5/7	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
271101	Aileron Control Wheel (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCF410-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ESTERLINE MASON
	Airframe		MSC					O/C			
271102	Aileron Control Wheel (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCF410-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ESTERLINE MASON
	Airframe		MSC					O/C			
271103	Aileron / Flight Spoiler Control System - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
271105	Aileron Actuator Load Relief Bungee (Left) - Removal / Installation		HRS		6181.2			0			0
	1159C20014-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM - APPLETON
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271106	Aileron Actuator Load Relief Bungee (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159C20014-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM - APPLETON
			MSC								
Airframe											
271107	Aileron Actuator Load Relief Bungee Assembly (Left) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
Airframe	[HRS: +50/-50]										
Notes: NEED MOD NO,ON CMP CODE 271105											
271108	Aileron Actuator Load Relief Bungee Assembly (Right) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
Airframe	[HRS: +50/-50]										
Notes: NEED MOD NO,ON CMP CODE 271106											
271109	Aileron Linkage Disconnect		HRS		6181.2			0			0
	1159SCC565-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TYEE AIRCRAFT INC
			MSC								INC
Airframe	O/C										
271110	Aileron Inter-Column Linkage Disconnect Assemblies - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		6.9	-3	48	31 May 2023	31 May 2027*	30 Jun 2027	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
271121	Aileron Primary Outboard Cable Assembly FS 101 - FS 605 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-17	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe	O/C										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271122	Aileron Primary Inboard Cable Assembly FS 101 - FS 605		HRS		6181.2			0			0
	(Left) - Removal / Installation		AFL		1568			0			0
	1159SCC561-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
271123	Aileron Primary Outboard (Left Forward) Cable Assembly		HRS		6181.2			0			0
	FS 605 - Rbs 125 - Removal / Installation		AFL		1568			0			0
	1159SCC561-19	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271124	Aileron Primary Inboard (Aft) Cable Assembly FS 605 -		HRS		6181.2			0			0
	Rbs 125 (Left) - Removal / Installation		AFL		1568			0			0
	1159SCC561-23	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271125	Right Aileron Primary Outboard Cable Assembly FS 101 -		HRS		6181.2			0			0
	FS 335 - Removal / Installation		AFL		1568			0			0
	1159SCC561-29	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271126	Right Aileron Primary Outboard Cable Assembly FS 335 -		HRS		6181.2			0			0
	FS 401 - Removal / Installation		AFL		1568			0			0
	1159SCC561-27	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271127	Right Aileron Primary Outboard Cable Assembly FS 401 -		HRS		6181.2			0			0
	FS 605 - Removal / Installation		AFL		1568			0			0
	1159SCC561-25	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271128	Aileron Primary Inboard Cable Assembly FS 101 - FS 605		HRS		6181.2			0			0
	(Right) - Removal / Installation		AFL		1568			0			0
	1159SCC561-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
271129	Aileron Primary Outboard (Right Forward) Cable		HRS		6181.2			0			0
	Assembly FS 605 - Rbs 125 - Removal / Installation		AFL		1568			0			0
	1159SCC561-19	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271130	Aileron Primary Inboard (Aft) Cable Assembly FS 605 -		HRS		6181.2			0			0
	Rbs 125 (Right) - Removal / Installation		AFL		1568			0			0
	1159SCC561-23	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC								SPECIALTY
Airframe											
271131	Aileron Primary Cable Assembly Forward Rbs 125 - Rbs		HRS		6181.2			0			0
	285 (Left Inboard) - Removal / Installation		AFL		1568			0			0
	NAS316C17-1660	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
271132	Aileron Primary Cable Assembly Forward Rbs 285 - Rbs		HRS		6181.2			0			0
	360 (Left Outboard) - Removal / Installation		AFL		1568			0			0
	NAS316C17-0816	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
271133	Aileron Primary Cable Assembly Aft Rbs 125 - Rbs 252		HRS		2357.4			3823.8			0
	(Left Inboard) - Removal / Installation		AFL		600			968			0
	NAS316C17-1330	NSN	MOS		112.2			22 Aug 2014			ASSEMBLY
			MSC								SPECIALTY
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271134	Aileron Primary Cable Assembly Aft Rbs 252 - Rbs 360 (Left Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	NAS316C16-1146	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								HPG
Airframe											
271135	Aileron Primary Cable Assembly Forward Rbs 125 - Rbs 285 (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	NAS316C14-0914	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
271136	Aileron Primary Cable Assembly Forward Rbs 285 - Rbs 360 (Right Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	NAS316C15-1544	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
271137	Aileron Primary Cable Assembly Aft Rbs 125 - Rbs 252 (Right Inboard) - Removal / Installation		HRS		3320.4			2860.8			0
			AFL		821			747			0
	NAS316C17-1330	NSN	MOS		136.4			16 Aug 2012			
			MSC								
Airframe											
271138	Aileron Primary Cable Assembly Aft Rbs 252 - Rbs 360 (Right Outboard) - Removal / Installation		HRS		3320.4			2860.8			0
			AFL		821			747			0
	NAS316C16-1146	NSN	MOS		136.4			16 Aug 2012			
			MSC								
Airframe											
271141	Aileron Actuator Load Relief Bungee (Left) - Load Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			MSC								
Airframe											
271142	Aileron Actuator Load Relief Bungee (Right) - Load Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271143	Elevator Actuator Load Relief Bungee (Left) - Load Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			MSC					O/C			
Airframe											
271144	Elevator Actuator Load Relief Bungee (Right) - Load Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			MSC					O/C			
Airframe											
271203	Aileron Trim Tab Control System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271204	Aileron Trim Tab Control System - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271301	Force Link Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	1159C50258-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271302	Force Link Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
	1159C50258-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
271303	Aileron Hardover Prevention System (Left) - Operational Check		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271304	Aileron Hardover Prevention System (Right) - Operational Check		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
			[HRS: +50/-50]								
Airframe											
271305	Aileron Actuator Hydraulic Deactivation Valves (Left Inboard) - Removal / Installation		HRS		6181.2			0			0
	1159SCH501-17		AFL		1568			0			0
	EFS1929		MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
271306	Aileron Actuator Hydraulic Deactivation Valves (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
	1159SCH501-17		AFL		1568			0			0
	EFS1928		MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
271307	Aileron Hydraulic Boost Actuator (Left) - Detailed Inspection		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.7			07 Jan 2008			
			MSC				O/C				
Airframe											
Notes: N/A BY P/N AND SER NO INSTALLED											
271308	Aileron Hydraulic Boost Actuator (Right) - Detailed Inspection		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.7			07 Jan 2008			
			MSC				O/C				
Airframe											
Notes: N/A BY P/N AND SER NO INSTALLED											
271309	Aileron Hydraulic Boost Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCH252-59		AFL		1568			0			0
	4810		MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271310	Aileron Hydraulic Boost Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH252-60	4815	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271311	Aileron Force Link Microswitch (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H50699-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271312	Aileron Force Link Microswitch (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H50699-2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271313	Microsw, L Force Link-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271314	Microsw, R Force Link-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271315	Aileron Hydraulic Actuator Deactivation Valve (Left) - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
271316	Aileron Hydraulic Actuator Deactivation Valve (Right) - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271317	Valve,Ail ACT Deactive-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
271319	Filter, L Aileron ACT-Inspect		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
271320	Filter, R Aileron ACT-Inspect		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
271401	Aileron Position Transducer (Left) - Removal / Installation		HRS		6181.2			0			0
	3A1316A	A1221	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
271402	Aileron Position Transducer (Right) - Removal / Installation		HRS		6181.2			0			0
	3A1316A	A1293	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			IPECO INC
	Airframe			MSC				O/C			
271403	Sensor, L Cont Wheel Pos Rvdt		HRS		6173.3			7.9			0
	1159SCF452-5	A0583	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			MPC PRODUCTS
	Airframe			MSC				O/C			
271404	Sensor, R Cont Wheel Pos Rvdt		HRS		6173.3			7.9			0
	1159SCF452-5	A0502	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			MPC PRODUCTS
	Airframe			MSC				O/C			
271410	Sensor, Aileron Trim FDR		HRS		6173.3			7.9			0
	1159SCF452-5	A0731	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			MPC PRODUCTS
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272001	Rudder - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159CS52205-802	GB2517	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7.2			24 May 2023			N/A
	Airframe		MSC								
272002	Rudder Hydraulic Actuator - Removal / Installation		HRS		3856.2			2325			0
	1159SCH502-63	0186CF	AFL		950			618			0
			MOS		148.5			12 Aug 2011			PARKER HANNIFIN CORPORATION
	Airframe		MSC								
272003	Rudder Trim Actuator - Removal / Installation		HRS		6181.2			0			0
	159SCC100-23	1213	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH SENSOR SYSTEMS
	Airframe		MSC								
272004	Rudder Torque Tube Bearing - Lubrication		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.1		48	27 Apr 2023	30 Apr 2027	31 May 2027	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
272005	Rudder Torque Tube - Removal / Installation		HRS		130.8			6050.4			0
	1159B21605-25S1	SN-UNKNOWN	AFL		29			1539			0
			MOS		8.1			26 Apr 2023			N/A
	Airframe		MSC								
272006	Rudder Hydraulic Deactivation Valve (No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCH501-17	EFS2036	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
	Airframe		MSC								
272007	Rudder Hydraulic Deactivation Valve (No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCH501-17	EFS2044	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272008	Rudder Hydraulic Deactivation Valve (No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH257-7	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC								
Airframe											
272011	Rudder Control System - Rigging		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
272012	Rudder Torque Tube - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	96	27 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
272013	Rudder System - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
			MSC								
Airframe											
272100	Rudder Pedals - Lubrication		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			AFL		150			1418			0
			MOS		45.3		72	20 Mar 2020	31 Mar 2026	30 Apr 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
272101	Rudder Primary Cable Assembly (Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-31	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
272102	Rudder Primary Cable Assembly (Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-35	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272105	Rudder Primary Cable Assembly (Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-33	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
272106	Rudder Primary Cable Assembly (Lower Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-37	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
272107	Rudder Control and Trim Cables In Pressurized Areas of Fuselage / Overwing to Aft Wing Links - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
272108	Rudder Control and Trim Cables In Main Wheel Well / Tail Compartment - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
272109	Rudder Trim Cable Assemblies (Left Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC562-43	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	ASSEMBLY SPECIALTY PRODUCTS INC
Airframe											
272110	Rudder Trim Cable Assemblies (Right Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC562-47	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	ASSEMBLY SPECIALTY PRODUCTS INC
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272111	Rudder Trim Cable Assemblies (Left Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC562-69	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC					O/C			
Airframe											
272112	Rudder Trim Cable Assemblies (Right Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC562-71	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC					O/C			
Airframe											
272113	Rudder and Trim Control System - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
			MSC					O/C			
Airframe											
272114	Rudder Primary Cable Pressure Seals - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
272118	Rudder Primary Pulley(S) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
272121	Rudder Trim Pulleys - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
272201	Rudder Trim Control Knob - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	528401-9	SN-UNKNOWN	MOS		208.3			21 Aug 2006			MAIN SOLUTIONS
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272202	Rudder Trim Artificial Feel Bungee Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159C20350-23	FAH0492	MOS		208.3			21 Aug 2006			FRISBY
	Airframe		MSC					O/C			AEROSPACE LLC.
272203	Rudder Trim Control System - Functional Test		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
	Airframe		MSC					O/C			
272204	Rudder Trim System - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
272301	Rudder Hardover Prevention System - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
	Airframe										[HRS: +50/-50]
272302	Valve, Rudder Hyd Selector		HRS		6181.2			0			0
	1159SCH501-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAISER FLUID
	Airframe		MSC					O/C			TECHNOLOGIES
272303	Standby Rudder System - Operational Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.8	-17	48	05 Jul 2022	30 Jun 2026*	31 Jul 2026	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
272401	Rudder Position Transducer - Removal / Installation		HRS		6173.3			7.9			0
	1159SCF452-5	A0586	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			IPECO INC
	Airframe		MSC					O/C			
272402	Potentiometer, Rudder NWS		HRS		6181.2			0			0
	1159SCL500-17	1349	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			EATON
	Airframe		MSC					O/C			AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272403	Potentiometer, Rudder Pedals		HRS		6181.2			0			0
	1159SCF452-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			MPC PRODUCTS
	Airframe		MSC					O/C			
272501	Valve, Rud Aux Sys Norm/Stby		HRS		6181.2			0			0
	1159SCH257-9	3852	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
273001	Elevator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159CS52093-419	318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
273002	Elevator (Right) - Removal / Installation		HRS		6181.2			0			0
	1159CS52093-420	318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
273005	Elevator Control System - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
	Airframe		MSC					O/C			
273006	Elevator Actuator Load Relief Bungee Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	1159C20014	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
273007	Elevator Actuator Load Relief Bungee Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
	1159C20014	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273008	Elevator Actuator Load Relief Bungee (Left) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			[HRS: +50/-50]								
Airframe											
Notes: NEED DASH NO AND SER NO,ON CMP CODE 273006											
273009	Elevator Actuator Load Relief Bungee (Right) - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		7.1			25 May 2023			
			[HRS: +50/-50]								
Airframe											
Notes: NEED DASH NO AND SER NO,ON CMP CODE 273007											
273011	Elevator Control ROD (Left)		HRS		3522.2			2659			0
	1159C52015-403	0001	AFL		865			703			0
			MOS		140.7			07 Apr 2012			
			MSC				O/C				
Airframe											
273012	Elevator Control ROD (Right)		HRS		3522.2			2659			0
		0007	AFL		865			703			0
			MOS		140.7			07 Apr 2012			
			MSC				O/C				
Airframe											
273013	Elevator Crank Assembly (Left)		HRS		6181.2			0			0
	1159CM52006-401	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
273014	Elevator Crank Assembly (Right)		HRS		6181.2			0			0
	1159CM52006-401	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
273019	Elevator Drive ROD - Lubrication		HRS		130.8			6050.4			0
			AFL		29			1539			0
	(273019)		MOS		7.9	-108	96	02 May 2023	31 Jan 2031*	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273020	Elevator Trim Drum Chain and Master Link - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		18**	26 Feb 2007	30 Sep 2024		
	Airframe		[End Of Month Item]								
273023	Elevator Trim Tab (Left) - Removal / Installation		HRS		6181.2			0			0
	1159CS52095-421	321	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC				O/C				
273024	Elevator Trim Tab (Right) - Removal / Installation		HRS		3522.2			2659			0
	1159CS52095-423	531	AFL		865			703			0
			MOS		141.5			14 Mar 2012			
	Airframe		MSC				O/C				
273025	Elevator Trim Tab Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	159SCC100-25	01496	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PROFESSIONAL AIRCRAFT ACCESSORIES
	Airframe		MSC				O/C				
273026	Elevator Trim Tab Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	159SCC100-25	01498	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PROFESSIONAL AIRCRAFT ACCESSORIES
	Airframe		MSC				O/C				
273028	Elevator Control System - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
273030	Elevator Trim Tab Control System - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273032	Longitudinal Control System Friction Check - Inspection / Check		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
			[HRS: +50/-50]								
Airframe											
273050	Torque Tube, Elevator		HRS		6181.2			0			0
	1159SCB502-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ALCOA
			MSC				O/C				FASTENING SYSTEMS CITY OF INDUSTRY
Airframe											
273093	Elevator Primary Cable Assemblies (Right Lower Forward) - Removal / Installation		HRS		6181.2			0			0
	1159SCC561-39	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC				O/C				SPECIALTY PRODUCTS INC
Airframe											
273094	Elevator Primary Cable Assemblies (Right Upper Forward) - Removal / Installation		HRS		6181.2			0			0
	1159SCC561-43	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
273097	Elevator Primary Cable Assemblies (Right Lower Aft) - Removal / Installation		HRS		6181.2			0			0
	1159SCC561-41	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC				O/C				SPECIALTY PRODUCTS INC
Airframe											
273098	Elevator Primary Cable Assemblies (Right Upper Aft)- Removal / Installation		HRS		6181.2			0			0
	1159SCC561-45	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ASSEMBLY
			MSC				O/C				SPECIALTY PRODUCTS INC
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273099	Elevator Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
273100	Elevator Control and Trim Cables In Main Wheel Well and Tail Compartment - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
273101	Elevator Primary Cable Assemblies (Left Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-39	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC					O/C			
Airframe											
273102	Elevator Primary Cable Assemblies (Left Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-43	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
273103	Cable Assembly, Elevator Primary (Left Lower Middle)		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
273104	Cable Assembly, Elevator Primary (Left Upper Middle)		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
273105	Elevator Primary Cable Assemblies (Left Lower Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-41	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273106	Elevator Primary Cable Assemblies (Left Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC561-45	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
273109	Eddy Current Damper (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC202-1	A0833	MOS		208.3			21 Aug 2006			MOOG INCORPORATED
			MSC								
Airframe											
273110	Eddy Current Damper (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC202-1	A0830	MOS		208.3			21 Aug 2006			MOOG INCORPORATED
			MSC								
Airframe											
273111	Elevator Disconnect Cable Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC564-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			TYEE AIRCRAFT INC
			MSC								
Airframe											
273113	Elevator Inter-Column Linkage Disconnect Assembly - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		6.9	-7	48	31 May 2023	31 May 2027*	30 Jun 2027	
Airframe											
273115	Elevator Hydraulic Deactivation Valves (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-17	EFS2041	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											
273116	Elevator Hydraulic Deactivation Valves (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-17	EFS2049	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273117	Elevator Hydraulic Deactivation Valves (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-17	EFS2043	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											
273118	Elevator Hydraulic Deactivation Valves (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-17	EFS2048	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											
273121	Elevator Input / Output Crank Assemblies (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159C50107-11	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
273122	Elevator Input / Output Crank Assemblies (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159C50108-11	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
273133	Pilot Elevator Control Column - Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	1159G50103-800-15	G00559704	MOS		203.5			15 Jan 2007			
			MSC								
Airframe											
Notes: CAMP CODE 270001											
273134	CO-Pilot Elevator Control Column - Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	1159G50103-800-16	G00559705	MOS		203.5			15 Jan 2007			
			MSC								
Airframe											
Notes: CAMP CODE 270002											
273201	Stall Barrier Angle of Attack Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	0861FW1	738	MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273202	Stall Barrier Angle of Attack Sensor (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	0861FW1	740	MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
			MSC								
Airframe											
273203	Stick Shaker Assembly (Pilot) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	C-36602	7082	MOS		208.3			21 Aug 2006			SAFE FLIGHT INSTRUMENT CORPORATION
			MSC								
Airframe											
273204	Stick Shaker Assembly (Copilot) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	C-36602	7086	MOS		208.3			21 Aug 2006			SAFE FLIGHT INSTRUMENT CORPORATION
			MSC								
Airframe											
273205	Stall Barrier - Functional Test		HRS		2367.8			3813.4			0
			AFL		603			965			0
			MOS		113.2			24 Jul 2014			
			MSC								
Airframe											
273206	Stall Barrier Actuator - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH503-55	0383	MOS		208.3			21 Aug 2006			EATON AEROSPACE
			MSC								
Airframe											
273209	Stall Barrier System - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
Notes: PN: 1159H47073-1 SN: <NONE>.											
273306	Elevator Trim Tab Control System - Functional Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273401	Elevator Hydraulic Dual Tandem Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH252-167	4992	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
273402	Elevator Hydraulic Dual Tandem Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH252-168	4975	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
273405	Elevator Hardover Prevention System - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
Airframe	[HRS: +50/-50]										
273407	Elevator Hydraulic Dual Tandem Actuator (Left) - Detailed Inspection		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179			29 Jan 2009			
			MSC					O/C			
Airframe											
Notes: N/A BY P/N AND SER NO INSTALLED											
273408	Elevator Hydraulic Dual Tandem Actuator (Right) - Detailed Inspection		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179			29 Jan 2009			
			MSC					O/C			
Airframe											
Notes: N/A BY P/N AND SER NO INSTALLED											
273501	Elevator Rotary Variable Differential Transducer (Rvdt) {Left} - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	3A1-315A	A0680	MOS		65.4			17 Jul 2018			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273502	Elevator Rotary Variable Differential Transducer (Rvdt)		HRS		1245.7			4935.5			0
	{Right} - Removal / Installation		AFL		296			1272			0
	3A1-315A	A0367	MOS		65.4			17 Jul 2018			
			MSC								
Airframe											
273503	Transducer, L Elv Trim Pos		HRS		6181.2			0			0
	3A2-266A	A0397	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
273504	Transducer, R Elv Trim Pos		HRS		6181.2			0			0
	3A2-266A	A0416	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
273505	Rvdt, L Elv Cont Column Posit		HRS		6173.3			7.9			0
	1159SB51917-2	A1180	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULSTREAM SAV
			MSC								- FLIGHT TEST IPT
Airframe											
273506	Rvdt, R Elv Cont Column Posit		HRS		6173.3			7.9			0
	1159SB51917-1	A1292	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULSTREAM SAV
			MSC								- FLIGHT TEST IPT
Airframe											
273525	Elevator Primary Pulley(S) - Removal / Installation		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
273530	Elevator Primary Pressure Seals - Removal / Installation		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274101	Flap / Horizontal Stabilizer Control Unit - Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	1159SCC651-5	404	MOS		203.4			16 Jan 2007			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
274102	Module, #1 Flap/Stab Auto Rig		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC509-3	0349	MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
274103	Module, #2 Flap/Stab Auto Rig		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC509-4	320	MOS		208.3			21 Aug 2006			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
274105	Flap / Stabilizer Control System - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9			02 Jul 2021			
	Airframe		MSC					O/C			
274106	Emergency Horizontal Stabilizer (Backup MODE) - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1	3	48	26 May 2023	31 May 2027*	30 Jun 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
274201	Horizontal Stabilizer Actuator - Removal / Installation		HRS	TSN:4218.1	1244.4			4936.8			0
			AFL	TSN:2539	290			1278			0
	1159SCC500-9	0404	MOS		64.4			16 Aug 2018			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
274202	Horizontal Stabilizer Actuator - Lubrication		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	60	36	02 Jul 2021	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

Notes: PN: 1159SCC500-5 SN: <NONE>.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274203	Horizontal Stabilizer Actuator - Adjustment / Test		HRS		1244.4			4936.8			0
			AFL		290			1278			0
			MOS		64.4			16 Aug 2018			
	Airframe		MSC					O/C			
Notes: PN: 1159SCC500-9 SN: 0404.											
274204	Horizontal Stabilizer Actuator (Installed Life) - Restore		HRS	TSN:4218.1	1244.4			4936.8			0
	1159SCC500-9	0404	AFL	TSN:2539	290			1278			0
			MOS		64.4		144	16 Aug 2018	31 Jul 2030		
	Airframe		[End Of Month Item]								
274205	Horizontal Stabilizer Actuator (Upper Gearbox) - Lubrication		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.6	53	72	09 Jul 2018	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
274206	Horizontal Stabilizer Actuator (Total Life) - Restore		HRS	TSN:4218.1	1244.4			4936.8			0
	1159SCC500-9	0404	AFL	TSN:2539	290			1278			0
			MOS		64.4		168	16 Aug 2018	23 Jul 2032		
	Airframe										
274301	Horizontal Stabilizer Position Resolver - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC652-11	A0060	MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
274302	Horizontal Stabilizer Position Resolver - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
Notes: PN: 1159SCC652-11 SN: A0060.											
275001	Flap Assembly (Left) - Removal / Installation		HRS	TSN:7.9	6173.3			7.9			0
	1159CS54102-23	0321	AFL	TSN:6	1562			6			0
			MOS	TSN:5	203.4			16 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275002	Flap Assembly (Right) - Removal / Installation		HRS	TSN:7.9	6173.3			7.9			0
	1159CS54102-24	0321	AFL	TSN:6	1562			6			0
			MOS	TSN:5	203.4			16 Jan 2007			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275003	Flap System - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
275004	Flap Control System - Functional Test		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		94.8			03 Feb 2016			
	Airframe		MSC					O/C			
275005	Flaps System - Rigging		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
275007	L/H Flap Control Relay (K55A)		HRS		6181.2			0			0
	1159AV20504-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
275008	R/H Flap Control Relay (K55A)		HRS		6181.2			0			0
	1159AV20504-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
275011	Flap Actuator Gearbox (Left Inboard) - Lubrication		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			AFL		600			968			0
			MOS		112.2		192	22 Aug 2014	31 Aug 2030	30 Sep 2030	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
275012	Flap Actuator Gearbox (Right Inboard) - Lubrication		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			AFL		600			968			0
			MOS		112.2		192	22 Aug 2014	31 Aug 2030	30 Sep 2030	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275013	Flap Actuator Gearbox (Left Outboard) - Lubrication		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			AFL		600			968			0
			MOS		112.2		192	22 Aug 2014	31 Aug 2030	30 Sep 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275014	Flap Actuator Gearbox (Right Outboard) - Lubrication		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			AFL		600			968			0
			MOS		112.2		192	22 Aug 2014	31 Aug 2030	30 Sep 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275015	Inboard Flap Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCC601-3	0330	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
275016	Inboard Flap Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCC601-3	0332	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
275017	Outboard Flap Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCC602-3	0327	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
275018	Outboard Flap Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCC602-3	0328	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
275019	Flap Actuator Travel Nut (Left) - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		7.9		24	02 May 2023	31 May 2025	30 Jun 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: WO SC13165											
275020	Flap Actuator Travel Nut (Right) - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		7.9		24	02 May 2023	31 May 2025	30 Jun 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275021	A Track Flap Rollers (Left Inboard) - Removal / Installation		HRS		6181.2			0			0
	KRP172108FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
	Airframe		MSC					O/C			
275022	A Track Flap Rollers (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
	KRP172108FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
	Airframe		MSC					O/C			
275023	A Track Flap Rollers (Left Outboard) - Removal / Installation		HRS		6181.2			0			0
	KRP172108FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
	Airframe		MSC					O/C			
275024	A Track Flap Rollers (Right Outboard) - Removal / Installation		HRS		6181.2			0			0
	KRP172108FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
	Airframe		MSC					O/C			
275025	A Track Flap Rollers (Left Trailing Edge) - Removal / Installation		HRS		6181.2			0			0
	MS14104-4	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			WESCO AIRCRAFT
	Airframe		MSC					O/C			
275026	A Track Flap Rollers (Right Trailing Edge) - Removal / Installation		HRS		6181.2			0			0
	MS14104-4	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			WESCO AIRCRAFT
	Airframe		MSC					O/C			
275027	B Track Flap Rollers (Left Outboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
	KRP170810FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275028	B Track Flap Rollers (Right Outboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170810FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC								
Airframe											
275029	B Track Flap Rollers (Left Outboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170912FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC								
Airframe											
275030	B Track Flap Rollers (Right Outboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170912FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC								
Airframe											
275031	B Track Flap Rollers (Left Outboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275032	B Track Flap Rollers (Right Outboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP5520-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275033	B Track Flap Rollers (Left Inboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275034	B Track Flap Rollers (Right Inboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275035	B Track Flap Rollers (Left Inboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170810FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC					O/C			
Airframe											
275036	B Track Flap Rollers (Right Inboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170810FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC					O/C			
Airframe											
275037	B Track Flap Rollers (Left Inboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170912FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC					O/C			
Airframe											
275038	B Track Flap Rollers (Right Inboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170912FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC					O/C			
Airframe											
275039	C Track Flap Rollers (Left Inboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
275040	C Track Flap Rollers (Right Inboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
275041	C Track Flap Rollers (Left Inboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275042	C Track Flap Rollers (Right Inboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
275043	C Track Flap Rollers (Left Inboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
275044	C Track Flap Rollers (Right Inboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
275045	C Track Flap Rollers (Left Outboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170708FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC							O/C	
Airframe											
275046	C Track Flap Rollers (Right Outboard Upper Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP171708FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
275047	C Track Flap Rollers (Left Outboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP172010FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC							O/C	
Airframe											
275048	C Track Flap Rollers (Right Outboard Upper Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP172010FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275049	C Track Flap Rollers (Left Outboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
275050	C Track Flap Rollers (Right Outboard Lower Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
275051	D Track Flap Rollers (Left Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
275052	D Track Flap Rollers (Right Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
275053	D Track Flap Rollers (Left Inboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170708FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		KAMATICS CORPORATION
Airframe											
275054	D Track Flap Rollers (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP170708FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		KAMATICS CORPORATION
Airframe											
275055	D Track Flap Rollers (Left Trailing Edge) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP172010FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		KAMATICS CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275056	D Track Flap Rollers (Right Trailing Edge) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP172010FT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			KAMATICS CORPORATION
			MSC								
Airframe											
275057	Flap Roller, Left (C-19)		HRS		6181.2			0			0
			AFL		1568			0			0
	KPR552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275058	Flap Roller, Right (C-19)		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275059	Flap Roller, Left (C-20)		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275060	Flap Roller, Right (C-20)		HRS		6181.2			0			0
			AFL		1568			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
275061	Flap Roller, Left (C-21)		HRS		6181.2			0			0
			AFL		1568			0			0
	MS14104-4	SN-UNKNOWN	MOS		208.3			21 Aug 2006			WESCO AIRCRAFT
			MSC								
Airframe											
275062	Flap Roller, Right (C-21)		HRS		6181.2			0			0
			AFL		1568			0			0
	MS14104-4	SN-UNKNOWN	MOS		208.3			21 Aug 2006			WESCO AIRCRAFT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275063	Flap Roller, Left (D-22)		HRS		6181.2			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275064	Flap Roller, Right (D-22)		HRS		6181.2			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275065	Flap Roller, Left (D-23)		HRS		6181.2			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275066	Flap Roller, Right (D-23)		HRS		6181.2			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275067	Flap Roller, Left (D-24)		HRS		6181.2			0			0
	MS14104-4	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			WESCO
	Airframe		MSC					O/C			AIRCRAFT
275068	Flap Roller, Right (D-24)		HRS		6181.2			0			0
	MS14104-4	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			WESCO
	Airframe		MSC					O/C			AIRCRAFT
275102	Flap Control Handle - Removal / Installation		HRS		6181.2			0			0
	3F3120001B	B0363	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			MPC PRODUCTS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275110	Flap Attach Points (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
			[End Of Month Item]								
275111	Flap Attach Points (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
			[End Of Month Item]								
275201	Flap Power Drive Unit - Removal / Installation		HRS		6181.2			0			0
	1159SCC505-7	0370B	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe			MSC				O/C			SUNDSTRAND
			[End Of Month Item]								
275202	Valve, Flap Selector		HRS		6181.2			0			0
	1159SCH501-	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
			[End Of Month Item]								
275302	Flap Tracks - General Visual Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1		48	27 Jun 2022	30 Jun 2026	31 Jul 2026	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
			[End Of Month Item]								
275305	Flap Torque Shaft (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe			MSC				O/C			SUNDSTRAND
			[End Of Month Item]								
275306	Flap Torque Shaft (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON
	Airframe			MSC				O/C			SUNDSTRAND
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275307	Flap Torque Shaft (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-25	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275308	Flap Torque Shaft (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-25	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275309	Flap Torque Shaft (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-27	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275310	Flap Torque Shaft (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-27	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275311	Flap Torque Shaft (Left No. 4) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275312	Flap Torque Shaft (Right No. 4) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275313	Flap Torque Shaft (Left No. 5) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-21	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275314	Flap Torque Shaft (Right No. 5) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-21	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275315	Flap Torque Shaft (Left No. 6) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-19	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275316	Flap Torque Shaft (Right No. 6) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-19	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275317	Flap Torque Shaft (Left No. 7) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-17	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275318	Flap Torque Shaft (Right No. 7) - Removal / Installation		HRS		6181.2			0			0
	1159SCC504-17	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275401	Flap Position Feedback Resolver Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCC603-1	0371	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275402	Flap Position Feedback Resolver Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC603-1	0360	MOS		208.3			21 Aug 2006			HAMILTON SUNDSTRAND
			MSC								
Airframe											
276001	Ground Spoiler Assembly (Left) - Removal / Installation		HRS	TSN:6387.5	1245.7			4935.5			0
			AFL	TSN:2339	296			1272			0
	1159CS55402-1	0035	MOS		65.4			17 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
276002	Ground Spoiler Assembly (Right) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	1159CS55402-4	S0025A	MOS	TSN:67	65.4			17 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
276003	Inboard Flight Spoiler Assembly (Left) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	1159CS55403-101	0239	MOS		65.4			17 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
276004	Outboard Flight Spoiler Assembly (Left) - Removal / Installation		HRS	TSN:895.5	1245.7			4935.5			0
			AFL	TSN:363	296			1272			0
	1159CS55404-1	0381	MOS		65.5			13 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
276005	Inboard Flight Spoiler Assembly (Right) - Removal / Installation		HRS	TSN:6254.5	1245.7			4935.5			0
			AFL	TSN:1970	296			1272			0
	1159CS55403-102	0346	MOS		65.4			17 Jul 2018			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276006	Outboard Flight Spoiler Assembly (Right) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	1159CS55404-2	S08	MOS	TSN:141	65.4			17 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
276007	Ground Spoiler Actuator Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH305-25	2241	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
276008	Ground Spoiler Actuator Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH305-26	2235	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
276009	Flight Spoiler Actuator Assembly (Left) - Removal / Installation		HRS	TSN:1350	4831.2			1350			0
			AFL	TSN:396	1172			396			0
	1159SCH250-27	2958	MOS	TSN:41	167.5			15 Jan 2010			
			MSC								
Airframe											
276010	Flight Spoiler Actuator Assembly (Right) - Removal / Installation		HRS	TSN:1350	4831.2			1350			0
			AFL	TSN:396	1172			396			0
	1159SCH250-28	2923	MOS	TSN:41	167.5			15 Jan 2010			
			MSC								
Airframe											
276011	Spoiler Hydraulic Deactivation Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-19	EFS0496	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											
276012	Spoiler Hydraulic Deactivation Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH501-19	EFS0498	MOS		208.3			21 Aug 2006			EFS AEROSPACE, INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276013	Valve,Gnd Spoil Press Cont MOD		HRS		655.48			5525.72			0
	1159SCH507-59	0128	AFL		147			1421			0
			MOS		39.9			02 Sep 2020			
	Airframe		MSC					O/C			
276014	Switch, Ground Spoiler Press		HRS		6181.2			0			0
	1159SCH213-5	6479	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM BRN SPARES IPT
	Airframe		MSC					O/C			
276015	Selector Hyd, L Spoiler		HRS		6181.2			0			0
	1159SCH501-17	EFS1921	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276016	Selector Hyd, R Spoiler		HRS		6181.2			0			0
	1159SCH501-17	EFS1955	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276017	Switch, Gnd Spoiler Arming		HRS		6181.2			0			0
	GAS850A322	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KORRY ELECTRONICS
	Airframe		MSC					O/C			
276099	Ground Spoiler Hydraulic Pressure Switch - Removal / Installation		HRS		6181.2			0			0
	1159SCH213-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276101	Speed Brake Cables (Left) - Removal / Installation		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276102	Speed Brake Cables (Right) - Removal / Installation		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276104	Speed Brake Cable Assemblies In Fuselage and Overwing AREA to Aft Links - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276105	Speed Brake Cable Assemblies In Main Wheel Well / Wing Trailing Edge - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276106	Speed Brake Control System - Functional Test		HRS		4282.2			1899			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276107	Speed Brake Handle Assembly - Removal / Installation		HRS		955.3			5225.9			0
	3F2043M200A	A0034	AFL		227			1341			0
			MOS		54.7			07 Jun 2019			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276109	Sector, Lh Speed Brake		HRS		6181.2			0			0
	1159CM50204-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276110	Sector, Rh Speed Brake		HRS		6181.2			0			0
	1159CM50204-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
276111	Overlay, Speedbrake Handle		HRS		6181.2			0			0
	3F24705001C	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276112	Overlay, Speedbrake Panel		HRS	TSN:5515.4	665.8			5515.4			0
	3F24705001C	218	AFL	TSN:1418	150			1418			0
			MOS	TSN:164	44.8			05 Apr 2020			N/A
	Airframe		MSC					O/C			
276130	Speed Brake Control Lever		HRS		6181.2			0			0
	3F2120001B	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276140	Speed Brake Cable Assemblies - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276201	Ground Spoiler Auto Deploy Rejected Takeoff MODE - Operational Test		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1	1	48	26 May 2023	31 May 2027*	30 Jun 2027	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
276202	Ground Spoiler Manual Retract MODE - Operational Test		HRS		654.07		1000	5527.13	6527.13	6577.13	0
			AFL		145			1423			0
			MOS		39.8		48	04 Sep 2020	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
276203	Ground Spoiler System - Functional Test		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
	Airframe		MSC					O/C			
276205	Ground Spoiler Output Bell Crank (Left) - Removal / Installation		HRS		6181.2			0			0
	1159CM50232-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276206	Ground Spoiler Output Bell Crank (Right) - Removal / Installation		HRS		6181.2			0			0
	1159CM50232-6	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276207	Ground Spoiler Pressure Control Module - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH507-55	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
276209	L/H Flap Pillow Block #1		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276210	R/H Flap Pillow Block #1		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276211	L/H Flap Pillow Block #2		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276212	R/H Flap Pillow Block #2		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276213	L/H Flap Pillow Block #3		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276214	R/H Flap Pillow Block #3		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276215	L/H Flap Pillow Block #4		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCC504-15	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276216	R/H Flap Pillow Block #4		HRS		6181.2			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276217	L/H Flap Pillow Block #5		HRS		6181.2			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276218	R/H Flap Pillow Block #5		HRS		6181.2			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276301	Inboard Flight Spoiler Bell Crank (Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159CM50208-7	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276302	Inboard Flight Spoiler Bell Crank (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159CM50208-8	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
276303	Outboard Flight Spoiler Bell Crank (Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159CM50209-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
276304	Outboard Flight Spoiler Bell Crank (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159CM50209-6	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276321	Outboard Flight Spoiler Bellcrank (Left) - Special Detailed Inspection		HRS		404.7			5776.5			0
			AFL		92		1500	1476	2976		0
			MOS		23.4			17 Jan 2022			
Airframe											
276322	Outboard Flight Spoiler Bellcrank (Right) - Special Detailed Inspection		HRS		404.7			5776.5			0
			AFL		92		1500	1476	2976		0
			MOS		23.4			17 Jan 2022			
Airframe											
276401	Ground Spoiler Primary Control Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH403-3	948A	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
276402	Ground Spoiler Secondary Control Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH568-3	0215	MOS		208.3			21 Aug 2006			MOOG INCORPORATED
			MSC				O/C				
Airframe											
276501	Ground Spoiler Position Sensor Switch (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159AV50506-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
276502	Ground Spoiler Position Sensor Switch (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159AV50506-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276505	Spoiler Position Transducer (Left Ground) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3A1316A	A1295	MOS		208.3			21 Aug 2006			IPECO INC
			MSC								
Airframe											
276506	Spoiler Position Transducer (Right Ground) - Removal / Installation		HRS		955.3			5225.9			0
			AFL		227			1341			0
	3A1316A	A0995	MOS		54.8			04 Jun 2019			IPECO INC
			MSC								
Airframe											
276507	Spoiler Position Transducer (Left Flight) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3A1316A	A1303	MOS		208.3			21 Aug 2006			IPECO INC
			MSC								
Airframe											
276508	Spoiler Position Transducer (Right Flight) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3A1316A	A1294	MOS		208.3			21 Aug 2006			IPECO INC
			MSC								
Airframe											
277001	Gust Lock Cable Systems - Rigging / Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
277002	Gust Lock System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
277003	Gust Lock System - Functional Check		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
Airframe [HRS: +50/-50]											

Notes: ADDED AND ALIGNED NEXT DUE WITH OTHER 2A CHECK PER AMM REV 25, SO 9-26-16

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
277005	Gust Lock Cable Assembly (Outboard) FS 84 - FS 362 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277006	Gust Lock Cable Assembly (Inboard) FS 84 - FS 790 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277007	Gust Lock Cable Assembly (Outboard) FS 362 - FS 410 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277008	Gust Lock Cable Assembly (Outboard) FS 410 - FS 790 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277009	Gust Lock Cable Assembly (Outboard) FS 790 - FS 905 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277010	Gust Lock Cable Assembly (Inboard) FS 790 - FS 905 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C
277012	Gust Lock Cable Pulleys - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe			MSC								O/C

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
277101	Gust Lock Handle Assembly - Removal / Installation		HRS		6181.2			0			0
	3F78495001B	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			MPC PRODUCTS
	Airframe		MSC					O/C			
28 - Fuel											
280001	Fuel System-- Inspection/Check		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.6			10 Nov 2021			
	Airframe		MSC					O/C			
280003	Fuel Tank Vapor Hazards - Reduction		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1			27 Apr 2023			
	Airframe		MSC					O/C			
280006	Auxiliary Power Unit Fuel System - Bleed		HRS		3320.4			2860.8			0
			AFL		821			747			0
			MOS		136.4			16 Aug 2012			
	Airframe		MSC					O/C			
280010	Refueling / Defueling Procedures - Servicing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
	Airframe		MSC					O/C			
280011	Fuel Tank - Sumping		HRS		10.1			6171.1			0
			AFL		1			1567			0
			DATE		16 d		10d	13 Dec 2023	23 Dec 2023		
	Airframe		[End Of Month Item]								
280012	Microbiological Contamination Test of Fuel Tank - Special Detail Inspection		HRS		33.9			6147.3			0
			AFL		6			1562			0
			MOS		2.3	9	4	20 Oct 2023	29 Feb 2024*	31 Mar 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281001	Fuel Tank (Left) - Leak Check		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.9			02 May 2021			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281002	Fuel Tank (Right) - Leak Check		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.9			02 May 2021			
	Airframe		MSC					O/C			
281005	Fuel Tank Contamination (Left) - Cleaning		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281006	Fuel Tank Contamination (Right) - Cleaning		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281010	Wing Centerline Rib - Leak Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281109	L/H Float Shutoff Valve		HRS		6181.2			0			0
	1159SCP583-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281110	R/H Float Shutoff Valve		HRS		6181.2			0			0
	1159SCP583-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281301	Overwing Gravity Fueling Adapter Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	457-1608	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281302	Overwing Gravity Fueling Adapter Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	457-1608	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281303	Gravity Fueling Adapter Assembly (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281304	Gravity Fueling Adapter Assembly (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281401	Gravity Fuel Drain Sys-OPS Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281405	Gravity Water / Fuel Drain Valve (Left, Inboard Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	79C3T2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ENVIROVAC, INC.
	Airframe		MSC					O/C			
281406	Gravity Water / Fuel Drain Valve (Right, Inboard Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	79C3T2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ENVIROVAC, INC.
	Airframe		MSC					O/C			
281407	Gravity Water / Fuel Drain Valve (Left) - Operational Test		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		[HRS: +50/-50]								
Notes: PN: 79C3T2 SN: <NONE>. WO SC13165											
281408	Gravity Water / Fuel Drain Valve (Right) - Operational Test		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		[HRS: +50/-50]								
Notes: PN: 79C3T2 SN: <NONE>. WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281409	Flapper Check Valve (Left) - General Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.5	-44	96	13 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
281410	Flapper Check Valve (Right) - General Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
281415	Heated Fuel Return System - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe							O/C			
281503	Vent Float / Pressure Relief Valve (3 Inch) {Left Wing} - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	8F111-101A	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe							O/C			
281504	Vent Float / Pressure Relief Valve (3 Inch) {Right Wing} - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	8F111-101A	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe							O/C			
281505	Vent Float / Nonrelieving Valve (AIR Passage) {Left Forward} - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP007-3	4237	MOS		208.3			21 Aug 2006			
	Airframe							O/C			
281506	Vent Float / Nonrelieving Valve (AIR Passage) {Right Forward} - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP007-3	4247	MOS		208.3			21 Aug 2006			
	Airframe							O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281507	Vent Float / Nonrelieving Valve (AIR Passage) {Left Aft} -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCP003-3	2988	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281508	Vent Float / Nonrelieving Valve (AIR Passage) {Right Aft} -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCP003-3	2987	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281509	Vent Float / Nonrelieving Valve (Vent Duct) {Left Forward}		HRS		6181.2			0			0
	- Removal / Installation		AFL		1568			0			0
	1159SCP006-1	3056	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281510	Vent Float / Nonrelieving Valve (Vent Duct) {Right		HRS		6181.2			0			0
	Forward} - Removal / Installation		AFL		1568			0			0
	1159SCP006-1	3062	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281513	Vent Float / Pressure Relief Valve (1 Inch) {Left Wing} -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCP007-3	4236	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281514	Vent Float / Pressure Relief Valve (1 Inch) {Right Wing} -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCP007-3	4248	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
281515	Wing Vent Float Drain Valve (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6	-41	96	10 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281516	Wing Vent Float Drain Valve (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6	-41	96	10 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281521	Aft Outboard Vent Float Drain (Vent Duct) Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P52025-2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281522	Aft Outboard Vent Float Drain (Vent Duct) Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P52025-2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281523	Vent Float Drain (Vent Tubing) Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	775C-80NW	3531	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
281524	Vent Float Drain (Vent Tubing) Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	775C-80NW	3526	MOS		208.3			21 Aug 2006			AUTO VALVE INC
	Airframe		MSC					O/C			
281527	Overboard Vent / Ram AIR Inlet Mast (Left) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281528	Overboard Vent / Ram AIR Inlet Mast (Right) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281601	Heated Fuel Return Shut-Off Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AV24B1441	SN-UNKNOWN	MOS		208.3			21 Aug 2006			AVTEC INC
			MSC								
Airframe											
281602	Heated Fuel Return Shut-Off Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AV24B1441	SN-UNKNOWN	MOS		208.3			21 Aug 2006			AVTEC INC
			MSC								
Airframe											
282001	Main Fuel Boost Pump (Left) - Removal / Installation		HRS	TSN:2860.8	3320.4			2860.8			0
	1159SCP500-7	1344	AFL	TSN:747	821			747			0
			MOS	TSN:72	136.4			16 Aug 2012			
			MSC								
Airframe											
282002	Main Fuel Boost Pump (Right) - Removal / Installation		HRS	TSN:2860.8	3320.4			2860.8			0
	1159SCP500-7	1318	AFL	TSN:747	821			747			0
			MOS	TSN:72	136.4			16 Aug 2012			
			MSC								
Airframe											
282003	Alternate Fuel Boost Pump (Left) - Removal / Installation		HRS	TSN:2860.8	3320.4			2860.8			0
	1159SCP500-7	1343	AFL	TSN:747	821			747			0
			MOS	TSN:72	136.4			16 Aug 2012			
			MSC								
Airframe											
282004	Alternate Fuel Boost Pump (Right) - Removal / Installation		HRS	TSN:2860.8	3320.4			2860.8			0
	1159SCP500-7	1342	AFL	TSN:747	821			747			0
			MOS	TSN:72	136.4			16 Aug 2012			
			MSC								
Airframe											
282005	Fuel Boost Pump Emi Filter (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCP500-15	0723	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282006	Fuel Boost Pump Emi Filter (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP500-15	0728	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
282007	Main Fuel Boost Pump (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282008	Main Fuel Boost Pump (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282009	Alternate Fuel Boost Pump (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282010	Alternate Fuel Boost Pump (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282011	Fuel Boost Pump Control System - Operational Check		HRS		3320.4			2860.8			0
			AFL		821			747			0
			MOS		136.4			16 Aug 2012			
			MSC								
Airframe											
282014	Fuel Boost Pump Emi Filter - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282103	Pressure Fueling - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282107	Suction Defueling - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
282110	Pressure Fueling / Defueling Adapter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61255	1051	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
282112	Engine Suction Fuel Feed (Left) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC					O/C			
282113	Engine Suction Fuel Feed (Right) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC					O/C			
282205	Pressure Fueling Shut-Off Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61086-1	658	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
282206	Pressure Fueling Shut-Off Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61086-1	660	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
282207	Pressure Fueling Sensing Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP004	684	MOS		208.3			21 Aug 2006			SHAW AERO DEVICES
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282208	Pressure Fueling Sensing Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP004	660	MOS		208.3			21 Aug 2006			SHAW AERO DEVICES
			MSC								
Airframe											
282213	High-Level Pilot Valve (Float) No. 1 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61087-4	1342	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
282214	High-Level Pilot Valve (Float) No. 2 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61087-4	1341	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
282215	High-Level Pilot Valve (Float) No. 1 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61087-4	1317	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
282216	High-Level Pilot Valve (Float) No. 2 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	61087-4	1321	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
282217	L High Level Pilot Valve - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
282218	R High Level Pilot Valve - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282219	Fuel Tank High-Level Shutoff (Automatic MODE) - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282220	Remote Fuel S/O Cont--Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282221	Remote Fueling Solenoid Shut-Off Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	V4700-96	642	MOS		208.3			21 Aug 2006			VALCOR ENG CORP
			MSC					O/C			
Airframe											
282222	Remote Fueling Solenoid Shut-Off Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	V4700-96	697	MOS		208.3			21 Aug 2006			VALCOR ENG CORP
			MSC					O/C			
Airframe											
282223	Fueling / Defueling Precheck Selector Valve No. 1 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	6BS100	2454	MOS		208.3			21 Aug 2006			ALLEN AIRCRAFT PRODUCTS INC
			MSC					O/C			
Airframe											
282224	Fueling / Defueling Precheck Selector Valve No. 2 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	6BS100	2456	MOS		208.3			21 Aug 2006			ALLEN AIRCRAFT PRODUCTS INC
			MSC					O/C			
Airframe											
282402	Fuel Cross-Flow / Intertank System - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282403	Intertank Shut-Off Valve Motor - Removal / Installation		HRS		4281.8			1899.4			0
	AV16B2199	AA37804	AFL		1032			536			0
			MOS		156.4			16 Dec 2010			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
282404	Intertank Shut-Off Valve - Removal / Installation		HRS		4281.8			1899.4			0
	AV17B1310C	AA37804	AFL		1032			536			0
			MOS		156.4			16 Dec 2010			ITT AEROSPACE CONTROLS
	Airframe		MSC					O/C			
282405	Intertank Shutoff Valve / Low Fuel Sensor - Functional		HRS		6181.2			0			0
	Check		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
282406	Cross-Flow Shut-Off Valve Motor - Removal / Installation		HRS		6181.2			0			0
	AV17B1310C	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ITT AEROSPACE CONTROLS
	Airframe		MSC					O/C			
282407	Cross-Flow Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
	AV24B1420	AA70266	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
282408	Cross-Flow Shut-Off Valve - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282503	Fuel Boost Pump Inlet Filter Screen (Left Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P52410-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
282504	Fuel Boost Pump Inlet Filter Screen (Left Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P54210-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282505	Fuel Boost Pump Inlet Filter Screen (Right Forward) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P54210-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282506	Fuel Boost Pump Inlet Filter Screen (Right Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159P54210-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282601	Engine Fuel Distribution System (Fuel Flow) - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
282602	APU Fuel Distribution System (Fuel Flow) - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
282603	Engine Feed Dual Wall Fuel Line Shroud (Left) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282604	Engine Feed Dual Wall Fuel Line Shroud (Right) -		HRS		130.8			6050.4			0
	Functional Test		AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282605	APU Feed Dual Wall Fuel Line Shroud - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282606	Engine Feed Dual Wall Fuel Line (Left) - Detailed		HRS		392.4			5788.8			0
	Inspection		AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282607	Engine Feed Dual Wall Fuel Line (Right) - Detailed		HRS		392.4			5788.8			0
	Inspection		AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282608	APU Feed Dual Wall Fuel Line - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282609	Engine Heated Return Feed Dual Wall Fuel Line (Left) -		HRS		392.4			5788.8			0
	Detailed Inspection		AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282610	Engine Heated Return Feed Dual Wall Fuel Line (Right) -		HRS		392.4			5788.8			0
	Detailed Inspection		AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282611	Engine Heated Return Feed Dual Wall Fuel Line Shroud (Left) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282612	Engine Heated Return Feed Dual Wall Fuel Line Shroud (Right) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	-18	96	18 Mar 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282613	Fuel Boost Pump Manifold Assembly (Left) - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	1159PM2000-7	HD1267	MOS		156.2			22 Dec 2010			
			MSC					O/C			
Airframe											
282614	Fuel Boost Pump Manifold Assembly (Right) - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	1159PM20000-8	HD1302	MOS		156.2			22 Dec 2010			
			MSC					O/C			
Airframe											
282619	Fuel Ejector Pump (Left, Hopper) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP002-7	0190	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282620	Fuel Ejector Pump (Right, Hopper) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP002-7	0199	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
282627	Fuel Ejector Pump and Check Valves (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282628	Fuel Ejector Pump and Check Valves (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
282629	Engine Fuel Shut-Off Valve (Left) - Operational Check		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
282630	Engine Fuel Shut-Off Valve (Right) - Operational Check		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
282631	Engine Fuel Shut-Off Valve (Left) - Removal / Installation		HRS	TSN:1899	4282.2			1899			0
	AV16B2199	AA70083	AFL	TSN:536	1032			536			0
			MOS	TSN:52	156.5			14 Dec 2010			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe			MSC				O/C			
282632	Engine Fuel Shut-Off Valve (Right) - Removal / Installation		HRS	TSN:4341	1840.2			4341			0
	AV16B2199	AA70075	AFL	TSN:1126	442			1126			0
			MOS	TSN:115	93.5			14 Mar 2016			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe			MSC				O/C			
282640	APU Fuel Shut-Off Valve - Removal / Installation		HRS	TSN:9.8	6154.1			27.1			0
	V4700-108-2	0153	AFL	TSN:4	1557			11			0
			MOS		202.7			06 Feb 2007			CARL F BOOTH & CO INC
	Airframe			MSC				O/C			
282641	APU Fuel Shut-Off Valve - Operational Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			19 May 2020			
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282643	Fuel Ejector Pump Motive Flow Check Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	Z02CV06-7	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
			MSC				O/C				
Airframe											
282644	Fuel Ejector Pump Motive Flow Check Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	Z02CV06-7	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
			MSC				O/C				
Airframe											
282645	Fuel Vapor Return Check Valve No. 1 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P17-533	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
			MSC				O/C				
Airframe											
282646	Fuel Vapor Return Check Valve No. 1 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P17-533	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
			MSC				O/C				
Airframe											
282647	Fuel Vapor Return Check Valve No. 2 (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P17-533	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282648	Fuel Vapor Return Check Valve No. 2 (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P17-533	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
	Airframe		MSC					O/C			
282649	Fuel System Manifold Assembly Check Valves (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	28C112	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ALLEN AIRCRAFT PRODUCTS, INC.
	Airframe		MSC					O/C			
282650	Fuel System Manifold Assembly Check Valves (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	28C112	SN-UNKNOWN	MOS		208.3			21 Aug 2006			ALLEN AIRCRAFT PRODUCTS, INC.
	Airframe		MSC					O/C			
282651	Main Fuel Boost Pump (Left) - Fuel Leak Check		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		[HRS: +50/-50]								
Notes: PN: 31760-3 SN: 1344.											
282652	Main Fuel Boost Pump (Right) - Fuel Leak Check		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		[HRS: +50/-50]								
Notes: PN: 31760-3 SN: 1316.											
282653	Alternate Fuel Boost Pump (Left) - Fuel Leak Check		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		[HRS: +50/-50]								
Notes: PN: 31760-3 SN: 1343.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282654	Alternate Fuel Boost Pump (Right) - Fuel Leak Check		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 31760-3 SN: 1342.											
284001	Fuel Indicator Functional Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC				O/C				
284002	Indicator, Fuel Quanity		HRS		6181.2			0			0
	366-926-001	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC				O/C				PARKER HANNIFIN CORPORATION
284101	Fuel Quantity System - Capacitance / Insulation		HRS		665.8			5515.4			0
	Resistance Check		AFL		150			1418			0
			MOS		44.9			01 Apr 2020			
Airframe			MSC				O/C				
284102	Fuel Quantity Signal Conditioner - Removal / Installation		HRS	TSN:1421.7	2860.1			3321.1			0
	367-933-002	472	AFL	TSN:321	711			857			0
	0	D	MOS	TSN:32	124.5			15 Aug 2013			
Airframe			MSC				O/C				PARKER HANNIFIN CORPORATION
284103	Fuel System Interface to Aircraft Systems - Operational		HRS		6173.3			7.9			0
	Check		AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
Airframe			MSC				O/C				
284104	Fuel Quantity Measuring / Indication System - Functional		HRS		6181.2			0			0
	Check		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284105	Fuel Quantity Densitometer (Left) - Removal / Installation		HRS		6181.2			0			0
	180-032-002	1684	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
284106	Fuel Quantity Densitometer (Right) - Removal / Installation		HRS		6181.2			0			0
	180-032-002	1675	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
284107	Fuel Ground Service Control Panel - Removal / Installation		HRS		6181.2			0			0
	366-926-001	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
284108	Fuel Ground Service Control Panel - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
284110	Fuel Quantity Signal Conditioner - Power / Ground Diode Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
284114	Refueling Door Fuel High-Level Warning Light - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
284117	L Fuel Quantity Probe Electrical Resistance - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284118	R Fuel Quantity Probe Electrical Resistance - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
284119	L Fuel Quantity Probe Electrical Capacitance - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
284120	R Fuel Quantity Probe Electrical Capacitance - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
284121	Fuel Quantity Probe No. 1 (Left) - Removal / Installation		HRS		6181.2			0			0
	021-935-001	0845	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			PARKER HANNIFIN CORPORATION
Airframe											
284122	Fuel Quantity Probe No. 2 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-001	0780	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			PARKER HANNIFIN CORPORATION
Airframe											
284123	Fuel Quantity Probe No. 3 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-002	0777	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			PARKER HANNIFIN CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284124	Fuel Quantity Probe No. 4 (Left) - Removal / Installation		HRS		6181.2			0			0
	022-901-001	0772	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284125	Fuel Quantity Probe No. 5 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-003	0778	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284126	Fuel Quantity Probe No. 6 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-004	0785	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284127	Fuel Quantity Probe No. 7 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-005	077	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284128	Fuel Quantity Probe No. 8 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-006	0764	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284129	Fuel Quantity Probe No. 9 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-007	552	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284130	Fuel Quantity Probe No. 10 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-008	0810	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284131	Fuel Quantity Probe No. 11 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-009	0788	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284132	Fuel Quantity Probe No. 12 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-010	0769	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284133	Fuel Quantity Probe No. 13 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-011	0783	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284134	Fuel Quantity Probe No. 14 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-012	792	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284135	Fuel Quantity Probe No. 15 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-013	0767	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284136	Fuel Quantity Probe No. 16 (Left) - Removal / Installation		HRS		6181.2			0			0
	020-989-014	0765	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284137	Fuel Quantity Probe No. 17 (Left) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	020-989-015	0785	AFL	TSN:1418	150			1418			0
			MOS	TSN:164	44.9			01 Apr 2020			N/A
	Airframe		MSC					O/C			
284138	Fuel Quantity Probe No. 18 (Left) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	020-989-016	0782	AFL	TSN:1418	150			1418			0
			MOS	TSN:164	44.9			01 Apr 2020			N/A
	Airframe		MSC					O/C			
284139	Fuel Quantity Probe No. 19 (Left) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
	020-989-017	767	AFL	TSN:1418	150			1418			0
			MOS	TSN:164	44.9			01 Apr 2020			N/A
	Airframe		MSC					O/C			
284140	Outboard High Fuel Level Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
	057-022-001	789	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284141	Fuel Quantity Probe No. 1 (Right) - Removal / Installation		HRS		6181.2			0			0
	021-935-001	0864	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284142	Fuel Quantity Probe No. 2 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-001	0776	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284143	Fuel Quantity Probe No. 3 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-002	0773	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284144	Fuel Quantity Probe No. 4 (Right) - Removal / Installation		HRS		6181.2			0			0
	022-901-001	0789	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284145	Fuel Quantity Probe No. 5 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-003	0768	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284146	Fuel Quantity Probe No. 6 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-004	0789	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284147	Fuel Quantity Probe No. 7 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-005	763	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284148	Fuel Quantity Probe No. 8 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-006	0774	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284149	Fuel Quantity Probe No. 9 (Right) - Removal / Installation		HRS		6181.2			0			0
	021-935-002	0498	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284150	Fuel Quantity Probe No. 10 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-008	0808	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
284151	Fuel Quantity Probe No. 11 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-009	774	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284152	Fuel Quantity Probe No. 12 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-010	0767	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284153	Fuel Quantity Probe No. 13 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-011	0780	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284154	Fuel Quantity Probe No. 14 (Right) - Removal / Installation		HRS		6181.2			0			0
	020-989-012	794	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284155	Fuel Quantity Probe No. 15 (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	020-989-013	0771	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
284156	Fuel Quantity Probe No. 16 (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	020-989-014	0779	MOS		208.3			21 Aug 2006			
			MSC						O/C		PARKER HANNIFIN CORPORATION
Airframe											
284157	Fuel Quantity Probe No. 17 (Right) - Removal /		HRS	TSN:5515.4	665.8			5515.4			0
	Installation		AFL	TSN:1418	150			1418			0
	020-989-015	774	MOS	TSN:164	44.9			01 Apr 2020			N/A
			MSC						O/C		
Airframe											
284158	Fuel Quantity Probe No. 18 (Right) - Removal /		HRS	TSN:5515.4	665.8			5515.4			0
	Installation		AFL	TSN:1418	150			1418			0
	020-989-016	0770	MOS	TSN:164	44.9			01 Apr 2020			N/A
			MSC						O/C		
Airframe											
284159	Fuel Quantity Probe No. 19 (Right) - Removal /		HRS	TSN:5515.4	665.8			5515.4			0
	Installation		AFL	TSN:1418	150			1418			0
	020-989-017	0869	MOS	TSN:164	44.9			01 Apr 2020			N/A
			MSC						O/C		
Airframe											
284160	Outboard High Fuel Level Sensor (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	057-022-001	787	MOS		208.3			21 Aug 2006			
			MSC						O/C		PARKER HANNIFIN CORPORATION
Airframe											
284165	Probe, Left #20 Fuel Quantity		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284166	Probe, Right #20 Fuel Quantity		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
284301	Fuel Tank Temperature Bulb - Functional Check		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1		48	27 Jun 2022	30 Jun 2026	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
284302	Fuel Tank Temperature Bulb (Left) - Removal / Installation		HRS		6181.2			0			0
	MS28034-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
284303	Fuel Tank Temperature Bulb (Right) - Removal / Installation		HRS		6181.2			0			0
	MS28034-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
284305	Main Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS		3320.4			2860.8			0
	1159SCP500-7	1344	AFL		821			747			0
			MOS		136.4			16 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
284306	Alternate Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS		3320.4			2860.8			0
	1150SCP500-7	1343	AFL		821			747			0
			MOS		136.4			16 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
284307	Main Fuel Boost Pump Pressure Switch (Right) - Removal / Installation		HRS		3320.4			2860.8			0
	1150SCP500-7	1318	AFL		821			747			0
			MOS		136.4			16 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284308	Alternate Fuel Boost Pump Pressure Switch (Right) - Removal / Installation		HRS		3320.4			2860.8			0
			AFL		821			747			0
	1159SCP500-7	1342	MOS		136.4			16 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC								
Airframe											
29 - Hydraulic Power											
290001	Hydraulic System Bleeding Procedure		HRS		2357.4			3823.8			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Airframe											
290002	Hydraulic System Bleed Procedure - Alternate		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC								
Airframe											
290003	Hydraulic System Automatic Bleed Procedure		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
			MSC								
Airframe											
290009	Hydraulic Fluid (Left) - Sampling / Analysis		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
Airframe											
290010	Hydraulic Fluid (Right) - Sampling / Analysis		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
Airframe											
290021	Hydraulic Fluid Heat Exchanger (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	10718000	659	MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
290022	Hydraulic Fluid Heat Exchanger (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	10718000	654	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC								DALLAS
Airframe											
290030	Hydraulic AIR Separator Can Assembly, Removal and Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SB59400-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
290031	L/H Hydraulic AIR Separator Bleeder Valve - Removal and Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
290032	L/H Hydraulic Reservoir Standpipe Bleeder Valve - Removal and Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
290033	R/H Hydraulic Reservoir Standpipe Bleeder Valve - Removal and Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
290034	R/H Hydraulic Low Pressure Relief Valve - Removal and Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
	1159SCH648-1	2302	MOS	TSN:20	43.3			21 May 2020			N/A
			MSC								
Airframe											
290100	Hydraulic Replenisher Tank - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH519-7	0189	MOS		208.3			21 Aug 2006			
			MSC								MEGGITT
Airframe											
AIRDYNAMICS, INC.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
290105	Hydraulic Replenisher Tank Selector Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH602-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC								
Airframe											
291001	Left Hydraulic System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
291002	Right Hydraulic System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
291006	Abex Engine-Driven Hydraulic Pump (Left) - Removal / Installation		HRS		2502.2			3679			0
			AFL		632			936			0
	1159SCH505-101	K1114	MOS		116.4			16 Apr 2014			EATON AEROSPACE
			MSC								
Airframe											
291008	Abex Engine-Driven Hydraulic Pump (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH505-101	K1456	MOS		208.3			21 Aug 2006			EATON AEROSPACE
			MSC								
Airframe											
291010	Attenuator, L Eng Hyd Pump		HRS		6181.2			0			0
			AFL		1568			0			0
	3A1006	SN-UNKNOWN	MOS		208.3			21 Aug 2006			CRISSAIR INC
			MSC								
Airframe											
291012	Attenuator, R Eng Hyd Pump		HRS		6181.2			0			0
			AFL		1568			0			0
	3A1006	SN-UNKNOWN	MOS		208.3			21 Aug 2006			CRISSAIR INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291030	Left System Manifold - Removal / Installation		HRS		6181.2			0			0
	1159SCH517-11	0343	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
291031	Right System Manifold - Removal / Installation		HRS		6181.2			0			0
	1159SCH518-11	0362	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
291033	Left System Manifold Filter / Filter Bowl (Main Pressure) - Removal / Installation		HRS		6181.2			0			0
	AC-C219F-161	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
291034	Right System Manifold Filter / Filter Bowl (Main Pressure) - Removal / Installation		HRS		6181.2			0			0
	AC-C219F-161	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
291035	Left System Manifold Filter / Filter Bowl (Main Return) - Removal / Installation		HRS		6181.2			0			0
	AC-C219F-161	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
291036	Right System Manifold Filter / Filter Bowl (Main Return) - Removal / Installation		HRS		6181.2			0			0
	AC-C219F-161	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291037	Left System Manifold Filter / Filter Bowl (Aux Return) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ACB451F10	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291038	Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ACB451F8	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291039	Left System Manifold Filter / Filter Bowl (Ptu Case Drain) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AC-C314F-8Y2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291040	Power Transfer Unit Manifold Filter and Bowl - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ACB451F16	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291041	Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AC-B451-8	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291042	Right System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AC-B451-8	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
291205	L, Engine Thrust Reverser Hose Assy		HRS		6181.2			0			0
			AFL		1568			0			0
	AE709616-86	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291206	R, Engine Thrust Reverser Hose Assy		HRS		6181.2			0			0
	AE709616	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
291401	Main Hydraulic System Manifold Differential Pressure Indicator (Left) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8			05 Apr 2021			
	Airframe		MSC					O/C			
291402	Right System Manifold Differential Pressure Indicator - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8			05 Apr 2021			
	Airframe		MSC					O/C			
291403	Left System Manifold Differential Pressure Indicator (Pressure) - Removal / Installation		HRS		6181.2			0			0
	366-929-001	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
291404	Right System Manifold Differential Pressure Indicator (Pressure) - Removal / Installation		HRS		6181.2			0			0
	TD470UK0901611	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
291405	Left System Manifold Low-Pressure Relief Valve - Removal / Installation		HRS		6181.2			0			0
	AA-9500-D3837	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
291406	Right System Manifold Low-Pressure Relief Valve - Removal / Installation		HRS		6181.2			0			0
	AD-C220-16D281	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291407	Left Engine Hydraulic System Acoustical Filter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH526-1	684	MOS		208.3			21 Aug 2006			PULSCO
	Airframe		MSC					O/C			DIVISION OF ADVANCED TECHNOLOGY
291408	Right Engine Hydraulic System Acoustical Filter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH526-1	691	MOS		208.3			21 Aug 2006			PULSCO
	Airframe		MSC					O/C			DIVISION OF ADVANCED TECHNOLOGY
291409	Left Manifold Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AA-99-00-D3837	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
291410	Right System Manifold High-Pressure Relief Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	AD-C220-11D11	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
291421	Left System Manifold Fluid Sampling Port - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ADB942-82D29Y3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			E A R SPECIALITY
	Airframe		MSC					O/C			COMPOSITE AERO
291422	Right System Manifold Fluid Sampling and Bleed Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	ADB942-82D29Y3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			E A R SPECIALITY
	Airframe		MSC					O/C			COMPOSITE AERO

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291429	Hydraulic System Pressure Reducing Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH219-33	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC								
Airframe											
291430	Hydraulic System Pressure Reducing Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH219-33	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC								
Airframe											
291431	Engine-Driven Hydraulic Pump Case Drain Filter Fluid Sample (Left) - Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
291432	Engine-Driven Hydraulic Pump Case Drain Filter Fluid Sample (Right) - Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
291433	Valve, L Main Press Rtn Sample		HRS		6181.2			0			0
	ADB942-82D29Y3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			E A R SPECIALITY COMPOSITE AERO
			MSC								
Airframe											
291434	Valve, R Main Press Rtn Sample		HRS		6181.2			0			0
	ADB942-82D29Y3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			E A R SPECIALITY COMPOSITE AERO
			MSC								
Airframe											
291501	Hydraulic System Shut-Off Valve (Left) - Operational Check		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291502	Hydraulic System Shut-Off Valve (Right) - Operational Check		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
291503	Left Hydraulic System Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH239-5	AA78113	MOS		208.3			21 Aug 2006			ITT AEROSPACE CONTROLS
			MSC					O/C			
Airframe											
291504	Right Hydraulic System Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH239-5	AA78115	MOS		208.3			21 Aug 2006			ITT AEROSPACE CONTROLS
			MSC					O/C			
Airframe											
291601	Left System Hydraulic Reservoir - Servicing		HRS		1911.2			4270			0
			AFL		473			1095			0
			MOS		94.6			11 Feb 2016			
			MSC					O/C			
Airframe											
291602	Right System Hydraulic Reservoir - Servicing		HRS		1911.2			4270			0
			AFL		473			1095			0
			MOS		94.6			11 Feb 2016			
			MSC					O/C			
Airframe											
291603	Left System Reservoir - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H50125-29	55-5124GT	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
291604	Right System Reservoir - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	1159H50126-23	55-5123GT	MOS		156.5			13 Dec 2010			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291609	Left Reservoir Hydraulic Quantity Transmitter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH525-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
291610	Right Reservoir Hydraulic Quantity Transmitter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH525-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
291611	Hydraulic Reservoir Quantity Transmitter (Left) - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
Notes: PN: 1159SCH525-1 SN: <NONE>.											
291612	Hydraulic Reservoir Quantity Transmitter (Right) - Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
Notes: PN: 1159SCH525-3 SN: <NONE>.											
291613	Valve, Hyd. Reservoir Selector- R / I		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH602-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
291701	Hydraulic System Accumulator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH206-5	60211-2198	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC						O/C		
Airframe											
291702	Hydraulic System Accumulator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH206-5	60211-2187	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291703	Hydraulic System Accumulator Pressure Gage (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	GP20-24	06-032419	MOS		208.3			21 Aug 2006			CUSTOM METAL WORKS
			MSC								
Airframe											
291704	Hydraulic System Accumulator Pressure Gage (Right) - Removal / Installation		HRS		5725.4			455.8			0
			AFL		1438			130			0
	GP20-24	0020492	MOS		191.6			11 Jan 2008			CUSTOM METAL WORKS
			MSC								
Airframe											
292002	Auxiliary Hydraulic System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
292101	Auxiliary Hydraulic Pump - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH504-3	MX699262	MOS		208.3			21 Aug 2006			EATON AEROSPACE
			MSC								
Airframe											
292102	Auxiliary Hydraulic Boost Pump - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH520-3	0337	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC								
Airframe											
292201	Power Transfer Unit Hydraulic Pump - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH511-3	MX699588	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
292202	Transducer, Power Transfer Unit (Ptu) {Sta 780}		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV600-1	HAL2778	MOS		208.3			21 Aug 2006			GULFSTREAM - LONG BEACH
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292203	Transducer, Lh Sys (Sta 850)		HRS		6181.2			0			0
	1159SCAV600-1	HAL2672	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM -
	Airframe		MSC					O/C			LONG BEACH
292204	Transducer, Rh Sys (Sta 850)		HRS		6181.2			0			0
	1159SCAV600-1	HAL2798	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM -
	Airframe		MSC					O/C			LONG BEACH
292205	Power Transfer Unit - Functional Test		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
	Airframe		MSC					O/C			
292206	Valve, Ptu Sample		HRS		6181.2			0			0
	ADB942-82D29Y3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			E A R SPECIALITY
	Airframe		MSC					O/C			COMPOSITE AERO
292207	Hydraulic Fluid (Ptu) - Sampling / Analysis		HRS		1913.2			4268			0
			AFL		474			1094			0
			MOS		100			29 Aug 2015			
	Airframe		MSC					O/C			
292208	Power Transfer Unit ARM Circuit - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
292501	Auxiliary Hydraulic Pump Manifold Differential Pressure Indicator - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		8.2			24 Apr 2023			
	Airframe		[HRS: +50/-50]								

Notes: PN: TD470UK096 SN: <NONE>. WO SC13165

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292502	Power Transfer Unit Manifold Differential Pressure Indicator - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		8.2			24 Apr 2023			
			[HRS: +50/-50]								
Airframe											
Notes: PN: TD470UK096 SN: <NONE>. WO SC13165											
292503	Auxiliary Hydraulic Pump Manifold - Removal / Installation		HRS		6181.2			0			0
	1159H51512-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
292504	Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation		HRS		6181.2			0			0
	1159SCH530-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
292505	Auxiliary Hydraulic Pump Manifold Relief Valve - Removal / Installation		HRS		6181.2			0			0
	1159SCH207-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TACTAIR FLUID
			MSC					O/C			CONTROLS INC
Airframe											
292506	Auxiliary Hydraulic Pump Manifold Differential Pressure Indicator - Removal / Installation		HRS		6181.2			0			0
	TD470UK096	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
292507	Auxiliary Hydraulic Pump Acoustical Filter (Muffler) - Removal / Installation		HRS		6181.2			0			0
	1159H51512-11	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292508	Power Transfer Unit Manifold - Removal / Installation		HRS		6181.2			0			0
	1159SCH529-3	0185	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
292509	Filter/Bowl,Pwr Xfer Manifold		HRS		6181.2			0			0
	AAB451-16Y1D2A	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
292510	Power Transfer Unit Manifold Differential Pressure Indicator - Removal / Installation		HRS		6181.2			0			0
	TD470UK096	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
292511	Switch, Ptp/L Hyd Sys Pressure		HRS		6181.2			0			0
	1206P0215	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ELECTRO
	Airframe		MSC					O/C			ENTERPRISES INC
292601	Auxiliary Hydraulic System Shut-Off Control - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
292602	Auxiliary Hydraulic Pump Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
	1159SCH516-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PNEUDRAULICS
	Airframe		MSC					O/C			INC
292603	Power Transfer Unit Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
	1159SCH516-1	0389	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292604	Valve, Aux Motor Shutoff		HRS		6181.2			0			0
	1159SCH514-3	1235	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PALL
	Airframe		MSC					O/C			AEROPOWER CORPORATION
293198	Hydraulic Pressure Switch (2600 Psi, Left) - Removal / Installation		HRS		6181.2			0			0
	1203P0142-01	0958	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			HPG
293199	Hydraulic Pressure Switch (2600 Psi, Right) - Removal / Installation		HRS		6181.2			0			0
	1203P0142-01	0952	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			HPG
293203	Hydraulic System Reservoir Temperature Transducer (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCH525-19	B0036	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293204	Hydraulic System Reservoir Temperature Transducer (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCH525-21	B0029	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293205	Transducer, Pwr Transfer Unit		HRS		6181.2			0			0
	1159H50106-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293206	Auxiliary Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
	1159SCAV600-1	HAL2796	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM -
	Airframe		MSC					O/C			LONG BEACH

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
293207	Left System Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
	1159SCAV600-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293208	Right System Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
	1159SCAV600-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293300	Power Transfer Unit Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
	1159SCAV600-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
293301	External Quantity Indicator - Removal / Installation		HRS		6181.2			0			0
	366-929-001	437	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
30 - Ice and Rain Protection											
301100	Wing Anti-Ice Control System - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
301101	Wing Anti-Ice Control Valve (Left) - Removal / Installation		HRS		1475.8			4705.4			0
	3215600-2	1029	AFL		349			1219			0
			MOS		75.3			21 Sep 2017			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301102	Wing Anti-Ice Control Valve (Right) - Removal / Installation		HRS		1245.7			4935.5			0
	3215600-2	710	AFL		296			1272			0
			MOS		65.5			13 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
301103	Bleed AIR / Wing Anti-Ice Controller (Left) - Removal - Installation		HRS		6181.2			0			0
	607712-7-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
301104	Bleed AIR / Wing Anti-Ice Controller (Right) - Removal / Installation		HRS		6181.2			0			0
	607712-7-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
301105	Wing Anti-Ice Inboard / Outboard Temperature Switch (Left Inboard) - Removal / Installation		HRS		6181.2			0			0
	975-0114-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
301106	Wing Anti-Ice Inboard / Outboard Temperature Switch (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
	975-0114-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
301107	Wing Anti-Ice Normal Temperature Switch (Left) - Removal / Installation		HRS		6181.2			0			0
	975-0114-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
301108	Wing Anti-Ice Normal Temperature Switch (Right) - Removal / Installation		HRS		6181.2			0			0
	975-0114-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301109	Wing Anti-Ice Inboard / Outboard Temperature Switch (Left Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	975-0114-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
301110	Wing Anti-Ice Inboard / Outboard Temperature Switch (Right Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	975-0114-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
301111	Wing Anti-Ice Temperature Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
			MSC					O/C			
Airframe											
301112	Wing Anti-Ice Temperature Sensor (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
			MSC					O/C			
Airframe											
301113	Wing Anti-Icing Thermal Sensor (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
			MSC					O/C			
Airframe											
301114	Wing Anti-Icing Thermal Sensor (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
			MSC					O/C			
Airframe											
301115	Wing Anti-Icing Thermal Sensor (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ASCA INC.
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301116	Wing Anti-Icing Thermal Sensor (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1151834-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								ASCA INC.
Airframe											
301117 (301117)	Wing Anti-Ice Thermal Switch (Left) - Functional Test		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		107.5	45	192	14 Jan 2015	28 Feb 2031*	31 Mar 2031	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
301118 (301118)	Wing Anti-Ice Thermal Switch (Right) - Functional Test		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		107.5	45	192	14 Jan 2015	28 Feb 2031*	31 Mar 2031	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
301121	Wing Hot / Wing Temp Low Message (Left) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8	-59	96	28 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
301122	Wing Hot / Wing Temp Low Message (Right) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8	-59	96	28 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
301143	Left Wing Normal Anti-Ice Temperature Switch - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8			28 Apr 2023			
	Airframe										O/C
301144	Right Wing Normal Anti-Ice Temperature Switch - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8			28 Apr 2023			
	Airframe										O/C

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301301	Wing Anti-Ice Check Valve (Left) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	3202756-1	851	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.5			12 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
301302	Wing Anti-Ice Check Valve (Right) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	3202756-1	849	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.5			12 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
301303	Wing Anti-Ice Check Valve (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5		72	12 Jul 2018	31 Jul 2024	31 Aug 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
301304	Wing Anti-Ice Check Valve (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5		72	12 Jul 2018	31 Jul 2024	31 Aug 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
301307	Wing Anti-Ice (Left) - Operational Test		HRS		1475.8			4705.4			0
			AFL		349			1219			0
			MOS		75.3			21 Sep 2017			
	Airframe		MSC					O/C			
301308	Wing Anti-Ice (Right) - Operational Test		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5			13 Jul 2018			
	Airframe		MSC					O/C			
302101	Cowl Anti-Ice Control Valve Open / Close Switch / Pressure Transducer (Left) - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
302102	Cowl Anti-Ice Control Valve Open / Close Switch /		HRS		6181.2			0			0
	Pressure Transducer (Right) - Functional Test		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
302103	Cowl Anti-Ice Valve (Left) - Removal / Installation		HRS		955.3			5225.9			0
	510-0020-5	D0405	AFL		227			1341			0
			MOS		54.5			12 Jun 2019			AIRCRAFT BELTS INC
			MSC					O/C			
Airframe											
302104	Cowl Anti-Ice Valve (Right) - Removal / Installation		HRS		955.3			5225.9			0
	510-0020-5	D0404	AFL		227			1341			0
			MOS		54.5			12 Jun 2019			AIRCRAFT BELTS INC
			MSC					O/C			
Airframe											
302105	Cowl Anti-Ice Pressure Transducer (Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	APTE-227-1000-75G	7113-1-518	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
302106	Cowl Anti-Ice Pressure Transducer (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	APTE-227-1000-75G	7113-1-493	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
302118	Forward Thermal Anti-Ice Duct (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	PN	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
303104	Pitot / Static and Total AIR Temperature Probe Heater -		HRS		609.87			5571.33			0
	Operational Check		AFL		126			1442			0
			MOS		33.4			18 Mar 2021			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304021	Windshield Heat Control Unit (No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1042-1	3630	MOS		208.3			21 Aug 2006			GULFSTREAM - LONG BEACH
			MSC					O/C			
Airframe											
304022	Windshield Heat Control Unit (No. 2) - Removal / Installation		HRS		5388.7			792.5			0
			AFL		1341			227			0
	1042-1	2798	MOS		185.3			21 Jul 2008			GULFSTREAM - LONG BEACH
			MSC					O/C			
Airframe											
304023	Metal Oxide Varistor (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	V131BA60	SN-UNKNOWN	MOS		208.3			21 Aug 2006			FINISHMASTER INC.
			MSC					O/C			
Airframe											
304024	Metal Oxide Varistor (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	V131BA60	SN-UNKNOWN	MOS		208.3			21 Aug 2006			FINISHMASTER INC.
			MSC					O/C			
Airframe											
304027	Windshield Heat (Left) - Operational Test		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC					O/C			
Airframe											
304028	Windshield Heat (Right) - Operational Test		HRS		1604.9			4576.3			0
			AFL		414			1154			0
			MOS		80.2			22 Apr 2017			
			MSC					O/C			
Airframe											
304029	Metal Oxide Varistor (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	V131BA60	SN-UNKNOWN	MOS		208.3			21 Aug 2006			FINISHMASTER INC.
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304030	Metal Oxide Varistor (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
	V131BA60	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FINISHMASTER
	Airframe		MSC					O/C			INC.
304031	Metal Oxide Varistor (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
	V131BA60	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FINISHMASTER
	Airframe		MSC					O/C			INC.
304032	Metal Oxide Varistor (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
	V131BA60	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FINISHMASTER
	Airframe		MSC					O/C			INC.
304105	Windshield Surface Seal (Left) - Detailed Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9	1	12	30 Mar 2023	31 Mar 2024*	30 Apr 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]						
Notes: WO SC13165											
304106	Windshield Surface Seal (Right) - Detailed Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9	1	12	30 Mar 2023	31 Mar 2024*	30 Apr 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]						
Notes: WO SC13165											
304107	Windshield Surface Seal (Left) - Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
304108	Windshield Surface Seal (Right) - Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
304110	Cabin Window Heat - Operational Test		HRS		130.8			6050.4			0	
	Airframe		AFL		29			1539			0	
			MOS			6.9			01 Jun 2023			
			MSC									
304201	Windshield Blower Duct (Left) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCAC579-17	SN-UNKNOWN	AFL		1568		0			0	
				MOS		208.3			21 Aug 2006		COX & COMPANY INC	
				MSC								
304202	Windshield Blower Duct (Right) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCAC579-18	SN-UNKNOWN	AFL		1568		0			0	
				MOS		208.3			21 Aug 2006		COX & COMPANY INC	
				MSC								
304203	Windshield Blower T-Duct - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCAC579-3	SN-UNKNOWN	AFL		1568		0			0	
				MOS		208.3			21 Aug 2006		COX & COMPANY INC	
				MSC								
304204	Windshield Blower Actuator - Removal / Installation		HRS		6173.3			7.9			0	
	Airframe	1159SCAC579-7	409	AFL		1562		6			0	
				MOS		203.4			16 Jan 2007		FLEXFAB INC	
				MSC								
304205	Windshield Blower Actuator Cable (Left) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCAC579-5	SN-UNKNOWN	AFL		1568		0			0	
				MOS		208.3			21 Aug 2006		COX & COMPANY INC	
				MSC								
304206	Windshield Blower Actuator Cable (Right) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCAC579-5	SN-UNKNOWN	AFL		1568		0			0	
				MOS		208.3			21 Aug 2006		COX & COMPANY INC	
				MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304207	Windshield Blower - Removal / Installation		HRS		6181.2			0			0
	1159SCAC579-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			KIRKHILL-TA COMPANY
	Airframe		MSC					O/C			
304208	Windshield Blower Bell Mouth Duct - Removal / Installation		HRS		6181.2			0			0
	1159SCAC579-11	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			COX & COMPANY INC
	Airframe		MSC					O/C			
304210	Windshield Rain Removal System - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
308001	Ice Detector Probe (Left) - Removal / Installation		HRS	TSN:5833.4	347.8			5833.4			0
	0871HH	780	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1			25 May 2022			
	Airframe		MSC					O/C			
308002	Ice Detector Probe (Right) - Removal / Installation		HRS	TSN:5833.4	347.8			5833.4			0
	0871HH	796	AFL	TSN:1491	77			1491			0
			MOS	TSN:189	19.1			25 May 2022			
	Airframe		MSC					O/C			
308003	Ice Detector Probe (Left) - Operational Test		HRS		347.8			5833.4			0
			AFL		77			1491			0
			MOS		19.1			25 May 2022			
	Airframe		MSC					O/C			
308004	Ice Detector Probe (Right) - Operational Test		HRS		347.8			5833.4			0
			AFL		77			1491			0
			MOS		19.1			25 May 2022			
	Airframe		MSC					O/C			

31 - Indicating/Recording Systems

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
312001	Pilot Cockpit Clock - Removal / Installation		HRS		6181.2			0			0
	1159SCAV409-2	0993	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PEERLESS ELECTRONICS INC
	Airframe		MSC					O/C			
312002	Copilot Cockpit Clock - Removal / Installation		HRS		6181.2			0			0
	1159SCAV409-2	0998	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PEERLESS ELECTRONICS INC
	Airframe		MSC					O/C			
312501	Thermal Printer - Removal / Installation		HRS		6181.2			0			0
	700750-1915	48402216	AFL		1568			0			0
	4	A	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
313001	Dfdr - Removal / Installation		HRS		348.1			5833.1			0
	2100-2043-00	000281602	AFL		78			1490			0
			MOS		19.7			06 May 2022			
	Airframe		MSC					O/C			
313002	Dfdr - Functional Test		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7	-44	24	06 May 2022 31 Mar 2024*	30 Apr 2024		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: PN: 2100-2043-00 SN: <NONE>.											
313006	Dfdr Underwater Locator Beacon - Battery Discard		HRS		467.9			5713.3			0
	DK120/90	AT147596	AFL		100			1468			0
			MOS		25.6			11 Nov 2021 31 May 2027			
	Airframe		MSC					DUE			EXPIRATION
Notes: NEXT DUE DATE 05/2024											
313009	Dfdr Underwater Locator Beacon - Battery Replacement		HRS		467.9			5713.3			0
	DK120/90	AT147596	AFL		100			1468			0
			MOS		25.6			11 Nov 2021			
	Airframe		MSC					O/C			
Notes: NEXT DUE DATE 05/2024											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313010	Dfdr Underwater Locator Beacon - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		24	18 Mar 2023	31 Mar 2025	30 Apr 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313020	Dfdr Underwater Locator Beacon - Switch Cleaning		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4		24	18 Mar 2023	31 Mar 2025	30 Apr 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313033	Flight Data Recorder (FDR) - Read-Out of Recorded Data (EASA ICAO)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3	4028	12	21 Aug 2006	31 Aug 2029*		
	Airframe		[End Of Month Item]								
313034	Flight Data Recorder (FDR) - Calibration of the FDR System (EASA ICAO)		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9		60	02 Jun 2023	30 Jun 2028		
	Airframe		[End Of Month Item]								
313035	Cockpit Voice Recorder (Cvr) - Read-Out of Recorded Data (EASA ICAO)		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.4			16 Mar 2021			
	Airframe		MSC				O/C				
		[End Of Month Item]									
313054	Recorder, Quick Access (Mini QAR)		HRS		6181.2			0			0
	QAR200-03-04	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
		[End Of Month Item]									
313101	Dfdr Impact Switch - Removal / Installation		HRS		6181.2			0			0
	1159SCAV402-2	2320	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			DAVTRON INC
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313102	Dfdr Tri-Axial Accelerometer - Removal / Installation		HRS		1245.7			4935.5			0
	3001-01-100	0409-15111	AFL		296			1272			0
			MOS		65.5			12 Jul 2018			AMETEK
	Airframe		MSC								AEROSPACE GULTON STATHAM PRODUCTS
313105	Dfdr Underwater Locator Beacon - Removal / Installation		HRS		467.9			5713.3			0
	DK120/90	AT147596	AFL		100			1468			0
			MOS		25.6			11 Nov 2021			
	Airframe		MSC								
314002	Central Maintenance Computer Module - Removal / Installation		HRS	TSN:2121.9	2159.9			4021.3			0
	7034055-1901	10081335	AFL	TSN:484	548			1020			0
			MOS	TSN:49	107.5			14 Jan 2015			HONEYWELL
	Airframe		MSC								
314025	Central Maintenance System - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC								
314120	Ascb - Telnet Sweep		HRS		1244.1			4937.1			0
			AFL		295			1273			0
			MOS		65.4			18 Jul 2018			
	Airframe		MSC								
Notes: N/A BY ACFT EFFECTIVITY											
314301	Power Supply Module No. 1 - Removal / Installation		HRS		6181.2			0			0
	7024440-1901	06065641	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC								
314302	Power Supply Module No. 2 - Removal / Installation		HRS		6181.2			0			0
	7024440-1901	06065653	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314303	Data Base Module No. 1 - Removal / Installation		HRS		6181.2			0			0
	7026532-1902	06071836	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314304	Data Base Module No. 2 - Removal / Installation		HRS		6181.2			0			0
	7026532-1902	06071847	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314305	Control I/O Module - Removal / Installation		HRS		4830.6			1350.6			0
	7026534-1902	07022412	AFL		1172			396			0
			MOS		167.5			15 Jan 2010			HONEYWELL
	Airframe		MSC					O/C			
314306	Custom I/O Module No. 1 - Removal / Installation		HRS		6181.2			0			0
	7026540-1901	06060654	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314307	Single Channel Gio Module No. 1 - Removal / Installation		HRS		1912.4			4268.8			0
	7025364-1901	13037829	AFL		474			1094			0
			MOS		99			30 Sep 2015			HONEYWELL
	Airframe		MSC					O/C			
314308	Single Channel Gio Module No. 2 - Removal / Installation		HRS		6181.2			0			0
	7025364-1902	06062083	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314310	Dbm - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314311	Network Interface Controller / Processor Module No. 1 - Removal / Installation		HRS		2860.1			3321.1			0
	7038231-1902	13064366	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			INTERNATIONAL

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314312	Network Interface Controller / Processor Module No. 2 - Removal / Installation		HRS		2860.1			3321.1			0
			AFL		711			857			0
	7038231-1902	13064242	MOS		124.5			15 Aug 2013			HONEYWELL
			MSC								INTERNATIONAL
Airframe											
314313	Dual Channel Gio Module No. 1 - Removal / Installation		HRS		1903.2			4278			0
			AFL		471			1097			0
	7025365-1902	06072441	MOS		94			29 Feb 2016			
			MSC								
Airframe											
314314	Advanced Graphic Module No. 1 - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	7036410-1901	10116861	MOS		156.5			14 Dec 2010			HONEYWELL
			MSC								
Airframe											
314317	Dual Channel Gio Module - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
314320	Modular Avionics Unit - Operational Check		HRS		693.08			5488.12			0
			AFL		154			1414			0
			MOS		45.8			04 Mar 2020			
			MSC								
Airframe											
314401	Power Supply Module No. 3 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7024440-1901	06065662	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								
Airframe											
314402	Power Supply Module No. 4 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7024440-1901	06065680	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								
Airframe											
314403	Video Module No. 1 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7026531-1902	06071017	MOS		208.3			21 Aug 2006			HONEYWELL
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314404	Custom I/O Module No. 2 - Removal / Installation		HRS		2860.1			3321.1			0
	7026540-1903	13043177	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC							O/C	
314405	Single Channel Gio Module No. 3 - Removal / Installation		HRS		6181.2			0			0
	7025364-1901	06062173	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC							O/C	
314406	Single Channel Gio Module No. 4 - Removal / Installation		HRS		0			6181.2			0
	7025364-1901	07062999	AFL		0			1568			0
			MOS		.4			18 Dec 2023			N/A
	Airframe		MSC							O/C	
314409	Network Interface Controller / Processor Module No. 3 - Removal / Installation		HRS		2860.1			3321.1			0
	7038231-1902	13064399	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL INTERNATIONAL
	Airframe		MSC							O/C	
314410	Network Interface Controller / Processor Module No. 4 - Removal / Installation		HRS		2860.1			3321.1			0
	7038231-1902	13064363	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL INTERNATIONAL
	Airframe		MSC							O/C	
314411	Dual Channel Gio Module No. 2 - Removal / Installation		HRS		693.08			5488.12			0
	7025365-1902	1405A145	AFL		154			1414			0
			MOS		45.8			04 Mar 2020			
	Airframe		MSC							O/C	
314412	Advanced Graphic Module No. 2 - Removal / Installation		HRS		4282.2			1899			0
	7036410-1901	10116862	AFL		1032			536			0
			MOS		156.5			14 Dec 2010			HONEYWELL
	Airframe		MSC							O/C	
314500	Single Channel Gio Module - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314501	Power Supply Module No. 5 - Removal / Installation		HRS		6181.2			0			0
	7024440-1901	06065682	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314502	Power Supply Module No. 6 - Removal / Installation		HRS		6181.2			0			0
	7024440-1901	06065690	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314503	Video Module No. 2 - Removal / Installation		HRS		6181.2			0			0
	7026531-1902	06071014	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314504	Custom I/O Module No. 3 - Removal / Installation		HRS		2860.2			3321			0
	7026540-1903	13043179	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			
314505	Single Channel Gio Module No. 5 - Removal / Installation		HRS		6181.2			0			0
	7025364-1901	04010528	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
314506	Single Channel Gio Module No. 6 - Removal / Installation		HRS		1903.2			4278			0
	7025364-1902	13064398	AFL		471			1097			0
			MOS		94			29 Feb 2016			HONEYWELL
	Airframe		MSC					O/C			
314507	Network Interface Controller / Processor Module No. 5 - Removal / Installation		HRS		2860.2			3321			0
	7034057-1902	13064398	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			INTERNATIONAL
314508	Network Interface Controller / Processor Module No. 6 - Removal / Installation		HRS		2860.2			3321			0
	7034057-1902	13064334	AFL		711			857			0
			MOS		124.5			15 Aug 2013			HONEYWELL
	Airframe		MSC					O/C			INTERNATIONAL

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314509	Advanced Graphic Module No. 3 - Removal / Installation		HRS		4281.8			1899.4			0
	7026545-1902	10116883	AFL		1032			536			0
			MOS		156.5			14 Dec 2010			HONEYWELL
	Airframe		MSC					O/C			
314510	Advanced Graphic Module No. 4 - Removal / Installation		HRS		4282.2			1899			0
	7036410-1901	10116864	AFL		1032			536			0
			MOS		156.5			14 Dec 2010			HONEYWELL
	Airframe		MSC					O/C			
314512	Nic / Processor - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314513	Custom I/O Module - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314514	Control I/O Module - Return to Service Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
314521	Nic / Processor Module Battery No. 1 - Discard		HRS		6181.2			0			0
	7025879-400	6642	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE
314524	Nic / Processor Module Battery No. 2 - Discard		HRS		6181.2			0			0
	7025879-400	6714	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE
314527	Nic / Processor Module Battery No. 3 - Discard		HRS		6181.2			0			0
	7025879-400	6639	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314530	Nic / Processor Module Battery No. 4 - Discard		HRS		6181.2			0			0
	7025879-400	6635	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE
314533	Nic / Processor Module Battery No. 5 - Discard		HRS		6181.2			0			0
	7025879-400	6948	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE
314536	Nic / Processor Module Battery No. 6 - Discard		HRS		6181.2			0			0
	7025879-400	6719	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			MANUFACTURE
315001	Central Warning System (Including Audio) - Operational Test		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		[HRS: +50/-50]								
Notes: WO SC13165											
315005	Switch, Alt Decompression Annu		HRS		6173.3			7.9			0
	214C50-60	G024857N	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM BRN SPARES IPT
	Airframe		MSC					O/C			
315610	Checklist - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
316001	Display Controller (Pilot) - Removal / Installation		HRS		4281.8			1899.4			0
	7007540-809	06102357	AFL		1032			536			0
			MOS		156.5			14 Dec 2010			HONEYWELL
	Airframe		MSC					O/C			
316002	Display Controller (Copilot) - Removal / Installation		HRS		1669.2			4512			0
	7007540-809	08012582	AFL		397			1171			0
			MOS		82.2			23 Feb 2017			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316003	Display Controller - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe			MSC				O/C			
316004	Display Brightness Control Panel - Removal / Installation		HRS		6181.2			0			0
	7007543-903	06061123	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe			MSC				O/C			HPG
316010	Cursor Control Device (Left) - Removal / Installation		HRS		130.8			6050.4			0
	1159F57160-9	0339	AFL		29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe			MSC				O/C			
316011	Cursor Control Device (Left) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe			MSC				O/C			
316013	Cursor Control Device (Right) - Removal / Installation		HRS		130.8			6050.4			0
	1159F57160	0518	AFL		29			1539			0
			MOS		6.9			02 Jun 2023			N/A
	Airframe			MSC				O/C			
316014	Cursor Control Device (Right) - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe			MSC				O/C			
316021	Display Unit No. 1 - Removal / Installation		HRS		6181.2			0			0
	7028140-901	06041712	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe			MSC				O/C			
316022	Display Unit No. 2 - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	7028140-901	06051708	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.1			25 Apr 2023			N/A
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316023	Display Unit No. 3 - Removal / Installation		HRS		130.8			6050.4			0
	7028140-911	15069593	AFL		29			1539			0
			MOS		8.1			27 Apr 2023			N/A
	Airframe		MSC					O/C			
316024	Display Unit No. 4 - Removal / Installation		HRS	TSN:7.9	6173.3			7.9			0
	7028140-901	06061812	AFL	TSN:6	1562			6			0
			MOS	TSN:5	203.4			16 Jan 2007			HONEYWELL
	Airframe		MSC					O/C			
316027	EDS - Return to Service Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
316030	Electronic Display System - Return to Service Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			
316201	Display Unit Manual Reversion - Operational Test		HRS		665.8		1500	5515.4	7015.4	7065.4	0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
	Airframe							[HRS: +50/-50]			
316203	McdU Capability to Display Standby Engine Instruments - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
316205	Dfdr Fail Message - Operational Test		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7		24	06 May 2022	31 May 2024	30 Jun 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
316206	Configuration Message - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.2		36	22 Apr 2021	30 Apr 2024	31 May 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316207	Egpws / Windshear Warning System - Operational Test		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		107.5			14 Jan 2015			
	Airframe		MSC					O/C			
316208	Elevator Mistrim / Aileron Retrim Messages - Operational Test		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		107.5			14 Jan 2015			
	Airframe		MSC					O/C			
317050	Monthly QAR Download		HRS		10.1			6171.1			0
			AFL		1			1567			0
			DATE		16 d			30d	13 Dec 2023	12 Jan 2024	
	Airframe										
Notes: PN: QAR200-03-04 SN: <NONE>											
319010	Honeywell Planeview Operational Software Master Operating System - Top Level System (White Disk)		HRS		404.7			5776.5			0
	EB7031236-00330		AFL		92			1476			0
	35697645		MOS	TSN:2	22.7			07 Feb 2022			
	Airframe		MSC					O/C			
319011	Planeview System Charts - Update		HRS		10.1			6171.1			0
			AFL		1			1567			0
			MOS		.5			12 Dec 2023	30 Dec 2023		
	Airframe		MSC					O/C			EXPIRATION
319012	Honeywell Planeview, Operational Software (Master Operating System) - Media (White Disk)		HRS		404.7			5776.5			0
	MM7031236-00330		AFL		92			1476			0
	35697645		MOS	TSN:2	22.7			07 Feb 2022			
	Airframe		MSC					O/C			
319013	Red Disk Honeywell / Jeppesen - Aerospace, Communication, Navigation Data, (28 Day Interval)		HRS		10.8			6170.4			0
			AFL		2			1566			0
			DATE		35 d			28d	24 Nov 2023	28 Dec 2023	
	Airframe										EXPIRATION
Notes: use code 346025 for red disc fms navigation, use code 319011 for blue disc chartsDO NOT ADD BACK SO 5-5-22											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
319015	Honeywell Planeview, Configuration (Aircraft Options)		HRS		597.1			5584.1			0
	Software - Top Level System (Yellow Disk)		AFL		124			1444			0
	TT60002648-50375	73071	MOS	TSN:1	29.7			08 Jul 2021			
			MSC							O/C	
Airframe											
319016	Green Disk Honeywell / Jeppesen - Terrain Data (on Condition or Six Month Interval)		HRS		69.6			6111.6			0
			AFL		14			1554			0
			MOS		3.8			04 Sep 2023			
			MSC							O/C	
Airframe											
319017	Honeywell Planeview, Aircraft Options Data Software - Media (White Disk)		HRS		597.1			5584.1			0
			AFL		124			1444			0
	DM60002648-50375	73071	MOS	TSN:1	29.7			08 Jul 2021			
			MSC							O/C	
Airframe											
319020	Gulfstream, Electronic Checklist Software (Purple Disk)		HRS		404.7			5776.5			0
			AFL		92			1476			0
	GVPV0105000008L.ECL	08DEC2020	MOS	TSN:13	22.7			07 Feb 2022			
			MSC							O/C	
Airframe											
319022	CD, Electronic Checklist Media		HRS		404.7			5776.5			0
			AFL		92			1476			0
	GVPV0105000008L.ECL	08DEC2020	MOS	TSN:14	22.7			07 Feb 2022			
			MSC							O/C	
Airframe											
319025	Gulfstream, Setting / Rigging Software (Grey Disk)		HRS		597.1			5584.1			0
			AFL		124			1444			0
	ECKBR 0XA7009C	2JULY2021	MOS	TSN:1	29.7			08 Jul 2021			
			MSC							O/C	
Airframe											
319027	CD, Settings / Rigging Media		HRS		597.1			5584.1			0
			AFL		124			1444			0
	ECKBR 0XA7009C	2JULY2021	MOS	TSN:1	29.7			08 Jul 2021			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
319030	Gulfstream, Central Maintenance Computer Loadable Diagnostic Information Software (Black Disk)		HRS		404.7			5776.5			0
			AFL		92			1476			0
	GV_912_00330_01_060420	5124	MOS		22.7			07 Feb 2022			
			MSC							O/C	
Airframe											
319032	CD, Cmc Diagnostic Media		HRS		404.7			5776.5			0
			AFL		92			1476			0
	GV_912_00330_01_060420	5124	MOS		22.7			07 Feb 2022			
			MSC							O/C	
Airframe											
319044	Gulfstream, Programmable CAS Messages Software (Turquoise Disk)		HRS		4282.2			1899			0
			AFL		1032			536			0
	6B88701D GVSP BLANK	4 APR 2007	MOS		156.5			14 Dec 2010			
			MSC							O/C	
Airframe											
319048^U	No.1 and No. 2 ATC Database		HRS		2358.2			3823			0
			AFL		600			968			0
	69000767-505	10126225	MOS		112.2			22 Aug 2014			
			MSC							-	
Airframe											
32 - Landing Gear											
320101	Main Gear Flow Regulator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	159H10040-155	2575G02	MOS		208.3			21 Aug 2006			
			MSC							O/C	AIRLIFT HYDRAULICS INCORPORATED
Airframe											
320102	Main Gear Flow Regulator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	159H10040-155	2568G02	MOS		208.3			21 Aug 2006			
			MSC							O/C	AIRLIFT HYDRAULICS INCORPORATED
Airframe											
321001	Main Landing Gear (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159L50001-19	MA0397	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321002	Main Landing Gear (Right) - Removal / Installation		HRS		6181.2			0			0
	1159L50001-20	MA0398	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
321003	Main Landing Gear Components (Left) - Detailed Corrosion Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4		48	18 Apr 2021	30 Apr 2025	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321004	Main Landing Gear Components (Right) - Detailed Corrosion Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4		48	18 Apr 2021	30 Apr 2025	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321005	Main Landing Gear (Left) - Lubrication		HRS		33.9			6147.3			0
			AFL		6			1562			0
			MOS		2.3	-23	4	20 Oct 2023	31 Jan 2024*	29 Feb 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321006	Main Landing Gear (Right) - Lubrication		HRS		33.9			6147.3			0
			AFL		6			1562			0
			MOS		2.3	-23	4	20 Oct 2023	31 Jan 2024*	29 Feb 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321007	Main Landing Gear Strut Assembly (Left) - Discard		HRS		6181.2			0			0
	1159L50001-25	SN-UNKNOWN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
321008	Main Landing Gear Strut Assembly (Right) - Discard		HRS		6181.2			0			0
	1159L50001-26	SN-UNKNOWN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
321009	Main Gear Structural Post (Left) - Discard		HRS		6181.2			0			0
	1159LM50126-9	MK0064	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
	Airframe										GOODRICH CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321010	Main Gear Structural Post (Right) - Discard		HRS		6181.2			0			0
	1159LM50126-10	MK0063	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321011	Main Landing Gear Structural Post (Left) - Restore		HRS		6181.2			0			0
	1159LM50126-9	MK0064	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321012	Main Landing Gear Structural Post (Right) - Restore		HRS		6181.2			0			0
	1159LM50126-10	MK0063	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321013	Main Landing Gear Trunnion Pin (Left Forward) - Discard		HRS		6181.2			0			0
	1159LM50853-3	AAP1713	AFL		1568		20000	0	20000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321014	Main Landing Gear Trunnion Pin (Right Forward) - Discard		HRS		6181.2			0			0
	1159LM50853-3	AAP1735	AFL		1568		20000	0	20000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321015	Main Landing Gear Forward Trunnion Pin (Left) - Restore		HRS		6181.2			0			0
	1159LM50853-3	AAP1713	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321016	Main Landing Gear Forward Trunnion Pin (Right) - Restore		HRS		6181.2			0			0
	1159LM50853-3	AAP1735	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321017	Main Landing Gear Trunnion Pin (Left Aft) - Discard		HRS		6181.2			0			0
	1159SCL566-13	MBM0457	AFL		1568		20000	0	20000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321018	Main Landing Gear Trunnion Pin (Right Aft) - Discard		HRS		6181.2			0			0
	1159SCL566-13	MBM0497	AFL		1568		20000	0	20000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321021	Main Landing Gear Spindle Pin (Left) - Discard		HRS		6181.2			0			0
	1159LM50137-7	MBM0146	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
321022	Main Landing Gear Spindle Pin (Right) - Discard		HRS		6181.2			0			0
	1159LM50137-7	MBM0154	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321023	Main Landing Gear Spindle Pin (Left) - Restore		HRS		6181.2			0			0
	1159LM50137-7	MBM0146	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
321024	Main Landing Gear Spindle Pin (Right) - Restore		HRS		6181.2			0			0
	1159LM50137-7	MBM0154	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
321025	Main Landing Gear (Left) - Rigging / Adjustment		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7				06 May 2022		
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321026	Main Landing Gear (Right) - Rigging / Adjustment		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7			06 May 2022			
	Airframe		MSC					O/C			
321027	Main Gear Trunnion Pin (Left Forward) - Removal / Installation		HRS	TSN:5581	597.1			5584.1			0
			AFL	TSN:1443	124			1444			0
	1159LM50853-3	AAP1713	MOS	TSN:176	32.4			16 Apr 2021			N/A
	Airframe		MSC					O/C			
321028	Main Gear Trunnion Pin (Right Forward) - Removal / Installation		HRS	TSN:5581	597.1			5584.1			0
			AFL	TSN:1443	124			1444			0
	1159LM50853-3	AAP1735	MOS	TSN:176	32.4			16 Apr 2021			N/A
	Airframe		MSC					O/C			
321029	Main Gear Trunnion Pin (Left Aft) - Removal / Installation		HRS	TSN:5581	597.1			5584.1			0
			AFL	TSN:1443	124			1444			0
	1159SCL566-13	MBM0457	MOS	TSN:176	32.4			16 Apr 2021			N/A
	Airframe		MSC					O/C			
321030	Main Gear Trunnion Pin (Right Aft) - Removal / Installation		HRS	TSN:5581	597.1			5584.1			0
			AFL	TSN:1443	124			1444			0
	1159SCL566-13	MBM0497	MOS	TSN:176	32.4			16 Apr 2021			N/A
	Airframe		MSC					O/C			
321031	Main Landing Gear (Left) - Restore		HRS		6181.2			0			0
	1159L50001-25	SN-UNKNOWN	AFL		1568		5000	0	5000		0
	Airframe		MOS		208.3			21 Aug 2006			
321032	Main Landing Gear (Right) - Restore		HRS		6181.2			0			0
	1159L50001-26	SN-UNKNOWN	AFL		1568		5000	0	5000		0
	Airframe		MOS		208.3			21 Aug 2006			
321039	Main Landing Gear Sponson Bores (Left) - Structural Inspection		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
	(321039)		MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321040	Main Landing Gear Sponson Bores (Right) - Structural Inspection		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		
(321040)											
Airframe											
321043	Main Gear Fairing (Left) - Removal / Installation		HRS		6181.2			0			0
	1159W50401-9	0320	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
321044	Main Gear Fairing (Right) - Removal / Installation		HRS		6181.2			0			0
	1159W50401-10	0320	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
321045	Main Landing Gear and Attachments (Left) - General Visual Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.2				24 Apr 2023		
			[HRS: +50/-50]								
Airframe											
Notes: WO SC13165											
321046	Main Landing Gear and Attachments (Right) - General Visual Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.2				24 Apr 2023		
			[HRS: +50/-50]								
Airframe											
Notes: WO SC13165											
321201	Main Landing Gear Shock Absorber (Left) - Servicing		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		48	19 Apr 2021	30 Apr 2025	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: FREQUENCY CHANGED FROM 36 MOS TO 48 MOS PER AMM REV. 26											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321202	Main Landing Gear Shock Absorber (Right) - Servicing		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		48	19 Apr 2021	30 Apr 2025	31 May 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
Notes: FREQUENCY CHANGED FROM 36 MOS TO 48 MOS PER AMM REV. 26											
321203	Main Gear Shock Absorber (Left) - Discard		HRS		6181.2			0			0
	1159L50100-11	PLT0082	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
321204	Main Gear Shock Absorber (Right) - Discard		HRS		6181.2			0			0
	1159L50100-11	PLT0080	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
321205	Main Gear Shock Absorber (Left) - Restore		HRS		6181.2			0			0
	1159L50100-11	PLT0082	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
321206	Main Gear Shock Absorber (Right) - Restore		HRS		6181.2			0			0
	1159L50100-11	PLT0080	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
321207	Main Gear Shock Strut Attachment Pin (Left Upper Attach Pin) - Discard		HRS		6181.2			0			0
	1159LM50147-11	CH0801	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
321208	Main Gear Shock Strut Attachment Pin (Right Upper Attach Pin) - Discard		HRS		6181.2			0			0
	1159LM50147-11	CH0796	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321209	Main Landing Gear Shock Strut Attach Pin (Left Upper) - Restore		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
	1159LM50147-11	CH0801	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321210	Main Landing Gear Shock Strut Attach Pin (Right Upper) - Restore		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
	1159LM50147-11	CH0796	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321211	Main Gear Shock Strut Attachment Pin (Left Lower Attach Pin) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM50147-11	CH0775	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321212	Main Gear Shock Strut Attachment Pin (Right Lower Attach Pin) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM50147-11	CH0827	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321213	Main Landing Gear Shock Strut Attach Pin (Left Lower) - Restore		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
	1159LM50147-11	CH0775	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321214	Main Landing Gear Shock Strut Attach Pin (Right Lower) - Restore		HRS		6181.2			0			0
			AFL		1568		5000	0	5000		0
	1159LM50147-11	CH0827	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321215	Main Gear Shock Strut Cylinder Nut (Left) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM50112-13	NSN	MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321216	Main Gear Shock Strut Cylinder Nut (Right) - Discard		HRS		6181.2			0			0
	1159LM50112-13	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321217	Main Landing Gear Shock Absorber (Left) - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	1159L50100-11	PLT0082	MOS	TSN:176	32.4			18 Apr 2021			N/A
			MSC					O/C			
Airframe											
Notes: UPDATE 321203 & 321205 IF REPLACED											
321218	Main Landing Gear Shock Absorber (Right) - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	1159L50100-11	PLT0080	MOS	TSN:176	32.4			17 Apr 2021			N/A
			MSC					O/C			
Airframe											
Notes: UPDATE 321204 & 321206 IF REPLACED											
321221	Main Landing Gear Corrosion Inhibiting Compound		HRS		130.8			6050.4			0
	Reapplication (Left)		AFL		29			1539			0
			MOS		7.8	-16	24	04 May 2023	30 Apr 2025*	31 May 2025	
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
321222	Main Landing Gear Corrosion Inhibiting Compound		HRS		130.8			6050.4			0
	Reapplication (Right)		AFL		29			1539			0
			MOS		7.8	-16	24	04 May 2023	30 Apr 2025*	31 May 2025	
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
321228	Main Landing Gear Axle Fitting Attach Pin (Left) Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC					O/C			
Airframe											
321232	Main Landing Gear Axle Fitting Attach Pin (Right)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			16 Apr 2021			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321235	Main Landing Gear Axle Fitting and Axle Fitting Nut (Left)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC							O/C	
Airframe											
321236	Main Landing Gear Axle Fitting and Axle Fitting Nut (Right)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC							O/C	
Airframe											
321239	Main Landing Gear Shock Absorber Upper and Lower Attach Pins (Left)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			17 Apr 2021			
			MSC							O/C	
Airframe											
321240	Main Landing Gear Shock Absorber Upper and Lower Attach Pins (Right)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			17 Apr 2021			
			MSC							O/C	
Airframe											
321243	Main Landing Gear Sidebrace Actuator Attach Pins / Trunnion AREA (Left)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC							O/C	
Airframe											
321244	Main Landing Gear Sidebrace Actuator Attach Pins / Trunnion AREA (Right)		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321247	Main Landing Gear Uplock Roller (Left) Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			16 Apr 2021			
			MSC							O/C	
Airframe											
321248	Main Landing Gear Uplock Roller (Right) Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			16 Apr 2021			
			MSC							O/C	
Airframe											
321251	Main Landing Gear Striker ARM (Left) Corrosion Inhibiting		HRS		597.1			5584.1			0
	Compound Application		AFL		124			1444			0
			MOS		32.4			17 Apr 2021			
			MSC							O/C	
Airframe											
321252	Main Landing Gear Striker ARM (Right) Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.4			17 Apr 2021			
			MSC							O/C	
Airframe											
321255	Nose Landing Gear Shock Strut and Axle Assembly		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.3			20 Apr 2021			
			MSC							O/C	
Airframe											
321256	Nose Landing Gear Trunnion Assembly Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.3			19 Apr 2021			
			MSC							O/C	
Airframe											
321259	Nose Landing Gear Truss Brace Assembly Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application - Servicing		AFL		124			1444			0
			MOS		32.3			19 Apr 2021			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321260	Nose Landing Gear Upper Trunnion Attach Pins Corrosion		HRS		597.1			5584.1			0
	Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.3			19 Apr 2021			
			MSC							O/C	
Airframe											
321263	Nose Landing Gear Upper Drag Brace Attach Pin		HRS		597.1			5584.1			0
	Corrosion Inhibiting Compound Application		AFL		124			1444			0
			MOS		32.3			19 Apr 2021			
			MSC							O/C	
Airframe											
321264	Nose Landing Gear Striker Arms Corrosion Inhibiting		HRS		597.1			5584.1			0
	Compound Application		AFL		124			1444			0
			MOS		32.3			19 Apr 2021			
			MSC							O/C	
Airframe											
321301	Main Landing Gear Axle Fitting (Left) - Removal /		HRS	TSN:2325.1	3856.1			2325.1			0
	Installation		AFL	TSN:618	950			618			0
	1159LM50140-7	MK0062	MOS	TSN:60	148.5			12 Aug 2011			
			MSC							O/C	
Airframe											
321302	Main Landing Gear Axle Fitting (Right) - Removal /		HRS	TSN:2325.1	3856.1			2325.1			0
	Installation		AFL	TSN:618	950			618			0
	1159LM50140-8	MK0071	MOS	TSN:60	148.5			12 Aug 2011			
			MSC							O/C	
Airframe											
321303	Main Landing Gear Axle Fitting (Left) - Restore		HRS		6181.2			0			0
	1159LM50140-7	MK0062	AFL		1568		5000	0	5000		0
			MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321304	Main Landing Gear Axle Fitting (Right) - Restore		HRS		6181.2			0			0
	1159LM50140-8	MK0071	AFL		1568		5000	0	5000		0
			MOS		208.3			21 Aug 2006			AIRLIFT HYDRAULICS INCORPORATE
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321305	Main Landing Gear Axle Fitting Attach Pin (Left) - Discard		HRS		6181.2			0			0
	1159LM50148-1	AT10004	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321306	Main Landing Gear Axle Fitting Attach Pin (Right) - Discard		HRS		6181.2			0			0
	1159LM50148-1	AT10019	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321307	Main Landing Gear Axle Fitting Attach Pin (Left) - Restore		HRS		6181.2			0			0
	1159LM50148-1	AT10004	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		STELLEX PRECISION MACHINING, I
Airframe											
321308	Main Landing Gear Axle Fitting Attach Pin (Right) - Restore		HRS		6181.2			0			0
	1159LM50148-1	AT10019	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		STELLEX PRECISION MACHINING, I
Airframe											
321309	Main Landing Gear Axle Fitting (Left) - Discard		HRS		6181.2			0			0
	1159LM50140-7	MK0062	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321310	Main Landing Gear Axle Fitting (Right) - Discard		HRS		6181.2			0			0
	1159LM50140-8	MK0071	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321401	Main Landing Gear Side Brace Upper Attach Pin (Left) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC								O/C
Airframe											

Notes: PN: 1159LM50164-13 SN: MBM0375.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321402	Main Landing Gear Side Brace Upper Attach Pin (Right) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
Notes: PN: 1159LM50164-13 SN: MBM0363.											
321403	Main Landing Gear Side Brace Lower Attach Pin (Left) - Discard		HRS		6181.2			0			0
			AFL		1568	16000		0	16000		0
	1159LM50164-13	MBM0375	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321404	Main Landing Gear Side Brace Lower Attach Pin (Right) - Discard		HRS		6181.2			0			0
			AFL		1568	16000		0	16000		0
	1159LM50164-13	MBM0363	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321405	Main Landing Gear Side Brace Lower Attach Pin (Left) - Restore		HRS		6181.2			0			0
			AFL		1568	5000		0	5000		0
	1159LM50164-13	MBM0375	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321406	Main Landing Gear Side Brace Lower Attach Pin (Right) - Restore		HRS		6181.2			0			0
			AFL		1568	5000		0	5000		0
	1159LM50164-13	MBM0363	MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
Airframe											
321407	Main Landing Gear Side Brace (Left) - Discard		HRS		6181.2			0			0
			AFL		1568	16000		0	16000		0
	1159SCL502-11	A707	MOS		208.3			21 Aug 2006			
Airframe											
321408	Main Landing Gear Side Brace (Right) - Discard		HRS	TSN:2317.2	3856.1			2325.1			0
			AFL	TSN:612	950	16000		618	16006		0
	1159SCL502-11	A752	MOS	TSN:55	148.5			12 Aug 2011			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321409	Main Landing Gear Side Brace (Left) - Restore		HRS		6181.2			0			0
	1159SCL502-11	A707	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		
Airframe											
321410	Main Landing Gear Side Brace (Right) - Restore		HRS	TSN:2317.2	3856.1			2325.1			0
	1159SCL502-11	A752	AFL	TSN:612	950		5000	618	5006		0
			MOS	TSN:55	148.5				12 Aug 2011		
Airframe											
321601	Main Landing Gear Weight on Wheels Cable Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCAV521-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		UNISON INDUSTRIES
Airframe											
321602	Main Landing Gear Weight on Wheels Cable Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCAV521-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		UNISON INDUSTRIES
Airframe											
321801	Main Landing Gear Door Hinges (Left) - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		8.2		24	23 Apr 2023	30 Apr 2025	31 May 2025	
Airframe [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Notes: WO SC13165											
321802	Main Landing Gear Door Hinges (Right) - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		8.2		24	23 Apr 2023	30 Apr 2025	31 May 2025	
Airframe [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Notes: WO SC13165											
321803	Main Landing Gear and Doors (Left) - Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	10	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Notes: SEE 1A WORKPACKAGE. LAST COMPLIANCE WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321804	Main Landing Gear and Doors (Right) - Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	10	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Notes: SEE 1A WORKPACKAGE. LAST COMPLIANCE WO SC13165											
321805	Main Gear Door (Left) - Removal / Installation		HRS		6181.2			0			0
	1159B54501-7	0318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
321806	Main Gear Door (Right) - Removal / Installation		HRS		6181.2			0			0
	1159B54501-8	0318	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
322001	Nose Landing Gear Assembly - Discard		HRS		6181.2			0			0
	1159L50004-19	PLT0095	AFL		1568		26200	0	26200		0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SER
Airframe											
322002	Nose Landing Gear - Removal / Installation		HRS		6181.2			0			0
	1159L50004-19	PLT0095	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
322003	Nose Landing Gear Components - Detailed Corrosion Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		48	20 Apr 2021	30 Apr 2025	31 May 2025	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322004	Nose Landing Gear - Lubrication		HRS		33.9			6147.3			0
			AFL		6			1562			0
			MOS		2.3	-23	4	20 Oct 2023	31 Jan 2024*	29 Feb 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
322005	Nose Landing Gear - Restore		HRS		6181.2			0			0
	1159L50004-19	PLT0095	AFL		1568		5000	0	5000		0
			MOS		208.3			21 Aug 2006			
Airframe											
322006	Nose Landing Gear and Attachments - General Visual Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.2			24 Apr 2023			
Airframe			[HRS: +50/-50]								
Notes: WO SC13165											
322200	Nose Landing Gear Shock Strut - Discard		HRS		6181.2			0			0
	1159L50500-13	PLT0095	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
Airframe											
322201	Nose Landing Gear Shock Strut - Removal / Installation		HRS		6181.2			0			0
	1159L50500-13	PLT0095	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			MSC				O/C				GOODRICH CORPORATION
322202	Nose Landing Gear Shock Strut - Servicing		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		48	20 Apr 2021	30 Apr 2025	31 May 2025	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
322205	Nose Landing Gear Shock Strut - Restore		HRS		6181.2			0			0
	1159L50500-13	PLT0095	AFL		1568		5000	0	5000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322206	Nose Landing Gear Shock Strut Cylinder Assembly - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM50700-1	PLT0095	MOS		208.3				21 Aug 2006		
Airframe											
322207	Nose Landing Gear Upper Torque ARM - Removal / Installation		HRS	TSN:5584.1	597.1			5584.1			0
			AFL	TSN:1444	124			1444			0
	1159LM50548-1	PLT0106	MOS	TSN:176	32.3				19 Apr 2021		N/A
			MSC					O/C			
Airframe											
322208	Nose Landing Gear Lower Torque ARM - Removal / Installation		HRS	TSN:5581	597.1			5584.1			0
			AFL	TSN:1443	124			1444			0
	1159LM30553-3	PLT0144	MOS	TSN:176	32.3				19 Apr 2021		N/A
			MSC					O/C			
Airframe											
322220	Nose Landing Gear Corrosion Inhibiting Compound Reapplication		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7	-8	24		06 May 2022 30 Apr 2024* 31 May 2024		
									[End Of Month Item] [MOS: +1m/-1m]		
Airframe											
322225	Nose Landing Gear Shock Strut Felt Wiper - Lubrication		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
322301	Nose Landing Gear Axle Fitting - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159LM50521-11	PLT0088	MOS		208.3				21 Aug 2006		
			MSC					O/C			AIRLIFT HYDRAULICS INCORPORATED
Airframe											
322305	Nose Gear Bungee - Removal / Installation		HRS		348.1			5833.1			0
			AFL		78			1490			0
	1159L10032-207	NSN	MOS		19.7				06 May 2022		
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322306	Nose Landing Gear Bungee - Lubrication		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7	-36	24	06 May 2022	31 Mar 2024*	30 Apr 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
322311	Nose Landing Gear Axle Assembly Piston - Discard		HRS		6181.2			0			0
	1159LM50521-11	PLT0088	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		
Airframe											
322401	Nose Landing Gear Trunnion - Discard		HRS		6181.2			0			0
	1159LM50690-3	PLT0138	AFL		1568		22750	0	22750		0
			MOS		208.3				21 Aug 2006		PRO-FAB, INC.
Airframe											
322402	Nose Landing Gear Trunnion - Restore		HRS		6181.2			0			0
	1159LM50690-3	PLT0138	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		PRO-FAB, INC.
Airframe											
322403	Nose Landing Gear Drag Brace - Discard		HRS		6181.2			0			0
	1159LM50585-1	PLT0076	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322404	Nose Landing Gear Drag Brace - Restore		HRS		6181.2			0			0
	1159LM50585-1	PLT0076	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322405	Nose Landing Gear Trunnion Pin (Left) - Discard		HRS		6181.2			0			0
	1159LM50611-3	PLTC0176	AFL		1568		32750	0	32750		0
			MOS		208.3				21 Aug 2006		AAR LANDING GEAR SERVICES
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322406	Nose Landing Gear Trunnion Pins (Left) - Restore		HRS		6181.2			0			0
	1159LM50611-3	PLTC0176	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		AAR LANDING GEAR SERVICES
Airframe											
322407	Nose Landing Gear Trunnion Pin (Right) - Discard		HRS		6181.2			0			0
	1159LM50613-3	PLTC0096	AFL		1568		32750	0	32750		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
322408	Nose Landing Gear Trunnion Pins (Right) - Restore		HRS		6181.2			0			0
	1159LM50613-3	PLTC0096	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
322409	Nose Landing Gear Truss Brace Assembly - Discard		HRS		6181.2			0			0
	1159LM40802-5	PLTT0108	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		
Airframe											
322410	Nose Landing Gear Truss Brace Assembly - Restore		HRS		6181.2			0			0
	1159LM40802-5	PLTT0108	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
322411	Nose Landing Gear Upper Drag Brace Pin - Discard		HRS		6181.2			0			0
	1159LM40588-19	PLTC0067	AFL		1568		4000	0	4000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
322412	Nose Landing Gear Drag Brace (Upper Pin) - Restore		HRS		6181.2			0			0
	1159LM40588-19	PLTC0067	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe						O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322413	Nose Landing Gear Lower Drag Brace Pin - Discard		HRS		6181.2			0			0
	1159LM50587-3	PLTC0105	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322414	Nose Landing Gear Lower Drag Brace Pin - Restore		HRS		6181.2			0			0
	1159LM50587-3	PLTC0105	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322415	Nose Landing Gear Actuator Attach Pins - Discard		HRS		6181.2			0			0
	1159LM40583-15	PLTC0095	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		
Airframe											
322416	Nose Landing Gear Actuator Attach Pins - Restore		HRS		6181.2			0			0
	1159LM40583-15	PTLC0095	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		PRECISION MACHINE OF SAVANNAH
Airframe											
322417	Nose Landing Gear Strut / Trunnion Pins - Discard		HRS		6181.2			0			0
	1159LM50568-13	PLT0111	AFL		1568		20000	0	20000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322418	Nose Landing Gear Strut Trunnion Pins - Restore		HRS		6181.2			0			0
	1159LM50568-13	PLT0111	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											
322419	Nose Landing Gear Upper Torque ARM - Discard		HRS		6181.2			0			0
	1159LM50548-1	PLT0106	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322420	Nose Landing Gear Upper Torque ARM - Restore		HRS		6181.2			0			0
	1159LM50548-1	PLT0106	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		
Airframe											
322421	Nose Landing Gear Lower Torque ARM - Discard		HRS		6181.2			0			0
	1159LM30553-3	PLT0144	AFL		1568		26200	0	26200		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
322422	Nose Landing Gear Lower Torque ARM - Restore		HRS		6181.2			0			0
	1159LM30553-3	PLT0144	AFL		1568		5000	0	5000		0
			MOS		208.3				21 Aug 2006		GOODRICH CORPORATION
Airframe											
322423	Nose Landing Gear Truss Brace Pin (Left Forward) -		HRS	TSN:5581	597.1			5584.1			0
	Removal / Installation		AFL	TSN:1443	124			1444			0
	1159LM40565	SN-UNKNOWN	MOS	TSN:176	32.3				19 Apr 2021		N/A
			MSC				O/C				
Airframe											
322424	Nose Landing Gear Trunnion - Removal / Installation		HRS		6181.2			0			0
	1159LM50690-3	PLT0138	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		PRO-FAB, INC.
			MSC				O/C				
Airframe											
322425	Nose Landing Gear Drag Brace - Removal / Installation		HRS		6181.2			0			0
	1159LM50585-1	PLT0076	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		B F GOODRICH AEROSPACE
			MSC				O/C				
Airframe											
322426	Nose Landing Gear Truss Brace Pin (Right Forward) -		HRS	TSN:5581	597.1			5584.1			0
	Removal / Installation		AFL	TSN:1443	124			1444			0
	1159LM40565	SN-UNKNOWN	MOS	TSN:176	32.3				19 Apr 2021		N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322427	Nose Landing Gear Truss Brace Pin (Left Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159LM40565	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
322428	Nose Landing Gear Truss Brace Pin (Right Aft) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159LM40565	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
322431	Truss Brace Assembly, Nose Landing Gear (Forward)		HRS		6181.2			0			0
			AFL		1568			0			0
	1159LM40802-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
322433	Truss Brace Assembly, Nose Landing Gear (Aft)		HRS		6181.2			0			0
			AFL		1568			0			0
	1159LM40806-7	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC							O/C	GOODRICH CORPORATION
Airframe											
322434	Nose Landing Gear Truss Brace Pin (Left Forward) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM40565	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe											
322435	Nose Landing Gear Truss Brace Pin (Right Forward) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM40565	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe											
322436	Nose Landing Gear Truss Brace Pin (Left Aft) - Discard		HRS		6181.2			0			0
			AFL		1568		16000	0	16000		0
	1159LM40565	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322437	Nose Landing Gear Truss Brace Pin (Right Aft) - Discard		HRS		6181.2			0			0
	1159LM40565	SN-UNKNOWN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
322501	Nose Gear Trunnion Assembly - Detailed Inspection		HRS		6181.2			0			0
			AFL				16000**		16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
322502	Nose Landing Gear Vertical Drag Brace Fitting Lug - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
322503	Nose Landing Gear Horizontal Drag Brace Fitting Skin Attachment - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
322504	Nose Landing Gear Horizontal Drag Brace Fitting (Forward Attach) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
322601	Nose Gear Electrical Harness - Removal / Installation		HRS		6181.2			0			0
	1159SCAV516-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				UNISON INDUSTRIES
Airframe											
322801	Nose Landing Gear Door Hinges - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		8.2		24	23 Apr 2023	30 Apr 2025	31 May 2025	
Airframe [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Notes: WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322802	Nose Landing Gear and Doors - Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	25	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Notes: WO SC13165											
322805	Valve, Park/Emerg Brake Bleed		HRS		6181.2			0			0
	1159SCH245-5	2465	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		PARKER HANNIFIN CORPORATION									
323001	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		130.8			6050.4			0
	Bottle (Left) - Removal / Installation		AFL		29			1539			0
	1159SCH233-5	30535C1	MOS		8.1			27 Apr 2023			N/A
Airframe		O/C									
323002	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		130.8			6050.4			0
	Bottle (Left) - (Hydrostatic) Restore		AFL		29			1539			0
			MOS		8.1		36	27 Apr 2023	31 Mar 2026		
Airframe		[End Of Month Item] HYDRO CHECK									
Notes: PN: 1159SCH233-5 SN: 30535C1.											
323003	Gage, L/G Dump Bottle Press		HRS		2357.4			3823.8			0
	GP20-24	08-051386	AFL		600			968			0
			MOS		112.2			22 Aug 2014			
Airframe		O/C CUSTOM METAL WORKS									
323004	Landing Gear Blow-Down Bottle Relief Valve - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCH234-5	V440	MOS		208.3			21 Aug 2006			
Airframe		O/C EATON AEROSPACE									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323005	Landing Gear Selector Panel - Removal / Installation		HRS		6181.2			0			0
	A486-19	645	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			NORTHERN FIBER GLASS SALES INC.
	Airframe		MSC					O/C			
323006	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - Servicing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
	Airframe		MSC					O/C			
323008	Nose Gear Hydraulic Flow Regulator - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH218-7	1132	MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
	Airframe		MSC					O/C			
323009	Landing Gear Hydraulic Selector / Dump Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH512-19	EFS0366A	MOS		208.3			21 Aug 2006			KAISER FLUID TECHNOLOGIES
	Airframe		MSC					O/C			
323010	Transducer, Gear Emerg Press		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV600-1	HAL2743	MOS		208.3			21 Aug 2006			GULFSTREAM - LONG BEACH
	Airframe		MSC					O/C			
323011	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Removal / Installation		HRS	TSN:337.1	130.8			6050.4			0
			AFL	TSN:71	29			1539			0
	1159SCH233-11	603-15433	MOS	TSN:20	6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323012	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		467.9			5713.3			0
	Bottle (Right) - (Hydrostatic) Restore		AFL		100			1468			0
			MOS		25.5		60	12 Nov 2021	31 Aug 2026		
			[End Of Month Item]								HYDRO CHECK
Airframe											
Notes: PN: 1159SCH233-11 SN: ALT603-14732.											
323014	Landing Gear Emergency Bottle AIR Release Control		HRS		130.8			6050.4			0
	Valve - Removal / Installation		AFL		29			1539			0
	1159H40089-9	11896136	MOS	TSN:1	6.8			03 Jun 2023			N/A
			MSC					O/C			
Airframe											
323015	Main Landing Gear Spindle Pin (Left) - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	PN	SN-UNKNOWN	MOS	TSN:176	32.4			18 Apr 2021			N/A
			MSC					O/C			
Airframe											
323016	Main Landing Gear Spindle Pin (Right) - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	PN	SN-UNKNOWN	MOS	TSN:176	32.4			18 Apr 2021			N/A
			MSC					O/C			
Airframe											
323021	Main Landing Gear Side Brace (Left) - Removal /		HRS	TSN:5584.1	597.1			5584.1			0
	Installation		AFL	TSN:1444	124			1444			0
	1159SCL502-11	A707	MOS	TSN:176	32.4			18 Apr 2021			N/A
			MSC					O/C			
Airframe											
Notes: UPDATE 321407 AND 321409 IF REPLACED											
323022	Main Landing Gear Side Brace (Right) - Removal /		HRS	TSN:5576.2	597.1			5584.1			0
	Installation		AFL	TSN:1438	124			1444			0
	1159SCL502-11	A752	MOS	TSN:172	32.4			18 Apr 2021			N/A
			MSC					O/C			
Airframe											
Notes: UPDATE 321408 AND 321410 IF REPLACED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323023	Main Landing Gear Spindle Pin Freeplay (Left) - Detailed Inspection		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.6			11 Aug 2015			
			MSC					O/C			
Airframe											
Notes: FREQUENCY REMOVED PER AMM REV. 25											
323024	Main Landing Gear Spindle Pin Freeplay (Right) - Detailed Inspection		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.6			11 Aug 2015			
			MSC					O/C			
Airframe											
Notes: FREQUENCY REMOVED PER AMM REV. 25											
323025	Main Landing Gear Sidebrace Actuator (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
323026	Main Landing Gear Sidebrace Actuator (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
323037	Main Landing Gear Bungee (Left) - Lubrication		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7	-36	24	06 May 2022 31 Mar 2024*	30 Apr 2024		
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
323038	Main Landing Gear Bungee (Right) - Lubrication		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7	-36	24	06 May 2022 31 Mar 2024*	30 Apr 2024		
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
323039	Main Landing Gear Bungee (Left) - Removal / Installation 1159L50903-1 NSN		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7			06 May 2022			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323040	Main Landing Gear Bungee (Right) - Removal / Installation		HRS		348.1			5833.1			0
			AFL		78			1490			0
	1159L50903-1	NSN	MOS		19.7			06 May 2022			
			MSC								
Airframe											
323041	Main Gear Door Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159H20264-21	55-5124GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											
Notes: END CAP											
323042	Main Gear Door Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	1159H20264-22	55-5124GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											
Notes: END CAP											
323043	Main Gear Door Actuator End CAP Fitting (Left) - Removal / Installation		HRS		6181.2			0			0
	1159H20264-21	55-5124GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
323044	Main Gear Door Actuator End CAP Fitting (Right) - Removal / Installation		HRS		6181.2			0			0
	1159H20264-22	55-5124GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
323045	Main Gear Door Actuator End CAP Fitting (Left) - Discard		HRS		6181.2			0			0
	1159H20264-21	55-5124GT	AFL		1568	9500		0	9500		0
			MOS		208.3			21 Aug 2006			
Airframe											
323046	Main Gear Door Actuator End CAP Fitting (Right) - Discard		HRS		6181.2			0			0
	1159H20264-22	55-5124GT	AFL		1568	9500		0	9500		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323051	Main Gear Uplock Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	1159H20263-9	FAH0445	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323052	Main Gear Uplock Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	1159H20263-10	FAH0455	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323053	Valve, L MLG Uplock Restrictor		HRS		6181.2			0			0
	8R3841-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
323054	Valve, R MLG Uplock Restrictor		HRS		6181.2			0			0
	8R3841-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
323060	Nose Landing Gear Actuator - Removal / Installation		HRS		6181.2			0			0
	1159H20262-21	55-5124GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
323061	Nose Gear Door Actuator - Removal / Installation		HRS		6181.2			0			0
	1159H20261-5	55-4056GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
323062	Actuator, Nose Gear Uplock		HRS		6181.2			0			0
	1159H20260-9	55-5123GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323063	Actuator, Nose Gear Downlock		HRS		6181.2			0			0
	1159L40840-5	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH CORPORATION
	Airframe		MSC					O/C			
323066	Nose Landing Gear Retract Actuator ROD End (1159SCL567) - Discard		HRS		6181.2			0			0
	1159SCL567-3	1963	AFL		1568	20000		0	20000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
323101	Main Landing Gear Uplock Timer (Left) - Removal / Installation		HRS		6181.2			0			0
	1159H20265-5	FAH0633	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
323102	Main Landing Gear Uplock Timer (Right) - Removal / Installation		HRS		6181.2			0			0
	1159H20265-5	FAH0627	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
323103	Main Landing Gear Retract Timer (Left) - Removal / Installation		HRS		6181.2			0			0
	1159H20265-1	FAH6511	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
323104	Main Landing Gear Retract Timer (Right) - Removal / Installation		HRS		6181.2			0			0
	1159H20265-1	FAH6524	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
323105	Valve, Lmg Uplock Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323106	Valve, Rmg Uplock Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323201	Main Gear Door Control Valve (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCH231-35	3274	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323202	Main Gear Door Control Valve (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCH231-35	3269	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323203	Valve, Lmg Door Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323204	Valve, Rmg Door Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323401	Regulator, L 3000 Psi Flow		HRS		6181.2			0			0
	1159SCH218-5	236	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PNEUDRAULICS
	Airframe		MSC					O/C			INC
323402	Regulator, R 3000 Psi Flow		HRS		6181.2			0			0
	1159SCH218-5	246	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PNEUDRAULICS
	Airframe		MSC					O/C			INC

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323403	Main Gear Hydraulic Swivels (Left Upper) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20270-5	55-5121GT	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323404	Main Gear Hydraulic Swivels (Right Upper) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20270-6	55-5120GT	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323405	Main Gear Hydraulic Swivels (Left Lower) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20271-8	55-5120GT	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323406	Main Gear Hydraulic Swivels (Right Lower) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20271-7	55-5120GT	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323501	Nose Landing Gear Uplock Timer - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20265-3	FAH6449	MOS		208.3			21 Aug 2006			FRISBY AEROSPACE LLC.
			MSC								
Airframe											
323502	Nose Landing Gear Retract Timer - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H20265-1	FAH6528	MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323601	Nose Gear Door Control Valve - Removal / Installation		HRS		6181.2			0			0
	1159SCH231-35	3266	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM - LONG BEACH
	Airframe		MSC					O/C			
323602	Valve, Ng Door ACT Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
323603	Nose Gear Door Actuator - Discard		HRS		6181.2			0			0
	1159H20261-5	55-4056GT	AFL		1568	13000		0	13000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
323700	Nose Landing Gear Sequencing Linkage - Check / Adjustment		HRS		348.1			5833.1			0
			AFL		78			1490			0
			MOS		19.7			06 May 2022			
	Airframe		MSC					O/C			
323701	Nose Gear Uplock Actuator - Removal / Installation		HRS		6181.2			0			0
	1159H20260-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323801	Nose Gear Hydraulic Swivel - Removal / Installation		HRS		6181.2			0			0
	7438-4	0377	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TELEDYNE CONTROLS
	Airframe		MSC					O/C			
323802	Valve, Ng Uplock ACT Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323803	Valve, Ng Actuator Shuttle		HRS		6181.2			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323804	Nose Gear Hydraulic Swivel		HRS		6181.2			0			0
	LSA14-15C4S	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323805	Nose Gear Hydraulic Swivel		HRS		6181.2			0			0
	LSA14-15C4S	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323806	Nose Gear Hydraulic Swivel		HRS		6181.2			0			0
	LSA15-14J6S	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323807	Nose Gear Hydraulic Swivel		HRS		6181.2			0			0
	LSA15-14J6S	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
323900	Landing Gear - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3			21 Apr 2021			
	Airframe		MSC					O/C			
323901	Landing Gear Emergency Extension - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8		36	03 Jun 2023	30 Jun 2026	31 Jul 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
323902	Landing Gear Emergency Extension Bottle Pressure		HRS		2357.4			3823.8			0
	Gage - Inspection		AFL		600			968			0
			MOS		112.2			22 Aug 2014			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323903	Handle, Landing Gear Emer Extn		HRS		1791.3			4389.9			0
	159F10825-15	NSN PROVIDED	AFL		422			1146			0
			MOS		85.1			25 Nov 2016			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323904	Valve, Gear Dump Bottle Relief		HRS		130.8			6050.4			0
	MC2574-3520	5073	AFL		29			1539			0
			MOS	TSN:3	6.9			02 Jun 2023			N/A
	Airframe		MSC					O/C			
323906	Landing Gear Cycling - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.8			04 May 2023			
	Airframe		MSC					O/C			
323907	Wheel Brakes - Operational Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.9			01 Apr 2020			
	Airframe		MSC					O/C			
323908	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - Discard		HRS		1476.7			4704.5			0
	1159SCH233-5	30535C1	AFL		350			1218			0
			MOS		75.5		288	15 Sep 2017 30 Jun 2036			
	Airframe							[End Of Month Item]			MANUFACTURE
323909	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Discard		HRS		467.9			5713.3			0
	1159SCH233-11	603-15433	AFL		100			1468			0
			MOS	TSN:1	25.5		180	12 Nov 2021 31 Jul 2036			
	Airframe							[End Of Month Item]			MANUFACTURE
Notes: UPDATED ACCORDED TO CERTIFICATION TAG ATTACHED TO CODE 323012											
323910	Landing Gear Emergency Extension T-Handle Linkage - General Visual Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.3		72	19 Jun 2018 30 Jun 2024 31 Jul 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
Notes: ALLIGNED WITH 6C INTERVAL											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323911	Landing Gear Emergency Extension Blowdown Bottle Relief Valve, Gage and Filler Assembly - General Visual Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	-12	36	01 Jul 2021	30 Jun 2024*	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
323914	Emergency Landing Gear System Lines - Flush		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
Airframe			MSC				O/C				
324001	Nose Wheel (Left) - Removal / Installation		HRS		467.9			5713.3			0
	55055	5067DV	AFL		100			1468			0
			MOS		25.5			12 Nov 2021			
Airframe			MSC				O/C				
324002	Nose Wheel (Right) - Removal / Installation		HRS		467.9			5713.3			0
	55055	WD110	AFL		100			1468			0
			MOS		25.5			12 Nov 2021			
Airframe			MSC				O/C				
324003	Main Wheel (Left Outboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL503-7	5267EE	AFL		124			1444			0
			MOS		32.3			19 Apr 2021			N/A
Airframe			MSC				O/C				
324004	Main Wheel (Left Inboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL503-7	5040EF	AFL		124			1444			0
	(1159L56003-		MOS		31.6			11 May 2021			N/A
Airframe			MSC				O/C				
324005	Main Wheel (Right Inboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL503-7	5026CU	AFL		124			1444			0
			MOS		32.3			19 Apr 2021			N/A
Airframe			MSC				O/C				
324006	Main Wheel (Right Outboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL503-7	5272EE	AFL		124			1444			0
			MOS		32.3			19 Apr 2021			N/A
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324007	Nose Wheel Bearings (Left) - Inspection / Pack		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.6			10 Nov 2021			
	Airframe		MSC					O/C			
324008	Nose Wheel Bearings (Right) - Inspection / Pack		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.6			10 Nov 2021			
	Airframe		MSC					O/C			
324009	Main Landing Gear Wheel Bearing (Left Outboard) - Inspection / Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.9			02 May 2023			
	Airframe		MSC					O/C			
324010	Main Landing Gear Wheel Bearing (Left Inboard) - Inspection / Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.9			02 May 2023			
	Airframe		MSC					O/C			
324011	Main Landing Gear Wheel Bearing (Right Inboard) - Inspection / Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.9			02 May 2023			
	Airframe		MSC					O/C			
324012	Main Landing Gear Wheel Bearing (Right Outboard) - Inspection / Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.9			02 May 2023			
	Airframe		MSC					O/C			
324014	Nose Tire - Inspection		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324015	Main Tire Assembly (Left Outboard) - Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			05 Jul 2018			
	Airframe		MSC					O/C			
324016	Main Tire Assembly (Right Outboard) - Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			05 Jul 2018			
	Airframe		MSC					O/C			
324017	Wheel and Brakes - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3			21 Apr 2021			
	Airframe		MSC					O/C			
324018	Nose Wheel Ndt (Left) - Special Detailed Inspection		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.5			12 Nov 2021			
	Airframe		MSC					A/R			
Notes: PN: AH55055 SN: 5041EC.											
324019	Nose Wheel Ndt (Right) - Special Detailed Inspection		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.5			12 Nov 2021			
	Airframe		MSC					A/R			
Notes: PN: AH55055 SN: 5040EC.											
324020	Main Wheel Ndt (Left Outboard) - Special Detailed Inspection		HRS		696.2			5485			0
			AFL		156			1412			0
			MOS		46.1			27 Feb 2020			
	Airframe		MSC					A/R			
Notes: PN: AHA2114 SN: 5267EE.											
324021	Main Wheel Ndt (Left Inboard) - Special Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.6			11 May 2021			
	Airframe		MSC					A/R			
Notes: PN: AHA2114 SN: 5273EE.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324022	Main Wheel Ndt (Right Inboard) - Special Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43			29 May 2020			
			MSC							A/R	
Airframe											
Notes: PN: AHA2114 SN: 5268EE.											
324023	Main Wheel Ndt (Right Outboard) - Special Detailed Inspection		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC							A/R	
Airframe											
Notes: PN: AHA2114 SN: 5272EE.											
324033	Main Tire Assembly (Left Inboard) - Inspection		HRS		955.3			5225.9			0
			AFL		227			1341			0
			MOS		55.2			23 May 2019			
			MSC							O/C	
Airframe											
324034	Main Tire Assembly (Right Inboard) - Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			05 Jul 2018			
			MSC							O/C	
Airframe											
324040	Nose Tire (Left) - Removal / Installation		HRS		467.9			5713.3			0
	217K22-1	0222496	AFL		100			1468			0
			MOS	TSN:19	25.6			10 Nov 2021			
			MSC							O/C	
Airframe											
324041	Nose Tire (Right) - Removal / Installation		HRS		467.9			5713.3			0
	217K22-1	92502441	AFL		100			1468			0
			MOS	TSN:5	25.6			10 Nov 2021			
			MSC							O/C	
Airframe											
324042	Main Tire (Left Outboard) - Removal / Installation		HRS		130.8			6050.4			0
	350K02-1	30335039	AFL		29			1539			0
			MOS		7.9			02 May 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324043	Main Tire (Left Inboard) - Removal / Installation		HRS		130.8			6050.4			0
	350K02-1	30335040	AFL		29			1539			0
			MOS		7.8			03 May 2023			
	Airframe		MSC					O/C			
324044	Main Tire (Right Inboard) - Removal / Installation		HRS		130.8			6050.4			0
	350K02-1	30225058	AFL		29			1539			0
			MOS		7.8			03 May 2023			
	Airframe		MSC					O/C			
324045	Main Tire (Right Outboard) - Removal / Installation		HRS		130.8			6050.4			0
	350K02-1	30205042	AFL		29			1539			0
			MOS		7.8			03 May 2023			
	Airframe		MSC					O/C			
324101	Main Wheel Brakes (Left) - Bleeding Procedures		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.2			22 Apr 2021			
	Airframe		MSC					O/C			
324102	Main Wheel Brakes (Right) - Bleeding Procedures		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.2			22 Apr 2021			
	Airframe		MSC					O/C			
324103	Brake Augmenter Valve - Removal / Installation		HRS		6181.2			0			0
	39-801	444	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			FINISHMASTER INC.
	Airframe		MSC					O/C			
324104	Brake System Hydraulic Fuses - Functional Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.1			26 May 2020			
	Airframe		MSC					O/C			
324105	Brake Assembly (Left Outboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL504-5	5068LQ	AFL		124			1444			0
			MOS		32.4			18 Apr 2021			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324106	Brake Assembly (Left Inboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL504-5	015CQ	AFL		124			1444			0
			MOS		32.4			18 Apr 2021			N/A
	Airframe		MSC								
324107	Brake Assembly (Right Inboard) - Removal / Installation		HRS	TSN:3259	597.1			5584.1			0
	1159SCL504-5	5220EJ	AFL	TSN:826	124			1444			0
			MOS	TSN:117	32.4			18 Apr 2021			N/A
	Airframe		MSC								
324108	Brake Assembly (Right Outboard) - Removal / Installation		HRS		597.1			5584.1			0
	1159SCL504-5	5307PB	AFL		124			1444			0
			MOS		32.4			18 Apr 2021			N/A
	Airframe		MSC								
324109	Parking / Emergency Brake Accumulator Pressure Gage - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC								
324110	Brake System Temperature Sensor (Left Outboard) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
			AFL	TSN:1418	150			1418			0
	1159SCL510-1	F9680	MOS	TSN:164	44.9			31 Mar 2020			N/A
	Airframe		MSC								
324111	Brake System Temperature Sensor (Left Inboard) - Removal / Installation		HRS	TSN:5515.4	665.8			5515.4			0
			AFL	TSN:1418	150			1418			0
	1159SCL510-1	F9681	MOS	TSN:164	44.9			31 Mar 2020			N/A
	Airframe		MSC								
324112	Brake System Temperature Sensor (Right Inboard) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
			AFL	TSN:1272	296			1272			0
	1159SCL510-1	F9674	MOS	TSN:143	65.6			09 Jul 2018			KAISER FLUID TECHNOLOGIES
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324113	Brake System Temperature Sensor (Right Outboard) - Removal / Installation		HRS	TSN:5515	665.8			5515.4			0
			AFL	TSN:1418	150			1418			0
	1159SCL510-1	F9680	MOS	TSN:165	43.3			21 May 2020			N/A
			MSC								
Airframe											
324114	Indicator, Brake Pressure(Ckpt 162LCP636		HRS		6181.2			0			0
		06077147	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			DILLON - MORGANS
			MSC								
Airframe											
324115	Gage, Brake Accum. Pressure GP20-24		HRS		4921.4			1259.8			0
		00204132	AFL		1190			378			0
			MOS		169.4			17 Nov 2009			CUSTOM METAL WORKS
			MSC								
Airframe											
324116	Dual Brake Metering Valve (Left) - Removal / Installation 1159SCL473-3		HRS		5255.6			925.6			0
		0361	AFL		1288			280			0
			MOS		179.1			26 Jan 2009			TACTAIR FLUID CONTROLS INC
			MSC								
Airframe											
324117	Dual Brake Metering Valve (Right) - Removal / Installation 1159SCL473-3		HRS		5255.6			925.6			0
		0359	AFL		1288			280			0
			MOS		179.1			26 Jan 2009			TACTAIR FLUID CONTROLS INC
			MSC								
Airframe											
324118	Brake Shuttle Valve (Forward) - Removal / Installation 1159SCH223-5		HRS		6181.2			0			0
		3205	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324119	Brake Shuttle Valve (Aft Auxiliary / Alternate) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH223-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
324120	Parking / Emergency Brake Accumulator - Removal / Installation		HRS		4921.4			1259.8			0
			AFL		1190			378			0
	1159SCH206-5	60211-2697NA	MOS		169.4			17 Nov 2009			PNEUDRAULICS INC
			MSC								
Airframe											
324121	Brake Accumulator Pressure Dump Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH245-5	2496	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC								
Airframe											
324122	Parking / Emergency Brake Selector Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	64560-3	1285	MOS		208.3			21 Aug 2006			ARC COM FABRICS
			MSC								
Airframe											
324123	Parking / Emergency Brake Accumulator Pressure Gauge - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCH241-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PROFESSIONAL AIRCRAFT ACCESSORIES
			MSC								
Airframe											
324124	Parking / Emergency Brake Accumulator - Servicing		HRS		176.2			6005			0
			AFL		38			1530			0
			MOS		11.5			13 Jan 2023			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324125	Brake Pressure Transmitter Switch (Left Outboard) -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCH240-7	HAL4648	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324126	Brake Pressure Transmitter Switch (Left Inboard) -		HRS		6181.2			0			0
	Removal / Installation		AFL		1568			0			0
	1159SCH240-7	HAL4639	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324127	Brake System Hydraulic Fuse (Upper Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCH261-5	3003	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324128	Brake System Hydraulic Fuse (Upper Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCH261-5	2994	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324129	Brake System Hydraulic Fuse (Lower Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCH261-5	2997	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324130	Brake System Hydraulic Fuse (Lower Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCH261-5	3002	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
324131	Brake Transducer Shuttle Valve (No. 1) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159H50362-5	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324132	Brake Transducer Shuttle Valve (No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159H50362-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
324133	Mechanical Brake Linkage AT Rudder Pedal - General Visual Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272		0	
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
324135	Brake Pressure Transmitter Switch (Right Inboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0		0	
	1159SCH240-7	HAL4547	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
324136	Brake Pressure Transmitter Switch (Right Outboard) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0		0	
	1159SCH240-7	HAL4561	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
324137	Limiter, #1 Brake Flow		HRS		6181.2			0			0
			AFL		1568			0		0	
	11226-6-1-7	W74377	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
324138	Limiter, #2 Brake Flow		HRS		6181.2			0			0
			AFL		1568			0		0	
	11226-6-1-7	W74387	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
324139	Limiter, #3 Brake Flow		HRS		6181.2			0			0
			AFL		1568			0		0	
	11226-6-1-7	W74416	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324140	Limiter, #4 Brake Flow		HRS		6181.2			0			0
	11226-6-1-7		AFL		1568			0			0
	W74435		MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
324141	Parking Brake Pressure Transducer - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1159SCAV600-1		MOS		208.3			21 Aug 2006			GULFSTREAM -
	HAL2699		MSC					O/C			LONG BEACH
Airframe											
324142	Fuse, Rh Emergency Brake		HRS		6181.2			0			0
	1159SCH261-5		AFL		1568			0			0
	3065		MOS		208.3			21 Aug 2006			EATON
	Airframe		MSC					O/C			AEROSPACE
324143	Fuse, Lh Emergency Brake		HRS		665.8			5515.4			0
	1159SCH261-5		AFL		150			1418			0
	7902		MOS	TSN:1	43.3			21 May 2020			N/A
	Airframe		MSC					O/C			
324144	Main Landing Gear Brake Assembly (Left Outboard) -		HRS		597.1			5584.1			0
	Detailed Inspection		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
	Airframe		MSC					O/C			
324145	Main Landing Gear Brake Assembly (Left Inboard) -		HRS		597.1			5584.1			0
	Detailed Inspection		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
	Airframe		MSC					O/C			
324146	Main Landing Gear Brake Assembly (Right Inboard) -		HRS		597.1			5584.1			0
	Detailed Inspection		AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324147	Main Landing Gear Brake Assembly (Right Outboard) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
	Airframe		MSC					O/C			
324148	Shuttle, R Fwd Aux Alt Brake		HRS		6181.2			0			0
	1159SCH223-5	3206	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
324149	Shuttle, R Aft Aux Alt Brake		HRS		6181.2			0			0
	1159SCH223-5	3148	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
324150	Nose Tire Assembly - Servicing		HRS		5725.4			455.8			0
			AFL		1438			130			0
			MOS		191.6			10 Jan 2008			
	Airframe		MSC					O/C			
324151	Brake Metering Valves (Left) - Bleeding Procedure		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
	Airframe		MSC					O/C			
324152	Brake Metering Valves (Right) - Bleeding Procedure		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324153	Brake Rotor Drive Clip (Left Outboard) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC						O/C		
Airframe											
Notes: N/A BY BRAKE P/N INSTALLED											
324154	Brake Rotor Drive Clip (Left Inboard) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC						O/C		
Airframe											
Notes: N/A BY BRAKE P/N INSTALLED											
324155	Brake Rotor Drive Clip (Right Inboard) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC						O/C		
Airframe											
Notes: N/A BY BRAKE P/N INSTALLED											
324156	Brake Rotor Drive Clip (Right Outboard) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4			18 Apr 2021			
			MSC						N/A		
Airframe											
Notes: N/A BY BRAKE P/N INSTALLED											
324183	Nose Wheel and Tire Assembly (Left) - Removal / Installation		HRS		467.9			5713.3			0
			AFL		100			1468			0
	1159L50400-11	5067DV	MOS		25.6			10 Nov 2021			
			MSC						O/C		
Airframe											
324184	Nose Wheel and Tire Assembly (Right) - Removal / Installation		HRS		467.9			5713.3			0
			AFL		100			1468			0
	1159L50400-11	WD110	MOS		25.6			10 Nov 2021			
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324201	Antiskid Control Box - Removal / Installation		HRS		6181.2			0			0
	1159SCL501-1	442	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			DUNLOP
	Airframe		MSC					O/C			AEROSPACE BRAKING SYSTEM
324202	Antiskid - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.2			22 Apr 2021			
	Airframe		MSC					O/C			
324205	Antiskid Control Valve (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCL501-3	765	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
324206	Antiskid Control Valve (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCL501-3	766	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
324207	Filter, Anti-Skid Control Valve (Left)		HRS		6181.2			0			0
	27446	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
324208	Filter, Anti-Skid Control Valve (Right)		HRS		6181.2			0			0
	27446	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
324211	Main Wheel and Tire Assembly (Left Outboard) - Removal / Installation		HRS		130.8			6050.4			0
	1159L56003-7	5267EE	AFL		29			1539			0
			MOS		7.8			03 May 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324212	Main Wheel and Tire Assembly (Left Inboard) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159L56003-7	5040EF	MOS		7.8			03 May 2023			N/A
			MSC								
Airframe											
324213	Main Wheel and Tire Assembly (Right Inboard) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159L56003-7	5026CU	MOS		7.8			03 May 2023			N/A
			MSC								
Airframe											
324214	Main Wheel and Tire Assembly (Right Outboard) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159L56003-7	5272EE	MOS		7.8			03 May 2023			N/A
			MSC								
Airframe											
324220	Wheel Speed Monitor Unit - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCL501-9	433	MOS		208.3			21 Aug 2006			HYDRO-AIRE, INC.
			MSC								
Airframe											
324221	Wheel Speed Transducer (Left Outboard) - Removal / Installation		HRS	TSN:5584.1	597.1			5584.1			0
			AFL	TSN:1444	124			1444			0
	1159SCL501-5	1465	MOS	TSN:176	32.4			18 Apr 2021			
			MSC								
Airframe											
324222	Wheel Speed Transducer (Left Inboard) - Removal / Installation		HRS	TSN:5584.1	597.1			5584.1			0
			AFL	TSN:1444	124			1444			0
	1159SCL501-5	1463	MOS	TSN:176	32.4			18 Apr 2021			
			MSC								
Airframe											
324223	Wheel Speed Transducer (Right Inboard) - Removal / Installation		HRS	TSN:5584.1	597.1			5584.1			0
			AFL	TSN:1444	124			1444			0
	1159SCL501-5	1451	MOS	TSN:176	32.4			18 Apr 2021			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324224	Wheel Speed Transducer (Right Outboard) - Removal / Installation		HRS	TSN:5584.1	597.1			5584.1			0
			AFL	TSN:1444	124			1444			0
	1159SCL501-5	1450	MOS	TSN:176	32.4			18 Apr 2021			
			MSC							O/C	
Airframe											
324291	Valve, Lh Brake Shuttle		HRS		6181.2			0			0
	1159SCH223-5	2516	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
324292	Valve, Rh Brake Shuttle		HRS		6181.2			0			0
	1159SCH223-5	2170	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
324303	Parking / Emergency Brake - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	60	36	02 Jul 2021	31 Aug 2024*	30 Sep 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
324304	Parking / Emergency Brake Cable Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	2603860-002	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM DALLAS
			MSC							O/C	
Airframe											
324305	Brake Wear Indicator (Left Outboard) - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
Airframe [HRS: +50/-50]											
Notes: PN: 1159SCL504-5 SN: <NONE>. WO SC13165											
324306	Brake Wear Indicator (Left Inboard) - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
Airframe [HRS: +50/-50]											
Notes: PN: 1159SCL504-5 SN: <NONE>. WO SC13165											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324307	Brake Wear Indicator (Right Inboard) - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCL505-4 SN: <NONE>. WO SC 13165											
324308	Brake Wear Indicator (Right Outboard) - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCL504-5 SN: <NONE>.											
324401	Brake Control System Hydraulic Fuse (Left, Outboard No. 1) - Operational Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.1		125	26 May 2020	31 Oct 2030	30 Nov 2030	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
324402	Brake Control System Hydraulic Fuse (Left, Inboard No. 2) - Operational Check		HRS								0
			AFL								0
			MOS				125		30 Sep 2031	31 Oct 2031	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
324403	Brake Control System Hydraulic Fuse (Right, Inboard No. 3) - Operational Check		HRS								0
			AFL								0
			MOS				125		30 Sep 2031	31 Oct 2031	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
324404	Brake Control System Hydraulic Fuse (Right, Outboard No. 4) - Operational Check		HRS								0
			AFL								0
			MOS				125		30 Sep 2031	31 Oct 2031	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
324601	Brake Pressure Transducer (Right) - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe			O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324700	Brake Temperature Indication - Functional Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			21 May 2020			
	Airframe		MSC					O/C			
325001	Nose Wheel Steering Unit - Removal / Installation		HRS		1044.7			5136.5			0
	1159SCL500-61	0123D	AFL		245			1323			0
			MOS		58.3			20 Feb 2019			EATON
	Airframe		MSC					O/C			AEROSPACE
325002	Tiller Assembly - Removal / Installation		HRS		6181.2			0			0
	1159SCL500-55	0438	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			EATON
	Airframe		MSC					O/C			AEROSPACE
325003	Steering - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
	Airframe		MSC					O/C			
325004	Nose Wheel Steering System - Autorig Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
	Airframe		MSC					O/C			
325101	Rudder Pedal Input Transducer Assembly - Removal / Installation		HRS		6181.2			0			0
	1159SCL500-17	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
325201	Nose Wheel Steering Unit - Lubrication		HRS		1044.7			5136.5			0
			AFL		245		2100	1323	3423		0
			MOS		58.3			20 Feb 2019			
	Airframe										

Notes: PN: 1159SCL500-61 SN: 0123D. 2100 CYCLES ADDED PER AMM REV. 25

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
325202	Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		8.2		24	23 Apr 2023	30 Apr 2025	31 May 2025	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											
325204	Nose Wheel Steering Collar Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCL500-23	SN-UNKNOWN	MOS		208.3			21 Aug 2006			EATON
			MSC				O/C				AEROSPACE
Airframe											
325205	Nose Wheel Steering Collar Assembly - Discard		HRS		6181.2			0			0
	1159SCL500-23	SN-UNKNOWN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
Airframe											
326105	Switch, Nose Gear Door		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV452-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
326201	Main Gear Weight on Wheels Switch (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV513-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GOODRICH
			MSC				O/C				CORPORATION
Airframe											
326202	Main Gear Weight on Wheels Switch (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV513-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GOODRICH
			MSC				O/C				CORPORATION
Airframe											
326203	Nose Landing Gear Weight on Wheels Switch - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV514-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326209	Main Landing Gear Weight on Wheels Cable Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV521-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			B F GOODRICH
			MSC					O/C			AEROSPACE
Airframe											
326210	Main Landing Gear Weight on Wheels Cable Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCAV521-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			B F GOODRICH
			MSC					O/C			AEROSPACE
Airframe											
326221	Nose Landing Gear Downlock Switch - Adjustment		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4				16 Jan 2007		
			MSC					O/C			
Airframe											
326230	Nose Landing Gear Weight on Wheels System - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
327000	Brake Metering Valve Retrofit Program		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
328101	Left Nose Landing Gear Door - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159B50510-47	5124	MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
328102	Right Nose Landing Gear Door - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159B50510-48	5124	MOS		208.3				21 Aug 2006		
			MSC					O/C			
Airframe											
33 - Lights											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330005	Interior Lights--OPS Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
330006	Exterior Lights--OPS Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
330901	Switch Panel #1		HRS		6173.3			7.9			0
	2501-2-002	206430033	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330902	Switch Panel #2		HRS		6173.3			7.9			0
	2501-1-065	206430026	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330903	Switch Panel #3		HRS	TSN:5507.5	665.8			5515.4			0
	2501-1-029	206420456	AFL	TSN:1412	150			1418			0
			MOS	TSN:161	43.3			20 May 2020			N/A
	Airframe		MSC					O/C			
330904	Switch Panel #4		HRS		6173.3			7.9			0
	2501-2-044	206420452	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330905	Switch Panel #5		HRS		6173.3			7.9			0
	2501-1-087	206430031	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330906	Switch Panel #6		HRS		6173.3			7.9			0
	2501-2-155	206430003	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330907	Switch Panel #7		HRS		6173.3			7.9			0
	2501-3-042	206430052	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330908	Switch Panel #8		HRS		6173.3			7.9			0
	2501-3-047	206420437	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330909	Switch Panel #9		HRS		6173.3			7.9			0
	2501-1-006	206420455	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330910	Switch Panel #10		HRS		6173.3			7.9			0
	2501-1-006	206420453	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330911	Switch Panel #11		HRS		6173.3			7.9			0
	2501-1-006	206420454	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330912	Switch Panel #12		HRS		6173.3			7.9			0
	2501-4-008	206420451	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330913	Switch Panel #13		HRS		6173.3			7.9			0
	2501-2-004	206430042	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330914	Switch Panel #14		HRS		6173.3			7.9			0
	2501-2-004	206430041	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330915	Switch Panel #15		HRS		6173.3			7.9			0
	2501-1-031	206430040	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330916	Switch Panel #16		HRS		6173.3			7.9			0
	2501-2-111	206430094	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330917	Switch Panel #17		HRS		6173.3			7.9			0
	2501-2-075	206430097	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330918	Switch Panel #18		HRS		6173.3			7.9			0
	2501-2-075	206430096	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330919	Switch Panel #19		HRS		6173.3			7.9			0
	2501-1-104	206430048	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330920	Switch Panel #20		HRS		6173.3			7.9			0
	2501-1-104	206430049	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330921	Switch Panel #21		HRS		6173.3			7.9			0
	2501-1-104	206430049	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330922	Switch Panel #22		HRS		6173.3			7.9			0
	2501-2-029	206430099	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330923	Switch Panel #23		HRS		6173.3			7.9			0
	2501-1-105	206430004	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330924	Switch Panel #24		HRS		6173.3			7.9			0
	2501-1-105	206430005	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330925	Switch Panel #25		HRS		6173.3			7.9			0
	2501-1-030	206430028	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330926	Switch Panel #26		HRS		6173.3			7.9			0
	2501-1-030	206430029	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330927	Switch Panel #27		HRS		6173.3			7.9			0
	2501-2-380	206430018	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330928	Switch Panel #28		HRS		6173.3			7.9			0
	2501-2-471	206400139	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330929	Switch Panel #29		HRS		6173.3			7.9			0
	2501-2-472	206430017	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330930	Switch Panel #30		HRS		6173.3			7.9			0
	2501-1-105	206430005	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330931	Switch Panel #31		HRS		6173.3			7.9			0
	2501-1-105	206430004	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330932	Switch Panel #32		HRS		6173.3			7.9			0
	2501-1-032	206430053	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330933	Switch Panel #33		HRS		6173.3			7.9			0
	2501-1-009	206430008	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330934	Switch Panel #34		HRS		6173.3			7.9			0
	2501-1-009	206430009	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330935	Switch Panel #35		HRS		6173.3			7.9			0
	2501-1-009	206430010	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330936	Switch Panel #36		HRS		6173.3			7.9			0
	2501-1-009	206430006	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330937	Switch Panel #37		HRS		6173.3			7.9			0
	2501-1-009	206430007	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330938	Switch Panel #38		HRS		6173.3			7.9			0
	2501-1-009	206430011	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330939	Switch Panel #39		HRS		6173.3			7.9			0
	2501-2-074	206430030	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330940	Switch Panel #40		HRS		6173.3			7.9			0
	2501-1-088	206430032	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330941	Switch Panel #41		HRS		6173.3			7.9			0
	2501-1-086	206430027	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330942	Switch Panel #42		HRS		6173.3			7.9			0
	2501-1-007	206430016	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330943	Switch Panel #43		HRS		6173.3			7.9			0
	2501-1-007	206430015	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330944	Switch Panel #44		HRS	TSN:5507.5	665.8			5515.4			0
	2501-1-134	206430046	AFL	TSN:1412	150			1418			0
			MOS	TSN:161	43.3			20 May 2020			N/A
	Airframe		MSC					O/C			
330945	Switch Panel #45		HRS		6173.3			7.9			0
	2501-1-134	206430047	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330946	Switch Panel #46		HRS		6173.3			7.9			0
	2501-2-030	206430051	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330947	Switch Panel #47		HRS		6173.3			7.9			0
	2501-2-002	206430034	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330948	Switch Panel #48		HRS		6173.3			7.9			0
	2501-2-002	206430035	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
330949	Switch Panel #49		HRS		6173.3			7.9			0
	2501-2-482	206430101	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
331001	Cockpit Annunciator Dim and Test Control Unit - Removal / Installation		HRS		4951.2			1230			0
	1159SCAV526-7	0253	AFL		1196			372			0
			MOS		170.5			14 Oct 2009			ELECTRONIC CABLE SPECIALISTS
	Airframe		MSC					O/C			
331005	Pilot Cockpit Lighting Control Panel Assembly - Removal / Installation		HRS		4830.6			1350.6			0
	1159AV59311-2	A00714195	AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
	Airframe		MSC					O/C			
331006	Copilot Cockpit Lighting Control Panel Assembly - Removal / Installation		HRS		6181.2			0			0
	1159AV59312-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
331010	Tray, Annunciator Lts Test		HRS		6181.2			0			0
	71-1046-1	1000	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHELTON INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
331100	Cockpit Annunciator Lights Dim and Test System (Press to Test) - Operational Check		HRS		584			5597.2			0
			AFL		123			1445			0
			MOS		28.3			19 Aug 2021			
			MSC							O/C	
Airframe											
332101	Power Supply, #1 Protected		HRS		6173.3			7.9			0
	AL-2000	49346	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE LIGHTING CORPORATION
			MSC							O/C	
Airframe											
332102	Power Supply, #2 Protected		HRS		6173.3			7.9			0
	AL-2000	49368	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE LIGHTING CORPORATION
			MSC							O/C	
Airframe											
332103	Power Supply, #3 Protected		HRS		6173.3			7.9			0
	AL-2000	49039	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE LIGHTING CORPORATION
			MSC							O/C	
Airframe											
332104	Power Supply, #4 Protected		HRS		6173.3			7.9			0
	AL-2000	49038	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE LIGHTING CORPORATION
			MSC							O/C	
Airframe											
332105	Power Supply, #5 Protected		HRS		6181.2			0			0
	AL-2000	49343	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			B/E AEROSPACE LIGHTING CORPORATION
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332106	Power Supply, #6 Protected		HRS		6173.3			7.9			0
	AL-2000	49344	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332107	Power Supply, #7 Protected		HRS		6173.3			7.9			0
	AL-2000	49345	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332191	Dimmer, #1 Cbn Lights		HRS		6173.3			7.9			0
	AL-2022	3351	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332201	Light Assy, #1 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5709	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332202	Light Assy, #2 Cabin		HRS	TSN:5576.2	597.1			5584.1			0
	5800-300-451000	5696	AFL	TSN:1438	124			1444			0
			MOS	TSN:172	32			30 Apr 2021			N/A
	Airframe		MSC					O/C			
332203	Light Assy, #3 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	8001	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332204	Light Assy, #4 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7990	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332205	Light Assy, #5 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7997	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332206	Light Assy, #6 Cabin		HRS	TSN:5576.2	597.1			5584.1			0
	5800-300-451000	8002	AFL	TSN:1438	124			1444			0
			MOS	TSN:172	32			30 Apr 2021			N/A
	Airframe		MSC					O/C			
332207	Light Assy, #7 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7991	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332208	Light Assy, #8 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	8003	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332209	Light Assy, #9 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7994	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332210	Light Assy, #10 Cabin		HRS		6173.3			7.9			0
	5800-300-451000		AFL		1562			6			0
	7993		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332211	Light Assy, #11 Cabin		HRS		6173.3			7.9			0
	5800-300-451000		AFL		1562			6			0
	7999		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332212	Light Assy, #12 Cabin		HRS		6173.3			7.9			0
	5800-300-451000		AFL		1562			6			0
	7992		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332213	Light Assy, #13 Cabin		HRS		6173.3			7.9			0
	5800-300-451000		AFL		1562			6			0
	7989		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332214	Light Assy, #14 Cabin		HRS		3521.5			2659.7			0
	5800-300-451000		AFL		865			703			0
	16829		MOS		141.5			14 Mar 2012			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332215	Light Assy, #15 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7988	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332216	Light Assy, #16 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7986	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332217	Light Assy, #17 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7101	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332218	Light Assy, #18 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7987	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332219	Light Assy, #19 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7996	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332220	Light Assy, #20 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	8000	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332221	Light Assy, #21 Cabin		HRS		6173.3			7.9			0
	5800-300-451000	7998	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332222	Light Assy, #22 Cabin		HRS		2159.9			4021.3			0
	5800-300-451000	18881	AFL		548			1020			0
			MOS		107.5			14 Jan 2015			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332223	Light Assy, #23 Cabin		HRS		2159.9			4021.3			0
	5800-300-451000	18890	AFL		548			1020			0
			MOS		107.5			14 Jan 2015			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332224	Light Assy, #24 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2636	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332225	Light Assy, #25 Cabin		HRS		6173.3			7.9			0
	5800-090-451000		AFL		1562			6			0
	2678		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332226	Light Assy, #26 Cabin		HRS		6173.3			7.9			0
	5800-090-451000		AFL		1562			6			0
	2638		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332227	Light Assy, #27 Cabin		HRS		6173.3			7.9			0
	5800-090-451000		AFL		1562			6			0
	2637		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332228	Light Assy, #28 Cabin		HRS		6173.3			7.9			0
	5800-090-451000		AFL		1562			6			0
	2681		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS
332229	Light Assy, #29 Cabin		HRS		6173.3			7.9			0
	5800-090-451000		AFL		1562			6			0
	2680		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC				O/C				SAV COMPLETION IPTS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332230	Light Assy, #30 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2683	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332231	Light Assy, #31 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2682	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332232	Light Assy, #32 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2685	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332233	Light Assy, #33 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2684	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332234	Light Assy, #34 Cabin		HRS		6173.3			7.9			0
	5800-090-451000	2679	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332235	Light Assy, #35 Cabin		HRS		597.1			5584.1			0
	5800-285-451000	5648	AFL		124			1444			0
			MOS	TSN:3	32			30 Apr 2021			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332236	Light Assy, #36 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5699	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332237	Light Assy, #37 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5707	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332238	Light Assy, #38 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5694	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332239	Light Assy, #39 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5691	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AV OX INC
	Airframe		MSC					O/C			
332240	Light Assy, #40 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5706	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332241	Light Assy, #41 Cabin		HRS		665.8			5515.4			0
	5800-285-451000	9444	AFL		150			1418			0
			MOS		43.4			18 May 2020			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332242	Light Assy, #42 Cabin		HRS		6173.3			7.9			0
	5800-120-451000	2629	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332243	Light Assy, #43 Cabin		HRS		6173.3			7.9			0
	5800-120-451000	2631	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332244	Light Assy, #44 Cabin		HRS		6173.3			7.9			0
	5800-120-451000	2630	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AV OX INC
	Airframe		MSC					O/C			
332245	Light Assy, #45 Cabin		HRS		6173.3			7.9			0
	5800-120-451000	2633	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332246	Light Assy, #46 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5698	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332247	Light Assy, #47 Cabin		HRS		6173.3			7.9			0
	5800-285-451000	5705	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332248	Light Assy, #48 Cabin		HRS		6173.3			7.9			0
	5800-105-451000		AFL		1562			6			0
	1837		MOS		203.7			08 Jan 2007			GULFSTREAM
	Airframe		MSC					O/C			SAV COMPLETION IPTS
332249	Light Assy, #49 Cabin		HRS		6173.3			7.9			0
	5800-105-451000		AFL		1562			6			0
	1780		MOS		203.7			08 Jan 2007			AV OX INC
	Airframe		MSC					O/C			
332250	Light Assy, #50 Cabin		HRS		6173.3			7.9			0
	5800-105-451000		AFL		1562			6			0
	1836		MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332263	Light Kit (No. 1)		HRS		6173.3			7.9			0
	5620-10		AFL		1562			6			0
	403		MOS		203.7			08 Jan 2007			BE Aerospace
	Airframe		MSC					O/C			
332264	Light Kit (No. 2)		HRS		6173.3			7.9			0
	5620-10		AFL		1562			6			0
	408		MOS		203.7			08 Jan 2007			BE Aerospace
	Airframe		MSC					O/C			
332307	Light Assy, #1 Cabin Spot		HRS		6173.3			7.9			0
	5500-06		AFL		1562			6			0
	2594		MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332310	Light Assy, #2 Cabin Spot		HRS		6173.3			7.9			0
	5500-06		AFL		1562			6			0
	2595		MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332313	Light Assy, #3 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2596	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332316	Light Assy, #4 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2597	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332319	Light Assy, #5 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2598	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332322	Light Assy, #6 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2599	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332325	Light Assy, #7 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2600	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332328	Light Assy, #8 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2601	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332331	Light Assy, #9 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2602	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332334	Light Assy, #10 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2603	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332337	Light Assy, #11 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2604	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332340	Light Assy, #12 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2605	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332343	Light Assy, #13 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2606	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332346	Light Assy, #14 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2607	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332349	Light Assy, #15 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2608	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332352	Light Assy, #16 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2609	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332355	Light Assy, #17 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2610	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332358	Light Assy, #18 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2611	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332361	Light Assy, #19 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2612	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332364	Light Assy, #20 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2613	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332367	Light Assy, #21 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2614	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332370	Light Assy, #22 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2615	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332373	Light Assy, #23 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2616	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332376	Light Assy, #24 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2617	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332379	Light Assy, #25 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2618	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			B/E AEROSPACE
	Airframe		MSC					O/C			LIGHTING CORPORATION
332400	Light Assy		HRS		6173.3			7.9			0
	5800-120-451000	2632	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332401	Light Assy		HRS		6173.3			7.9			0
	5800-120-451000	2255	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332402	Light Assy		HRS		6173.3			7.9			0
	5800-105-451000	1780	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332403	Light Assy		HRS		6173.3			7.9			0
	5800-105-451000	1836	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332404	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5692	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332405	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5693	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332406	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5701	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332407	Light Assy		HRS		665.8			5515.4			0
	5800-285-451000	9449	AFL		150			1418			0
			MOS		43.4			18 May 2020			N/A
	Airframe		MSC					O/C			
332408	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5697	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332409	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5704	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332410	Light Assy		HRS		665.8			5515.4			0
	5800-285-451000	9443	AFL		150			1418			0
			MOS		43.4			18 May 2020			N/A
	Airframe		MSC					O/C			
332411	Light Assy		HRS		6173.3			7.9			0
	5800-285-451000	5700	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332412	Light Assy, #26 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2619	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
332413	Light Assy, #27 Cabin Spot		HRS		6173.3			7.9			0
	5500-06	2621	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
333027	R/H #1 Psu Lower Effect Light #1 - Removal / Installation (Elite)		HRS		130.8			6050.4			0
	7801-300-500420	7370	AFL		29			1539			0
			MOS	TSN:9	6.8			03 Jun 2023			
	Airframe		MSC					O/C			
334001	Landing Light Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
	50-0137-9	1789	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
334002	Landing Light Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
	50-0137-10	1780	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			HONEYWELL GRIMES AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334007	Nose Wheel Taxi Lights Lamp (Left) - Replacement		HRS		2724.3			3456.9			0
	GE4587	NSN	AFL		676			892			0
			MOS		121			28 Nov 2013			HONEYWELL
	Airframe		MSC								GRIMES AEROSPACE
334008	Nose Wheel Taxi Lights Lamp (Center) - Replacement		HRS		2519.1			3662.1			0
	GE4587	NSN	AFL		636			932			0
			MOS		116.7			08 Apr 2014			HONEYWELL
	Airframe		MSC								GRIMES AEROSPACE
334009	Nose Wheel Taxi Lights Lamp (Right) - Replacement		HRS		1389.8			4791.4			0
	GE4587	-	AFL		330			1238			0
			MOS	TSN:21	73.4			16 Nov 2017			HONEYWELL
	Airframe		MSC								GRIMES AEROSPACE
334010	Exterior Lights - Operational Test		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC								
334025	Anticollision Strobe Light Power Supply Unit (Left) - Removal / Installation		HRS		6181.2			0			0
	60-4943-1	1183	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TRANSTAR
	Airframe		MSC								METALS
334026	Anticollision Strobe Light Power Supply Unit (Right) - Removal / Installation		HRS		6181.2			0			0
	60-4943-1	1184	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TRANSTAR
	Airframe		MSC								METALS
334027	Anticollision Strobe Light Power Supply Unit (Tail) - Removal / Installation		HRS		6181.2			0			0
	60-4943-1	1219	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TRANSTAR
	Airframe		MSC								METALS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334039	Navigation Light Lens (Left) - Removal / Installation		HRS		1910.5			4270.7			0
	1159WP56414-1	SN-UNKNOWN	AFL		473			1095			0
			MOS		94.9			02 Feb 2016			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC								
334040	Navigation Light Lens (Right) - Removal / Installation		HRS		665.8			5515.4			0
	1159WP56414-22	0003141039	AFL		150			1418			0
			MOS	TSN:10	44.7			06 Apr 2020			
	Airframe		MSC								
334050	Navigation (Position) Light Lens - Detailed Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.3		24	19 Mar 2023	31 Mar 2025	30 Apr 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
334061	Navigation Position Lights (Left Wing Outboard) - Led Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
	30-2900-1	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL GRIMES AEROSPACE
	Airframe		MSC								
334062	Navigation Position Lights (Right Wing Outboard) - Led Replacement		HRS		4830.6			1350.6			0
			AFL		1172			396			0
	30-2900-2	3626	MOS		167.5			15 Jan 2010			HONEYWELL GRIMES AEROSPACE
	Airframe		MSC								
334063	Navigation Position Lights (Left Wing Inboard) - Led Replacement		HRS		1571.1			4610.1			0
			AFL		368			1200			0
	30-2900-1	9301	MOS	TSN:9	79.3			20 May 2017			HONEYWELL GRIMES AEROSPACE
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334064	Navigation Position Lights (Right Wing Inboard) - Led Replacement		HRS		4830.6			1350.6			0
			AFL		1172			396			0
	30-2900-2	3608	MOS		167.5			15 Jan 2010			HONEYWELL
			MSC								GRIMES AEROSPACE
Airframe											
334065	Navigation Position Lights (Tail Upper) - Led Replacement		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	30-3041-9	SN-UNKNOWN	MOS		156.2			22 Dec 2010			HONEYWELL
			MSC								GRIMES AEROSPACE
Airframe											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
334066	Navigation Position Lights (Tail Lower) - Led Replacement		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	30-3041-9	SN-UNKNOWN	MOS		156.2			22 Dec 2010			HONEYWELL
			MSC								GRIMES AEROSPACE
Airframe											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
334095	Wing-Tip Anticollision Strobe Light Assembly (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	30-2446-3	1070	MOS		208.3			21 Aug 2006			VOUGHT
			MSC								AIRCRAFT INDUSTRIES INC.
Airframe											
334096	Wing-Tip Anticollision Strobe Light Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	30-2446-3	1255	MOS		208.3			21 Aug 2006			VOUGHT
			MSC								AIRCRAFT INDUSTRIES INC.
Airframe											
334097	Tail Cone Anticollision Strobe Light Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	30-2446-3	SN-UNKNOWN	MOS		208.3			21 Aug 2006			VOUGHT
			MSC								AIRCRAFT INDUSTRIES INC.
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334098	Beacon Anticollision Light Assembly - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	30-2140-9	1455	MOS		208.3			21 Aug 2006			AVIATION AVIONICS & INSTRUMENTS CORP
			MSC					O/C			
Airframe											
334099	Anticollision Strobe Lights - Operational Test		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					O/C			
Airframe											
334100	Remote Control Antenna		HRS		6181.2			0			0
	1033-28-8	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
334205	Tail Navigation Position Lights (Upper) - Led Discard		HRS		4281.8		8000	1899.4	9899.4		0
	30-3041-9	SN-UNKNOWN	AFL		1032			536			0
			MOS		156.2			22 Dec 2010			
Airframe											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
334206	Tail Navigation Position Lights (Lower) - Led Discard		HRS		4281.8		8000	1899.4	9899.4		0
	30-3041-9	SN-UNKNOWN	AFL		1032			536			0
			MOS		156.2			22 Dec 2010			
Airframe											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
334213	Wing Navigation Position Lights (Left Outboard) - Led Discard		HRS		6181.2		7000	0	7000		0
			AFL		1568			0			0
	30-2900	NSN	MOS		208.3			21 Aug 2006			
Airframe											
334214	Wing Navigation Position Lights (Right Outboard) - Led Discard		HRS		4830.6		7000	1350.6	8350.6		0
			AFL		1172			396			0
	30-2900-2	3626	MOS		167.5			15 Jan 2010			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334215	Wing Navigation Position Lights (Left Inboard) - Led		HRS		1571.1		7000	4610.1	11610.1		0
	Discard		AFL		368			1200			0
	30-2900-1	9301	MOS	TSN:9	79.3			20 May 2017			
Airframe											
334216	Wing Navigation Position Lights (Right Inboard) - Led		HRS		4830.6		7000	1350.6	8350.6		0
	Discard		AFL		1172			396			0
	30-2900-2	3608	MOS		167.5			15 Jan 2010			
Airframe											
334401	Logo Light Assembly (Left) - Removal / Installation		HRS		3727.5			2453.7			0
	30-2445-1	1984	AFL		916			652			0
			MOS		146			28 Oct 2011			ELECTRO ENTERPRISES INC
			MSC				O/C				
Airframe											
334402	Logo Light Assembly (Right) - Removal / Installation		HRS		1966.2			4215			0
	1987	SN-UNKNOWN	AFL		490			1078			0
			MOS		102.8			04 Jun 2015			ELECTRO ENTERPRISES INC
			MSC				O/C				
Airframe											
334403	Logo Lights - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
335001	Battery Power Supply, Emergency Floorpath Lighting (No. 1)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	100865	C06935	MOS	TSN:3	65.8			03 Jul 2018			
			MSC				O/C				
Airframe											
335002	Battery Power Supply, Emergency Floorpath Lighting (No. 2)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	100865	C06937	MOS	TSN:3	65.8			03 Jul 2018			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
335003	Battery Power Supply, Emergency Floorpath Lighting (No. 3)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	100865	C06893	MOS	TSN:3	65.8			03 Jul 2018			
			MSC							O/C	
Airframe											
335006	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 1) - Restore		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.7	-67	18	08 Mar 2023	31 Jul 2024*	31 Aug 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
335007	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 2) - Restore		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.7	-67	18	08 Mar 2023	31 Jul 2024*	31 Aug 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
335008	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 3) - Restore		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.7	-67	18	08 Mar 2023	31 Jul 2024*	31 Aug 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
335016	Emergency Floorpath Lighting Battery Pack No. 1 - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	2013-BR	B12596	MOS		9.7			08 Mar 2023			N/A
			MSC							O/C	
Airframe											
335017	Emergency Floorpath Lighting Battery Pack No. 2 - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	2013-BR	B12598	MOS		9.7			08 Mar 2023			N/A
			MSC							O/C	
Airframe											
335018	Emergency Floorpath Lighting Battery Pack No. 3 - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	2013-BR	B12584	MOS		9.7			08 Mar 2023			N/A
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
335020	Cabin Emergency Lighting - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-76	12	02 Jun 2023	31 Mar 2024*	30 Apr 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
34 - Navigation											
34008	RVSM Hmu Monitoring (European)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe			O/C								
341001	Radio Altimeter Antenna (No. 1 - Transmit) - Removal / Installation		HRS	TSN:4153.7	1245.7			4935.5			0
			AFL	TSN:1071	296			1272			0
	DMPN19-2-1	3448	MOS	TSN:143	65.8			04 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe			O/C								
341002	Radio Altimeter Antenna (No. 1 - Receive) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	DMPN19-2-1	8234	MOS	TSN:51	65.8			04 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe			O/C								
341003	Radio Altimeter Antenna (No. 2 - Transmit) - Removal / Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
	DM-PN19-2-1	3447	MOS		65.8			04 Jul 2018			
Airframe			O/C								
341004	Radio Altimeter Antenna (No. 2 - Receive) - Removal / Installation		HRS	TSN:4153.7	1245.7			4935.5			0
			AFL	TSN:1071	296			1272			0
	DMPN19-2-1	3413	MOS	TSN:143	65.8			04 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
Airframe			O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)							Manufacturer
											Date Type
	341005	Radio Altimeter System - Operational Check									
Airframe					29			1539			0
					9.4	-7		18 Mar 2023			
										O/C	
										[End Of Month Item]	
341006	Radio Altimeter System - Zero Altitude Adjustment				392.4			5788.8			0
Airframe					88			1480			0
					21.6	4		11 Mar 2022			
										O/C	
										[End Of Month Item]	
341010	Radio Altimeter R/T No. 1 - Removal / Installation				6181.2			0			0
Airframe	7001840-932	0607C813			1568			0			0
					208.3			21 Aug 2006			HONEYWELL
										O/C	
341011	Radio Altimeter R/T No. 2 - Removal / Installation				2860.1			3321.1			0
Airframe	7001840-932	01029015		TSN:3321.1	711			857			0
				TSN:84	124.5			15 Aug 2013			HONEYWELL
										O/C	
341020	AIR Data Module No. 1 - Removal / Installation				6181.2			0			0
Airframe	HG1153CA02	06071630			1568			0			0
					208.3			21 Aug 2006			HONEYWELL INTERNATIONAL
										O/C	
341021	AIR Data Module No. 2 - Removal / Installation				6181.2			0			0
Airframe	HG1153CA02	05010893			1568			0			0
					208.3			21 Aug 2006			HONEYWELL INTERNATIONAL
										O/C	
341022	AIR Data Module No. 3 - Removal / Installation				6181.2			0			0
Airframe	HG1153CA02	06041541			1568			0			0
					208.3			21 Aug 2006			
										O/C	
341023	AIR Data Module No. 1 - Certification				130.8			6050.4			0
Airframe					29			1539			0
					8.6		24	10 Apr 2023	31 Mar 2025		
										[End Of Month Item]	CALIBRATION

Notes: PN: HG1153CA02 SN: <NONE>.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341024	AIR Data Module No. 2 - Certification		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	31 Mar 2025		
Airframe			[End Of Month Item]								CALIBRATION
Notes: PN: HG1153CA02 SN: <NONE>.											
341025	AIR Data Module No. 3 - Certification		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	31 Mar 2025		
Airframe			[End Of Month Item]								CALIBRATION
Notes: PN: HG1153CA02 SN: <NONE>.											
341029	Digital AIR Data Computing System - Functional Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe			MSC				O/C			
341030	Pitot / Static System - Reconnect Check		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.4			18 Mar 2021			
	Airframe			MSC				O/C			
341095	Total AIR Temperature Probe - Operational Check		HRS		858.68			5322.52			0
			AFL		202			1366			0
			MOS		51.4			17 Sep 2019			
	Airframe			MSC				O/C			
341098	Total AIR Temperature Probe No. 1 - Removal / Installation		HRS		858.68			5322.52			0
			AFL		202			1366			0
	102LK2AG	B625	MOS		51.4			17 Sep 2019			
	Airframe			MSC				O/C			
341099	Total AIR Temperature Probe No. 2 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	102LK2AG	A66128	MOS		208.3			21 Aug 2006			GOODRICH SENSOR SYSTEMS
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341100	Pitot / Static Probe (Left Lower) - Removal / Installation		HRS		6181.2			0			0
	0856TK1	238503	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH
	Airframe		MSC					O/C			SENSOR SYSTEMS
341101	Pitot / Static Probe (Right Lower) - Removal / Installation		HRS		6181.2			0			0
	0856TK2	239056	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH
	Airframe		MSC					O/C			SENSOR SYSTEMS
341102	Pitot / Static Probe (Left Upper) - Removal / Installation		HRS		609.87			5571.33			0
	0856TK3	318314	AFL		126			1442			0
			MOS	TSN:6	33.4			18 Mar 2021			
	Airframe		MSC					O/C			
341103	Pitot / Static Probe (Right Upper) - Removal / Installation		HRS		6181.2			0			0
	0856TK4	238889	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH
	Airframe		MSC					O/C			SENSOR SYSTEMS
341300	Pitot / Static System Probes / Lines - Contamination Check		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.4			18 Mar 2021			
	Airframe		MSC					O/C			
341303	Indicator, Stby Alt/Airspeed		HRS	TSN:2860.8	3320.4			2860.8			0
	WL102AMS6	0900	AFL	TSN:747	821			747			0
			MOS	TSN:72	136.4			16 Aug 2012			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
341304	AIR Data System No. 1 - Functional / Leak Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	30 Apr 2025		
	Airframe			[End Of Month Item]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341305	AIR Data System No. 2 - Functional / Leak Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	30 Apr 2025		
	Airframe			[End Of Month Item]							
341306	AIR Data System No. 3 - Functional / Leak Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	30 Apr 2025		
	Airframe			[End Of Month Item]							
341307	Standby Pitot / Static System - Functional / Leak Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	30 Apr 2025		
	Airframe			[End Of Month Item]							
342001	Standby Ebdi - Removal / Installation		HRS		3320.4			2860.8			0
	501-1871-0101	1590	AFL		821			747			0
		1.0	MOS		136.4			16 Aug 2012			HUGHES INDUSTRIAL
	Airframe			MSC			O/C				
342005	Integrated Standby Flight Display - Removal / Installation		HRS		6181.2			0			0
	501-1860-0102	0900	AFL		1568			0			0
		2.1	MOS		208.3			21 Aug 2006			L-3 COMMUNICATIO NS AVIONICS SYSTEMS INC.
	Airframe			MSC			O/C				
342015	Detachable Configuration Module		HRS		6181.2			0			0
	501-1870-16	1020	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe			MSC			O/C				
342602	Display Drive Unit - Removal / Installation		HRS		6181.2			0			0
	7023173-902	06060336	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe			MSC			O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342603	Ohu - Removal / Installation		HRS		1245.7			4935.5			0
	7023171-901	05080280	AFL		296			1272			0
			MOS		66.2			23 Jun 2018			HONEYWELL
	Airframe		MSC					O/C			
342604	Combiner Assembly - Removal / Installation		HRS		6181.2			0			0
	7023172-907	06050709	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
342608	Visual Guidance System - Operational Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC					O/C			
342621	Forward Looking Infrared Camera Assembly (Evs) - Preventative Maintenance		HRS		6162.8			18.4			0
	48534-101	501	AFL		1564			4			0
			MOS		202.9			31 Jan 2007			KOLLSMAN, INC.
	Airframe		MSC					O/C			OVERHAUL
Notes: DECLARED ON-CONDITION											
342623	Enhanced Vision System Processor - Removal / Installation		HRS	TSN:27.1	6154.1			27.1			0
	48535-101	426	AFL	TSN:11	1557			11			0
			MOS	TSN:6	202.7			06 Feb 2007			4 FLIGHT
	Airframe		MSC					O/C			
342624	Enhanced Vision System Sapphire Window Assembly - Functional Test		HRS		2357.4		10000	3823.8	13823.8	13873.8	0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			KOLLSMAN, INC.
	Airframe			[HRS: +50/-50]							
Notes: PN: 48856-101 SN: 479.											
342625	Evs Window Heat Controller - Removal / Installation		HRS		6181.2			0			0
	49322-101	418	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TAPIS CORP
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342633	Enhanced Vision System - Functional Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			20 May 2020			
	Airframe		MSC					O/C			
342650	Forward Looking Infrared Window Assembly - Removal / Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
	48856-101	483	MOS		43.3			20 May 2020			N/A
	Airframe		MSC					O/C			
342701	Integrated Standby Flight Display / Magnetometer - Compensation Adjustment		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
342702	Magnetometer - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	501-1826-01	1608	MOS		208.3			21 Aug 2006			L-3
	Airframe		MSC					O/C			COMMUNICATIO NS AVIONICS SYSTEMS INC.
342710	Integrated Standby Instrument System - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
342715	Integrated Standby Flight Display / Magnetometer - Calibration Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
342801	Standby Electronic Bearing Distance Indicator - Operational Check		HRS		5725.4			455.8			0
			AFL		1438			130			0
			MOS		191.5			12 Jan 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342802	Standby Compass-Function Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
342900	Enhanced Vision System Manual Window Heat - Operational Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			20 May 2020			
	Airframe		MSC					O/C			
343001	Marker Beacon Antenna - Removal / Installation S35-2000-10		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			04 Jul 2018			
	Airframe		MSC					O/C			
343101	Glide Slope Antenna - Removal / Installation S41422-2		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			CASTLE METALS/A.M. CASTLE & CO
344001	Inertial Reference Unit No. 1 - Removal / Installation HG2100AB07		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.5			12 Aug 2015			
	Airframe		MSC					O/C			AEROCONTROLE X GROUP
344002	Inertial Reference Unit No. 2 - Removal / Installation HG2100AB07		HRS		985.9			5195.3			0
			AFL		234			1334			0
			MOS		55.6			10 May 2019			
	Airframe		MSC					O/C			AEROCONTROLE X GROUP
344003	Inertial Reference Unit No. 3 - Removal / Installation HG2100AB07		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.6			11 Jul 2021			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344004	Inertial Reference Sys-Func Ck		HRS		1913.2			4268			0
			AFL		474			1094			0
			MOS		100			29 Aug 2015			
	Airframe		MSC					O/C			
344015	Lasertrak Nav Display-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
344025	Irs MODE Select Panel - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
344101	Weather Radar Receiver / Transmitter - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7021450-801	06076475	MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
344105	Weather Radar Controller No. 1 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7006921-825	06063309	MOS		208.3			21 Aug 2006			REBLING PLASTICS
	Airframe		MSC					O/C			
344106	Weather Radar Controller No. 2 - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	7006921-825	06063310	MOS		208.3			21 Aug 2006			REBLING PLASTICS
	Airframe		MSC					O/C			
344111	Weather Radar System - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC					O/C			
344151	Lightning Sensor Processor Unit - Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	7011822-904	05101459	MOS		203.7			08 Jan 2007			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344152	Lightning Sensor Antenna - Removal / Installation		HRS		6173.3			7.9			0
	7014062-901	04090682	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			HONEYWELL
	Airframe		MSC					O/C			
344153	Lightning Sensor Controller - Removal / Installation		HRS		6173.3			7.9			0
	7012738-905	05090582	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			HONEYWELL
	Airframe		MSC					O/C			
344201	Egpws Module No. 1 - Removal / Installation		HRS		69.6			6111.6			0
	7028419-1902	06061190	AFL		14			1554			0
			MOS		3.8			04 Sep 2023			
	Airframe		MSC					O/C			
344202	Egpws Module No. 2 - Removal / Installation		HRS		44.7			6136.5			0
	7028419-1902	05090881	AFL		7			1561			0
			MOS		2.6			09 Oct 2023			N/A
	Airframe		MSC					O/C			
344204	Egpws - Database Update		HRS		69.6			6111.6			0
			AFL		14			1554			0
			MOS		3.8			04 Sep 2023			
	Airframe		MSC					O/C			
344206	Inertial Reference System No. 1 - Operational Check		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.5			12 Aug 2015			
	Airframe		MSC					O/C			
344207	Enhanced Ground Proximity Windshear Warning System - Return to Service Test		HRS		69.6			6111.6			0
			AFL		14			1554			0
			MOS		3.8			04 Sep 2023			
	Airframe		MSC					O/C			
344208	Inertial Reference System No. 2 - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344209	Inertial Reference System No. 3 - Operational Check		HRS		597.1			5584.1			0
	Airframe		AFL		124			1444			0
			MOS			29.6			11 Jul 2021		
			MSC						O/C		
344301	TCAS Computer - Removal / Installation		HRS	TSN:2860.8	3320.4			2860.8			0
	Airframe	7517900-55020	20008330	AFL	TSN:747	821		747			0
		A-F	A	MOS	TSN:72	136.4			16 Aug 2012		AVGROUP
				MSC					O/C		ATLANTA
344302	TCAS - Operational Check		HRS		2860.1			3321.1			0
	Airframe		AFL		711			857			0
			MOS			124.5			15 Aug 2013		
			MSC						O/C		
344303	TCAS Antenna No. 1 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	Airframe	7514060-902	ANE24042	AFL	TSN:1272	296		1272			0
				MOS	TSN:143	65.8			04 Jul 2018		AVGROUP
				MSC					O/C		ATLANTA
344304	TCAS Antenna No. 2 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	Airframe	DM NI50-9-2	7917	AFL	TSN:1272	296		1272			0
				MOS	TSN:143	65.8			04 Jul 2018		AVGROUP
				MSC					O/C		ATLANTA
344306	Module, TCAS Configuration		HRS		6181.2			0			0
	Airframe	071-00097-1000	SN-UNKNOWN	AFL		1568		0			0
				MOS		208.3			21 Aug 2006		GULFSTREAM
				MSC					O/C		DALLAS
345001	VOR / Localizer Antenna (Left) - Removal / Installation		HRS		6181.2			0			0
	Airframe	DMN4-17-1/P	22881	AFL		1568		0			0
				MOS		208.3			21 Aug 2006		AIL SYSTEMS
				MSC					O/C		INC.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345002	VOR / Localizer Antenna (Right) - Removal / Installation		HRS		6181.2			0			0
	DMN4-17-1/P	22883	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AIL SYSTEMS INC.
	Airframe		MSC					O/C			
345004	VOR - IFR Check		HRS		10.1			6171.1			0
			AFL		1			1567			0
			DATE		21 d			08 Dec 2023	07 Jan 2024		
	Airframe										
345005	Very High Frequency Omnidirectional Range / Instrument Landing System / Data Link Module No. 1 - Removal / Installation		HRS		793.5			5387.7			0
			AFL		186			1382			0
	7026202-801	06061877	MOS		49.5			13 Nov 2019			
	Airframe		MSC					O/C			
345006	Very High Frequency Omnidirectional Range / Instrument Landing System / Data Link Module No. 2 - Removal / Installation		HRS		721.58			5459.62			0
			AFL		160			1408			0
	7026202-801	11086503	MOS		46.8			03 Feb 2020			
	Airframe		MSC					O/C			
345011	Very High Frequency Omnidirectional Range / Instrument Landing System / Data Link - Functional Check		HRS		793.5			5387.7			0
			AFL		186			1382			0
			MOS		49.5			13 Nov 2019			
	Airframe		MSC					O/C			
345020	Navigation / Communication System - Functional Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
345060	McdU Software Load (Warranty Managed Program)		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345101	DME Module No. 1 - Removal / Installation		HRS		6181.2			0			0
	7510184-855	0605A946	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
345102	DME Module No. 2 - Removal / Installation		HRS		6181.2			0			0
	7510184-855	0603A582	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
345105	DME Antenna No. 1 - Removal / Installation		HRS		1245.7			4935.5			0
	DM N150-9-2	13722	AFL		296			1272			0
			MOS		65.8			04 Jul 2018			
	Airframe		MSC					O/C			
345106	DME Antenna No. 2 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	DM N150-9-2	7826	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.8			04 Jul 2018			
	Airframe		MSC					O/C			
345109	DME #1 - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
345110	DME #2 - Functional Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
345115	DME - Functional Check		HRS		1244.1			4937.1			0
			AFL		295			1273			0
			MOS		65.4			18 Jul 2018			
	Airframe		MSC					O/C			
345201	ADF Receiver No. 1 - Removal / Installation		HRS		6181.2			0			0
	7510114-855	0603A500	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345202	ADF Receiver No. 2 - Removal / Installation		HRS		6181.2			0			0
	7510114-855	0604A686	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			
345203	ADF System No. 1 - Operational Check		HRS		1244.1			4937.1			0
			AFL		295			1273			0
			MOS		65.4			18 Jul 2018			
	Airframe		MSC					O/C			
345204	ADF System No. 2 - Operational Check		HRS		2860.1			3321.1			0
			AFL		711			857			0
			MOS		124.5			15 Aug 2013			
	Airframe		MSC					O/C			
345205	ADF Antenna No. 1 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	7510300-901	0605A450	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.8			04 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			
345206	ADF Antenna No. 2 - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	7510300-901	0605A451	AFL	TSN:1272	296			1272			0
			MOS	TSN:143	65.8			04 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			
345301	ATC MODE S Diversity Transponder Module No. 1 - Removal / Installation		HRS		2860.1			3321.1			0
	7517402-970	0701C200	AFL		711			857			0
			MOS		124.5			15 Aug 2013			
	Airframe		MSC					O/C			
345302	ATC MODE S Diversity Transponder Module No. 2 - Removal / Installation		HRS	TSN:3321.1	2860.1			3321.1			0
	7517402-970	0604B013	AFL	TSN:857	711			857			0
			MOS	TSN:84	124.5			15 Aug 2013			
	Airframe		MSC					O/C			
345305	ATC (No. 1) - Functional Test / Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	31 Mar 2025		
	Airframe		[End Of Month Item]								CALIBRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345306	ATC (No. 2) - Functional Test / Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6		24	10 Apr 2023	31 Mar 2025		
Airframe			[End Of Month Item]								CALIBRATION
345315	ATC MODE S Antenna No. 1 (Upper) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
			AFL	TSN:1272	296			1272			0
	DM N150-9-2	7931	MOS	TSN:143	65.8			04 Jul 2018			
			MSC					O/C			
Airframe											
345316	ATC MODE S Antenna No. 2 (Upper) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
			AFL	TSN:1272	296			1272			0
	DM N150-9-2	7934	MOS	TSN:143	65.8			04 Jul 2018			
			MSC					O/C			
Airframe											
345317	ATC MODE S Antenna No. 1 (Lower) - Removal / Installation		HRS	TSN:3321.1	2860.1			3321.1			0
			AFL	TSN:857	711			857			0
	DM N150-9-2	7932	MOS	TSN:84	124.5			15 Aug 2013			
			MSC					O/C			
Airframe											
345318	ATC MODE S Antenna No. 2 (Lower) - Removal / Installation		HRS	TSN:3321.1	2860.1			3321.1			0
			AFL	TSN:857	711			857			0
	DM N150-9-2	7933	MOS	TSN:84	124.5			15 Aug 2013			
			MSC					O/C			
Airframe											
345801	GPS Antenna No. 1 - Removal / Installation		HRS	TSN:3036.4	1245.7			4935.5			0
	S67-1575-237	825-0496	AFL	TSN:736	296			1272			0
			MOS	TSN:91	65.8			04 Jul 2018			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
345802	GPS Antenna No. 2 - Removal / Installation		HRS	TSN:3036.4	1245.7			4935.5			0
	S67-1575-237	825-0497	AFL	TSN:736	296			1272			0
			MOS	TSN:91	65.8			04 Jul 2018			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345810	GPS - Operational Check		HRS		2860.1			3321.1			0
			AFL		711			857			0
			MOS		124.5			15 Aug 2013			
	Airframe		MSC					O/C			
345813	Global Positioning System Module No. 1 - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	245-604067-100	07092471	MOS		156.5			14 Dec 2010			
	Airframe		MSC					O/C			
345814	Global Positioning System Module No. 2 - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	245-604067-100	08073377	MOS		156.5			14 Dec 2010			
	Airframe		MSC					O/C			
346000	Multifunction Control Display Unit - Operational Test		HRS		467.9			5713.3			0
			AFL		100			1468			0
			MOS		25.6			10 Nov 2021			
	Airframe		MSC					O/C			
346001	Multifunction Control Display Unit No. 1 - Removal / Installation		HRS		818.7			5362.5			0
			AFL		188			1380			0
	7033700-951	11114081	MOS		50.3			21 Oct 2019			
	Airframe		MSC					O/C			
346002	Multifunction Control Display Unit No. 2 - Removal / Installation		HRS		792.2			5389			0
			AFL		184			1384			0
	7033700-951	11043623	MOS		49.2			23 Nov 2019			
	Airframe		MSC					O/C			
346003	Multifunction Control Display Unit No. 3 - Removal / Installation		HRS		467.9			5713.3			0
			AFL		100			1468			0
	A50A000-00-450	A4504996	MOS	TSN:1	25.6			10 Nov 2021			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
346005	FMS - Software Verification		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe			MSC				O/C			
346040	Data Management Unit - Removal / Installation		HRS		2358.2			3823			0
	7031051-901	05050564	AFL		600			968			0
			MOS		112.2			22 Aug 2014			HONEYWELL
	Airframe			MSC				O/C			
35 - Oxygen											
350001	Oxygen System - Operational Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.5			15 Apr 2020			
	Airframe			MSC				O/C			
350002	Crew / Passenger Oxygen System Check Valves - Operational Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		44.9		72	01 Apr 2020	30 Apr 2026	31 May 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
351001	Oxygen Mask / Regulator (Pilot) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7	-52	36	28 May 2023	06 Apr 2026*	06 May 2026	
	Airframe							[MOS: +1m/-1m]			
351002	Oxygen Mask / Regulator (Copilot) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7	-52	36	28 May 2023	06 Apr 2026*	06 May 2026	
	Airframe							[MOS: +1m/-1m]			
351003	Oxygen Mask / Regulator (Observer) - Functional Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7	-52	36	28 May 2023	06 Apr 2026*	06 May 2026	
	Airframe							[MOS: +1m/-1m]			
351011	Oxygen Mask / Regulator (Pilot) - Restore		HRS		665.8			5515.4			0
	MC10-15-158	SE23974	AFL		150			1418			0
			MOS		45		72	30 Mar 2020	31 Mar 2026		N/A
	Airframe							[End Of Month Item]			EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351012	Oxygen Mask / Regulator (Copilot) - Restore		HRS		665.8			5515.4			0
	MC10-15-158	SE20839	AFL		150			1418			0
			MOS		45		72	30 Mar 2020	31 Mar 2026		N/A
	Airframe										EXPIRATION
351013	Oxygen Mask / Regulator (Observer) - Restore		HRS		665.8			5515.4			0
	MC10-15-158	61279	AFL		150			1418			0
			MOS		45		72	30 Mar 2020	31 Mar 2026		N/A
	Airframe										EXPIRATION
351021	Oxygen Mask and Regulator Stowage Box (Pilot) - Removal / Installation		HRS		665.8			5515.4			0
	MC10-15-158	SE23974	AFL		150			1418			0
			MOS		45			30 Mar 2020			N/A
	Airframe		MSC				O/C				
351022	Oxygen Mask and Regulator Stowage Box (Copilot) - Removal / Installation		HRS		665.8			5515.4			0
	MC10-15-158	SE20839	AFL		150			1418			0
			MOS		45			30 Mar 2020			N/A
	Airframe		MSC				O/C				
351023	Observer Oxygen Mask and Regulator Stowage Box - Removal / Installation		HRS		665.8			5515.4			0
	MC10-15-158	61279	AFL		150			1418			0
			MOS		45			30 Mar 2020			N/A
	Airframe		MSC				O/C				
351101	Crew Oxygen Quantity Gage - Removal / Installation		HRS		6181.2			0			0
	163LCP81	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				GULFSTREAM BRN SPARES IPT
351102	Crew Oxygen Servicing Pressure Gage - Removal / Installation		HRS		4830.6			1350.6			0
	P24094-1	0975	AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
	Airframe		MSC				O/C				HORIZON AEROSPACE LLC

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351110	Crew Oxygen Mask / Regulator / Box Assembly (Pilot) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7		36	28 May 2023	31 May 2026	30 Jun 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351111	Crew Oxygen Mask / Regulator / Box Assembly (Copilot) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7		36	28 May 2023	31 May 2026	30 Jun 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351112	Crew Oxygen Mask / Regulator / Box Assembly (Observer) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7		36	28 May 2023	31 May 2026	30 Jun 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351201	Crew Oxygen Cylinder (No. 1) - Discard		HRS		665.8			5515.4			0
	805983-15	C19110728	AFL		150			1418			0
			MOS		44.7		180	06 Apr 2020	30 Nov 2034		N/A
	Airframe		[End Of Month Item] MANUFACTURE								
351202	Passenger Oxygen Cylinder (No. 2) - Discard		HRS		665.8			5515.4			0
	805983-15	C20020809	AFL		150			1418			0
			MOS		44.7		180	06 Apr 2020	28 Feb 2035		N/A
	Airframe		[End Of Month Item] MANUFACTURE								
351206	Crew Oxygen Low-Pressure Switch - Operational Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		72	06 Apr 2020	30 Apr 2026	31 May 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351207	Passenger Oxygen Low Pressure Switch - Operational Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		72	06 Apr 2020	30 Apr 2026	31 May 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351211	Crew Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test		HRS								0
			AFL								0
			MOS		44.9		60	31 Mar 2020	30 Nov 2024		
	Airframe				[End Of Month Item]						HYDRO CHECK
Notes: PN: 805983-15 SN: C19110728											
351212	Passenger Oxygen Bottle (No. 2) - (Hydrostatic) Functional Test		HRS								0
			AFL								0
			MOS		44.9		60	31 Mar 2020	30 Nov 2024		
	Airframe				[End Of Month Item]						HYDRO CHECK
Notes: PN: 805983-15 SN: C20020809											
351216	Reg/Sov, Oxy Cylinder #1		HRS		6181.2			0			0
	803213-06	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
351217	Reg/Sov, Oxy Cylinder #2		HRS		6181.2			0			0
	803213-06	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
351221	Crew Oxygen Cylinder and Regulator Assembly - Removal / Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
	805983-15	C19110728	MOS	TSN:5	44.9			01 Apr 2020			N/A
	Airframe		MSC				O/C				
351222	Passenger Oxygen Cylinder (No. 2) - Removal / Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
	805983-15	C20020809	MOS	TSN:2	44.9			01 Apr 2020			N/A
	Airframe		MSC				O/C				
351230	Crew Oxygen Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	CZ92A5-9	SN-UNKNOWN	MOS		208.3			21 Aug 2006			CYTEC ENGINEERED MATERIALS
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351301	Valve, Crew Oxygen Shutoff		HRS		6181.2			0			0
	02C74T01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			NEWARK ELECTRONICS
	Airframe		MSC					O/C			
351302	Valve, Copilot Oxygen Shutoff		HRS		6181.2			0			0
	02C74T01	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			NEWARK ELECTRONICS
	Airframe		MSC					O/C			
352003	Passenger Oxygen System (Auto / Manual MODE) - Operational Test		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			21 May 2020			
	Airframe		MSC					O/C			
352004	Passenger Oxygen Drop-Down Mask Assemblies - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.8	-11	36	03 Jul 2021	30 Jun 2024*	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
352006	Passenger Oxygen System - Flight Check		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.2			22 Jun 2018			
	Airframe		MSC					O/C			
352009	Passenger Oxygen System (Auto / Manual MODE) - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.8		36	03 Jul 2021	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
352013	Crew Oxygen Low-Pressure Switch (No. 1) - Removal / Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
	P24029	2130	MOS		203.7			08 Jan 2007			PACIFIC PRECISION PRODUCTS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352014	Passenger Oxygen Control Panel - Removal / Installation		HRS		1912.4			4268.8			0
	412040-11	0921	AFL		474			1094			0
			MOS		100.5			13 Aug 2015			ADAMS RITE
	Airframe		MSC					O/C			AEROSPACE
352015	Indicator , Pax Oxygen(Cockpit		HRS		6181.2			0			0
	163LCP75	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HORIZON
	Airframe		MSC					O/C			AEROSPACE LLC
352016	Passenger Oxygen Pressure Transducer - Removal / Installation		HRS		6181.2			0			0
	CZ92A5-9	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CYTEC
	Airframe		MSC					O/C			ENGINEERED MATERIALS
352017	Passenger Oxygen Low-Pressure Switch (No. 2) - Removal / Installation		HRS		6181.2			0			0
	P24029	2154	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PACIFIC
	Airframe		MSC					O/C			PRECISION PRODUCTS
352101	Presentation Unit #1 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1671	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM,
	Airframe		MSC					O/C			INC.
352102	Presentation Unit #2 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1672	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM,
	Airframe		MSC					O/C			INC.
352103	Presentation Unit #3 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1673	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM,
	Airframe		MSC					O/C			INC.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352104	Presentation Unit #4 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1674	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352105	Presentation Unit #5 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1675	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352106	Presentation Unit #6 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1676	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352107	Presentation Unit #7 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1677	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352108	Presentation Unit #8 Oxygen		HRS		6173.3			7.9			0
	833-610-12	0951	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352109	Presentation Unit #9 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1666	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352110	Presentation Unit #10 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1667	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352111	Presentation Unit #11 Oxygen		HRS		6173.3			7.9			0
	833-610-12	0952	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352112	Presentation Unit #12 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1668	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352113	Presentation Unit #13 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1669	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352114	Presentation Unit #14 Oxygen		HRS		6173.3			7.9			0
	833-610-12	0956	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352115	Presentation Unit #15 Oxygen		HRS		6173.3			7.9			0
	833-610-13	1678	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352120	Presentation Unit, Jumpseat		HRS		6173.3			7.9			0
	833-801-03	0182	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
352121	Presentation Unit Galley		HRS		6173.3			7.9			0
	833-610-13	1665	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352122	Presentation Unit Aft Lav		HRS		6173.3			7.9			0
	833-610-13	1670	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352123	Presentation Unit Fwd Lav		HRS		6173.3			7.9			0
	833-610-13	1664	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			
352501	Outlet, #1 Therapeutic Oxygen		HRS		6173.3			7.9			0
	02C40T01-2C	NSN	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GULFSTREAM - LONG BEACH
	Airframe		MSC					O/C			
352506	Therapeutic Oxygen System (Outlet No. 1) - Functional Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.8	-11	36	03 Jul 2021	30 Jun 2024*	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
352516	Therapeutic Oxygen Mask (No. 1) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.8	-8	36	03 Jul 2021	30 Jun 2024*	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
352521	Valve, Therapeutic O2 Solenoid		HRS		6173.3			7.9			0
	P21046	0883	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			PACIFIC PRECISION PRODUCTS
	Airframe		MSC					O/C			
353001	Portable Oxygen Bottle (No. 1) - Removal / Installation		HRS		130.8			6050.4			0
	5600-9M6A-F30AN	P10070010	AFL		29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
353002	Portable Oxygen Bottle and Mask Assembly (No. 1) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3		12	19 Mar 2023	31 Mar 2024	30 Apr 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
Notes: PN: 5600-9M6A-F30AN SN: <NONE>. 353004											
353003	Portable Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.7		60	06 Jul 2022	31 Jul 2027		
	[End Of Month Item]										HYDRO CHECK
Airframe											
Notes: PN: 5600-9M6A-F30AN SN: P10070010.											
353004	Portable Oxygen System (No. 1 Bottle) - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	-7	36	02 Jul 2021	30 Jun 2024*	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
353016	Portable Oxygen Mask (No. 1) - Restore		HRS		6181.2			0			0
	10800A2F	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
											AVOX SYSTEM, INC. OVERHAUL
Airframe											
353020	Mask, Portable Oxygen (No. 1)		HRS		3320.4			2860.8			0
	10800A2F	NSN	AFL		821			747			0
			MOS		136.4			16 Aug 2012			
			MSC								
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
36 - Pneumatic											
360001	Pneumatic Distribution-Func Ck		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
											O/C
Airframe											
360002	L Servo Press Reg/Motor-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
											O/C
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
360003	R Servo Press Reg/Motor-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
360011	Total Temperature Probe Valve - Removal / Installation		HRS		6181.2			0			0
	320154-4-1	1674	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
361001	Bleed AIR Controller (Left) - Removal / Installation		HRS		1245.7			4935.5			0
	1151582-6	151582-01777	AFL		296			1272			0
			MOS		65.5			12 Jul 2018			HONEYWELL
	Airframe		MSC					O/C			
361002	Bleed AIR Controller (Right) - Removal / Installation		HRS		4692.4			1488.8			0
	1151582-6	018C-0469	AFL		1142			426			0
			MOS		165.2			22 Mar 2010			HONEYWELL
	Airframe		MSC					O/C			
361091	8TH Stage Valve Servo Regulator and Torque Motor Filter		HRS		6181.2			0			0
	(Left) - Removal / Installation		AFL		1568			0			0
	4000091-600-BT	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
361092	8TH Stage Valve Servo Regulator and Torque Motor Filter		HRS		876.9			5304.3			0
	(Right) - Removal / Installation		AFL		210			1358			0
	4000091-600-BT	NSN	MOS		52.8			05 Aug 2019			
	Airframe		MSC					O/C			
361101	High-Pressure Shut-Off Valve (Left) - Removal /		HRS		876.9			5304.3			0
	Installation		AFL		210			1358			0
	3291298-2	782	MOS		52.8			05 Aug 2019			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361102	High-Pressure Shut-Off Valve (Right) - Removal / Installation		HRS		876.9			5304.3			0
			AFL		210			1358			0
	3291298-2	773	MOS		52.8			05 Aug 2019			
			MSC							O/C	
Airframe											
361103	High-Pressure Stage 5 AIR Nonreturn Valve (Left) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
			AFL	TSN:1272	296			1272			0
	3202752-1	877	MOS	TSN:143	65.8			04 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC							O/C	
Airframe											
361104	High-Pressure Stage 5 AIR Nonreturn Valve (Right) - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
			AFL	TSN:1272	296			1272			0
	3202752-1	876	MOS	TSN:143	65.8			04 Jul 2018			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC							O/C	
Airframe											
361105	Bleed AIR Pressure Regulating and Shut-Off Valve (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3215662-2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC							O/C	
Airframe											
361106	Bleed AIR Pressure Regulating and Shut-Off Valve (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3215662-2	SN-UNKNOWN	MOS		208.3			21 Aug 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC							O/C	
Airframe											
361107	Valve, Airstart Assist		HRS		6173.3			7.9			0
			AFL		1562			6			0
	PYLB52589	335	MOS		203.4			16 Jan 2007			SCHEIDL MANUFACTURING COMPANY INC
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361201	APU Check Valve - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	3202754-1	855	AFL	TSN:1272	296			1272			0
			MOS	TSN:142	66.3			20 Jun 2018			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
361202	APU Check Valve - Detailed Inspection		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
			AFL		296			1272			0
			MOS		66.3			20 Jun 2018			
	Airframe		[HRS: +50/-50]								
361203	Bleed AIR Isolation Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
	3291826-1	146	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL- ENGINEERING SYSTEMS & SERV.
	Airframe		MSC					O/C			
361204	8TH Stage Valve Servo Regulator and Torque Motor (Left) - Removal / Installation		HRS		6181.2			0			0
	3215636-2	837	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
361205	8TH Stage Valve Servo Regulator and Torque Motor (Right) - Removal / Installation		HRS		6181.2			0			0
	3215636-2	814	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
361207	Valve, External AIR Check		HRS		6181.2			0			0
	3202754-1	856	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361215	Bleed AIR Flow Control and Pressure Regulation -		HRS		1245.7			4935.5			0
	Operational Test		AFL		296			1272			0
			MOS		65.5			13 Jul 2018			
			MSC							O/C	
Airframe											
361401	Bleed AIR Precooler (Left) - Removal / Installation		HRS		6181.2			0			0
	2341172-1	433	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe											
361402	Bleed AIR Precooler (Right) - Removal / Installation		HRS		6181.2			0			0
	2341172-2	427	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	HONEYWELL
Airframe											
361403	Precooler Inlet Temperature Sensor (Left) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1150124-2	1150124-06407	MOS		208.3			21 Aug 2006			
			MSC							O/C	HONEYWELL ASCA INC.
Airframe											
361404	Precooler Inlet Temperature Sensor (Right) - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	1150124-2	1150124-06406	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
361407	Fan AIR Valve (Left) - Removal / Installation		HRS		6167			14.2			0
	3291252-1	810	AFL		1560			8			0
			MOS		203.3			20 Jan 2007			
			MSC							O/C	HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361408	Fan AIR Valve (Right) - Removal / Installation		HRS		6181.2			0			0
	3291252-1	760	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ENGINES SYSTEMS & SERVICE
362101	Manifold Pressure Sensor (Left) - Removal / Installation		HRS		6181.2			0			0
	1151584-1	115184-05295	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ASCA INC.
362102	Manifold Pressure Sensor (Right) - Removal / Installation		HRS		6181.2			0			0
	1151584-1	1151584-05294	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			HONEYWELL
	Airframe		MSC					O/C			ASCA INC.
38 - Water/Waste											
380001	Vacuum Toilet (Aft) - Removal / Installation		HRS		6181.2			0			0
	7900268	63-880	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ENVIROVAC, INC.
	Airframe		MSC					O/C			
380002	Toilet, Fwd Lav		HRS		6173.3			7.9			0
	7900268	63-1050	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			MONOGRAM
	Airframe		MSC					O/C			SYSTEMS
380003	Vacuum Blower - Removal / Installation		HRS		6181.2			0			0
	7900138-004	0484	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ENVIROVAC, INC.
	Airframe		MSC					O/C			
380004	Logic Control Module - Removal / Installation		HRS		5000.2			1181			0
	7700201-002	1056	AFL		1213			355			0
			MOS		172.3			20 Aug 2009			ENVIROVAC, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
380005	Status Panel - Removal / Installation		HRS		1604.9			4576.3			0
	7700202-004	591	AFL		414			1154			0
			MOS		80.2			22 Apr 2017			ENVIROVAC, INC.
	Airframe		MSC					O/C			
380008	Valve, Vacuum Toilet Dump		HRS		6181.2			0			0
	2651-375-1	0198	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			SCALAMANDRE
	Airframe		MSC					O/C			
380015	Waste Tank Ultrasonic Level Sensor (Left) - Removal / Installation		HRS		10.1			6171.1			0
	7700953	3809	AFL		1			1567			0
			MOS		.5			12 Dec 2023			
	Airframe		MSC					O/C			
Notes: CAMP CODE 380010											
380031	Waste Tank Ultrasonic Level Sensor (Left) - Cleaning		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
380032	Waste Tank Ultrasonic Level Sensor (Right) - Cleaning		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
380050	Water System Heater (Water Tank) - Operational Test		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			04 Jul 2018			
	Airframe		MSC					O/C			
380100	Ice Maker, Backflow Valve #1		HRS		6181.2			0			0
	PN	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			4E4350-1
	Airframe		MSC					O/C			
380101	Ice Maker, Backflow Valve #2		HRS		6181.2			0			0
	4E4350-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381001	Conformal Water Tank - Removal / Installation		HRS		4831.2			1350			0
	4E2493-3	NO632401	AFL		1172			396			0
			MOS		167.5			15 Jan 2010			GOODRICH
	Airframe		MSC					O/C			
381009	Sensor Assembly, Water Level		HRS		1383			4798.2			0
	4E4185-2	N0729903	AFL		326			1242			0
			MOS		73			29 Nov 2017			
	Airframe		MSC					O/C			
381011	Heater, Galley Water		HRS		5255.6			925.6			0
	MRX2000-102	2002-382	AFL		1288			280			0
			MOS		179.1			26 Jan 2009			TIA, A DIVISION OF THE RICHARDS CO.
	Airframe		MSC					O/C			
381012	Heater, Fwd Lav Water		HRS		597.1			5584.1			0
	MRX-1000-102A	1002-1214A	AFL		124			1444			0
			MOS	TSN:10	32			29 Apr 2021			N/A
	Airframe		MSC					O/C			
381013	Heater, Aft Lav Water		HRS		5255.6			925.6			0
	MRX1000-102	1002-371	AFL		1288			280			0
			MOS		179.1			26 Jan 2009			GULFSTREAM - LGB
	Airframe		MSC					O/C			
381015	Tank Heater - Removal / Installation		HRS		6173.3			7.9			0
	MRX1000-102	SN-UNKNOWN	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			TIA, A DIVISION OF THE RICHARDS CO.
	Airframe		MSC					O/C			
381023	Water Level Controller - Removal / Installation		HRS		6173.3			7.9			0
	4E186-1	U0256	AFL		1562			6			0
			MOS		203.4			16 Jan 2007			GOODRICH
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381027	Water Sterilizer Quartz Glass Sheath - Restore		HRS		665.8		3000	5515.4	8515.4		0
	09-130021-102	1-0872 MOD 3,4	AFL		150			1418			0
			MOS		44.7			06 Apr 2020			
Airframe											
381028	Germicidal Lamp - Discard		HRS		665.8		3000	5515.4	8515.4		0
	02-160202-004	NSN	AFL		150			1418			0
			MOS		44.7			06 Apr 2020			
Airframe											
381029	Water System - Operational Test		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
			MSC				O/C				
Airframe											
381031	Valve, Fwd Lav Water		HRS		6173.3			7.9			0
	4E4484-1	NO617902	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			FLORIDA PIPE & SUPPLY
			MSC				O/C				
Airframe											
381034	Water Filter Cartridge / Element (No. 2) - Discard		HRS		6181.2			0			0
	AC-2	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				-				
Airframe											
381035	Potable Water System - Cleaning / Sanitizing		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC				O/C				
Airframe											
381037	Water Filter Cartridge / Element (No. 1) - Removal / Installation		HRS		3521.5			2659.7			0
			AFL		865			703			0
	770102	SN-UNKNOWN	MOS		141.5			14 Mar 2012			PEERLESS ELECTRONICS INC
			MSC				O/C				
Airframe											
381039	Water Sterilizer - Removal / Installation		HRS		130.8			6050.4			0
	09-130021-102	1-0872 MOD 3,4	AFL		29			1539			0
			MOS		7.1			26 May 2023			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381052	Supply Line Motor Drain Valve - Removal / Installation		HRS		392.4			5788.8			0
	4E499-1-1	N0723402	AFL		88			1480			0
			MOS		21.4			17 Mar 2022			
	Airframe		MSC							O/C	
381055	Power Switching Controller - Removal / Installation		HRS		6181.2			0			0
	4E4265-1	U207	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GOODRICH
	Airframe		MSC							O/C	
381060	Switch, Aft H2O Heater Blanket		HRS		6181.2			0			0
	2457-1-2	206080191	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TAPIS CORP
	Airframe		MSC							O/C	
381065	Contactor, Aft Baggage		HRS		6181.2			0			0
	SA106E	CP-38694	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC							O/C	
381300	Supply Line Motor Drain Valve - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.4	3	24	17 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
381301	Drain Line Motor Drain Valve - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.4	3	24	17 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
381501	Water Supply Line Linnerline Heater Controller (Left) - Removal / Installation		HRS		6181.2			0			0
	3434-01	731	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			COX & COMPANY INC
	Airframe		MSC							O/C	
381502	Water Supply Line Linnerline Heater Controller (Right) - Removal / Installation		HRS		6181.2			0			0
	3435-01	734	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			TAPIS CORP
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381503	Water Supply / Drain Line Innerline Heater Controller - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3514-01	736	MOS		208.3			21 Aug 2006			COX & COMPANY INC
			MSC					O/C			
Airframe											
381510	Cont, Aft Eer Interline		HRS		6181.2			0			0
			AFL		1568			0			0
	3434-01	284	MOS		208.3			21 Aug 2006			COX & COMPANY INC
			MSC					O/C			
Airframe											
382002	Water Sterilizer Filter - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	06-133802-001	NSN	MOS	TSN:6	7.1			26 May 2023			
			MSC					O/C			
Airframe											
382003	Water Sterilizer Filter - Discard		HRS		130.8			6050.4			0
			AFL		29			1539			0
	06-133802-001	NSN	MOS		7.1			26 May 2023	31 May 2024	30 Jun 2024	
			[End Of Month Item] [MOS: +1m]								
Airframe											
382011	Water System Heater (Water Supply Innerline) - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
382012	Water System Heater (Water Drain Innerline) - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
382013	Water System Heater (Supply / Fill / Purge Valve) - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
382015	Water System Servicing Cable - Rigging		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
Notes: PN: 4E4181-7 SN: <NONE>.											
382104	Valve, Aft Lav H2O Shutoff		HRS		6173.3			7.9			0
	4E4483-1	NO617903	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
382105	Valve, Aft Galley H2O Shutoff		HRS		6173.3			7.9			0
	4E4474-1	NO612622	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			GOODRICH
	Airframe		MSC					O/C			
382106	Vacuum Toilet Rinse Valve (Aft) - Removal / Installation		HRS		6173.3			7.9			0
	4E4474-1	NO626307	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
382107	Vacuum Toilet Rinse Valve (Forward) - Removal / Installation		HRS		6173.3			7.9			0
	4E4485-1	N6010104	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
382108	Valve, Fwd Galley H2O Shutoff		HRS		6173.3			7.9			0
	4E4474-1	NO608820	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
383000	Water System Heater (Aft Drain Mast) - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
383001	Aft Drain Mast - Removal / Installation		HRS		1245.7			4935.5			0
	70WS001-216	HF0485	AFL		296			1272			0
			MOS	TSN:1	65.8			04 Jul 2018			GOODRICH
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
383010	Valve, Aft Lav Vanity Drain		HRS		6173.3			7.9			0
	4E4474-1	NO626308	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
383024	Waste Tank Ultrasonic Level Sensor (Right) - Removal /		HRS		3521.5			2659.7			0
	Installation		AFL		865			703			0
	7700395-001	0733	MOS		141.5			14 Mar 2012			ENVIROVAC, INC.
	Airframe		MSC					O/C			
383027	Valve, Galley H2O Drain #1		HRS		6173.3			7.9			0
	4E4350-4	613120	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					O/C			
383028	Valve, Galley H2O Drain #2		HRS		6181.2			0			0
	4E4273-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
383501	Waste Drain Valve Cable Assembly - Removal /		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
	570-713-251	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
49 - Airborne Auxiliary Power											
490001	APU - Auxiliary Power Unit - Functional Test		HRS		385			3805.5			0
			APUS		0			0			0
			MOS		31.4			17 May 2021			
	APU		MSC					O/C			
490003	APU - APU Performance Run - Functional Test		HRS		3751.5			439			0
			APUS		-200			200			0
			MOS		193.6			09 Nov 2007			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491005	APU Enclosure FS 767 - FS 797 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6	-11	24	10 Apr 2023	31 Mar 2025*	30 Apr 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
491007	APU Enclosure Thermal Blanket / Coating - General		HRS		1245.7			4935.5			0
	Visual Inspection		AFL		296			1272			0
			MOS		66.1			25 Jun 2018			
	Airframe		MSC					O/C			
491101	APU - APU - Removal / Installation		HRS	TSN:1473	2717.5			1473			0
	WE3800700-1	P-447	APUS	TSN:583	-583			583			0
			MOS		146.2			24 Oct 2011			HONEYWELL AVIATION AFTERMARKET SERVICES
	APU		MSC					O/C			
491104	APU - APU Mount Bracket - General Visual Inspection		HRS		2717.5			1473			0
			APUS		-583			583			0
			MOS		146.2			24 Oct 2011			
	APU		MSC					O/C			
491105	APU - APU Isolator Mounts - General Visual Inspection		HRS		2717.5			1473			0
			APUS		-583			583			0
			MOS		146.2			24 Oct 2011			
	APU		MSC					O/C			
491201	APU - AIR Inlet Door - Removal / Installation		HRS		4190.5			0			0
	1159P50703-3	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
491206	APU - Auxiliary Power Unit Inlet Door Actuator - Removal /		HRS		1380.5			2810			0
	Installation		APUS		0			0			0
	SYLC52630-2	300	MOS		112.2			22 Aug 2014			SMITHS AEROSPACE, INC.
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491207	APU Inlet Door and Actuator - Detailed Inspection		HRS		2382.12			3799.08			0
			AFL		1568			0			0
			MOS		33.5		48	12 Mar 2021	31 Mar 2025	30 Apr 2025	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
491208	APU - Inlet Door Actuator - Adjustment Test		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU			MSC				O/C			
491216	APU - AIR Intake Duct Removal / Installation		HRS		4190.5			0			0
	1159SCP107-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU			MSC				O/C			
491300	APU Compartment Drain Collectors - General Visual Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
491301	APU - Auxiliary Power Unit Turbine Plenum Drains - Operational Test		HRS		235.5			3955			0
			APUS		0			0			0
			MOS		21.6		24	11 Mar 2022	31 Mar 2024	30 Apr 2024	
	APU			[End Of Month Item] [MOS: +1m/-1m]							
491302	APU - APU Turbine Plenum Drain - Operational Test		HRS		2991.5			1199			0
			APUS		-240			240			0
			MOS		157.8			03 Nov 2010			
	APU			MSC				O/C			
491303	APU Compartment Drains - (Ezip) - Operational Check		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		94.9			02 Feb 2016			
	Airframe			MSC				O/C			
491304	APU Compartment Drains - Operational Check		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							

Notes: ACCOMPLISH AT NEXT AUXILIARY POWER UNIT TURBINE PLENUM DRAINS - OPERATIONAL TEST, 49-13-00, CODE 491301 AND EVERY 2C THEREAFTER

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491306	Interior and Exterior Surfaces of APU Compartment (APU Box) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
491350	APU - APU Combustor - Wash		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
492001	APU - Impeller - Discard		HRS		4190.5		10000	0	10000		0
	WB3822573-1	050350109169	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU										
492002	APU - APU 1ST Stage Turbine Rotor Assembly - Discard		HRS		4190.5		10000	0	10000		0
	WK3840142-1	052241001135	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU										
492003	APU - 2ND Stage Turbine Rotor - Discard		HRS		4190.5		10000	0	10000		0
	WE897994-3	060134504824	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU										
492101	APU - APU Wire Harness - Removal / Installation		HRS		4190.5			0			0
	3888362	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
492102	APU - Branched Wiring Harness (Wiring Harness) -		HRS		387.5			3803			0
	General Visual Inspection		APUS		0			0			0
			MOS		33			30 Mar 2021			
	APU		MSC					O/C			
492301	APU - Compressor and Turbine Section - Rotation Check		HRS		387.5			3803			0
	and / or Borescope Inspection		APUS		0			0			0
			MOS		33			30 Mar 2021			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
492601	APU - Starter Gear / Clutch Module - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WK3860976	SN-UNKNOWN	MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											
493001	APU - APU Engine Fuel and Control System - Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											
493004	APU - APU Fuel Filter Element - Removal / Installation		HRS		3442.5			748			0
	3882496-1	LOT# 579497	APUS		-240			240			0
			MOS	TSN:38	180.5			13 Dec 2008			HONEYWELL
			MSC							O/C	HPG
APU											
493010	APU - Primary Fuel Shut-Off Valve - Removal / Installation		HRS		4190.5			0			0
	66917-30286-1	1246	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											
493011	APU - Fuel Flow Divider Solenoid Valve - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WE3883738-2	00463	MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											
493012	APU - Fuel Flow Divider Valve - Leakage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											
493015	APU - Lube Module, Fuel Pump		HRS		4190.5			0			0
	WE3881600-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC							O/C	
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493101	APU - Fuel Control Unit - Removal / Installation		HRS		4190.5			0			0
	441903-4	CUB10481	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL
	APU		MSC					O/C			AVIATION AFTERMARKET SERVICES
493103	APU - Seal Witness Drain Leakage - Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
493105	APU - APU Fuel Strainer - Removal / Installation		HRS		4190.5			0			0
	3882496-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL
	APU		MSC					O/C			HPG
493106	APU - Fuel Strainer - Contamination Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
493107	APU - Fuel Strainer - Leakage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
493108	APU - Fuel Strainer - Cleaning		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
493111	APU - Fuel Nozzles Assy, APU		HRS		4190.5			0			0
	WE3830464-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493112	APU - Fuel Nozzle Assembly Connections - Leakage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493113	APU - Fuel Nozzle Assemblies - Damage / Contamination Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493301	APU - Flow Divider Supply Tube Assembly - Leakage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493312	APU - Primary and Secondary Fuel Manifolds - Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493321	APU - Orifice Fitting Assembly - Removal / Installation 3616783-1 SN-UNKNOWN		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493322	APU - Orifice Fitting Assembly - Drainage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											
493323	APU - Orifice Fitting Assembly - General Visual / Dimensional Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC					O/C			
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493401	APU - Fuel Filter Bypass Indicator Valve - Removal / Installatio		HRS		4190.5			0			0
			APUS		0			0			0
	3883512-1	SN-UNKNOWN	MOS		209.4			17 Jul 2006			
			MSC								
APU											
493402	APU - Fuel Filter Bypass Indicator - Detailed Inspection (Delta P Indicator)		HRS		391.42		600	3799.08	4399.08	4449.08	0
			APUS		0			0			0
			MOS		33.5			12 Mar 2021			
APU	[HRS: +50/-50]										
493404	APU Fuel System Components, Lines and Connections - General Visual Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
(493404)	[HRS: +50/-50]										
Airframe											
494001	APU - APU Starter Motor - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	2704554-2	1111	MOS		209.4			17 Jul 2006			
			MSC								
APU	O/C										
	HONEYWELL AVIATION AFTERMARKET SERVICES										
494002	APU - Auxiliary Power Unit Starter - Detailed Inspection		HRS		391.42		600	3799.08	4399.08	4449.08	0
			APUS		0			0			0
			MOS		33.5			12 Mar 2021			
APU	[HRS: +50/-50]										
494003	APU - Starter Motor - Brush Wear Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC								
APU	O/C										
494201	APU - APU Ignition Exciter - Removal / Installation		HRS		2991.5			1199			0
			APUS		-240			240			0
	9049820-6 (WE3876295-6)	040218051067	MOS		158.5			12 Oct 2010			
			MSC								
APU	O/C										
	HONEYWELL AVIATION AFTERMARKET SERVICES										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494202	APU - Left Igniter Plug Lead - Removal / Installation		HRS		4190.5			0			0
	WE3888353-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL AVIATION AFTERMARKET SERVICES
	APU		MSC					O/C			
494203	APU - Right Igniter Plug Lead - Removal / Installation		HRS		4190.5			0			0
	WE3888353-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL AVIATION AFTERMARKET SERVICES
	APU		MSC					O/C			
494205	APU - APU Igniter Plug Lead Electrical Properties (Right) - Inspection / Check		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
494206	APU - Igniter Plug (Left) - Removal / Installation		HRS		387.5			3803			0
	WB3888354-1	NSN	APUS		0			0			0
			MOS		33			30 Mar 2021			N/A
	APU		MSC					O/C			
494207	APU - Igniter Plug (Right) - Removal / Installation		HRS		387.5			3803			0
	WB3888401-1	NSN	APUS		0			0			0
			MOS	TSN:1	32.9			01 Apr 2021			
	APU		MSC					O/C			
494208	APU - APU Igniter Plug (Left) - Inspection / Check		HRS		387.5			3803			0
			APUS		0			0			0
			MOS		33			30 Mar 2021			
	APU		MSC					O/C			
494209	APU - APU Igniter Plug (Right) - Inspection / Check		HRS		387.5			3803			0
			APUS		0			0			0
			MOS		33			30 Mar 2021			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494211	APU - No. 1 APU Ignition / Starting System Ignition		HRS		4190.5			0			0
	System Igniter Plug - Cleaning / Painting		APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC						O/C		
APU											
494212	APU - No. 2 APU Ignition / Starting System Ignition		HRS		4190.5			0			0
	System Igniter Plug - Cleaning / Painting		APUS		0			0			0
			MOS		209.4			17 Jul 2006			
			MSC						O/C		
APU											
495001	APU - APU Surge Control Valve - Removal / Installation		HRS		4190.5			0			0
	3291212-4	719	APUS		0			0			0
			MOS		209.4			17 Jul 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC						O/C		
APU											
495002	APU - APU Load Control Valve - Removal / Installation		HRS		3400.5			790			0
	3291210-4	896	APUS		-240			240			0
			MOS		179.1			27 Jan 2009			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC						O/C		
APU											
495005	APU - Duct, APU Surge Valve		HRS		4190.5			0			0
	1159P50731-1	0333	APUS		0			0			0
			MOS		209.4			17 Jul 2006			GULFSTREAM SAV PROD-IPT
			MSC						O/C		
APU											
495010	APU - Inlet Pressure Sensor - Removal / Installation		HRS		4190.5			0			0
	WE3876283-1	051121420268	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL AEROSPACE ACADEMY
			MSC						O/C		
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
495201	APU - APU Bleed Diffuser - Removal / Installation		HRS		4190.5			0			0
	WB3827365-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
496101	APU - Electronic Control Unit - Removal / Installation		HRS		385			3805.5			0
	2118946-10	16-M0011	APUS		0			0			0
			MOS		31.4			16 May 2021			
	APU		MSC					O/C			
496102	APU - Exhaust Gas and Temperature Sensor No. 1 -		HRS		1380.5			2810			0
	Removal / Installation		APUS		0			0			0
	WE3876352-1	5061	MOS		94.8			03 Feb 2016			
	APU		MSC					O/C			
497001	APU - Cockpit Overhead Indicator - Removal / Installation		HRS		4190.5			0			0
	789543-1	0502	APUS		0			0			0
			MOS		209.4			17 Jul 2006			INTERTECHNIQU
	APU		MSC					O/C			E
497005	APU - Thermocouple, APU #1 Egt		HRS		1380.5			2810			0
	WE3876352-1	05061	APUS		0			0			0
			MOS		94.8			03 Feb 2016			HONEYWELL
	APU		MSC					O/C			INTERNATIONAL INC.
497007	APU - Time Totalizing Meter - Read and Record		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		202.6			09 Feb 2007			
	APU		MSC					O/C			
497010	APU - APU Temperature Sensor (Inlet, T2) - Removal /		HRS		3751.5			439			0
	Installation		APUS		-200			200			0
	MS28034-1	NSN	MOS		193.6			09 Nov 2007			GULFSTREAM
	APU		MSC					O/C			DALLAS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
497015	APU - APU Speed Sensor - Removal / Installation		HRS		4190.5			0			0
	WE3876281-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			HONEYWELL INTERNATIONAL INC.
	APU		MSC					O/C			
497020	APU - Inlet Pressure Sensor - Removal / Installation		HRS		3751.5			439			0
	WE3876283-1	061121420491	APUS		-200			200			0
			MOS		193.6			09 Nov 2007			
	APU		MSC					O/C			
498001	APU - APU Exhaust Duct - General Visual Inspection		HRS		385		600	3805.5	4405.5	4455.5	0
			APUS		0			0			0
			MOS		32.6			10 Apr 2021			
	APU		[HRS: +50/-50]								
499001	APU - APU Oil Level / Remote Oil Panel - Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499002	APU - Soap Sample - APU		HRS		1387			2803.5			0
			APUS		0			0			0
			MOS		96.4			18 Dec 2015			
	APU		MSC					O/C			
499003	APU - APU AIR / Oil Cooler - Removal / Installation		HRS		4190.5			0			0
	160534-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			LORI, INC.
	APU		MSC					O/C			
499004	APU - APU Oil Sump Heater - Removal / Installation		HRS		4190.5			0			0
	WE3876292-2	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499005	APU - APU Oil Level Sensor - Removal / Installation		HRS		4190.5			0			0
	WE3876285-1	SN-UNKNOWN	APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499006	APU - APU Low Oil Pressure Switch - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WE3876291-1	VN09227	MOS		209.4			17 Jul 2006			HONEYWELL ENGINES SYSTEMS & SERVICE
APU			MSC				O/C				
499007	APU - Lube Filter Bypass Indicator Valve - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WE3876293-1	VN11426	MOS		209.4			17 Jul 2006			HONEYWELL INTERNATIONAL INC.
APU			MSC				O/C				
499010	APU - Auxiliary Power Unit Oil System - Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
APU			MSC				O/C				
499014	APU - Generator Filter Bypass Indicator Valve - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WE3876294-1	VN11426	MOS		209.4			17 Jul 2006			HONEYWELL INTERNATIONAL INC.
APU			MSC				O/C				
499015	APU - APU Lube / Generator Filter Elements - Removal / Installation		HRS		1387			2803.5			0
			APUS		0			0			0
	WE3881767-1	SN-UNKNOWN	MOS	TSN:4	96.4			18 Dec 2015			HONEYWELL
APU			MSC				O/C				
499019	APU - APU Magnetic Drain Plug - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	572-510-9151	SN-UNKNOWN	MOS		209.4			17 Jul 2006			
APU			MSC				O/C				
499020	APU - Chip Collector - Inspection		HRS		1387			2803.5			0
			APUS		0			0			0
			MOS		97.3			19 Nov 2015			
APU			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499022	APU - Auxiliary Power Unit Oil - Servicing		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499025	APU - APU Oil - Change		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499110	APU - APU Lube Pump Assembly (Pump) Seal Plate - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	715331	SN-UNKNOWN	MOS		209.4			17 Jul 2006			HAMILTON SUNDSTRAND
	APU		MSC					O/C			
499115	APU - Lube Pump Assembly - Removal / Installation		HRS		4190.5			0			0
	WE3881781-1		APUS		0			0			0
		VE2044	MOS		209.4			17 Jul 2006			HONEYWELL AVIATION AFTERMARKET SERVICES
	APU		MSC					O/C			
499116	APU - Lube Pump Assembly - General Visual / Leakage Inspection		HRS		4190.5			0			0
			APUS		0			0			0
			MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499125	APU - Turbine Bearing Supply and Return Tube Assembly - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	WE361681-1	SN-UNKNOWN	MOS		209.4			17 Jul 2006			
	APU		MSC					O/C			
499130	APU - APU Deprime / Deoil Valve - Removal / Installation		HRS		4190.5			0			0
			APUS		0			0			0
	4141028-4	SN-UNKNOWN	MOS		209.4			17 Jul 2006			AEROCONTROLE X GROUP
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49APU1	APU		HRS	TSN:1848.5	3320.4			2860.8			0
	WE3800700-1	P-447	AFL		821			747			0
			MOS		136.4			16 Aug 2012			
	Airframe		MSC					E/C			
51 - STD Practices and Struct-Genrl											
510013	External Metallic Surfaces - Polishing		HRS		347.1			5834.1			0
			AFL		75			1493			0
			MOS		18.9			02 Jun 2022			
	Airframe		MSC					O/C			
[End Of Month Item]											
52 - Doors											
520005	Exterior Cabin Doors and Exits - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1	-88	96	27 May 2023 28 Feb 2031* 31 Mar 2031			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521001	Main Entrance Door - Removal / Installation		HRS	TSN:7.9	6173.3			7.9			0
	1159B57011-800-23	5999	AFL	TSN:6	1562			6			0
			MOS	TSN:5	203.4			16 Jan 2007			
	Airframe		MSC					O/C			
521002	Main Entrance Door Seal - Removal / Installation		HRS		6181.2			0			0
	1159SCB500-11	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
521003	Main Entrance Door Actuator - Removal / Installation		HRS		6181.2			0			0
	159H10030-51	55-5122GT	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
521004	Valve, Main Entrance Door Reducer		HRS		6181.2			0			0
	1159SCH219-25	384	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			PNEUDRAULICS INC

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521005	Valve, Main Entrance Door Selector		HRS		6181.2			0			0
	1159SCH247-3	1523G	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PNEUDRAULICS INC
	Airframe		MSC					O/C			
521007	Main Entrance Door Bayonet Position Indicator DOTS - General Visual Inspection		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.5		60	12 Mar 2021	31 Mar 2026	30 Apr 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521008	Main Entrance Door Hinge Pins - Removal / Installation		HRS		597.1			5584.1			0
	1159BM50108-11	NSN	AFL		124			1444			0
			MOS	TSN:20	29.7			06 Jul 2021			N/A
	Airframe		MSC					O/C			
521009	Main Entrance Door Hinge Pins - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.7	56	36	06 Jul 2021	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521010	Main Entrance Door - Lubrication		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	-74	12	31 May 2023	31 Mar 2024*	30 Apr 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521011	Main Entrance Door - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3	-20	96	20 Mar 2023	28 Feb 2031*	31 Mar 2031	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521012	Main Entrance Door Internal - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.3		72	20 Mar 2023	31 Mar 2029	30 Apr 2029	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521015	Main Entrance Door - Operating Procedures		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			31 May 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521016 (521016) Airframe	Main Entrance Door Cables - Tension Check		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5	50	72	12 Jul 2018	31 Aug 2024*	30 Sep 2024	
					[End Of Month Item] [MOS: +1m/-1m]						
523001 Airframe	Baggage Door - Removal / Installation		HRS	TSN:4935.5	1245.7			4935.5			0
	1159B51046-37	5124	AFL	TSN:1272	296			1272			0
			MOS	TSN:142	66.1			25 Jun 2018			
			MSC								O/C
523002 Airframe	Baggage Compartment Door Inflatable Door Seal - Removal / Installation		HRS		6181.2			0			0
	1159SCB524-1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								O/C
523003 Airframe	Baggage Compartment Door Seal - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	9	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
					[End Of Month Item] [MOS: +1m/-1m]						
523004 Airframe	Baggage Compartment Door Seal AIR Supply Moisture Drain Orifice - Detailed Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	9	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
					[End Of Month Item] [MOS: +1m/-1m]						
523005 Airframe	Baggage Compartment Door - Lubrication		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-33	12	21 Apr 2023	31 Mar 2024*	30 Apr 2024	
					[End Of Month Item] [MOS: +1m/-1m]						
523006 Airframe	Baggage Compartment Door - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
					[End Of Month Item] [MOS: +1m/-1m]						
523008 Airframe	Baggage Compartment Door Seal Check Valve - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	9	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
					[End Of Month Item] [MOS: +1m/-1m]						

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
523009	Baggage Compartment Door Seal Pressure Regulator - Removal / Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	3215634-6	1781	MOS		156.5			15 Dec 2010			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC								
Airframe											
523010	Filter, Baggage Compartment Door Seal		HRS		6181.2			0			0
	1159SCAC001-1	3022	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AIRCRAFT SEAL AND GASKET CORP.
			MSC								
Airframe											
523012	Baggage Compartment Door Inflatable Seal System - Operational Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
523013	Inflatable Door Seal - Purging Procedure		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
523018	Baggage Compartment Door Seal High Flow Pressure Regulator - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	3215634-6	SN-UNKNOWN	MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
523021	Bolts, Baggage Door Stop		HRS		6181.2			0			0
	NAS428K4A12	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STORK FOKKER AESP B.V.
			MSC								
Airframe											
523201	Baggage Compartment Door Internal Structure - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1		96	25 Jun 2018	30 Jun 2026	31 Jul 2026	
Airframe											

[End Of Month Item] [MOS: +1m/-1m]

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
524001	Tail Compartment Door - Zonal Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.3		144	20 Jun 2018	30 Jun 2030	31 Jul 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
524004	Door, Tail Compartment		HRS		6181.2			0			0
	1159B51527-25	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
525001	Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.2	-66	12	24 May 2023	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
525002	Auxiliary Pressure Bulkhead Door - Zonal Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1		144	25 Jun 2018	30 Jun 2030	31 Jul 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
525004	Auxiliary Pressure Bulkhead Door - Removal / Installation		HRS		6181.2			0			0
	1159HS51886-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
527001	Main Entrance Door Secondary Handle Lock Switch and Circuitry - Operational Test		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	13	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
527003	Main Entrance Door Locked Relay Circuit - Functional Test		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			AFL		150			1418			0
			MOS		43.5			15 May 2020			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

527201	Internal Baggage Door - Functional Check		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.9		48	01 Apr 2020	30 Apr 2024	31 May 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									

Notes: ACCOMPLISH INITIAL AT NEXT COMPLIANCE OF AIR DATA SYSTEM - FUNCTIONAL / LEAK TEST, CODE 341304, NOT TO EXCEED 4C FOLLOWING DATE OF REVISION 30, AND EVERY 4C THEREAFTER

528103	Door, Nose Gear Fairing		HRS		6181.2			0			0
	1159B50511-800-9	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			LEONARD'S METAL INC.
Airframe		MSC O/C									

53 - Fuselage

530005	Radome - Removal / Installation		HRS	TSN:5515.9	665.8			5515.4			0
	1159B57290-5	3-148	AFL	TSN:1418	150			1418			0
			MOS	TSN:166	43.3			20 May 2020			N/A
Airframe		MSC O/C									

530006	Forward Section		HRS		6181.2			0			0
	1159B5009-804-1	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									

530007	Cockpit Enclosure		HRS		6181.2			0			0
	1159B30800	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									

530008	Forward Combo Section		HRS		6181.2			0			0
	1159B57004-801-1	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									

530009	Center Mid Section		HRS		6181.2			0			0
	1159B50005-801	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530010	Aft Mid Section		HRS		6181.2			0			0
	1159B50009-801PH1	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
530011	Torque Box		HRS		6181.2			0			0
	1159B51701-45	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
530012	Aft Fuselage Section		HRS		6181.2			0			0
	1159B50006-802-1	5124	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
530013	Tail Cone Section		HRS		130.8			6050.4			0
	1159B52901-35	5124	AFL		29			1539			0
			MOS		7.2			24 May 2023			N/A
	Airframe		MSC					O/C			
530014	Dorsal Fin		HRS		6181.2			0			0
	1159B21506	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
530025	Fuselage Penetrations Production and Outfitting		HRS		1245.7			4935.5			0
	Installations - Detailed Inspection		AFL		296	-1272	8000**	1272	8000*		0
			MOS		65.7			06 Jul 2018			
Airframe											
530027	Floorboard Clip Nut - Check		HRS		129.3			6051.9			0
			AFL		28			1540			0
			MOS		6.8			04 Jun 2023			
	Airframe		MSC					O/C			
530201	Radome to Structure Perimeter Steps - Detailed		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		6.9		24	01 Jun 2023	30 Jun 2025	31 Jul 2025	
Airframe											
											[End Of Month Item] [MOS: +1m/-1m]

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530205	Birdstrike Plate (Left) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159B50207-31	NSN	AFL	TSN:62	29			1539			0
			MOS	TSN:201	7			30 May 2023			N/A
	Airframe		MSC					O/C			
530206	Birdstrike Plate (Right) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	1159B50207-31	NSN	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7			30 May 2023			N/A
	Airframe		MSC					O/C			
531005	External Lower Fuselage FS -4 Thru FS 758 View from Ground - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18		24	28 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
531010	Radome FS -4 Thru FS 63 - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		96	05 Apr 2021	30 Apr 2029	31 May 2029	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
531012	Exterior Radome Fairing Installation - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		8.2			23 Apr 2023			
	Airframe			[HRS: +50/-50]							
531013	Enhanced Vision System Fairing and Rain Diverter Fairing - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-52	96	21 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
531014	Enhanced Vision System Sapphire Window Installation - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			AFL		29			1539			0
			MOS		9.4			18 Mar 2023			
	Airframe			[HRS: +50/-50]							
531015	Nose Gear Wheel Well FS 44 - FS 119 - Zonal Inspection		HRS		130.8			6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	15	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531016	Nose Landing Gear Skin Cutout - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531019	Cockpit Internal Skin and Substructure FS 63 Thru FS 145 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	144	23 Apr 2023	28 Feb 2035*	31 Mar 2035	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531020	Cockpit Below Floor FS 119 - FS 145 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-52	96	21 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531025	Lower Fuselage FS 85 - FS 119 Cheek Panel (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-52	96	21 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531026	Lower Fuselage FS 85 - FS 119 Cheek Panel (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-52	96	21 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531030	Internal Cockpit Below Floor FS 63 - FS 85, WI 81 - WI 71 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	96	08 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531035	Cabin Below Floor FS 229 - FS 426 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-50	96	19 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531036	Cabin Below Floor FS 145 - FS 229 - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.9	61	48	01 Jul 2022	31 Aug 2026*	30 Sep 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531040	Upper Surface of Center Wing FS 426 - FS 576 from Wheel Well - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531041	Upper Surface of Center Wing FS 426 - FS 576 from Cabin - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-52	96	21 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531045	Main Gear Wheel Wells FS 576 - FS 632 (Left) - Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	10	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
531046	Main Gear Wheel Wells FS 576 - FS 632 (Right) - Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.1	10	12	26 Mar 2023	30 Apr 2024*	31 May 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
531047	Main Gear Wheel Wells FS 576 - FS 632 (Cove Panel Drain Holes) - (Enhanced) Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9	6	12	30 Mar 2023	30 Apr 2024*	31 May 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
531048	Main Gear Wheel Wells FS 576 - FS 632 (Wiring Harness) - (Enhanced) Zonal Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9	6	12	30 Mar 2023	30 Apr 2024*	31 May 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531050	Overwing AREA FS 354 - FS 736 Between Drag Beam and Wing to Body Fairing (Left) - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		96	20 Apr 2021	30 Apr 2029	01 May 2029	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531051	Overwing AREA FS 354 - FS 736 Between Drag Beam and Wing to Body Fairing (Right) - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		96	20 Apr 2021	30 Apr 2029	31 May 2029	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531055	Aft Cabin Below Floor FS 632 - FS 684 - Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	19	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531060	Baggage Compartment Below Floor FS 684 - FS 758 - Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	19	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531065	External Upper Fuselage FS 63 - FS 758 View from Ground - Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531066	External Upper Fuselage FS 63 - FS 758 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
531068	External Fuselage - General Visual Inspection		HRS		597.1		2000	5584.1	7584.1		0
			AFL		124		800	1444	2244		0
			MOS		32.6			10 Apr 2021			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531070	Cockpit Above Floor FS 63 - FS 145 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531074	Cabin Above Floor Internal FS 145 - FS 758 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531075	Cabin Above Floor FS 145 - FS 758 - Zonal Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1				26 Feb 2007		
	Airframe		MSC		O/C						
531076	Cabin Above Floor Internal FS 145 - FS 758 - (Enhanced) Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531080	Left Electronic Equipment Rack FS 141 - FS 166 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	22	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531081	Right Electronic Equipment Rack FS 147 - FS 181 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	22	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531082	Electronic Equipment Rack FS 147 - FS 181 - (Enhanced) Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531085	External Aft Fuselage and Empennage FS 758 - FS 1123		HRS		392.4			5788.8			0
	Viewed from Ground - Zonal Inspection		AFL		88			1480			0
			MOS		21.6	8	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531090	External Aft Fuselage and Empennage FS 758 - FS 1123 -		HRS		130.8			6050.4			0
	Zonal Inspection		AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531093	Lavatory Service Panel Pressure Box Structure - Detailed		HRS		6181.2			0			0
	Inspection		AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC							O/C	
Airframe											
531095	Aft Fuselage Above Floor FS 758 - FS 974 - Zonal		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		8.1	-22	24	27 Apr 2023	30 Apr 2025*	31 May 2025	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531100	Aft Fuselage Below Floor FS 758 - FS 797 - Zonal		HRS		321.8			5859.4			0
	Inspection		AFL		68			1500			0
			MOS		18		48	28 Jun 2022	30 Jun 2026	31 Jul 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531105	Aft Fuselage Below Floor FS 797 - FS 974 - Zonal		HRS		130.8			6050.4			0
	Inspection		AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531110	Tail Cone FS 974 - FS 1026 - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531115	Cockpit Window Skins (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531116	Cockpit Window Skins (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531200	Bulkhead Installation FS 44 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-41	144	08 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531205	Bulkhead Installation FS 63 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6	-42	144	09 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531210	Bulkhead Installation FS 85 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-41	144	08 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531215	Bulkhead Installation FS 119 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-41	144	08 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531218	Cabin Window Ring Frame Windows 6 and 7 (No. 6) - Ndt Inspection		HRS		6181.2			0			0
			AFL				4700**		4700		0
			MOS		208.3				21 Aug 2006		
Airframe											
531219	Cabin Window Ring Frame Windows 6 and 7 (No. 7) - Ndt Inspection		HRS		6181.2			0			0
			AFL				4700**		4700		0
			MOS		208.3				21 Aug 2006		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531220	Bulkhead Installation FS 133 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	144	23 Apr 2023	28 Feb 2035*	31 Mar 2035	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531225	FS 145 Frame - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
531300	Longeron Installation L / R BI 12 FS 119 - 145 (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.9		144	01 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531305	Longeron Installation L / R BI 12 FS 119 - 145 (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.9		144	01 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531700	Windshield Rails and Posts (Left) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531701	Windshield Rails and Posts (Right) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531703	Cockpit Window Structure (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
531704	Cockpit Window Structure (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531705	Side Window Rails and Posts (Left) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531706	Side Window Rails and Posts (Right) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531707	Upper Cockpit RAIL (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC		O/C						
531708	Upper Cockpit RAIL (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC		O/C						
531711	Cockpit Lower RAIL BI 0 Splice - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC		O/C						
531715	Side Post Upper Attach (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
531716	Side Post Upper Attach (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
531717	Cockpit Side Post and Lower RAIL Attachment (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				6100**		6100		0
			MOS		208.3			21 Aug 2006			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531718	Cockpit Side Post and Lower RAIL Attachment (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				6100**		6100		0
			MOS		208.3			21 Aug 2006			
Airframe											
531721	Center Post Lower Attachment - Ndt Inspection		HRS		6181.2			0			0
			AFL				6300**		6300		0
			MOS		208.3			21 Aug 2006			
Airframe											
531722	Upper Cockpit Center Post - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
531730	Cockpit Center Post - Discard		HRS		6181.2			0			0
	1159BM50024	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
Airframe											
531733	Cockpit Side Post (Left) - Discard		HRS		6181.2			0			0
	1159BM50025-11	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
Airframe											
531734	Cockpit Side Post (Right) - Discard		HRS		6181.2			0			0
	1159BM50025	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3			21 Aug 2006			
Airframe											
531741	Cockpit Lower RAIL Fastener (Left) - Discard		HRS		6181.2			0			0
	1159BM50033	NSN	AFL		1568		15000	0	15000		0
			MOS		208.3			21 Aug 2006			
Airframe											
531742	Cockpit Lower RAIL Fastener (Right) - Discard		HRS		6181.2			0			0
	1159BM50033	NSN	AFL		1568		15000	0	15000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531747	FS 465 Mainframe Fittings (Left Forward) - Discard		HRS		6181.2			0			0
	1159BM50913-13	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531748	FS 465 Mainframe Fittings (Right Forward) - Discard		HRS		6181.2			0			0
	1159BM50914-13	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531749	FS 465 Mainframe Fittings (Left Aft) - Discard		HRS		6181.2			0			0
	1159BM50913-13	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531750	FS 465 Mainframe Fittings (Right Aft) - Discard		HRS		6181.2			0			0
	1159BM50914-13	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531753	FS 576 Mainframe Fittings (Left Forward) - Discard		HRS		6181.2			0			0
	1159BM50915-17	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531754	FS 576 Mainframe Fittings (Left Aft) - Discard		HRS		6181.2			0			0
	1159BM50915-17	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531757	FS 576 Mainframe Fittings (Right Forward) - Discard		HRS		6181.2			0			0
	1159BM50916-17	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											
531758	FS 576 Mainframe Fittings (Right Aft) - Discard		HRS		6181.2			0			0
	1159BM50916-17	NSN	AFL		1568		16000	0	16000		0
			MOS		208.3				21 Aug 2006		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531900	Nose Wheel Well Trunnion Fitting Assembly - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
532100	Pedestal Assembly		HRS		6181.2			0			0
	1159SCF550-13	G0338	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			MPC PRODUCTS
			MSC					O/C			
Airframe											
532105	Cabin Internal Structure Headliner Removed All Penetrations - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.7		144	06 Jul 2018	31 Jul 2030	31 Aug 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532110	Below Emergency Exits - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5		96	12 Jul 2018	31 Jul 2026	31 Aug 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532115	Baggage Door Surround Structure - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1		96	25 Jun 2018	30 Jun 2026	31 Jul 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532120	Cabin Internal Below Floor and Below Stringer 19 Left / Right - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-50	96	19 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532125	Longitudinal Skin Splices (Left) - Gvi		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC					O/C			
Airframe											
532126	Longitudinal Skin Splices (Right) - Gvi		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532201	FS 169 Frames - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
532205	FS 417 and FS 515 Frame Inner CAP Splice - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
532215	Fuselage Stability Frames - Gvi		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2				22 Aug 2014		
			MSC				O/C				
Airframe											
532300	Longeron 22 Installation Under Galley / Lavatory (Wet Areas) FS 145 - FS 426 - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4		96		16 Apr 2021 30 Apr 2029 31 May 2029		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532305	Longeron 22 Installation Not Under Galleys and Lavatories (Dry Areas), FS 145 - FS 426 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2		-56 192		23 Apr 2023 28 Feb 2039* 31 Mar 2039		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532320	Left Stringer 6 Splice Fitting - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
532500	Floor Structure Under Galleys, Lavatories FS 139 - FS 758 (Wet Areas) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.4		96		16 Apr 2021 30 Apr 2029 31 May 2029		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532505	Floor Structure Not Under Galleys, Lavatories FS 139 - FS 758 (Dry Areas) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	144	23 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532510	Floorboards FS 426 - FS 632 Between Left / Right BI 30 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	144	23 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532515	Floorboards FS 426 - FS 632 Outboard Left / Right BI 30 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	144	23 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532520	Floor Beam and Wing Link FS 465 - FS 576 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-55	96	24 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532525	Floorboards FS 426 - FS 632 Areas Below Galleys, Lavatory (Wet Areas) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8	-104	96	28 Apr 2023	31 Jan 2031*	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532600	Electronic Equipment Rack to Fuselage Upper Attachment Structure (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	144	07 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532601	Electronic Equipment Rack to Fuselage Upper Attachment Structure (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	144	07 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532610	Traffic Alert and Collision Avoidance System Antenna		HRS		1245.7			4935.5			0
	Spacer - Detailed Inspection		AFL		296			1272			0
			MOS		65.8		144	03 Jul 2018	31 Jul 2030	31 Aug 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532901	Main Entrance Door Cutout Surround Structure - Ndt		HRS		6181.2			0			0
	Inspection		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
532905	Main Entrance Door Surround Longeron - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
532920	Main Entrance Door Pin Support - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
533110	FS465 / FS576 Production Splices - General Visual		HRS		2357.7			3823.5			0
	Inspection		AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC				O/C				
Airframe											
533120	Fuselage Skins AT Wing Pressure Box Cutout (Left) - Ndt		HRS		6181.2			0			0
	Inspection		AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533122	Fuselage Skins AT Wing Pressure Box Cutout (Right) -		HRS		6181.2			0			0
	Ndt Inspection		AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533201	FS 632 Bulkhead - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533202	FS 426 Bulkhead - Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
533203	FS 465 Frame Stringer 9 and Above (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533204	FS 465 Frame Stringer 9 and Above (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533205	FS 465 Frame Stringer 9 and Below (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
533206	FS 465 Frame Stringer 9 and Below (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
533207	FS 576 Frame (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533208	FS 576 Frame (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
533211	Window Surround Frame Splice - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3				21 Aug 2006		
Airframe											
533215	Baggage Door Redistribution Frames AT FS 694 and FS 734 - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											
533220	Pressure Bulkhead Installation Below Floor FS 758 - Ndt Inspection		HRS		6181.2			0			0
			AFL				7400**		7400		0
			MOS		208.3				21 Aug 2006		
Airframe											
533300	Longeron 24 Left and Right FS 632 - FS 758 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533305	Dorsal Tee - Ndt Inspection		HRS		6181.2			0			0
			AFL				13000**		13000		0
			MOS		208.3				21 Aug 2006		
Airframe											
533309	Longeron 9 and Longeron 13 (Left No. 9) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533310	Longeron 9 and Longeron 13 (Right No. 9) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
533315	Longeron 7 and Longeron 15 AT FS 576 (Left No. 7) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533316	Longeron 7 and Longeron 15 AT FS 576 (Right No. 7) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533319	Longeron 9 and Longeron 13 (Left No. 13) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
533320	Longeron 9 and Longeron 13 (Right No. 13) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
533321	Longeron 7 and Longeron 15 AT FS 576 (Left No. 15) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533322	Longeron 7 and Longeron 15 AT FS 576 (Right No. 15) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533330	Stringer Splices AT FS 684 and FS 758 - General Visual Inspection		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC					O/C			
Airframe											
533335	Longeron 22 AT FS 417 - FS 426.5 - Detailed Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533400	Bulkhead Installation FS 426 Aft Face - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-41	144	08 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533401	Right Butt Line 6 Floor Beam Support Links (FS 499.00) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
			AFL	TSN:1539	29			1539			0
	1159BM50566-7	NSN	MOS	TSN:199	8.5			13 Apr 2023			N/A
			MSC					O/C			
Airframe											
533402	Right Butt Line 6 Floor Beam Support Links (FS 531.00) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
			AFL	TSN:1539	29			1539			0
	1159BM50535-7	NSN	MOS	TSN:199	8.5			13 Apr 2023			N/A
			MSC					O/C			
Airframe											
533403	Right Butt Line 6 Floor Beam Support Links (FS 569.50) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
			AFL	TSN:1539	29			1539			0
	1159BM50535-7	NSN	MOS	TSN:199	8.5			13 Apr 2023			N/A
			MSC					O/C			
Airframe											
533405	Lower Bulkhead Stiffeners and Angles AT FS 632 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	144	07 Apr 2023	28 Feb 2035*	31 Mar 2035	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533410	Torque Box Installation / Connections - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1		144	25 Jun 2018	30 Jun 2030	31 Jul 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533411	Support, L MLG Door ACT-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
533412	Support, R MLG Door ACT - Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
533415	Drag Beam Overwing Installation - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533416	Overwing Drag Beam - Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533421	Forward Wing to Fuselage Fitting (Left) - Inspection		HRS		6181.2			0			0
			AFL				7500**		7500		0
			MOS		208.3			21 Aug 2006			
Airframe											
533422	Forward Wing to Fuselage Fitting (Right) - Inspection		HRS		6181.2			0			0
			AFL				7500**		7500		0
			MOS		208.3			21 Aug 2006			
Airframe											
533423	Aft Wing to Fuselage Fitting (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533424	Aft Wing to Fuselage Fitting (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533435	BI 6 Forward Wing to Fuselage Attachment Link - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
533501	Pressure Floor Tension Straps - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533510	Frame and Pressure Floor Clips - Detailed Inspection		HRS		6181.2			0			0
			AFL				6800**	0	6800		0
			MOS		208.3			21 Aug 2006			
	Airframe										
533600	Auxiliary Pressure Bulkhead Installation Below Floor FS 684 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-57	96	26 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533605	Auxiliary Pressure Bulkhead Installation Above Floor FS 684 - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	144	07 Apr 2023	28 Feb 2035*	31 Mar 2035	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533610	Forward Engine Mounts Installation FS 758 - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		144	05 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533615	Pressure Bulkhead Installation Below Floor FS 758 -		HRS		130.8			6050.4			0
	Detailed Inspection		AFL		29			1539			0
			MOS		8.1	-57	96	26 Apr 2023	28 Feb 2031*	31 Mar 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
533620	Pressure Bulkhead FS 758 Composite Panels - Detailed		HRS		1245.7			4935.5			0
	Inspection		AFL		296			1272			0
			MOS		66.1		72	25 Jun 2018	30 Jun 2024	31 Jul 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
533701	Cabin Window Ring Frame Windows 1 Thru 5 (Left) - Ndt		HRS		6181.2			0			0
	Inspection		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
533702	Cabin Window Ring Frame Windows 1 Thru 5 (Right) -		HRS		6181.2			0			0
	Ndt Inspection		AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
533705	Window Frame Structure (Left) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
533706	Window Frame Structure (Right) - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				
533801	Baggage Door Cut Out Surround Skin - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533810	Mid Fuselage Cutouts, Exposed to Exterior - Gvi		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
	Airframe		MSC					O/C			
533813	Mid Fuselage Cutouts, Covered By Fairings - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
533817	Wing Link Cutout FS 465 (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
533819	Wing Link Cutout FS 465 (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
534000	Aft Engine Mount Frame Structure - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
534001	Baggage Compartment Electronic Equipment Rack FS 689 - FS 698 - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	7	48	27 Jun 2022	31 Jul 2026*	31 Aug 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
534005	Forward Engine Mount Upper Bulkhead Fitting (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				5000**		5000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534006	Forward Engine Mount Upper Bulkhead Fitting (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				5000**		5000		0
			MOS		208.3			21 Aug 2006			
Airframe											
534011	Aft Engine Mount Upper Bulkhead Fitting (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
534012	Aft Engine Mount Upper Bulkhead Fitting (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
534202	Flat Pressure Bulkhead Forward and Aft Face Above Floor, FS 758 - Special Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.9		72	01 Apr 2020	30 Apr 2026	31 May 2026	
								[End Of Month Item] [MOS: +1m/-1m]			
Airframe											
534203	Primary Pressure Bulkhead Composite Panels / Beams and Metallic Structures Above Floor - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.1			27 Mar 2020			
			MSC				-				
Airframe [End Of Month Item]											
534310	Stringer Splices AT FS 850 - General Visual Inspection		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC				O/C				
Airframe											
534715	FS 820 Bulkhead - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534910	Aft Fuselage Belly Access Cutouts - Gvi		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
	Airframe		MSC					O/C			
534915	Aft Fuselage Exposed Cutouts - Det Insp		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
	Airframe		MSC					O/C			
534920	Aft Fuselage Covered Cutouts (Left) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
534922	Aft Fuselage Covered Cutouts (Right) - Detailed Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
535000	Rudder Actuator Attachment - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568		3600	0	3600		0
			MOS		208.3			21 Aug 2006			
	Airframe										
535020	Cockpit Crossbeam - Ndt Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
535028	Tail Compartment Above Floor Electrical Junction Boxes - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18		48	28 Jun 2022	30 Jun 2026	31 Jul 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
539004	Lower Antenna and Penetration Interface - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		72	04 Jul 2018	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
539005	Upper Antenna and Penetration Interface - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.7		72	06 Jul 2018	31 Jul 2024	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
54 - Nacelles/Pylons											
541005	Pylons External (Left) - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541006	Pylons External (Right) - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541010	Pylons Internal (Left) - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541011	Pylons Internal (Right) - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545003	Pylon Leading Edge (Left) - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	2	6	31 May 2023	31 Dec 2023*	31 Jan 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545004	Pylon Leading Edge (Right) - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	2	6	31 May 2023	31 Dec 2023*	31 Jan 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
55 - Stabilizers											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551001	Horizontal Stabilizer - Removal / Installation		HRS		6181.2			0			0
	1159CS50001-803	GA0818	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STORK FOKKER
	Airframe		MSC					O/C			AESP B.V.
551003	Horizontal Stabilizer - General Visual Inspection		HRS		597.1			5584.1			0
			AFL		124		4000	1444	5444		0
			MOS		32.8			05 Apr 2021			
Airframe											
551005	Horizontal Leading Edge (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-59	192	26 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
551006	Horizontal Leading Edge (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-59	192	26 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
551010	Horizontal Stabilizer Box (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	192	25 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
551011	Horizontal Stabilizer Box (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	192	25 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
551012	Horizontal Stabilizer Assembly (Interior, Left) - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	31 May 2028	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS FROM EIS, ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30 (SEE TABLE 40) AND EVERY 96 MONTHS THEREAFTER AIRCRAFT BEYOND

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
551013	Horizontal Stabilizer Assembly (Interior, Right) - Detailed Inspection		HRS		665.8			5515.4			0	
			AFL		150			1418			0	
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	31 May 2028		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS FROM EIS, ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30 (SEE TABLE 40) AND EVERY 96 MONTHS THEREAFTER AIRCRAFT BEYOND												
551014	Horizontal Stabilizer Hinge and Actuator Fitting - Detailed Inspection		HRS		1245.7			4935.5			0	
			AFL		296			1272			0	
			MOS		65.6		144	09 Jul 2018	31 Jul 2030	31 Aug 2030		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
551015	Horizontal Stabilizer Trailing Edge (Left) - Zonal Inspection		HRS		130.8			6050.4			0	
			AFL		29			1539			0	
			MOS		8.7	-39	96	08 Apr 2023	28 Feb 2031*	31 Mar 2031		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
551016	Horizontal Stabilizer Trailing Edge (Right) - Zonal Inspection		HRS		130.8			6050.4			0	
			AFL		29			1539			0	
			MOS		8.7	-39	96	08 Apr 2023	28 Feb 2031*	31 Mar 2031		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
551018	Horizontal Stabilizer Access Cutouts - Ndt Inspection		HRS		6181.2			0			0	
			AFL				8000**		8000		0	
			MOS		208.3			21 Aug 2006				
Airframe												
551020	Horizontal Stabilizer Pivot Fitting Lugs - Ndt Inspection		HRS		6181.2			0			0	
			AFL		1568			0			0	
			MOS		208.3			21 Aug 2006				
			MSC					O/C				
Airframe												
551022	Horizontal Stabilizer Pivot Fitting Bolts - Detailed Inspection		HRS		6181.2			0			0	
			AFL		1568		4800	0	4800		0	
			MOS		208.3			21 Aug 2006				
(551022)												
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW										Manufacturer
	MM Ref											Date Type
	Ops Number(s)											
551025	Horizontal Stabilizer Leading Edge Upper and Lower Surfaces (Left) - General Visual Inspection		HRS		665.8			5515.4				0
			AFL		150			1418				0
			MOS		45.3		72	19 Mar 2020	31 Mar 2026	30 Apr 2026		
[End Of Month Item] [MOS: +1m/-1m]												
Airframe												
Notes: INITIAL DUE AT 72 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 72 MONTHS THEREAFTER. AIRCRAFT BEYOND 60 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS OF REVISION 30 AND EVERY 72 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT TIME OF HORIZONTAL ST												
551026	Horizontal Stabilizer Leading Edge Upper and Lower Surfaces (Right) - General Visual Inspection		HRS		665.8			5515.4				0
			AFL		150			1418				0
			MOS		45.3		72	19 Mar 2020	31 Mar 2026	30 Apr 2026		
[End Of Month Item] [MOS: +1m/-1m]												
Airframe												
Notes: INITIAL DUE AT 72 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 72 MONTHS THEREAFTER. AIRCRAFT BEYOND 60 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS OF REVISION 30 AND EVERY 72 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT TIME OF HORIZONTAL ST												
551027	Horizontal Stabilizer Trailing Edge AREA (Elevator Curtains Removed, Left) - Detailed Inspection		HRS		665.8			5515.4				0
			AFL		150			1418				0
			MOS		44.7		48	07 Apr 2020	30 Apr 2024	31 May 2024		
[End Of Month Item] [MOS: +1m/-1m]												
Airframe												
Notes: AIRCRAFT SERIAL NUMBER 5001 THROUGH 5158, EXCLUDE 5093,5132,5143&5156, ACCOMPLISH NO LATER THAN DEC 31, 2020 AND EVERY 48 MONTHS THEREAFTER. RECOMMEND INITIAL COMPLIANCE AT TIME OF CB 190 PART I OR PART II. AIRCRAFT SERIAL # 5159 AND SUB, INCLUD												
551028	Horizontal Stabilizer Trailing Edge AREA (Elevator Curtains Removed, Right) - Detailed Inspection		HRS		665.8			5515.4				0
			AFL		150			1418				0
			MOS		44.7		48	07 Apr 2020	30 Apr 2024	31 May 2024		
[End Of Month Item] [MOS: +1m/-1m]												
Airframe												
Notes: AIRCRAFT SERIAL NUMBER 5001 THROUGH 5158, EXCLUDE 5093,5132,5143&5156, ACCOMPLISH NO LATER THAN DEC 31, 2020 AND EVERY 48 MONTHS THEREAFTER. RECOMMEND INITIAL COMPLIANCE AT TIME OF CB 190 PART I OR PART II. AIRCRAFT SERIAL # 5159 AND SUB, INCLUD												
551029	Horizontal Stabilizer Ultrasound / Mobile Automated Scanner (Left) - Ndt Inspection		HRS		665.8			5515.4				0
			AFL		150			1418				0
			MOS		43.3		96	20 May 2020	31 May 2028	30 Jun 2028		
[End Of Month Item] [MOS: +1m/-1m]												
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551030	Horizontal Stabilizer Ultrasound / Mobile Automated Scanner (Right) - Ndt Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3		96	20 May 2020	31 May 2028	30 Jun 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
551031	Horizontal Stabilizer Leading Edge Internal Structure (Leading Edge Removed, Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-59	192	26 Apr 2023	28 Feb 2039*	31 Mar 2039	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 192 MOS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 192 MOS THEREAFTER. AIRCRAFT 5001 THRU 5158, EXCLUDING 5093, 5132, 5143, 5156, WITH MORE THAN 168 MOS SINCE EIS FOLLOWING DATE OF REV 30 ACCOMPLISH NO LATER THAN DEC 31ST, 2020											
551032	Horizontal Stabilizer Leading Edge Internal Structure (Leading Edge Removed, Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-59	192	26 Apr 2023	28 Feb 2039*	31 Mar 2039	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 192 MOS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 192 MOS THEREAFTER. AIRCRAFT 5001 THRU 5158, EXCLUDING 5093, 5132, 5143, 5156, WITH MORE THAN 168 MOS SINCE EIS FOLLOWING DATE OF REV 30 ACCOMPLISH NO LATER THAN DEC 31ST, 2020											
551033	Horizontal Stabilizer Internal Structure (Left) - Special Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	01 May 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30, AND EVERY 96 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT T											
551034	Horizontal Stabilizer Internal Structure (Right) - Special Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	31 May 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30, AND EVERY 96 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT T											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551035	Horizontal Stabilizer Internal Skin / Bond Lines (Left) - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	31 May 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30, AND EVERY 96 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT T											
551036	Horizontal Stabilizer Internal Skin / Bond Lines (Right) - Detailed Inspection		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.7		96	08 Apr 2020	30 Apr 2028	31 May 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
Notes: INITIAL DUE AT 144 MONTHS FOLLOWING ENTRY INTO SERVICE (EIS) AND EVERY 96 MONTHS THEREAFTER. AIRCRAFT BEYOND 132 MONTHS EIS ACCOMPLISH WITHIN 15 MONTHS FOLLOWING DATE OF REVISION 30, AND EVERY 96 MONTHS THEREAFTER. RECOMMEND ACCOMPLISHMENT AT T											
551040	Horizontal Stabilizer Lower Bonded Skin - Hand Scan - Left		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
551041	Horizontal Stabilizer Lower Bonded Skin - Hand Scan - Right		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
551042	Horizontal Stabilizer Lower Bonded Skin - Permanent Repair - Left		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
551043	Horizontal Stabilizer Lower Bonded Skin - Permanent Repair - Right		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551044	Horizontal Stabilizer Lower Bonded Skin - Time Limited Repair - Left		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.5		48	14 May 2020	14 May 2024		
Airframe											
Notes: Accomplished GSL505510019-1 Time Limited Repair on 5/14/2020											
551045	Horizontal Stabilizer Lower Bonded Skin - Time Limited Repair - Right		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.5		48	14 May 2020	14 May 2024		
Airframe											
Notes: Accomplished GSL505510019-1 Time Limited Repair on 5/14/2020											
551109	Horizontal Stabilizer Rub Blocks - General Visual Inspection		HRS		665.8		3000	5515.4	8515.4	8565.4	0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
[HRS: +50/-50]											
Airframe											
Notes: WO FL016294 & 16365											
551110	Horizontal Stabilizer Rub Blocks - Functional Test		HRS		665.8		3000	5515.4	8515.4	8565.4	0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
[HRS: +50/-50]											
Airframe											
Notes: WO FL016294 & 16365											
551111	Elevator Upper Surface (External) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	3	48	28 Jun 2022	31 Jul 2026*	31 Aug 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
551113	Horizontal Stabilizer Leading Edge - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-1	6	03 Jun 2023	31 Dec 2023*	31 Jan 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
551201	Horizontal Stabilizer Internal Corrosion Inhibiting Compound (Left) - Restore		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	18 May 2024	18 Aug 2024	
[End Of Month Item] [MOS: +3m/-3m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551202	Horizontal Stabilizer Internal Corrosion Inhibiting Compound (Right) - Restore		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1		48**	26 Feb 2007	18 May 2024	18 Aug 2024	
Airframe		[End Of Month Item] [MOS: +3m/-3m]									
552001	Elevator External for Delamination (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
552002	Elevator External for Delamination (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
552005	Elevator Hinge (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.6		96	10 Jul 2018	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
552006	Elevator Hinge (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
552010	Elevator Skins and Hinges (Left) - General Visual Inspection		HRS		665.8			5515.4			0
			AFL		150		1800	1418	3218		0
			MOS		44.7			07 Apr 2020			
Airframe											
552012	Elevator Hinge Bolts and Sleeves - Detailed Inspection		HRS		6181.2			0			0
			AFL				8300**		8300		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
552015	Elevator Skins and Hinges (Right) - General Visual Inspection		HRS		665.8			5515.4			0
			AFL		150		1800	1418	3218		0
			MOS		44.6			09 Apr 2020			
Airframe											
553001	Vertical Stabilizer		HRS		6181.2			0			0
	1159CS50003-806	GA0818	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
			MSC				O/C				AEROSPACE
Airframe											
553005	Vertical Stabilizer Leading Edge Lower Section - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	192	23 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553010	Vertical CAP, SATCOM and Bullet Fairing - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-53	96	22 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553013	Vertical Stabilizer Leading Edge - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8	-1	6	03 Jun 2023	31 Dec 2023*	31 Jan 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553015	Vertical Stabilizer Box Section Internal Structure - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	192	25 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553016	Vertical Stabilizer Box Section Internal Flight Controls - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
553020	Vertical Stabilizer Rear Beam Aft Face - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553025	Vertical Stabilizer Assembly Internal - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	144	25 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553030	Vertical Stabilizer Rudder Support Structure - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-60	144	27 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553035	Vertical Stabilizer Upper Boomerang Fittings - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	144	25 Apr 2023	28 Feb 2035*	31 Mar 2035	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553036	Vertical Fin to Fuselage- General Visual Inspection		HRS		6181.2			0			0
			AFL		1568		8000	0	8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
553039	Fuselage Attach Boomerang Fittings - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
553040	Vertical Stabilizer - General Visual Inspection		HRS		597.1			5584.1			0
			AFL		124		4000	1444	5444		0
			MOS		32.8			05 Apr 2021			
Airframe											
553042	Vertical Stabilizer Forward STAR Fitting - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
553044	Vertical Stabilizer Aft STAR Fitting - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
553048	Vertical Stabilizer Access Cutouts - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
	Airframe										
553410	Vertical Stabilizer Rear Beam AT Pivot Fitting - Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
554005	Rudder External for Delamination - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	04 Jul 2018	31 Jul 2026	31 Aug 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
554010	Rudder Assembly Front Beam Internal - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		144	04 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
554015	Rudder Assembly Hinges, Bushing and Brackets - Detailed Inspection		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		107.5		144	14 Jan 2015	31 Jan 2027	28 Feb 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
554020	Rudder Hinge Fittings Bolts and Sleeves - Detailed Inspection		HRS		6181.2			0			0
			AFL				8300**		8300		0
			MOS		208.3			21 Aug 2006			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
554022	Rudder Skins and Hinges - General Visual Inspection		HRS		665.8			5515.4			0
			AFL		150		1800	1418	3218		0
			MOS		44.7			06 Apr 2020			
Airframe											
56 - Windows											
560001	Emergency Window Release Mechanism - Functional Test		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.7	56	48	06 Jul 2022	31 Aug 2026*	30 Sep 2026	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
561005	Windshield (Left) - Removal / Installation		HRS		1476.7			4704.5			0
	1159SCB5102-13	16272H6154	AFL		350			1218			0
			MOS	TSN:10	75.5			15 Sep 2017			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
561006	Windshield (Right) - Removal / Installation		HRS		1604.9			4576.3			0
	1159SCB5102-15	16260H5237	AFL		414			1154			0
			MOS		80.2			22 Apr 2017			CHASE WALTON ELASTOMERS
			MSC				O/C				
Airframe											
561011	Side Windows (Left) - Removal / Installation		HRS		1910.5			4270.7			0
	1159SCB5100-9	15308H1296	AFL		473			1095			0
			MOS	TSN:3	94.6			09 Feb 2016			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
561012	Side Windows (Right) - Removal / Installation		HRS		1910.5			4270.7			0
	1159SCB5100-11	15195H8632	AFL		473			1095			0
			MOS	TSN:6	94.6			09 Feb 2016			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
561101	Windshield Weather Seal (Hump Seal) (Left) - Detailed Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.4		24	18 Mar 2023	31 Mar 2025	30 Apr 2025	
								[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
561102	Windshield Weather Seal (Hump Seal) (Right) - Detailed Inspection		HRS		130.8		500	6050.4	6550.4	6600.4	0
			AFL		29			1539			0
			MOS		9.4		24	18 Mar 2023	31 Mar 2025	30 Apr 2025	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											
562001	Fixed Cabin Window (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00043	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											
562002	Fixed Cabin Window (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00044	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											
562003	Fixed Cabin Window (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00401	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											
562004	Fixed Cabin Window (Left No. 4) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00377	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											
562005	Fixed Cabin Window (Left No. 5) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00389	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											
562006	Fixed Cabin Window (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00388	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC					O/C			INC
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562007	Fixed Cabin Window (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00361	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
562008	Fixed Cabin Window (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00087	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
562009	Fixed Cabin Window (Right No. 4) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00203	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
562010	Fixed Cabin Window (Right No. 5) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-21	00378	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
562011	Emergency Exit Cabin Window (Left No. 1) - Removal / Installation		HRS		130.8			6050.4			0
	1159CE50001-79	PPG00436	AFL		29			1539			0
			MOS		6.9			01 Jun 2023			N/A
	Airframe		MSC					O/C			
562012	Emergency Exit Cabin Window (Left No. 2) - Removal / Installation		HRS		130.8			6050.4			0
	1159CE50001-79	PPG00350	AFL		29			1539			0
			MOS		6.9			01 Jun 2023			N/A
	Airframe		MSC					O/C			
562013	Emergency Exit Cabin Window (Right No. 1) - Removal / Installation		HRS		130.8			6050.4			0
	1159CE50001-79	PPG00393	AFL		29			1539			0
			MOS		7			30 May 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562014	Emergency Exit Cabin Window (Right No. 2) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159CCE50001-89	12201	MOS		6.9			01 Jun 2023			N/A
			MSC								
Airframe											
562015	Overwing Emergency Exits - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-54	96	23 Apr 2023	28 Feb 2031*	31 Mar 2031	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
562021	Fixed Cabin Window Inner Pane (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-19	06161H0456	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562022	Fixed Cabin Window Inner Pane (Left No. 2) - Removal / Installation		HRS	TSN:18.4	6162.8			18.4			0
			AFL	TSN:10	1558			10			0
	1159SCCE500-19	06164H0480	MOS	TSN:6	202.9			01 Feb 2007			PPG INDUSTRIES INC
			MSC								
Airframe											
562023	Fixed Cabin Window Inner Pane (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-19	06173H0600	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562024	Fixed Cabin Window Inner Pane (Left No. 4) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-19	06132H0251	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562025	Fixed Cabin Window Inner Pane (Left No. 5) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-19	06117H0142	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562026	Fixed Cabin Window Inner Pane (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	06161H0461	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562027	Fixed Cabin Window Inner Pane (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	05192H0399	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562028	Fixed Cabin Window Inner Pane (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	05201H0547	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562029	Fixed Cabin Window Inner Pane (Right No. 4) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	05250H0306	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562030	Fixed Cabin Window Inner Pane (Right No. 5) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	06161H0449	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562031	Emergency Exit Cabin Window Pane (Left Inner No. 1) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	06164H0483	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			
562032	Emergency Exit Cabin Window Pane (Left Inner No. 2) - Removal / Installation		HRS		6181.2			0			0
	1159SCCE500-19	06097H0973	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562033	Emergency Exit Cabin Window Pane (Right Inner No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-19	06164H0482	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562034	Emergency Exit Cabin Window Pane (Right Inner No. 2) - Removal / Installation		HRS		890.8			5290.4			0
			AFL		213			1355			0
	1159CE50001-89	12201	MOS		53.1			25 Jul 2019			
			MSC								
Airframe											
562041	Fixed Cabin Window Outer Pane (Left No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562042	Fixed Cabin Window Outer Pane (Left No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562043	Fixed Cabin Window Outer Pane (Left No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562044	Fixed Cabin Window Outer Pane (Left No. 4) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											
562045	Fixed Cabin Window Outer Pane (Right No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562046	Fixed Cabin Window Outer Pane (Right No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562047	Fixed Cabin Window Outer Pane (Right No. 3) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562048	Fixed Cabin Window Outer Pane (Right No. 4) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562049	Emergency Exit Cabin Window Pane (Left Outer No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562050	Emergency Exit Cabin Window Pane (Left Outer No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562051	Emergency Exit Cabin Window Pane (Right Outer No. 1) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
562052	Emergency Exit Cabin Window Pane (Right Outer No. 2) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		208.3			21 Aug 2006			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562101	Cabin Window (Left No. 1) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562102	Cabin Window (Left No. 2) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562103	Cabin Window (Left No. 3) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562104	Cabin Window (Left No. 4) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562105	Cabin Window (Left No. 5) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562106	Cabin Window (Right No. 1) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562107	Cabin Window (Right No. 2) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562108	Cabin Window (Right No. 3) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562109	Cabin Window (Right No. 4) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562110	Cabin Window (Right No. 5) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562111	Cabin Window (Left Emergency No. 1) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562112	Cabin Window (Left Emergency No. 2) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562113	Cabin Window (Right Emergency No. 1) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562114	Cabin Window (Right Emergency No. 2) - Special Detailed Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
	Airframe		MSC					O/C			
562115	Cabin Windows - Leak Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
	Airframe		MSC					O/C			

57 - Wings

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570001	Wing Assy, Left		HRS		6181.2			0			0
	1159W50002-41	819	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
570002	Wing Assy, Right		HRS		6181.2			0			0
	1159W50002-42	819	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
570005	Wing Upper Surface View from on Wing (Left) - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		48	05 Apr 2021	30 Apr 2025	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570006	Wing Upper Surface View from on Wing (Right) - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		48	05 Apr 2021	30 Apr 2025	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570009	Wing Lower Surface (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	29	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570010	Wing Lower Surface (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	22	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570013	Upper Wing Extension BI 542 - BI 545 (View from on Wing) {Left} - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		48	05 Apr 2021	30 Apr 2025	31 May 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570014	Upper Wing Extension BI 542 - BI 545 (View from on Wing) {Right} - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		48	05 Apr 2021	30 Apr 2025	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570015	Lower Wing Extension BI 542 - BI 545 (View from Ground) {Left} - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	18	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570016	Lower Wing Extension BI 542 - BI 545 (View from Ground) {Right} - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.4	18	24	18 Mar 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570017	Wing Rear Beam AT Aileron (Ws 386 - Ws 479) (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	-60	96	15 Mar 2023	31 Jan 2031*	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570018	Wing Rear Beam AT Aileron (Ws 386 - Ws 479) (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	-60	96	15 Mar 2023	31 Jan 2031*	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570200	Wing Box Structure Forward Spar Through Gap Bands (Left) - General Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	96	27 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570201	Wing Box Structure Forward Spar Through Gap Bands (Right) - General Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	96	27 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570205	Fuel Tank Internal (Left) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.7		96	06 Apr 2021	30 Apr 2029	31 May 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570206	Fuel Tank Internal (Right) - Detailed Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.3		96	21 Apr 2021	30 Apr 2029	31 May 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
571110	Lower Cover Splice and Coaming Stringers (Left) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		208.3				21 Aug 2006		
	Airframe										
571112	Lower Cover Splice and Coaming Stringers (Right) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		208.3				21 Aug 2006		
	Airframe										
571200	Rear Spar - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1				26 Feb 2007		
	Airframe		MSC O/C								
Notes: N/A DUE TO ASC 80 INCORPORATED											
571201	Rear Spar BI 6 - BI 35 (Left) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		208.3				21 Aug 2006		
	Airframe										
571202	Rear Spar BI 6 - BI 35 (Right) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		208.3				21 Aug 2006		
	Airframe										
571203	BI 0 Lower Rib AT Rear Spar - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3				21 Aug 2006		
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571204	BI 0 Lower Rib AT Rear Spar (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571207	BI 6 Rib Web AT Forward Fitting (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571208	BI 6 Rib Web AT Forward Fitting (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571209	BI 18.5 Rib (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571210	BI 18.5 Rib (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571211	BI 35.8 Rib AT Wing to Fuselage Fitting (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571212	BI 35.8 Rib AT Wing to Fuselage Fitting (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
571220	Rear Spar Sponson and Trailing Edge Extension (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571222	Rear Spar Sponson and Trailing Edge Extension (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571225	Rear Spar Covered Areas Outboard of BI 35 (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571227	Rear Spar Covered Areas Outboard of BI 35 (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571303	Rear Spar AT Spoiler Actuator Fitting Doubler Repair (Left) - Ndt Inspection		HRS			1350.6	20000**		21350.6*		0
			AFL			396	8000**		8396*		0
			MOS		208.3			21 Aug 2006			
Airframe											
571304	Rear Spar AT Spoiler Actuator Fitting Doubler Repair (Right) - Ndt Inspection		HRS			1350.6	20000**		21350.6*		0
			AFL			396	8000**		8396*		0
			MOS		208.3			21 Aug 2006			
Airframe											
571401	Lower Sponson Doubler (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				6000**		6000		0
			MOS		208.3			21 Aug 2006			
Airframe											
571402	Lower Sponson Doubler (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				6000**		6000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571403	Rbs 109.5 Sponson Rib (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
571404	Rbs 109.5 Sponson Rib (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
571405	BI 91.06 Sponson Rib (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
571406	BI 91.06 Sponson Rib (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
571420	Sponson Lugs (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
571422	Sponson Lugs (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											
571601	Wing to Fuselage Attach Corrosion Resistant Steel / Titanium Fitting - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-58	96	27 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571701	BI 0 Lower Wing Skin Splice AT Front Spar (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571702	BI 0 Lower Wing Skin Splice AT Front Spar (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571703	BI 0 Lower Wing Centerline Splice AT Front Spar (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571704	BI 0 Lower Wing Centerline Splice AT Front Spar (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571705	BI 0 Lower Wing Skin Splice AT Rear Spar (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571706	BI 0 Lower Wing Skin Splice AT Rear Spar (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
571707	Rear Beam Web AT BI 91 Sponson Rib Fastener Holes - Ndt Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
Airframe											
571709	External Rear Beam Web AT BI 49 - Ndt Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
573001	Winglet (Left) - Removal / Installation		HRS		6181.2			0			0
	1159W57131-21	0319	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
573002	Winglet (Right) - Removal / Installation		HRS		6181.2			0			0
	1159W57131-22	0319	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
573005	Wing Extension BI 542 - BI 545 (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	192	23 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573006	Wing Extension BI 542 - BI 545 (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.2	-56	192	23 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573010	Winglet Blade (View from Ground) {Left} - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18	-3	48	28 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573011	Winglet Blade (View from Ground) {Right} - Zonal Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18.1	-2	48	27 Jun 2022	30 Jun 2026*	31 Jul 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574001	Leading Edge, L Wing #1		HRS		6181.2			0			0
	1159W56301-91	844	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
574002	Leading Edge, L Wing #2		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56002-9	841	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.2			23 Apr 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574003	Leading Edge, L Wing #3		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56003-9	841	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.2			22 Apr 2023			
	Airframe		MSC					O/C			
574004	Leading Edge, L Wing #4		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56004-15	841	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.2			22 Apr 2023			
	Airframe		MSC					O/C			
574005	Leading Edge, L Wing #5		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56005-9	842	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.2			23 Apr 2023			
	Airframe		MSC					O/C			
574006	Leading Edge, L Wing #6		HRS		6181.2			0			0
	1159W56402-49	837	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
574007	Leading Edge, R Wing #1		HRS		6181.2			0			0
	1159W56301-92	841	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
574008	Leading Edge, R Wing #2		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56002-10	828	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	8.2			23 Apr 2023			
	Airframe		MSC					O/C			
574009	Leading Edge, R Wing #3		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56003-10	836	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7.1			25 May 2023			
	Airframe		MSC					O/C			
574010	Leading Edge, R Wing #4		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56004-16	837	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7.1			25 May 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574011	Leading Edge, R Wing #5		HRS	TSN:6050.4	130.8			6050.4			0
	1159W56005-10	837	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	7.1			25 May 2023			
	Airframe		MSC					O/C			
574012	Leading Edge, R Wing #6		HRS		6181.2			0			0
	1159W56402-50	838	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
574013	Wing Leading Edge (Left) - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	2	6	31 May 2023 31 Dec 2023*	31 Jan 2024		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574014	Wing Leading Edge (Right) - Polishing		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9	2	6	31 May 2023 31 Dec 2023*	31 Jan 2024		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574015	Wing Leading Edge External BI 44.0 - BI 529 Inboard of Navigation Light (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	25	24	15 Mar 2023 30 Apr 2025*	31 May 2025		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574016	Wing Leading Edge External BI 44.0 - BI 529 Inboard of Navigation Light (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	25	24	15 Mar 2023 30 Apr 2025*	31 May 2025		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574017	Wing Leading Edge With Gap Bands Removed (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.4	-49	96	18 Apr 2023 28 Feb 2031*	31 Mar 2031		
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574018	Wing Leading Edge With Gap Bands Removed (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.4	-49	96	18 Apr 2023	28 Feb 2031*	31 Mar 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
574019	Wing Leading Edges Removed (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-54	192	21 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
574020	Wing Leading Edges Removed (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.3	-54	192	21 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575001	Wing Trailing Edge (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	21	24	15 Mar 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575002	Wing Trailing Edge (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		9.5	21	24	15 Mar 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575003	Wing Rear Beam (Left) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-8	24	27 Apr 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575004	Wing Rear Beam (Right) - Zonal Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.1	-8	24	27 Apr 2023	30 Apr 2025*	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575005	Wing Box Section (Left) - Zonal Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								O/C
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575006	Wing Box Section (Right) - Zonal Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575007	Wing Tank Internal Inboard 3 Panels Each Wing (Left) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.8		24	05 Jul 2022	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575008	Wing Tank Internal Inboard 3 Panels Each Wing (Right) - Detailed Inspection		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		17.8		24	05 Jul 2022	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575021	Wing Rear Beam (Left Enhanced) - Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575022	Wing Rear Beam (Right Enhanced) - Zonal Inspection		HRS		392.4			5788.8			0
			AFL		88			1480			0
			MOS		21.6	7	24	11 Mar 2022	31 Mar 2024*	30 Apr 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575101	Flap B and C Track (Left B Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575102	Flap B and C Track (Right B Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575103	Flap B and C Track (Left C Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575104	Flap B and C Track (Right C Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575105	Flap A and D Track (Left A Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575106	Flap A and D Track (Right A Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575107	Flap A and D Track (Left D Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575108	Flap A and D Track (Right D Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
575111	Flap B and C Track Lower Flange (Left B Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL				7200**		7200		0
			MOS		208.3			21 Aug 2006			
	Airframe										
575112	Flap B and C Track Lower Flange (Right B Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL				7200**		7200		0
			MOS		208.3			21 Aug 2006			
	Airframe										
575113	Flap B and C Track Lower Flange (Left C Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL				7200**		7200		0
			MOS		208.3			21 Aug 2006			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575114	Flap B and C Track Lower Flange (Right C Track) - Ndt Inspection		HRS		6181.2			0			0
			AFL								0
			MOS		208.3			21 Aug 2006	7200**		
Airframe											
575115	Flap D Track Lower Flange (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe								O/C			
575116	Flap D Track Lower Flange (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe								O/C			
575205	Left Wing Box Section - Zonal Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
Airframe								O/C			
575206	Right Wing Box Section - Zonal Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
Airframe								O/C			
575210	Flap Front Spar AT A, B, C and D Tracks (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe								O/C			
575212	Flap Front Spar AT A, B, C and D Tracks (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe								O/C			
575215	Flap Front Spar AT Spoiler Doors (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL						8000**		0
			MOS		208.3			21 Aug 2006		8000	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575217	Flap Front Spar AT Spoiler Doors (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				8000**		8000		0
			MOS		208.3			21 Aug 2006			
Airframe											
575220	Flap Rear Spar AT B, C and D Track Cutouts (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
Airframe											
575222	Flap Rear Spar AT B, C and D Track Cutouts (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				12000**		12000		0
			MOS		208.3			21 Aug 2006			
Airframe											
575601	Trailing Edge Flight Control Attach Hinge / Support Fittings (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
575602	Trailing Edge Flight Control Attach Hinge / Support Fittings (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
576005	Aileron Ballast Weights (Left) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
576006	Aileron Ballast Weights (Right) - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8		96	05 Jul 2018	31 Jul 2026	31 Aug 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
576010	Aileron Tab / Spoilers External for Delamination - Detailed Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.3		96	21 Jun 2018	30 Jun 2026	31 Jul 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
577001	Spoiler Hinge Fitting (Left Ground) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											
577002	Spoiler Hinge Fitting (Right Ground) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											
577003	Spoiler Hinge Fitting (Left Inboard Flight) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											
577004	Spoiler Hinge Fitting (Right Inboard Flight) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											
577005	Spoiler Hinge Fitting (Left Outboard Flight) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											
577006	Spoiler Hinge Fitting (Right Outboard Flight) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
577210	Spoiler Support Hinges (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
577211	Spoiler Support Hinges (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
577215	Spoiler Drive Hinges (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
577216	Spoiler Drive Hinges (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
71 - Power Plant											
710001	Engine (Left) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	BR700-710C4-11 15351		AFL	TSN:1539	29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			
710002	Engine (Right) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	BR700-710C4-11 15350		AFL	TSN:1539	29			1539			0
			MOS		6.8			03 Jun 2023			N/A
	Airframe		MSC					O/C			
710005	No. 1 Engine - Engine Midlife Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			

Notes: PN: BR700-710C4-11 SN: 15351. ENGINE DECLARED TASK ORIENTED

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710005 (710006)	No. 2 Engine - Engine Midlife Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
Notes: PN: BR700-710C4-11 SN: 15350. ENGINE DECLARED TASK ORIENTED											
710009	No. 1 Engine - Engine Overhaul		HRS		6181.2			0			0
	BR700-710C4-11	15351	ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD.
Notes: ENGINE DECLARED TASK ORIENTED											
710009 (710010)	No. 2 Engine - Engine Overhaul		HRS		6181.2			0			0
	BR700-710C4-11	15350	ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD.
Notes: ENGINE DECLARED TASK ORIENTED											
710011	No. 1 Engine - Engine Run - Pre-Operational Checks		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
	Engine		MSC					O/C			
710011 (710012)	No. 2 Engine - Engine Run - Pre-Operational Checks		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
	Engine		MSC					O/C			
710013	No. 1 Engine - Engine Run - Checklist		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			
710013 (710014)	No. 2 Engine - Engine Run - Checklist		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710015	No. 1 Engine - Engine Test 1 - Wet Motor Operation Leak Check		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
			MSC						O/C		
Engine											
710015 (710016)	No. 2 Engine - Engine Test 1 - Wet Motor Operation Leak Check		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
			MSC						O/C		
Engine											
710017	No. 1 Engine - Engine Run Leak Check Test 2A - Lp Fuel System / Oil System		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC						O/C		
Engine											
710017 (710018)	No. 2 Engine - Engine Run Leak Check Test 2A - Lp Fuel System / Oil System		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC						O/C		
Engine											
710019	No. 1 Engine - Engine Run Leak Check Test 2B - Hp Fuel System		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
710019 (710020)	No. 2 Engine - Engine Run Leak Check Test 2B - Hp Fuel System		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
710021	Engine Test 3A (Left) - Thrust Reverser Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710022	Engine Test 3A (Right) - Thrust Reverser Check		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC					O/C			
710023	Engine Test 3B (Left) - Thrust Reverser / Line Replacement Unit Leak Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
710024	Engine Test 3B (Right) - Thrust Reverser / Line Replacement Unit Leak Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
710025	No. 1 Engine - Engine Test 4 - Engine Power Assurance Check		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			
710025 (710026)	No. 2 Engine - Engine Test 4 - Engine Power Assurance Check		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			
710027	No. 1 Engine - Engine Test 5 - Pretested Replacement Engine Test		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			
710027 (710028)	No. 2 Engine - Engine Test 5 - Pretested Replacement Engine Test		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710029	No. 1 Engine - Engine Test 6 - Vibration Survey		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
	Engine		MSC					O/C			
710029 (710030)	No. 2 Engine - Engine Test 6 - Vibration Survey		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		31.7			06 May 2021			
	Engine		MSC					O/C			
710031	No. 1 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
710031 (710032)	No. 2 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
710033	No. 1 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance (Alternate)		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
710033 (710034)	No. 2 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance (Alternate)		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
710035	No. 1 Engine - Low-Pressure Compressor (Fan) Blade SET - RE-Index		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710035 (710036)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		6181.2			0			0
	SET - RE-Index		ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
710037	No. 1 Engine - Engine Test 9 - Full Authority Digital Engine		HRS		130.8			6050.4			0
	Control (Fadec) Operational Test		ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC							O/C	
Engine											
710037 (710038)	No. 2 Engine - Engine Test 9 - Full Authority Digital Engine		HRS		130.8			6050.4			0
	Control (Fadec) Operational Test		ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC							O/C	
Engine											
710039	No. 1 Engine - Cockpit Engine Vibration Monitor (EVM)		HRS		130.8			6050.4			0
	Card - Vibration Run		ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC							O/C	
Engine											
710039 (710040)	No. 2 Engine - Cockpit Engine Vibration Monitor (EVM)		HRS		130.8			6050.4			0
	Card - Vibration Run		ENC		29			1539			0
			MOS		6.9			02 Jun 2023			
			MSC							O/C	
Engine											
710061	No. 1 Engine - Engine Maintenance Program Declaration		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.1			26 Feb 2007			
Engine											
Notes: ENGINE DECLARED TASK ORIENTED											
710061 (710062)	No. 2 Engine - Engine Maintenance Program Declaration		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.1			26 Feb 2007			
Engine											
Notes: ENGINE DECLARED TASK ORIENTED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711001	Inlet Cowl (Left) - Removal / Installation		HRS		6181.2			0			0
	04C0001-019	GVSP123	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AIRFRAME COMPONENT & REPAIR INC
	Airframe		MSC					O/C			
711002	Inlet Cowl (Right) - Removal / Installation		HRS		6181.2			0			0
	04C0001-020	GVSP122	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			AIRFRAME COMPONENT & REPAIR INC
	Airframe		MSC					O/C			
711003	Inlet Cowl Aerodynamic Surfaces (Left) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe		[HRS: +50/-50]								
711004	Inlet Cowl Aerodynamic Surfaces (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe		[HRS: +50/-50]								
711005	Cowl Fasteners and Attachment Features (Left) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
	Airframe		[HRS: +50/-50]								
711006	Cowl Fasteners and Attachment Features (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe		[HRS: +50/-50]								
711007	Inlet Cowl Rear Bulkhead (Left) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.7			07 Apr 2023			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711008	Inlet Cowl Rear Bulkhead (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe				[HRS: +50/-50]						
711015	Fixed Cowls (Left) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe				[HRS: +50/-50]						
711016	Fixed Cowls (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			09 Apr 2023			
	Airframe				[HRS: +50/-50]						
711017	Apron, L Engine Fixed		HRS		6181.2			0			0
	04E2001-001	GVSP124\SB2693	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe						O/C				
711018	Apron, R Engine Fixed		HRS		6181.2			0			0
	04E0002-027	GVSP124\SB2694	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe						O/C				
711019	Lower Cowl Door (Left) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	04D4002-001	GVSP125 SB2697	AFL	TSN:1539	29			1539			0
			MOS	TSN:201	6.8			03 Jun 2023			N/A
	Airframe						O/C				
711020	Lower Cowl Door (Right) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
	04D4003-001	GVSP125 SB2698	AFL	TSN:1539	29			1539			0
			MOS	TSN:200	7.4			16 May 2023			N/A
	Airframe						O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)	MOS	TSN	Time	Date	Date	Date	Manufacturer
											Date Type
711021	Upper Cowl Door (Left) - Removal / Installation				HRS	TSN:6041.4	130.8			6050.4	0
	04D4001-001	GVSP125 SB2695			AFL	TSN:1538	29			1539	0
					MOS	TSN:200	7.4			16 May 2023	N/A
	Airframe				MSC					O/C	
711022	Upper Cowl Door (Right) - Removal / Installation				HRS	TSN:6041.4	130.8			6050.4	0
	04D4001-002	GVSP125 SB2696			AFL	TSN:1538	29			1539	0
					MOS	TSN:200	7.4			16 May 2023	N/A
	Airframe				MSC					O/C	
711109	Inlet Cowl Lipskin (Left) - Polishing				HRS		130.8			6050.4	0
					AFL		29			1539	0
					MOS		6.9	2	6	31 May 2023 31 Dec 2023* 31 Jan 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m]						
711110	Inlet Cowl Lipskin (Right) - Polishing				HRS		130.8			6050.4	0
					AFL		29			1539	0
					MOS		6.9	2	6	31 May 2023 31 Dec 2023* 31 Jan 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m]						
711301	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (Viewed from Ground) - Zonal Inspection				HRS		392.4			5788.8	0
					AFL		88			1480	0
					MOS		21.6	8	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m]						
711302	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (Viewed from Ground) - Zonal Inspection				HRS		392.4			5788.8	0
					AFL		88			1480	0
					MOS		21.6	8	24	11 Mar 2022 31 Mar 2024* 30 Apr 2024	
	Airframe				[End Of Month Item] [MOS: +1m/-1m]						
711305	Powerplant / Nacelle External (View from Platform) - Zonal Inspection				HRS		597.1			5584.1	0
					AFL		124			1444	0
					MOS		32.8		96	05 Apr 2021 30 Apr 2029 31 May 2029	
	Airframe				[End Of Month Item] [MOS: +1m/-1m]						

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711306	Powerplant / Nacelle External (View from Platform) - Zonal Inspection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		32.8		96	05 Apr 2021	30 Apr 2029	31 May 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
711310	Powerplant Nose Cowls Internal (Left) - Zonal Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.6		144	09 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
711311	Powerplant Nose Cowls Internal (Right) - Zonal Inspection		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.6		144	09 Jul 2018	31 Jul 2030	31 Aug 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
711315	Powerplant and Nacelle Doors Internal (Left) - Zonal Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
711316	Powerplant and Nacelle Doors Internal (Right) - Zonal Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		6.8			03 Jun 2023			
	Airframe		[HRS: +50/-50]								
712011	Chatterproof Bolt (Left Upper) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7			06 Apr 2023			
	Airframe		MSC				O/C				
712015	Chatterproof Bolt (Left Lower) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7			06 Apr 2023			
	Airframe		MSC				O/C				
712020	Chatterproof Bolt (Right Upper) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7			06 Apr 2023			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
712024	Chatterproof Bolt (Right Lower) - Detailed Inspection		HRS		130.8			6050.4			0	
	Airframe		AFL		29			1539			0	
			MOS		8.7			06 Apr 2023				
			MSC					O/C				
712101	Mount, L Engine Fwd Trunnion		HRS		6181.2			0			0	
	Airframe	1159B51971-5	B0130	AFL		1568		0			0	
				MOS		208.3		21 Aug 2006			THAYER	
				MSC				O/C			AEROSPACE	
712102	Mount, R Engine Fwd Trunnion		HRS		6181.2			0			0	
	Airframe	1159B51971-6	B0131	AFL		1568		0			0	
				MOS		208.3		21 Aug 2006			THAYER	
				MSC				O/C			AEROSPACE	
712103	Forward Engine Mount (Left) - Detailed Inspection		HRS		130.8			6050.4			0	
	Airframe			AFL		29		1539			0	
				MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
												[End Of Month Item] [MOS: +1m/-1m]
712104	Forward Engine Mount (Right) - Detailed Inspection		HRS		130.8			6050.4			0	
	Airframe			AFL		29		1539			0	
				MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
												[End Of Month Item] [MOS: +1m/-1m]
712105	Forward Upper Engine Link (Left) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCP570-1	1296	AFL		1568		0			0	
				MOS		208.3		21 Aug 2006			CHASE WALTON	
				MSC				O/C			ELASTOMERS	
712106	Forward Upper Engine Link (Right) - Removal / Installation		HRS		6181.2			0			0	
	Airframe	1159SCP570-1	1305	AFL		1568		0			0	
				MOS		208.3		21 Aug 2006			CHASE WALTON	
				MSC				O/C			ELASTOMERS	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712107	Forward Lower Engine Link (Left) - Removal / Installation		HRS		6181.2			0			0
	1159SCP570-1	1297	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHASE WALTON
	Airframe		MSC					O/C			ELASTOMERS
712108	Forward Lower Engine Link (Right) - Removal / Installation		HRS		6181.2			0			0
	1159SCP570-1	1307	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			CHASE WALTON
	Airframe		MSC					O/C			ELASTOMERS
712109	Link Assemblies (Engine Removed) (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712110	Link Assemblies (Engine Removed) (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712111	Forward Upper Fuselage Link (Left) - Removal / Installation		HRS		6181.2			0			0
	1159BM51245-3	J048093-011	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712112	Forward Upper Fuselage Link (Right) - Removal / Installation		HRS		6181.2			0			0
	1159BM51245-3	039880-006	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712113	Pin, Lh Fuselage/Engine Mount		HRS		6181.2			0			0
	1159BM51246-13	403417-18	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712114	Pin, Rh Fuselage/Engine Mount		HRS		6181.2			0			0
	1159BM51246-13	403417-23	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712115	Pin, Lh Fuselage/Engine Link		HRS		6181.2			0			0
	1159BM51246-13	314420-21	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712116	Pin, Rh Fuselage/Engine Link		HRS		6181.2			0			0
	1159BM51246-13	314420-19	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712117	CAP, Lh Beam Brace/Trunnion		HRS		6181.2			0			0
	1159BM51248-11	311190-22	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712118	CAP, Rh Beam Brace/Trunnion		HRS		6181.2			0			0
	1159BM51248-11	313318-2	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712119	CAP, Lh Fuselage/Beam Brace		HRS		6181.2			0			0
	1159BM51248-11	311190-3	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712120	CAP, Rh Fuselage/Beam Brace		HRS		6181.2			0			0
	1159BM51248-11	313318-64	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712121	Pin, Lh Trunnion/Eng Link UPR		HRS		6181.2			0			0
	1159BM51247-11	042130-037	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712122	Pin, Rh Trunnion/Eng Link UPR		HRS		6181.2			0			0
	1159BM51247-11	042130-025	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712123	Pin, Lh Trunnion/Eng Link Lwr		HRS		6181.2			0			0
	1159BM51247-11	042130-035	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712124	Pin, Rh Trunnion/Eng Link Lwr		HRS		6181.2			0			0
	1159BM51247-11	042130-036	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712125	CAP, Lh Trunnion/Eng Link UPR		HRS		6181.2			0			0
	1159BM51249-11	311194-121	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712126	CAP, Rh Trunnion/Eng Link UPR		HRS		6181.2			0			0
	1159BM51249-11	311194-170	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712127	CAP, Lh Trunnion/Eng Link Lwr		HRS		6181.2			0			0
	1159BM51249-11	313406-122	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712128	CAP, Rh Trunnion/Eng Link Lwr		HRS		6181.2			0			0
	1159BM51249-11	311194-140	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712129	Pin, Lh Link/Engine Mount		HRS		6181.2			0			0
	1159BM51246-15	310986-25	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712130	Pin, Rh Link/Engine Mount		HRS		6181.2			0			0
	1159BM51246-15	312985-5	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712131	CAP, Lh Trunnion/Fuselage Lwr		HRS		6181.2			0			0
	1159BM51248-11	313318-61	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712132	CAP, Rh Trunnion/Fuselage Lwr		HRS		6181.2			0			0
	1159BM51248-11	313318-62	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712133	Forward Upper Engine Link (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
	Airframe		MSC					O/C			
712134	Forward Upper Engine Link (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712137	Forward Upper Fueselage Link (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				2700**		2700		0
			MOS		210			30 Jun 2006			
Airframe											
712138	Forward Upper Fueselage Link (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				2700**		2700		0
			MOS		210			29 Jun 2006			
Airframe											
712139	Forward Engine Mount, PT.F (Lug A) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC				O/C				
Airframe											
712140	Forward Engine Mount, PT.F (Lug A) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC				O/C				
Airframe											
712141	Forward Engine Mount, PT.E (Lug B) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC				O/C				
Airframe											
712142	Forward Engine Mount, PT.E (Lug B) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC				O/C				
Airframe											
712143	Forward Engine Mount, PT.C (Lug C) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712144	Forward Engine Mount, PT.C (Lug C) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC					O/C			
Airframe											
712145	Forward Engine Mount, PT.G (Lug D) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC					O/C			
Airframe											
712146	Forward Engine Mount, PT.G (Lug D) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC					O/C			
Airframe											
712147	Forward Engine Mount, PT.N (Lug E) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC					O/C			
Airframe											
712148	Forward Engine Mount, PT.N (Lug E) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC					O/C			
Airframe											
712149	Forward Engine Mount, PT.U (Lug F) (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
			MSC					O/C			
Airframe											
712150	Forward Engine Mount, PT.U (Lug F) (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712160	Forward Engine Mount Spherical Bearings and Bearing Inner and Outer Housings (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.5		192	14 May 2023	31 May 2039	30 Jun 2039	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
712162	Forward Engine Mount Spherical Bearings and Bearing Inner and Outer Housings (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.5		192	14 May 2023	31 May 2039	30 Jun 2039	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
712201	Mount, L Engine Fwd Fuse-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									
712202	Mount, R Engine Fwd Fuse-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									
712203	Mount, L Eng Aft Fuse-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									
712204	Mount, R Eng Aft Fuse-Insp		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
Airframe		MSC O/C									
712205	Engine Aft Suspension Upper Strut Assembly (Left) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159SCP567-1	TY-4813	MOS	TSN:22	7.9			02 May 2023			N/A
Airframe		MSC O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712206	Engine Aft Suspension Upper Strut Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP567-1	TY2124	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
712207	Engine Aft Suspension Lower Strut Assembly (Left) - Removal / Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
	1159SCP568-1	TY-4853	MOS	TSN:21	7.9			02 May 2023			N/A
			MSC						O/C		
Airframe											
712208	Engine Aft Suspension Lower Strut Assembly (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP568-1	TY2200	MOS		208.3			21 Aug 2006			
			MSC						O/C		
Airframe											
712209	Aft Engine Mount Strut Assemblies External (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712210	Aft Engine Mount Strut Assemblies External (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712211	Mount, L Fwd UPR Fwd Fuselage		HRS		6181.2			0			0
			AFL		1568			0			0
	1159BM50505-5	039029-010	MOS		208.3			21 Aug 2006			
			MSC						O/C		STELLEX PRECISION MACHINING, INC
Airframe											
712212	Mount, L Fwd UPR Aft Fuselage		HRS		6181.2			0			0
			AFL		1568			0			0
	1159BM50505-3	039161-019	MOS		208.3			21 Aug 2006			
			MSC						O/C		STELLEX PRECISION MACHINING, INC
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712213	Mount, L Fwd Lwr Fwd Fuselage		HRS		6181.2			0			0
	1159BM50506-5	J050966-006	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712214	Mount, L Fwd Lwr Aft Fuselage		HRS		6181.2			0			0
	1159BM50506-1	043141-001	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712215	Mount, R Fwd UPR Fwd Fuselage		HRS		6181.2			0			0
	1159BM50505-5	039030-001	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STELLEX PRECISION MACHINING, INC
	Airframe		MSC					O/C			
712216	Mount, R Fwd UPR Aft Fuselage		HRS		6181.2			0			0
	1159BM50505-3	039161-026	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			STELLEX PRECISION MACHINING, INC
	Airframe		MSC					O/C			
712217	Mount, R Fwd Lwr Fwd Fuselage		HRS		6181.2			0			0
	1159BM50506-5	038658-001	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712218	Mount, R Fwd Lwr Aft Fuselage		HRS		6181.2			0			0
	1159BM50506-1	043141-003	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712219	Mount, L Aft UPR Fwd Fuselage		HRS		6181.2			0			0
	1159BM50919-13	040040-003	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712220	Mount, L Aft UPR Aft Fuselage		HRS		6181.2			0			0
	1159BM50923-13	04445-007	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712221	Mount, L Aft Lwr Fwd Fuselage		HRS		6181.2			0			0
	1159BM50921-13	038928-003	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712222	Mount, L Aft Lwr Aft Fuselage		HRS		6181.2			0			0
	1159BM50924-13	J045310-003	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712223	Mount, R Aft UPR Fwd Fuselage		HRS		6181.2			0			0
	1159BM50919-13	040040-007	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712224	Mount, R Aft UPR Aft Fuselage		HRS		6181.2			0			0
	1159BM50923-13	044449-004	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712225	Mount, R Aft Lwr Fwd Fuselage		HRS		6181.2			0			0
	1159BM50921-13	038928-006	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712226	Mount, R Aft Lwr Aft Fuselage		HRS		6181.2			0			0
	1159BM50924-13	J045310-007	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712227	Pin, L Eng Rear Mount Ring		HRS		6181.2			0			0
	1159BM51253-11	038085-047	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712228	Pin, R Eng Rear Mount Ring		HRS		6181.2			0			0
	1159BM51253-11	038085-046	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712229	Pin, Lh Rear UPR Link/Fuselage		HRS		6181.2			0			0
	1159BM51247-11	042130-015	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712230	Pin, Rh Rear UPR Link/Fuselage		HRS		6181.2			0			0
	1159BM51247-11	040095-012	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712231	Pin, Lh Rear Lwr Link/Fuselage		HRS		6181.2			0			0
	1159BM51247-11	042130-031	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712232	Pin, Rh Rear Lwr Link/Fuselage		HRS		6181.2			0			0
	1159BM51247-11	040095-023	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712233	CAP, Lh Rear UPR Link/Fuselage		HRS		6181.2			0			0
	1159BM51249-11	313406-52	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712234	CAP, Rh Rear UPR Link/Fuselage		HRS		6181.2			0			0
	1159BM51249-11	313406-157	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712235	CAP, Lh Rear Lwr Link/Fuselage		HRS		6181.2			0			0
	1159BM51249-11	313406-30	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712236	CAP, Rh Rear Lwr Link/Fuselage		HRS		6181.2			0			0
	1159BM51249-11	313406-193	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712237	Aft Upper Swaged Strut (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
	Airframe		MSC					O/C			
712238	Aft Upper Swaged Strut (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
	Airframe		MSC					O/C			
712249	Aft Engine Mount Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712250	Aft Engine Mount Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712301	Engine Thrust Strut (Left) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCP566-3	TY1056	AFL		29			1539			0
			MOS		7.9			02 May 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712302	Engine Thrust Strut (Right) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCP566-4	TY1051	AFL		29			1539			0
			MOS		8			29 Apr 2023			N/A
	Airframe		MSC					O/C			
712303	Thrust and Alignment Strut Assemblies External (Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712304	Thrust and Alignment Strut Assemblies External (Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712307	Aft Attach Fitting Thrust / Alignment (FS 820, Left) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712308	Aft Attach Fitting Thrust / Alignment (FS 820, Right) - Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712309	Pin, Lh Thrust Strut Aft		HRS		6181.2			0			0
	1159BM51253-13	043125-039	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712310	Pin, Rh Thrust Strut Aft		HRS		6181.2			0			0
	1159BM51253-13	043125-023	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712311	Pin, Lh Thrust Strut Fwd		HRS		6181.2			0			0
	1159BM51253-15	170	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712312	Pin, Rh Thrust Strut Fwd		HRS		6181.2			0			0
	1159BM51253-15	163	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			PRO-FAB, INC.
	Airframe		MSC					O/C			
712313	CAP, Lh Thrust Strut Aft		HRS		6181.2			0			0
	1159BM51249-11	313406-54	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712314	CAP, Rh Thrust Strut Aft		HRS		6181.2			0			0
	1159BM51249-11	313406-25	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712315	CAP, Lh Thrust Strut Fwd		HRS		6181.2			0			0
	1159BM51249-11	313406-198	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712316	CAP, Rh Thrust Strut Fwd		HRS		6181.2			0			0
	1159BM51249-11	313406-164	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			
712317	Mount, L Thrust/Jury Fuselage		HRS		6181.2			0			0
	1159BM51243-7	050176-004	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712318	Mount, R Thrust/Jury Fuselage		HRS		6181.2			0			0
	1159BM51243-8	J050178-002	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			THAYER
	Airframe		MSC					O/C			AEROSPACE
712321	Thrust Strut Fitting (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			30 Jun 2006			
	Airframe		MSC					O/C			
712322	Thrust Strut Fitting (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		210			29 Jun 2006			
	Airframe		MSC					O/C			
712401	Engine Jury / Alignment Strut (Left) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCP578-1	TY-1958	AFL		29			1539			0
			MOS	TSN:45	7.9			02 May 2023			N/A
	Airframe		MSC					O/C			
712402	Engine Jury / Alignment Strut (Right) - Removal / Installation		HRS		130.8			6050.4			0
	1159SCP578-2	TY-1661	AFL		29			1539			0
			MOS	TSN:104	8			29 Apr 2023			N/A
	Airframe		MSC					O/C			
712403	Thrust and Alignment Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712404	Thrust and Alignment Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-39	192	06 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712407	No. 1 Engine - Tapered Pin Assembly (Upper) - Discard		HRS		6181.2			0			0
	JR2859A	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
712407 (712408)	No. 2 Engine - Tapered Pin Assembly (Upper) - Discard		HRS		6181.2			0			0
	JR2859A	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
712409	No. 1 Engine - Tapered Pin Assembly (Lower) - Discard		HRS		6181.2			0			0
	JR29859A	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
712409 (712410)	No. 2 Engine - Tapered Pin Assembly (Lower) - Discard		HRS		6181.2			0			0
	JR29859A	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
712500	Engines Declared as Task Oriented		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
712501	Pin, L Engine Thrust		HRS		130.8			6050.4			0
	1159BM51250-3	1851	AFL		29			1539			0
			MOS	TSN:2	7.4			18 May 2023			N/A
	Airframe		MSC					O/C			
712502	Pin, R Engine Thrust		HRS		130.8			6050.4			0
	1159BM51250-3	1855	AFL		29			1539			0
			MOS	TSN:2	7.4			18 May 2023			N/A
	Airframe		MSC					O/C			
712503	Forward Engine Mount Thrust Pin (Ndt) (Left) - Special		HRS		130.8			6050.4			0
	Detailed Inspection		AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712504	Forward Engine Mount Thrust Pin (Ndt) (Right) - Special Detailed Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.7	-40	192	07 Apr 2023	28 Feb 2039*	31 Mar 2039	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
712505	Sleeve, Lh Fwd Mount Taper Pin		HRS		6181.2			0			0
	1159BM51251-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
712506	Sleeve, Rh Fwd Mount Taper Pin		HRS		6181.2			0			0
	1159BM51251-3	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
712507	Engine Attach Pins (Left) - Ndt Inspection		HRS		6181.2			0			0
			AFL				10200**		10200		0
			MOS		210			30 Jun 2006			
Airframe											
712508	Engine Attach Pins (Right) - Ndt Inspection		HRS		6181.2			0			0
			AFL				10200**		10200		0
			MOS		210			29 Jun 2006			
Airframe											
717001	No. 1 Engine - Engine Drains Tank Ejector - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	CV41-14	06-052319	MOS		210			30 Jun 2006			
			MSC					O/C			
Engine											
717001 (717002)	No. 2 Engine - Engine Drains Tank Ejector - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	CV41-14	06-0113148	MOS		210			29 Jun 2006			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
717003	No. 1 Engine - Drains Collection Tank - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	BRR18235	SN-UNKNOWN	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
717003 (717004)	No. 2 Engine - Drains Collection Tank - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	BRR18235	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
717005	No. 1 Engine - Element, Motive Flow(EPA)		HRS		6181.2			0			0
	QA07861	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			30 Jun 2006			PAS
			MSC							O/C	
Engine											
717005 (717006)	No. 2 Engine - Element, Motive Flow(EPA)		HRS		6181.2			0			0
	QA07861	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			29 Jun 2006			PAS
			MSC							O/C	
Engine											
717007	No. 1 Engine - Engine Drains System - Detailed Inspection		HRS		597.1		1000	5584.1	6584.1	6634.1	0
			ENC		124			1444			0
			MOS		32.7			06 Apr 2021			
										[HRS: +50/-50]	
Engine											
717007 (717008)	No. 2 Engine - Engine Drains System - Detailed Inspection		HRS		597.1		1000	5584.1	6584.1	6634.1	0
			ENC		124			1444			0
			MOS		32.7			06 Apr 2021			
										[HRS: +50/-50]	
Engine											
717009	No. 1 Engine - Engine Drains Tank Ejector Pump Filter - Clean		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
717009 (717010)	No. 2 Engine - Engine Drains Tank Ejector Pump Filter - Clean		HRS		5725.4			455.8			0
			ENC		1438			130			0
			MOS		191.6			09 Jan 2008			
			MSC					O/C			
Engine											
71EN1	No. 1 Engine		HRS		6181.2			0			0
	BR700-710C4-11	15351	AFL		1568			0			0
			MOS		209.1			25 Jul 2006			
			MSC					E/C			
Airframe											
71EN2	No. 2 Engine		HRS		6181.2			0			0
	BR700-710C4-11	15350	AFL		1568			0			0
			MOS		209.1			25 Jul 2006			
			MSC					E/C			
Airframe											
72 - Engine											
720009	No. 1 Engine - Intermediate Case - Discard		HRS		6181.2			0			0
	BRR22752	00879	ENC		1568		20000	0	20000		0
			MOS		210			30 Jun 2006			
Engine											
720009 (720010)	No. 2 Engine - Intermediate Case - Discard		HRS		6181.2			0			0
	BRR22752	00880	ENC		1568		20000	0	20000		0
			MOS		210			29 Jun 2006			
Engine											
723001	No. 1 Engine - Low-Pressure Compressor (Fan) Module - Removal / Installation		HRS		6181.2			0			0
	FW33927	STDK35433	ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC					O/C			
Engine											
723001 (723002)	No. 2 Engine - Low-Pressure Compressor (Fan) Module - Removal / Installation		HRS		6181.2			0			0
	FW33927	STDK35495	ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723101	No. 1 Engine - Low-Pressure Compressor (Fan) Blades - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
	Engine		[HRS: +50/-50]								
723101 (723102)	No. 2 Engine - Low-Pressure Compressor (Fan) Blades - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
	Engine		[HRS: +50/-50]								
723103	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus Fillers - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			ENC		29			1539			0
			MOS		9.6			11 Mar 2023			
	Engine		[HRS: +50/-50]								
723103 (723104)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus Fillers - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			ENC		29			1539			0
			MOS		9.5			13 Mar 2023			
	Engine		[HRS: +50/-50]								
723107	No. 1 Engine - Lp Compressor Disk Assembly - Discard FW33927		HRS		6181.2			0			0
	STDK35433		ENC		1568		5600	0	5600		0
			MOS		210			30 Jun 2006			
	Engine										
723107 (723108)	No. 2 Engine - Lp Compressor Disk Assembly - Discard FW33927		HRS		6181.2			0			0
	STDK35495		ENC		1568		5600	0	5600		0
			MOS		210			29 Jun 2006			
	Engine										
723109	No. 1 Engine - Low-Pressure Compressor Inlet Cone - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			ENC		29			1539			0
			MOS		9.3			19 Mar 2023			
	Engine		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723109 (723110)	No. 2 Engine - Low-Pressure Compressor Inlet Cone - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			ENC		29			1539			0
			MOS		9.5			13 Mar 2023			
[HRS: +50/-50]											
Engine											
723113	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 1 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32993	MOS		112.2			22 Aug 2014			
Engine											
723113 (723137)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 1 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE31104	MOS		112.2			22 Aug 2014			
Engine											
723114	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 2 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32982	MOS		112.2			22 Aug 2014			
Engine											
723114 (723138)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 2 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32820	MOS		112.2			22 Aug 2014			
Engine											
723115	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 3 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32947	MOS		112.2			22 Aug 2014			
Engine											
723115 (723139)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 3 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32827	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723116	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 4 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33010	MOS		112.2			22 Aug 2014			
Engine											
723116 (723140)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 4 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32810	MOS		112.2			22 Aug 2014			
Engine											
723117	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 5 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33007	MOS		112.2			22 Aug 2014			
Engine											
723117 (723141)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 5 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32765	MOS		112.2			22 Aug 2014			
Engine											
723118	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 6 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32953	MOS		112.2			22 Aug 2014			
Engine											
723118 (723142)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 6 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32817	MOS		112.2			22 Aug 2014			
Engine											
723119	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 7 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33025	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723119 (723143)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 7 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32783	MOS		112.2			22 Aug 2014			
Engine											
723120	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 8 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32954	MOS		112.2			22 Aug 2014			
Engine											
723120 (723144)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 8 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32774	MOS		112.2			22 Aug 2014			
Engine											
723121	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 9 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32985	MOS		112.2			22 Aug 2014			
Engine											
723121 (723145)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 9 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32808	MOS		112.2			22 Aug 2014			
Engine											
723122	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 10 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33013	MOS		112.2			22 Aug 2014			
Engine											
723122 (723146)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 10 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32776	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723123	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 11 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32999	MOS		112.2			22 Aug 2014			
Engine											
723123 (723147)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 11 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32792	MOS		112.2			22 Aug 2014			
Engine											
723124	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 12 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32948	MOS		112.2			22 Aug 2014			
Engine											
723124 (723148)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 12 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32786	MOS		112.2			22 Aug 2014			
Engine											
723125	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 13 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32933	MOS		112.2			22 Aug 2014			
Engine											
723125 (723149)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 13 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32829	MOS		112.2			22 Aug 2014			
Engine											
723126	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 14 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32960	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723126 (723150)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 14 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32816	MOS		112.2			22 Aug 2014			
Engine											
723127	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 15 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32991	MOS		112.2			22 Aug 2014			
Engine											
723127 (723151)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 15 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32787	MOS		112.2			22 Aug 2014			
Engine											
723128	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 16 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33012	MOS		112.2			22 Aug 2014			
Engine											
723128 (723152)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 16 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32805	MOS		112.2			22 Aug 2014			
Engine											
723129	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 17 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32941	MOS		112.2			22 Aug 2014			
Engine											
723129 (723153)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 17 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32800	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723130	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7			3823.5			0
	No. 18 - Removal / Installation		ENC		600		10000	968	10968		0
	FW33513	RGE85112	MOS		112.2			22 Aug 2014			
Engine											
Notes: REFERENCE GAC SAV WORK ORDER SC378115											
723130 (723154)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 18 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32779	MOS		112.2			22 Aug 2014			
Engine											
723131	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 19 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32976	MOS		112.2			22 Aug 2014			
Engine											
723131 (723155)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 19 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32812	MOS		112.2			22 Aug 2014			
Engine											
723132	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 20 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33030	MOS		112.2			22 Aug 2014			
Engine											
723132 (723156)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 20 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32775	MOS		112.2			22 Aug 2014			
Engine											
723133	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 21 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32989	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723133 (723157)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 21 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32833	MOS		112.2			22 Aug 2014			
Engine											
723134	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 22 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32934	MOS		112.2			22 Aug 2014			
Engine											
723134 (723158)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.7	2357.4			3823.8			0
	No. 22 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32834	MOS		112.2			22 Aug 2014			
Engine											
723135	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 23 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32996	MOS		112.2			22 Aug 2014			
Engine											
723135 (723159)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 23 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32789	MOS		112.2			22 Aug 2014			
Engine											
723136	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.7			3823.5			0
	No. 24 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE33033	MOS		112.2			22 Aug 2014			
Engine											
723136 (723160)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS	TSN:4163.4	2357.4			3823.8			0
	No. 24 - Removal / Installation		ENC	TSN:1415	600		10000	968	9553		0
	FW33980	RGE32823	MOS		112.2			22 Aug 2014			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723161	No. 1 Engine - Lp Compressor Front Blade Retaining Ring		HRS		130.8			6050.4			0
	- Detailed Inspection		ENC		29			1539			0
			MOS		9.6			11 Mar 2023			
			MSC							A/R	
Engine											
723161 (723162)	No. 2 Engine - Lp Compressor Front Blade Retaining Ring		HRS		130.8			6050.4			0
	- Detailed Inspection		ENC		29			1539			0
			MOS		9.5			13 Mar 2023			
			MSC							A/R	
Engine											
723165	No. 1 Engine - Front Blade Retaining Ring - Removal /		HRS	TSN:1779.7	130.8			6050.4			0
	Installation		ENC	TSN:444	29			1539			0
	BRR20843	SN-UNKNOWN	MOS	TSN:200	9.6			11 Mar 2023			N/A
			MSC							O/C	
Engine											
723165 (723166)	No. 2 Engine - Front Blade Retaining Ring - Removal /		HRS		130.8			6050.4			0
	Installation		ENC		29			1539			0
	BRR20843	2001607463-3	MOS		9.5			13 Mar 2023			N/A
			MSC							O/C	
Engine											
723181	No. 1 Engine - Low-Pressure Compressor (Fan) Disc -		HRS		6181.2			0			0
	Removal / Installation		ENC		1568			0			0
	FW33927	STDK35433	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
723181 (723182)	No. 2 Engine - Low-Pressure Compressor (Fan) Disc -		HRS		6181.2			0			0
	Removal / Installation		ENC		1568			0			0
	FW33927	STDK35495	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
723201	No. 1 Engine - Fan Outlet Guide Vanes - Detailed		HRS		665.8		2000	5515.4	7515.4	7565.4	0
	Inspection		ENC		150			1418			0
			MOS		45.2			23 Mar 2020			
Engine											

[HRS: +50/-50]

Notes: REMOVED OVERFLY FOR REENROLLMENT PURPOSES, SO 7-26-16

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723201 (723202)	No. 2 Engine - Fan Outlet Guide Vanes - Detailed Inspection		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			ENC		150			1418			0
			MOS		45.2			23 Mar 2020			
			[HRS: +50/-50]								
Engine											
Notes: REMOVED OVERFLY FOR REENROLLMENT PURPOSES, SO 7-26-16											
723203	No. 1 Engine - Engine Section Stators - Detailed Inspection		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			[HRS: +50/-50]								
Engine											
723203 (723204)	No. 2 Engine - Engine Section Stators - Detailed Inspection		HRS		2357.4		4000	3823.8	7823.8	7873.8	0
			ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			[HRS: +50/-50]								
Engine											
723205	No. 1 Engine - Fan Shaft Assembly - Discard		HRS		6181.2			0			0
	BRR23914	CL20311	ENC		1568		25000	0	25000		0
			MOS		210			30 Jun 2006			
Engine											
723205 (723206)	No. 2 Engine - Fan Shaft Assembly - Discard		HRS		6181.2			0			0
	BRR23914	CL20261	ENC		1568		25000	0	25000		0
			MOS		210			29 Jun 2006			
Engine											
723301	No. 1 Engine - Hp Compressor Rotor Disk Assembly (Stages 7-10) - Discard		HRS		6181.2			0			0
	BRR24357	3278	ENC		1568		15000	0	15000		0
			MOS		210			30 Jun 2006			
Engine											
723301 (723302)	No. 2 Engine - Hp Compressor Rotor Disk Assembly (Stages 7-10) - Discard		HRS		6181.2			0			0
	BRR24357	3266	ENC		1568		15000	0	15000		0
			MOS		210			29 Jun 2006			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723303	No. 1 Engine - Hp Compressor Rotor Disk Assembly		HRS		6181.2			0			0
	(Stages 1-6) - Discard		ENC		1568		15000	0	15000		0
	BRR24382	2169	MOS		210			30 Jun 2006			
Engine											
723303 (723304)	No. 2 Engine - Hp Compressor Rotor Disk Assembly		HRS		6181.2			0			0
	(Stages 1-6) - Discard		ENC		1568		15000	0	15000		0
	BRR24382	2172	MOS		210			29 Jun 2006			
Engine											
723401	No. 1 Engine - Fan Track / Cold Stream Duct - Detailed		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	Inspection		ENC		29			1539			0
			MOS		9.3			19 Mar 2023			
[HRS: +50/-50]											
Engine											
723401 (723402)	No. 2 Engine - Fan Track / Cold Stream Duct - Detailed		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	Inspection		ENC		29			1539			0
			MOS		9.5			13 Mar 2023			
[HRS: +50/-50]											
Engine											
Notes: PN: BRR24357 SN: <NONE>.											
723403	No. 1 Engine - Fan Case Kevlar Wrap - Detailed		HRS		665.8		3000	5515.4	8515.4	8565.4	0
	Inspection		ENC		150			1418			0
			MOS		45.4			18 Mar 2020			
[HRS: +50/-50]											
Engine											
Notes: WO FL016294 & 16365											
723403 (723404)	No. 2 Engine - Fan Case Kevlar Wrap - Detailed		HRS		665.8		3000	5515.4	8515.4	8565.4	0
	Inspection		ENC		150			1418			0
			MOS		45.4			18 Mar 2020			
[HRS: +50/-50]											
Engine											
Notes: WO FL016294 & 16365											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723500	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 1 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723500 (723501)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 1 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723502	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 2 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723502 (723503)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 2 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723504	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 3 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723504 (723505)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 3 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723506	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 4 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723506 (723507)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 4 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723508	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 5 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723508 (723509)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 5 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723510	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 6 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723510 (723511)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 6 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723512	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 7 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723512 (723513)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 7 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723514	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 8 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723514 (723515)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 8 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723516	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 9 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723516 (723517)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 9 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
[HRS: +400/-400]											
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723518	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 10 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723518 (723519)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 10 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723520	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 11 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723520 (723521)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 11 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723522	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 12 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723522 (723523)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 12 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723524	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 13 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723524 (723525)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 13 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723526	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 14 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723526 (723527)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 14 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723528	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 15 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723528 (723529)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 15 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723530	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 16 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: <NONE>.											
723530 (723531)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 16 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723532	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 17 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723532 (723533)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 17 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723534	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 18 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723534 (723535)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 18 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723536	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 19 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723536 (723537)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 19 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723538	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 20 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723538 (723539)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 20 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723540	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 21 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											
723540 (723541)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 21 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
Engine			[HRS: +400/-400]								
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723542	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 22 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723542 (723543)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 22 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723544	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 23 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723544 (723545)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 23 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723546	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.7	176.5	4000	3823.5	8000*	8400	0
	No. 24 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											
723546 (723547)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		2357.4	176.2	4000	3823.8	8000*	8400	0
	No. 24 Metco 58 Coating - Refurbishment		ENC		600		3000	968	3968		0
			MOS		112.2			22 Aug 2014			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33980 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723801	No. 1 Engine - Nose Cone Assembly - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	BRR24229	3175765/001	MOS		9.5			12 Mar 2023			N/A
			MSC								
Engine											
723801 (723802)	No. 2 Engine - Nose Cone Assembly - Removal / Installation		HRS	TSN:662.7	130.8			6050.4			0
			ENC	TSN:157	29			1539			0
	BRR24229	20833524359546	MOS	TSN:40	9.5			13 Mar 2023			N/A
			MSC								
Engine											
723805	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus Filler No. 1 - Removal / Installation		HRS		130.8			6050.4			0
			ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49079	MOS		9.6			11 Mar 2023			N/A
Engine											
723805 (723829)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus Filler No. 1 - Removal / Installation		HRS		130.8			6050.4			0
			ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH50040	MOS		9.5			13 Mar 2023			N/A
Engine											
723806	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus Filler No. 2 - Removal / Installation		HRS		130.8			6050.4			0
			ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49031	MOS		9.5			12 Mar 2023			N/A
Engine											
723806 (723830)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus Filler No. 2 - Removal / Installation		HRS	TSN:5124.4	130.8			6050.4			0
			ENC	TSN:1259	29		6300	1539	6580		0
	BRR22626	HLAH76226	MOS	TSN:169	9.5			13 Mar 2023			N/A
Engine											
723807	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus Filler No. 3 - Removal / Installation		HRS		130.8			6050.4			0
			ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49047	MOS		9.5			12 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723807 (723831)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 3 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35206	MOS		9.5			13 Mar 2023			N/A
Engine											
723808	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 4 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49077	MOS		9.5			12 Mar 2023			N/A
Engine											
723808 (723832)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 4 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH48522	MOS		9.5			13 Mar 2023			N/A
Engine											
723809	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 5 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49051	MOS		9.5			12 Mar 2023			N/A
Engine											
723809 (723833)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 5 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH34181	MOS		9.5			13 Mar 2023			N/A
Engine											
723810	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 6 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49029	MOS		9.5			12 Mar 2023			N/A
Engine											
723810 (723834)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 6 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35223	MOS		9.5			13 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723811	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 7 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49024	MOS		9.5			12 Mar 2023			N/A
Engine											
723811 (723835)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 7 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35236	MOS		9.5			13 Mar 2023			N/A
Engine											
723812	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 8 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49046	MOS		9.5			12 Mar 2023			N/A
Engine											
723812 (723836)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 8 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35204	MOS		9.5			13 Mar 2023			N/A
Engine											
723813	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 9 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49086	MOS		9.5			12 Mar 2023			N/A
Engine											
723813 (723837)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 9 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35243	MOS		9.5			13 Mar 2023			N/A
Engine											
723814	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 10 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49043	MOS		9.5			12 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723814 (723838)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 10 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH34182	MOS		9.5			13 Mar 2023			N/A
Engine											
723815	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 11 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49082	MOS		9.5			12 Mar 2023			N/A
Engine											
723815 (723839)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 11 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35248	MOS		9.5			13 Mar 2023			N/A
Engine											
723816	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 12 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49025	MOS		9.5			12 Mar 2023			N/A
Engine											
723816 (723840)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 12 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35281	MOS		9.5			13 Mar 2023			N/A
Engine											
723817	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 13 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49026	MOS		9.5			12 Mar 2023			N/A
Engine											
723817 (723841)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 13 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35227	MOS		9.5			13 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723818	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 14 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49065	MOS		9.5			12 Mar 2023			N/A
Engine											
723818 (723842)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 14 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35230	MOS		9.5			13 Mar 2023			N/A
Engine											
723819	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 15 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49042	MOS		9.5			12 Mar 2023			N/A
Engine											
723819 (723843)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 15 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35205	MOS		9.5			13 Mar 2023			N/A
Engine											
723820	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 16 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49063	MOS		9.5			12 Mar 2023			N/A
Engine											
723820 (723844)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 16 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35228	MOS		9.5			13 Mar 2023			N/A
Engine											
723821	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 17 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49039	MOS		9.5			12 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723821 (723845)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 17 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35209	MOS		9.5			13 Mar 2023			N/A
Engine											
723822	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 18 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49072	MOS		9.5			12 Mar 2023			N/A
Engine											
723822 (723846)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 18 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35234	MOS		9.5			13 Mar 2023			N/A
Engine											
723823	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 19 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49028	MOS		9.5			12 Mar 2023			N/A
Engine											
723823 (723847)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 19 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35229	MOS		9.5			13 Mar 2023			N/A
Engine											
723824	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 20 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49010	MOS		9.5			12 Mar 2023			N/A
Engine											
723824 (723848)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 20 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35226	MOS		9.5			13 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723825	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 21 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH48992	MOS		9.5			12 Mar 2023			N/A
Engine											
723825 (723849)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 21 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35238	MOS		9.5			13 Mar 2023			N/A
Engine											
723826	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 22 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49001	MOS		9.5			12 Mar 2023			N/A
Engine											
723826 (723850)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 22 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35233	MOS		9.5			13 Mar 2023			N/A
Engine											
723827	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 23 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH49004	MOS		9.5			12 Mar 2023			N/A
Engine											
723827 (723851)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 23 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH35246	MOS		9.5			13 Mar 2023			N/A
Engine											
723828	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 24 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH48999	MOS		9.5			12 Mar 2023			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723828 (723852)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		130.8			6050.4			0
	Filler No. 24 - Removal / Installation		ENC	TSN:1539	29		6300	1539	6300		0
	BRR22626	HLAH48553	MOS		9.5			13 Mar 2023			N/A
Engine											
723853	No. 1 Engine - Nose Cone Rotating Fairing - Removal /		HRS		130.8			6050.4			0
	Installation		ENC		29			1539			0
	BRR24368	BA81572	MOS		9.5			12 Mar 2023			N/A
			MSC				O/C				
Engine											
723853 (723854)	No. 2 Engine - Nose Cone Rotating Fairing - Removal /		HRS	TSN:6050.4	130.8			6050.4			0
	Installation		ENC	TSN:1539	29			1539			0
	BRR24368	BA81638	MOS	TSN:200	9.5			13 Mar 2023			N/A
			MSC				O/C				
Engine											
724001	No. 1 Engine - Hp Turbine Rotor Disc, Stage 1 - Discard		HRS		6181.2			0			0
	BRR23952	LDRQA01252	ENC		1568		6200	0	6200		0
			MOS		210			30 Jun 2006			
Engine											
724001 (724002)	No. 2 Engine - Hp Turbine Rotor Disc, Stage 1 - Discard		HRS		6181.2			0			0
	BRR23952	LDRQA01264	ENC		1568		6200	0	6200		0
			MOS		210			29 Jun 2006			
Engine											
724003	No. 1 Engine - Hp Turbine Rotor Disc, Stage 2 - Discard		HRS		6181.2			0			0
	BRR22008	LDRQA01319	ENC		1568		10500	0	10500		0
			MOS		210			30 Jun 2006			
Engine											
724003 (724004)	No. 2 Engine - Hp Turbine Rotor Disc, Stage 2 - Discard		HRS		6181.2			0			0
	BRR22008	LDRQA01311	ENC		1568		10500	0	10500		0
			MOS		210			29 Jun 2006			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
724005	No. 1 Engine - High-Pressure Turbine Stage 1 Rotor		HRS		600.2		1000	5581	6581	6631	0
	Blades - Special Detailed Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724005 (724006)	No. 2 Engine - High-Pressure Turbine Stage 1 Rotor		HRS		600.2		1000	5581	6581	6631	0
	Blades - Special Detailed Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724007	No. 1 Engine - High-Pressure Turbine Nozzle Guide		HRS		600.2		1000	5581	6581	6631	0
	Vaness - Special Detailed Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724007 (724008)	No. 2 Engine - High-Pressure Turbine Nozzle Guide		HRS		600.2		1000	5581	6581	6631	0
	Vaness - Special Detailed Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724009	No. 1 Engine - Combustion Liner - Special Detailed		HRS		600.2		1000	5581	6581	6631	0
	Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724009 (724010)	No. 2 Engine - Combustion Liner - Special Detailed		HRS		600.2		1000	5581	6581	6631	0
	Inspection		ENC		125		500	1443	1943		0
			MOS		33			30 Mar 2021			
	Engine		[HRS: +50/-50]								
724201	No. 1 Engine - Curvic Ring - Discard		HRS		6181.2			0			0
	BRH20340	6397	ENC		1568		15000	0	15000		0
			MOS		210			30 Jun 2006			
	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
724201 (724202)	No. 2 Engine - Curvic Ring - Discard		HRS		6181.2			0			0
	BRR20340	6401	ENC		1568		15000	0	15000		0
			MOS		210				29 Jun 2006		
Engine											
724203	No. 1 Engine - Pipes, Stage 4 AIR		HRS		6181.2			0			0
	BRR23274	SN-UNKNOWN	ENC		1568			0			0
			MOS		210				30 Jun 2006		
Engine											
724203 (724204)	No. 2 Engine - Pipes, Stage 4 AIR		HRS		6181.2			0			0
	BRR23274	SN-UNKNOWN	ENC		1568			0			0
			MOS		210				29 Jun 2006		
Engine											
725101	No. 1 Engine - Lp Turbine Rotor Shaft - Discard		HRS		6181.2			0			0
	BRR19612	SBAN777	ENC		1568		25000	0	25000		0
			MOS		210				30 Jun 2006		
Engine											
725101 (725102)	No. 2 Engine - Lp Turbine Rotor Shaft - Discard		HRS		6181.2			0			0
	BRR19612	SBAN827	ENC		1568		25000	0	25000		0
			MOS		210				29 Jun 2006		
Engine											
725103	No. 1 Engine - Lp Turbine Rotor Disc, Stage 1 - Discard		HRS		6181.2			0			0
	BRR15535	6360	ENC		1568		25000	0	25000		0
			MOS		210				30 Jun 2006		
Engine											
725103 (725104)	No. 2 Engine - Lp Turbine Rotor Disc, Stage 1 - Discard		HRS		6181.2			0			0
	BRR15535	6355	ENC		1568		25000	0	25000		0
			MOS		210				29 Jun 2006		
Engine											
725105	No. 1 Engine - Lp Turbine Rotor Disc, Stage 2 - Discard		HRS		6181.2			0			0
	BRR11896	6362	ENC		1568		25000	0	25000		0
			MOS		210				30 Jun 2006		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725105 (725106)	No. 2 Engine - Lp Turbine Rotor Disc, Stage 2 - Discard		HRS		6181.2			0			0
	BRR11896	6380	ENC		1568		25000	0	25000		0
			MOS		210				29 Jun 2006		
Engine											
725107	No. 1 Engine - No.4 Stubshaft - Discard		HRS		6181.2			0			0
	BRR23080	NSN	ENC		1568		19000	0	19000		0
			MOS		210				30 Jun 2006		
Engine											
725107 (725108)	No. 2 Engine - No.4 Stubshaft - Discard		HRS		6181.2			0			0
	BRR23080	NSN	ENC		1568		19000	0	19000		0
			MOS		210				29 Jun 2006		
Engine											
725109	No. 1 Engine - No.5 Stubshaft		HRS		6181.2			0			0
	BRR40703	855	ENC		1568			0			0
			MOS		210				30 Jun 2006		
Engine											
725109 (725110)	No. 2 Engine - No.5 Stubshaft		HRS		6181.2			0			0
	BRR40703	856	ENC		1568			0			0
			MOS		210				29 Jun 2006		
Engine											
725603	No. 1 Engine - Turbine Exhaust Support Strut Assembly - Inspection / Check		HRS		2622.3			3558.9			0
			ENC		659			909			0
			MOS		118.5				14 Feb 2014		
Engine											
725603 (725604)	No. 2 Engine - Turbine Exhaust Support Strut Assembly - Inspection / Check		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210				29 Jun 2006		
Engine											
726001	No. 1 Engine - Gearbox, Engine Accessory		HRS		6181.2			0			0
	39500226	761	ENC		1568			0			0
			MOS		210				30 Jun 2006		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
726001 (726002)	No. 2 Engine - Gearbox, Engine Accessory		HRS		6181.2			0			0
	39500226	758	ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
726303	No. 1 Engine - Low-Pressure Turbine Reference Tube		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
	Pawl Mechanism Interface and Stirrup - Detailed		ENC		296			1272			0
	Inspection		MOS		65.8			04 Jul 2018			
	Engine		[HRS: +50/-50]								
726303 (726304)	No. 2 Engine - Low-Pressure Turbine Reference Tube		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
	Pawl Mechanism Interface and Stirrup - Detailed		ENC		296			1272			0
	Inspection		MOS		65.8			04 Jul 2018			
	Engine		[HRS: +50/-50]								
726309	No. 1 Engine - Fuel Shut-Off Cable (Stirrup to Elbow) -		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
	Special Detailed Inspection		ENC		296			1272			0
			MOS		65.8			04 Jul 2018			
	Engine		[HRS: +50/-50]								
726309 (726310)	No. 2 Engine - Fuel Shut-Off Cable (Stirrup to Elbow) -		HRS		1245.7		5000	4935.5	9935.5	9985.5	0
	Special Detailed Inspection		ENC		296			1272			0
			MOS		65.8			04 Jul 2018			
	Engine		[HRS: +50/-50]								
727101 (727102)	No. 2 Engine - Bypass Duct Inner Surface - General		HRS		6181.2			0			0
	Visual Inspection		ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
727103	No. 1 Engine - Bypass Duct Inner Surface - General		HRS		665.8		2000	5515.4	7515.4	7565.4	0
	Visual Inspection		ENC		150			1418			0
			MOS		44.9			31 Mar 2020			
	Engine		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
727103 (727104)	No. 2 Engine - Bypass Duct Inner Surface - General		HRS		665.8		2000	5515.4	7515.4	7565.4	0
	Visual Inspection		ENC		150			1418			0
			MOS		44.9			31 Mar 2020			
[HRS: +50/-50]											
Engine											
73 - Engine Fuel and Control											
730470^U	No. 1 Engine - Rolls Royce Tv 170830R1 - Eec Firebox		HRS		665.8		1000**	5515.4	0		0
	Paint Damage Fly-on Allowance		ENC		150			1418	0		0
			MOS		43.1			26 May 2020			
Engine											
730471^U	No. 2 Engine - Rolls Royce Tv 170830R1 - Eec Firebox		HRS		665.8		1000**	5515.4	0		0
	Paint Damage Fly-on Allowance		ENC		150			1418	0		0
			MOS		43.1			26 May 2020			
Engine											
731001	No. 1 Engine - Fuel Pump - Removal / Installation		HRS		6181.2			0			0
	828200-2	1292	ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC				O/C				
Engine											
731001 (731002)	No. 2 Engine - Fuel Pump - Removal / Installation		HRS	TSN:3823.8	2357.4			3823.8			0
	828200-2	1296	ENC	TSN:968	600			968			0
			MOS	TSN:98	112.2			22 Aug 2014			
			MSC				O/C				
Engine											
731005	No. 1 Engine - Fuel Metering Unit - Removal / Installation		HRS		6181.2			0			0
	8061-977	14219714	ENC		1568			0			0
			MOS		210			30 Jun 2006			DILLON -
			MSC				O/C				MORGANS
Engine											
731005 (731006)	No. 2 Engine - Fuel Metering Unit - Removal / Installation		HRS		6181.2			0			0
	8061-977	14696000	ENC		1568			0			0
			MOS		210			29 Jun 2006			DILLON -
			MSC				O/C				MORGANS
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731011	No. 1 Engine - Heated Fuel Return Shut-Off Valve - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	AV24B1441	AA77079	MOS		210			30 Jun 2006			AVTEC INC
			MSC								
Engine											
731011 (731012)	No. 2 Engine - Heated Fuel Return Shut-Off Valve - Removal / Installation		HRS		3245.3			2935.9			0
			ENC		793			775			0
	AV24B1441	AA299703	MOS	TSN:1	133.8			05 Nov 2012			AVTEC INC
			MSC								
Engine											
731019	No. 1 Engine - Fuel Pump Vespel Coupling - Discard		HRS		6181.2		3500	0	7323.5		0
			ENC		1568			0			0
	PN	SN-UNKNOWN	MOS		210			30 Jun 2006			
Engine											
731019 (731020)	No. 2 Engine - Fuel Pump Vespel Coupling - Discard		HRS		6181.2		3500	0	7323.5		0
			ENC		1568			0			0
	PN	SN-UNKNOWN	MOS		210			29 Jun 2006			
Engine											
731021	No. 1 Engine - High Pressure Fuel Filter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	QAO7517	SN-UNKNOWN	MOS		210			30 Jun 2006			
			MSC								
Engine											
731021 (731022)	No. 2 Engine - High Pressure Fuel Filter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	QAO7517	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC								
Engine											
731023	No. 1 Engine - Low-Pressure Fuel Filter - Detailed Inspection		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		32.7			06 Apr 2021			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Engine											

Notes: PN: QA07865 SN: <NONE>.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731023 (731024)	No. 2 Engine - Low-Pressure Fuel Filter - Detailed Inspection		HRS		597.1			5584.1			0
			ENC		124			1444			0
			MOS		32.7			06 Apr 2021			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC							O/C	
Engine											
Notes: PN: QA07865 SN: <NONE>.											
731027	No. 1 Engine - Low-Pressure Fuel Filter - Removal / Installation		HRS		597.1			5584.1			0
			ENC		124			1444			0
	QA07865	NSN	MOS	TSN:5	32.7			06 Apr 2021			N/A
			MSC							O/C	
Engine											
731027 (731028)	No. 2 Engine - Low-Pressure Fuel Filter - Removal / Installation		HRS		597.1			5584.1			0
			ENC		124			1444			0
	QA07865	NSN	MOS	TSN:5	32.7			06 Apr 2021			N/A
			MSC							O/C	
Engine											
731029	No. 1 Engine - Low-Pressure Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8910-210	SN-UNKNOWN	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731029 (731030)	No. 2 Engine - Low-Pressure Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8910-210	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731100	No. 1 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20331	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731100 (731120)	No. 2 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20391	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731101	No. 1 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20332	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731101 (731121)	No. 2 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20392	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731102	No. 1 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20333	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731102 (731122)	No. 2 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20393	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731103	No. 1 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20334	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731103 (731123)	No. 2 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20394	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731104	No. 1 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20335	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731104 (731124)	No. 2 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20395	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731105	No. 1 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20336	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731105 (731125)	No. 2 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20396	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731106	No. 1 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20337	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731106 (731126)	No. 2 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20397	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731107	No. 1 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20338	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731107 (731127)	No. 2 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20398	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731108	No. 1 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20339	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731108 (731128)	No. 2 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20399	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731109	No. 1 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20340	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731109 (731129)	No. 2 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20400	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731110	No. 1 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20341	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731110 (731130)	No. 2 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20401	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731111	No. 1 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20342	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731111 (731131)	No. 2 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20402	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731112	No. 1 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20343	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731112 (731132)	No. 2 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20403	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731113	No. 1 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E11	N20344	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											
731113 (731133)	No. 2 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E11	N20404	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
731114	No. 1 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20345	MOS		210			30 Jun 2006			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731114 (731134)	No. 2 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20405	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731115	No. 1 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20346	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731115 (731135)	No. 2 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20406	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731116	No. 1 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20347	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731116 (731136)	No. 2 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20407	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731117	No. 1 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20348	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731117 (731137)	No. 2 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20409	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731118	No. 1 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20349	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731118 (731138)	No. 2 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20409	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731119	No. 1 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20350	MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
731119 (731139)	No. 2 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	6940426E14	N20410	MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
731141	No. 1 Engine - Drains Tank Ejector Inline Filter - Inspection		HRS		130.8		2000	6050.4	8050.4	8100.4	0
			ENC		29			1539			0
			MOS		8.6			09 Apr 2023			
											[HRS: +50/-50]
Engine											
731141 (731142)	No. 2 Engine - Drains Tank Ejector Inline Filter - Inspection		HRS		130.8		2000	6050.4	8050.4	8100.4	0
			ENC		29			1539			0
			MOS		8.6			09 Apr 2023			
											[HRS: +50/-50]
Engine											
731143	No. 1 Engine - Drains Tank Ejector Filter Element - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	QA07861	RJ4-4554	MOS	TSN:9	8.6			09 Apr 2023			N/A
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731143 (731144)	No. 2 Engine - Drains Tank Ejector Filter Element - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	QA07861	RJ3-6641	MOS	TSN:9	8.6			09 Apr 2023			N/A
			MSC								
Engine											
731201	No. 1 Engine - Engine Fuel Mainfold - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC								
Engine											
731201 (731202)	No. 2 Engine - Engine Fuel Mainfold - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC								
Engine											
731203	No. 1 Engine - Core Fuel Distribution Tubes and Fittings - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC								
Engine											
731203 (731204)	No. 2 Engine - Core Fuel Distribution Tubes and Fittings - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC								
Engine											
731301	No. 1 Engine - Fuel Return to Tank Valve - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8910-312	14742405	MOS		210			30 Jun 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Engine											
731301 (731302)	No. 2 Engine - Fuel Return to Tank Valve - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8910-312	14753987	MOS		210			29 Jun 2006			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731303	No. 1 Engine - Manifold, Splitter / Overspeed		HRS		6181.2			0			0
	8910-214	1721984	ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
731303 (731304)	No. 2 Engine - Manifold, Splitter / Overspeed		HRS		6181.2			0			0
	8910-214	14705094	ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
732001	No. 1 Engine - Engine Electronic Controller - Removal /		HRS	TSN:4589.8	665.8			5515.4			0
	Installation		ENC	TSN:1138	150			1418			0
	EECU3000-02AD	BX970271	MOS		44			28 Apr 2020			N/A
	Engine		MSC					O/C			
Notes: P/N & S/N PHYSICALLY CHECKED ON 8-DEC-2018											
732001 (732002)	No. 2 Engine - Engine Electronic Controller - Removal /		HRS	TSN:4589.8	665.8			5515.4			0
	Installation		ENC	TSN:1138	150			1418			0
	EECU3000-02AD	BX970274	MOS		44			28 Apr 2020			N/A
	Engine		MSC					O/C			
Notes: P/N & S/N PHYSICALLY CHECKED ON 8-DEC-2018											
732103	No. 1 Engine - Dedicated Generator - Removal /		HRS		626.47			5554.73			0
	Installation		ENC		132			1436			0
	514842-1	N15050054	MOS	TSN:27	34.7			08 Feb 2021			
	Engine		MSC					O/C			
732103 (732104)	No. 2 Engine - Dedicated Generator - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	83311-430117	3347	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
732105	No. 1 Engine - T30 Thermocouple (Inboard) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	TC428-01	RRAD0664	MOS		210			30 Jun 2006			GULFSTREAM DALLAS
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732105 (732106)	No. 2 Engine - T30 Thermocouple (Inboard) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC428-01	RRAD0848	MOS		210			29 Jun 2006			GULFSTREAM
			MSC								DALLAS
Engine											
732107	No. 1 Engine - T30 Thermocouple (Outboard) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC428-01	RRAD0845	MOS		210			30 Jun 2006			GULFSTREAM
			MSC								DALLAS
Engine											
732107 (732108)	No. 2 Engine - T30 Thermocouple (Outboard) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC428-01	RRAD0649	MOS		210			29 Jun 2006			GULFSTREAM
			MSC								DALLAS
Engine											
732119	No. 1 Engine - Electronic Engine Controller Close Fitting Box - Detailed Inspection		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			ENC		150			1418			0
			MOS		45.1			25 Mar 2020			
											[HRS: +50/-50]
Engine											
732119 (732120)	No. 2 Engine - Electronic Engine Controller Close Fitting Box - Detailed Inspection		HRS		665.8		2000	5515.4	7515.4	7565.4	0
			ENC		150			1418			0
			MOS		45.1			25 Mar 2020			
											[HRS: +50/-50]
Engine											
Notes: REMOVED OVERFLY FOR REENROLLMENT PURPOSES, SO 7-26-16											
733101	No. 1 Engine - Fuel Flow Transmitter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	9-217-82	235682-47	MOS	TSN:8	202.1			26 Feb 2007			
			MSC								O/C
Engine											
733101 (733102)	No. 2 Engine - Fuel Flow Transmitter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	9-217-82	235682-50	MOS	TSN:8	202.1			26 Feb 2007			
			MSC								O/C
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
733201	No. 1 Engine - Fuel Temperature Transducer, (A Channel)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	1122806	M6510	MOS		210			30 Jun 2006			COVER
	Engine		MSC					O/C			GRAPHICS INC
733201 (733202)	No. 2 Engine - Fuel Temperature Transducer, (A Channel)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	1122806	N0539	MOS		210			29 Jun 2006			COVER
	Engine		MSC					O/C			GRAPHICS INC
733203	No. 1 Engine - Fuel Temperature Transducer, (B Channel)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	1122806	M9459	MOS		210			30 Jun 2006			COVER
	Engine		MSC					O/C			GRAPHICS INC
733203 (733204)	No. 2 Engine - Fuel Temperature Transducer, (B Channel)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	1122806	N0547	MOS		210			29 Jun 2006			COVER
	Engine		MSC					O/C			GRAPHICS INC
733301	No. 1 Engine - Fuel Low Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	21SN04-432	G020129	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
733301 (733302)	No. 2 Engine - Fuel Low Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	21SN04-432	G020127	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
733401	No. 1 Engine - Fuel Differential Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	21SN04-430	G023112	MOS		210			30 Jun 2006			ROLLS- ROYCE
	Engine		MSC					O/C			DEUTSCHLAND LTD. & CO. KG

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
733401 (733402)	No. 2 Engine - Fuel Differential Pressure Switch -		HRS		6181.2			0			0
	Removal / Installation		ENC		1568			0			0
	21SN04-430	G023113	MOS		210			29 Jun 2006			ROLLS- ROYCE
	Engine		MSC					O/C			DEUTSCHLAND LTD. & CO. KG
74 - Ignition											
741001	No. 1 Engine - Ignition Unit (Outboard) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	9060440-2	06203018	MOS		210			30 Jun 2006			UNISON
	Engine		MSC					O/C			INDUSTRIES
741001 (741002)	No. 2 Engine - Ignition Unit (Outboard) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	9060440-2	06151266	MOS		210			29 Jun 2006			UNISON
	Engine		MSC					O/C			INDUSTRIES
741003	No. 1 Engine - Ignition Unit (Inboard) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	9060440-2	06233867	MOS		210			30 Jun 2006			UNISON
	Engine		MSC					O/C			INDUSTRIES
741003 (741004)	No. 2 Engine - Ignition Unit (Inboard) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	9060440-2	06151269	MOS		210			29 Jun 2006			UNISON
	Engine		MSC					O/C			INDUSTRIES
742001	No. 1 Engine - Engine Igniter Plug (No. 1) - Removal /		HRS	TSN:355.1	600.2			5581			0
	Installation		ENC	TSN:102	125			1443			0
	Y242-5	19027817	MOS	TSN:23	33			30 Mar 2021			N/A
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742001 (742002)	No. 2 Engine - Engine Igniter Plug (No. 1) - Removal / Installation		HRS	TSN:1300.6	600.2			5581			0
			ENC	TSN:347	125			1443			0
	Y242-5	15032511	MOS	TSN:67	33			30 Mar 2021			N/A
			MSC							O/C	
Engine											
742003	No. 1 Engine - Engine Igniter Plug (No. 2) - Removal / Installation		HRS	TSN:345.4	600.2			5581			0
			ENC	TSN:101	125			1443			0
	Y242-5	19027815	MOS	TSN:23	33			30 Mar 2021			N/A
			MSC							O/C	
Engine											
742003 (742004)	No. 2 Engine - Engine Igniter Plug (No. 2) - Removal / Installation		HRS	TSN:1300.6	600.2			5581			0
			ENC	TSN:347	125			1443			0
	Y242-5	15019313	MOS	TSN:67	33			30 Mar 2021			N/A
			MSC							O/C	
Engine											
742005	No. 1 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection		HRS		600.2		1000	5581	6581	6631	0
			ENC		125			1443			0
			MOS		33			30 Mar 2021			
											[HRS: +50/-50]
Engine											
Notes: PN: Y242-5 SN: 15014387.											
742005 (742006)	No. 2 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection		HRS		600.2		1000	5581	6581	6631	0
			ENC		125			1443			0
			MOS		33			30 Mar 2021			
											[HRS: +50/-50]
Engine											
Notes: PN: Y242-5 SN: <NONE>.											
742007	No. 1 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection		HRS		600.2		1000	5581	6581	6631	0
			ENC		125			1443			0
			MOS		33			30 Mar 2021			
											[HRS: +50/-50]
Engine											
Notes: PN: Y242-5 SN: 15027840.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742007 (742008)	No. 2 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection		HRS		600.2		1000	5581	6581	6631	0
			ENC		125			1443			0
			MOS		33			30 Mar 2021			
			[HRS: +50/-50]								
Engine											
Notes: PN: Y242-5 SN: <NONE>.											
742011	No. 1 Engine - Ignition Lead (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	430911-1	SN-UNKNOWN	MOS		210			30 Jun 2006			
			MSC				O/C				
Engine											
742011 (742012)	No. 2 Engine - Ignition Lead (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	430911-1	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC				O/C				
Engine											
742013	No. 1 Engine - Ignition Lead (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	430911-1	SN-UNKNOWN	MOS		210			30 Jun 2006			
			MSC				O/C				
Engine											
742013 (742014)	No. 2 Engine - Ignition Lead (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	430911-1	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC				O/C				
Engine											
742023	No. 1 Engine - Ignition System - Operational Check		HRS		600.2			5581			0
			ENC		125			1443			0
			MOS		32.9			31 Mar 2021			
			MSC				O/C				
Engine											
742023 (742024)	No. 2 Engine - Ignition System - Operational Check		HRS		600.2			5581			0
			ENC		125			1443			0
			MOS		32.9			31 Mar 2021			
			MSC				O/C				
Engine											
75 - AIR											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
752001	No. 1 Engine - Buffer AIR Valve - Removal / Installation		HRS		6181.2			0			0
	8910-512	14700295	ENC		1568			0			0
			MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
752001 (752002)	No. 2 Engine - Buffer AIR Valve - Removal / Installation		HRS		6181.2			0			0
	8910-512	14743482	ENC		1568			0			0
			MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
753001	No. 1 Engine - HP5 Bleed Valve (Left, Lower) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMD143	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
753001 (753002)	No. 2 Engine - HP5 Bleed Valve (Left, Lower) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMK230	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
753003	No. 1 Engine - HP5 Bleed Valve (Right, Upper) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMD144	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
753003 (753004)	No. 2 Engine - HP5 Bleed Valve (Right, Upper) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	SN-UNKNOWN	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
753005	No. 1 Engine - HP5 Bleed Valve (Right, Lower) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMD145	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753005 (753006)	No. 2 Engine - HP5 Bleed Valve (Right, Lower) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMK232	MOS		210			29 Jun 2006			
			MSC						O/C		
	Engine										
753007	No. 1 Engine - HP8 Bleed Valve (Left, Upper) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMD146	MOS		210			30 Jun 2006			
			MSC						O/C		
	Engine										
753007 (753008)	No. 2 Engine - HP8 Bleed Valve (Left, Upper) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EB100420D	EMK233	MOS		210			29 Jun 2006			
			MSC						O/C		
	Engine										
753011	No. 1 Engine - Bleed Valve Solenoid Control Block - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EA100118G	EME193	MOS		210			30 Jun 2006			
			MSC						O/C		
	Engine										
753011 (753012)	No. 2 Engine - Bleed Valve Solenoid Control Block - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	EA100118G	EML107	MOS		210			29 Jun 2006			
			MSC						O/C		
	Engine										
753015	No. 1 Engine - Variable Stator Vane Actuator - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8100-115	14721999	MOS		210			30 Jun 2006			
			MSC						O/C		ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine										
753015 (753016)	No. 2 Engine - Variable Stator Vane Actuator - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	8100-115	14735538	MOS		210			29 Jun 2006			
			MSC						O/C		ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753025	No. 1 Engine - Variable Stator Vane Mechanism - Lubrication		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.2			23 Feb 2007			
			MSC							O/C	
Engine											
Notes: N/A DUE SB 72-101414 IS N/A BY ENG S/N											
753025 (753026)	No. 2 Engine - Variable Stator Vane Mechanism - Lubrication		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.2			23 Feb 2007			
			MSC							O/C	
Engine											
Notes: N/A DUE SB 72-101414 IS N/A BY ENG S/N											
76 - Engine Controls											
761001	Throttle Quadrant Assembly - Removal / Installation		HRS		6181.2			0			0
	1159SCF552-5	B0424	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ESTERLINE
			MSC							O/C	MASON
Airframe											
77 - Engine Indicating											
771201	No. 1 Engine - Channel A Hp Speed Probe (No. 1) - Removal / Installation		HRS		6181.2			0			0
	889-1-13	7499	ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
771201 (771202)	No. 2 Engine - Channel A Hp Speed Probe (No. 1) - Removal / Installation		HRS		6181.2			0			0
	889-3-13	7495	ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											
771203	No. 1 Engine - Channel B Hp Speed Probe (No. 2) - Removal / Installation		HRS		6181.2			0			0
	889-1-13	7500	ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771203 (771204)	No. 2 Engine - Channel B Hp Speed Probe (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	889-3-13	7496	MOS		210			29 Jun 2006			
			MSC							O/C	
	Engine										
771205	No. 1 Engine - Shared Hp Speed Probe (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	889-1-13	7501	MOS		210			30 Jun 2006			
			MSC							O/C	
	Engine										
771205 (771206)	No. 2 Engine - Shared Hp Speed Probe (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	889-3-13	7497	MOS		210			29 Jun 2006			
			MSC							O/C	
	Engine										
771207	No. 1 Engine - EVM / Idg Hp Speed Probe (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	889-1-13	7502	MOS		210			30 Jun 2006			
			MSC							O/C	
	Engine										
771207 (771208)	No. 2 Engine - EVM / Idg Hp Speed Probe (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	889-3-13	7498	MOS		210			29 Jun 2006			
			MSC							O/C	
	Engine										
772001	No. 1 Engine - Engine Turbine Overheat Thermocouple and Support Tube - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	920-4-14	2327	MOS		210			30 Jun 2006			AIRSHOW INC.
			MSC							O/C	
	Engine										
772001 (772002)	No. 2 Engine - Engine Turbine Overheat Thermocouple and Support Tube - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	920-4-14	2329	MOS		210			29 Jun 2006			AIRSHOW INC.
			MSC							O/C	
	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772003	No. 1 Engine - Thermocouple, #2 Turbine O/H		HRS		6181.2			0			0
	920-4-14	2328	ENC		1568			0			0
			MOS		210			30 Jun 2006			AIRSHOW INC.
	Engine		MSC					O/C			
772003 (772004)	No. 2 Engine - Thermocouple, #2 Turbine O/H		HRS		6181.2			0			0
	920-4-14	2330	ENC		1568			0			0
			MOS		210			29 Jun 2006			AIRSHOW INC.
	Engine		MSC					O/C			
772011	No. 1 Engine - Tgt Thermocouple (No. 1) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	TC429-01	RRAE00401	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772011 (772012)	No. 2 Engine - Tgt Thermocouple (No. 1) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	TC429-01	RRAE00104	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772013	No. 1 Engine - Tgt Thermocouple (No. 2) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	TC429-01	RRAE00403	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772013 (772014)	No. 2 Engine - Tgt Thermocouple (No. 2) - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	TC429-01	RRAE00400	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772015	No. 1 Engine - Tgt Thermocouple (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00422	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772015 (772016)	No. 2 Engine - Tgt Thermocouple (No. 3) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00405	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772017	No. 1 Engine - Tgt Thermocouple (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00437	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772017 (772018)	No. 2 Engine - Tgt Thermocouple (No. 4) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00406	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772019	No. 1 Engine - Tgt Thermocouple (No. 5) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00504	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772019 (772020)	No. 2 Engine - Tgt Thermocouple (No. 5) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00418	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772021	No. 1 Engine - Tgt Thermocouple (No. 6) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00508	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772021 (772022)	No. 2 Engine - Tgt Thermocouple (No. 6) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00505	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772023	No. 1 Engine - Tgt Thermocouple (No. 7) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00519	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772023 (772024)	No. 2 Engine - Tgt Thermocouple (No. 7) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	TC429-01	RRAE00509	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
773001	Engine Vibration Monitor Unit - Removal / Installation		HRS		1821.6			4359.6			0
	241-265-000-011	AB34847	AFL		433			1135			0
			MOS		86.7			07 Oct 2016			VIBRO-METER SA
	Airframe		MSC					O/C			
773005	No. 1 Engine - Engine Forward Vibration Tranducer - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	144-151-000-301	AB84954	MOS		210			30 Jun 2006			GULFSTREAM SAV PROD-IPT
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
773005 (773006)	No. 2 Engine - Engine Forward Vibration Transducer - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	144-151-000-301	AB84956	MOS		210			29 Jun 2006			GULFSTREAM
	Engine		MSC				O/C				SAV PROD-IPT
773007	No. 1 Engine - Engine Aft Vibration Transducer - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	144-151-000-301	AB84956	MOS		210			30 Jun 2006			GULFSTREAM
	Engine		MSC				O/C				SAV PROD-IPT
773007 (773008)	No. 2 Engine - Engine Aft Vibration Transducer - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	144-151-000-301	AB84957	MOS		210			29 Jun 2006			GULFSTREAM
	Engine		MSC				O/C				SAV PROD-IPT
773101	Engine Vibration Monitor System - Operational Test		HRS		1821.6			4359.6			0
			AFL		433			1135			0
			MOS		86.7			07 Oct 2016			
	Airframe		MSC				O/C				
78 - Exhaust											
780005	Thrust Reverser and Exhaust (Left) - Zonal Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe						[HRS: +50/-50]				
780006	Thrust Reverser and Exhaust (Right) - Zonal Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe						[HRS: +50/-50]				
780007	Thrust Reverser (Left) - Inspection / Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
780008	Thrust Reverser (Right) - Inspection / Check		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
780009	Thrust Reverser (Left) - Bleed Procedure		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
780010	Thrust Reverser (Right) - Bleed Procedure		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
781101	No. 1 Engine - Exhaust Nozzle - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
781101^U	Exhaust Nozzle (Left) - Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		MSC					O/C			
781101 (781102)	No. 2 Engine - Exhaust Nozzle - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
781102^U	Exhaust Nozzle (Right) - Visual Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		MSC					O/C			
781103	No. 1 Engine - Exhaust Cone Assembly - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
781103^U	Exhaust Cone Assembly (Left) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		MSC					O/C			
781103 (781104)	No. 2 Engine - Exhaust Cone Assembly - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
781104^U	Exhaust Cone Assembly (Right) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		MSC					O/C			
781111	No. 1 Engine - Exhaust Cone Assembly - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	PN	SN-UNKNOWN	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
781111 (781112)	No. 2 Engine - Exhaust Cone Assembly - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	PN	SN-UNKNOWN	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
783001	Engine Thrust Reverser (Left) - Removal / Installation		HRS		3521.5			2659.7			0
	25G0001-001	LH250	AFL		865			703			0
			MOS		140.7			07 Apr 2012			
	Airframe		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
783002	Engine Thrust Reverser (Right) - Removal / Installation		HRS		6181.2			0			0
	25G0001-003	RH247	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			GULFSTREAM - LONG BEACH

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783003	T/Rev Pivot Door Deflector Plates / Fixed Structure		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	Discharge Fairing (Left) - General Visual Inspection		AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
783004	T/Rev Pivot Door Deflector Plates / Fixed Structure		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	Discharge Fairing (Right) - General Visual Inspection		AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
783005	Thrust Reverser Manual Restow System (Left) -		HRS		130.8			6050.4			0
	Operational Test		AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC				O/C				
783006	Thrust Reverser Manual Restow System (Right) -		HRS		130.8			6050.4			0
	Operational Test		AFL		29			1539			0
			MOS		6.9			02 Jun 2023			
	Airframe		MSC				O/C				
783007	Thrust Reverser (Left) - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC				O/C				
783008	Thrust Reverser (Right) - Operational Check		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
	Airframe		MSC				O/C				
783009	Thrust Reverser Front Face Torsion Box Front Frame		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	(Left) - Detailed Inspection		AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783010	Thrust Reverser Front Face Torsion Box Front Frame (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
783013	Thrust Reverser Ground Relay (Left) - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	60	36	02 Jul 2021	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
783014	Thrust Reverser Ground Relay (Right) - Operational Test		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		29.9	60	36	02 Jul 2021	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
783040	Thrust Reverser / Exhaust Flow Path Surface (Left) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
783041	Thrust Reverser / Exhaust Flow Path Surface (Right) - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
	Airframe		[HRS: +50/-50]								
783101	Thrust Reverser Upper Pivoting Door (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	04G2037-003	UL-1235	MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								
783102	Thrust Reverser Upper Pivoting Door (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	04G2037-004	UR1236	MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783103	Thrust Reverser Lower Pivoting Door (Left) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
			AFL	TSN:1539	29			1539			0
	25G2039-001	LL-1127	MOS	TSN:201	7			30 May 2023			N/A
			MSC							O/C	
Airframe											
783104	Thrust Reverser Lower Pivoting Door (Right) - Removal / Installation		HRS	TSN:6050.4	130.8			6050.4			0
			AFL	TSN:1539	29			1539			0
	25G2039-002	LR1128	MOS	TSN:201	7			30 May 2023			N/A
			MSC							O/C	
Airframe											
783105	Upper Thrust Reverser Door (Left) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783106	Upper Thrust Reverser Door (Right) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783107	Lower Thrust Reverser Door (Left) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783108	Lower Thrust Reverser Door (Right) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783109	Thrust Reverser Pivoting Doors (Left) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
			MSC							O/C	
Airframe											
783110	Thrust Reverser Pivoting Doors (Right) - Inspection		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		8.6			10 Apr 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783111	Primary Door Actuator ROD End (Left) - Detailed Inspection		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.4		72	16 Mar 2021	16 Mar 2027	16 Apr 2027	
	Airframe		[MOS: +1m/-1m]								
783112	Primary Door Actuator ROD End (Right) - Detailed Inspection		HRS		609.87			5571.33			0
			AFL		126			1442			0
			MOS		33.4		72	16 Mar 2021	16 Mar 2027	16 Apr 2027	
	Airframe		[MOS: +1m/-1m]								
783115	Thrust Reverser Deactivate / Activate (Left) - Procedure		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7			30 May 2023			
	Airframe		MSC O/C								
Notes: PN: 04C0001-020 SN: <NONE>											
783116	Thrust Reverser Deactivate / Activate (Right) - Procedure		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7			30 May 2023			
	Airframe		MSC O/C								
783130	Fan Duct Outer Skin (Left) - General Visual Inspection		HRS		6181.2		4000	0	6584.1	6634.1	0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		[HRS: +50/-50]								
783131	Fan Duct Outer Skin (Right) - General Visual Inspection		HRS		6181.2		4000	0	6584.1	6634.1	0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		[HRS: +50/-50]								
783301	T/Rev Isolation Control Unit (Left) - Removal / Installation		HRS		6181.2			0			0
	P463A0001-07		AFL		1568			0			0
	DAW692-06		MOS		208.3			21 Aug 2006			
	Airframe		MSC O/C ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783302	T/Rev Isolation Control Unit (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P463A0001-07	DAW691-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783303	T/Rev Direction Control Unit (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P464A 0001-01	DAW 673-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783304	T/Rev Direction Control Unit (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P464A0001-01	DAW 672-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
783305	Upper Door Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P471A0001-01	DAW2086-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											
783306	Upper Door Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P471A0001-01	DAW2031-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											
783307	Lower Door Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P471A0001-01	DAW2087-06	MOS		208.3			21 Aug 2006			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783308	Lower Door Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	P471A0001-01	DAW2030-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783309	Outer T/Rev Primary Lock Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
	P466A0001-02	DAW 2368-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783310	Outer T/Rev Primary Lock Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
	P466A0001-02	DAW 2367-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783311	Upper Thrust Reverser Tertiary Lock (Left) - Removal / Installation		HRS		6181.2			0			0
	P516A 0001-00	DAW 2287-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783312	Upper Thrust Reverser Tertiary Lock (Right) - Removal / Installation		HRS		6181.2			0			0
	P516A 0001-00	DAW 2281-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783313	Lower Thrust Reverser Tertiary Lock (Left) - Removal / Installation		HRS		6181.2			0			0
	P516A0001-00	DAW 2288-06	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783314	Lower Thrust Reverser Tertiary Lock (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P516A 0001-00	DAW2282-06	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783315	Upper Tertiary Lock (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
783316	Upper Tertiary Lock (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
783317	Inboard T/Rev Primary Lock Actuator (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P466A0001-02	DAW 23620-06	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783318	Inboard T/Rev Primary Lock Actuator (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	P466A0001-02	DAW 2361-06	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783319	Isolation Control Unit (Left) - Servicing		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
783320	Isolation Control Unit (Right) - Servicing		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783321	Inner Primary Lock S-Hook (Left) - Removal / Installation		HRS		6181.2			0			0
	04G0421-055	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783322	Inner Primary Lock S-Hook (Right) - Removal / Installation		HRS		6181.2			0			0
	04G0421-055	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783323	Outer Primary Lock S-Hook (Left) - Removal / Installation		HRS		6181.2			0			0
	04G0421-055	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783324	Outer Primary Lock S-Hook (Right) - Removal / Installation		HRS		6181.2			0			0
	04G0421-055	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783325	Thrust Reverser Upper Tertiary Lock (Left) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783326	Thrust Reverser Upper Tertiary Lock (Right) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783327	Thrust Reverser Lower Tertiary Lock (Left) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783328	Thrust Reverser Lower Tertiary Lock (Right) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC					O/C			
Airframe											
783401	Upper Inboard Door Stow Switch (Left) - Removal / Installation		HRS		1284.7			4896.5			0
			AFL		306			1262			0
	T7013-3	1141	MOS		67.6			09 May 2018			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783402	Upper Inboard Door Stow Switch (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	T7013	S/N 1894	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783403	Upper Outboard Door Stow Switch (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	T7013	S/N1883	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783404	Upper Outboard Door Stow Switch (Right) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	T7013	S/N1859	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783405	Lower Inboard Door Stow Switch (Left) - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	T7013	S/N1903	MOS		208.3			21 Aug 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783406	Lower Inboard Door Stow Switch (Right) - Removal / Installation		HRS		4100.8			2080.4			0
			AFL		994			574			0
	T7013	2283	MOS		153.4			18 Mar 2011			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Airframe											
783407	Lower Outboard Door Stow Switch (Left) - Removal / Installation		HRS	TSN:2080.4	4100.8			2080.4			0
			AFL	TSN:574	994			574			0
	T7013	1902	MOS	TSN:55	153.4			18 Mar 2011			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Airframe											
783408	Lower Outboard Door Stow Switch (Right) - Removal / Installation		HRS	TSN:2080.4	4100.8			2080.4			0
			AFL	TSN:574	994			574			0
	T7013	1901	MOS	TSN:55	153.4			18 Mar 2011			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Airframe											
783409	Door Position Sensor (Left Upper) - Removal / Installation		HRS		6181.2			0			0
	133 F 025 005	A100717	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
783410	Door Position Sensor (Right Upper) - Removal / Installation		HRS		4355.3			1825.9			0
			AFL		1047			521			0
	133 F 025 005	A100852	MOS		157.8			05 Nov 2010			
			MSC								
Airframe											
783411	Door Position Sensor (Left Lower) - Removal / Installation		HRS		6181.2			0			0
	133 F 025 005	A100718	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
783412	Door Position Sensor (Right Lower) - Removal / Installation		HRS	TSN:1825.9	4355.3			1825.9			0
			AFL	TSN:521	1047			521			0
	133 F 025 005	A100716	MOS	TSN:51	157.8			04 Nov 2010			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783413	Thrust Reverser Test Switch (Left) - Removal / Installation		HRS		6181.2			0			0
	101TL2834-6	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			JERRY PAIR
	Airframe		MSC					O/C			
783414	Thrust Reverser Test Switch (Right) - Removal / Installation		HRS		6181.2			0			0
	101TL2834-6	SN-UNKNOWN	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			JERRY PAIR
	Airframe		MSC					O/C			
783415	Door Position Sensor (Left Upper) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783416	Door Position Sensor (Right Upper) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783417	Door Position Sensor (Left Lower) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
783418	Door Position Sensor (Right Lower) - Adjustment / Test		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
	Airframe		MSC					O/C			
79 - Oil											
790001	Oil Servicing Reservoir - Removal / Installation		HRS		6181.2			0			0
	1159SCP565-3	0224	AFL		1568			0			0
			MOS		208.3			21 Aug 2006			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	MSC							Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790002	Engine and APU Oil Servicing Pump - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1B5-17	5BB44	MOS		208.3			21 Aug 2006			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
790004	Oil Replenishing System Selector Valve - Removal / Installation		HRS		6181.2			0			0
			AFL		1568			0			0
	1159SCP105-1	0392	MOS		208.3			21 Aug 2006			CHASE WALTON ELASTOMERS
			MSC					O/C			
Airframe											
790011	No. 1 Engine - Magnetic Chip Detectors - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
			[HRS: +50/-50]								
Engine											
790011 (790012)	No. 2 Engine - Magnetic Chip Detectors - Detailed Inspection		HRS		130.8	33.7	500	6050.4	6584.1*	6634.1	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
			[HRS: +50/-50]								
Engine											
790015	No. 1 Engine - Engine Fwd Bearing Chamber Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	11063	MOS		8.7			08 Apr 2023			N/A
			MSC					O/C			
Engine											
790015 (790016)	No. 2 Engine - Engine Fwd Bearing Chamber Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	11056	MOS		8.6			09 Apr 2023			N/A
			MSC					O/C			
Engine											
790017	No. 1 Engine - Engine Aft Bearing Chamber Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	11053	MOS		8.6			09 Apr 2023			N/A
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790017 (790018)	No. 2 Engine - Engine Aft Bearing Chamber Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	11059	MOS		8.6			09 Apr 2023			N/A
			MSC							O/C	
Engine											
790019	No. 1 Engine - Engine Accessory Gearbox Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	11065	MOS		8.6			09 Apr 2023			N/A
			MSC							O/C	
Engine											
790019 (790020)	No. 2 Engine - Engine Accessory Gearbox Magnetic Chip Detector - Removal / Installation		HRS		130.8			6050.4			0
			ENC		29			1539			0
	VA3510-1	15162	MOS		8.6			09 Apr 2023			N/A
			MSC							O/C	
Engine											
791101	Engine Oil Tank Sight Gage / Remote Oil Panel (Left) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
791102	Engine Oil Tank Sight Gage / Remote Oil Panel (Right) - Inspection		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC							O/C	
Airframe											
792005	No. 1 Engine - Engine Oil Pump - Removal / Installation		HRS		6181.2			0			0
	LR47000C	C0184	ENC		1568			0			0
			MOS		210			30 Jun 2006			
			MSC							O/C	
Engine											
792005 (792006)	No. 2 Engine - Engine Oil Pump - Removal / Installation		HRS		6181.2			0			0
	LR47000C	C0180	ENC		1568			0			0
			MOS		210			29 Jun 2006			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792101	No. 1 Engine - Oil Pressure Filter - Detailed Inspection		HRS		597.1		1000	5584.1	6584.1	6634.1	0
			ENC		124			1444			0
			MOS		32.6		48	09 Apr 2021	30 Apr 2025	31 May 2025	
Engine		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Notes: PN: QA07520 SN: <NONE>.											
792101 (792102)	No. 2 Engine - Oil Pressure Filter - Detailed Inspection		HRS		597.1		1000	5584.1	6584.1	6634.1	0
			ENC		124			1444			0
			MOS		32.6		48	09 Apr 2021	30 Apr 2025	31 May 2025	
Engine		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Notes: PN: QA07520 SN: <NONE>.											
792103	No. 1 Engine - Core Oil Tubes and Fittings - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
Engine		MSC O/C									
792103 (792104)	No. 2 Engine - Core Oil Tubes and Fittings - Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
Engine		MSC O/C									
792105	No. 1 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		597.1			5584.1			0
	QA08196 NSN		ENC		124			1444			0
			MOS	TSN:3	32.6			09 Apr 2021			N/A
Engine		MSC O/C									
792105 (792106)	No. 2 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		597.1			5584.1			0
	QA08196 NSN		ENC		124			1444			0
			MOS	TSN:3	32.6			09 Apr 2021			N/A
Engine		MSC O/C									
792107	No. 1 Engine - Engine Scavange Strainers - Detailed Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
(792108)		MSC O/C									
Engine											
Notes: PN: BRR20974 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792107 (792108)	No. 2 Engine - Engine Scavange Strainers - Detailed Inspection		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			29 Jun 2006			
	(792108) Engine		MSC					O/C			
Notes: PN: BRR20974 SN: <NONE>.											
792201	No. 1 Engine - Engine Fuel Cooled Oil Cooler - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	55006001-31	55006-1147	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
792201 (792202)	No. 2 Engine - Engine Fuel Cooled Oil Cooler - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	55006001-31	55006-1131	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
792205	No. 1 Engine - Va/ACT AIR Cooled Oil Cool		HRS		6181.2			0			0
	4502004-4	SN-UNKNOWN	ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
792205 (792206)	No. 2 Engine - Va/ACT AIR Cooled Oil Cool		HRS		6181.2			0			0
			ENC		1568			0			0
	4502004-4	SN-UNKNOWN	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			
793001	No. 1 Engine - Oil Filter Differential Pressure Indicator - Detailed Inspection		HRS		130.8	-35	500	6050.4	6515.4*	6565.4	0
			ENC		29			1539			0
			MOS		8.7			07 Apr 2023			
	Engine							[HRS: +50/-50]			
Notes: PN: QA07508 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MM Ref	Ops Number(s)							Manufacturer
											Date Type
	793001 (793002)	No. 2 Engine - Oil Filter Differential Pressure Indicator - Detailed Inspection									
			ENC		29			1539			0
			MOS		8.6			09 Apr 2023			
	Engine										
	Notes: PN: QA07508 SN: <NONE>.										
793003	No. 1 Engine - Engine Oil Filter Differential Pressure POP-Up Indicator - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	QA07508	RQ6-2154	MOS		210			30 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
793003 (793004)	No. 2 Engine - Engine Oil Filter Differential Pressure POP-Up Indicator - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	QA07508	RQ4-5546	MOS		210			29 Jun 2006			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
793005	No. 1 Engine - Oil Differential Pressure Transducer (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	PDCR300164001M1	2355114	MOS		210			30 Jun 2006			CAPPLUGS LLC.
	Engine		MSC					O/C			
793005 (793006)	No. 2 Engine - Oil Differential Pressure Transducer (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	PDCR300164001M1	2355125	MOS		210			29 Jun 2006			CAPPLUGS LLC.
	Engine		MSC					O/C			
793009	No. 1 Engine - Engine Oil Quantity Transmitter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	029-910-001	SN-UNKNOWN	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793009 (793010)	No. 2 Engine - Engine Oil Quantity Transmitter - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	029-910-001	SN-UNKNOWN	MOS		210			29 Jun 2006			
			MSC						O/C		
Engine											
793011	No. 1 Engine - Oil Temperature Transducer (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	1122806	N1154	MOS		210			30 Jun 2006			COVER
			MSC						O/C		GRAPHICS INC
Engine											
793011 (793012)	No. 2 Engine - Oil Temperature Transducer (No. 1) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	1122806	M6508	MOS		210			29 Jun 2006			COVER
			MSC						O/C		GRAPHICS INC
Engine											
793015	No. 1 Engine - Oil Filter Differential Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	21SN04-472	G025981	MOS		210			30 Jun 2006			EATON
			MSC						O/C		AEROSPACE/EN GINEERED SENSORS LLC
Engine											
Notes: N/A BY P/N INSTALLED											
793015 (793016)	No. 2 Engine - Oil Filter Differential Pressure Switch - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	21SN04-472	G020213	MOS		210			29 Jun 2006			EATON
			MSC						O/C		AEROSPACE/EN GINEERED SENSORS LLC
Engine											
Notes: N/A BY P/N INSTALLED											
793017	No. 1 Engine - Oil Temperature Transducer (No. 2) - Removal / Installation		HRS		6181.2			0			0
			ENC		1568			0			0
	1122806	N1162	MOS		210			30 Jun 2006			COVER
			MSC						O/C		GRAPHICS INC
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793017 (793018)	No. 2 Engine - Oil Temperature Transducer (No. 2) -		HRS		6181.2			0			0
	Removal / Installation		ENC		1568			0			0
	1122806	M6511	MOS		210			29 Jun 2006			COVER
	Engine		MSC					O/C			GRAPHICS INC
793019	No. 1 Engine - Oil Differential Pressure Transducer (No. 2)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	PDCR300164001M1	2355116	MOS		210			30 Jun 2006			CAPPLUGS LLC.
	Engine		MSC					O/C			
793019 (793020)	No. 2 Engine - Oil Differential Pressure Transducer (No. 2)		HRS		6181.2			0			0
	- Removal / Installation		ENC		1568			0			0
	PDCR300164001M1	2355135	MOS		210			29 Jun 2006			CAPPLUGS LLC.
	Engine		MSC					O/C			
80 - Starting											
801001	No. 1 Engine - AIR Turbine Starter - Removal / Installation		HRS	TSN:2584.2	5725.3			455.9			0
	3505934-8	019-294CD	ENC	TSN:939	1438			130			0
	Engine		MOS		191.3			21 Jan 2008			COMPONENT
			MSC					O/C			SOURCE INC.
801001 (801002)	No. 2 Engine - AIR Turbine Starter - Removal / Installation		HRS		6181.2			0			0
	3505934-8		ENC		1568			0			0
		0606-1713	MOS		210			29 Jun 2006			COMPONENT
	Engine		MSC					O/C			SOURCE INC.
801003	No. 1 Engine - Starter Qad Adapter - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	3504760-2	SN-UNKNOWN	MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
801003 (801004)	No. 2 Engine - Starter Qad Adapter - Removal /		HRS		6181.2			0			0
	Installation		ENC		1568			0			0
	3504760-2	SN-UNKNOWN	MOS		210			29 Jun 2006			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
801005	No. 1 Engine - Starter AIR Valve - Removal / Installation		HRS		6181.2			0			0
	3291182-4	0406-1857	ENC		1568			0			0
			MOS		210			30 Jun 2006			HONEYWELL-ENGINEERING SYSTEMS & SERV.
	Engine		MSC					O/C			
801005 (801006)	No. 2 Engine - Starter AIR Valve - Removal / Installation		HRS		6181.2			0			0
	3291182-4	0606-1895	ENC		1568			0			0
			MOS		210			29 Jun 2006			HONEYWELL-ENGINEERING SYSTEMS & SERV.
	Engine		MSC					O/C			
801007	No. 1 Engine - Starter Oil Level - Detailed Inspection		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		6.8			03 Jun 2023			
	Engine		MSC					O/C			
801007 (801008)	No. 2 Engine - Starter Oil Level - Detailed Inspection		HRS		130.8			6050.4			0
			ENC		29			1539			0
			MOS		8.6			09 Apr 2023			
	Engine		MSC					O/C			
801009	No. 1 Engine - AIR Turbine Starter Oil - Change		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		210			30 Jun 2006			
	Engine		MSC					O/C			
801009 (801010)	No. 2 Engine - AIR Turbine Starter Oil - Change		HRS		5725.4			455.8			0
			ENC		1438			130			0
			MOS		191.6			09 Jan 2008			
	Engine		MSC					O/C			
801011	No. 1 Engine - AIR Turbine Starter Magnetic Chip Collector - Detailed Inspection		HRS		130.8		1000	6050.4	7050.4	7100.4	0
			ENC		29			1539			0
			MOS		8.7		48	07 Apr 2023	30 Apr 2027	31 May 2027	
	Engine							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

801011 (801012)	No. 2 Engine - AIR Turbine Starter Magnetic Chip		HRS		130.8		1000	6050.4	7050.4	7100.4	0
	Collector - Detailed Inspection		ENC		29			1539			0
			MOS		8.6		48	09 Apr 2023	30 Apr 2027	31 May 2027	

[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]

Engine

92 - -

920010^U	A/V Distribution Ctrl		HRS		6173.3			7.9			0
	2023-1-1	206370226	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920011^U	Switch Panel, Bbml		HRS		6173.3			7.9			0
	GC543700000-257G	12201	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920012^U	Data Port W/Cover, Bbml #2		HRS		6173.3			7.9			0
	106084-1	1361006	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920013^U	Data Port W/Cover, Bbml #3		HRS		6173.3			7.9			0
	106084-1	1381006	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920014^U	Coffee Maker RAIL Assembly		HRS		6173.3			7.9			0
	416-0201-27	243162701	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920015^U	Ir/RF Remote		HRS		6173.3			7.9			0
	2033-1-1	206400153	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			
920016^U	Light Kit #3		HRS		6173.3			7.9			0
	5620-10	276	AFL		1562			6			0
			MOS		203.7			08 Jan 2007			
	Airframe		MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
920020^U	GSL505510021 "Allowable Damage – Rebate Flange and Closure Bean, Horizontal Stabilizer"		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			20 May 2020			
			MSC								
Airframe											
920021^U	Gael 20-04-C.Rcd Cabin Entertainment System (MOD)		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		43.3			20 May 2020			
			MSC								
Airframe											
CS 26.370^U	Cs 26.370 - Continuing Airworthiness Tasks and Aircraft Maintenance Programme — Operators and Organisations Responsible for Maintenance Programmes for Large Aeroplanes Under Part-M		HRS								0
			AFL								0
			DATE				16000**		16000		
			MSC								
Airframe											
99 - Airworthiness Directives											
991618^U	AD 2006-16-18 R1 Sandel Model ST3400 TAWS/Rmi Units		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		208.3			21 Aug 2006			
			MSC								
Airframe											
Notes: N/A due equipment not installed											
AD - Airworthiness Directives											
991619^U	FAA AD 2022-24-06		HRS								0
			AFL								0
			MOS								
			MSC							INF	
Airframe											
992013-25^U	Cf-2013-25 Honeywell Asca Inc. – Battery Wiring Installation Discrepancies		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
Airframe [End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
992014-0019^U	EASA 2014-0019 Equipment / Furnishings – Crash		HRS		651.02			5530.18			0
	Position Indicator – Modification Ircaft Flight Manual –		AFL		143			1425			0
	Amendment		MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								
992014-0088^U	EASA 2014-0088 Team (Trading as Cobham Avionics) –		HRS		651.02			5530.18			0
	Cockpit Voice Recorder – Replacement		AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								
992014-0095R1^U	EASA 2014-0095 Hr Smith (Technical Developments) –		HRS		651.02			5530.18			0
	Crash Position Indicator – Modification Aircraft Flight		AFL		143			1425			0
	Manual – Amendment		MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								
992014-0125^U	EASA 2014-0125 Hr Smith (Technical Developments) –		HRS		651.02			5530.18			0
	Crash Position Indicator System – Replacement; Aircraft		AFL		143			1425			0
	Flight Manual – Amendment		MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								
992014-0187^U	EASA 2014-0187 Geven S.P.A. – Safety Belt Attachment		HRS		651.02			5530.18			0
	Bolts – Inspection / Replacement		AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								
992014-0279^U	EASA 2014-0279 Romtex Anjou Aeronautique – Restraint		HRS		651.02			5530.18			0
	System Rotary Buckle Sub-Assembly		AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
992015-0093 ^U	EASA 2015-0093 Northrop Grumman Litef Gmbh – Attitude Heading Reference System		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
992015-10-51 ^U	FAA 2015-10-51 Avidyne Corporation - Airplane Flight Manual (Supplement) - Amendment		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
992016-0026 ^U	EASA 2016-0026 Heinrich Mertens – Emergency Parachute Rubber Bands – Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
992016-0042 ^U	EASA 2016-0042-E ATA 25 – Equipment / Furnishings – Emergency Parachute Harness – Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
992016-0062 ^U	EASA 2016-0062 Spekon Sächsische Spezialkonfektionen Gmbh – Emergency Parachute Harness – Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
993000 ^U	FAA AD 2009-26-12		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										
993001 ^U	EASA AD 2009-0100		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
993002^U Airframe	EASA AD 2007-0294		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
EASA 2005-0001 (992550) Airframe	EASA AD 2005-0001 Indicating/Warning System - Operating Procedures and Flight Manual		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		227.5			13 Jan 2005			
			MSC					-			
Notes: N/A - CW CERT D											
EASA 2007-0156 (992751) Airframe	EASA AD 2007-0156 - Comm Units & Transponders - Modification / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
EASA 2008-0097 (992851) Airframe	EASA AD 2008-0097 - Passenger Seats - Inspection / Repair / Modification		HRS		5043.2			1138			0
			AFL		1222			346			0
			MOS		173.9			01 Jul 2009			
			MSC					-			
Notes: NOT APPLICABLE - N/A BY MODEL NOT INSTALLED											
EASA 2008-0135 (992852) Airframe	EASA AD 2008-0135 - Passenger Seat Backrest - Replacement		HRS		651.02			5530.18			0
			AFL		143	-925		1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
EASA 2008-0158 R02 (992856) Airframe	EASA AD 2008-0158R2 - MODE-S Transponders - Limitation		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
EASA 2008-0159 (992850) Airframe	EASA AD 2008-0159 Navigation-MODE S Transponder		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2008-0174 (992854) Airframe	EASA AD 2008-0174 - Emergency Parachute - Replacement of the Drogue Parachute.		HRS		651.02			5530.18			0
			AFL		143			1425			0
			DATE		1191 d	-4375		24 Sep 2020			
			MSC								
EASA 2008-0183 (992855) Airframe	EASA AD 2008-0183 - MODE-S Transponders - Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 2009-0173 R01 (992958) Airframe	EASA AD 2009-0173R1 MODE S Transponder-MOD		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 2009-0180 R01 (992959) Airframe	EASA AD 2009-0180-R1 APU Enclosure Inspection		HRS		5043.2			1138			0
			AFL		1222			346			0
			MOS		173.9			01 Jul 2009			
			MSC								
Notes: N/A BY SERIAL NUMBER											
EASA 2009-0180-E (992951) Airframe	EASA AD 2009-0180-E APU Enclosure Inspection		HRS		5043.2			1138			0
			AFL		1222			346			0
			MOS		173.9			01 Jul 2009			
			MSC								
Notes: COMPLIED WITH - IAW THE SB COMPLIED WITH ACCORDING ACB 009A											
EASA 2009-0251-E (992956) Airframe	EASA Emergency AD 2009-0251-E - Portable Halon 1211 FIRE Extinguishers		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 2009-0262 R01 (992957) Airframe	EASA AD 2009-0262 R1 - Portable Halon 1211 FIRE Extinguishers		HRS		651.02			5530.18			0
			AFL		143			1425			0
			DATE		1191 d	-3892		24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2009-0278	EASA AD 2009-0278 - Portable Halon 1211 FIRE		HRS		651.02			5530.18			0
	Extinguishers - Identification / Replacement		AFL		143			1425			0
	(992960)		MOS		39.2			24 Sep 2020			
	Airframe		MSC								
EASA 2010-0003 R02	EASA AD 2010-0003R2 MODE S Transponder Aircraft		HRS		1864.9			4316.3			0
	Type MODE Strapping - Check / Modification		AFL		445			1123			0
	(993059)		MOS		88.7			06 Aug 2016			
	Airframe		MSC								
Notes: N/A EQUIPMENT NOT INSTALLED											
EASA 2010-0062 R01	EASA AD 2010-0062R1 - FIRE Fighting Enterprises		HRS		1889.4			4291.8			0
	Limited Portable Halon 1211 FIRE Extinguishers		AFL		454			1114			0
	(993055)		MOS		90.1			27 Jun 2016			
	Airframe		MSC								
Notes: PN: AS INDICATED BY ASB 26-116 ISSUE B SN: <NONE>. N/A BY P/N INSTALLED. SEE LOG BOOK AIRWORTHINESS DIRECTIVES											
EASA 2010-0067	EASA AD 2010-0067 Tdr-94 and Tdr-94D Transponders		HRS		1889.4			4291.8			0
	(993054)		AFL		454			1114			0
	Airframe		MOS		90.1			27 Jun 2016			
			MSC								
Notes: CODE IS N/A, REFERENCE LOGBOOK ENTRY SO 7-28-16											
EASA 2010-0075	No. 1 Engine - EASA AD 2010-0075 - Engines - High-		HRS		1912.4			4268.8			0
	Pressure (Hp) Turbine Discs Stage 1 and 2 Assembly Life		ENC		474			1094			0
	Limits - Modification		MOS		100.2			22 Aug 2015			
	(993051)		MSC								
Engine											
EASA 2010-0075 (993061)	No. 2 Engine - EASA AD 2010-0075 - Engines - High-		HRS		1912.4			4268.8			0
	Pressure (Hp) Turbine Discs Stage 1 and 2 Assembly Life		ENC		474			1094			0
	Limits - Modification		MOS		100.2			22 Aug 2015			
	(993051)		MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2010-0076	No. 1 Engine - EASA AD 2010-0076 - Engines - High-Pressure (Hp) Turbine Discs Stage 1 and 2 Assembly Life Limits - Modification		HRS		1912.4			4268.8			0
			ENC		474			1094			0
			MOS		100.2			22 Aug 2015			
			MSC								
(993052)	Engine										
EASA 2010-0076 (993062)	No. 2 Engine - EASA AD 2010-0076 - Engines - High-Pressure (Hp) Turbine Discs Stage 1 and 2 Assembly Life Limits - Modification		HRS		1912.4			4268.8			0
			ENC		474			1094			0
			MOS		100.2			22 Aug 2015			
			MSC								
(993052)	Engine										
EASA 2010-0077	No. 1 Engine - EASA AD 2010-0077 - Engines - Change of Life Cycle Counting Method for Touch-and-Go and Overshoot		HRS		1912.4			4268.8			0
			ENC		474			1094			0
			MOS		100.2			22 Aug 2015			
			MSC								
(993053)	Engine										
EASA 2010-0077 (993063)	No. 2 Engine - EASA AD 2010-0077 - Engines - Change of Life Cycle Counting Method for Touch-and-Go and Overshoot		HRS		1912.4			4268.8			0
			ENC		474			1094			0
			MOS		100.2			22 Aug 2015			
			MSC								
(993053)	Engine										
EASA 2010-0152	EASA AD 2010-0152 Intertechnique, Eros Oxygen Mask Regulator-MOD		HRS		1889.4			4291.8			0
			AFL		454			1114			0
			MOS		90.1			27 Jun 2016			
			MSC								
(993056)	Airframe										
Notes: N/A - EQUIPMENT NOT INSTALLED,SEE LOG BOOK AIRWORTHINESS DIRECTIVES.											
EASA 2010-0204	EASA AD 2010-0204 Tdr-94 and Tdr-94D Transponders		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
(993057)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2011-0090 R01 (993091) Airframe	EASA AD 2011-0090R1 Oxygen Mask Regulator Inflatable		HRS		3856.1			2325.1			0
	Harness - Identification / Replacement		AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
Notes: N/A - MANUFACTURED BEFORE WEEK 33 OF 2008 AND NOT AFFECTED BY UNSAFE CONDITIONS (CAMP REF)											
EASA 2011-0094 (993092) Airframe	EASA AD 2011-0094 - Equipment and Furnishing - Life		HRS		1889.4			4291.8			0
	Jacket Vacuum Bag - Modification		AFL		454			1114			0
			MOS		90.1			27 Jun 2016			
			MSC								
Notes: N/A. SEE LOG BOOK AIRWORTHINESS DIRECTIVES.											
EASA 2012-0161 R01 (993115) Engine	No. 1 Engine - 2012-0161 R01 - Engine - Accessory		HRS		2357.7		4000	3823.5	7823.5		0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		600			968			0
	Coupling		MOS		112.2			22 Aug 2014			
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833 RELATED TO 994011											
EASA 2012-0161 R01 (993116) (993115) Engine	No. 2 Engine - 2012-0161 R01 - Engine - Accessory		HRS		2357.7		4000	3823.5	7823.5		0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		600			968			0
	Coupling		MOS		112.2			22 Aug 2014			
Notes: REFERENCE ROLLS ROYCE SERVICE BULLETINS / AIRWORTHINESS DIRECTIVES LOG STATING NEXT DUE ON GAC SAV WORK ORDER SC378115 TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833 RELATED TO 994012											
EASA 2012-0166 (993097) Engine	No. 1 Engine - 2012-0166 Engine - High Pressure Turbine		HRS		1864.9			4316.3			0
	Rotor Disc Stage 1 and Stage 2 Life Limit Implementation		ENC		445			1123			0
			MOS		88.7			06 Aug 2016			
			MSC								
Notes: NA S/N INSTALLED NOT AFFECTED BY AD											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2012-0166 (993098) (993097) Engine	No. 2 Engine - 2012-0166 Engine - High Pressure Turbine		HRS		1864.9			4316.3			0
	Rotor Disc Stage 1 and Stage 2 Life Limit Implementation		ENC		445			1123			0
			MOS		88.7			06 Aug 2016			
			MSC								
Notes: NA S/N INSTALLED NOT AFFECTED BY AD											
EASA 2012-0254 (993100) Airframe	EASA AD 2012-0254 Flight Crew Oxygen Regulator -		HRS		3194.8			2986.4			0
	Identification / Operational Procedure / Replacement		AFL		782			786			0
			MOS		132.6			10 Dec 2012			
			MSC								
Notes: N/A BY S/N											
EASA 2012-0254 R01 (993101) Airframe	EASA AD 2012-0254R1 Flight Crew Oxygen Regulator -		HRS		3194.8			2986.4			0
	Identification / Operational Procedure / Replacement		AFL		782			786			0
			MOS		132.6			10 Dec 2012			
			MSC								
EASA 2013-0020 (993102) Airframe	EASA AD 2013-0020 - Safety Belts / Torso Restraint		HRS		6181.2			0			0
	Systems - Inspection / Replacement		AFL		1568			0			0
			MOS		129.5			14 Mar 2013			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
EASA 2013-0020 R01 (993107) Airframe	EASA AD 2013-0020R1 - Safety Belts / Torso Restraint		HRS		6181.2			0			0
	Systems - Inspection / Replacement		AFL		1568			0			0
			MOS		125.5			15 Jul 2013			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
EASA 2013-0020 R02 (993110) Airframe	EASA AD 2013-0020R2 - Safety Belts / Torso Restraint		HRS		6181.2			0			0
	Systems - Inspection / Replacement		AFL		1568			0			0
			MOS		116.7			08 Apr 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2013-0020 R03 (993120) Airframe	EASA AD 2013-0020R3 - Safety Belt / Torso Restraint Systems - Inspection / Replacement		HRS		3102.3			3078.9			0
			AFL		755			813			0
			MOS		129.3			19 Mar 2013			
			MSC								
EASA 2013-0020 R04 (993121) Airframe	EASA AD 2013-0020R4 - Safety Belt / Torso Restraint Systems - Inspection / Replacement		HRS		3102.3			3078.9			0
			AFL		755			813			0
			MOS		129.3			19 Mar 2013			
			MSC								
EASA 2013-0106 (993108) Airframe	EASA AD 2013-0106 Varnish on Veneered Panels - Inspection / Refurbishment		HRS		626.47			5554.73			0
			AFL		132			1436			0
			MOS		35.2			24 Jan 2021			
			MSC								
EASA 2013-0296 (993111) Engine	No. 1 Engine - EASA AD 2013-0296 High Pressure Compressor and Combustion Fairings - Inspection / Replacement		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		123.8			03 Sep 2013			
			MSC								
Notes: N/A BY ENG S/N											
EASA 2013-0296 (993112) (993111) Engine	No. 2 Engine - EASA AD 2013-0296 High Pressure Compressor and Combustion Fairings - Inspection / Replacement		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		123.8			03 Sep 2013			
			MSC								
Notes: N/A BY ENG S/N											
EASA 2014-0142 (993113) Airframe	EASA AD 2014-0142 - Oxygen Mask Regulator Inflatable Harness / Hose		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2014-0142 R01 (993114) Airframe	EASA AD 2014-0142R1 - Oxygen Mask Regulator		HRS		2357.7			3823.5			0
	Inflatable Harness / Hose		AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
EASA 2016-0034^U (994024) Airframe	EASA AD 2016-0034 - Low Pressure Turbine Fuel Shut-Off Pawl Carrier Pivot Pin - Replacement		HRS		1889.4			4291.8			0
			AFL		454			1114			0
			MOS		87.5			15 Sep 2016			
			MSC								
Notes: N/A BY ENGINE S/N. P/N INSTALLED BR700-710C4-11 S/N 15350 AND 15351											
EASA 2016-0044 (994025) Airframe	EASA AD 2016-0044 -Engine and Auxiliary Power Unit		HRS		1902.1			4279.1			0
	Automatic FIRE Extinguishers - Inspection/Overhaul		AFL		471			1097			0
			MOS		93.2			22 Mar 2016			
			MSC								
Notes: N/A BY P/N INSTALLED											
EASA 2016-0163 (994030) Airframe	EASA AD 2016-0163 - Cabin Attendant Seat - Modification / Replacement		HRS		1840.2			4341			0
			AFL		442			1126			0
			MOS		87.5			15 Sep 2016			
			MSC								
Notes: N/A CABIN SEAT ATTENDANT NOT INSTALLED											
EASA 2016-0164 (994031) Airframe	EASA AD 2016-0164 - Cabin Attendant Seat - Inspection		HRS		1840.2			4341			0
			AFL		442			1126			0
			MOS		87.5			15 Sep 2016			
			MSC								
Notes: N/A CABIN SEAT ATTENDANT NOT INSTALLED - Superseded by 2017-0001											
EASA 2016-0167 (994032) Airframe	EASA AD 2016-0167 - Rear Cabin Attendant Seat - Inspection / Repair		HRS		1840.2			4341			0
			AFL		442			1126			0
			MOS		87.5			15 Sep 2016			
			MSC								
Notes: N/A CABIN SEAT ATTENDANT NOT INSTALLED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2017-0198 (994046) Engine	No. 1 Engine - EASA AD 2017-0198 - Engine Electronic Controller Firebox Assembly - Replacement		HRS		665.8			5515.4	0		0
			ENC		150			1418	0		0
			MOS		43.1			26 May 2020			
			MSC								
EASA 2017-0198 (994047) (994046) Engine	No. 2 Engine - EASA AD 2017-0198 - Engine Electronic Controller Firebox Assembly - Replacement		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		43			28 May 2020			
			MSC								
EASA 2017-0198- CN (990409) Engine	No. 1 Engine - Cancelled: Engine Fuel & Control - Engine Electronic Controller Firebox Assembly - Replacement (Cancelled)		HRS		655.47			5525.73			0
			ENC		147			1421			0
			MOS		40.7			07 Aug 2020			
			MSC								
EASA 2017-0198- CN (990409) Engine	No. 2 Engine - Cancelled: Engine Fuel & Control - Engine Electronic Controller Firebox Assembly - Replacement (Cancelled)		HRS		655.47			5525.73			0
			ENC		147			1421			0
			MOS		40.7			07 Aug 2020			
			MSC								
EASA 2018-0115 (994062) Engine	No. 1 Engine - 2018-0115 - Engine - Accessory Gearbox Mount Assembly Tie Bolts - Replacement (Cancelled By EASA AD 2018-0115-Cn)		HRS		1265.9			4915.3			0
			ENC		301			1267			0
			MOS		67.5			15 May 2018			
			MSC								
Notes: N/A: SB-BR700-72-101466 NOT C/W, SERVICE BULLETIN ONLY APPLICABLE FOR ESPECIAL MISSION A/CANCELLED BY EASA											
EASA 2018-0115 (994063) (994062) Engine	No. 2 Engine - 2018-0115 - Engine - Accessory Gearbox Mount Assembly Tie Bolts - Replacement (Cancelled By EASA AD 2018-0115-Cn)		HRS		1265.9			4915.3			0
			ENC		301			1267			0
			MOS		67.5			15 May 2018			
			MSC								
Notes: N/A: SB-BR700-72-101466 NOT C/W, SERVICE BULLETIN ONLY APPLICABLE FOR ESPECIAL MISSION A/CANCELLED BY EASA											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2019-0235	EASA AD 2019-0235 ACR Electronics, Inc - C406 & G406		HRS		760.8			5420.4			0
	Emergency Locator Transmitters		AFL		175			1393			0
	(994074)		DATE		1476 d			14 Dec 2019			
	Airframe		MSC								
Notes: N/A - THE ELT P/N: 453-5000-999 S/N: 210-11764 HAS NOT BEEN INSTALLED ON AN HELICOPTER											
EASA 2019-0299 PARA (1)	No. 1 Engine - EASA AD 2019-0299 Part 1 High Pressure		HRS		764.4			5416.8			0
	Turbine Stage 1 Discs - Life Limit Reduction /		ENC		177			1391			0
	Replacement		DATE		1480 d			10 Dec 2019			
	(994076)		MSC								
Notes: N/A BY HP TURBINE STAGE 1 S/N (S/N INSTALLED LDRQA01252)											
EASA 2019-0299 PARA (1)	No. 2 Engine - EASA AD 2019-0299 Part 1 High Pressure		HRS		764.4			5416.8			0
	Turbine Stage 1 Discs - Life Limit Reduction /		ENC		177			1391			0
	Replacement		DATE		1480 d			10 Dec 2019			
	(994076)		MSC								
Notes: N/A BY HP TURBINE STAGE 1 S/N (S/N INSTALLED LDRQA01264)											
EASA 2019-0299 PARA (2)	No. 1 Engine - EASA AD 2019-0299 Part 2 High Pressure		HRS		764.4			5416.8			0
	Turbine Stage 1 Discs - Life Limit Reduction /		ENC		177			1391			0
	Replacement		MOS		48.6			10 Dec 2019			
	(994077)		MSC								
Notes: N/A BY HP TURBINE STAGE 1 S/N (S/N INSTALLED LDRQA01264)											
EASA 2019-0299 PARA (2)	No. 2 Engine - EASA AD 2019-0299 Part 2 High Pressure		HRS		764.4			5416.8			0
	Turbine Stage 1 Discs - Life Limit Reduction /		ENC		177			1391			0
	Replacement		MOS		48.6			10 Dec 2019			
	(994077)		MSC								
Notes: N/A BY HP TURBINE STAGE 1 S/N (S/N INSTALLED LDRQA01264)											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2022-0033	No. 1 Engine - ATA 05 - Time Limits / Maintenance		HRS		347.5			5833.7			0
	Checks - Time Limits Manual / Maintenance Programme -		ENC		76			1492			0
	Amendment (Mandatory)		MOS		19.1			27 May 2022			
			MSC								
(992233)	Engine										
EASA 2022-0033	No. 2 Engine - ATA 05 - Time Limits / Maintenance		HRS		347.5			5833.7			0
	Checks - Time Limits Manual / Maintenance Programme -		ENC		76			1492			0
	Amendment (Mandatory)		MOS		19.1			27 May 2022			
			MSC								
(992233)	Engine										
EASA 2022-0110	No. 1 Engine - EASA 2022-0110 - Engine - Low Pressure		HRS		327.2			5854			0
	Compressor Rotor (Fan) Disc - Inspection		ENC		72			1496			0
			DATE		556 d			21 Jun 2022			
			MSC								
(992211)	Engine										
EASA 2022-0110 (992212)	No. 2 Engine - EASA 2022-0110 - Engine - Low Pressure		HRS		327.2			5854			0
	Compressor Rotor (Fan) Disc - Inspection		ENC		72			1496			0
			DATE		556 d			21 Jun 2022			
			MSC								
(992211)	Engine										
EASA 2022-0110 R01	No. 1 Engine - EASA 2022-0110 R01 - Engine - Low		HRS		10.8		500	6170.4	6670.4		0
	Pressure Compressor Rotor (Fan) Disc - Inspection		ENC		2		150	1566	1716		0
	(Mandatory)		DATE		36 d			23 Nov 2023			
(992213)	Engine										
EASA 2022-0110 R01 (992214)	No. 2 Engine - EASA 2022-0110 R01 - Engine - Low		HRS		10.8		500	6170.4	6670.4		0
	Pressure Compressor Rotor (Fan) Disc - Inspection		ENC		2		150	1566	1716		0
	(Mandatory)		DATE		36 d			23 Nov 2023			
(992213)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 990097^U (990097) Airframe	EASA AD 2009-0097 MODE S Transponder - Check / Modification (Tdr-94 and Tdr-94D Transponders).		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 990256^U (990256) Airframe	EASA AD 2016-0256 - Equipment / Furnishings - Pilot and CO-Pilot Seats - Modification		HRS		1689.6			4491.6			0
			AFL		406			1162			0
			MOS		82.8			03 Feb 2017			
			MSC								
Notes: N/A BY P/N EFFECTIVITY - Supperseded by 2018-0262											
EASA 992010-03-02^U (992010-03-02) Airframe	EASA AD Us-2010-03-02 - Lifesavings Systems CORP. - D-Lok Hook of the Rescue Hoist - Inspection / Removal from Service / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992010-07-08^U (992010-07-08) Airframe	EASA AD Us-2010-07-08 - Kelly Aerospace Energy Systems - Rebuilt Turbochargers - Identification / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992010-09-04^U (992010-09-04) Airframe	EASA AD Us-2010-09-04 - Honeywell International Inc. - Primus Epic and Apex Flight Management Systems (FMS) - Airplane Flight Manual (Afm) Revision		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992010-12-09^U (992010-12-09) Airframe	EASA AD Us-2010-12-09 - Honeywell International Inc. Airborne Auxiliary Power - Fuel Control Unit (Fcu) - Inspection		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 992010-13-10^U (992010-13-10) Airframe	EASA AD Us-2010-13-10 - Ontic Engineering and Manufacturing, Inc. - Propeller Governors - Removal		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992012-06-25^U (992012-06-25) Airframe	EASA AD Us-2012-06-25 - Goodrich (Formerly Bf Goodrich) - Evacuation System - Inspection / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992013-10-01^U (992013-10-01) Airframe	EASA AD Us-2013-10-01 - Spectrolab, Inc. - Nightsun Xp Searchlight - Inspection / Removal / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992017-0192^U (992017-0192) Airframe	EASA AD 2017-0192 Recaro Aircraft Seating Gmbh & CO. Kg - Passenger Seats - Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992017-0225^U (992017-0225) Airframe	EASA AD 2017-0225 Schroth Safety Products Gmbh - Equipment / Furnishings – Seat Restraint Systems – Afm Amendment / Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 992018-0223^U (992018-0223) Airframe	EASA AD 2018-0223 Seat Energy Absorber Assembly - Modificatin		HRS		1133.7			5047.5			0
			AFL		267			1301			0
			MOS		62.2			22 Oct 2018			
			MSC								

Notes: N/A BY P/N INSTALLED

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 992018-0247^U (992018-0247) Airframe	EASA AD 2018-0247 - Appliances - Trig Avionics - Transponders		HRS		1084.4			5096.8			0
			AFL		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: N/A BY P/N INSTALLED. P/N INSTALLED 7517400-950											
EASA 992018-0262^U (992018-0262) Airframe	EASA AD 2018-0262 - Type 3A063 Flight Crew Seats		HRS		1084.4			5096.8			0
			AFL		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: N/A BY P/N INSTALLED.IPECO FLIGHT CREW SEATS INSTALLED P/N"S 1159SCF513-23/-24 (TYPE 3A317).											
EASA 992018-0264^U (992018-0264) Airframe	EASA AD 2018-0264 - Centaurus Passenger Seats		HRS		1084.4			5096.8			0
			AFL		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: N/A BY P/N INSTALLED.CENTAURUS PASSENGER SEATS NOT INSTALLED ON THIS AIRCRAFT. P/N"S INSTALLED 2524.524.01 SERIES & 2524.525.01 SERIES.											
EASA 992018-0264R1^U (992018-0264R1) Airframe	EASA AD 2018-0264 R1		HRS		998.1			5183.1			0
			AFL		236			1332			0
			MOS		57.4			18 Mar 2019			
			MSC								
Notes: N/A DUE SEATS NOT INSTALLED											
EASA 993093^U (993093) Airframe	EASA 2011-0093 ELT Antenna MOD. Chelton Limited		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 993094^U (993094) Airframe	EASA AD 2011-0103 ELT Antenna MOD/Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 993099^U (993099) Airframe	EASA AD 2011-0239 Navigation Radio Altimeter Indicator Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 994033^U (994033) Airframe	EASA AD 2016-0167R1 - Rear Cabin Attendant Seat - Inspection/Repair		HRS		1355.5			4825.7			0
			AFL		318			1250			0
			MOS		70.9			02 Feb 2018			
			MSC								
Notes: N/A CABIN ATTENDANT SEAT NOT INSTALLED											
EASA 994035^U (994035) Airframe	EASA AD 2017-0001 - Cabin Attendant Seat - Inspection		HRS		1689.6			4491.6			0
			AFL		406			1162			0
			MOS		82.8			03 Feb 2017			
			MSC								
Notes: N/A NOT INSTALLED SEAT ON A/C											
EASA 9940620^U (9940620) Engine	No. 1 Engine - Lta 2018-136 - Rr - BR700-710C4-11 - EASA 2018-0115		HRS		1265.9			4915.3			0
			ENC		301			1267			0
			MOS		67.5			15 May 2018			
Notes: N/A: SB-BR700-72-101466 NOT C/W, SERVICE BULLETIN ONLY APPLICABLE FOR ESPECIAL MISSION A/C											
EASA 9940620 (9940630)^U (9940620 (9940630)) Engine	No. 2 Engine - Lta 2018-136 - Rr - BR700-710C4-11 - EASA 2018-0115		HRS		1265.9			4915.3			0
			ENC		301			1267			0
			MOS		67.5			15 May 2018			
Notes: N/A: SB-BR700-72-101466 NOT C/W, SERVICE BULLETIN ONLY APPLICABLE FOR ESPECIAL MISSION A/C											
EASA 999018^U (999018) Airframe	EASA 2008-0084 - Saphir 20 Model 095 - APU Turbine Wheel / Replmnt: New Life		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 999019^U (999019) Airframe	EASA 2008-0080 - Sicma Aero Seat - Passenger Seats / In		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999022^U (999022) Airframe	EASA 2016-0024-1 PMC,PMC31 and Gmc Smoke Detectors		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		94.9			01 Feb 2016			
			MSC								
Notes: N/A BY P/N INSTALLED - INSTALLED 72130001-006											
EASA 999203^U (999203) Airframe	EASA AD Us-2012-14-15 Navigation Software Problem - Limitations Section of the Aircraft Flight Manual - Placard / Revision - Installation		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999204^U (999204) Airframe	EASA AD 2012-0038 Equipment & Furnishings - Passenger Seat Backrest Link - Inspection / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999205^U (999205) Airframe	EASA AD 2012-0037 FIRE Protection - Hand Operated FIRE Extinguisher - Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999210^U (999210) Airframe	EASA AD 2018-0195 Restraint Systems Rotary Buckle Sub Assembly		HRS		1084.4			5096.8			0
			AFL		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: N/A BY P/N INSTALLED.P/N OF RESTRAINT SYSTEM INSTALLED IAW IPECO CMM 25-11-48 : 5000-1-02A8089/5000-1-01A8089 (AMSAFE)											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 999212^U (999212) Airframe	EASA AD 2010-0186 Communication - Very High Frequency (VHF/ Am) Transceiver - Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999215^U (999215) Airframe	EASA Ead 2010-0009-E Equipment / Furnishings - Emergency Parachute - Inspection / Rework		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999217^U (999217) Airframe	EASA AD 2009-0200 Navigation - MODE A/C Transponder - Check / Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999218^U (999218) Airframe	EASA AD 2006-0334R1 Communications - Thales Communications VHF Data Radio - Modification		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999227^U (999227) Airframe	EASA AD 2007-0256 Equipment and Furnishing - Seat Restraint System Plastic Rotary Buckle Handle - Inspection / Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999230^U (999230) Airframe	EASA AD 2006-0286R1 Oxygen Reserve Cylinders - Removal / Emptying		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
EASA 999956^U (999956) Airframe	EASA AD 2006-0140R4- Ctt Systems Ab- Zonal Drying System Deactivation		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 1974-08-09 R02 (997427) Airframe	AD 74-08-09 R2 Lavatory Inspection		HRS		3521.5			2659.7			0
			AFL		865			703			0
			MOS		141.5			14 Mar 2012			
			MSC								
FAA 1974-08-09 R03 (994002) Airframe	AD 74-08-09 R3 Lavatory Paper and Linen Waste		HRS		130.8		1000	6050.4	7050.4		0
	Receptacle Enclosure Access Door and Disposal Door		AFL		29			1539			0
	Inspection		MOS		6.8			03 Jun 2023			
FAA 2003-07-11^U (992302) Airframe	AD 2003-07-11 RT Engine - Lp Compressor Fan Disc -		HRS		6151.5			29.7			0
	Inspection (Superseded By FAA AD 2005-21-05)		AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
FAA 2003-07-11^U (992301) Airframe	AD 2003-07-11 Lt Engine - Lp Compressor Fan Disc -		HRS		6151.5			29.7			0
	Inspection (Superseded By FAA AD 2005-21-05)		AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
FAA 2003-26-14 (992310) Airframe	AD 2003-26-14 898052 FIRE Bottl		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY SERIAL NUMBER											
FAA 2004-02-01 (992401) Airframe	AD 2004-02-01 Lg Select Dump Valve		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY PART NUMBER											
FAA 2004-22-16 (992412) Airframe	AD 2004-22-16 Wire Harness Clear		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY SERIAL NUMBER											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2005-04-06 (992503) Airframe	AD 2005-04-06 Cockpit Flight Panel Displays		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY SERIAL NUMBER											
FAA 2005-16-14 (992509) Airframe	AD 2005-16-14 Adel Wiggins Floor Heater - Deactivation		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY SERIAL NUMBER NO HEATER SYSTEM INSTALLED											
FAA 2005-20-26 (992513) Airframe	AD 2005-20-26 Aviointeriors Model 312 Seats		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY PART NUMBER											
FAA 2006-04-13 (992602) Airframe	AD 2006-04-13 Afm Procedures, Cockpit Displays Malfunction		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
FAA 2006-04-13 R01 (992603) Airframe	AD 2006-04-13 R1 Afm Procedure, Ckpt Displays Malfunction		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			17 Jan 2007			
			MSC								
Notes: COMPLIED WITH BY INSERTING G550 FLIGHT MANUAL REVISION NO. 15 DATED 21/01/2006. SEE LOG BOOK, AIRWORTHINESS DIRECTIVES COMPLIANCE RECORD											
FAA 2006-11-03 (992604) Airframe	AD 2006-11-03 Insp Aileron & Elevator ACT. Assy.		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
Notes: N/A BY SERIAL NUMBER											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2006-18-08 (992608) Airframe	AD 2006-18-08 Goodyear Aviation Tires		HRS		6174.1			7.1			0
			AFL		1562			6			0
			MOS		203.5			12 Jan 2007			
			MSC					-			
Notes: N/A BY S/N											
FAA 2006-18-13 (992609) Airframe	AD 2006-18-13 Aileron Hops Wire Harness		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
Notes: N/A BY SERIAL NUMBER											
FAA 2006-19-04 PARA (F) (992610) Airframe	AD 2006-19-04 Honeywell International (14 Day)		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		94.3			19 Feb 2016			
			MSC					-			
Notes: N/A BY P/N CAMP REF.											
FAA 2007-12-25 (992707) Airframe	FAA 2007-12-25 - Water/Waste - Revising the Airplane Flight Manuals (AFMS) of Those Airplanes, and Doing Repetitive Functional Checks of the Forward Water Drain/Supply Valves and Applicable Corrective Actions		HRS		5919.3			261.9			0
			AFL		1493			75			0
			MOS		197.9			01 Jul 2007			
			MSC					-			
Notes: N/A, FOUND ASC #7 N/A											
FAA 2009-08-01 (992901) Airframe	AD 2009-08-01 - Honeywell Navigation Computers and Integrated Avionics Computers		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
FAA 2009-17-01 (992902) Airframe	AD 2009-17-01 Inspection for Sealant Applied to the Exterior of the Auxiliary Power Unit (APU) Enclosure		HRS		5043.1			1138.1			0
			AFL		1222			346			0
			MOS		173.9			01 Jul 2009			
			MSC					-			
Notes: CW ACB9A ON. SEE LOG BOOK AND CAMP REF. - SUPERSEDED BY 2017-20-08											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2009-21-10 R01 (992904) Airframe	AD 2009-21-10 R1 Avox Systems and B/E Aerospace		HRS		6181.2			0			0
	Oxygen Cylinder Assemblies		AFL		1568			0			0
			MOS		99.8			04 Sep 2015			
			MSC								
Notes: N/A BY P/N GPL 4/9/15											
FAA 2010-01-03 (993001) Airframe	AD 2010-01-03 FIRE Fighting Enterprises Limited		HRS		1912.4			4268.8			0
	Portable Halon 1211 FIRE Extinguishers		AFL		474			1094			0
			MOS		100.2			22 Aug 2015			
			MSC								
Notes: PN: ANY SN: <NONE>											
FAA 2010-07-02 (993004) Airframe	AD 2010-07-02 Honeywell Primus li Rnz-850/-851		HRS		3320.4			2860.8			0
			AFL		821			747			0
			MOS		136.4			16 Aug 2012			
			MSC								
FAA 2010-11-05 (993021) Airframe	AD 2010-11-05 - Avox Systems and B/E Aerospace		HRS		1889.4			4291.8			0
	Oxygen Cylinders as Installed on Various 14 CFR Part 23		AFL		454			1114			0
	and CAR 3 Airplanes		MOS		90.1			27 Jun 2016			
			MSC								
Notes: CODE IS N/A, REFERENCE LOGBOOK ENTRY SO 7-28-16											
FAA 2010-25-05 TBL 1 (993007) Engine	No. 1 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		6181.2			0			0
	Turbine Discs Stage 1 Assembly Life Limits - Modification		ENC		1568	521	6200	0	6721*		0
			DATE								
FAA 2010-25-05 TBL 1 (993008) (993007) Engine	No. 2 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		6181.2			0			0
	Turbine Discs Stage 1 Assembly Life Limits - Modification		ENC		1568	521	6200	0	6721*		0
			DATE								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2010-25-05 TBL 2 (993010) Engine	No. 1 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		6181.2			0			0
	Turbine Discs Stage 2 Assembly Life Limits - Modification		ENC		1568		10500	0	10500		0
			DATE								
FAA 2010-25-05 TBL 2 (993011) (993010) Engine	No. 2 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		6181.2			0			0
	Turbine Discs Stage 2 Assembly Life Limits - Modification		ENC		1568		10500	0	10500		0
			DATE								
FAA 2011-01-09 (993009) Airframe	AD 2011-01-09 B/E Aerospace Pbe (P/N) 119003-11		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		99.8				04 Sep 2015		
			MSC				-				
Notes: N/A BY P/N GPL 4/9/15 FAA 2011-14-08 (993014) Airframe	AD 2011-14-08 -B/E Aerospace, Continuous Flow		HRS		3856.1			2325.1			0
	Passenger Oxygen Assembly		AFL		950			618			0
			MOS		148.5				12 Aug 2011		
			MSC				-				
FAA 2011-22-01 (993016) Engine	No. 1 Engine - 2011-22-01 - Engine - General - Change of		HRS		1912.4			4268.8			0
	Life Cycle Counting Method for Touch-and-Go and		ENC		474			1094			0
	Overshoot		MOS		100.2				22 Aug 2015		
			MSC				-				
FAA 2011-22-01 (993017) (993016) Engine	No. 2 Engine - 2011-22-01 - Engine - General - Change of		HRS		1912.4			4268.8			0
	Life Cycle Counting Method for Touch-and-Go and		ENC		474			1094			0
	Overshoot		MOS		100.2				22 Aug 2015		
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2011-24-02 (994000) Airframe	AD 2011-24-02 Gulfstream Aerospace Corporation (Third Halon FIRE Bottle for Engines)		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
			MSC					-			
Notes: SEE ACB 10A											
FAA 2012-02-08 (994001) Airframe	AD 2012-02-08 - Aviation Communication & Surveillance Systems, Llc		HRS		3311.5			2869.7			0
			AFL		821			747			0
			MOS		136.4			16 Aug 2012			
			MSC					-			
Notes: SEE ACB 10A											
FAA 2012-13-12 PARA (G) (994008) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Afm Revision		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		94.3			19 Feb 2016			
			MSC					-			
Notes: N/A BY A/C S/N											
FAA 2012-13-12 PARA (H)(1) (994009) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Measurement		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		94.3			19 Feb 2016			
			MSC					-			
Notes: N/A BY A/C S/N											
FAA 2012-13-12 PARA (I)(1) (994010) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Corrective Action		HRS		1902.1			4279.1			0
			AFL		471			1097			0
			MOS		94.3			19 Feb 2016			
			MSC					-			
Notes: N/A BY A/C S/N											
FAA 2012-26-15 (998000) Airframe	AD 2012-26-15 Honeywell International		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		108.8			03 Dec 2014			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2012-26-15 R01 (998001) Airframe	AD 2012-26-15 R1 Honeywell International		HRS		1864.9			4316.3			0
			AFL		445			1123			0
			MOS		88.7			06 Aug 2016			
			MSC								
Notes: N/A - PN NOT INSTALLED											
FAA 2013-03-17 (993103) Engine	No. 1 Engine - 2013-03-17 - Engine - High Pressure Turbine Rotor Disc Stage 1 and Stage 2 Life Limitation - Implementation		HRS		6181.2			0			0
			ENC				2300**		2300		0
			DATE								
FAA 2013-03-17 (993104) (993103) Engine	No. 2 Engine - 2013-03-17 - Engine - High Pressure Turbine Rotor Disc Stage 1 and Stage 2 Life Limitation - Implementation		HRS		6181.2			0			0
			ENC				2300**		2300		0
			DATE								
FAA 2013-05-13 (994011) Engine	No. 1 Engine - AD 2013-05-13 - Engine - Accessory Gearbox Module - Replacement of the Fuel Pump Splined Coupling		HRS		2357.7			3823.5			0
			ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833 RELATED TO 993115											
FAA 2013-05-13 (994012) (994011) Engine	No. 2 Engine - AD 2013-05-13 - Engine - Accessory Gearbox Module - Replacement of the Fuel Pump Splined Coupling		HRS		2357.7			3823.5			0
			ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833 RELATED TO 993116											
FAA 2013-22-19 (994013) Airframe	AD 2013-22-19 Fuel Boost Pump		HRS		2692.7			3488.5			0
			AFL		674			894			0
			MOS		120.3			20 Dec 2013			
			MSC								
Notes: PCW CB 122 16/AUG/2012 AND REVISED AMP E3R03											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2014-18-01	AD 2014-18-01 Rockwell Collins MODE S Transponders		HRS		1840.2			4341			0
	Tdr-94/Tdr-94D		AFL		442			1126			0
	(994015)		MOS		87.5			15 Sep 2016			
	Airframe		MSC								
Notes: N/A DUE HONEYWELL TRANSPONDER P/N 7517400-950 INSTALLED											
FAA 2015-08-07	AD 2015-08-07 Zodiac Aerotechnics (Formerly		HRS		1476.7			4704.5			0
	Intertechnique Aircraft Systems) - Oxygen Mask Regulator		AFL		350			1218			0
	Inflatable Harness - Identification / Replacement		MOS		75.5			15 Sep 2017			
	(994018)		MSC								
Airframe											
Notes: PCW AS N/A BY GESTAIR CAMO											
FAA 2015-16-04	AD 2015-16-04 Kidde Graviner		HRS		1889.4			4291.8			0
	(994019)		AFL		454			1114			0
	Airframe		MOS		89.4			18 Jul 2016			
			MSC								
Notes: NA BY PN INSTALLED - REFER TO GKBR002- JET AVIATION - INSTALLED 892408, 898052 AN D 100-9750											
FAA 2016-11-20	AD 2016-11-20 - B/E Aerospace Pbe P/N 119003-11		HRS		1840.2			4341			0
	(994026)		AFL		442			1126			0
	Airframe		MOS		87.5			15 Sep 2016			
			MSC								
Notes: NOT APPLICABLE - PN AFFECTED NOT INSTALLED - Superseded by 2017-18-12											
FAA 2016-13-12	No. 1 Engine - 2016-13-12 - Engine - Pawl Carrier Pivot		HRS		1805.6			4375.6			0
	Pins, Part Number (P/N) BRR17117, - Remove from		ENC		428			1140			0
	Service / Replace		MOS		85.9			01 Nov 2016			
	(994027)		MSC								
Engine											
Notes: N/A BY ENGINE S/N. P/N INSTALLED BR700-710C4-11 S/N 15350 AND 15351											
FAA 2016-13-12 (994028)	No. 2 Engine - 2016-13-12 - Engine - Pawl Carrier Pivot		HRS		1805.6			4375.6			0
	Pins, Part Number (P/N) BRR17117, - Remove from		ENC		428			1140			0
	Service / Replace		MOS		85.9			01 Nov 2016			
	(994027)		MSC								
Engine											
Notes: N/A BY ENGINE S/N. P/N INSTALLED BR700-710C4-11 S/N 15350 AND 15351											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2016-18-11	AD 2016-18-11 Gulfstream Aerospace Corporation (MLG End CAP)		HRS		1840.2			4341			0
			AFL		442			1126			0
			MOS		87.5			15 Sep 2016			
	(994029) Airframe		MSC								
Notes: INCORPORATED TR 5-3 AND REV 25 TO PMGES (MAINTENANCE PROGRAM) ONLY APPLICABLE TO A/C UNDER FAA RULES NOT FOR EASA											
FAA 2016-22-04	AD 2016-22-04 Gulfstream Aerospace Corporation (ALS Amm Chapter 05-10-10)		HRS		1787			4394.2			0
			AFL		419			1149			0
			MOS		84.9			01 Dec 2016			
	(994034) Airframe		MSC								
Notes: UPDATED MAINTENANCE PROGRAM WITH REVISION 25 OF AMM											
FAA 2017-08-01	AD 2017-08-01 - Gulfstream Aerospace - Fuel Boost Pump		HRS		1571.1			4610.1			0
			AFL		369			1199			0
			MOS		79.4			17 May 2017			
	(994039) Airframe		MSC								
Notes: REVISED AIRPLANE MAINTENANCE PROGRAM AND TASK 28-26-01 OF THE G550 MAINTENANCE MANUAL REV 25 WAS ALREADY INCLUDED											
FAA 2017-18-12	AD 2017-18-12 B/E Aerospace		HRS		1355.5			4825.7			0
			AFL		318			1250			0
			MOS		70.9			31 Jan 2018			
	(994042) Airframe		MSC								
Notes: NOT APPLICABLE - PN AFFECTED NOT INSTALLED											
FAA 2017-20-08	AD 2017-20-08 - Gulfstream Aerospace - Gulfstream Afm Supplement Incorporation		HRS		1382.9			4798.3			0
			AFL		326			1242			0
			MOS		73			29 Nov 2017			
	(994045) Airframe		MSC								
FAA 2018-18-14	No. 1 Engine - AD 2018-18-14 - Electronic Engine Controller (Eec) Firebox Assembly		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		45.1			26 Mar 2020			
	(994066) Engine		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2018-18-14 (994067) (994066) Engine	No. 2 Engine - AD 2018-18-14 - Electronic Engine		HRS		665.8			5515.4			0
	Controller (Eec) Firebox Assembly		ENC		150			1418			0
			MOS		43.1			26 May 2020			
			MSC								
FAA 2018-21-14 (994070) Airframe	AD 2018-21-14 Zodiac Aerotechnics (Formerly		HRS		404.7			5776.5	0		0
	Intertechnique) - Oxygen Mask Regulator Harness		AFL		92			1476	0		0
	Inflation Hose - Identification / Replacement		MOS		23.1			27 Jan 2022			
			MSC								
Notes: EQUIVALENT TO EASA AD 2014-0142.C/W (REFER TO TAG KBR-388).											
FAA 2019-15-10^U Airframe	FAA AD 2019-15-10 Safran Aerosystems		HRS		843.7			5337.5			0
			AFL		199			1369			0
			MOS		51.3			20 Sep 2019			
			MSC								
Notes: N/A BY P/N INSTALLED.LIFE VESTS INSTALLED 63600-105 AND 63600-505.											
FAA 2019-21-06^U Airframe	FAA AD 2019-21-06 Ipeco Holdings Limited		HRS		792.2		750**	5389			0
			AFL		184			1384			0
			MOS		49.5			14 Nov 2019			
Notes: N/A BY P/N INSTALLED.IPECO FLIGHT CREW SEATS INSTALLED P/N'S 1159SCF513-23/-24 (TYPE 3A317).											
FAA 2019-21-09^U Airframe	FAA 2019-21-09 Aviointeriors S.P.A.		HRS		792.2		600**	5389			0
			AFL		184			1384			0
			MOS		49.5		3**	14 Nov 2019			
Notes: N/A - CENTAURUS ECONOMY CLASS NOT INSTALLED.											
FAA 2020-10-05^U (992099) Airframe	Appliance AD - Navigation - Rockwell Collins Pro Line 4		HRS		655.47			5525.73			0
	and Pro Line 21 Flight Management Systems		AFL		147			1421			0
	(Mandatory)		MOS		41.8			03 Jul 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2020-16-08^U	Appliance AD - Aspen Avionics, Inc. - EFD1000 Flight Display Systems - Airplane Flight Manual - Revision (Mandatory)		HRS		651.02			5530.18	0		0
			AFL		143			1425	0		0
			MOS		39.2			24 Sep 2020			
			MSC								
Airframe											
Notes: N/A due equipment not installed. The AD correction does not apply either											
FAA 2020-18-51-E	Appliance/Emergency AD - Sandia Aerospace - Airplane Flight Manual - Section Limitations - Amendment (N/A Equipment Not Installed)		HRS		652.67			5528.53	0		0
			AFL		144			1424	0		0
			MOS		39.2			22 Sep 2020			
			MSC								
(990048)											
Airframe											
FAA 2020-21-02	Appliance AD - FIRE Protection - Kidde Aerospace & Defense Cargo FIRE Extinguisher Halon Bottles - Replacement (Mandatory)		HRS		651.02			5530.18	0		0
			AFL		143			1425	0		0
			MOS		39.2			24 Sep 2020			
			MSC								
(992100)											
Airframe											
FAA 2021-07-13	Appliance AD - Equipment and Furnishing - Seat Restraint System Plastic Rotary Buckle Handle - Inspection/Replacement (Mandatory)		HRS								0
			AFL								0
			DATE								
			MSC								
(990714)											
Airframe											
FAA 2021-07-13 PARA (E)(1)	Inspect the Buckle Handle for A Crack and IF Cracked, before Further Flight, Replace IT With an Airworthy Buckle (Mandatory)		HRS								0
			AFL								0
			MOS				6**				
(990715)											
Airframe											
FAA 2021-07-13 PARA (E)(2)	Measure the Thickness of the Buckle Handle Vane; IF Thickness Is 0.125 Inch or Greater, before Further Flight, Remove the Buckle from Service and Replace IT With an Airworthy Buckle (Mandatory)		HRS								0
			AFL								0
			MOS				12**				
(990716)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2021-07-13 PARA (E)(3)	Do Not Install A Buckle or Restraint System With A Buckle		HRS								0
	P/N 1111430 or 1111475, All Dash Numbers, With A		AFL								0
	Handle Vane Thickness of 0.125 Inch or Greater (Mandatory)		DATE								
(990717)			MSC								-
Airframe											
FAA 2021-23-12	Indicating / Recording / Navigation - Radio (Radar)		HRS		404.7			5776.5			0
	Altimeter - Afm Revision to Incorporate Limitations (Mandatory)		AFL		92			1476			0
			MOS		23.5			13 Jan 2022			
(992199)			MSC								-
Airframe											
FAA 2021-26-02	2021-26-02 - Landing Gear - Main Landing Gear (MLG)		HRS		404.7			5776.5			0
	Trunnion Pin - Life Limit		AFL		92			1476			0
			MOS		23.1			27 Jan 2022			
(992126)			MSC								-
Airframe											
FAA 2022-04-09	Oxygen - Oxygen Valve Assemblies, and Oxygen Cylinder		HRS		263.6			5917.6			0
	and Valve Assemblies - Inspect / Replace (Mandatory)		AFL		54			1514			0
			MOS		15.1			25 Sep 2022			
(999221)			MSC								-
Airframe											
FAA 2022-04-09 PARA (H) & (I)	Inspect the Oxygen Valve Assemblies, and Oxygen		HRS		263.6			5917.6			0
	Cylinder and Valve Assemblies, to Determine IF an		AFL		54			1514			0
	Effected Part Installed; IF Installed, before Further Flight, Do A Detailed Inspection for Correct Spacing of the Gap Between the Bottom of the Packing Retainer and Top of the Valve Body and Perform Corrective Actions (Mandatory)		DATE		460 d			25 Sep 2022			
(999222)			MSC								-
Airframe											
FAA 2022-04-09 PARA (J)	Report the Results of the Inspection (Mandatory)		HRS		263.6			5917.6			0
			AFL		54			1514			0
			DATE		460 d			25 Sep 2022			
(999223)			MSC								-
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2022-16-04	2022-16-04 - Horizontal Stabilizer Structure - Horizontal		HRS		263.6			5917.6			0
	Stabilizer Lower Bonded Skin Assemblies - Inspection		AFL		54			1514			0
	(Mandatory)		DATE		460 d			25 Sep 2022			
	(992255)		MSC								
Airframe											
FAA 2022-16-04 PARA (G)	2022-16-04 Para (G) - Incorporation of Airworthiness		HRS		263.6			5917.6			0
	Limitations (ALS) Revisions (Mandatory)		AFL		54			1514			0
	(992256)		DATE		460 d			25 Sep 2022			
	Airframe		MSC								
Airframe											
FAA 2022-16-04 PARA (I)	2022-16-04 Para (I) - Perform the Horizontal Stabilizer		HRS		263.6			5917.6			0
	Lower Skin Resonance C-Scan Inspection (Part II		AFL		54			1514			0
	Inspection) for Bond Line Corrosion and Apply Corrosion		MOS		15.1			25 Sep 2022			
	(992257)		MSC								
Airframe											
FAA 2022-26-02 PARA (G) EASA (1.1)	No. 1 Engine - 2022-26-02 Para (G) EASA (1.1) - Replace		HRS								0
	Each Component before Exceeding the Applicable Life		ENC								0
	Limit or before Exceeding the Applicable Threshold, or		DATE								
	(991600)		MSC								
Engine											
FAA 2022-26-02 PARA (G) EASA (1.1)	No. 2 Engine - 2022-26-02 Para (G) EASA (1.1) - Replace		HRS								0
	Each Component before Exceeding the Applicable Life		ENC								0
	Limit or before Exceeding the Applicable Threshold, or		DATE								
	(991600)		MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2022-26-02 PARA (G) EASA (3)	No. 1 Engine - 2022-26-02 Para (G) EASA (3) - Accessory Gearboxes - Incorporate the Actions and Associated		HRS		115.4			6065.8			0
	Thresholds and Intervals, Including Life Limits and		ENC		24			1544			0
	Maintenance Tasks, Into the Existing Approved		DATE		204 d			08 Jun 2023			
	Maintenance or Inspection Program, as Applicable (Mandatory)		MSC								
(991601)											
Engine											
FAA 2022-26-02 PARA (G) EASA (3)	No. 2 Engine - 2022-26-02 Para (G) EASA (3) - Accessory Gearboxes - Incorporate the Actions and Associated		HRS		115.4			6065.8			0
	Thresholds and Intervals, Including Life Limits and		ENC		24			1544			0
	Maintenance Tasks, Into the Existing Approved		DATE		204 d			08 Jun 2023			
	Maintenance or Inspection Program, as Applicable (Mandatory)		MSC								
(991601)											
Engine											
FAA 2023-02-02	2023-02-02 - Landing Gear System - Life Limit Main		HRS		156.3			6024.9			0
	Landing Gear (MLG) Trunnion Pin (Mandatory)		AFL		34			1534			0
			MOS		10.1			26 Feb 2023			
			MSC								
(992302)											
Airframe											
FAA 2023-10-02	Appliance AD - FAA 2023-10-02 - Indicating/Recording System/Navigation - Radio Altimeter - Afm Revision (Mandatory)		HRS		105.6			6075.6			0
			AFL		23			1545			0
			MOS		6.3			21 Jun 2023			
			MSC								
(992312)											
Airframe											
FAA 2023-10-02 PARA (H)	FAA 2023-10-02 Para (H) - Revise the Limitations Section of the Existing Afm (until 30--June- 2023 - Satisfied By FAA 2021-23-12) (Mandatory)		HRS		105.6			6075.6			0
			AFL		23			1545			0
			MOS		6.3			21 Jun 2023			
			MSC								
(992313)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2023-10-02 PARA (I) (992314) Airframe	FAA 2023-10-02 Para (I) - Revise the Limitations Section and Remove the Afm Revision Required By Para (H) (after 30 Jun 2023) (Mandatory)		HRS		96.5			6084.7			0
			AFL		22			1546			0
			MOS		6			30 Jun 2023			
			MSC								
FAA 2023-21-05 (991205) Airframe	Appliance AD - FAA 2023-21-05 - Navigation - Flight Management Computer 2/Navigation Modules - Operational Limitations/Amendment (Mandatory)		HRS		10.8			6170.4	0		0
			AFL		2			1566	0		0
			DATE		36 d			23 Nov 2023			
			MSC								
FAA 929918^U (929918) Airframe	AD2007-07-12		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
Notes: Superseded by FAA AD 2009-08-01											
FAA 990006^U (990006) Airframe	2010-0079 Microturbo - Auxiliary Power Unit Turbine Wheel - Life Limit Reduction		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 990017^U (990017) Airframe	Us-2011-13-03 Hartzell Engine Technologies, Llc (Het) Turbochargers - Inspection / Cleaning		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 990024^U (990024) Airframe	Us-2012-10-52 [Final Rule] Hartzell Engine Technologies, Llc - Turbochargers - Removal from Service		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 990829^U (990829) Airframe	AD2008-06-28R1 Avidyne CORP Primary Flight Display		HRS		651.02			5530.18	0		0
			AFL		143			1425	0		0
			MOS		39.2			24 Sep 2020			
			MSC								
Notes: Superseded by FAA AD 2009-05-05											
FAA 992016-0210^U (992016-0210) Airframe	AD 2016-0210 B/E Aerospace Fischer Gmbh - Seat Energy Absorber Assembly - Replacement		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 992017-09-09^U (992017-09-09) Airframe	AD 2017-09-09 Zodiac Seats California Llc Seating Systems		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 992018-02-04^U (992018-02-04) Airframe	AD 2018-02-04 Aerospace Welding Minneapolis - Engine Exhaust - Muffler - Inspection		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 992018-16-13^U (992018-16-13) Airframe	FAA AD 2018-16-13 Zodiac Seats France - Inspect Safety Belt Webbing		HRS		1136			5045.2			0
			AFL		271			1297			0
			MOS		62.6			09 Oct 2018			
			MSC								
Notes: N/A: CABIN SEAT ATTENDANT NOT INSTALLED											
FAA 992018-19-15^U (992018-19-15) Airframe	FAA AD 2018-19-15 Joint Aircraft System Component (Jasc) 2500 Code, Cabin Equipment/Furnishings.		HRS		1133.7			5047.5			0
			AFL		267			1301			0
			MOS		62.2			22 Oct 2018			
			MSC								
Notes: N/A - SEATS P/N D1-03-()()-()() & D1-02-()()-()() NOT INSTALLED IN THIS A/C											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 992018-21-14^U (992018-21-14) Airframe	FAA AD 2018-21-14 Zodiac - Crew O2 System		HRS		1045.1			5136.1			0
			AFL		245			1323			0
			MOS		58.7			08 Feb 2019			
			MSC								
Notes: EQUIVALENT TO EASA AD 2014-0142.C/W (REFER TO TAG KBR-388).											
FAA 992018-23-01^U (992018-23-01) Airframe	AD 2018-23-01 - Zodiac Seats France Cabin Attendant Seats		HRS		1056.6			5124.6			0
			AFL		247			1321			0
			MOS		60.5			15 Dec 2018			
			MSC								
Notes: N/A - CABIN ATTENDANT SEAT NOT INSTALLED.											
FAA 992018-23-12^U (992018-23-12) Airframe	FAA AD 2018-23-12 - Appliance AD - Equipment / Furnishings - Zodiac Aero Evacuation Systems Fusible Plugs		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 992019-0004^U (992019-0004) Airframe	AD 2019-0004		HRS		1056.6			5124.6			0
			AFL		247			1321			0
			MOS		60.5			15 Dec 2018			
			MSC								
Notes: N/A BY P/N INSTALLED.GPS RECEIVER INSTALLED P/N 245-604067-001.											
FAA 992019-0010^U (992019-0010) Airframe	AD 2019-0010		HRS		1056.6			5124.6			0
			AFL		247			1321			0
			MOS		60.5			15 Dec 2018			
			MSC								
Notes: N/A BY P/N INSTALLED.LIFE VESTS INSTALLED P/N 63600-105 AND 63600-505.											
FAA 992019-01-02^U (992019-01-02) Airframe	2019-01-02 Aspen Avionics, Inc.: Amendment 39-19541; Docket No. FAA-2018-1085; Product Identifier 2018-Sw-100-AD.		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 992019-07-03^U (992019-07-03) Airframe	FAA AD 2019-07-03 Zodiac Seats		HRS		998.1			5183.1			0
			AFL		236			1332			0
			MOS		57.4			18 Mar 2019			
			MSC					-			
Notes: N/A DUE SEATS NOT INSTALLED											
FAA 992019-07-10^U (992019-07-10) Airframe	FAA AD 2019-07-10		HRS		985.9			5195.3			0
			AFL		234			1334			0
			MOS		55.7			07 May 2019			
			MSC					-			
Notes: N/A DUE P/N OF EQUIPMENT NOT INSTALLED											
FAA 992019-08-01^U (992019-08-01) Airframe	FAA AD 2019-08-01		HRS		985.9			5195.3			0
			AFL		234			1334			0
			MOS		55.7			07 May 2019			
			MSC					-			
Notes: N/A BECAUSE OF THE AFFECTED PN CAN NOT BE INSTALLED IN THIS AIRCRAFT											
FAA 992019-12-09^U Airframe	FAA AD 2019-12-09		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.5			13 Mar 2020			
			MSC					-			
Notes: N/A - THIS AD IS NOT ADOPTED BY EASA - FDSA-6500 P/N'S NOT INSTALLED											
FAA 992573^U (992573) Airframe	AD 2008-06-27, Goodrich (Formerly Bf Goodrich)		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
FAA 992579^U (992579) Airframe	AD 2009-05-08, Trimble or Freeflight Systems		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			
FAA 992581^U (992581) Airframe	AD 2009-21-03, Hamilton Sundstrand Power Systems		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 992708^U (992708) Airframe	AD 2007-12-25 Water Drain/Supply Valves (Terminating Action) (Mandatory)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		203.4			17 Jan 2007			
			MSC								
FAA 992768^U (992768) Airframe	AD 2009-05-05 Avidyne Corporation Primary Flight Displays (Part Numbers 700-00006-000, -001, -002, -003, and -100)		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 992819^U (992819) Airframe	AD 2008-19-01 (Moegliche Blockade Der Pitot / Angle of Attack Probes Durch Gefrierendes Kondenswasser Infolge Mangelhafter Funktion Der Probe Heaters		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 9940460^U (9940460) Engine	No. 1 Engine - Lba Lta D-2017-251-Engine Fuel and Control - Engine Electronic Controller Firebox Assembly - Replacement Sb-BR700-73-A101981		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		45.1			26 Mar 2020			
			MSC								
Notes: RELATED TO 994046											
FAA 9940460 (9940470)^U (9940460 (9940470)) Engine	No. 2 Engine - No. 2 Engine - Lbs-Lta-D-2017-251-Engine Fuel Control - Engine Electronic Controller Firebox Assembly - Replacement Sb-BR700-73-A101981		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		45.1			26 Mar 2020			
			MSC								
Notes: RELATED TO 994047											
FAA 994052^U (994052) Airframe	AD 2017-22-14 - Rockwell Collins, Inc.: Amendment 39-19094; Docket No. FAA-2017-0659		HRS		1389.7			4791.5			0
			AFL		330			1238			0
			MOS		73.6			10 Nov 2017			
			MSC								
Notes: NOT INSTALLED TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS, (RCPN) 822-2132-001											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 994060^U (994060) Airframe	AD 2007-04-19 R1		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 999016^U (999016) Airframe	FAA 2008-08-17 - Kelly Aerospace Power System Turbochargers / Inspection		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 999023^U (999023) Airframe	FAA 2008-02-06 Cor - Garmin Gsm 85 Servo Gearbox Unites / Ident of MOD Level		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 999200^U (999200) Airframe	AD 2014-05-27 Rockwell Collins MODE S Transponders		HRS		651.02			5530.18	0		0
			AFL		143			1425	0		0
			MOS		39.2			24 Sep 2020			
			MSC								
Notes: N/A due P/N not installed											
FAA 999235^U (999235) Airframe	AD 2007-23-01		HRS		651.02			5530.18			0
			AFL		143			1425			0
			MOS		39.2			24 Sep 2020			
			MSC								
FAA 999324^U (999324) Airframe	AD2018-03-04 Replacement of Rosemount Aerospace Inc. Model 851AK Pitot Probes Repaired By Csi Aerospace Inc.		HRS		651.02			5530.18	0		0
			AFL		143			1425	0		0
			MOS		39.2			24 Sep 2020			
			MSC								
Notes: N/A due PN not installed											
FAA 999832^U (999832) Airframe	FAA AD 2017-06-03 - Meggit (Troy) Inc. Combustion Heaters		HRS		1136			5045.2			0
			AFL		271			1297			0
			MOS		62.6			09 Oct 2018			
			MSC								
Notes: EQUIPMENT NOT INSTALLED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

FAA 999902^U (999902) Airframe	AD 2017-11-11 Navworx, Inc. ADS-B Tranceiver Units	HRS		1136				5045.2			0
		AFL		271				1297			0
		MOS		62.6				09 Oct 2018			
		MSC									

Notes: N/A - P/N IS NOT INSTALLED

FAA 999907^U (999907) Airframe	FAA AD 2017-19-05 Siemens S.A.S. Smoke Detectors	HRS		1414.1				4767.1			0
		AFL		332				1236			0
		MOS		73.8				04 Nov 2017			
		MSC									

Notes: N/A BY P/N INSTALLED - INSTALLED 72130001-006

FAA 999930^U (999930) Airframe	FAA AD 2017-04-06 Appliances: United Instruments, Inc. Altimeters - Replacement	HRS		1476.7				4704.5			0
		AFL		350				1218			0
		MOS		75.5				15 Sep 2017			
		MSC									

Notes: N/A BY P/N INSTALLED, INSTALLED 7001840-932

FAA 999935^U (999935) Airframe	AD 2017-16-01 Emergency Locator Beacon	HRS		651.02				5530.18			0
		AFL		143				1425			0
		MOS		39.2				24 Sep 2020			
		MSC									

FAA AD 2019-13-03^U Airframe	FAA AD 2019-13-03 Trig Avionics Limited	HRS		792.2				5389	0		0
		AFL		184				1384	0		0
		DATE		1506 d		90d**		14 Nov 2019			

[End Of Month Item]

Notes: This AD does not apply by P/N - Transponders P/N installed is 7517402-970

TCCA CF-2009-44 (992980) Airframe	Transport Canada AD Cf-2009-44 - 406 MHZ Elts - Potential Failure to Transmit Required 406MHZ Coded Signal	HRS		651.02				5530.18			0
		AFL		143				1425			0
		MOS		39.2				24 Sep 2020			
		MSC									

SIAC - Service Information/Bulletins

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235555^U	Magnastar C-2000 1MHZ Band, Service Bulletin		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
	Airframe		MSC					-			
901100^U	ST02343CH-D 16 Passenger Corporate Executive Cabin Interior		HRS		6173.6			7.6			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
	Airframe		MSC					-			
Notes: ICA GC52801A444 DATED 2/2007.											
941400	FAA NEXTGEN Program Mandate: ADS-B Out Compliance		HRS		843.7			5337.5			0
			AFL		199			1369			0
	(941400)		MOS		51.3			20 Sep 2019			
	Airframe		MSC					-			
941401	FAA NEXTGEN Program Mandate: FANS 1/A+ Compliance		HRS		843.7			5337.5			0
			AFL		199			1369			0
	(941401)		MOS		51.3			20 Sep 2019			
	Airframe		MSC					-			
949005	Cmc Module Reliability Enhancement Program (Mp-17-5501)		HRS		6181.2			0			0
			AFL		1568			0			0
	(949005)		DATE								
	Airframe		MSC					-			
980001^U	Sb 7025725-34-0011 MOD G to the McdU		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	Airframe		MSC					-			
ACB001 PART I	Acb 1 Wiring/O2 Bottle PART1		HRS		6151.5			29.7			0
			AFL		1555			13			0
	(990010)		MOS		210.7			08 Jun 2006			
	Airframe		MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB001 PART II (990011) Airframe	Acb 1 Wiring/O2 Bottle PART2		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB002 (990020) Airframe	Acb 2 Ascba Noise Test		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB003 (990030) Airframe	Acb 3 De-Activation-Adel Wiggins Floor Heater System		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB004A (990041) Airframe	Acb 4A Wing Rib Reinforcement Angles		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB005 (990050) Airframe	Acb 5 - Inspect Goodyear NLG Tires		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB006A (990061) Airframe	Acb 6A - Ail/Elev ACT Load Relief Bungees		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
ACB008 (990080) Airframe	Acb 8 Modification-Tail Compartment Ladder		HRS		5603.8			577.4			0
			AFL		1408			160			0
			MOS		189.1			27 Mar 2008			
			MSC					-			
Notes: N/A ASC 62 NOT C/W											
ACB009 (990090) Airframe	Acb 9 - Operational Limitations - Auxiliary Power Unit (APU)		HRS		5121.6			1059.6			0
			AFL		1243			325			0
			MOS		175.1			26 May 2009			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB009A	Acb 9A - Operational Limitations - Auxiliary Power Unit (APU)		HRS		5043.1			1138.1			0
			AFL		1222			346			0
			MOS		173.9			01 Jul 2009			
	(990091)		MSC								
Airframe											
ACB010 PART I	Acb 10 Part I - Inspection - Third Engine FIRE Bottle Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
	(990100)		MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED.											
ACB010 PART II	Acb 10 Part II - Inspection - Third Engine FIRE Bottle Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
	(990101)		MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED.											
ACB010A PART I	Acb 10A Part 1 - Inspection - Third Engine FIRE Bottle Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
	(990102)		MSC								
Airframe											
Notes: THIRD ENGINE FIRE BOTTLE INSTALLATION NOT APPLICABLE APPLIANCE NOT INSTALLED (CAMP REF)											
ACB010A PART II	Acb 10A Part 2 - Inspection - Third Engine FIRE Bottle Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.5			15 Dec 2010			
	(990103)		MSC								
Airframe											
ACB011	Acb 11 - Operational Limitations - Auxiliary Power Unit (APU) Enclosure With Thermal Barrier Coating		HRS		3617.8			2563.4			0
			AFL		892			676			0
			MOS		144.3			20 Dec 2011			
	(990110)		MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB013	ACB013 - Engine Turbine / Ducted Fan (ATA 72)		HRS		321.4			5859.8			0
	Inspection - BR710 Fan Disc (Rolls-Royce Nmsb Alert Sb-		AFL		67			1501			0
	BR700-72-A900732), Alert Customer Bulletin		DATE		534 d			13 Jul 2022			
	(Mandatory)		MSC								
(990130)											
Airframe											
ASC002	ASC 2 Digital FDR Upgrade		HRS		6173.3			7.9			0
			AFL		1562			6			0
	(970020)		MOS		203.4			16 Jan 2007			
	Airframe		MSC								
ASC002A	ASC 2A Digital Flight Data Recorder Sys Upgrade		HRS		6181.2			0			0
			AFL		1568			0			0
	(970021)		DATE								
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC002B	ASC 2B Digital Flight Recorder System Upgrade		HRS		6181.2			0			0
			AFL		1568			0			0
	(970022)		MOS		118.2			24 Feb 2014			
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC002C	ASC 2C Digital Flight Data Recorder System Upgrade (88		HRS		6181.2			0			0
	Parameters)		AFL		1568			0			0
	(970023)		MOS		118.2			24 Feb 2014			
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC002D	ASC 2D Digital Flight Data Recorder System Upgrade (88		HRS		3124.6			3056.6			0
	Parameters)		AFL		767			801			0
	(970024)		MOS		130.2			22 Feb 2013			
	Airframe		MSC								
ASC008	ASC 8 Max Gross Wgt 75K Placard		HRS		6173.3			7.9			0
			AFL		1562			6			0
	(970080)		MOS		203.4			16 Jan 2007			
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC008A (970081) Airframe	ASC 8A Maximum Gross Weight 75,000 Pounds		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC008B (970082) Airframe	ASC 8B Maximum Gross Weight 75,000 Pounds		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC009 (970090) Airframe	ASC 9 Max Zero Fuel Gross Wgt		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
ASC009A (970091) Airframe	ASC 9A Maximum Zero Fuel Gross Weight 53,500 Pounds - Placard Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC009B (970092) Airframe	ASC 9B Maximum Zero Fuel Gross Weight 53,500 Pounds - Placard Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC011 (970110) Airframe	ASC 11 G550 Data Plate Install		HRS		6175.4			5.8			0
			AFL		1563			5			0
			MOS		208.2			22 Aug 2006			
			MSC								
ASC014 (970140) Airframe	ASC 14 Category Ii Annunciation - Activation		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC014A (970141) Airframe	ASC 14A Category Ii Annunciation - Activation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC033 (970330) Airframe	ASC 33 Bonded Honeycomb Panels		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC035A PART 1 (970351) Airframe	ASC 35A (Part 1) EASA / Jaa Cert - BASIC Requirements		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
ASC035A PART 2 (970352) Airframe	ASC 35A (Part 2) EASA / Jaa Cert - BASIC Requirements		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC044A (970441) Airframe	ASC 44A Planeview Avionics Enhancement		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
ASC049 (970490) Airframe	ASC 49 Lightning Sensor System (Lss) Installation		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
ASC049A (970491) Airframe	ASC 49A Lightning Sensor System (Lss) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		96.6			10 Dec 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC049B (970492) Airframe	ASC 49B Lightning Sensor System (Lss) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC049C	Navigation (ATA 34) - Lightning Sensor System (Lss) - Installation, Aircraft Service Change (Optional)		HRS								0
(970493)			AFL								0
Airframe			DATE								
			MSC								
ASC052	ASC 52 Planeview Avionics Enhancement		HRS		5725.3			455.9			0
(970520)			AFL		1438			130			0
Airframe			MOS		191.3			21 Jan 2008			
			MSC								
ASC053	ASC 53 Comm Management Fnc ARINC Direct-Datalink		HRS		6150.7			30.5			0
(970530)			AFL		1554			14			0
Airframe			MOS		202.3			20 Feb 2007			
			MSC								
ASC053A	ASC 53A Communications Management Function ARINC Direct - Datalink Service Provider		HRS		6181.2			0			0
(970531)			AFL		1568			0			0
Airframe			DATE								
			MSC								
ASC057A	ASC 57A - Electrical Lines-Contact Prevention (Cb 32 AM1)		HRS		5255.6			925.6			0
(970571)			AFL		1288			280			0
Airframe			MOS		179.1			26 Jan 2009			
			MSC								
ASC058	ASC 58 Engine Fuel and Control (S3.4 Fadec MOD.)		HRS		6181.2			0			0
(970580)			AFL		1568			0			0
Airframe			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC058A	ASC 58A Engine Fuel and Control (S3.4 Fadec MOD.)		HRS		5725.3			455.9			0
(970581)			AFL		1438			130			0
Airframe			MOS		191.3			21 Jan 2008			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC059 (970590) Airframe	ASC 59 Aux Hydraulic Boost Pump Circuit Protection		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			21 May 2021			
			MSC					-			

ASC060 (970600) Airframe	ASC 60 Enhanced Vision System Window Bonding MOD		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			

ASC061 (970610) Airframe	ASC 61 Synthetic Vision-Primary Flight Display (Sv-Pfd) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC061 AM1 (970611) Airframe	ASC 61 AM1- Synthetic Vision Primary Flight Display (Sv-Pf)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC061A (970612) Airframe	ASC 61A Synthetic Vision-Primary Flight Display (Sv-Pfd) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC061A AM1 (970613) Airframe	ASC 61A AM1 Synthetic Vision - Primary Flight Display (Sv-Pfd) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC061B (970614) Airframe	ASC 61B Synthetic Vision-Primary Flight Display (Sv-Pfd) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			

ASC062 (970620) Airframe	ASC 62 Tail Compt Ladder Replacement		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.5			15 Jan 2008			
			MSC					O/C			

ASC063 (970630) Airframe	ASC 63 Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		128.9			01 Apr 2013			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC063B PART 1 (970633) Airframe	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD Part 1		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		91.5			12 May 2016			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC063B PART 2 (970634) Airframe	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD Part 2		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		91.5			12 May 2016			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC063B PART 3 (970635) Airframe	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD Part 3		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		91.5			12 May 2016			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC063C PART 1	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		6181.2			0			0
	Part 1		AFL		1568			0			0
(970636)			DATE								
Airframe			MSC				-				
ASC063C PART 2	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		6181.2			0			0
	Part 2		AFL		1568			0			0
(970637)			DATE								
Airframe			MSC				-				
ASC063C PART 3	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		6181.2			0			0
	Part 3		AFL		1568			0			0
(970638)			DATE								
Airframe			MSC				-				
ASC065	ASC 65 Runway Awareness Advisory System (Raas)-		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
(970650)			MOS		118.2			24 Feb 2014			
Airframe			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC065A	ASC 65A Runway Awareness Advisory System-		HRS		6181.2			0			0
	Installation		AFL		1568			0			0
(970651)			DATE								
Airframe			MSC				-				
ASC066	ASC 66 Auxiliary Power Unit (APU) Bond Strap		HRS		5255.6			925.6			0
	Installation		AFL		1288			280			0
(970660)			MOS		179.1			26 Jan 2009			
Airframe			MSC				-				
ASC069A	ASC 69A Engine Electronic Controller (Eec) Upgrade to		HRS		5255.6			925.6			0
	V1.3 / EECU3000		AFL		1288			280			0
(970691)			MOS		179.1			26 Jan 2009			
Airframe			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC069A AM1 (970692) Airframe	ASC 69A AM1 Engine Electronic Controller (Eec) Upgrade to V1.3 / EECU3000		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC070 (970700) Airframe	ASC 70 Nose Landing Gear Door Actuator Modification		HRS		5725.4			455.8			0
			AFL		1438			130			0
			MOS		191.6			09 Jan 2008			
			MSC								
ASC071 (970710) Airframe	ASC 71 Micro Quick Access Recorder Installation		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC								
Notes: THIS ITEM HAS BEEN ENTERED OUT OF ORDER. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC072 (970720) Airframe	ASC 72 Medeco Door Locks Installation		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC								
ASC073 (970730) Airframe	ASC 73 Nose Gear Uplock Hook Spring Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC073A (970731) Airframe	ASC 73A Nose Gear Uplock Hook Spring Replacement		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC								
ASC074 (970740) Airframe	ASC 74 Dual Brake Metering Valve Replacement		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC158164											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC074A (970741) Airframe	ASC 74A Dual Brake Metering Valve Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC074A AM1 (970742) Airframe	ASC 74A AM1 Dual Brake Metering Valve Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC075 (970750) Airframe	ASC 75 Led Tail Position Light Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC075A (970751) Airframe	ASC 75A Led Tail Position Light Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC076 (970760) Airframe	ASC 76 Planeview Avionics Enhancement (Sv-Pfd)		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC076 AM1 (970761) Airframe	ASC 76 AM1 Planeview Avionics Enhancement (Sv-Pfd)		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC077 (970770) Airframe	ASC 77 - Decal Installation - Remote Oil Servicing Panel		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC077A (970771) Airframe	ASC 77A - Decal Installation - Remote Oil Servicing Panel		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC078 (970780) Airframe	ASC 78 Potable Water System Purge-Plackard		HRS		5350.4			830.8			0
			AFL		1317			251			0
			MOS		182.3			21 Oct 2008			
			MSC					-			
ASC079 (970790) Airframe	ASC 79 Main Landing Gear Emergency Line Modification		HRS		597.1			5584.1			0
			AFL		124			1444			0
			DATE		952 d			21 May 2021			
			MSC					-			
ASC080 (970800) Airframe	ASC 80 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			
ASC080 AM1 (970801) Airframe	ASC 80 AM1 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
ASC080 AM2 (970802) Airframe	ASC 80 AM2 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			
ASC082 (970820) Airframe	ASC 82 Tail Compartment Ladder - Hinge Pin and Placard		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC158164											
ASC082A (970821) Airframe	ASC 82A Tail Compartment Ladder - Hinge Pin and Placard		HRS		5047.2			1134			0
			AFL		1228			340			0
			MOS		174.4			18 Jun 2009			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC082A AM1	ASC 82A AM1 Tail Compartment Ladder - Hinge Pin and Placard		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
	(970822)		MSC								
Airframe											
ASC083	ASC 83 Planeview Avionics Enhancement (Cert Fox)		HRS		6181.2			0			0
			AFL		1568			0			0
	(970830)		MOS		118.2			24 Feb 2014			
			MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC083A	ASC 83A Planeview Avionics Enhancement (Cert Fox)		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	(970831)		MOS		156.3			21 Dec 2010			
			MSC								
Airframe											
ASC084	ASC 84 Enhanced Navigation		HRS		6181.2			0			0
			AFL		1568			0			0
	(970840)		MOS		118.2			24 Feb 2014			
			MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC084A	ASC 84A Enhanced Navigation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	(970841)		MOS		156.3			21 Dec 2010			
			MSC								
Airframe											
Notes: THIS ITEM HAS BEEN ENTERED OUT OF ORDER. THIS CODE HAS BEEN CANCELLED.											
ASC084B	ASC 84B Enhanced Navigation		HRS		6181.2			0			0
			AFL		1568			0			0
	(970842)		MOS		103.3			21 May 2015			
			MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. PCW REVISION A OF ASC											
ASC084C	ASC 84C Enhanced Navigation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
	(970843)		MOS		156.3			21 Dec 2010			
			MSC								
Airframe											
Notes: PCW REVISION A OF ASC											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC084D (970844) Airframe	ASC 84D Enhanced Navigation		HRS		1265.9			4915.3			0
			AFL		301			1267			0
			MOS		67.5			15 May 2018			
			MSC					-			
Notes: PCW REVISION A OF ASC											
ASC085 (970850) Airframe	ASC 85 Xm Weather Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC085A (970851) Airframe	ASC 85A Xm Weather Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		72.4			18 Dec 2017			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC085B (970852) Airframe	ASC 85B Xm Weather Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED											
ASC085B-CN (970852) Airframe	ASC085B-Cn - Indicating/Recording - Xm Weather Installation (New Installations Discontinued See All Mol-22 -0016), Aircraft Service Change (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED											
ASC087 (970870) Airframe	ASC 87 Canadian Certification Requirements		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC089 (970890) Airframe	ASC 89 Stage 4 Noise Standards - Certification		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		124.3			20 Aug 2013			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC089A (970891) Airframe	ASC 89A Stage 4 Noise Standards - Certification		HRS		3521.5			2659.7			0
			AFL		865			703			0
			MOS		141.5			14 Mar 2012			
			MSC					-			

ASC090 (970900) Airframe	ASC 90 Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.9			02 Dec 2010			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC090 AM1 (970901) Airframe	ASC 90 AM1 Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC090A (970902) Airframe	ASC 90A Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.9			02 Dec 2010			
			MSC					-			

ASC091 (970910) Airframe	ASC 91 Enhanced Baggage Door Seal System - Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			18 Dec 2010			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC091A (970911) Airframe	ASC 91A Enhanced Baggage Door Seal System - Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			18 Dec 2010			
			MSC								
ASC092 (970920) Airframe	ASC 92 Communication Management Function (Cmf) - SATCOM Direct - Datalink Service Provider		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC093A (970931) Airframe	ASC 93A Aileron Cable Fairleads AT Sponson Rib - Installation		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.3			21 Dec 2010			
			MSC								
ASC094 (970940) Airframe	ASC 94 Landing Gear Door Close - Restrictor		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC094A (970941) Airframe	ASC 94A Landing Gear Door Close - Restrictor		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC094B (970942) Airframe	ASC 94B Landing Gear Door Close - Restrictor		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
ASC095B (970952) Airframe	ASC 95B Planeview Avionics Enhancement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC096 (970960) Airframe	ASC 96 CPDLC - FANS 1/A		HRS		1265.9			4915.3			0
			AFL		301			1267			0
			MOS		67.5			15 May 2018			
			MSC								
Notes: PCW ASC 084A – ENHANCED NAVIGATION INSTALLED HAVE MET THE INTENT OF THIS INSTALLATION											
ASC097B (970972) Airframe	ASC 97B Data Link Recording		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC099 (970990) Airframe	ASC 99 Aileron and Elevator Power Disconnect - Removal		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
Notes: THIS ITEM HAS BEEN ENTERED OUT OF ORDER. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC099A (970991) Airframe	ASC 99A Aileron and Elevator Power Disconnect - Removal		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
ASC103 (971030) Airframe	ASC 103 TCAS 7.1 Installation		HRS		3320.4			2860.8			0
			AFL		821			747			0
			MOS		136.4			16 Aug 2012			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC293839											
ASC104 (971040) Airframe	ASC 104 Aileron Cable Penetrations AT FS 576.5 Floor Beam - Rework		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.3			21 Feb 2013			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC316147											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC105 (971050) Airframe	ASC 105 Automatic Dependent Surveillance - Broadcast		HRS		6181.2			0			0
	(ADS-B) Out Installation		AFL		1568			0			0
			MOS		102.5			15 Jun 2015			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708											
ASC105A (971051) Airframe	ASC 105A Automatic Dependent Surveillance - Broadcast		HRS		6181.2			0			0
	(ADS-B) Out Installation		AFL		1568			0			0
			MOS		90.5			15 Jun 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC105B (971052) Airframe	ASC 105B Automatic Dependent Surveillance - Broadcast		HRS		6181.2			0			0
	(ADS-B) Out Installation		AFL		1568			0			0
			MOS		88.2			24 Aug 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC105C (971053) Airframe	ASC 105C Automatic Dependent Surveillance - Broadcast		HRS		1864.9			4316.3			0
	(ADS-B) Out Installation		AFL		445			1123			0
			MOS		88.7			06 Aug 2016			
			MSC								
Notes: PCW ORIGINAL ISSUE - UPDATED REFERENCING GAC SAV WORK ORDER SC332708											
ASC106 (971060) Airframe	ASC 106 Fuel Quantity Signal Conditioner - Revision G		HRS		2860.1			3321.1			0
	Software		AFL		711			857			0
			MOS		124.5			15 Aug 2013			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708											
ASC107 (971070) Airframe	ASC 107 Planeview Avionics Enhancement		HRS		2860.1			3321.1			0
			AFL		711			857			0
			MOS		124.5			15 Aug 2013			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC108	ASC 108 APU Enclosure Non-Compliant Sealant - Modification		HRS		6181.2			0			0
	(971080)		AFL		1568			0			0
Airframe			DATE								
			MSC								
ASC109	ASC109 - Stabilizers (ATA 55) - Horizontal Stabilizer Interior Corrosion Inhibiting Compound (Cic) - Restorative Application, Aircraft Service Change (Mandatory)		HRS								0
	(971090)		AFL								0
Airframe			MOS			48**		18 May 2024	18 Aug 2024		
			[MOS: +3m/-3m]								
ASC110	ASC 110 Cockpit Portable FIRE Extinguisher - Relocation		HRS		6181.2			0			0
	(971100)		AFL		1568			0			0
Airframe			MOS		122.9			02 Oct 2013			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC110A PART I	ASC 110A (Part 1) Cockpit Portable FIRE Extinguisher / Pilot Seat Track Stop - Relocation		HRS		3124.6			3056.6			0
	(971101)		AFL		767			801			0
Airframe			MOS		130.3			21 Feb 2013			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC316147											
ASC111	ASC 111 Mandates Package (CPDLC / ADS-B Out)		HRS		6181.2			0			0
	(971110)		AFL		1568			0			0
Airframe			MOS		113			29 Jul 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC111A	ASC 111A Communication / Navigation (ATA 23 / 34) Mandates Package (CPDLC / ADS-B Out)		HRS		6181.2			0			0
	(971111)		AFL		1568			0			0
Airframe			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC112 (971120) Airframe	ASC 112 Elevator Hardover Prevention System (Hops) - Improvement		HRS		2357.4			3823.8			0
			AFL		600			968			0
			MOS		112.3			19 Aug 2014			
			MSC								
ASC113 (971130) Airframe	ASC 113 Planeview Avionics Enhancement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		111.4			18 Sep 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC113A (971131) Airframe	ASC 113A Planeview Avionics Enhancement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC114A (971141) Airframe	ASC 114A Automatic Dependent Surveillance - Broadcast (ADS-B) Out Version 1 Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC116 (971160) Airframe	ASC 116 Nose Landing Gear (NLG) Harness - Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		99.4			17 Sep 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC116A (971161) Airframe	ASC 116A Nose Landing Gear (NLG) Harness - Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		89.9			01 Jul 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC116B (971162) Airframe	ASC 116B Nose Landing Gear (NLG) Harness - Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		67.6			10 May 2018			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC116C (971163) Airframe	ASC 116C Nose Landing Gear (NLG) Harness - Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC117 (971170) Airframe	ASC 117 - Baggage Door Striker Plates - Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
ASC120 (971200) Airframe	ASC 120 Engine Driven Pump (Edp) Case Drain Hose Routing In Left Pylon		HRS		2159.9			4021.3			0
			AFL		548			1020			0
			MOS		108.2			23 Dec 2014			
			MSC								
ASC122 (971220) Airframe	ASC 122 Pressure Supply Line - Modification		HRS		1889.4			4291.8			0
			AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
			MSC								
Notes: SEE NOT ON CMP CARD											
ASC123 (971230) Airframe	ASC 123 Planeview Avionics Enhancement		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.5			12 Jul 2018			
			MSC								
ASC123A (971231) Airframe	ASC 123A Planeview Avionics Enhancement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		55.5			14 May 2019			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC123B (971232) Airframe	ASC 123B Planeview Avionics Enhancement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC123C (971233) Airframe	ASC 123C Planeview Avionics Enhancement		HRS		404.7			5776.5			0
			AFL		92			1476			0
			DATE		690 d			07 Feb 2022			
			MSC					-			
ASC126 (971260) Airframe	ASC 126 Cargo Lights Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
ASC126A (971261) Airframe	ASC126A - Lights (ATA 33) - Cargo Lights Replacement, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC127 (971270) Airframe	ASC 127 Led Navigation and Anticollision Strobe Light Upgrade		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
ASC128 (971280) Airframe	ASC 128 Flashlights - Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		66.2			22 Jun 2018			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC128A (971281) Airframe	ASC 128A Flashlights - Replacement		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
ASC128B (971282) Airframe	Equipment and Furnishings (ATA 25) - Flashlights – Replacement, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC129 (971290) Airframe	ASC 129 Junction Panel Relay Obsolescence Modification		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		62.1			26 Oct 2018			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC129A (971291) Airframe	ASC 129A Junction Panel Relay Obsolescence Modification		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								

ASC132 (971320) Airframe	ASC132 - Fuselage Structure (ATA 53) - Auxiliary Power Unit Enclosure Installation - Modification, Aircraft Service Change (Optional)		HRS		10.8			6170.4			0
			AFL		2			1566			0
			MOS		1.8			05 Nov 2023			
			MSC								

ASC133 (971330) Airframe	ASC 133 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED.

ASC133A PART 1 (971331) Airframe	ASC133A - Part 1 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 1 Modification Instructions (-1 Kit, Aft Equipment Bay Installation)), Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC								

ASC133A PART 2 (971332) Airframe	ASC133A - Part 2 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 2 Modification Instructions (-2 Kit, Baggage Compartment Installation)), Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC134 (971340) Airframe	ASC 134 Auxiliary Hydraulic Pump - Grounding Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
			DATE		1368 d			31 Mar 2020			
			MSC								
ASC135 (971350) Airframe	Indicating / Recording (ATA 31) - High-Speed LAN Implementation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC								
ASC136 (971360) Airframe	ASC 136 Wing to Body Fairings Av-Dec Gasket Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		66.4			18 Jun 2018			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC136A (971361) Airframe	ASC 136A Wing to Body Fairings Av-Dec Gasket Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		60.5			13 Dec 2018			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC136B (971362) Airframe	ASC 136B Wing to Body Fairings Av-Dec Gasket Installation		HRS		130.8			6050.4			0
			AFL		29			1539			0
			DATE		217 d			26 May 2023			
			MSC								
ASC137 (971370) Airframe	ASC 137 Horizontal Stabilizer Cove Panels Av-Dec Gasket Installation		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		58.3			19 Feb 2019			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC137A	ASC 137A Horizontal Stabilizer Cove Panels Av-Dec		HRS		6181.2			0			0
	Gasket Installation		AFL		1568			0			0
(971371)			DATE								
Airframe			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC137B	ASC137B - Stabilizers (ATA 55) - Horizontal Stabilizer		HRS		130.8			6050.4			0
	Cove Panels Av-Dec Gasket Installation		AFL		29			1539			0
(971372)			MOS		7.1			26 May 2023			
Airframe			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC138	ASC 138 Cabin Seat Tracks (FS 426.5 - FS 632.0) Av-		HRS		6181.2			0			0
	Dec Sealant Installation		AFL		1568			0			0
(971380)			DATE								
Airframe			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC138A	Fuselage Structure (ATA 53) - Cabin Seat Tracks (FS		HRS		130.8			6050.4			0
	426.5 - FS 632.0) Av-Dec Sealant Installation, Aircraft		AFL		29			1539			0
(971381)	Service Change (Optional)		DATE		212 d			31 May 2023			
Airframe			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC139	ASC139 - Fuselage Structure (ATA 53) Elevator Trim		HRS								0
	Servo - Bracket Installation, Aircraft Service Change		AFL								0
(971390)	(Optional)		DATE								
Airframe			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC139A	ASC139A - Fuselage Structure (ATA 53) Elevator Trim		HRS								0
	Servo - Bracket Installation, Aircraft Service Change		AFL								0
(971391)	(Optional)		DATE								
Airframe			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC143 (971430) Airframe	ASC143 - Stabilizers (ATA 55) - Horizontal Stabilizer		HRS								0
	Upper Access Panels Av-Dec Gasket - Installation, Aircraft		AFL								0
	Service Change (Optional)		DATE								
			MSC								
ASC148 (971480) Airframe	ASC148 - Communications (ATA 23) - Communications		HRS								0
	Management Function (Cmf) SATCOM Direct (Non-Sita)		AFL								0
	Datalink Service Provider, Aircraft Service Change		DATE								
	(Optional)		MSC								
ASC905 (979050) Airframe	ASC 905 Planeview Master Operating System Software		HRS		6173.3			7.9			0
	Update		AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
ASC906 (979060) Airframe	ASC 906 Planeview Master Operating System		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
ASC907 (979070) Airframe	ASC 907 Planeview Master Operating System Software		HRS		6181.2			0			0
	Update (Sv-Pfd)		AFL		1568			0			0
			DATE								
			MSC								
ASC907 AM01 (979071) Airframe	ASC 907 AM1 Planeview Master Operating System		HRS		6181.2			0			0
	Software Update (S)		AFL		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC908 (979080) Airframe	ASC 908 Planeview Master Operating System Software Update (Cert Fox)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED.

ASC908A (979081) Airframe	ASC 908A Planeview Master Operating System Software Update (Cert Fox)		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			

ASC909B (979092) Airframe	ASC 909B Planeview Master Operating System Software Update		HRS		176.2			6005			0
			AFL		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC					-			

ASC910 (979100) Airframe	ASC 910 Planeview Master Operating System Software Update		HRS		2860.1			3321.1			0
			AFL		711			857			0
			MOS		124.5			15 Aug 2013			
			MSC					-			

Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708

ASC911 (979110) Airframe	ASC 911 Planeview Master Operating System Software Update		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		111.4			18 Sep 2014			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC911A (979111) Airframe	ASC 911A Planeview Master Operating System Software Update		HRS		2357.4			3823.8			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC					-			

Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC378115

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC912 (979120) Airframe	ASC 912 Planeview Master Operating System Software Update		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.6			11 Jul 2018			
			MSC								
ASC912A (979121) Airframe	ASC 912A Planeview Master Operating System Software Update		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		55.5			14 May 2019			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC912B (979122) Airframe	ASC 912B Planeview Master Operating System Software Update		HRS		176.2			6005			0
			AFL		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
ASC912C (979123) Airframe	ASC 912C Planeview Master Operating System Software Update		HRS		404.7			5776.5			0
			AFL		92			1476			0
			DATE		690 d			07 Feb 2022			
			MSC								
BR700-78-101512^U (897839) Airframe	BR700-78-101512 - Improvements to the Thrust Reverser Pivoting Doors (Right)		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-78-101512^U (887839) Airframe	BR700-78-101512 - Improvements to the Thrust Reverser Pivoting Doors (Left)		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-78-101514^U (887840) Airframe	BR700-78-101514 - T/R Fixed Structure - Upper Inhibition Bolt Fitting (Left)		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-78-101514^U (897840) Airframe	BR700-78-101514 - T/R Fixed Structure - Upper Inhibition Bolt Fitting (Right)		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
BR700-78-101996^U (887862) Airframe	Sb BR700-78-101996 - Right Tru - Introduction of Revised Seal Supports and Inhibition Keeper		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
BR700-78-101996^U (887861) Airframe	Sb BR700-78-101996 - Left Tru - Introduction of Revised Seal Supports and Inhibition Keeper		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
BR700-78-102008 R01^U (887860) Airframe	Sb BR700-78-102008R1 - Right Tru - Introduction of A Drainage Hole Within the Thrust Reverser Fixed Structure to Prevent Corrosion.		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
BR700-78-102008 R01^U (887859) Airframe	Sb BR700-78-102008R1 - Left Tru - Introduction of A Drainage Hole Within the Thrust Reverser Fixed Structure to Prevent Corrosion.		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC					-			
BR700-78-900350^U (887850) Airframe	BR700-78-900350 - Primary Door Lock Actuator - Insp (Left)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
			MSC					-			

Notes: N/A NEW P/N INSTALLED

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-78-900350^U (897850) Airframe	BR700-78-900350 - Primary Door Lock Actuator - Insp (Right)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		202.1			26 Feb 2007			
			MSC								
Notes: N/A NEW P/N INSTALLED											
BR700-78-900350 R02^U (887853) Airframe	Sb BR700-78-900350R2 - Inspection of the Spherical Bearing of the Primary Door Lock Actuator (Pdla) and Cleaning of the S-Hook Assembly (Left)		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: PN: P466A0001-01 SN: <NONE>											
BR700-78-900350 R02^U (897853) Airframe	Sb BR700-78-900350R2 - Inspection of the Spherical Bearing of the Primary Door Lock Actuator (Pdla) and Cleaning of the S-Hook Assembly (Right)		HRS		6181.2			0			0
			AFL		1568			0			0
			DATE								
			MSC								
Notes: PN: P466A0001-01 SN: <NONE>											
CB006 (980060) Airframe	Cb 6 Ail/Elev ACT Retrofit		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
CB025 (980250) Airframe	Cb 25 - Insp Tail Anti-Coll Strobe Lt		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			17 Jan 2007			
			MSC								
CB027 AM1 (980271) Airframe	Cb 27 AM1 Replace-Aileron / Elevator ACT Load Relief Bungees		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			17 Jan 2007			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB030 (980300) Airframe	Cb 30 Decompression Vent Panels-Insp		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			
CB032 AM1 (980321) Airframe	Cb 32 AM1 - Electrical Lines Contact Prevention-MOD (ASC 57A)		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB033 (980330) Airframe	Cb 33 Enhanced Vision System Window Bonding Strap- MOD		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			
CB035 (980350) Airframe	Cb 35 Rudder Stop Bolts-Insp		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			
Notes: NO DEFECTS NOTED.											
CB036 (980360) Airframe	Cb 36 Right Pylon Case Drain Line Routing-MOD		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			
CB037 PART I (980370) Airframe	Cb 37 (PART1) Bbml Operational Limitation Placard-Insp		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			
CB037 PART II (980371) Airframe	Cb 37 (Part 2) Bbml Operational Limitation Placard-Insp		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB038 (980380) Airframe	Cb 38 Auxiliary Hydraulic Boost Pump-Insp		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
Notes: THIS CB IS FOR AIRCRAFT S/N: 5001-5123. THIS AIRCRAFT IS 5124.											
CB040 (980400) Airframe	Cb 40 MOD-Seal Nose Gear Switch		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		203.4			16 Jan 2007			
			MSC								
Notes: COMPLETED CB.											
CB041 (980410) Airframe	Cb 41 Battery Chargers - Inspection		HRS		6162.8			18.4			0
			AFL		1558			10			0
			MOS		202.9			31 Jan 2007			
			MSC								
Notes: COMPLIED WITH CB 41. BATTERY CHARGERS NOT EFFECTED PER ELDEC SB8-42-24-0. (S/N NOT EFFECTED)											
CB042 PART I (980420) Airframe	Cb 42 Insp-Trim Valve Servo Pressure Supply Part 1		HRS		6144.7			36.5			0
			AFL		1550			18			0
			MOS		202.7			06 Feb 2007			
			MSC								
CB042 PART II (980421) Airframe	Cb 42 Insp-Trim AIR Valve Servo Pressure Supply Part 2		HRS		6162.8			18.4			0
			AFL		1558			10			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: COMPLETED NO DEFECTS NOTED.											
CB043 PART I (980430) Airframe	Cb 43 Insp, Water Level Sensor Harness Part 1		HRS		6151.5			29.7			0
			AFL		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
CB043 PART II (980431) Airframe	Cb 43 Insp, Water Level Sensor Harness Part 2		HRS		6150.7			30.5			0
			AFL		1554			14			0
			MOS		202.5			15 Feb 2007			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB044 (980440) Airframe	Cb 44 Right Eng Integrated Drive Generator Cable Inst, MOD		HRS		6144.7			36.5			0
			AFL		1550			18			0
			MOS		202.1			26 Feb 2007			
			MSC								
CB045 (980450) Airframe	Cb 45 Aux Hyd Boost Pump Circuit Protection, MOD (ASC 059)		HRS		597.1			5584.1	0		0
			AFL		124			1444	0		0
			MOS		31.3			21 May 2021			
			MSC								
CB046 (980460) Airframe	Cb 46 No. 2 ADF Antenna Lead Instl AT F.S. 288		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		199.5			14 May 2007			
			MSC								
Notes: NA BY AIRCRAFT SN											
CB047 (980470) Airframe	Cb 47 APU Enclosure Sensor Instl - Insp		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB049 (980490) Airframe	Cb 49 MOD-Left and Right Power Distribution Box (Pdb)		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB050 (980500) Airframe	Cb 50 Insp- Left Main Batt Lead Instl AT Wing Anti-Ice Valve		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB051 (980510) Airframe	Cb 51 Broadband Multi-Link (Bbml) Antenna Control Unit- Insp		HRS		5884.3			296.9			0
			AFL		1483			85			0
			MOS		196			28 Aug 2007			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB053 (980530) Airframe	Cb 53 - Modification - Broadband Multi-Link Antenna Installation		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB053A (980531) Airframe	Cb 53A - Modification - Broadband Multi-Link Antenna Installation		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB055 (980550) Airframe	Cb 55 Local AREA Network (LAN) Connectors - Inspection		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB055 AM2 (980552) Airframe	Cb 55 AM2 Local AREA Network (LAN) Connectors - Inspection		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB057 (980570) Airframe	Cb 57 FMS Wiring Harness Inst AT Fuselage Sta 63 Bkhd		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								
CB058 (980580) Airframe	Cb 58 Nose Landing Gear Door Actuator (ASC 070)		HRS		5725.4			455.8			0
			AFL		1438			130			0
			MOS		191.6			09 Jan 2008			
			MSC								
CB060 (980600) Airframe	Cb 60 Modification-Tail Compartment Door Seal		HRS		5725.3			455.9			0
			AFL		1438			130			0
			MOS		191.3			21 Jan 2008			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB062 (980620) Airframe	Cb 62 Inspection-Flap Drive ROD Installation		HRS		5616.4			564.8			0
			AFL		1401			167			0
			MOS		189.3			19 Mar 2008			
			MSC					-			
CB065 (980650) Airframe	Cb 65 Auxiliary Power Unit (APU) Bond Strap Installation (ASC 066)		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB066 PART I (980660) Airframe	Cb 66 PT 1 - Inspection - Fuel Metering Unit - Independent Overspeed Protection Coil Wiring		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB066 PART II (980661) Airframe	Cb 66 PT 2 - Inspection - Fuel Metering Unit - Independent Overspeed Protection Coil Wiring		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB067 (980670) Airframe	Cb 67 Inspection-Fuel Boost Pump Manifolds		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.2			22 Dec 2010			
			MSC					-			
Notes: CUSTOMER REQUEST FREQUENCY TO BE CHANGED TO LINE UP WIHT CODE 575007, SEE ATTACHMENT SO 4-11-18											
CB069 (980690) Airframe	Cb 69 MOD-Nose Gear Uplock Hook Spring (ASC 73)		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB070 (980700) Airframe	Cb 70 Replacement-Tee Clips AT FS. 734, Left No. 3 and No.4 Stringers		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB071 (980710) Airframe	Cb 71 Inspect-Water System Drain Valve		HRS		5350.4			830.8			0
			AFL		1317			251			0
			MOS		182.3			21 Oct 2008			
			MSC					-			
CB072 (980720) Airframe	Cb 72 MOD-Main Landing Gear Emergency Line (ASC 79)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3	-4297		21 May 2021			
			MSC					-			
CB074 (980740) Airframe	Cb 74 - Flight Spoiler Actuator Attachment Point - Inspection		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
CB074A (980741) Airframe	Cb 74A - Flight Spoiler Actuator Attachment Point - Inspection		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB074A AM1 (980742) Airframe	Cb 74A AM1- Flight Spoiler Actuator Attachment Point - Inspection		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
CB075 (980750) Airframe	Cb 75 Inspection-Rudder Cable Guide Bracket		HRS		4503.1			1678.1			0
			AFL		1088			480			0
			MOS		161			28 Jul 2010			
			MSC					-			
CB078 (980780) Airframe	Cb 78 - Inspection - HF-9000 Series, Fiber Optic Connector Crimping		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB080 (980800) Airframe	Cb 80 MOD - Tail Compartment Access Ladder (ASC 082)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
CB080A (980801) Airframe	Cb 80A MOD - Tail Compartment Access Ladder (ASC 082A)		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
CB081 (980810) Airframe	Cb 81 - Divan Seat Belt Anchor Installation		HRS		5255.6			925.6			0
			AFL		1288			280			0
			MOS		179.1			26 Jan 2009			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
CB083 (980830) Airframe	Cb 83 Modification- Wing Rear Beam Flight Spoiler Actuator Attachment Point (ASC 80)		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			
CB083 AM1 (980831) Airframe	Cb 83 AM1 Modification- Wing Rear Beam Flight Spoiler Actuator Attachment Point (ASC 80)		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			
CB086 (980860) Airframe	Cb 86 Modification - Sealing of Nose Wheel Steering Electrical Connectors		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			
CB087 (980870) Airframe	Cb 87 Global Positioning System Cable Installation AT Fuselage Station 139		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB088 (980880) Airframe	Cb 88 Baggage Compartment Below Floor - Overheat Thermal Switch		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB088A (980881) Airframe	Cb 88A Baggage Compartment Below Floor - Overheat Thermal Switch		HRS		4830.6			1350.6			0
			AFL		1172			396			0
			MOS		167.5			15 Jan 2010			
			MSC								
CB089 (980890) Airframe	Cb 89 Replacement - Power Distribution Box Contactors, Pn 5912336-3		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB090 (980900) Airframe	Cb 90 Inspection - Winslow Life Raft		HRS		4692.4			1488.8			0
			AFL		1142			426			0
			MOS		165.2			22 Mar 2010			
			MSC								
CB091 (980910) Airframe	Cb 91 Modification - Nose Jack Point		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB092 (980920) Airframe	Cb 92 Modification - Pilot / Copilot Seat - Forward / Aft Adjustment Control Lever		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB093 (980930) Airframe	Cb 93 Inspection - Horizontal Stabilizer Actuator		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB096	Cb 96 Replacement - Emergency Brake Accumulator and Landing Gear Emergency Extension Nitrogen Blow-Down Bottle Charging Valves		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.3			21 Dec 2010			
			MSC								
(980960)											
Airframe											
CB098	Cb 98 Repair - Right System Hydraulic Reservoir		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(980980)											
Airframe											
CB098A	Cb 98A Repair - Right System Hydraulic Reservoir		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(980981)											
Airframe											
CB101 PART I	Cb 101 (Part I) Inspection - Portable Oxygen Bottle Secondary Mask Assembly		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(981010)											
Airframe											
CB101 PART II	Cb 101 (Part II) Inspection - Portable Oxygen Bottle Secondary Mask Assembly		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(981011)											
Airframe											
CB102	Cb 102 Modification - Emergency Battery Pack		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			18 Dec 2010			
			MSC								
(981020)											
Airframe											
CB103	Cb 103 Inspection - Fasteners AT Fuselage Station 63, Left and Right Butt Line 19		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(981030)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB104 (981040) Airframe	Cb 104 Inspection - Engine Electronic Controller Lane A Harness 1A		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB106 (981060) Airframe	Cb 106 Fuel Quantity Signal Conditioner to Install Revision F Software		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB106A (981061) Airframe	Cb 106A Replacement - Fuel Quantity Signal Conditioner to Install Revision F Software		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB107 (981070) Airframe	Cb 107 Inspection - Door Control Valve Hydraulic Lines		HRS		4281.8			1899.4			0
			AFL		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
CB108 (981080) Airframe	Cb 108 - Inspection - Left Engine Hydraulic Pressure Line		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
CB110 (981100) Airframe	Cb 110 Modification - Landing Gear Door Close - Restrictor Installation (ASC 094)		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
CB110A (981101) Airframe	Cb 110A Modification - Landing Gear Door Close - Restrictor Installation (ASC 094)		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB111 (981110) Airframe	Cb 111 Inspection - Enhanced Vision System (Evs) Radome Support Strut, P/N 1159SCAM561-1		HRS		3856.1			2325.1			0
			AFL		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
CB112 (981120) Airframe	Cb 112 Modification - Tail Compartment Ladder Attach Fittings		HRS		3521.5			2659.7			0
			AFL		865			703			0
			MOS		141.5			14 Mar 2012			
			MSC								
CB113 (981130) Airframe	Cb 113 Modification - Broadband Multi-Link (Bbml) Antenna		HRS		3521.5			2659.7			0
			AFL		865			703			0
			MOS		141.5			14 Mar 2012			
			MSC								
CB114 (981140) Airframe	Cb 114 Non-Compliance - Stage 3 Noise Certification (ASC 008B)		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.8			03 Aug 2015			
			MSC								
Notes: CUSTOMER DECLINED											
CB116 (981160) Airframe	Cb 116 Inspection - Engine / Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief Discharge Port		HRS		3681.3			2499.9			0
			AFL		902			666			0
			MOS		145.4			18 Nov 2011			
			MSC								
CB117A (981171) Airframe	Cb 117A Inspection - Flight Data Recorder (FDR) and Cockpit Voice Recorder (Cvr) Mounting Hardware		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2974		13 May 2021			
			MSC								
CB119 PART I (981190) Airframe	Cb 119 Inspection (Part I) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS		3521.5			2659.7			0
			AFL		865			703			0
			MOS		153.5			14 Mar 2011			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB119 PART II	Cb 119 Inspection (Part Ii) - Auxiliary Power Unit (APU)		HRS		6181.2			0			0
	Enclosure Thermal Barrier Coating		AFL		1568			0			0
	(981191)		MOS		118.2			24 Feb 2014			
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB119A PART I	Cb 119A Inspection (Part I) - Auxiliary Power Unit (APU)		HRS		3521.5			2659.7			0
	Enclosure Thermal Barrier Coating		AFL		865			703			0
	(981192)		MOS		153.5			14 Mar 2011			
	Airframe		MSC								
CB119A PART II	Cb 119A Inspection (Part Ii) - Auxiliary Power Unit (APU)		HRS		1912.4			4268.8			0
	Enclosure Thermal Barrier Coating		AFL		474			1094			0
	(981193)		MOS		100.8			03 Aug 2015			
	Airframe		MSC								
CB122	Cb 122 Replacement - Fuel Boost Pumps, P/N		HRS		3320.4			2860.8			0
	1159SCP500-5		AFL		821			747			0
	(981220)		MOS		136.4			16 Aug 2012			
	Airframe		MSC								
CB122A	Cb 122A Replacement - Fuel Boost Pumps, P/N		HRS		1901.5			4279.7			0
	1159SCP500-5		AFL		464			1104			0
	(981221)		MOS		91.5			13 May 2016			
	Airframe		MSC								
Notes: "PREVIOUSLY COMPLIED WITH."											
CB123	Cb 123 Inspection - Rudder Actuator Pressure Monitoring		HRS		3320.4			2860.8			0
	Port Plugs		AFL		821			747			0
	(981230)		MOS		136.4			16 Aug 2012			
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB123A	Cb 123A Inspection - Rudder Actuator Pressure		HRS		3320.4			2860.8			0
	Monitoring Port Plugs		AFL		821			747			0
			MOS		136.4			16 Aug 2012			
	(981231)			MSC							
Airframe											
CB124	Cb 124 Replacement - Nose Wheel Steering Collar		HRS		3320.4			2860.8			0
	Hardware		AFL		821			747			0
			MOS		136.4			16 Aug 2012			
	(981240)			MSC							
Airframe											
CB125	Cb 125 Removal - Aileron and Elevator Power Disconnect		HRS		6181.2			0			0
	(ASC 099)		AFL		1568			0			0
			MOS		128.9			01 Apr 2013			
	(981250)			MSC							
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB125A	Cb 125A Removal - Aileron and Elevator Power		HRS		3124.6			3056.6			0
	Disconnect (ASC 099)		AFL		767			801			0
			MOS		130.2			22 Feb 2013			
	(981251)			MSC							
Airframe											
CB126A	Cb 126A Software Modification - Digital Flight Data		HRS		597.1			5584.1			0
	Recorder		AFL		124			1444			0
			MOS		31.5	-2455		13 May 2021			
	(981261)			MSC							
Airframe											
CB127	Cb 127 Inspection - Xm Weather Antenna Doubler		HRS		597.1			5584.1	0		0
	Installation		AFL		124			1444	0		0
			MOS		31.5			13 May 2021			
	(981270)			MSC							
Airframe											
Notes: N/A BY P/N INSTALLED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB128 (981280) Airframe	Cb 128 Inspection - Aft Equipment Bay / Engine Pylon Temperature Sensor Switches		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2405		13 May 2021			
			MSC								
CB129A (981291) Airframe	Cb 129A - Replacement - Elevator Horn Bearings		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2377		13 May 2021			
			MSC								
CB130 (981300) Airframe	Cb 130 Aileron Cable Feed-Thru Holes AT FS 576.5 (ASC 104)		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
CB131 (981310) Airframe	Cb 131 Inspection - Cabin Window Seals		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-1604		13 May 2021			
			MSC								
CB132 (981320) Airframe	Cb 132 - Flight Controls (ATA 27), Inspection - Gust Lock Handle Assembly on Aircraft With ASC 002		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
CB132A (981321) Airframe	Cb 132A Flight Controls (ATA 27), Inspection - Gust Lock Handle Assembly on Aircraft With ASC 002		HRS		3124.6			3056.6			0
			AFL		767			801			0
			MOS		130.2			22 Feb 2013			
			MSC								
CB133A (981331) Airframe	Cb 133A FIRE Protection, Modification - Relocation of Third Engine FIRE Bottle		HRS		597.1			5584.1	0		0
			AFL		124			1444	0		0
			MOS		31.5			13 May 2021			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB134 (981340) Airframe	Cb 134 - Inspection - Tail Cone Anticollision Light - Fault Indicator Wiring		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2556		13 May 2021			
			MSC								
CB135 (981350) Airframe	Cb 135 - Replacement - Main Battery Chargers		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		125.8			05 Jul 2013			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB135A (981351) Airframe	Cb 135A - Replacement - Main Battery Chargers		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB136 (981360) Airframe	Cb 136 - Modification - Plug-In Monitors, P/N 7002-260 and 7002-261, Installed With Avds		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
			MSC								
CB137 (981370) Airframe	Cb 137 - Inspection - AIR Inlet Door Actuator		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
			MSC								
CB138 (981380) Airframe	Cb 138 - Replacement - AIR Inlet Door Actuator		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2493		14 May 2021			
			MSC								
CB139 (981390) Airframe	Cb 139 - Inspection - Outboard Rudder Trim Cable Installation AT Fuselage Station 733		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2409		14 May 2021			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB140	Cb 140 - Inspection - Fuel Boost Pump Electromagnetic Interference (Emi) Filter Connectors		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2348		14 May 2021			
			MSC								
(981400)											
Airframe											
CB141	Cb 141 Inspection - Main Landing Gear Timers - Striker ARM Shaft		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
(981410)											
Airframe											
CB142	Cb 142 - Replacement - Motive Flow Lines for Mid-Wing Fuel Ejector (ASC 063A)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-1222		14 May 2021			
			MSC								
(981420)											
Airframe											
CB143	Cb 143 - Inspection - Engine Removable Fairings - Non-Conformance		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5			14 May 2021			
			MSC								
(981430)											
Airframe											
CB144	Cb 144 - Inspection - Passenger Oxygen System - Tube Assembly Bonding		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2306		14 May 2021			
			MSC								
(981440)											
Airframe											
CB145	Cb 145 Elevator Hardover Prevention System (Hops) Improvement (ASC 112)		HRS		2357.4			3823.8			0
			AFL		600			968			0
			MOS		112.3			19 Aug 2014			
			MSC								
(981450)											
Airframe											
CB146	Cb 146 - Inspection - Transformer Rectifier Unit (Tru) Feeder Cable Clamp Installation		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2190		14 May 2021			
			MSC								
(981460)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB147 (981470) Airframe	Cb 147 - Inspection - Right Electrical Equipment Rack (Reer) Circuit Breaker Terminals		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2190		14 May 2021			
			MSC								
CB148 (981480) Airframe	Cb 148 - Inspection - Pressure Relief Valve Remote AIR Filter		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.5	-2169		14 May 2021			
			MSC								
CB149 (981490) Airframe	Cb 149 Inspection - Auxiliary Power Unit (APU) Mount Pallet Shimming		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB149A (981491) Airframe	Cb 149A Inspection - Auxiliary Power Unit (APU) Mount Pallet Shimming		HRS		2357.7			3823.5			0
			AFL		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
CB150 (981500) Airframe	Cb 150 Modification - Aircraft Main Battery Chargers		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		110.8			03 Oct 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB150A (981501) Airframe	Cb 150A Modification - Aircraft Main Battery Chargers		HRS		1889.3			4291.9			0
			AFL		454			1114			0
			MOS		89.5			13 Jul 2016			
			MSC								
CB150B (981502) Airframe	Cb 150B Modification - Aircraft Main Battery Chargers		HRS		1840.2			4341			0
			AFL		442			1126			0
			MOS		87.5			15 Sep 2016			
			MSC								
Notes: PCW ORIGINAL ISSUE IN JET AVIATION GENEVA											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB151	Cb 151 - Inspection - Cockpit Center Pedestal Assembly -		HRS		597.1			5584.1			0
	Gust Lock Bell Crank Bearings		AFL		124			1444			0
	(981510)		MOS		31.5	-1706		14 May 2021			
	Airframe		MSC								
CB152	Cb 152 - Inspection - Forward Cabin Pocket Door		HRS		597.1			5584.1			0
	Bulkhead AT FS 265		AFL		124			1444			0
	(981520)		MOS		31.5	-2064		14 May 2021			
	Airframe		MSC								
CB153	Cb 153 - Inspection - Cockpit Overhead Circuit Breaker		HRS		2159.9			4021.3			0
	Panels		AFL		548			1020			0
	(981530)		MOS		107.5			14 Jan 2015			
	Airframe		MSC								
CB154	Cb 154 Inspection - Rudder Actuator Aft ROD End		HRS		2159.9			4021.3			0
	Attaching Hardware		AFL		548			1020			0
	(981540)		MOS		107.5			14 Jan 2015			
	Airframe		MSC								
Notes: THIS ITEM HAS BEEN ENTERED OUT OF ORDER. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB154A	Cb 154A Inspection - Rudder Actuator Aft ROD End		HRS		2159.9			4021.3			0
	Attaching Hardware		AFL		548			1020			0
	(981541)		MOS		107.5			14 Jan 2015			
	Airframe		MSC								
CB155	Cb 155 Inspection - Engine Driven Pump (Edp) Case		HRS		2159.9			4021.3			0
	Drain Hydraulic Hose - Left Engine Pylon (ASC 120)		AFL		548			1020			0
	(981550)		MOS		108.2			23 Dec 2014			
	Airframe		MSC								
CB156A	Cb 156A Replacement - Engine Driven Pump (Edp)		HRS		597.1			5584.1			0
	Hydraulic Damper		AFL		124			1444			0
	(981561)		MOS		31.5	-1772		14 May 2021			
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB157 (981570) Airframe	Cb 157 Inspection - Main Landing Gear Door Actuator		HRS		2094.4			4086.8			0
			AFL		521			1047			0
			MOS		105.8			05 Mar 2015			
			MSC								
Notes: END CAP											
CB158 (981580) Airframe	Cb 158 Inspection - Heated Fuel Return Line Coupling Nut Subassembly		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.4			16 Aug 2015			
			MSC								
CB158A (981581) Airframe	Cb 158A Inspection - Heated Fuel Return Line Coupling Nut Subassembly		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC								
CB159 (981590) Airframe	Cb 159 Replacement - Main Landing Gear Door Actuator End CAP - Life Limit		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.4			17 Aug 2015			
			MSC								
CB160 (981600) Airframe	Cb 160 Modification - Pressure Supply Line (ASC 122)		HRS		1912.4			4268.8			0
			AFL		474			1094			0
			MOS		100.4			16 Aug 2015			
			MSC								
CB160A (981601) Airframe	Cb 160A Modification - Pressure Supply Line (ASC 122)		HRS		1889.4			4291.8			0
			AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
			MSC								
Notes: "PREVIOUSLY COMPLIED WITH"											
CB161 (981610) Airframe	Cb 161 Inspection - Elevator Hinge Brackets		HRS		1910.5			4270.7			0
			AFL		473			1095			0
			MOS		94.9			02 Feb 2016			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB163	Cb 163 Modification - Nose Landing Gear Electrical		HRS		6181.2			0			0
	Harness Installation (ASC 116A)		AFL		1568			0			0
			MOS		82.5			15 Feb 2017			
	(981630)		MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB163A	Cb 163A Modification - Nose Landing Gear Electrical		HRS		1689.6			4491.6			0
	Harness Installation (ASC 116B)		AFL		406			1162			0
			MOS		82.8			03 Feb 2017			
	(981631)		MSC								
Airframe											
Notes: NOT CW ASC 116											
CB164 PART I	Cb 164 Modification - Spoiler Throwboard Mounting Point		HRS		1910.5			4270.7			0
	(Part 1)		AFL		473			1095			0
			MOS		95			28 Jan 2016			
	(981640)		MSC								
Airframe											
CB164 PART II	Cb 164 Modification - Spoiler Throwboard Mounting Point		HRS		1910.5			4270.7			0
	(PART2)		AFL		473			1095			0
			MOS		94.9			02 Feb 2016			
	(981641)		MSC								
Airframe											
CB164A	Cb 164A Modification - Spoiler Throwboard Mounting		HRS		1326.1			4855.1			0
	Points		AFL		312			1256			0
			MOS		68.8			05 Apr 2018			
	(981642)		MSC								
Airframe											
Notes: N/A PREVIOUSLY COMPLIED WITH CB 164.											
CB165	Cb 165 Nose Wheel Steering Hydraulic Line Contact With		HRS		597.1			5584.1			0
	Structure		AFL		124			1444			0
			MOS		31.3			20 May 2021			
	(981650)		MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB166 (981660) Airframe	Cb 166 Inspection - Rudder Actuator Return Line for Contact With Elevator Torque Tube		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC								
CB167 (981670) Airframe	Cb 167 Inspection - Engine Stage 5 AIR Nonreturn Valve		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			04 Jul 2018			
			MSC								
CB168 (981680) Airframe	Cb 168 - Inspection - Landing Gear Extension/Retraction Hydraulic Lines.		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3	-1237		20 May 2021			
			MSC								
CB169 (981690) Airframe	Cb 169 Inspection - Wire Installation In Right Electrical Equipment Rack (Reer) Circuit Breaker (Cb) Panel		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC								
CB170 (981700) Airframe	Cb 170 Inspection - Connector Pins In Baggage Electronic Equipment Rack (Beer)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB171 (981710) Airframe	Cb 171 Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve		HRS		1889.4			4291.8			0
			AFL		454			1114			0
			MOS		89.4			18 Jul 2016			
			MSC								
CB171A (981711) Airframe	Cb 171A Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve		HRS		1476.7			4704.5			0
			AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB172	Cb 172 Inspection - Cockpit Overhead Circuit Breaker		HRS		1476.7			4704.5			0
	Panels - Location G3		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	(981720)		MSC								
Airframe											
Notes: N/A. NO CIRCUIT BREAKER INSTALLED IN G3 LOCATION.											
CB173	Cb 173 Inspection - Thrust Reverser Primary Door Lock		HRS		597.1			5584.1			0
	Actuator Hydraulic Connections (Rolls-Royce Nmsb Sb-		AFL		124			1444			0
	BR700-78-900590)		MOS		31.3			20 May 2021			
	(981730)		MSC								
Airframe											
CB174	Cb 174 Inspection - Rudder Actuator Hard Over		HRS		1476.7			4704.5			0
	Protection System (Hops) Wiring Harness Installation		AFL		350			1218			0
			MOS		75.5			15 Sep 2017			
	(981740)		MSC								
Airframe											
CB175	Cb 175 Modification - Pedestal Assembly Edge Light		HRS		6181.2			0			0
	Panel Upgrade		AFL		1568			0			0
			MOS		89.2			22 Jul 2016			
	(981750)		MSC								
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB175A	Cb 175A Modification - Pedestal Assembly Edge Light		HRS		597.1			5584.1			0
	Panel Upgrade		AFL		124			1444			0
			MOS		31.3			20 May 2021			
	(981751)		MSC								
Airframe											
CB176 (LT IB)	Cb 176 Inspection - Main Landing Gear Wheel Bearings -		HRS		1245.7			4935.5			0
	Non-Conforming (Left Inboard Wheel)		AFL		296			1272			0
			MOS		66.1			26 Jun 2018			
	(981761)		MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB176 (LT OB) (981760) Airframe	Cb 176 Inspection - Main Landing Gear Wheel Bearings - Non-Conforming (Left Outboard Wheel)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1			26 Jun 2018			
			MSC								
CB176 (RT IB) (981762) Airframe	Cb 176 Inspection - Main Landing Gear Wheel Bearings - Non-Conforming (Right Inboard Wheel)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1			26 Jun 2018			
			MSC								
CB176 (RT OB) (981763) Airframe	Cb 176 Inspection - Main Landing Gear Wheel Bearings - Non-Conforming (Right Outboard Wheel)		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		66.1			26 Jun 2018			
			MSC								
CB177 (981770) Airframe	Cb 177 Inspection - Main Fuel Line Installation		HRS		1245.7			4935.5			0
			AFL		296			1272			0
			MOS		65.8			04 Jul 2018			
			MSC								
CB178 (981780) Airframe	Cb 178 Inspection - Landing Gear Emergency Extension Right Nitrogen Blow-Down Bottle		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB179 (981790) Airframe	Cb 179 Inspection - Lateral Flight Control ROD Ends - Wing Trailing Edge (Triumph Sb-Tagv/Gvsp-27-JG0170)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB180 (981800) Airframe	Cb 180 Replacement - Engine Electronic Controller (Eec) Firebox Assembly (Rolls-Royce Sb-BR700-73-A101981 / Sb-BR700-73-A101985)		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.1			25 Mar 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB181 (981810) Airframe	Cb 181 Inspection - Feeder Cable Installation AT Fuselage Station 169, Stringer 19 Right		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB182 (981820) Airframe	Cb 182 Auxiliary Power Unit (APU) Filter Bypass Indicator Valve (Honeywell Sb RE220-49-8218)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB183 (981830) Airframe	Cb 183 Inspection - Life Raft Mooring Line		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB184 (981840) Airframe	Cb 184 Inspection - Fuel Line Couplings In Pylon		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB185B (981852) Airframe	Cb 185B Life Raft Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470 / Sb 25-476)		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB186 (981860) Airframe	Cb 186 Inspection - Elevator Trim Servo Bracket Mount		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB187 (981870) Airframe	Cb 187 Modification - Auxiliary Hydraulic Pump Grounding Installation (ASC 134)		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		44.9			31 Mar 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB188 (981880) Airframe	Cb 188 Inspection - Main Landing Gear Hydraulic Brake Fuses		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3	-774		20 May 2021			
			MSC								
CB189 (981890) Airframe	Cb 189 Inspection - Horizontal Stabilizer Vortex Generator Configuration		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		56			30 Apr 2019			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB189A (981891) Airframe	Cb 189A Inspection - Horizontal Stabilizer Vortex Generator Configuration		HRS		96.5			6084.7	0		0
			AFL		22			1546	0		0
			MOS		6.1			25 Jun 2023			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB189B (981892) Airframe	Cb 189B Inspection - Horizontal Stabilizer Vortex Generator Configuration		HRS		321.8			5859.4			0
			AFL		68			1500			0
			MOS		18			28 Jun 2022			
			MSC								
CB190 PART I (981900) Airframe	Cb 190 (Part 1) Inspection - Horizontal Stabilizer Lower Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		60.3			21 Dec 2018			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB190 PART II (981901) Airframe	Cb 190 (Part 2) Inspection - Horizontal Stabilizer Lower Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		HRS		6181.2			0			0
			AFL		1568			0			0
			MOS		60.3			21 Dec 2018			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB190A PART I	Cb 190A (Part 1) Inspection - Horizontal Stabilizer Lower		HRS		96.5			6084.7	0		0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		22			1546	0		0
	(981902)		MOS		6.1			25 Jun 2023			
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB190A PART II	Cb 190A (Part 2) Inspection - Horizontal Stabilizer Lower		HRS		96.5			6084.7	0		0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		22			1546	0		0
	(981903)		MOS		6.1			25 Jun 2023			
	Airframe		MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB190B PART I	Cb 190B (Part 1) Inspection - Horizontal Stabilizer Lower		HRS		665.8			5515.4			0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		150			1418			0
	(981904)		MOS		43.1			26 May 2020			
	Airframe		MSC								DUE**
CB190B PART II	Cb 190B (Part 2) Inspection - Horizontal Stabilizer Lower		HRS		665.8			5515.4			0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		150			1418			0
	(981905)		MOS		43.4			18 May 2020			
	Airframe		MSC								
CB190B PART III	Cb 190B (Part 3) Inspection - Horizontal Stabilizer Lower		HRS		665.8			5515.4			0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		150			1418			0
	(981906)		DATE		1320 d			18 May 2020			
	Airframe		MSC								
CB191	Cb 191 Inspection - Wing Internal - Integral Fuel Tank		HRS		597.1			5584.1			0
	Coating		AFL		124			1444			0
	(981910)		MOS		31.3			20 May 2021			
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB192 (981920) Airframe	Cb 192 - Left Engine Thrust Reverser Hydraulic Supply Line and Clips (Rolls Royce Sb-BR700-29-900644)		HRS		1044.7			5136.5			0
			AFL		245			1323			0
			MOS		58.5			12 Feb 2019			
			MSC								
CB193 (981930) Airframe	Cb 193 Replacement - Emergency Batteries Not Repaired Per Manufacturer Instructions		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3	-153		20 May 2021			
			MSC								
CB194 (981940) Airframe	Cb 194 Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		597.1			5584.1	0		0
			AFL		124			1444	0		0
			MOS		31.3			20 May 2021			
			MSC								
Notes: N/A - HONEYWELL KA-BAND NOT INSTALLED, AIRCRAFT EQUIPPED WITH BBML (KU-BAND)											
CB194A (981941) Airframe	Cb 194A Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		96.5			6084.7	0		0
			AFL		22			1546	0		0
			MOS		6.1			25 Jun 2023			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
CB194B (981942) Airframe	Cb 194B Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB195 (981950) Airframe	Cb 195 Inspection - Right Electronic Equipment Rack Panel Latch - Contact With Wiring		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB196 (981960) Airframe	Cb 196 Inspection - Display Unit Tray Assembly, Ground Strap Plating Flaking		HRS		404.7			5776.5			0
			AFL		92			1476			0
			MOS		23.1			27 Jan 2022			
			MSC								
CB197 (981970) Airframe	Cb 197 Inspection - Lavatory Blower Pressure Switch Sensing Port		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
			MSC								
CB198 (981980) Airframe	Cb 198 Replacement - Life Raft Containing SRB406 ELT		HRS		597.1			5584.1			0
			AFL		124			1444			0
			MOS		31.3			20 May 2021			
			MSC								
CB199 (981990) Airframe	Cb 199 Modification - Jetwave System BLV7.1 Software Release (Honeywell Sb Jetwave-23-007)		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.5			13 Mar 2020			
			MSC								
CB200 (982000) Airframe	Cb 200 Flight Controls (ATA 27), Inspection - Aileron Force Link Wiring Harness Installation		HRS		665.8			5515.4			0
			AFL		150			1418			0
			MOS		45.3			19 Mar 2020			
			MSC								
CB201 (982010) Airframe	Cb 201 Inspection - Outboard Flight Spoiler Bellcrank		HRS								0
			AFL								0
			DATE								
			MSC								
CB201A (982011) Airframe	Cb 201A Flight Controls (ATA 27) - Inspection - Outboard Flight Spoiler Bellcrank, Customer Bulletin		HRS		404.7			5776.5			0
			AFL		92			1476			0
			MOS		23.4			17 Jan 2022			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB201B (982012) Airframe	CB201B - Flight Controls (ATA 27) - Inspection - Outboard Flight Spoiler Bellcrank, Customer Bulletin (Mandatory)		HRS		404.7			5776.5			0
			AFL		92			1476			0
			MOS		23.4			18 Jan 2022			
			MSC								
CB203 (982030) Airframe	Cb 203 Installation - Horizontal Stabilizer Cove Panels Av-Dec Gaskets (ASC 137A)		HRS		130.8			6050.4			0
			AFL		29			1539			0
			MOS		7.1			26 May 2023			
			MSC								
CB209 (982090) Airframe	Engine Fuel and Control (ATA 73) - Replacement – Engine Fuel Control Dedicated Generator (Rolls-Royce Sb BR700-73-101856), Customer Bulletin		HRS		176.2			6005			0
			AFL		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
CB209A (982091) Airframe	Engine Fuel and Control (ATA 73) - Replacement - Engine Fuel Control Dedicated Generator (Rolls-Royce Sb BR700-73-101856), Customer Bulletin (Mandatory)		HRS		321.4			5859.8			0
			AFL		67			1501			0
			MOS		17.5			13 Jul 2022			
			MSC								
CB209B (982092) Airframe	CB209B - Engine Fuel and Control (ATA 73) - Replacement - Engine Fuel Control Dedicated Generator (Rolls-Royce Sb BR700-73-101856), Customer Bulletin (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC								
CB213A (982131) Airframe	CB213A - Communications (ATA 23) - Modification - Jetwave System BLV8.1 Software Release (Honeywell Sb Jetwave-23-0009), Customer Bulletin (Mandatory)		HRS								0
			AFL								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB214	CB214 - Ice and Rain Protection (ATA 30) - Inspection -		HRS		404.7			5776.5	0		0
	Wing Anti-Ice Supply Duct Installation Behind Landing		AFL		92			1476	0		0
	Light (Temp Suspended See G550-Mol-22-0002),		MOS		23.5			14 Jan 2022			
	Customer Bulletin (Mandatory)		MSC								
(982140)	Airframe										
CB215	CB215 - FIRE Protection (ATA 26) - Inspection - Engine		HRS		130.8			6050.4			0
	FIRE Bottle Thermal Relief Discharge Port, Customer		AFL		29			1539			0
	Bulletin		MOS		8.3			21 Apr 2023			
			MSC								
(982150)	Airframe										
CB216	CB216 - Stabilizers (ATA 55) - Horizontal Stabilizer Interior		HRS		176.2			6005			0
	Preventative Corrosion Inhibiting Compound (Cic)		AFL		38			1530			0
	Application, Customer Bulletin (Mandatory)		MOS		11.8			03 Jan 2023			
			MSC								
(982160)	Airframe										
CB217	CB217 - Engine Controls (ATA 76), Inspection - Throttle		HRS		176.2			6005			0
	Quadrant, Customer Bulletin (Mandatory)		AFL		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
(982170)	Airframe										
CB218	CB218 - Stabilizers (ATA 55) - Horizontal Stabilizer Interior		HRS		96.5			6084.7			0
	Mrb Report Task 55.10.00/10 - Maintenance Program		AFL		22			1546			0
	Initiation, Customer Bulletin (Mandatory)		DATE		187 d			25 Jun 2023			
			MSC								
(982180)	Airframe										
CB219	CB219 - Electrical Power (ATA 24) - Inspection - Aircraft		HRS		10.8			6170.4			0
	Main Batteries (Saft SB0323), Customer Bulletin		AFL		2			1566			0
	(Mandatory)		MOS		1.8			05 Nov 2023			
			MSC								
(982190)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB219A	Electrical Power (ATA 24) - Inspection – Aircraft Main		HRS								0
	Batteries (Saft SB0323), Customer Bulletin (Mandatory)		AFL								0
	(982191)		MOS								
	Airframe		MSC								
CB220	CB220 - Communications (ATA 23) - Replacement -		HRS								0
	Satellite Data Units (Sdu) DL150-00, Customer Bulletin		AFL								0
	(982200)		MOS								
	Airframe		MSC								
CS 26.170^U	Cs 26.170 - Task Description: Lavatory Halon FIRE		HRS								0
	Extinguisher		AFL								0
	PN	SN-UNKNOWN	MOS								
	Airframe		MSC								
CSB019	Ce-Csb-5019 - CSB019 - Cabin Systems - Advanced		HRS								0
	Cabin Server (Acs) (Gen 4) Cabin View Software Update,		AFL								0
	(940190)		DATE								
	Airframe		MSC								
CSB-5008	Ce-Csb-5008 (Csb-008) Gulfstream Cabin Management		HRS		1864.9			4316.3			0
	System (Gcms) Firmware Update		AFL		445			1123			0
	(940080)		MOS		88.7			06 Aug 2016			
	Airframe		MSC								
Notes: N/A BY A/C S/N											
CSB-5009	Ce-Csb-5009 (Csb-009) Advanced Cabin Server (Acs)		HRS		1864.9			4316.3			0
	System Software Update		AFL		445			1123			0
	(940090)		MOS		88.7			06 Aug 2016			
	Airframe		MSC								
Notes: N/A BY A/C S/N											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ST00892LA (901022) Airframe	ST00892LA Emergency Vision Assurance System (EVAS)		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA DOCUMENT: 8017 AND WARRANTY DOCUMENT #8018, REV. B PAGE 3											
ST02047CH-D (901071) Airframe	ST02047CH-D Magnastar MCS-7000		HRS		6173.6			7.6			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA GC51104A000 REV. - DATED 4/19/2005											
ST02048CH-D (901072) Airframe	ST02048CH-D Airshow 4000 System		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA GC51504A001 REV. - DATED 4/9/2005											
ST02049CH-D (901073) Airframe	ST02049CH-D Securaplane 500		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: NOTE: SEE CMP CODES 237225, 237228, 237235, AND 232245 FOR ICA REQUIREMENTS ICA GC51456A000 REV. - DATED 4-19-2005											
ST02696AT-D (901001) Airframe	ST02696AT-D Pax Oxy Control		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA GC51453A003 REV. B DATED 8/25/2004											
ST02697AT-D (901007) Airframe	ST02697AT-D Emergency Lighting		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA GC51 486A002 REV. A DATED 2/12/2004											
ST02699AT-D (901009) Airframe	ST02699AT-D Atg Window Shades		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC								
Notes: ICA GC51506A001 REV. - DATED 7/21/2003											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ST02715AT-D (901010) Airframe	ST02715AT-D External Camera		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC					-			

Notes: ICA GC51505A005 REV. B DATED 9/5/2004

ST02796AT-D (901024) Airframe	ST02796AT-D Broad Band Multi-Link Sys (Bbml)		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC					-			

Notes: ICA GC51303A005 REV. - DATED 5/8/2006

ST02915AT-D (901023) Airframe	ST02915AT-D Lsz-860 Lightning Detector		HRS		6173.3			7.9			0
			AFL		1562			6			0
			MOS		202.7			06 Feb 2007			
			MSC					-			

Notes: ICA GC51225A000 REV. - DATED 4/5/2005

SIAE - APU/Engine Service Information/Bulletins

49-7933 R05 (957935) APU	APU - Sb 49-7933 R05 Airborne Auxiliary Power Unit		HRS		4190.5			0			0
	(APU) Oil - General - Approved Oils		APUS		0			0			0
			MOS		95			29 Jan 2016			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

49-7933 R06 (957936) APU	APU - Sb 49-7933 R06 Airborne Auxiliary Power Unit		HRS		4190.5			0			0
	(APU) Oil - General - Approved Oils		APUS		0			0			0
			MOS		81.5			13 Mar 2017			
			MSC					-			

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

49-7933 R08 (957938) APU	APU - Sb 49-7933 R08 Airborne Auxiliary Power Unit		HRS		4190.5			0			0
	(APU) Oil - General - Approved Oils		APUS		0			0			0
			DATE								
			MSC					DUE**			

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49-8252	APU - 49-8252 - Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial Apus		HRS		4190.5			0			0
(958252)			APUS		0			0			0
APU			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
880320	No. 1 Engine - Sb BR700-73-900423 - One Time Inspection of Eec Firebox Assembly for Paint Damage		HRS		6181.2			0			0
(880320)			ENC		1568			0			0
Engine			MOS		111.6			09 Sep 2014			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708											
880320 (890320)	No. 2 Engine - Sb BR700-73-900423 - One Time Inspection of Eec Firebox Assembly for Paint Damage		HRS		6181.2			0			0
(880320)			ENC		1568			0			0
Engine			MOS		111.6			09 Sep 2014			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC332708											
888819	No. 1 Engine - Sb BR700-72-101144 (Use Cmp Code 880271)		HRS		6151.5			29.7			0
(888819)			ENC		1555			13			0
Engine			MOS		210.7			08 Jun 2006			
			MSC								
888819 (898819)	No. 2 Engine - Sb BR700-72-101144 (Use Cmp Code 880271)		HRS		6151.5			29.7			0
(888819)			ENC		1555			13			0
Engine			MOS		210.7			08 Jun 2006			
			MSC								
888822	No. 1 Engine - Use Cmp Code 880422 / 890422		HRS		6151.5			29.7			0
(888822)			ENC		1555			13			0
Engine			MOS		210.7			08 Jun 2006			
			MSC								
888822 (888822)	No. 2 Engine - Use Cmp Code 880422 / 890422		HRS		6151.5			29.7			0
(888822)			ENC		1555			13			0
Engine			MOS		210.7			08 Jun 2006			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
APU-49 R11	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC								
APU											
Notes: THIS CODE HAS BEEN CANCELLED.											
APU-49 R12	APU - Sil APU-49 R12 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC								
(950011)											
APU											
APU-49 R13	APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC								
(950012)											
APU											
BR700-29-102142	No. 1 Engine - Sb BR700-29-102142 - Left Engine Hydraulic Tubes and Fittings (Ebu) - Introduction of Clips With Higher Strength		HRS								0
			ENC								0
			DATE								
			MSC								
(882915)											
Engine											
BR700-29-102142 (892915)	No. 2 Engine - Sb BR700-29-102142 - Left Engine Hydraulic Tubes and Fittings (Ebu) - Introduction of Clips With Higher Strength		HRS								0
			ENC								0
			DATE								
			MSC								
(882915)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-29-900511	No. 1 Engine - Sb BRR700-29-900511 Left Engine -		HRS		3856.1			2325.1			0
	Hydraulic Tubes and Fittings		ENC		950			618			0
	(882900)		MOS		148.7			06 Aug 2011			
	Engine		MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC253220											
BR700-29-900511	No. 2 Engine - Sb BRR700-29-900511 Left Engine -		HRS		3856.1			2325.1			0
	Hydraulic Tubes and Fittings		ENC		950			618			0
	(882900)		MOS		148.7			06 Aug 2011			
	Engine		MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC253220											
BR700-29-900644	No. 1 Engine - Sb BR700-29-900644 - Left Engine		HRS		1044.7			5136.5			0
	Hydraulic Tubes and Fittings Engine Build Unit (Ebu) -		ENC		245			1323			0
	Inspection of Clips and Tubes		MOS		58.5			12 Feb 2019			
	(880660)		MSC								
Engine											
BR700-29-900644 (890660)	No. 2 Engine - Sb BR700-29-900644 - Left Engine		HRS			5096.8					0
	Hydraulic Tubes and Fittings Engine Build Unit (Ebu) -		ENC		1568			0			0
	Inspection of Clips and Tubes		MOS								
	(880660)		MSC								
Engine											
Notes: REMOVE FREQUENCY ONCE CW											
BR700-29-900644 R01	No. 1 Engine - Sb BR700-29-900644 R01 - Left Engine		HRS		665.8		2000	5515.4	7515.4		0
	Hydraulic Tubes and Fittings (Ebu) - Inspection of Clips		ENC		150			1418			0
	and Tubes		MOS		45.3			19 Mar 2020			
(882916)											
Engine											
BR700-29-900644 R01 (892916)	No. 2 Engine - Sb BR700-29-900644 R01 - Left Engine		HRS		665.8			5515.4			0
	Hydraulic Tubes and Fittings (Ebu) - Inspection of Clips		ENC		150			1418			0
	and Tubes		DATE		1310 d			28 May 2020			
	(882916)		MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-70-900040 R11 (887001) Engine	No. 1 Engine - Sb BR700-70-900040 (Rev 14) - Engine		HRS		6151.5			29.7			0
	Life Management - Fixed Interval Rework Engines		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											
BR700-70-900040 R11 (897001) (887001) Engine	No. 2 Engine - Sb BR700-70-900040 (Rev 14) - Engine		HRS		6151.5			29.7			0
	Life Management - Fixed Interval Rework Engines		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											
BR700-70-900294 R03 (887002) Engine	No. 1 Engine - Sb BR700-70-900294 Rev 3 - Task		HRS		6151.5			29.7			0
	Oriented Engine Inspection		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											
BR700-70-900294 R03 (897002) (887002) Engine	No. 2 Engine - Sb BR700-70-900294 Rev 3 - Task		HRS		6151.5			29.7			0
	Oriented Engine Inspection		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											
BR700-70-900412 (887003) Engine	No. 1 Engine - Sb BR700-70-900412 - BR710 Engine		HRS		6151.5			29.7			0
	Maint Prog		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											
BR700-70-900412 (897003) (887003) Engine	No. 2 Engine - Sb BR700-70-900412 - BR710 Engine		HRS		6151.5			29.7			0
	Maint Prog		ENC		1555			13			0
			MOS		202.3			20 Feb 2007			
			MSC								
Notes: ENGINE DECLARED TASK ORIENTED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-101206 (887166) Engine	No. 1 Engine - Sb BR700-71-101206 - Power Plant		HRS		6151.5			29.7			0
	External Drain Tubes and Fitting		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-71-101206 (897166) (887166) Engine	No. 2 Engine - Sb BR700-71-101206 - Power Plant		HRS		6151.5			29.7			0
	External Drain Tubes and Fitting		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-71-102131 (888017) Engine	No. 1 Engine - Sb BR700-71-102131 - Drains System		HRS								0
	Collection Tank - Introduction of Thicker Bracket for the		ENC								0
	Fuel Drains Tank		DATE								
			MSC								
BR700-71-102131 (898017) (888017) Engine	No. 2 Engine - Sb BR700-71-102131 - Drains System		HRS								0
	Collection Tank - Introduction of Thicker Bracket for the		ENC								0
	Fuel Drains Tank		DATE								
			MSC								
BR700-71-900505 (887195) Engine	No. 1 Engine - Sb BR700-71-900505 Eec Lane A Harness		HRS		4281.8			1899.4			0
	- Inspection		ENC		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
BR700-71-900505 (897195) (887195) Engine	No. 2 Engine - Sb BR700-71-900505 Eec Lane A Harness		HRS		4281.8			1899.4			0
	- Inspection		ENC		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-100981 (880237) Engine	No. 1 Engine - Sb BR700-72-100981 - Lp Impact Adhesive and Filler		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-100981 (890237) (880237) Engine	No. 2 Engine - Sb BR700-72-100981 - Lp Impact Adhesive and Filler		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101195 (880285) Engine	No. 1 Engine - Sb BR700-72-101195 - Intermediate Compressor Case		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101195 (890285) (880285) Engine	No. 2 Engine - Sb BR700-72-101195 - Intermediate Compressor Case		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101203 (880287) Engine	No. 1 Engine - Sb BR700-72-101203 - Hpc Variable Guide Vanes Actuating Mechanism		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101203 (890287) (880287) Engine	No. 2 Engine - Sb BR700-72-101203 - Hpc Variable Guide Vanes Actuating Mechanism		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101349 (880414) Engine	No. 1 Engine - Sb BR700-72-101349 - Fuel Shutoff Cable		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101349 (890414) (880414) Engine	No. 2 Engine - Sb BR700-72-101349 - Fuel Shutoff Cable		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101410 (880572) Engine	No. 1 Engine - Sb BR700-72-101410 - Hp Alternative Part Number for Hp Turbine		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101410 (890572) (880572) Engine	No. 2 Engine - Sb BR700-72-101410 - Hp Alternative Part Number for Hp Turbine		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101414 (880422) Engine	No. 1 Engine - Sb BR700-72-101414 - Hpc Front Case - New Coated Brushes		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.2			23 Feb 2007			
			MSC								
Notes: N/A BY ENG S/N											
BR700-72-101414 (890422) (880422) Engine	No. 2 Engine - Sb BR700-72-101414 - Hpc Front Case - New Coated Brushes		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		202.2			23 Feb 2007			
			MSC								
Notes: N/A BY ENG S/N											
BR700-72-101419 (880425) Engine	No. 1 Engine - Sb BR700-72-101419 - Hpc Vigv Actuating Mechanism		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101419 (890425) (880425) Engine	No. 2 Engine - Sb BR700-72-101419 - Hpc Vlgv Actuating Mechanism		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101431 (880428) Engine	No. 1 Engine - Sb BR700-72-101431 Hp Turbine Stage 1 Nozzle Guide Seals		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101431 (890428) (880428) Engine	No. 2 Engine - Sb BR700-72-101431 Hp Turbine Stage 1 Nozzle Guide Seals		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101463 (880437) Engine	No. 1 Engine - Sb BR700-72-101463 - Engine Hp Compressor Rear Inner Case		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101463 (890437) (880437) Engine	No. 2 Engine - Sb BR700-72-101463 - Engine Hp Compressor Rear Inner Case		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-72-101469 R01 (880611) Engine	No. 1 Engine - Sb BR700-72-101469 R1 - Hp Compressor Vortex Reducer Ring		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101469 R01 (890611) (880611) Engine	No. 2 Engine - Sb BR700-72-101469 R1 - Hp Compressor Vortex Reducer Ring		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101474 R01 (880581) Engine	No. 1 Engine - Sb BR700-72-101474R1 - Laser Shock		HRS		176.2			6005			0
	Peened Lp Compressor Rotor Disc		ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
BR700-72-101474 R01 (890581) (880581) Engine	No. 2 Engine - Sb BR700-72-101474R1 - Laser Shock		HRS		176.2			6005			0
	Peened Lp Compressor Rotor Disc		ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
BR700-72-101476 R01 (880612) Engine	No. 1 Engine - Sb BR700-72-101476R1 - Introduction of A		HRS		6181.2			0			0
	New Combustion Chamber Without Cooling Ribs		ENC		1568			0			0
			MOS		98.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101476 R01 (890612) (880612) Engine	No. 2 Engine - Sb BR700-72-101476R1 - Introduction of A		HRS		6181.2			0			0
	New Combustion Chamber Without Cooling Ribs		ENC		1568			0			0
			MOS		98.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101540 R04 (880613) Engine	No. 1 Engine - Sb BR700-72-101540 R4 - Outlet Guide		HRS		6181.2			0			0
	Vane Housing Assembly		ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101540 R04 (890613) (880613) Engine	No. 2 Engine - Sb BR700-72-101540 R4 - Outlet Guide		HRS		6181.2			0			0
	Vane Housing Assembly		ENC		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101550 R01 (883007) Engine	No. 1 Engine - Sb BR700-72-101550R1 - Deletion of Breather Filter and Changes to Breather Cover, Tank Covers and Obturator Plate		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101550 R01 (893007) (883007) Engine	No. 2 Engine - Sb BR700-72-101550R1 - Deletion of Breather Filter and Changes to Breather Cover, Tank Covers and Obturator Plate		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101837 (883006) Engine	No. 1 Engine - Sb BR700-72-101837 - Introduction of an Hp Turbine Stage 1 Disc Made from A Different Material		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101837 (893006) (883006) Engine	No. 2 Engine - Sb BR700-72-101837 - Introduction of an Hp Turbine Stage 1 Disc Made from A Different Material		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101858 (880610) Engine	No. 1 Engine - Sb BR700-72-101858 - Introduction of A Hp Compressor Stages 7 to 10 Rotor Disc Assembly With Revised Liner Coating		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		98.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101858 (890610) (880610) Engine	No. 2 Engine - Sb BR700-72-101858 - Introduction of A Hp Compressor Stages 7 to 10 Rotor Disc Assembly With Revised Liner Coating		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		98.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-72-101891	No. 1 Engine - Sb BR700-72-101891 - Introduction of A		HRS		6181.2			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1568			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		105.4			18 Mar 2015			
			MSC								

(880614)

Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 (890614)	No. 2 Engine - Sb BR700-72-101891 - Introduction of A		HRS		6181.2			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1568			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		105.4			18 Mar 2015			
			MSC								

(880614)

Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R02	No. 1 Engine - Sb BR700-72-101891R2 - Introduction of A		HRS		6181.2			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1568			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		64.1			27 Aug 2018			
			MSC								

(880644)

Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R02 (890644)	No. 2 Engine - Sb BR700-72-101891R2 - Introduction of A		HRS		6181.2			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1568			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		64.1			27 Aug 2018			
			MSC								

(880644)

Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R03	No. 1 Engine - Sb BR700-72-101891R3 - Introduction of A		HRS		6181.2			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1568			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		DATE								
			MSC								

(880654)

Engine

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101891 R03 (890654) (880654) Engine	No. 2 Engine - Sb BR700-72-101891R3 - Introduction of A Redesigned Gearline 12 Assembly Which Is Balanced Including the Permanent Magnetic Alternator (PMA) Rotor		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101897 (880615) Engine	No. 1 Engine - Sb BR700-72-101897 - Introduction of an Alternative Standard of Hp Compressor Stage 1 Blade		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101897 (890615) (880615) Engine	No. 2 Engine - Sb BR700-72-101897 - Introduction of an Alternative Standard of Hp Compressor Stage 1 Blade		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101969 (880645) Engine	No. 1 Engine - Sb BR700-72-101969 - Introduction of A New Fan Shaft Assembly With an Additional Inspection Method During the Manufacturing Process		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-101969 (890645) (880645) Engine	No. 2 Engine - Sb BR700-72-101969 - Introduction of A New Fan Shaft Assembly With an Additional Inspection Method During the Manufacturing Process		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102038 (880157) Engine	No. 1 Engine - Sb BR700-72-102038 - Low Pressure Compressor Internal Gearbox AIR Distribution Tubes - Introduction of A New AIR Manifold Housing		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102038 (890157) (880157) Engine	No. 2 Engine - Sb BR700-72-102038 - Low Pressure Compressor Internal Gearbox AIR Distribution Tubes - Introduction of A New AIR Manifold Housing		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102070 (880657) Engine	No. 1 Engine - Sb BR700-72-102070- Introduction of Alternative Drain Plugs AT the Engine Oil Tank Drain Location of the Accessory Gearbox		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102070 (890657) (880657) Engine	No. 2 Engine - Sb BR700-72-102070- Introduction of Alternative Drain Plugs AT the Engine Oil Tank Drain Location of the Accessory Gearbox		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102102 (880648) Engine	No. 1 Engine - Sb BR700-72-102102 - Introduction of an Intermediate Case With Alternative Bushes Made from A Different Material		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102102 (890648) (880648) Engine	No. 2 Engine - Sb BR700-72-102102 - Introduction of an Intermediate Case With Alternative Bushes Made from A Different Material		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-72-102139 (888830) Engine	No. 1 Engine - Engine - Low Pressure (Lp) Compressor Nose Cone Assembly - Introduction of A Nose Cone Assembly With A Modified Nose Cone Coating, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102139	No. 2 Engine - Engine - Low Pressure (Lp) Compressor		HRS								0
	Nose Cone Assembly - Introduction of A Nose Cone		ENC								0
	Assembly With A Modified Nose Cone Coating, Service		DATE								
	Bulletin (Optional)		MSC				-				
(888830)	Engine										
BR700-72-102167	No. 1 Engine - Low Pressure (Lp) Turbine Fuel Shut-Off		HRS								0
	(Fso) Cable and Fittings - Introduction of A New Conduit		ENC								0
	Assembly for the Fuel Shut-Off Mechanism, Service		DATE								
	Bulletin (Optional)		MSC				-				
(888841)	Engine										
BR700-72-102167	No. 2 Engine - Low Pressure (Lp) Turbine Fuel Shut-Off		HRS								0
	(Fso) Cable and Fittings - Introduction of A New Conduit		ENC								0
	Assembly for the Fuel Shut-Off Mechanism, Service		DATE								
	Bulletin (Optional)		MSC				-				
(888841)	Engine										
BR700-72-102169	No. 1 Engine - Internal Gearbox Drive-Driven Assembly -		HRS								0
	Introduction of an Alternative Spirallock Insert for the		ENC								0
	Radial Drive Shaft (Rds) Lower Support Housing, Service		DATE								
	Bulletin (Optional)		MSC				-				
(888831)	Engine										
BR700-72-102169 (898831)	No. 2 Engine - Internal Gearbox Drive-Driven Assembly -		HRS								0
	Introduction of an Alternative Spirallock Insert for the		ENC								0
	Radial Drive Shaft (Rds) Lower Support Housing, Service		DATE								
	Bulletin (Optional)		MSC				-				
(888831)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102322	No. 1 Engine - BR700-72-102322 - Accessory Gearbox		HRS								0
	Module and Accessory Gearbox Module Attach Parts and		ENC								0
	Fittings - Introduction of Alternative Accessory Gearbox		DATE								
	Components, Service Bulletin (Optional)		MSC								
(888859)											
Engine											
BR700-72-102322 (898859)	No. 2 Engine - BR700-72-102322 - Accessory Gearbox		HRS								0
	Module and Accessory Gearbox Module Attach Parts and		ENC								0
	Fittings - Introduction of Alternative Accessory Gearbox		DATE								
	Components, Service Bulletin (Optional)		MSC								
(888859)											
Engine											
BR700-72-900369	No. 1 Engine - Sb BR700-72-900369 - HPT1, Ngv & Cric		HRS		6151.5			29.7			0
	Borescope		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(880579)											
Engine											
BR700-72-900369 (890579)	No. 2 Engine - Sb BR700-72-900369 - HPT1, Ngv & Cric		HRS		6151.5			29.7			0
	Borescope		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(880579)											
Engine											
BR700-72-900409	No. 1 Engine - Sb BR700-72-900409 - Lp Compressor		HRS		2357.4			3823.8			0
	Case		ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
(880567)											
Engine											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC378115											
BR700-72-900409 (890567)	No. 2 Engine - Sb BR700-72-900409 - Lp Compressor		HRS		2357.4			3823.8			0
	Case		ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
(880567)											
Engine											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC378115											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900455 R01 (887256) Engine	No. 1 Engine - Sb BR700-72-900455 Rev 1 Visual Insp -		HRS		6181.2			0			0
	Lp Compressor Annulus Fillers		ENC		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC185345											
BR700-72-900455 R01 (897256) (887256) Engine	No. 2 Engine - Sb BR700-72-900455 Rev 1 Visual Insp -		HRS		6181.2			0			0
	Lp Compressor Annulus Fillers		ENC		1568			0			0
			MOS		118.2			24 Feb 2014			
			MSC								
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC185345											
BR700-72-900521 R01 PART A (880591) Engine	No. 1 Engine - Sb BR700-72-900521 (Part A) Rev 1-		HRS		3856.1			2325.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		950			618			0
			MOS		148.5			12 Aug 2011			
			[End Of Month Item]								
BR700-72-900521 R01 PART A (890591) (880591) Engine	No. 2 Engine - Sb BR700-72-900521 (Part A) Rev 1-		HRS		3856.1			2325.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		950			618			0
			MOS		148.5			12 Aug 2011			
			[End Of Month Item]								
BR700-72-900521 R01 PART B (880592) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Rev 1-		HRS		3856.1			2325.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								
BR700-72-900521 R01 PART B (890592) (880592) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Rev 1-		HRS		3856.1			2325.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		950			618			0
			MOS		148.5			12 Aug 2011			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900521 R02 PART A (880589) Engine	No. 1 Engine - Sb BR700-72-900521 (Part A) Rev 2 - Inspection - Lp Compressor Annulus Fillers		HRS		3521.5			2659.7			0
			ENC		865			703			0
			MOS		141.5			14 Mar 2012			
			[End Of Month Item]								
BR700-72-900521 R02 PART A (890589) (880589) Engine	No. 2 Engine - Sb BR700-72-900521 (Part A) Rev 2 - Inspection - Lp Compressor Annulus Fillers		HRS		3521.5			2659.7			0
			ENC		865			703			0
			MOS		141.5			14 Mar 2012			
			[End Of Month Item]								
BR700-72-900521 R02 PART B (880590) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Rev 2 - Inspection - Lp Compressor Annulus Fillers		HRS		3521.5			2659.7			0
			ENC		865			703			0
			MOS		141.5			14 Mar 2012			
			[End Of Month Item]								
BR700-72-900521 R02 PART B (890590) (880590) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Rev 2 - Inspection - Lp Compressor Annulus Fillers		HRS		3521.5			2659.7			0
			ENC		865			703			0
			MOS		141.5			14 Mar 2012			
			[End Of Month Item]								
BR700-72-900521 R03 PART B (880603) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Rev 3 - Inspection - Lp Compressor Annulus Fillers		HRS		3124.6			3056.6			0
			ENC		767			801			0
			MOS		130.2			22 Feb 2013			
			[End Of Month Item]								
BR700-72-900521 R03 PART B (890603) (880603) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Rev 3 - Inspection - Lp Compressor Annulus Fillers		HRS		3124.6			3056.6			0
			ENC		767			801			0
			MOS		130.2			22 Feb 2013			
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900668	No. 1 Engine - Low Pressure (Lp) Compressor Case -		HRS								0
	Inspection Under the Fan Track Liner on Lp Compressor		ENC								0
	Cases of Pre Sb-BR700-72-100981 Standard - Non-		DATE								
	Modification Service Bulletin, Service Bulletin (Recommended)		MSC				ESV**				
(888832)	Engine										
BR700-72-900668	No. 2 Engine - Low Pressure (Lp) Compressor Case -		HRS								0
	Inspection Under the Fan Track Liner on Lp Compressor		ENC								0
	Cases of Pre Sb-BR700-72-100981 Standard - Non-		DATE								
	Modification Service Bulletin, Service Bulletin (Recommended)		MSC				ESV**				
(888832)	Engine										
BR700-72-900743	No. 1 Engine - BR700-72-900743 - Low Pressure (Lp)		HRS								0
	Compressor Rotor Disc - Ultrasonic Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		MOS								
	Bulletin, Service Bulletin (Recommended)		MSC				-				
(888857)	Engine										
BR700-72-900743 (898857)	No. 2 Engine - BR700-72-900743 - Low Pressure (Lp)		HRS								0
	Compressor Rotor Disc - Ultrasonic Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		MOS								
	Bulletin, Service Bulletin (Recommended)		MSC				-				
(888857)	Engine										
BR700-72- A101523 R03	No. 1 Engine - BR700-72-A101523 R03 - Engine - Low		HRS		1902.1			4279.1			0
	Pressure (Lp) Turbine Shut-Off Pawl Carrier - Introduction		ENC		471			1097			0
	of Fuel Shut-Off Pawl Carrier Pivot Pins Made from A		MOS		94.3			19 Feb 2016			
	Different Material With Improved Corrosion Protection Properties		MSC				-				
(880128)	Engine										

Notes: N/A BY S/N

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A101523 R03 (890128)	No. 2 Engine - BR700-72-A101523 R03 - Engine - Low Pressure (Lp) Turbine Shut-Off Pawl Carrier - Introduction		HRS		1902.1			4279.1			0
	of Fuel Shut-Off Pawl Carrier Pivot Pins Made from A Different Material With Improved Corrosion Protection Properties		ENC		471			1097			0
			MOS		94.3			19 Feb 2016			
			MSC								
(880128)											
Engine											
Notes: N/A BY S/N											
BR700-72- A101962 R02^U	No. 1 Engine - Sb BR700-72-A101962 R02 - Introduction of Mount Pins With Revised Material on A Magnesium Accessory Gearbox		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		44.7			06 Apr 2020			
			MSC								
(880647)											
Engine											
Notes: SB BR700-72-A101962R2 IS N/A DUE TO CURRENT ENGINE HARDWARE CONFIGURATION STANDARD INSTALLED (710C4-11).											
BR700-72- A101962 R02 (890647)^U	No. 2 Engine - Sb BR700-72-A101962 R02 - Introduction of Mount Pins With Revised Material on A Magnesium Accessory Gearbox		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		44.7			06 Apr 2020			
			MSC								
(880647)											
Engine											
Notes: SB BR700-72-A101962R2 IS N/A DUE TO CURRENT ENGINE HARDWARE CONFIGURATION STANDARD INSTALLED (710C4-11).											
BR700-72- A900504 (880044)	No. 1 Engine - Asb BR700-72-A900504 Change of Life Counting Method for Touch-and-Go and Overshoot		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
(880044)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-72- A900504 (890044)	No. 2 Engine - Asb BR700-72-A900504 Change of Life Counting Method for Touch-and-Go and Overshoot		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
(880044)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900509 R04 (880339) Engine	No. 1 Engine - Alert Sb BR700-72-A900509 (Revision 4)		HRS		2357.7			3823.5			0
	Replacement of the Fuel Pump Splined Coupling		ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833											
BR700-72- A900509 R04 (890339) (880339) Engine	No. 2 Engine - Alert Sb BR700-72-A900509 (Revision 4)		HRS		2357.7			3823.5			0
	Replacement of the Fuel Pump Splined Coupling		ENC		600			968			0
			MOS		112.2			22 Aug 2014			
			MSC								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833											
BR700-72- A900509 R05 (888854) Engine	No. 1 Engine - Sb BR700-72-A900509 R05 - Accessory		HRS								0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC								0
	Coupling - Non-Modification Service Bulletin, Alert Service		DATE								
	Bulletin (Optional)		MSC								
BR700-72- A900509 R05 (888854) Engine	No. 2 Engine - Sb BR700-72-A900509 R05 - Accessory		HRS								0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC								0
	Coupling - Non-Modification Service Bulletin, Alert Service		DATE								
	Bulletin (Optional)		MSC								
BR700-72- A900659 R01 PART A (880661) Engine	No. 1 Engine - Alert Sb BR700-72-A900659 R1 - Part A		HRS		656.1			5525.1			0
	Replacement of the Hp Turbine Stage 1 Discs		ENC		148			1420			0
			MOS		42.5			12 Jun 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900659 R01 PART A (890661) (880661) Engine	No. 2 Engine - Alert Sb BR700-72-A900659 R1 - Part A		HRS		656.1			5525.1			0
	Replacement of the Hp Turbine Stage 1 Discs		ENC		148			1420			0
			MOS		42.5			12 Jun 2020			
			MSC								
BR700-72- A900659 R01 PART B (880662) Engine	No. 1 Engine - Alert Sb BR700-72-A900659 R1 - Part B		HRS		656.1			5525.1			0
	Replacement of the Hp Turbine Stage 1 Discs		ENC		148			1420			0
			MOS		42.5			12 Jun 2020			
			MSC								
BR700-72- A900659 R01 PART B (890662) (880662) Engine	No. 2 Engine - Alert Sb BR700-72-A900659 R1 - Part B		HRS		656.1			5525.1			0
	Replacement of the Hp Turbine Stage 1 Discs		ENC		148			1420			0
			MOS		42.5			12 Jun 2020			
			MSC								
BR700-72- A900732 (888855) Engine	No. 1 Engine - Sb BR700-72-A900732 - Low Pressure		HRS		321.4			5859.8			0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp		ENC		67			1501			0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE		534 d			13 Jul 2022			
	Bulletin, Alert Service Bulletin (Alert)		MSC								
BR700-72- A900732 (888855) Engine	No. 2 Engine - Sb BR700-72-A900732 - Low Pressure		HRS		321.4			5859.8			0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp		ENC		67			1501			0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE		534 d			13 Jul 2022			
	Bulletin, Alert Service Bulletin (Alert)		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900732 R01	No. 1 Engine - BR700-72-A900732 R01 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp -		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								
(888856)	Engine										
BR700-72- A900732 R01 (898856)	No. 2 Engine - BR700-72-A900732 R01 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp -		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								
(888856)	Engine										
BR700-73-101376	No. 1 Engine - Sb BR700-73-101376 - Combination of		HRS		6181.2			0			0
	Eec Hardware Standard		ENC		1568			0			0
			DATE								
			MSC								
(880302)	Engine										
BR700-73-101376 (890302)	No. 2 Engine - Sb BR700-73-101376 - Combination of		HRS		6181.2			0			0
	Eec Hardware Standard		ENC		1568			0			0
			DATE								
			MSC								
(880302)	Engine										
BR700-73-101380	No. 1 Engine - Sb BR700-73-101380 - Introduction of an		HRS		6151.5			29.7			0
	Eed With A New Hardware Standard		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(880303)	Engine										
BR700-73-101380 (890303)	No. 2 Engine - Sb BR700-73-101380 - Introduction of an		HRS		6151.5			29.7			0
	Eed With A New Hardware Standard		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(880303)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101415 (887361) Engine	No. 1 Engine - Sb BR700-73-101415 - Fuel System - Flexible AIR Tubes		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-73-101415 (897361) (887361) Engine	No. 2 Engine - Sb BR700-73-101415 - Fuel System - Flexible AIR Tubes		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
BR700-73-101438 R04 (880325) Engine	No. 1 Engine - Sb BR700-73-101438R4 - External Dressings for New Standard of Engine Electronic Controller		HRS		1084.4			5096.8			0
			ENC		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: "PREVIOUSLY COMPLIED WITH" - ASC 96A C/W 925.6 H 280 C 26 JAN 2009."THIS SERVICE BULLETIN MUST BE DONE AT THE SAME TIME AS SB-BR700-73-101496"											
BR700-73-101438 R04 (890325) (880325) Engine	No. 2 Engine - Sb BR700-73-101438R4 - External Dressings for New Standard of Engine Electronic Controller		HRS		1084.4			5096.8			0
			ENC		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: "PREVIOUSLY COMPLIED WITH" - ASC 69A C/W 925.6 H 280 C 26 JAN 2009."THIS SERVICE BULLETIN MUST BE DONE AT THE SAME TIME AS SB-BR700-73-101496"											
BR700-73-101438 R05 (888843) Engine	No. 1 Engine - Engine Fuel and Control - External Fuel System AIR Tubes and Fittings - Introduction of External Dressings Changes for New Standard of Engine Electronic Controller (Eec), Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
BR700-73-101438 R05 (888843) Engine	No. 2 Engine - Engine Fuel and Control - External Fuel System AIR Tubes and Fittings - Introduction of External Dressings Changes for New Standard of Engine Electronic Controller (Eec), Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101438 R05 PART 1	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes With Replacement of the Bypass Duct (Production Standard) (Optional)		MSC				-				
(880777)											
Engine											
BR700-73-101438 R05 PART 1 (890777)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes With Replacement of the Bypass Duct (Production Standard) (Optional)		MSC				-				
(880777)											
Engine											
BR700-73-101438 R05 PART 2	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes Without Replacement of the Bypass Duct (Retrofit Standard) (Optional)		MSC				-				
(880778)											
Engine											
BR700-73-101438 R05 PART 2 (890778)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes Without Replacement of the Bypass Duct (Retrofit Standard) (Optional)		MSC				-				
(880778)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101438 R05 PART 3	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin RE-Introduction of Bypass Duct Access Panel Attaching Bolts of Pre Service Bulletin Sb-BR700-72- 101286 Standard (Optional)		MSC								
(880780)											
Engine											
BR700-73-101438 R05 PART 3 (890780)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin RE-Introduction of Bypass Duct Access Panel Attaching Bolts of Pre Service Bulletin Sb-BR700-72- 101286 Standard (Optional)		MSC								
(880780)											
Engine											
BR700-73-101443	No. 1 Engine - Sb BR700-73-101443 - Engine Fuel and		HRS		6151.5			29.7			0
	Control (DEP)		ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(887367)											
Engine											
BR700-73-101443 (897367)	No. 2 Engine - Sb BR700-73-101443 - Engine Fuel and		HRS		6181.2			0			0
	Control (DEP)		ENC		1568			0			0
			DATE								
			MSC								
(887367)											
Engine											
BR700-73-101496 R03	No. 1 Engine - Sb BR700-73-101496 Rev 3 - Eec		HRS		1084.4			5096.8			0
	Hardware and Software		ENC		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
(880315)											
Engine											

Notes: "PREVIOUSLY COMPLIED WITH" - ASC 69A C/W 925.6 H 280 C 26 JAN 2009."THIS SERVICE BULLETIN MUST BE DONE AT THE SAME TIME AS SB-BR700-73-101438"

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101496 R03 (890315) (880315) Engine	No. 2 Engine - Sb BR700-73-101496 Rev 3 - Eec		HRS		1084.4			5096.8			0
	Hardware and Software		ENC		252			1316			0
			MOS		61.4			17 Nov 2018			
			MSC								
Notes: "PREVIOUSLY COMPLIED WITH" - ASC 69A C/W 925.6 H 280 C 26 JAN 2009."THIS SERVICE BULLETIN MUST BE DONE AT THE SAME TIME AS SB-BR700-73-101438"											
BR700-73-101558 (880316) Engine	No. 1 Engine - Sb BR700-73-101558 - Fuel Flow		HRS		6181.2			0			0
	Transmitter (Fft)		ENC		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-73-101558 (890316) (880316) Engine	No. 2 Engine - Sb BR700-73-101558 - Fuel Flow		HRS		6181.2			0			0
	Transmitter (Fft)		ENC		1568			0			0
			DATE								
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-73-101833 R02 (880340) Engine	No. 1 Engine - Sb BR700-73-101833R2 - Introduction of A		HRS		2357.7			3823.5			0
	Revised Drive Shaft Connection for the Fuel Pump		ENC		600			968			0
			DATE								
			MSC								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833											
BR700-73-101833 R02 (890340) (880340) Engine	No. 2 Engine - Sb BR700-73-101833R2 - Introduction of A		HRS		2357.7		4000**	3823.5	7823.5		0
	Revised Drive Shaft Connection for the Fuel Pump		ENC		600			968			0
			MOS								
Notes: TERMINATING ACTION IS COMPLIANCE OF SB BR700-73-101833											
BR700-73-101833 R03 (888847) Engine	No. 1 Engine - BR700-73-101833 R03 - Engine Fuel and		HRS								0
	Control - Fuel Pump - Introduction of A Revised Drive		ENC								0
	Shaft Connection for the Fuel Pump, Service Bulletin		DATE								
	(Optional)		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-73-101833 R03 (898847)	No. 2 Engine - BR700-73-101833 R03 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised Drive Shaft Connection for the Fuel Pump, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888847) Engine											

BR700-73-101856 R02	No. 1 Engine - Campaign Sb - BR700-73-101856R2 - Introduction of A New Varnish for the Windings of the Permanent Magnetic Alternator (PMA)		HRS		6181.2					0	0
			ENC		1568					0	0
			DATE								
			MSC								
(880129) Engine											

BR700-73-101856 R02 (890129)	No. 2 Engine - Campaign Sb - BR700-73-101856R2 - Introduction of A New Varnish for the Windings of the Permanent Magnetic Alternator (PMA)		HRS		6181.2					0	0
			ENC		1568					0	0
			DATE								
			MSC								
(880129) Engine											

BR700-73-900423 R01	No. 1 Engine - Sb BR700-73-900423R1 - One Time Inspection of Eec Firebox Assembly for Paint Damage		HRS		6181.2					0	0
			ENC		1568					0	0
			MOS		105.6				10 Mar 2015		
			MSC								
(880324) Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-73-900423 R01 (890324)	No. 2 Engine - Sb BR700-73-900423R1 - One Time Inspection of Eec Firebox Assembly for Paint Damage		HRS		6181.2					0	0
			ENC		1568					0	0
			MOS		105.6				10 Mar 2015		
			MSC								
(880324) Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-900423 R04	No. 1 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - One-Time Inspection of the		ENC								0
	Eec Firebox Assembly for Paint Damage - Non-		DATE								
	Modification Service Bulletin (This Non-Modification Sb- BR700-73-9000423 Is No Longer Valid and Can Be Closed), Service Bulletin (Optional)		MSC								
(888842)											
Engine											
BR700-73-900423 R04	No. 2 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - One-Time Inspection of the		ENC								0
	Eec Firebox Assembly for Paint Damage - Non-		DATE								
	Modification Service Bulletin (This Non-Modification Sb- BR700-73-9000423 Is No Longer Valid and Can Be Closed), Service Bulletin (Optional)		MSC								
(888842)											
Engine											
BR700-73-900463	No. 1 Engine - Sb BR700-73-900463 - Removal of Eec for		HRS		176.2			6005			0
	C-15 Capacitor Replacement		ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
(880319)											
Engine											
BR700-73-900463 (890319)	No. 2 Engine - Sb BR700-73-900463 - Removal of Eec for		HRS		176.2			6005			0
	C-15 Capacitor Replacement		ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
(880319)											
Engine											
BR700-73- A101981 R02	No. 1 Engine - Alert Sb BR700-73-A101981R2 -		HRS		6181.2			0			0
	Introduction of A New Eec Firebox Assembly With A		ENC		1568			0			0
	Revised Paint System.		MOS		77.5			12 Jul 2017			
			MSC								
(880465)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-73- A101981 R02 (890465) (880465) Engine	No. 2 Engine - Alert Sb BR700-73-A101981R2 - Introduction of A New Eec Firebox Assembly With A Revised Paint System.		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		77.5			12 Jul 2017			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-73- A101981 R03 (880466) Engine	No. 1 Engine - Alert Sb BR700-73-A101981R3 - Introduction of A New Eec Firebox Assembly With A Revised Paint System.		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		45.1			26 Mar 2020			
			MSC								

BR700-73- A101981 R03 (890466) (880466) Engine	No. 2 Engine - Alert Sb BR700-73-A101981R3 - Introduction of A New Eec Firebox Assembly With A Revised Paint System.		HRS		665.8			5515.4			0
			ENC		150			1418			0
			MOS		45.1			26 Mar 2020			
			MSC								

BR700-73- A101981 R04 (880832) Engine	No. 1 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED.

BR700-73- A101981 R04 (880832) Engine	No. 2 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73- A101981 R05	No. 1 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - Introduction of A New Eec		ENC								0
	Firebox Assembly With A Revised Paint System, Service		DATE								
	Bulletin (Optional)		MSC								
(888844)	Engine										
BR700-73- A101981 R05	No. 2 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - Introduction of A New Eec		ENC								0
	Firebox Assembly With A Revised Paint System, Service		DATE								
	Bulletin (Optional)		MSC								
(888844)	Engine										
BR700-73- A101985 R04	No. 1 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - Introduction of A New Eec		ENC								0
	Firebox Assembly With A Revised Paint System, Service		DATE								
	Bulletin (Optional)		MSC								
(888833)	Engine										
BR700-73- A101985 R04	No. 2 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - Introduction of A New Eec		ENC								0
	Firebox Assembly With A Revised Paint System, Service		DATE								
	Bulletin (Optional)		MSC								
(888833)	Engine										
BR700-73- A900083	No. 1 Engine - Alert Sb BR700-73-A900083 -		HRS		6181.2			0			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		1568			0			0
	Assembly		MOS		80.8			03 Apr 2017			
			MSC								
(880124)	Engine										

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-73- A900083 (890124) (880124) Engine	No. 2 Engine - Alert Sb BR700-73-A900083 -		HRS		6181.2			0			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		1568			0			0
	Assembly		MOS		80.8			03 Apr 2017			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-73- A900083 R01 (880131) Engine	No. 1 Engine - Alert Sb BR700-73-A900083R1 -		HRS		1476.7			4704.5			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		350			1218			0
	Assembly		MOS		75.5			15 Sep 2017			
			MSC								

Notes: PCW SB BR700-73-101438

BR700-73- A900083 R01 (890131) (880131) Engine	No. 2 Engine - Alert Sb BR700-73-A900083R1 -		HRS		1476.7			4704.5			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		350			1218			0
	Assembly		MOS		75.5			15 Sep 2017			
			MSC								

Notes: PCW SB BR700-73-101438

BR700-73- A900083 R02 (880133) Engine	No. 1 Engine - Alert Sb BR700-73-A900083R2 -		HRS		665.8			5515.4			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		150			1418			0
	Assembly		MOS		45.1			25 Mar 2020			
			MSC								

BR700-73- A900083 R02 (890133) (880133) Engine	No. 2 Engine - Alert Sb BR700-73-A900083R2 -		HRS		665.8			5515.4			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		150			1418			0
	Assembly		MOS		45.2			24 Mar 2020			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73- A900083 R03	No. 1 Engine - Engine Fuel and Control Engine Electronic Controller (Eec) - Replacement of Non-Conforming Parts of the Eec Firebox Assembly - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888849)											
Engine											
BR700-73- A900083 R03	No. 2 Engine - Engine Fuel and Control Engine Electronic Controller (Eec) - Replacement of Non-Conforming Parts of the Eec Firebox Assembly - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888849)											
Engine											
BR700-74-102193	No. 1 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888835)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-74-102193	No. 2 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888835)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-74-102193 R01	No. 1 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888837)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-102193 R01	No. 2 Engine - Ignition - Igniter Plug - Introduction of A New Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888837)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
BR700-74-102193 R02	No. 1 Engine - Ignition - Igniter Plug - Introduction of A New Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888838)											
Engine											
BR700-74-102193 R02	No. 2 Engine - Ignition - Igniter Plug - Introduction of A New Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
(888838)											
Engine											
BR700-75-101097	No. 1 Engine - Sb BR700-75-101097 - Core AIR Tubes and Fittings - Intro		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(887514)											
Engine											
BR700-75-101097 (897514)	No. 2 Engine - Sb BR700-75-101097 - Core AIR Tubes and Fittings - Intro		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC								
(887514)											
Engine											
BR700-75-101694	No. 1 Engine - Sb BR700-75-101694 - Handling Bleed Valve Solenoid Control Block		HRS		4281.8			1899.4			0
			ENC		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC								
(887500)											
Engine											
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-101694 (897500) (887500) Engine	No. 2 Engine - Sb BR700-75-101694 - Handling Bleed Valve Solenoid Control Block		HRS		4281.8			1899.4			0
			ENC		1032			536			0
			MOS		156.4			17 Dec 2010			
			MSC					-			
Notes: UPDATED REFERENCING GAC SAV WORK ORDER SC227934											
BR700-75-900693 (888845) Engine	No. 1 Engine - Campaign Sb - BR700-75-900693 - AIR - Vsv Actuator - Replacement of Variable Stator Vane (Vsv) Actuators - Non-Modification Service Bulletin, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC					-			
BR700-75-900693 (888845) Engine	No. 2 Engine - Campaign Sb - BR700-75-900693 - AIR - Vsv Actuator - Replacement of Variable Stator Vane (Vsv) Actuators - Non-Modification Service Bulletin, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC					-			
BR700-77-101536 (887708) Engine	No. 1 Engine - Sb BR700-77-101536 - Turbine Gas Temp (Tgt) Harness		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
BR700-77-101536 (897708) (887708) Engine	No. 2 Engine - Sb BR700-77-101536 - Turbine Gas Temp (Tgt) Harness		HRS		6151.5			29.7			0
			ENC		1555			13			0
			MOS		210.7			08 Jun 2006			
			MSC					-			
BR700-77-101875 (880121) Engine	No. 1 Engine - Sb BR700-77-101875 - N2 Speed Probes - Introduction of New Attaching Bolts With Shorter Length		HRS		6181.2			0			0
			ENC		1568			0			0
			MOS		98.5			15 Oct 2015			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-77-101875 (890121) (880121) Engine	No. 2 Engine - Sb BR700-77-101875 - N2 Speed Probes -		HRS		6181.2			0			0
	Introduction of New Attaching Bolts With Shorter Length		ENC		1568			0			0
			MOS		98.5			15 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-77-101875 R02 (880134) Engine	No. 1 Engine - Sb BR700-77-101875R2 - N2 Speed		HRS		6181.2			0			0
	Probes - Introduction of New Attaching Bolts With Shorter Length		ENC		1568			0			0
			DATE								
			MSC								
BR700-77-101875 R02 (890134) (880134) Engine	No. 2 Engine - Sb BR700-77-101875R2 - N2 Speed		HRS		6181.2			0			0
	Probes - Introduction of New Attaching Bolts With Shorter Length		ENC		1568			0			0
			DATE								
			MSC								
BR700-78-101997 (880642) Engine	No. 1 Engine - Sb BR700-78-101997 - Introduction of		HRS		6181.2			0			0
	New Fastener Definitions Which Are Used to Mount the		ENC		1568			0			0
	Tru Access Panels Onto the Tru Structure.		DATE								
			MSC								
BR700-78-101997 (890642) (880642) Engine	No. 2 Engine - Sb BR700-78-101997 - Introduction of		HRS		6181.2			0			0
	New Fastener Definitions Which Are Used to Mount the		ENC		1568			0			0
	Tru Access Panels Onto the Tru Structure.		DATE								
			MSC								
BR700-79-101803 R01 (887944) Engine	No. 1 Engine - Sb BR700-79-101803R1 - Introduction of		HRS		6181.2			0			0
	New Oil Pump Unit With Improved Gears		ENC		1568			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-79-101803 R01 (897944) (887944) Engine	No. 2 Engine - Sb BR700-79-101803R1 - Introduction of New Oil Pump Unit With Improved Gears		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-80-101900 R01 (880646) Engine	No. 1 Engine - Sb BR700-80-101900R1 - Introduction of A New AIR Turbine Starter With Revised Oil Seal.		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-80-101900 R01 (890646) (880646) Engine	No. 2 Engine - Sb BR700-80-101900R1 - Introduction of A New AIR Turbine Starter With Revised Oil Seal.		HRS		6181.2			0			0
			ENC		1568			0			0
			DATE								
			MSC								
BR700-80-900427 (888011) Engine	No. 1 Engine - Sb BR700-80-900427 - Starter AIR Valve		HRS		176.2			6005			0
			ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
BR700-80-900427 (898011) (888011) Engine	No. 2 Engine - Sb BR700-80-900427 - Starter AIR Valve		HRS		176.2			6005			0
			ENC		38			1530			0
			MOS		11.8			03 Jan 2023			
			MSC								
WE3881600-49-7350 R02 (952056) APU	APU - Sb WE3881600-49-7350 R02 - Airborne Auxiliarypower- Oil Pump Assembly - Replace Plug, Pn AN814-4D With Pn AN814-4DL, Filter Housing, Pn WE3881618-1 With Pn WE3881771-1, Oil Filter Elements, Pn WE3881639-1 With Pn WE3881767-1, and Bolt Pn MS9556-08 With Pn MS9565-08, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC								

ESV**