

Phone: +1-912-298-1281
Fax: 1-912-963-0265/1-800-944-1775
Analyst: Pedro Alvarez

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		GULFSTREAM AEROSPACE CORPORATION G550	5198	02 Jan 2024	4057.8	1184
Engine	1	ROLLS-ROYCE DERBY PLC BR700-710C4-11 (G550)	15499	02 Jan 2024	4057.8	1184
Engine	2	ROLLS-ROYCE DERBY PLC BR700-710C4-11 (G550)	15500	02 Jan 2024	4057.8	1184
APU		HONEYWELL RE220 (G550)	P-526	02 Jan 2024	2575	1839

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

00 - General

000080 ^U	Aircraft Weight and Balance	HRS	957.9		3099.9	0
		AFL	313		871	0
		MOS	41.3	48	23 Aug 2020	23 Aug 2024
Airframe						

01 - Watch List

010010	Service Center Maintenance Induction Checklist	HRS	0		4057.8	0
		AFL	0		1184	0
		MOS	.8		05 Jan 2024	
		MSC			O/C	
Airframe						

10 - Parking, Mooring, Store and Ret to Serv

101001	Short Term Storage	HRS	4057.8		0	0
		AFL	1184		0	0
		MOS	188.2		24 May 2008	
		MSC			O/C	
Airframe						

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW										Manufacturer
	MM Ref											Date Type
	Ops Number(s)											

101002	Long Term Storage		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

11 - Placards and Markings

111010	Exterior Paint 1		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			

Notes: PN: CA8800/I1050 SN: MATTERHORN WHITE. MANUFACTURE: PRC-DESOTO

111015	Exterior Paint 2		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			

Notes: PN: H10679 SN: <NONE>. MANUFACTURE: PRC-DESOTO

111020	Exterior Paint 3		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			

Notes: PN: H60448 SN: GLOSS BLACK. MANUFACTURE: SHERWIN-WILLIAMS

111025	Exterior Paint 4		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			

Notes: PN: 564933 SN: SUNFAST RED. MANUFACTURE: SHERWIN-WILLIAMS

111030	Exterior Paint 5		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			

Notes: PN: 85261 SN: FIRE RED. MANUFACTURE: SHERWIN-WILLIAMS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
111035	Exterior Paint 6		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
Notes: PN: AF74 SN: CLEAR COAT. MANUFACTURE: PRC-DESOTO											
111040	Exterior Paint 7		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
Notes: PN: CA8905HP SN: CLEAR COAT. MANUFACTURE: NAZ-DAR											
111111	Exterior Strip and Paint		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		66.6			13 Jul 2018			
	Airframe		MSC					O/C			
12 - Servicing											
121400	No. 1 Engine - AIR Turbine Starter Oil - Change		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			ENC		44			1140			0
			MOS		5.4			20 Aug 2023			
	Engine		[HRS: +50/-50]								
121400 (121401)	No. 2 Engine - AIR Turbine Starter Oil - Change		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			ENC		44			1140			0
			MOS		5.4			20 Aug 2023			
	Engine		[HRS: +50/-50]								
121500	Hydraulic System Reservoir (Left) - Servicing		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5			15 Jun 2022			
	Airframe		MSC					O/C			
121501	Hydraulic System Reservoir (Right) - Servicing		HRS		583.8			3474			0
			AFL		211			973			0
			MOS		18.1			28 Jul 2022			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
123300	Nose Tire Assembly - Servicing		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
	Airframe		MSC					O/C			
123301	Main Tire Assembly - Servicing		HRS		43.4			4014.4			0
			AFL		16			1168			0
			MOS		2.5			16 Nov 2023			
	Airframe		MSC					O/C			
20 - Standard Practices - Airframe											
200091	Pre Maintenance Checklist		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.9			02 Jan 2024			
	Airframe		MSC					O/C			
200092	Post Maintenance Checklist		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2			25 Jan 2024			
	Airframe		MSC					O/C			
200093	Post Maintenance - Servicing		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.5			17 Sep 2023			
	Airframe		MSC					O/C			
21 - AIR Conditioning											
210001	AIR Conditioning System - Functional Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.8			05 Sep 2020			
	Airframe		MSC					O/C			
212101	Cabin Silencer (Upper) - Removal / Installation		HRS		4057.8			0			0
	1159AC50153-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212102	Cockpit Silencer - Removal / Installation		HRS		4057.8			0			0
	1159AC50153-7	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
212103	Pack Inlet Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	396610-6	1245	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
Notes: Q308411											
212104	Pack Inlet Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	396610-6	1252	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
Notes: Q308411											
212105	Cold AIR Manifold - Removal / Installation		HRS		4057.8			0			0
	1159AC50103-27	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			STANLEY AVIATION CORPORATION
	Airframe		MSC					O/C			
212106	Hot AIR Manifold - Removal / Installation		HRS		4057.8			0			0
	1159AC50103-27	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			STANLEY AVIATION CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212201	Ram AIR Check Valve - Removal / Installation		HRS		4057.8			0			0
	3202776-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
212202	Ram AIR Check Valve - Detailed Inspection		HRS		4057.8		5000	0	5000	5050	0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		[HRS: +50/-50]								
212204	Ram AIR Exhaust (Left) - Removal / Installation		HRS		4057.8			0			0
	3202776-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
212205	Ram AIR Exhaust (Right) - Removal / Installation		HRS		4057.8			0			0
	3202776-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
212401	Cockpit Airflow Control Valve - Removal / Installation		HRS		4057.8			0			0
	BYLB-52588	401	AFL		1184			0			0
			MOS		188.2			24 May 2008			SMITHS AEROSPACE, INC.
	Airframe		MSC					O/C			
Notes: Q300491											
212508	Avionics Cooling Valve - Removal / Installation		HRS		4057.8			0			0
	BYLB-52587	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			SMITHS AEROSPACE, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212510	Aft Equipment Cooling Fan - Removal / Installation		HRS		4057.8			0			0
	011586501	108055786	AFL		1184			0			0
			MOS		188.2			24 May 2008			AMETEK
	Airframe		MSC					O/C			
212511	CRT Display FANS/Filter-Clean		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
212513	Electronic Equipment Rack Cooling FANS (Left) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
212514	Electronic Equipment Rack Cooling FANS (Right) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
212517	Detector, Aft Eer Low Speed		HRS		4057.8			0			0
	035640501	E08090002	AFL		1184			0			0
			MOS		188.2			24 May 2008			AMETEK
	Airframe		MSC					O/C			
212530	Fan, Pedestalcooling -OPS Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
213001	Cabin Pressurization Control - System Check		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			03 Sep 2008			
	Airframe		MSC					O/C			
213006	Cabin Pressure Controller - Removal / Installation		HRS		4057.8			0			0
	2119146-4	08-F0213	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM DALLAS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	MSC							Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213007	Cabin Pressurization Selector Panel - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2118936-1	48-B0480	MOS		188.2			24 May 2008			HONEYWELL
			MSC					O/C			
	Airframe										
	Notes: VERIFIED BY PQ514										
213009	Cabin Pressurization Controller - System Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
	Airframe										
213011	Outflow Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	103878-1	48-A0377	MOS		188.2			24 May 2008			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC					O/C			
	Airframe										
	Notes: Q300491										
213015	Pressure Relief Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	103832-2	18-C0317	MOS		188.2			24 May 2008			HONEYWELL
			MSC					O/C			
	Airframe										
	Notes: Q300491										
213100	Fuselage - Ground Pressurization Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.2			24 Aug 2020			
			MSC					O/C			
	Airframe										
213301	Decompression Advisory System - Functional Test		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			AFL		44			1140			0
			MOS		4.5			17 Sep 2023			
			[HRS: +50/-50]								
	Airframe										
213302	Differential Pressure Limiter Valve (Primary) - Functional Check		HRS		1909.3		2500	2148.5	4648.5	4698.5	0
			AFL		573			611			0
			MOS		87.9			03 Oct 2016			
			[HRS: +50/-50]								
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213303	Differential Pressure Limiter Valve (Secondary) -		HRS		1909.4		2500	2148.4	4648.4	4698.4	0
	Functional Check		AFL		573			611			0
			MOS		87.9			03 Oct 2016			
	Airframe		[HRS: +50/-50]								
213304	Differential Pressure Limiter Valve (Negative) - Functional		HRS		1909.4		2500	2148.4	4648.4	4698.4	0
	Check		AFL		573			611			0
			MOS		87.9			03 Oct 2016			
	Airframe		[HRS: +50/-50]								
213305	Baggage Compartment Shut-Off Valve and Reset Switch -		HRS		1909.3		2500	2148.5	4648.5	4698.5	0
	Operational Test		AFL		573			611			0
			MOS		87.9			03 Oct 2016			
	Airframe		[HRS: +50/-50]								
213306	Baggage Compartment Decompression Warning Circuit -		HRS		4057.8			0			0
	Operational Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
213307	Baggage Compartment Ventilation Check Valve - Detailed		HRS		4057.8		5000	0	5000	5050	0
	Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		[HRS: +50/-50]								
213308	Pressure Relief Valve Remote AIR Filter - Detailed		HRS		1909.4		2500	2148.4	4648.4	4698.4	0
	Inspection		AFL		573			611			0
			MOS		88.7			09 Sep 2016			
	Airframe		[HRS: +50/-50]								
213309	Remote AIR Filter - Removal / Installation		HRS		1909.4			2148.4			0
	147240-1	NSN	AFL		573			611			0
			MOS		88.7			09 Sep 2016			
	Airframe		MSC O/C A.S.A.P. TECHNOLOGIES INC.								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213315	Switch, Bag Compt Decompress #2		HRS		4057.8			0			0
	P20M-H23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			Precision Sensors Inc.
	Airframe		MSC					O/C			
213401	Cabin Pressure Indicator (No. 1) - Removal / Installation		HRS		4057.8			0			0
	789537-2-2	0708	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
Notes: VER BY PQ648											
213403	Cabin Pressure Acquisition Module - Removal / Installation		HRS	TSN:11.2	4048.2			9.6			0
			AFL	TSN:5	1179			5			0
	789538-1-2	0549	MOS		184.9			03 Sep 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
215101	AIR Conditioning Controller (Left) - Removal / Installation		HRS		3092.8			965			0
	1151582-6	1151582-01972	AFL		910			274			0
			MOS		143.7			08 Feb 2012			HONEYWELL
	Airframe		MSC					O/C			
215102	AIR Conditioning Controller (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151582-6	1151582-02280	MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
215103	Pack Outlet Temperature Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	05465	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
215104	Pack Outlet Temperature Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	05472	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215105	Compressor Outlet Temperature Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	1150124-07523	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
Notes: Q308411											
215106	Compressor Outlet Temperature Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	1150124	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
Notes: Q308411											
215201	AIR Conditioning Pack (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2215080-3	1172	MOS		188.2			24 May 2008			
			MSC								
Airframe											
215202	AIR Conditioning Pack (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2215080-3	1174	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: Q309044											
215213	Turbine Inlet Temperature Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	07497	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
215214	Turbine Inlet Temperature Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	07504	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
Notes: Q309044											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215217	Servo Pressure Regulator (Left) - Removal / Installation		HRS		4057.8			0			0
	3215634-1	2546	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
215218	Servo Pressure Regulator (Right) - Removal / Installation		HRS		4057.8			0			0
	3215634-1	2547	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
215219	Water Extractor (Left) - Removal / Installation		HRS		4057.8			0			0
	2341144-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
215220	Water Extractor (Right) - Removal / Installation		HRS		4057.8			0			0
	2341144-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
215221	Compressor Bypass Check Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	3202782-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215222	Compressor Bypass Check Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3202782-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
215223	Water Extractor Aspirator Line and Nozzle (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215224	Water Extractor Aspirator Line and Nozzle (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215225	Strainer, L Ecs H2O Extr-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215226	Strainer, R Ecs H2O Extr-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215229	Primary / Secondary Heat Exchangers (Left Secondary, Sb-2215080-21-2768) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2341682-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215230	Primary / Secondary Heat Exchangers (Right, Secondary, Sb-2215080-21-2768) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2341682-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
215231	Primary / Secondary Heat Exchangers (Left, Primary, Sb-2215080-21-2768) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2341680-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
215232	Primary / Secondary Heat Exchangers (Right, Primary, Sb-2215080-21-2768) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2341680-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
215235	Primary / Secondary Heat Exchangers (Left) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215236	Primary / Secondary Heat Exchangers (Right) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
215237	Water Extractor Strainer (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159ACM50843-1	SN-UNKNOWN	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC								
Airframe											
215240	Water Extractor Strainer (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159ACM50843-1	SN-UNKNOWN	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215301	Valve, Bag Comp Cooling Supply		HRS		4057.8			0			0
	FYLB52635	421	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
216101	Zone Trim AIR Valve (Cockpit) - Removal / Installation		HRS		4057.8			0			0
	3291268-4	1385	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM - LGB
	Airframe		MSC					O/C			
216102	Zone Trim AIR Valve (Forward Cabin) - Removal / Installation		HRS		4057.8			0			0
	3291268-4	1391	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM - LGB
	Airframe		MSC					O/C			
216103	Zone Trim AIR Valve (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
	3291268-4	1388	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM - LGB
	Airframe		MSC					O/C			
216104	Overheat Thermostats Zone Supply (Cockpit) - Removal / Installation		HRS		4057.8			0			0
	129740-1-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			
216105	Overheat Thermostats Zone Supply (Forward Cabin) - Removal / Installation		HRS		4057.8			0			0
	129740-1-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216106	Overheat Thermostats Zone Supply (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	129740-1-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC								
Airframe											
216107	AIR Supply / Zone Trim AIR Check Valve (Left Cold AIR Manifold) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
216108	AIR Supply / Zone Trim AIR Check Valve (Right Cold AIR Manifold) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
216109	Temperature Control Rheostat (Cockpit) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151502-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
			MSC								
Airframe											
216113	AIR Supply and Zone Trim AIR Check Valves (Left Hot AIR Manifold) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	3202760-1	1312	MOS		40.8			05 Sep 2020			N/A
			MSC								
Airframe											
216114	AIR Supply and Zone Trim AIR Check Valve (Right Hot AIR Manifold) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	3202760-1	1317	MOS		40.9			04 Sep 2020			N/A
			MSC								
Airframe											
216115	AIR Supply and Zone Trim AIR Check Valve (Left Cold AIR Manifold) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	3202758-1	1000	MOS		40.8			05 Sep 2020			N/A
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216116	AIR Supply and Zone Trim AIR Check Valve (Right Cold AIR Manifold) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	3202758-1	1005	MOS		40.9			04 Sep 2020			N/A
			MSC								
Airframe											
216117	AIR Supply / Zone Trim AIR Check Valve (Left Hot AIR Manifold) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
216118	AIR Supply / Zone Trim AIR Check Valve (Right Hot AIR Manifold) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
216119	Low Speed Warning Detector (Cockpit) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	035640501	SN-UNKNOWN	MOS		188.2			24 May 2008			AMETEK
			MSC								
Airframe											
216120	Low Speed Warning Detector (Forward Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	035640501	SN-UNKNOWN	MOS		188.2			24 May 2008			AMETEK
			MSC								
Airframe											
216121	Low Speed Warning Detector (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	035640501	SN-UNKNOWN	MOS		188.2			24 May 2008			AMETEK
			MSC								
Airframe											
216122	Detector, L Pdb Low Speed		HRS		4057.8			0			0
			AFL		1184			0			0
	035850500	SN-UNKNOWN	MOS		188.2			24 May 2008			AMETEK
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216123	Detector, Bagg Compt Low Speed		HRS		4057.8			0			0
	035850500	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			AMETEK
	Airframe		MSC					O/C			
216201	Cabin / Cockpit Temperature Indication - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
216401	Cabin / Cockpit Temperature Indicator (Cockpit) - Removal / Installation		HRS		4057.8			0			0
	789575-2-1	0659	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VER BY PQ648											
216404	Zone Supply Temperature Sensor (Cockpit) - Removal / Installation		HRS		4057.8			0			0
	1151834-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
216405	Zone Supply Temperature Sensor (Forward Cabin) - Removal / Installation		HRS		4057.8			0			0
	1151834-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
216406	Zone Supply Temperature Sensor (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
	1151834-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			
216407	Zone Temperature Sensor (Cockpit) - Removal / Installation		HRS		4057.8			0			0
	1151834-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216408	Zone Temperature Sensor (Fwd Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				ASCA INC.
Airframe											
216409	Zone Temperature Sensor (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				ASCA INC.
Airframe											
216410	Zone Temperature Sensor Fan (Cockpit) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	011590500	SN-UNKNOWN	MOS		188.2			24 May 2008			MPC PRODUCTS
			MSC				O/C				
Airframe											
216411	Zone Temperature Sensor Fan (Fwd Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	011590500	SN-UNKNOWN	MOS		188.2			24 May 2008			MPC PRODUCTS
			MSC				O/C				
Airframe											
216412	Zone Temperature Sensor Fan (Aft Cabin) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	011590500	SN-UNKNOWN	MOS		188.2			24 May 2008			MPC PRODUCTS
			MSC				O/C				
Airframe											
217001	Ozone Converter (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAC501-1	7039	MOS		188.2			24 May 2008			COX & COMPANY
			MSC				O/C				INC
Airframe											

Notes: Q308411

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
217002	Ozone Converter (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCAC501-1	7038	AFL		1184			0			0
			MOS		188.2			24 May 2008			COX & COMPANY INC
	Airframe		MSC					O/C			
Notes: Q308411											
217003	Ozone Converter (Left) - Functional Test		HRS		4057.8		10000	0	10000	10050	0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		[HRS: +50/-50]								
217004	Ozone Converter (Right) - Functional Test		HRS		4057.8		10000	0	10000	10050	0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		[HRS: +50/-50]								
22 - Auto Flight											
221001	Flight Guidance Panel - Removal / Installation		HRS		1654.7			2403.1			0
	7021852-901	08040691	AFL		493			691			0
			MOS		68.7			10 May 2018			
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
221002	Autopilot - Operational Test		HRS		592			3465.8			0
			AFL		217			967			0
			MOS		18.9			04 Jul 2022			
	Airframe		MSC					O/C			
221201	Aileron Servo No. 1 - Removal / Installation		HRS		4057.8			0			0
	6256-164	667	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: Q313266											
221202	Aileron Servo No. 2 - Removal / Installation		HRS		4057.8			0			0
	6256-164	630	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: Q313266											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
221203	Aileron Servo Bracket Assembly No. 1 - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	6256-151-1	5315	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: Q313266											
221204	Aileron Servo Bracket Assembly No. 2 - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	6256-151-1	5318	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: Q313266											
221205	Lane A1 Aiop Module - Removal / Installation		HRS		2020.5			2037.3			0
	7029305-1902	16033528	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
221206	Lane B1 Aiop Module - Removal / Installation		HRS		2020.5			2037.3			0
	7028432-1902	1604M774	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
221207	Lane A2 Aiop Module - Removal / Installation		HRS		2020.5			2037.3			0
	7029305-1902	16033526	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
221208	Lane B2 Aiop Module - Removal / Installation		HRS		2020.5			2037.3			0
	7028432-1902	1604M808	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
221300	Elevator Autopilot Servo - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.5			17 Sep 2023			
	Airframe		MSC					O/C			
221301	Elevator Autopilot Servo No. 1 - Removal / Installation		HRS		4057.8			0			0
	6256-162	388	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: Q312091											
221302	Elevator Autopilot Servo No. 2 - Removal / Installation		HRS		4057.8			0			0
	6256-162	747	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: Q312091											
221303	Elevator Autopilot Servo Bracket Assembly No. 1 - Removal / Installation		HRS		4057.8			0			0
	6256-151-1	5320	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: Q312091											
221304	Elevator Autopilot Servo Bracket Assembly No. 2 - Removal / Installation		HRS		4057.8			0			0
	6256-151-1	5400	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: Q312091											
221305	Elevator Trim Servo - Removal / Installation		HRS		134.1			3923.7			0
	7000260-503	1407H648	AFL		44			1140			0
			MOS		4.5			16 Sep 2023			N/A
	Airframe		MSC					O/C			
Notes: VER BY PQ650											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
221306	Elevator Trim Servo Bracket - Removal / Installation		HRS		134.1			3923.7			0
	7000261-604	1403H637	AFL		44			1140			0
			MOS		4.5			16 Sep 2023			N/A
	Airframe		MSC							O/C	
Notes: VER BY PQ650											
223005	Auto Throttle - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
23 - Communications											
230106	Airshow Mounting Tray		HRS		4057.8			0			0
	925041-100	G0100226	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
230205	Ka-Band Mid Fairing Radome - Removal / Installation		HRS		1654.7			2403.1			0
	5282-550-1	047	AFL		493			691			0
			MOS		65.7			08 Aug 2018			
	Airframe		MSC							O/C	
231003	VHF Antenna No. 1 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	DM-C50-22-1	1911	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.3			23 Jul 2020			N/A
	Airframe		MSC							O/C	
231004	VHF Antenna No. 2 - Removal / Installation		HRS		957.9			3099.9			0
	DM-C50-22-1	4734	AFL		313			871			0
			MOS	TSN:1	42.3			23 Jul 2020			N/A
	Airframe		MSC							O/C	
231005	Transceiver, #3 VHF Comm		HRS	TSN:2403.1	1654.7			2403.1			0
	7026203-813	08040406	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.7			09 Aug 2018			HONEYWELL
	Airframe		MSC							O/C	
231006	VHF Antenna No. 3 - Removal / Installation		HRS		884.1			3173.7			0
	DM C50-22-1	4776	AFL		291			893			0
			MOS	TSN:8	33.7			08 Apr 2021			
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231010	VHF Voice Communications - Operational Test		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.4			20 Jul 2021			
	Airframe		MSC							O/C	
231015	VHF Data Radio - Return to Service Test		HRS		884.1			3173.7			0
			AFL		291			893			0
			MOS		33.7			09 Apr 2021			
	Airframe		MSC							O/C	
231101	High Frequency Receiver / Transmitter No. 1 - Removal / Installation		HRS	TSN:3200.1	857.7			3200.1			0
			AFL	TSN:904	280			904			0
	822-0102-001	3518	MOS	TSN:158	30.3			21 Jul 2021			N/A
	Airframe		MSC							O/C	
Notes: VERIFIED BY PQ040											
231102	High Frequency Receiver / Transmitter No. 2 - Removal / Installation		HRS		1947.2			2110.6			0
			AFL		587			597			0
	822-0102-001	5327	MOS		90.4			20 Jul 2016			ROCKWELL COLLINS
	Airframe		MSC							O/C	
Notes: PQ040											
231105	HF Antenna Coupler No. 1 - Removal / Installation		HRS		0			4057.8			0
			AFL		0			1184			0
	622-8114-002	9384	MOS		.3			23 Jan 2024			N/A
	Airframe		MSC							O/C	
Notes: VERIFIED BY PQ040											
231106	HF Antenna Coupler No. 2 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	622-8114-002	8565	MOS		188.2			24 May 2008			ROCKWELL COLLINS
	Airframe		MSC							O/C	
Notes: VERIFIED BY PQ040											
231110	HF Antenna - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159CS52061-413	GA0393	MOS		188.2			24 May 2008			STORK FOKKER AESP B.V.
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231120	HF Voice Communication - Operational Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.3			21 Jul 2021			
	Airframe		MSC					O/C			
231121	HF Antenna Adapter - Removal / Installation		HRS		4057.8			0			0
	822-0089-001	1096	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROCKWELL COLLINS
	Airframe		MSC					O/C			
Notes: PQ514											
231203	Antenna, Radio Telephone 800MZ		HRS	TSN:3099.9	957.9			3099.9			0
	S67-1575-165	449-2615	AFL	TSN:871	313			871			0
			MOS	TSN:147	42			30 Jul 2020			N/A
	Airframe		MSC					O/C			
231241	Voice / Data Radio Module No. 1 - Removal / Installation		HRS		4057.8			0			0
	7026201-813	07053400	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
231244	Voice / Data Radio Module No. 2 - Removal / Installation		HRS		4057.8			0			0
	7026201-813	08024211	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
231301	HF Antenna Coupler (No. 1) - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
231302	HF Antenna Coupler (No. 2) - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231481	Aircell Satellite Transceiver - Removal / Installation		HRS		2943.3			1114.5			0
	P12023	1202311003	AFL		858			326			0
			MOS	TSN:52	136.5			15 Sep 2012			
	Airframe		MSC					O/C			
231502	Dual Channel Satellite Antenna (Aircell) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
231510	Aircell Handset Interface Unit - Removal / Installation		HRS		4057.8			0			0
	029A5	1234610513	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
231511	Custom Retractable Handset (Aircell) # 2		HRS		4057.8			0			0
	P12793-011	1279370033	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
231513	Aircell Satellite Interface Unit - Removal / Installation		HRS		4057.8			0			0
	P12777	1277710107	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIRCELL
	Airframe		MSC					O/C			
Notes: VER BY Q311219											
231514	Aircell Cabin Telecommunications Router - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P12083-001	1208370085	MOS		188.2			24 May 2008			Aircell
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ037											
231516	Dual Iridium Antenna - Removal / Installation		HRS		957.9			3099.9			0
	S67-1575-365	915-0884	AFL		313			871			0
			MOS		42			30 Jul 2020			N/A
	Airframe		MSC					O/C			
Notes: STA 1020 WEIGHT 9.2											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231517	Iridium Data Link - Removal / Installation		HRS		1654.7			2403.1			0
	DL150-00	60057	AFL		493			691			0
			MOS		65.7			08 Aug 2018			
	Airframe		MSC					O/C			
231530	SATCOM Antenna - Removal / Installation		HRS		4057.8			0			0
	806-10-1001-3	OP000321	AFL		1184			0			0
	A	A,B	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
231531	Diplexer / Low Noise Amplifier - Removal / Installation		HRS		4057.8			0			0
	804-10-0011	3081061	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
232030	Selective Calling / Datalink - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
232102	Satellite Data Unit - Removal / Installation		HRS		1668			2389.8			0
	7516118-27011	04060837	AFL		497			687			0
	A,D,G-H	A-D,S	MOS		71.2			25 Feb 2018			HONEYWELL
	Airframe		MSC					O/C			
232103	High Power Amplifier - Removal / Installation		HRS		4048.2			9.6			0
	7516250-60050	306	AFL		1179			5			0
	A-G	A-G	MOS		186.3			22 Jul 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VER BY 310229											
232150	Cabin Network Accelerator		HRS		4025.2			32.6			0
	1110-A-0501-01	630	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			EMS TECH
	Airframe		MSC					O/C			
232152	Xcvr, SATCOM High Speed Data		HRS		2648.7			1409.1			0
	1252-A-3600-01	306	AFL		782			402			0
			MOS		123.5			17 Oct 2013			EMS
	Airframe		MSC					O/C			TECHNOLOGIES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232157	Handset, SATCOM (Cockpit)		HRS		4025.2			32.6			0
	938810A-C	3001928	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ICG JETPHONE
	Airframe		MSC					O/C			
232168	Router, LAN Interface		HRS		4025.2			32.6			0
	USR8200A	2WBARBSG0464	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			US ROBOTICS
	Airframe		MSC					O/C			
232210	Facsimile Machine (No. 1) - Final Phase Removal /		HRS		4025.2			32.6			0
	Installation		AFL		1170			14			0
	MFC-420CN	EGF884975	MOS		184.6			12 Sep 2008			BROTHER
	Airframe		MSC					O/C			
232230	Antenna, Cisco Di-Pole (Wireless LAN)		HRS		4025.2			32.6			0
	AIR-ANT4941	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			CISCO
	Airframe		MSC					O/C			
232231	Antenna, Cisco Di-Pole (Wireless LAN)		HRS		4025.2			32.6			0
	AIR-ANT4941	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			CISCO
	Airframe		MSC					O/C			
232246	Storage Drive		HRS		4025.2			32.6			0
	USR8800-250	1WBE739E0050	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			US ROBOTICS
	Airframe		MSC					O/C			
232253	Point, Bbml Wireless Access #1		HRS		4025.2			32.6			0
	GC514280075-01	00509	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GULFSTREAM
	Airframe		MSC					O/C			
232263	Switch, Pressure (Bbml)		HRS		1654.7			2403.1			0
	214C50-87A	WO36859	AFL		493			691			0
			MOS		65.7			08 Aug 2018			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232996	Speaker, Cabin PA #7		HRS		4025.2			32.6			0
	DT-PA2N	081171026	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
232997	Speaker, Cabin PA #8		HRS		4025.2			32.6			0
	DT-PA2N	081171025	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233002	Speaker, Galley Call System		HRS		4025.2			32.6			0
	DT-PA2N	081171015	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233008	Galley / Galley Annex Passenger Address Speaker (No. 1) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	DT-PA2N	081171016	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233010	Speaker, Lav PA		HRS		4025.2			32.6			0
	DT-PA2N	080485019	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233011	Speaker, Cabin PA #1		HRS		4025.2			32.6			0
	DT-PA2N	082173016	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233012	Speaker, Cabin PA #2		HRS		4025.2			32.6			0
	DT-PA2N	082173042	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233013	Speaker, Cabin PA #3		HRS		4025.2			32.6			0
	DT-PA2N	082173011	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233014	Speaker, Cabin PA #4		HRS		4025.2			32.6			0
	DT-PA2N	082173050	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233015	Speaker, Cabin PA #5		HRS		4025.2			32.6			0
	DT-PA2N	082173038	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233016	Speaker, Cabin PA #6		HRS		4025.2			32.6			0
	DT-PA2N	081178014	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEM
	Airframe		MSC					O/C			
233056	AMP, #1 Speaker		HRS		4057.8			0			0
	105210-0001	101001	AFL		1184			0			0
			MOS		188.2			24 May 2008			BOSE
	Airframe		MSC					O/C			
Notes: VER BY Q310229											
233057	AMP, #2 Speaker		HRS		4057.8			0			0
	105210-0001	101006	AFL		1184			0			0
			MOS		188.2			24 May 2008			BOSE
	Airframe		MSC					O/C			
Notes: VER BY Q310229											
233061	Compact Disc Player (No. 1) - Final Phase Removal /		HRS		1909.4			2148.4			0
	Installation		AFL		573			611			0
	3210-1-1	0415096	MOS		88.1			29 Sep 2016			AIRSHOW
	Airframe		MSC					O/C			
233071	Controller, #1 Cbn RF Rvcr		HRS		4025.2			32.6			0
	2033-1-1	208170240	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233078	Remote, #1 Cabin		HRS		4025.2			32.6			0
	0300-408	0804P015	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233079	Remote, #2 Cabin		HRS		4025.2			32.6			0
	0300-402	0805P018	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233084	Digital Video Disc Player (No. 1) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	866-0027-005	725-0357	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
233089	Digital Video Disc Player (No. 2) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	866-0027-005	725-0320	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
233101	Monitor, #1 Lh Seat		HRS		4025.2			32.6			0
	7000-061	0805J035	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233102	Monitor, #1 Rh Seat		HRS		4025.2			32.6			0
	7000-060	0805J025	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233103	Monitor, #2 L/H Seat		HRS		4025.2			32.6			0
	7000-060	0805J026	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233104	Monitor, #2 R/H Seat		HRS		4025.2			32.6			0
	7000-061	0805J034	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233111	Monitor, Crew Rest / Work Sta		HRS		4025.2			32.6			0
	7000-060	0805J030	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233116	Monitor, Lcd		HRS		4025.2			32.6			0
	1700-002	0805T013	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233117	Monitor, Lcd		HRS		4025.2			32.6			0
	1700-002	0805T016	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233118	Monitor, Lcd		HRS		4025.2			32.6			0
	2002-002	0805N008	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233185	Remote, Cabin #1 Touch Screen		HRS		4025.2			32.6			0
	2507-1-003	208210112	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW INC.
	Airframe		MSC					O/C			
233186	Remote, Cabin #2 Touch Screen		HRS		4025.2			32.6			0
	2507-1-003	208210113	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW INC.
	Airframe		MSC					O/C			
233201	Camera, Vertical Stab		HRS		0			4057.8			0
	PN	NOT INSTALLED	AFL		0			1184			0
			MOS		.7			10 Jan 2024			
	Airframe		MSC					O/C			
233202	Camera, Fwd Looking		HRS		134.1			3923.7			0
	100-1056-02	1132609	AFL		44			1140			0
			MOS		5.4			19 Aug 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233203	Camera, Aft Looking		HRS	TSN:3067.3	957.9			3099.9			0
	100-1056-02	0809823	AFL	TSN:857	313			871			0
			MOS	TSN:143	42.1			27 Jul 2020			N/A
	Airframe		MSC					O/C			
233210	Interface Unit, Camera		HRS		4025.2			32.6			0
	100-2415-01	0809543	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SECURAPLANE
	Airframe		MSC					O/C			
233222	Computer, Airshow Display		HRS		260.2			3797.6			0
	925000-100	4FHPB	AFL		97			1087			0
			MOS		9			01 May 2023			
	Airframe		MSC					O/C			
Notes: MODS: A,B,E,F,H,K											
233223	Controller, Airshow		HRS		4057.8			0			0
	922000-2	H01003544	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROCKWELL COLLINS AIRSHOW SYSTEMS
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
233251	Subwoofer, #1		HRS		4025.2			32.6			0
	DT-AUS-4MSGGA	081517001	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233252	Subwoofer, #2		HRS		2943.3			1114.5			0
	DT-AUS-4MSGGA	081517002	AFL		858			326			0
			MOS	TSN:48	136.5			15 Sep 2012			DT SYSTEMS
	Airframe		MSC					O/C			
233253	Subwoofer, #3		HRS		2943.3			1114.5			0
	DT-AUS-4MSGGA	081517003	AFL		858			326			0
			MOS	TSN:48	136.5			15 Sep 2012			DT SYSTEMS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233254	Subwoofer, #4		HRS		2943.3			1114.5			0
	DT-AUS-4MSG	081517004	AFL		858			326			0
			MOS	TSN:48	136.5			15 Sep 2012			DT SYSTEMS
	Airframe		MSC					O/C			
233261	Module, Cabin Management		HRS		4057.8			0			0
	1944-1-8	208030059	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
233270^U	Checklist Controller		HRS		4025.2			32.6			0
	CMS400-1-G5	401003768	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			HEAD UP TECH
	Airframe		MSC					O/C			
233301	Speaker, #1 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673016	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233302	Speaker, #2 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673017	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233303	Speaker, #3 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673018	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233304	Speaker, #4 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673019	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233305	Speaker, #5 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673020	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233306	Speaker, #6 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673021	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233307	Speaker, #7 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673010	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233308	Speaker, #8 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673011	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233309	Speaker, #9 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673012	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233310	Speaker, #10 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673013	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233311	Speaker, #11 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673014	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233312	Speaker, #12 Cbn Entertainment		HRS		4025.2			32.6			0
	DT-A8GAK	074673015	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			DT SYSTEMS
	Airframe		MSC					O/C			
233411	Controller, Circuit #1		HRS		2702.8			1355			0
	2023-1-1	205260123	AFL		803			381			0
			MOS		126.2			24 Jul 2013			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233412	Controller, Circuit #2		HRS		4025.2			32.6			0
	2023-1-1	208220043	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
233445	Cabin Entertainment Video - Final Phase Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
233511	Receptacle, Monitor Lh #1		HRS		4025.2			32.6			0
	0100-002	0803K037	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233512	Receptacle, Monitor Rh #1		HRS		4025.2			32.6			0
	0100-002	0803K039	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233513	Receptacle, Monitor Lh #2		HRS		4025.2			32.6			0
	0100-002	0803K038	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233514	Receptacle, Monitor Rh #2		HRS		4025.2			32.6			0
	0100-002	0803K040	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233525	Receptacle, Monitor - Crew Rest		HRS		4025.2			32.6			0
	0100-002	0803K042	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ROSEN
	Airframe		MSC					O/C			
233651	Antenna, WIFI - Removal / Installation		HRS		4057.8			0			0
	P16917-001	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233655	Airplane Personality Module - Removal / Installation		HRS		1654.7			2403.1			0
	90401121	000001211	AFL		493			691			0
			MOS		65.7			08 Aug 2018			
	Airframe		MSC							O/C	
233656	Ka-Band Aircell Network Data Unit - Removal / Installation		HRS		1654.7			2403.1			0
	90401566	000001979	AFL		493			691			0
			MOS		65.7			08 Aug 2018			
	Airframe		MSC							O/C	
235003	Network / Audio Interface Module No. 1 (Left) - Removal / Installation		HRS		857.7			3200.1			0
	7517964-918	06122450	AFL		280			904			0
		N/A	MOS		30.4			20 Jul 2021			
	Airframe		MSC							O/C	
Notes: MODS: AK,AL,AM,AN,AT											
235004	Network / Audio Interface Module No. 2 (Right) - Removal / Installation		HRS		1632.7			2425.1			0
	7517964-918	09106723	AFL		489			695			0
			MOS		64.8			07 Sep 2018			HONEYWELL
	Airframe		MSC							O/C	
Notes: MODS: AK,AL,AM,AN,AT											
235005	Audio Control Panel No. 1 - Removal / Installation		HRS		4048.2			9.6			0
	7511900-90302	06012194	AFL		1179			5			0
			MOS		185.1			29 Aug 2008			HONEYWELL
	Airframe		MSC							O/C	
Notes: REMOVED S/N 08044971 MOD: A,C,G,H,J,N,V,W,AB,AG. FACE PLATE WAS DAMAGED PQ183											
235006	Audio Control Panel No. 2 - Removal / Installation		HRS		4057.8			0			0
	7511900-90302	08045055	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
Notes: MOD: A,C,G,H,J,N,V,W,AB,AG.											
235007	Audio Control Panel No. 3 - Removal / Installation		HRS		4057.8			0			0
	7511900-90302	08045034	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC							O/C	
Notes: MOD: A,C,G,H,J,N,V,W,AB,AG.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235010	Audio Integrating System - Operational Check		HRS		2020.5			2037.3			0
			AFL		612			572			0
			MOS		92.6			12 May 2016			
	Airframe		MSC					O/C			
235012	Modular Radio System - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
235013	Modular Radio Cabinet (Left) - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	7517959-904	08043704	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.7			09 Aug 2018			
	Airframe		MSC					O/C			
235016	Modular Radio Cabinet (Right) - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	7517959-904	08033791	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.7			09 Aug 2018			
	Airframe		MSC					O/C			
235301	Oxygen Mask Microphone (Pilot) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.8			06 Jun 2023			
	Airframe		MSC					O/C			
235302	Oxygen Mask Microphone (Copilot) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.8			06 Jun 2023			
	Airframe		MSC					O/C			
235303	Oxygen Mask Microphone (Observer) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.8			06 Jun 2023			
	Airframe		MSC					O/C			
236001	L Wing Static Wicks / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5	31	48	15 Jul 2020 31 Aug 2024* 30 Sep 2024			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236002	R Wing Static Wicks / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		48	15 Jul 2020	31 Jul 2024	31 Aug 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
236003	L Horizontal Stabilizer Static Wick / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3	31	48	23 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
236004	R Horizontal Stabilizer Static Wick / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3	31	48	23 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
236005	Vertical Stabilizer Static Wick / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.1	2	48	29 Aug 2020	31 Aug 2024*	30 Sep 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
236006	Tail Cone Static Wick / Bonding - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5	31	48	15 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
236011	Static Wick (Left Wing No. 1) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe			MSC			O/C				
236012	Static Wick (Left Wing No. 2) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe			MSC			O/C				
236013	Static Wick (Left Wing No. 3) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe			MSC			O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236014	Static Wick (Right Wing No. 1) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe		MSC					O/C			
236015	Static Wick (Right Wing No. 2) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe		MSC					O/C			
236016	Static Wick (Right Wing No. 3) - Removal / Installation		HRS		4057.8			0			0
	GAW20A1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe		MSC					O/C			
236017	Static Wick (Left Horizontal Stabilizer No. 1) - Removal / Installation		HRS		4057.8			0			0
	FON9-1481-0IT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
236018	Static Wick (Left Horizontal Stabilizer No. 2) - Removal / Installation		HRS		4057.8			0			0
	FON9-1481-0IT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
236019	Static Wick (Left Horizontal Stabilizer No. 3) - Removal / Installation		HRS		4057.8			0			0
	FON9-1481-0IT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
236020	Static Wick (Right Horizontal Stabilizer No. 1) - Removal / Installation		HRS		4057.8			0			0
	FON9-1481-0IA	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236021	Static Wick (Right Horizontal Stabilizer No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
236022	Static Wick (Right Horizontal Stabilizer No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
236023	Static Wick (Center Horizontal Stabilizer) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	FON9-1481-0IA	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
236024	Static Wick (Tail Cone No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAW20A1	SN-UNKNOWN	MOS		188.2			24 May 2008			CHELTON INC
			MSC							O/C	
Airframe											
236025	Static Wick (Tail Cone No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAW20A1	SN-UNKNOWN	MOS		188.2			24 May 2008			CHELTON INC
			MSC							O/C	
Airframe											
237001	Cockpit Voice Recorder Unit - Removal / Installation		HRS	TSN:2322.4	1735.4			2322.4			0
			AFL	TSN:664	520			664			0
	980-6023-002	ARCVR-11009	MOS	TSN:112	76.7			08 Sep 2017			AIRSHOW INC.
			MSC							O/C	
Airframe											
237003	Cockpit Voice Recorder Cockpit AREA Microphone - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	0980-6113-010	05178	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237004	Cockpit Voice Recorder - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.8	35	12	06 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
237005	Cvr Monitoring - Flight Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
237012	Cockpit Voice Recorder Underwater Locator Beacon - Battery Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	DK120/90	AT72375	MOS		76.7			08 Sep 2017	01 Sep 2024		SPINNEYBECK
Airframe			MSC				DUE			EXPIRATION	
			[End Of Month Item]								
237013	Cockpit Voice Recorder Underwater Locator Beacon - Removal / Installation		HRS		1735.4			2322.4			0
			AFL		520			664			0
	DK120/90	AT72375	MOS		76.7			08 Sep 2017			SPINNEYBECK
Airframe			MSC				O/C				
237014	Cockpit Voice Recorder Underwater Locator Beacon - Battery Replacement		HRS		1735.4			2322.4			0
			AFL		520			664			0
	DK120/90	AT72375	MOS		76.7			08 Sep 2017			SPINNEYBECK
Airframe			MSC				O/C				
237016	Cockpit Voice Recorder Underwater Locator Beacon - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	02 Jun 2024	02 Jul 2024	
Airframe			[MOS: +1m/-1m]								
237018	Cockpit Voice Recorder Underwater Locator Beacon - Switch Cleaning		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237020	Cockpit Voice Recorder Impact Switch - Functional Check		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.9		72	03 Sep 2023	30 Sep 2029		
Airframe											[End Of Month Item]
237021	Cockpit Voice Recorder Impact Switch - Removal / Installation		HRS	TSN:3923.7	134.1			3923.7			0
			AFL	TSN:1140	44			1140			0
	1159SCAV402-2	2692	MOS	TSN:183	4.9			03 Sep 2023			N/A
Airframe			MSC								O/C
Notes: Q310159											
237201	Security System Battery Pack (No. 1) - Final Phase Restore		HRS		957.9			3099.9			0
			AFL		313			871			0
	100-1032-01	0809742	MOS		41.5		48	17 Aug 2020	31 Aug 2024		N/A
Airframe											[End Of Month Item] MANUFACTURE
237202	Security System Control Display Unit - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	100-0106-01	0809012	MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
Airframe			MSC								O/C
237203	Ultra High Frequency Antenna - Final Phase Removal / Installation		HRS	TSN:3099.9	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM C57-1	9094	MOS	TSN:146	42.3			21 Jul 2020			N/A
Airframe			MSC								O/C
237204	Indicator, Security Sys Alarm		HRS		4025.2			32.6			0
			AFL		1170			14			0
	100-0651-01	0808535	MOS		184.6			12 Sep 2008			SECURAPLANE
Airframe			MSC								O/C
237205	Panel, Security Sys Solar		HRS		4025.2			32.6			0
			AFL		1170			14			0
	443-0101-01	0100707-101377	MOS		184.6			12 Sep 2008			SECURAPLANE
Airframe			MSC								O/C

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237207	Passive Infrared Sensor (Forward Nose Wheel Well) -		HRS		4025.2			32.6			0
	Final Phase Removal / Installation		AFL		1170			14			0
	100-0401-11	0707783	MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237208	Passive Infrared Sensor (Aft Nose Wheel Well) - Final		HRS		4025.2			32.6			0
	Phase Removal / Installation		AFL		1170			14			0
	100-0401-11	0707783	MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237209	Passive Infrared Sensor (Left Main Gear Wheel Well) -		HRS		4025.2			32.6			0
	Final Phase Removal / Installation		AFL		1170			14			0
	100-0401-11	0707785	MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237210	Passive Infrared Sensor (Right Main Gear Wheel Well) -		HRS		4025.2			32.6			0
	Final Phase Removal / Installation		AFL		1170			14			0
	100-0401-11	0707786	MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237213	Transceiver, Security System		HRS		4025.2			32.6			0
	444EX600	004TJQ2481	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											
237214	Battery Pack - 550 (No. 1) - Final Phase Removal /		HRS	TSN:2115.8	1909.4			2148.4			0
	Installation		AFL	TSN:597	573			611			0
	100-1032-01	0809742	MOS	TSN:99	88.1			29 Sep 2016			SECURAPLANE TECHNOLOGIES, LLC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237222	Aircraft Security - Final Phase Operational Test		HRS		957.9			3099.9			0
	Airframe		AFL		313			871			0
			MOS		41.5			17 Aug 2020			
			MSC					O/C			
237243	Mat Switch (No. 1) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	Airframe	1SE1	NSN	AFL	1170			14			0
				MOS	184.6			12 Sep 2008			MICROSWITCH
				MSC				O/C			
237244	Mat Switch (No. 2) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	Airframe	1SE1	NSN	AFL	1170			14			0
				MOS	184.6			12 Sep 2008			MICROSWITCH
				MSC				O/C			
237245	Switch, Cabin Security Mat #3		HRS		4025.2			32.6			0
	Airframe	1SE1	NSN	AFL	1170			14			0
				MOS	184.6			12 Sep 2008			MICROSWITCH
				MSC				O/C			
237255	Cockpit Voice Recorder Underwater Locator Beacon - Battery Voltage Check		HRS		1735.4			2322.4			0
	Airframe		AFL		520			664			0
				MOS		76.7			08 Sep 2017		
				MSC				O/C			
237310	Unit, Video Distribution		HRS		4025.2			32.6			0
	Airframe	MSM2925-01-1	070800655	AFL	1170			14			0
				MOS	184.6			12 Sep 2008			AUDIO INT.
				MSC				O/C			
24 - Electrical Power											
240101	Emergency Battery (Left) - Removal / Installation		HRS		957.9			3099.9			0
	Airframe	1159SCAV524-3	P01089	AFL	313			871			0
				MOS	42.1			29 Jul 2020			N/A
				MSC				O/C			
240102	Emergency Battery (Right) - Removal / Installation		HRS		857.7			3200.1			0
	Airframe	1159SCAV524-3	P0855	AFL	280			904			0
				MOS	30.4			18 Jul 2021			N/A
				MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
240103	Emergency Battery (Forward) - Removal / Installation		HRS		616			3441.8			0
	1159SCAV524-3	P5954	AFL		220			964			0
			MOS		19.9			03 Jun 2022			
	Airframe		MSC					O/C			
240104	Emergency Battery (Aft) - Removal / Installation		HRS		616			3441.8			0
	1159SCAV524-3	P4528	AFL		220			964			0
			MOS		19.9			03 Jun 2022			
	Airframe		MSC					O/C			
240106	L Emergency Battery - Bite / Battery Level Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9	55	24	04 Jun 2022	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: TC 3005											
240107	R Emergency Battery - Bite / Battery Level Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
240108	Fwd Emergency Battery - Bite / Battery Level Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
240109	Aft Emergency Battery - Bite / Battery Level Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
240111	Emergency Battery Pack (Left) - Restore		HRS		957.9			3099.9			0
	102-1103-01	200619-40	AFL		313			871			0
			MOS		42.1		48	29 Jul 2020	31 Jul 2024		
	Airframe		[End Of Month Item]								
240112	Emergency Battery Pack (Right) - Restore		HRS		857.7			3200.1			0
	102-1103-01	210609-03	AFL		280			904			0
			MOS	TSN:1	30.4		48	18 Jul 2021	30 Jun 2025		N/A
	Airframe		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
240113	Emergency Battery Pack (Forward) - Restore		HRS		616			3441.8			0
	102-1103-01	P5954	AFL		220			964			0
			MOS		19.9		48	03 Jun 2022	30 Sep 2025		
Airframe			[End Of Month Item]								
240114	Emergency Battery Pack (Aft) - Restore		HRS		616			3441.8			0
	102-1103-01	P4528	AFL		220			964			0
			MOS		19.9		48	03 Jun 2022	30 Nov 2025		
Airframe			[End Of Month Item]								
240121	Emergency Battery Power System (Left) - Operational		HRS		229.7			3828.1			0
	Test		AFL		82			1102			0
			MOS		7.8		12	07 Jun 2023	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
240122	Emergency Battery Power System (Right) - Operational		HRS		229.7			3828.1			0
	Test		AFL		82			1102			0
			MOS		7.8		12	07 Jun 2023	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
240123	Emergency Battery Power System (Forward) -		HRS		229.7			3828.1			0
	Operational Test		AFL		82			1102			0
			MOS		7.8		12	07 Jun 2023	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
240124	Emergency Battery Power System (Aft) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.8		12	07 Jun 2023	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 100-0302-1 SN: <NONE>.											
241005	L Idg AIR Cooled Oil Cooler - Removal / Installation		HRS		4057.8			0			0
	50028001-11	50028-1311	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
241006	R Idg AIR Cooled Oil Cooler - Removal / Installation		HRS		4057.8			0			0
	50028001-1	50028-1301	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
242001	Tail Compartment AC Feeder Cables - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8	23	96	07 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
242005	Standby Electrical Power System - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		24	15 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
242100	Engine Alternating Current Generation - Operational Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.3			21 Jul 2021			
	Airframe		MSC					O/C			
242101	Adaptor, L Eng Generator Qad		HRS		4057.8			0			0
	1159SCAV500-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
242102	Adaptor, R Eng Generator Qad		HRS		4057.8			0			0
	1159SCAV500-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
242103	L Idg - Removal / Installation		HRS		4057.8			0			0
	1159SCAV500-3	0955	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242104	R Idg - Removal / Installation		HRS		4057.8			0			0
	1159SCAV500-3	0956	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
242105	Integrated Drive Generator Oil Scavenge Filter (Left) - Removal / Installation		HRS		2414			1643.8			0
	AC-F451F-16	NSN	AFL		716			468			0
			MOS		111.8			05 Oct 2014			
	Airframe		MSC					O/C			
242106	Integrated Drive Generator Oil Scavenge Filter (Right) - Removal / Installation		HRS		2414			1643.8			0
	AC-F451F-16	NSN	AFL		716			468			0
			MOS		111.8			05 Oct 2014			
	Airframe		MSC					O/C			
242109	Integrated Drive Generator (Left) - Oil Level Check		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
	Airframe		MSC					O/C			
242110	Integrated Drive Generator (Right) - Oil Level Check		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
	Airframe		MSC					O/C			
242111	Integrated Drive Generator (Left) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.4			18 Aug 2023			
	Airframe		[HRS: +50/-50]								
242112	Integrated Drive Generator (Right) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.4			18 Aug 2023			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242113	Integrated Drive Generator Disconnect System (Left) - Operational Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.6	-16	50	13 Jul 2021	31 Aug 2025*	30 Sep 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
242114	Integrated Drive Generator Disconnect System (Right) - Operational Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.6	-13	50	13 Jul 2021	31 Aug 2025*	30 Sep 2025	
			[MOS: +1m/-1m]								
Airframe											
242115	Integrated Drive Generator (Left) - Servicing		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
			[HRS: +50/-50]								
Airframe											
242116	Integrated Drive Generator (Right) - Servicing		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
			[HRS: +50/-50]								
Airframe											
242117	Integrated Drive Generator Oil Scavenger Filter (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
			MSC				O/C				SUNDSTRAND
Airframe											
Notes: PN: 5905018 SN: <NONE>.											
242118	Integrated Drive Generator Oil Scavenger Filter (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
			MSC				O/C				SUNDSTRAND
Airframe											
Notes: PN: 5905018 SN: <NONE>.											
242141	Integrated Drive Generator Oil Scavenger Filter Differential Pressure Indicator (Left) - Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242142	Integrated Drive Generator Oil Scavenger Filter		HRS		134.1			3923.7			0
	Differential Pressure Indicator (Right) - Inspection		AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
			MSC					O/C			
Airframe											
242200	APU AC Generation Sys-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
242201	APU Generator - Removal / Installation		HRS		4057.8			0			0
	1159SCAV501-1	0649	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
			MSC					O/C			SUNDSTRAND
Airframe											
242202	APU Gcu - Removal / Installation		HRS		4057.8			0			0
	1702787B	1021	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
			MSC					O/C			SAV PROD-IPT
Airframe											
Notes: VERIFIED BY: PQ092											
242205	Idg, Oil APU - Service		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
242206	APU AC Generation System - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
242300	Emergency Inverter-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242301	Emergency Inverter - Removal / Installation		HRS		3087.3			970.5			0
	1-002-0102-1346	GC000057	AFL		908			276			0
			MOS		143.5			15 Feb 2012			AVIONIC INSTRUMENTS INC
	Airframe		MSC					O/C			
242400	Hyd Motor AC Gen Sys-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
242401	Hydraulic Motor Generator - Removal / Installation		HRS		616			3441.8			0
	1159SCAV522-7	G0910870	AFL		220			964			0
			MOS		19.5			14 Jun 2022			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311721											
242402	Hmg Gcu - Removal / Installation		HRS		4057.8			0			0
	1159SCAV523-1	C70810780	AFL		1184			0			0
			MOS		188.2			24 May 2008			SECURAPLANE TECHNOLOGIES, LLC
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ650											
242603	L Idg Gcu - Removal / Installation		HRS	TSN:3200.1	857.7			3200.1			0
	1702787B	1019	AFL	TSN:904	280			904			0
			MOS	TSN:158	30.6			13 Jul 2021			N/A
	Airframe		MSC					O/C			
Notes: VERIFIED BY: PQ092											
242604	R Idg Gcu - Removal / Installation		HRS	TSN:3200.1	857.7			3200.1			0
	1702787B	1021	AFL	TSN:904	280			904			0
			MOS	TSN:158	30.6			13 Jul 2021			N/A
	Airframe		MSC					O/C			
242700	60 HZ Power Generation System - Functional Check		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		MSC					O/C			
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242701	Converter (400 to 60 HZ) - Removal / Installation		HRS		0			4057.8			0
	1-002-0102-2052	HT000975	AFL		0			1184			0
			MOS		1.1			28 Dec 2023			N/A
	Airframe		MSC						O/C		
Notes: VER BY 310229											
242722	60 Hertz Cabin Pressure Switch - Functional Check		HRS								0
			AFL								0
			MOS				72		30 Sep 2028	31 Oct 2028	
	Airframe								[End Of Month Item] [MOS: +1m/-1m]		
243001	Main Battery (Left) - Removal / Installation		HRS		229.7			3828.1			0
	1159SCAV519-1	090520005C13A	AFL		82			1102			0
			MOS		7.5			16 Jun 2023			
	Airframe		MSC						O/C		
243002	Main Battery (Right) - Removal / Installation		HRS		229.7			3828.1			0
	1159SCAV519-1	0905200251BE9	AFL		82			1102			0
			MOS		7.5			16 Jun 2023			
	Airframe		MSC						O/C		
243003	L Main Battery Charger - Removal / Installation		HRS		2176.4			1881.4			0
	1159SCAV520-7	289534-762	AFL		663			521			0
			MOS		100.8			07 Sep 2015			UNISON INDUSTRIES
	Airframe		MSC						O/C		
Notes: VERIFIED BY Q 310159											
243004	R Main Battery Charger - Removal / Installation		HRS		4057.8			0			0
	1159SCAV520-3	B1368	AFL		1184			0			0
			MOS		188.2			24 May 2008			UNISON INDUSTRIES
	Airframe		MSC						O/C		
Notes: VERIFIED BY Q 310159											
243011	L Main Battery - Capacity Check		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.5	32	12	16 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe								[End Of Month Item] [MOS: +1m/-1m]		
Notes: PN: 1159SCAV519-1 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243012	R Main Battery - Capacity Check		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.5	32	12	16 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 1159SCAV519-1 SN: <NONE>.											
243013	L Main Battery Service and Electrolyte Level - Check		HRS		3739.7			318.1			0
			AFL		1091			93			0
			MOS		171.1			28 Oct 2009			
Airframe			MSC				O/C				
243014	R Main Battery Service and Electrolyte Level - Check		HRS		3739.7			318.1			0
			AFL		1091			93			0
			MOS		171.1			28 Oct 2009			
Airframe			MSC				O/C				
243015	Main Battery - Operational Check		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.5			16 Jun 2023			
Airframe			MSC				O/C				
243017	Probe, #1 Battery Temperature		HRS		4057.8			0			0
	P600-14B	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			FOXTRONICS INC
Airframe			MSC				O/C				
243018	Probe, #2 Battery Temperature		HRS		4057.8			0			0
	P600-14B	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			FOXTRONICS INC
Airframe			MSC				O/C				
243020	Tail Compartment Dc Feeder Cables - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8	23	96	07 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
243100	L Main Tru - Removal / Installation		HRS		4057.8			0			0
	1159SCAV508-3	B2731	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243101	L Essential Tru - Removal / Installation		HRS		4057.8			0			0
	1159SCAV508-3	B2730	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU
	Airframe		MSC					O/C			E
243102	R Main Tru - Removal / Installation		HRS		4057.8			0			0
	1159SCAV508-3	B2733	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU
	Airframe		MSC					O/C			E
243103	R Essential Tru - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
	1159SCAV508-3	B2734	AFL	TSN:611	573			611			0
			MOS	TSN:100	88.1			28 Sep 2016			INTERTECHNIQU
	Airframe		MSC					O/C			E
243104	Auxiliary Tru - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
	1159SCAV508-3	B2732	AFL	TSN:611	573			611			0
			MOS		88.1			28 Sep 2016			INTERTECHNIQU
	Airframe		MSC					O/C			E
243801	Battery Volt / AMP Meter - Removal / Installation		HRS		4057.8			0			0
	789550-2-1	0654	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VER BY PQ648											
244200	External AC Power System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
244300	External Dc Power System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245005	AC Load Distribution System - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
245101	Left Power Distribution Box - Removal / Installation		HRS		4057.8			0			0
	1703230	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
245102	Right Power Distribution Box - Removal / Installation		HRS		4057.8			0			0
	1703232	0353	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
245121	Left Power Distribution Box Mounting Tray - Removal / Installation		HRS		4057.8			0			0
	1703237A	0338	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
245122	Right Power Distribution Box Mounting Tray - Removal / Installation		HRS		4057.8			0			0
	1703239A	0226	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
245345	No. 1 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	106186-2	26830608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245346	No. 2 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	106186-2	26860608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245347	No. 3 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26840608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245348	No. 4 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26870608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245349	No. 5 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26900608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245351	No. 7 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26850608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245352	No. 8 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26890608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245353	No. 9 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26750608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											
245354	No. 10 60 HZ Power Outlet - Final Phase Removal / Installation		HRS		4025.2			32.6			0
			AFL		1170			14			0
	106186-2	26760608	MOS		184.6			12 Sep 2008			MID CONTINENT CONTROLS
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245355	Outlet, #11 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26770608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245356	Outlet, #12 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26780608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245357	Outlet, #13 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26630608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245358	Outlet, #14 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26720608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245359	Outlet, #15 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26800608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245360	Outlet, #16 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26790608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245361	Outlet, #17 60 HZ Universal		HRS		957.9			3099.9			0
	106186-2	76200620	AFL		313			871			0
			MOS		41.1			28 Aug 2020			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245362	Outlet, #18 60 HZ Universal		HRS		4025.2			32.6			0
	106186-2	26900608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245370	Controller, #1 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37850708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245371	Controller, #2 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37880708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245372	Controller, #3 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37830708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245373	Controller, #4 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37860708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245374	Controller, #5 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37970708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245375	Controller, #6 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37840708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245376	Controller, #7 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37870708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245377	Controller, #8 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	26890608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245378	Controller, #9 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	30620308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245379	Controller, #10 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	30630308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245380	Controller, #11 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	30640308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245381	Controller, #12 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	30650308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245382	Controller, #13 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	34610508	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245383	Controller, #14 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	34600508	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245384	Controller, #15 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	30610308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245385	Controller, #16 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	36110608	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245386	Controller, #17 60 HZ AC Power		HRS		4025.2			32.6			0
	106075-1	34210508	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
245387^U	Controller, #18 60HZ AC Power		HRS		4025.2			32.6			0
	106075-1	37970708	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			MID CONTINENT
	Airframe		MSC					O/C			CONTROLS
246001	L Bpcu - Removal / Installation		HRS		4057.8			0			0
	1702789A	0677	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
246002	R Bpcu - Removal / Installation		HRS		4057.8			0			0
	1702789A	0679	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
246005	Direct Current Load Distribution System - Operational Check		HRS		1909.3			2148.5			0
			AFL		573			611			0
			MOS		88			30 Sep 2016			
			MSC					O/C			
Airframe											
246010	Ground Service Bus - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
248020	E System Controller (No. 1)		HRS		4057.8			0			0
	2052-1-8	208020155	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			ELECTRO ENTERPRISES INC
Airframe											
Notes: MODS A,B,D,E,F,G,H,J,K,											
25 - Equipment/Furnishings											
250010	Towbar, Aircraft		HRS		4057.8			0			0
	WYG45XLT	4354	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			AERO WELD INC
Airframe											
251001	Pilot Seat - Removal / Installation		HRS	TSN:3559.4	498.9			3558.9			0
	1159SCF513-23	52703	AFL	TSN:998	186			998			0
			MOS	TSN:172	16			01 Oct 2022			N/A
			MSC					O/C			
Airframe											
251002	Copilot Seat - Removal / Installation		HRS		957.9			3099.9			0
	1159SCF513-24	52922	AFL		313			871			0
			MOS		42.6			13 Jul 2020			N/A
			MSC					O/C			
Airframe											
251003	Observer Seat - Removal / Installation		HRS	TSN:2148.5	1909.3			2148.5			0
	1159SCF501-1	331-1425	AFL	TSN:611	573			611			0
			MOS	TSN:100	88			30 Sep 2016			
			MSC					O/C			AIRCRAFT SEATING PRODUCTS
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251006	Crew Seats Inertia Reel (Pilot) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
251007	Crew Seats Inertia Reel (Copilot) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
251008	Crew Seats Inertia Reel (Observer) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
251011	Crew Seat Tracks (Pilot) - Lubrication		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
251012	Crew Seat Tracks (Copilot) - Lubrication		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
251013	Crew Seat Track (Observer) - Lubrication		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
251016	Crew Seat Restraints (Pilot) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
251017	Crew Seat Restraints (Copilot) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251018	Crew Seat Restraints (Observer) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
251021	Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
251022	Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
251023	Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
251101	Glareshield (Cockpit)		HRS		4057.8			0			0
	1159FP40014-S803	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		
	Airframe						O/C				
252001	Cabin Full Size Single Seat (Left No. 1) - Final Phase Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	2524.524.01-117159B	080606-07	MOS		65.7				09 Aug 2018		AIRCRAFT MODULAR
	Airframe						O/C				
252002	Cabin Full Size Single Seat (Left No. 2) - Final Phase Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	2524.524.01-614758A	080606-10	MOS		65.7				09 Aug 2018		AIRCRAFT MODULAR
	Airframe						O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252003	Cabin Full Size Single Seat (Left No. 3) - Final Phase		HRS		1654.7			2403.1			0
	Removal / Installation		AFL		493			691			0
	2524.524.01-614859B	080606-11	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252006	Cabin Full Size Single Seat (Right No. 1) - Final Phase		HRS		1654.7			2403.1			0
	Removal / Installation		AFL		493			691			0
	2524.524.01-614856B	080606-08	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252007	Cabin Full Size Single Seat (Right No. 2) - Final Phase		HRS		1654.7			2403.1			0
	Removal / Installation		AFL		493			691			0
	2524.524.01-614783A	080606-07	MOS	TSN:119	65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252012	Cabin Double Seat (Aft Facing No. 2) - Final Phase		HRS		1654.7			2403.1			0
	Removal / Installation		AFL		493			691			0
	2524.525.01-4016A	080606-06	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252013	Cabin Double Seat (Forward Facing No. 1) - Final Phase		HRS		1654.7			2403.1			0
	Removal / Installation		AFL		493			691			0
	2524.525.01-4010B	080606-05	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252015	Divan, Four Place (No. 1)		HRS		1654.7			2403.1			0
	2523.700-01-03		AFL		493			691			0
		080606-04	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											
252016	Divan, Four Place (No. 2)		HRS		1654.7			2403.1			0
	2523.700-01-03		AFL		493			691			0
		080606-03	MOS		65.7			09 Aug 2018			AIRCRAFT
			MSC								MODULAR
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252021	Shade, Window (Left, No. 1)		HRS		616			3441.8			0
	WSFA-20-008	0633-101	AFL		220			964			0
			MOS	TSN:165	19.8			07 Jun 2022			
	Airframe		MSC					O/C			
252022	Shade, Window (Left, No. 2)		HRS		4025.2			32.6			0
	WSFA-20-008	0633-104	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC					O/C			
252023	Shade, Window (Left, No. 3)		HRS	TSN:3584.9	440.3			3617.5			0
	WSFA-20-008	0633-106	AFL	TSN:1007	163			1021			0
			MOS	TSN:170	14.3			22 Nov 2022			N/A
	Airframe		MSC					O/C			
252024	Shade, Window (Left, No. 4)		HRS		1756.7			2301.1			0
	ATG20F011	000070690	AFL		531			653			0
			MOS		79.3			23 Jun 2017			ATG
	Airframe		MSC					O/C			
252025	Shade, Window (Left, No. 5)		HRS		4025.2			32.6			0
	WSFA-20-008	0633-108	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC					O/C			
252026	Shade, Window (Left, No. 6)		HRS	TSN:3067.3	957.9			3099.9			0
	WSFA-20-007	0633-503	AFL	TSN:857	313			871			0
			MOS	TSN:144	41.2			25 Aug 2020			
	Airframe		MSC					O/C			
252027	Shade, Window (Right, No. 1)		HRS		4025.2			32.6			0
	ATG-WS-2002	0633-901	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC					O/C			
252028	Shade, Window (Right, No. 2)		HRS		4025.2			32.6			0
	ATG-WS-2002	0633-902	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252029	Shade, Window (Right, No. 3)		HRS		47.9			4009.9			0
	WSFA-20-008	0668-107	AFL		19			1165			0
			MOS		2.8			07 Nov 2023			
	Airframe		MSC						O/C		
252030	Shade, Window (Right, No. 4)		HRS	TSN:3977.3	47.9			4009.9			0
	WSFA-20-008	0633-102	AFL	TSN:1151	19			1165			0
			MOS	TSN:182	2.8			06 Nov 2023			
	Airframe		MSC						O/C		
252031	Shade, Window (Right, No. 5)		HRS		4025.2			32.6			0
	WSFA-20-008	0633-105	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC						O/C		
252032	Shade, Window (Right, No. 6)		HRS		3118.8			939			0
	WSFA-20-007	0633-501	AFL		916			268			0
			MOS		144.5			16 Jan 2012			ATG
	Airframe		MSC						O/C		
252033	Shade, Window (Left, No. 7)		HRS		4025.2			32.6			0
	WSFA-20-007	0633-504	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ATG
	Airframe		MSC						O/C		
252034	Shade, Window (Right, No. 7)		HRS		957.9			3099.9			0
	WSFA-20-007	0711-504	AFL		313			871			0
			MOS		41.4			19 Aug 2020			ATG
	Airframe		MSC						O/C		
252047	Divan, Four Place (No. 3)		HRS		1654.7			2403.1			0
	2523.700-01-04	080606-02	AFL		493			691			0
			MOS		65.7			09 Aug 2018			AIRCRAFT
	Airframe		MSC						O/C		MODULAR
252048	Divan, Four Place (No. 4)		HRS		1654.7			2403.1			0
	2523.700-01-04	080606-01	AFL		493			691			0
			MOS		65.7			09 Aug 2018			AIRCRAFT
	Airframe		MSC						O/C		MODULAR

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252051	Conference Table Lift - Final Phase Removal / Installation		HRS		2943.3			1114.5			0
	70221-18H	33104	AFL		858			326			0
			MOS	TSN:48	136.5			15 Sep 2012			ENFLITE
	Airframe		MSC					O/C			
252070	Supplemental Floor Heater No. 1 - Removal / Installation		HRS		4057.8			0			0
	80WS033	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV COMPLETION IPTS
	Airframe		MSC					O/C			
252101	Passenger Seats Attachments and Locking - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.3	10	48	21 Aug 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
252102	Passenger Seats Restraints - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
252103	Passenger Seats and Seat Tracks - Lubrication		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
	Airframe		MSC					O/C			
252104	Passenger Seats Inertia Reels - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
252501	Table, Forward (Left)		HRS		4025.2			32.6			0
	53775-15	33838	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ENFLITE, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252503	Table, Mid (Left)		HRS		4025.2			32.6			0
	53775-25	33102	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ENFLITE, INC.
	Airframe		MSC					O/C			
252504	Table, Mid (Right)		HRS		4025.2			32.6			0
	53775-25	33103	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ENFLITE, INC.
	Airframe		MSC					O/C			
253010	Microwave Oven - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	R-21HT	04747	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SHARP
	Airframe		MSC					O/C			
253011	Oven (Galley) {No. 1}		HRS		4025.2			32.6			0
	2510-0069-03	314015201	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			BE AEROSPACE
	Airframe		MSC					O/C			
253017	Coffeemaker (No. 1) - Final Phase Removal / Installation		HRS		4025.2			32.6			0
	400-1794-02	08-07-43871	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			TIA
	Airframe		MSC					O/C			
253029	Refrigerator		HRS		1094.4			2963.4			0
	DA1200CSU-GA44	CSU-0302	AFL		342			842			0
			MOS		50.6			12 Nov 2019			N/A
	Airframe		MSC					O/C			
253201	Espresso Machine		HRS		3884.3			173.5			0
	AL-EX15-200E-29	270	AFL		1138			46			0
			MOS		178.3			23 Mar 2009			AEROLUX
	Airframe		MSC					O/C			
253203	Valve, Coffee Fill (No. 1)		HRS		4025.2			32.6			0
	9693-1-3	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ADAMS-RITE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
253204	Valve, Coffee Fill (No. 2)		HRS		4025.2			32.6			0
	9693-1-3	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ADAMS-RITE
	Airframe		MSC					O/C			
254101	Lavatory Compartment - Inspection		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
	Airframe		MSC					O/C			
256006	Goggles, Crew Smoke (Pilot)		HRS		4057.8			0			0
	MXP210-00	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
256007	Goggles, Crew Smoke (Copilot)		HRS		4057.8			0			0
	MXP210-00	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
256008	Goggles, Crew Smoke (Observer)		HRS		4057.8			0			0
	MXP210-00	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
256009	Goggles, CSO (Communications Stations)		HRS		4057.8			0			0
	MXP210-00	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			INTERTECHNIQU E
	Airframe		MSC					O/C			
256011	Crew Smoke Goggles (Pilot) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5	-3	36	16 Aug 2023	31 Aug 2026*	30 Sep 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256012	Crew Smoke Goggles (Copilot) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5	-3	36	16 Aug 2023	31 Aug 2026*	30 Sep 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256013	Crew Smoke Goggles (Observer) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5	-3	36	16 Aug 2023	31 Aug 2026*	30 Sep 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256016	Axe, FIRE / Crash		HRS		4025.2			32.6			0
	4208331	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GARRETT
	Airframe		MSC O/C								
256017	FIRE / Crash Axe - Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256025	Ditching Line - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5	31	48	14 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256041	No. 1 First AID Kit		HRS		192.1			3865.7			0
	AFAK 1.0	082019032	AFL		78			1106			0
			MOS		7.7			09 Jun 2023			
	Airframe		MSC O/C								
256043	First AID Kit (No. 1) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.7	40	12	09 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256045	First AID Kit (No. 1) Time Limited Supplies - Discard		HRS		192.1			3865.7			0
	AFAK 1.0	082019032	AFL		78			1106			0
			MOS		7.7		12	09 Jun 2023	30 Jun 2024		
	Airframe		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256061	Flashlight (No. 1) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
	106-000-646	R32774497	AFL	TSN:1102	82			1102			0
			MOS	TSN:181	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256062	Flashlight (No. 2) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
	106-000-646	R32774221	AFL	TSN:1102	82			1102			0
			MOS	TSN:181	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256063	Flashlight (No. 3) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
	106-000-646	R32772566	AFL	TSN:1102	82			1102			0
			MOS	TSN:181	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256064	Flashlight (No. 4) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
	106-000-646	32695336	AFL	TSN:1102	82			1102			0
			MOS	TSN:181	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256071	Flashlight (No. 1) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256072	Flashlight (No. 2) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256073	Flashlight (No. 3) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256074	Flashlight (No. 4) - Operational Test		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256201	Life Vest(S) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256202	Life Raft(S) (No. 1) - Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.5	-13	12	15 Jun 2023	30 Jun 2024*	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256203	Life Raft(S) (No. 2) - Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.5	-13	12	15 Jun 2023	30 Jun 2024*	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 1421FAUL-6K0-1-100 SN: <NONE>.											
256205	Life Vest - Restore		HRS		1654.7			2403.1			0
	63600-505	L789539	AFL		493			691			0
			MOS		65.7		120	09 Aug 2018	03 Jul 2028		
	Airframe										
256211	Life Vest (No. 1) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3812925	AFL	TSN:438	82			1102			0
			MOS	TSN:71	7.9			04 Jun 2023			
	Airframe		MSC		O/C						
	Notes: CMP UPDATE FOR INSTALLED S/N										
256212	Life Vest (No. 2) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762534	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC		O/C						
	Notes: CMP UPDATE FOR INSTALLED S/N										
256213	Life Vest (No. 3) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762508	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC		O/C						
	Notes: CMP UPDATE FOR INSTALLED S/N										
256214	Life Vest (No. 4) - Removal / Installation		HRS	TSN:751.8	229.7			3828.1			0
	63600-105	L4742149	AFL	TSN:233	82			1102			0
			MOS	TSN:49	7.9			04 Jun 2023			
	Airframe		MSC		O/C						

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256215	Life Vest (No. 5) - Removal / Installation		HRS	TSN:751.8	229.7			3828.1			0
	63600-105	L4742160	AFL	TSN:233	82			1102			0
			MOS	TSN:49	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256216	Life Vest (No. 6) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762498	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256217	Life Vest (No. 7) - Removal / Installation		HRS	TSN:751.8	229.7			3828.1			0
	63600-105	L4742065	AFL	TSN:233	82			1102			0
			MOS	TSN:49	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256218	Life Vest (No. 8) - Removal / Installation		HRS	TSN:751.8	229.7			3828.1			0
	63600-105	L4742144	AFL	TSN:233	82			1102			0
			MOS	TSN:49	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256219	Life Vest (No. 9) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762531	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256220	Life Vest (No. 10) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762509	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256221	Life Vest (No. 11) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762507	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256222	Life Vest (No. 12) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762588	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256223	Life Vest (No. 13) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762598	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256224	Life Vest (No. 14) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3812924	AFL	TSN:438	82			1102			0
			MOS	TSN:71	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256225	Life Vest (No. 15) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3812926	AFL	TSN:438	82			1102			0
			MOS	TSN:71	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256226	Life Vest (No. 16) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-105	L3762575	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256250	Life Vest (Pilot) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-505	L3554156	AFL	TSN:438	82			1102			0
			MOS	TSN:79	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256251	Life Vest (Copilot) - Removal / Installation		HRS		229.7			3828.1			0
	63600-505	L4962782	AFL		82			1102			0
			MOS	TSN:42	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256252	Life Vest (Observer) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
	63600-505	L3765085	AFL	TSN:438	82			1102			0
			MOS	TSN:73	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
256253	Life Vest (Crew Member) - Removal / Installation		HRS	TSN:751.8	229.7			3828.1			0
	63600-505	L4962784	AFL	TSN:233	82			1102			0
			MOS	TSN:42	7.9			04 Jun 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256260	Life Raft (No. 1) - Removal / Installation		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-100	14UL-00347	AFL		78			1106			0
			MOS		7.5			15 Jun 2023			
	Airframe		MSC					O/C			
256261	Life Raft (No. 2) - Removal / Installation		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-100	14UL-00348	AFL		78			1106			0
			MOS		7.5			15 Jun 2023			
	Airframe		MSC					O/C			
256265	ELT Battery, Life Raft (No. 1) - Scrap		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-100	14UL-00347	AFL		78			1106			0
			MOS		7.5			15 Jun 2023	31 Mar 2027		
	Airframe		MSC					DUE			EXPIRATION
											[End Of Month Item]
256266	ELT Battery, Life Raft (No. 2) - Scrap		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-10	14UL-00348	AFL		78			1106			0
			MOS		7.5		72	15 Jun 2023	31 Jan 2029		
	Airframe										EXPIRATION
											[End Of Month Item]
Notes: CUSTOMER REQUEST FREQUENCY											
256270	Life Raft (No. 1) - Restore		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-100	14UL-00347	AFL		78			1106			0
			MOS		7.5		36	15 Jun 2023	30 Jun 2026		
	Airframe										EXPIRATION
											[End Of Month Item]
256271	Life Raft (No. 2) - Restore		HRS		192.1			3865.7			0
	1421FAUL-6K0-1-100	14UL-00348	AFL		78			1106			0
			MOS		7.5		36	15 Jun 2023	30 Jun 2026		
	Airframe										EXPIRATION
											[End Of Month Item]
256274	ELT, Life Raft (No. 1) - Operational Check		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
	Airframe		MSC					O/C			
256275	ELT, Life Raft (No. 2) - Operational Check		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256281	Protective Breathing Equipment (No. 1) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
			AFL	TSN:438	82			1102			0
	MR-10039N	E1704172	MOS	TSN:70	7.9			04 Jun 2023			
			MSC							O/C	
Airframe											
256282	Protective Breathing Equipment (No. 1) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe											
256283	Protective Breathing Equipment (No. 1) - Discard		HRS		1735.4			2322.4			0
	MR-10039N	E1704172	AFL		520			664			0
			MOS		76.8		126	05 Sep 2017	01 Feb 2028		GULFSTREAM SAV COMPLETION IPTS EXPIRATION
Airframe											
256284	Protective Breathing Equipment (No. 2) - Removal / Installation		HRS	TSN:1505.7	229.7			3828.1			0
			AFL	TSN:438	82			1102			0
	MR-10039N	E1704217	MOS	TSN:70	7.9			04 Jun 2023			
			MSC							O/C	
Airframe											
256285	Protective Breathing Equipment (No. 2) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe											
256286	Protective Breathing Equipment (No. 2) - Discard		HRS		1735.4			2322.4			0
	MR-10039N	E1704217	AFL		520			664			0
			MOS		76.8		126	05 Sep 2017	01 Feb 2028		GULFSTREAM SAV COMPLETION IPTS EXPIRATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	TSN							Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256301	Emergency Locator Transmitter - Removal / Installation		HRS		134.1			3923.7			0
	453-5060	07863	AFL		44			1140			0
			MOS		5.2			26 Aug 2023			N/A
	Airframe		MSC					O/C			
256302	Emergency Locator Transmitter Batteries - Discard		HRS		134.1			3923.7			0
	452-0133	398519-016	AFL		44			1140			0
			MOS	TSN:8	5.2		60	26 Aug 2023	31 Jan 2028		
	Airframe		[End Of Month Item]								EXPIRATION
256303	Emergency Locator Transmitter Antenna - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	110-341	51238	MOS	TSN:3	42.3			21 Jul 2020			N/A
	Airframe		MSC					O/C			
256306	Emergency Locator Transmitter - Operational Test (FAR 91.207)		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.7		12	10 Jun 2023	30 Jun 2024		
	Airframe		[End Of Month Item]								
256311	Emergency Locator Transmitter - Operational Check		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.2			26 Aug 2023			
	Airframe		MSC					O/C			
256326	Emergency Locator Transmitter Antenna - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3			22 Jul 2020			
	Airframe		MSC					O/C			
256401	Defibrillator		HRS		1189.2			2868.6			0
	500247	18G00001791	AFL		361			823			0
			MOS		52.6			11 Sep 2019			AGILENT TECH
	Airframe		MSC					O/C			
256412	Defibrillator - Operational Check		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256413	Defibrillator - Final Phase Inspection		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
	Airframe			MSC				O/C			
256421	Humidifier, Bubble		HRS		4025.2			32.6			0
	02C33K08-30	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			O2 CORP
	Airframe			MSC				O/C			
256429	Battery, Defibrillator (No. 1) - Manufacture Life		HRS		1189.2			2868.6			0
	500247	18G00001791	AFL		361			823			0
			MOS		52.7		72	10 Sep 2019	30 Nov 2024		
	Airframe										MANUFACTURE
26 - FIRE Protection											
260301	Baggage Compartment Smoke Evacuation Valve -		HRS		957.9			3099.9			0
	Operational Test		AFL		313			871			0
			MOS		40.9	31	72	04 Sep 2020	31 Oct 2026*	30 Nov 2026	
	Airframe										[End Of Month Item] [MOS: +1m/-1m]
260302	Smoke Evacuation Valve - Removal / Installation		HRS		4057.8			0			0
	B-43YF2-RD-SS	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GE
	Airframe			MSC				O/C			POLYMERSHAPE S
261101	Equipment Overheat Thermal Switch (Leer, 056S4) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850-DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			
261102	Equipment Overheat Thermal Switch (Leer, 056S5) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261103	Equipment Overheat Thermal Switch (Leer, 056S6) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261104	Equipment Overheat Thermal Switch (Left Shelf No. 4) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261105	Equipment Overheat Thermal Switch (Reer, 056S20) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261106	Equipment Overheat Thermal Switch (Reer, 056S21) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261107	Equipment Overheat Thermal Switch (Right Shelf No. 3) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261108	Equipment Overheat Thermal Switch (Right Shelf No. 4) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC								
Airframe											
261109	Equipment Overheat Thermal Switch (Leer) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
261110	Equipment Overheat Thermal Switch (Reer) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
261145	Engine FIRE and Heat Sensing (Left) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
261146	Engine FIRE and Heat Sensing (Right) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
261151	FIRE Detection RAIL Assembly No. 5 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-196	08-01-9678	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Airframe											
261152	FIRE Detection RAIL Assembly No. 5 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-196	08-02-9761	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261155	FIRE Detection RAIL Assembly No. 2 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-201	08-03-9919	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261156	FIRE Detection RAIL Assembly No. 2 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-201	08-03-9918	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261157	FIRE Detection RAIL Assembly No. 3 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-198	08-02-9806	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261158	FIRE Detection RAIL Assembly No. 3 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	51291-198	08-02-9803	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
261201	FIRE Detection Control Box (Left Engine) - Removal / Installation		HRS		1803			2254.8			0
			AFL		543			641			0
	51653-154	3290	MOS		81.5			17 Apr 2017			KIDDE AEROSPACE
			MSC					O/C			
Airframe											
Notes: SWAP FOR TS											
261202	FIRE Detection Control Box (Right Engine) - Removal / Installation		HRS		498.9			3558.9			0
			AFL		186			998			0
	51653-274	02730	MOS	TSN:19	15.9			04 Oct 2022			N/A
			MSC					O/C			
Airframe											
Notes: SWAP FOR TS											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261203	Pylon Thermal Switch (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261204	Pylon Thermal Switch (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261205	Pylon Thermal Switch (Left No. 3) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261206	Pylon Thermal Switch (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261207	Pylon Thermal Switch (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261208	Pylon Thermal Switch (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
	GAS850DF512-250	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
261209	Pylon Thermal Switch (Left) - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261210	Pylon Thermal Switch (Right) - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
261211	FIRE Detection Control Box (Left Engine) - Functional Test		HRS		1803			2254.8			0
			AFL		543			641			0
			MOS		81.5			17 Apr 2017			
	Airframe							O/C			
261212	FIRE Detection Control Box (Right Engine) - Functional Test		HRS		498.9			3558.9			0
			AFL		186			998			0
			MOS		15.9			04 Oct 2022			
	Airframe							O/C			
261301	APU FIRE Detection Loop - Removal / Installation		HRS		4057.8			0			0
	6360-12-1000/450-7	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			MEGGITT SAFETY SYSTEMS
	Airframe							O/C			
261302	APU (FIRE) Shut-Down Circuit - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
261305	APU Compartment FIRE Detect Loop - Operational Test		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			AFL		44			1140			0
			MOS		4.8			06 Sep 2023			
	Airframe			[HRS: +50/-50]							
261401	Equipment Overheat Thermal Switch (Baggage Electronic Equipment Rack, 056S8) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
	Airframe							O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261402	Equipment Overheat Thermal Switch (Baggage Electronic Equipment Rack, 056S9) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC					O/C			
Airframe											
261403	Equipment Overheat Thermal Switch (Left Aft Floor, 056S12) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261404	Equipment Overheat Thermal Switch (Left Aft Floor, 056S13) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261405	Equipment Overheat Thermal Switch (Left Aft Floor, 056S14) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261406	Equipment Overheat Thermal Switch (Center Aft Floor, 056S15) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261407	Equipment Overheat Thermal Switch (Right Aft Floor, 056S16) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
261408	Equipment Overheat Thermal Switch (Aft Equipment, 056S10) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261409	Equipment Overheat Thermal Switch (Aft Equipment, 056S11) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
261410	Equipment Overheat Thermal Switch (Right Aft Floor, 056S27) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
261411	Equipment Overheat Thermal Switch (Right Aft Floor, 056S28) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
261412	Equipment Overheat Thermal Switch (Center Aft Floor, 056S29) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-250	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
261413	Equipment Overheat Thermal Switch (Forward Floor, 056S24) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											
261414	Equipment Overheat Thermal Switch (Forward Floor, 056S25) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC				O/C				COMMERCIAL ELECTRONICS SYSTEMS
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261415	Equipment Overheat Thermal Switch (Forward Floor, 056S26) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC					O/C			
Airframe											
261416	Equipment Overheat Thermal Switch (Forward Floor, 056S30) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC					O/C			
Airframe											
261417	Equipment Overheat Thermal Switch (Forward Floor, 056S31) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GAS850DF512-150	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
			MSC					O/C			
Airframe											
261418	Aft Equipment Overheat Thermal Switches - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5	31	48	15 Jul 2020	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
261419	Baggage Compartment Below Floor Overheat Thermal Switch - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
261503	Smoke Detection Unit (Baggage Compartment) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	72130001-006	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261601	FIRE Detection and Indication - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
262020	Engine FIRE Bottle (Left) - Removal / Installation		HRS		616			3441.8			0
	33800100-1	60419D1	AFL		220			964			0
			MOS		19.8			07 Jun 2022			
	Airframe		MSC					O/C			
262021	Engine FIRE Bottle (Left) - (Hydrostatic) Functional Test		HRS		1735.4			2322.4			0
			AFL		520			664			0
			MOS		76.7			08 Sep 2017			
	Airframe		MSC					O/C			
Notes: PN: 33800100-1 SN: <NONE>. Q306794											
262025	Engine FIRE Bottle (Right) - Removal / Installation		HRS		134.1			3923.7			0
	33800100-1	58969D1	AFL		44			1140			0
			MOS		4.5			16 Sep 2023			N/A
	Airframe		MSC					O/C			
262026	Engine FIRE Bottle (Right) - (Hydrostatic) Functional Test		HRS		1735.4			2322.4			0
			AFL		520			664			0
			MOS		76.7			08 Sep 2017			
	Airframe		MSC					O/C			
Notes: PN: 33800100-1 SN: <NONE>. VERIFIED BY Q309044											
262101	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Removal / Installation		HRS	TSN:2868.6	1189.2			2868.6			0
			AFL	TSN:823	361			823			0
	35201023-1	N/A	MOS	TSN:136	52.9			04 Sep 2019			MATRIX AVIATION INC
	Airframe		MSC					O/C			
262102	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Removal / Installation		HRS	TSN:2868.6	1189.2			2868.6			0
			AFL	TSN:823	361			823			0
	35201023-1	N/A	MOS	TSN:136	52.9			04 Sep 2019			MATRIX AVIATION INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262103	Engine FIRE Pull Handle (Left) - Functional Test		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
262105	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Detailed Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.9		120	04 Sep 2019	30 Sep 2029	31 Oct 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262106	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Detailed Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.9		120	04 Sep 2019	30 Sep 2029	31 Oct 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262108	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903852	2588VB	MOS		76.7		120	08 Sep 2017	30 Sep 2027		PACIFIC SCIENTIFIC CO
	Airframe		[End Of Month Item]								
Notes: VERIFIED BY Q309044											
262109	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903933	0025AM	MOS		19.7		180	08 Jun 2022	31 May 2036		MANUFACTURE
	Airframe		[End Of Month Item]								
262110	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903876	0891VK	MOS		76.7		120	08 Sep 2017	30 Sep 2027		PACIFIC SCIENTIFIC CO
	Airframe		[End Of Month Item]								
Notes: Q306794											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262111	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903959	2760BH	MOS		19.8		180	07 Jun 2022	30 Nov 2036		
Airframe											MANUFACTURE
Notes: Q306794											
262112	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903928	1158VK	MOS		76.7		120	08 Sep 2017	30 Sep 2027		
Airframe											PACIFIC SCIENTIFIC CO
Notes: Q306794											
262113	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903931	0422CA	MOS		19.8		180	07 Jun 2022	28 Feb 2037		
Airframe											MANUFACTURE
Notes: Q306794											
262114	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903876	0110VK	MOS		76.7		120	08 Sep 2017	30 Sep 2027		
Airframe											PACIFIC SCIENTIFIC CO
Notes: VERIFIED BY Q309044											
262115	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903959	2792BH	MOS		19.7		180	08 Jun 2022	30 Nov 2036		
Airframe											MANUFACTURE
Notes: VERIFIED BY Q309044											
262116	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903828	1182UK	MOS		76.7		120	08 Sep 2017	30 Sep 2027		
Airframe											PACIFIC SCIENTIFIC CO
Notes: VERIFIED BY Q309044											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262117	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903931	0408CA	MOS		19.7		180	08 Jun 2022	28 Feb 2037		MANUFACTURE
Airframe											
Notes: VERIFIED BY Q309044											
262118	Engine FIRE Bottle Cartridge (Left Bottle, APU / Spare Squib, Service Life) - Discard		HRS		1735.4			2322.4			0
			AFL		520			664			0
	30903852	0330VB	MOS		76.7		120	08 Sep 2017	30 Sep 2027		PACIFIC SCIENTIFIC CO
Airframe											
Notes: Q306794											
262119	Engine FIRE Bottle Cartridge (Left Bottle, APU / Spare Squib, Manufacturers Life) - Discard		HRS		616			3441.8			0
			AFL		220			964			0
	30903933	0024AM	MOS		19.8		180	07 Jun 2022	31 May 2036		MANUFACTURE
Airframe											
Notes: Q306794											
262120	Engine FIRE Pull Handle (Left) - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	GAB850DT1	1583	MOS		65.7			09 Aug 2018			ESTERLINE MASON
Airframe											
Notes: VERIFIED BY PQ514											
262121	Engine FIRE Pull Handle (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	24293-2	335	MOS		188.2			24 May 2008			JANCO CORPORATION
Airframe											
Notes: VERIFIED BY PQ514											
262122	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (Left Engine) - Functional Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.7	30	36	10 Jul 2021	31 Aug 2024*	30 Sep 2024	
Airframe											
[End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262123	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (Right Engine) - Functional Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.7	30	36	10 Jul 2021	31 Aug 2024*	30 Sep 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262124	Engine FIRE Bottle Pressure Switch (Left) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		60	07 Jun 2022	30 Jun 2027	31 Jul 2027	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262125	Engine FIRE Bottle Pressure Switch (Right) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		60	08 Jun 2022	30 Jun 2027	31 Jul 2027	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262126	Engine and APU FIRE Extinguishing Firing Circuitry Integrity (APU) - Functional Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.7	30	36	10 Jul 2021	31 Aug 2024*	30 Sep 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262128	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903959	2760BH	MOS	TSN:6	19.8			07 Jun 2022			
			MSC				O/C				
Airframe											
262129	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903931	0422CA	MOS	TSN:3	19.8			07 Jun 2022			
			MSC				O/C				
Airframe											
262130	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903933	0024AM	MOS	TSN:12	19.8			07 Jun 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262131	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903959	2792BH	MOS	TSN:6	19.7			08 Jun 2022			
			MSC							O/C	
Airframe											
262132	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903931	0408CA	MOS	TSN:3	19.7			08 Jun 2022			
			MSC							O/C	
Airframe											
262133	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Removal / Installation		HRS		616			3441.8			0
			AFL		220			964			0
	30903852	0025AM	MOS	TSN:12	19.7			08 Jun 2022			
			MSC							O/C	
Airframe											
262138	Engine FIRE Bottle Low Pressure Switch (Functional Check) (Right) - Restore		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2	3317		24 May 2008			
			MSC							O/C	
Airframe [End Of Month Item]											
262139	Engine FIRE Bottle (Left) - Weight Check		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		53		60	30 Aug 2019 30 Aug 2024 30 Sep 2024			
Airframe [MOS: +1m/-1m]											
262140	Engine FIRE Bottle (Right) - Weight Check		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		53		60	30 Aug 2019 31 Aug 2024 30 Sep 2024			
Airframe [End Of Month Item] [MOS: +1m/-1m]											
262510	Portable Water FIRE Extinguisher (Forward Cabin) - Removal / Installation		HRS		229.7			3828.1			0
			AFL		82			1102			0
	892480	20370	MOS		7.9			04 Jun 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262511	Portable Water FIRE Extinguisher (Forward Cabin) - Restore		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
			MSC					O/C			OVERHAUL
Airframe											
Notes: PN: 892480 SN: 20317.											
262512	Portable Water FIRE Extinguisher (Forward Cabin) - (Proof Pressure Test) Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9		60	04 Sep 2020	30 Jun 2025		
											HYDRO CHECK
[End Of Month Item]											
Airframe											
262513	Portable Water FIRE Extinguisher (Forward Cabin) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9		12	04 Jun 2023	30 Jun 2024	31 Jul 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262550	Extinguisher, Trash (Aft Lavatory)		HRS		1654.7			2403.1			0
	474276	SN-UNKNOWN	AFL		493			691			0
			MOS		65.7			09 Aug 2018			WALTER KIDDE
			MSC					O/C			
Airframe											
262551	Extinguisher, Trash (Forward Lavatory)		HRS		4025.2			32.6			0
	474276	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			WALTER KIDDE
			MSC					O/C			
Airframe											
262553	Extinguisher, Trash (Forward Galley / Annex)		HRS		4025.2			32.6			0
	474276	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			WALTER KIDDE
			MSC					O/C			
Airframe											
262560	Trash Receptacle Enclosure (Aft Lavatory) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9		34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262561	Trash Receptacle Enclosure (Forward Lavatory) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262563	Trash Receptacle Enclosure (Forward Galley / Annex) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262570	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Aft Lavatory) - Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		60	07 Jun 2022	30 Jun 2027	31 Jul 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262571	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Forward Lavatory) - Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		60	07 Jun 2022	30 Jun 2027	31 Jul 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262573	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Forward Galley) - Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		60	07 Jun 2022	30 Jun 2027	31 Jul 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262584	Trash Receptacle FIRE Extinguisher Nozzles (Forward Lavatory) - Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	(262584)	Airframe		[End Of Month Item] [MOS: +1m/-1m]							
262600	Portable Halon FIRE Extinguisher (Cockpit) - Removal / Installation		HRS		192.1			3865.7			0
			AFL		78			1106			0
	898052	X-659949	MOS		7.9			04 Jun 2023			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item] [MOS: +1m/-1m]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262601	Portable Halon FIRE Extinguisher (Cockpit) - Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe										
262602	Portable Halon FIRE Extinguisher (Cockpit) - Weight Check		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	-2	12	04 Jun 2023	30 Jun 2024*	31 Jul 2024	
	Airframe										WEIGHT CHECK
262610	Portable Halon FIRE Extinguisher (Forward Cabin) - Removal / Installation		HRS		192.1			3865.7			0
			AFL		78			1106			0
	100-9750	X-192925	MOS		7.9			04 Jun 2023			
	Airframe										O/C
262611	Portable Halon FIRE Extinguisher (Forward Cabin) - Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe										
262612	Portable Halon FIRE Extinguisher (Forward Cabin) - Weight Check		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	-2	12	04 Jun 2023	30 Jun 2024*	31 Jul 2024	
	Airframe										WEIGHT CHECK
262614	Portable Halon FIRE Extinguisher (Forward Cabin) - Final Phase Restore		HRS		1189.2			2868.6			0
			AFL		361			823			0
	100-9750	X-192925	MOS		52.6		72	12 Sep 2019	30 Sep 2025		FLAG FIRE OVERHAUL
	Airframe										
262630	Portable Halon FIRE Extinguisher (Aft Lavatory) - Removal / Installation		HRS		192.1			3865.7			0
			AFL		78			1106			0
	100-9750	X-192572	MOS		7.9			04 Jun 2023			
	Airframe										O/C

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262631	Portable Halon FIRE Extinguisher (Aft Lavatory) - Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	34	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262632	Portable Halon FIRE Extinguisher (Aft Lavatory) - Weight Check		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	-2	12	04 Jun 2023	30 Jun 2024*	31 Jul 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
262634	Portable Halon FIRE Extinguisher (Aft Lavatory) - Final Phase Restore		HRS		1189.2			2868.6			0
			AFL		361			823			0
	100-9750	X-192572	MOS		52.6		72	12 Sep 2019	30 Sep 2025		FLAG FIRE OVERHAUL
[End Of Month Item]											
Airframe											
27 - Flight Controls											
270005	Aileron and Rudder Trim Control Head / Secondary Control Rods - Removal / Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
	528401-13	203	MOS		185.6				13 Aug 2008		MAIN SOLUTIONS
[End Of Month Item]											
Airframe											
Notes: Q305828											
270995	Lateral Control System Rigging from Control Wheels to Wing Rear Beam Station 125		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
[End Of Month Item]											
Airframe											
270998	Lateral Control System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271001	Aileron Trim Tab - Removal / Installation		HRS		4057.8			0			0
	1159CSH55300-5	0393	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
271002	Trim Tab Actuator (Aileron) - Removal / Installation		HRS		4057.8			0			0
	159SCC100-25	01796	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
271003	Cable, Ail Trim UPR (Wing)		HRS		4057.8			0			0
	NAS313C17-5252	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
271004	Cable, Ail Trim Lower (Wing)		HRS		4057.8			0			0
	NAS313C16-5197	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
271005	Cable, Ail Trim Lh-Fuselage		HRS		4057.8			0			0
	1159SCC562-129	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
271006	Cable, Ail Trim Rh-Fuselage		HRS		4057.8			0			0
	1159SCC562-127	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
271008	Aileron Trim Tab Actuator / Linkage - General Visual Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	18	96	12 Sep 2016 30 Sep 2024* 31 Oct 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271009	Aileron Rigging (Wing Rear Beam Station 125 to Outboard)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
271010	Aileron Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	16	96	14 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271011	Aileron Control and Trim Cables In Main Wheel Wells / Wing Trailing Edge - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	10 Jun 2022	30 Jun 2024	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271012	Lateral Control System - Friction Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
271013	Aileron Input Control ROD Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	A-UV04-403	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
271014	Aileron Input Control ROD Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	A-GUV04-403	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
271021	Aileron Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159CS55004-5	0393	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

Notes: VERFIED BY PQ040

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271022	Aileron Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
	1159CS55005-1	0393	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
271023	Aileron Primary Pressure Seals - Removal / Installation		HRS	TSN:1114.1	2943.7			1114.1			0
	1159C50020-7	NSN	AFL	TSN:326	858			326			0
			MOS	TSN:51	137.3			21 Aug 2012			
	Airframe		MSC					O/C			
271101	Aileron Control Wheel (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCF410-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ESTERLINE MASON
	Airframe		MSC					O/C			
271102	Aileron Control Wheel (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCF410-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ESTERLINE MASON
	Airframe		MSC					O/C			
271103	Aileron / Flight Spoiler Control System - Functional Test		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1			27 Dec 2023			
	Airframe		MSC					O/C			
271105	Aileron Actuator Load Relief Bungee (Left) - Removal / Installation		HRS		4057.8			0			0
	1159C20014-7	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM - APPLETON
	Airframe		MSC					O/C			
271106	Aileron Actuator Load Relief Bungee (Right) - Removal / Installation		HRS		4057.8			0			0
	1159C20014-7	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM - APPLETON
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271109	Aileron Linkage Disconnect		HRS		4057.8			0			0
	1159SCC565-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			TYEE AIRCRAFT INC
	Airframe		MSC					O/C			
271110	Aileron Inter-Column Linkage Disconnect Assemblies - Operational Test		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.6		48	13 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
271121	Aileron Primary Outboard Cable Assembly FS 101 - FS 605 (Left) - Removal / Installation		HRS		2943.7			1114.1			0
	1159SCC561-17	NSN	AFL		858			326			0
			MOS		137.3			21 Aug 2012			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
271122	Aileron Primary Inboard Cable Assembly FS 101 - FS 605 (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCC561-21	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
271123	Aileron Primary Outboard (Left Forward) Cable Assembly FS 605 - Rbs 125 - Removal / Installation		HRS		4057.8			0			0
	1159SCC561-19	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
271124	Aileron Primary Inboard (Aft) Cable Assembly FS 605 - Rbs 125 (Left) - Removal / Installation		HRS		1909.4			2148.4			0
	1159SCC561-23	NSN	AFL		573			611			0
			MOS	TSN:2	88.5			14 Sep 2016			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271125	Right Aileron Primary Outboard Cable Assembly FS 101 - FS 335 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-29	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
Airframe			MSC				O/C				
271126	Right Aileron Primary Outboard Cable Assembly FS 335 - FS 401 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-27	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
Airframe			MSC				O/C				
271127	Right Aileron Primary Outboard Cable Assembly FS 401 - FS 605 - Removal / Installation		HRS		2943.7			1114.1			0
			AFL		858			326			0
	1159SCC561-25	NSN	MOS		137.3			21 Aug 2012			ASSEMBLY SPECIALTY PRODUCTS INC
Airframe			MSC				O/C				
271128	Aileron Primary Inboard Cable Assembly FS 101 - FS 605 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-21	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
Airframe			MSC				O/C				
271129	Aileron Primary Outboard (Right Forward) Cable Assembly FS 605 - Rbs 125 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-19	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
Airframe			MSC				O/C				
271130	Aileron Primary Inboard (Aft) Cable Assembly FS 605 - Rbs 125 (Right) - Removal / Installation		HRS		1909.4			2148.4			0
			AFL		573			611			0
	1159SCC561-23	NSN	MOS	TSN:2	88.5			15 Sep 2016			ASSEMBLY SPECIALTY PRODUCTS INC
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271131	Aileron Primary Cable Assembly Forward Rbs 125 - Rbs 285 (Left Inboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C17-1660	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271132	Aileron Primary Cable Assembly Forward Rbs 285 - Rbs 360 (Left Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C17-0816	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271133	Aileron Primary Cable Assembly Aft Rbs 125 - Rbs 252 (Left Inboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C17-1330	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	ASSEMBLY SPECIALTY PRODUCTS INC
Airframe											
271134	Aileron Primary Cable Assembly Aft Rbs 252 - Rbs 360 (Left Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C16-1146	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	HONEYWELL HPG
Airframe											
271135	Aileron Primary Cable Assembly Forward Rbs 125 - Rbs 285 (Right Inboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C14-0914	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271136	Aileron Primary Cable Assembly Forward Rbs 285 - Rbs 360 (Right Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C15-1544	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271137	Aileron Primary Cable Assembly Aft Rbs 125 - Rbs 252 (Right Inboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	NAS316C15-1306	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271138	Aileron Primary Cable Assembly Aft Rbs 252 - Rbs 360		HRS		4057.8			0			0
	(Right Outboard) - Removal / Installation		AFL		1184			0			0
	NAS316C14-1156	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271139	Aileron Primary Outboard Cable Assembly FS 101 - FS		HRS		4057.8			0			0
	605 (Right) - Removal / Installation		AFL		1184			0			0
	1159SC50002-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
271141	Aileron Actuator Load Relief Bungee (Left) - Load		HRS		0			4057.8			0
	Inspection		AFL		0			1184			0
			MOS		1.1			27 Dec 2023			
			MSC							O/C	
Airframe											
271142	Aileron Actuator Load Relief Bungee (Right) - Load		HRS		0			4057.8			0
	Inspection		AFL		0			1184			0
			MOS		1.1			27 Dec 2023			
			MSC							O/C	
Airframe											
271143	Elevator Actuator Load Relief Bungee (Left) - Load		HRS		0			4057.8			0
	Inspection		AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
			MSC							O/C	
Airframe											
271144	Elevator Actuator Load Relief Bungee (Right) - Load		HRS		0			4057.8			0
	Inspection		AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
			MSC							O/C	
Airframe											
271147	Aileron Primary Forward Sector Assy (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159C50200-7	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271148	Aileron Primary Forward Sector Assy (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C50200-8	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
271203	Aileron Trim Tab Control System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
271204	Aileron Trim Tab Control System - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
271219	Aileron Force Sensor (Left) - Removal / Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
	1159SCC473-7	TY-01096	MOS		185.6			13 Aug 2008			JAMAICA BEARINGS CO. INC.
			MSC								
Airframe											
271222	Aileron Force Sensor (Right) Removal / Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
	1159SCC473-7	TY-01102	MOS		185.6			13 Aug 2008			JAMAICA BEARINGS CO. INC.
			MSC								
Airframe											
271301	Force Link Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C50258-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
271302	Force Link Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C50258-2	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271303	Aileron Hardover Prevention System (Left) - Operational		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
	Check		AFL		0			1184			0
			MOS		1.1			27 Dec 2023			
	Airframe		[HRS: +50/-50]								
271304	Aileron Hardover Prevention System (Right) - Operational		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
	Check		AFL		0			1184			0
			MOS		1.1			27 Dec 2023			
	Airframe		[HRS: +50/-50]								
271305	Aileron Actuator Hydraulic Deactivation Valves (Left		HRS		4057.8			0			0
	Inboard) - Removal / Installation		AFL		1184			0			0
	1159SCH501-17	EFS3037	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
271306	Aileron Actuator Hydraulic Deactivation Valves (Right		HRS		4057.8			0			0
	Inboard) - Removal / Installation		AFL		1184			0			0
	1159SCH501-17	EFS3041	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
271309	Aileron Hydraulic Boost Actuator (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH252-59	5526	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
271310	Aileron Hydraulic Boost Actuator (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH252-60	5511	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271311	Aileron Force Link Microswitch (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50699-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271312	Aileron Force Link Microswitch (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50699-2	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271313	Microsw, L Force Link-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271314	Microsw, R Force Link-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271315	Aileron Hydraulic Actuator Deactivation Valve (Left) - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271316	Aileron Hydraulic Actuator Deactivation Valve (Right) - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
271317	Valve,Ail ACT Deactive-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271319	Filter, L Aileron ACT-Inspect		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
271320	Filter, R Aileron ACT-Inspect		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
271401	Aileron Position Transducer (Left) - Removal / Installation		HRS		4057.8			0			0
	3A1316A	A2277	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
271402	Aileron Position Transducer (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1316A	A2261	MOS		188.2			24 May 2008			IPECO INC
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
271403	Sensor, L Cont Wheel Pos Rvdt		HRS		4048.2			9.6			0
	1159SCF452-5	A1913	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
271404	Sensor, R Cont Wheel Pos Rvdt		HRS		4048.2			9.6			0
	1159SCF452-5	A1915	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
271410	Sensor, Aileron Trim FDR		HRS		4048.2			9.6			0
	1159SCF452-5	A1914	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			MPC PRODUCTS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272001	Rudder - Removal / Installation		HRS		134.1			3923.7			0
	1159CS52205-802	1786171	AFL		44			1140			0
			MOS		5.3			21 Aug 2023			N/A
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
272002	Rudder Hydraulic Actuator - Removal / Installation		HRS	TSN:36.5	4021.3			36.5			0
	1159SCH502-63	0430	AFL	TSN:15	1169			15			0
			MOS		184.2			26 Sep 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
272003	Rudder Trim Actuator - Removal / Installation		HRS		4057.8			0			0
	159SCC100-23	1374	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH SENSOR SYSTEMS
	Airframe		MSC					O/C			
Notes: Q312091											
272004	Rudder Torque Tube Bearing - Lubrication		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.7		48	10 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
272005	Rudder Torque Tube - Removal / Installation		HRS		1909.4			2148.4			0
	1159B21605-15	SN-UNKNOWN	AFL		573			611			0
			MOS		88.1			28 Sep 2016			
	Airframe		MSC					O/C			
272006	Rudder Hydraulic Deactivation Valve (No. 1) - Removal / Installation		HRS		4057.8			0			0
	1159SCH501-17	EFS3082	AFL		1184			0			0
			MOS		188.2			24 May 2008			EFS AEROSPACE, INC
	Airframe		MSC					O/C			
Notes: Q305319											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272007	Rudder Hydraulic Deactivation Valve (No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH501-17	EFS3089	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC								
Airframe											
Notes: Q305319											
272008	Rudder Hydraulic Deactivation Valve (No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH257-7	SN-UNKNOWN	MOS		188.2			24 May 2008			PNEUDRAULICS INC
			MSC								
Airframe											
272011	Rudder Control System - Rigging		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
272012	Rudder Torque Tube - Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.1	2	96	28 Sep 2016 30 Sep 2024* 31 Oct 2024			
Airframe [End Of Month Item] [MOS: +1m/-1m]											
272013	Rudder System - Functional Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.6			12 Sep 2023			
			MSC								
Airframe											
272100	Rudder Pedals - Lubrication		HRS		957.9		2000	3099.9	5099.9	5149.9	0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020 31 Oct 2026* 30 Nov 2026			
Airframe [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
272101	Rudder Primary Cable Assembly (Upper Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-31	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272102	Rudder Primary Cable Assembly (Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-35	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
272105	Rudder Primary Cable Assembly (Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-33	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
272106	Rudder Primary Cable Assembly (Lower Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-37	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
272107	Rudder Control and Trim Cables In Pressurized Areas of Fuselage / Overwing to Aft Wing Links - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	15	96	15 Sep 2016	30 Sep 2024*	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
272108	Rudder Control and Trim Cables In Main Wheel Well / Tail Compartment - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
272109	Rudder Trim Cable Assemblies (Left Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC562-43	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY
			MSC								SPECIALTY
Airframe											
PRODUCTS INC											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272110	Rudder Trim Cable Assemblies (Right Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC562-47	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
272111	Rudder Trim Cable Assemblies (Left Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC562-69	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
272112	Rudder Trim Cable Assemblies (Right Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC562-71	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
272113	Rudder and Trim Control System - Operational Test		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
			MSC								
Airframe											
272114	Rudder Primary Cable Pressure Seals - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
272118	Rudder Primary Pulley(S) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
272121	Rudder Trim Pulleys - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272125	Rudder Attach Points - Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.3			21 Aug 2023			
	Airframe			MSC				O/C			
272201	Rudder Trim Control Knob - Removal / Installation		HRS		4057.8			0			0
	528401-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			MAIN SOLUTIONS
	Airframe			MSC				O/C			
272202	Rudder Trim Artificial Feel Bungee Assembly - Removal / Installation		HRS		4057.8			0			0
	1159C20350-23	FAH0641	AFL		1184			0			0
			MOS		188.2			24 May 2008			FRISBY AEROSPACE LLC.
	Airframe			MSC				O/C			
Notes: Q312091											
272203	Rudder Trim Control System - Functional Test		HRS		4021.3			36.5			0
			AFL		1169			15			0
			MOS		184.2			26 Sep 2008			
	Airframe			MSC				O/C			
272204	Rudder Trim System - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			
272301	Rudder Hardover Prevention System - Operational Test		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe			[HRS: +50/-50]							
272302	Valve, Rudder Hyd Selector		HRS		4057.8			0			0
	1159SCH501-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAISER FLUID TECHNOLOGIES
	Airframe			MSC				O/C			
272303	Standby Rudder System - Operational Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		48	23 Jul 2020	31 Jul 2024	31 Aug 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272401	Rudder Position Transducer - Removal / Installation		HRS		4057.8			0			0
	3A1316A	A2325	AFL		1184			0			0
			MOS		188.2			24 May 2008			IPECO INC
	Airframe		MSC					O/C			
Notes: Q312091											
272402	Potentiometer, Rudder NWS		HRS		4057.8			0			0
	1159SCL500-17	1530	AFL		1184			0			0
			MOS		188.2			24 May 2008			EATON
	Airframe		MSC					O/C			AEROSPACE
272403	Potentiometer, Rudder Pedals		HRS		4048.2			9.6			0
	1159SCF452-5	A1912	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
272420	Rudder Force Sensor - Removal / Installation		HRS		4048.2			9.6			0
	1159SCC473-11	TY-00960	AFL		1179			5			0
			MOS		187.5			16 Jun 2008			GULFSTREAM
	Airframe		MSC					O/C			BRN COMPLETIONS IPT
272501	Valve, Rud Aux Sys Norm/Stby		HRS		4057.8			0			0
	1159SCH257-9	311721	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY Q311721											
273001	Elevator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159CS52093-421	393	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273002	Elevator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159CS52093-422	394	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273005	Elevator Control System - Operational Test		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		MSC							O/C	
273006	Elevator Actuator Load Relief Bungee Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C20014-7	NSN	MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273007	Elevator Actuator Load Relief Bungee Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C20014-7	NSN	MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273011	Elevator Control ROD (Left)		HRS		4057.8			0			0
	1159C52015-403	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273012	Elevator Control ROD (Right)		HRS		4057.8			0			0
	1159C52015-403	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273013	Elevator Crank Assembly (Left)		HRS		4057.8			0			0
	1159CM52006-401	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273014	Elevator Crank Assembly (Right)		HRS		4057.8			0			0
	1159CM52006-401	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
273015	Elevator Primary Sector Assy, Left		HRS		4057.8			0			0
	1159C50100-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273016	Elevator Primary Sector Assy, Right		HRS		4057.8			0			0
	1159C50100-6	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273018	Elevator Hops, Pilot Input Switch		HRS		4057.8			0			0
	1159C50120-17	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273019 (273019)	Elevator Drive ROD - Lubrication		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88	96		30 Sep 2016	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
273020	Elevator Trim Drum Chain and Master Link - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	18**		23 Sep 2008	30 Sep 2024		
	Airframe							[End Of Month Item]			
273023	Elevator Trim Tab (Left) - Removal / Installation		HRS		4057.8			0			0
	1159CS52095-421	402	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GULFSTREAM SAV PROD-IPT
273024	Elevator Trim Tab (Right) - Removal / Installation		HRS		4057.8			0			0
	1159CS52095-423	402	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311215											
273025	Elevator Trim Tab Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	159SCC100-25	01861	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			PROFESSIONAL AIRCRAFT ACCESSORIES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273026	Elevator Trim Tab Actuator (Right) - Removal / Installation		HRS		3507.5			550.3			0
	159SCC100-25	522	AFL		1015			169			0
			MOS		160.5			17 Sep 2010			PROFESSIONAL
	Airframe		MSC					O/C			AIRCRAFT ACCESSORIES
273028	Elevator Control System - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273030	Elevator Trim Tab Control System - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273032	Longitudinal Control System Friction Check - Inspection / Check		HRS		0		1000	4057.8	5057.8	5107.8	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe										[HRS: +50/-50]
273050	Torque Tube, Elevator		HRS		4057.8			0			0
	1159SCB502-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ALCOA
	Airframe		MSC					O/C			FASTENING SYSTEMS CITY OF INDUSTRY
273093	Elevator Primary Cable Assemblies (Right Lower Forward) - Removal / Installation		HRS		1909.3			2148.5			0
	1159SCC561-47	NSN	AFL		573			611			0
			MOS	TSN:9	88			01 Oct 2016			ASSEMBLY
	Airframe		MSC					O/C			SPECIALTY PRODUCTS INC
273094	Elevator Primary Cable Assemblies (Right Upper Forward) - Removal / Installation		HRS		1909.3			2148.5			0
	1159SCC561-39	NSN	AFL		573			611			0
			MOS	TSN:9	88			01 Oct 2016			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273097	Elevator Primary Cable Assemblies (Right Lower Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-41	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
273098	Elevator Primary Cable Assemblies (Right Upper Aft)- Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCC561-45	SN-UNKNOWN	MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
273099	Elevator Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	15	96	15 Sep 2016 30 Sep 2024*	31 Oct 2024		
Airframe											
273100	Elevator Control and Trim Cables In Main Wheel Well and Tail Compartment - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022 30 Jun 2024	31 Jul 2024		
Airframe											
273101	Elevator Primary Cable Assemblies (Left Lower Forward) - Removal / Installation		HRS		1909.3			2148.5			0
			AFL		573			611			0
	1159SCC561-39	NSN	MOS	TSN:9	88			01 Oct 2016			ASSEMBLY SPECIALTY PRODUCTS INC
			MSC								
Airframe											
273102	Elevator Primary Cable Assemblies (Left Upper Forward) - Removal / Installation		HRS		1909.3			2148.5			0
			AFL		573			611			0
	1159SCC561-47	NSN	MOS	TSN:9	88			01 Oct 2016			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273103	Cable Assembly, Elevator Primary (Left Lower Middle)		HRS		4057.8			0			0
	1159SCC	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273104	Cable Assembly, Elevator Primary (Left Upper Middle)		HRS		4057.8			0			0
	1159SCC	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273105	Elevator Primary Cable Assemblies (Left Lower Aft) - Removal / Installation		HRS		4057.8			0			0
	1159SCC561-41	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
273106	Elevator Primary Cable Assemblies (Left Upper Aft) - Removal / Installation		HRS		4057.8			0			0
	1159SCC561-45	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
273109	Eddy Current Damper (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCC202-1	A1047	AFL		1184			0			0
			MOS		188.2			24 May 2008			MOOG INCORPORATED
	Airframe		MSC					O/C			
273110	Eddy Current Damper (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCC202-1	A1045	AFL		1184			0			0
			MOS		188.2			24 May 2008			MOOG INCORPORATED
	Airframe		MSC					O/C			
273111	Elevator Disconnect Cable Assembly - Removal / Installation		HRS		4057.8			0			0
	1159SCC564-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			TYEE AIRCRAFT INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273113	Elevator Inter-Column Linkage Disconnect Assembly - Operational Test		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.6		48	13 Jul 2021	31 Jul 2025	31 Aug 2025	
[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Airframe											
273115	Elevator Hydraulic Deactivation Valves (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH501-17	EFS2756	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC					O/C			
Airframe											
Notes: Q305319											
273116	Elevator Hydraulic Deactivation Valves (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH501-17	EFS3049	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC					O/C			
Airframe											
Notes: Q305319											
273117	Elevator Hydraulic Deactivation Valves (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH501-17	EFS3051	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC					O/C			
Airframe											
Notes: Q305319											
273118	Elevator Hydraulic Deactivation Valves (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH501-17	EFS3085	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC					O/C			
Airframe											
Notes: Q305319											
273121	Elevator Input / Output Crank Assemblies (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C50107-11	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273122	Elevator Input / Output Crank Assemblies (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C50108-11	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273133	Pilot Elevator Control Column - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C40103-3	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273134	CO-Pilot Elevator Control Column - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159C40103-4	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273201	Stall Barrier Angle of Attack Sensor (Left) - Removal / Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
	0861FW1	825	MOS		186.3			22 Jul 2008			GULFSTREAM DALLAS
			MSC							O/C	
Airframe											
Notes: Q306892											
273202	Stall Barrier Angle of Attack Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	0861FW1	893	MOS		188.2			24 May 2008			GULFSTREAM DALLAS
			MSC							O/C	
Airframe											
Notes: Q306892											
273203	Stick Shaker Assembly (Pilot) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	C-36602	7385	MOS		188.2			24 May 2008			SAFE FLIGHT INSTRUMENT CORPORATION
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273204	Stick Shaker Assembly (Copilot) - Removal / Installation		HRS		4057.8			0			0
	C-36602	7387	AFL		1184			0			0
			MOS		188.2			24 May 2008			SAFE FLIGHT INSTRUMENT CORPORATION
	Airframe		MSC					O/C			
273205	Stall Barrier - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273206	Stall Barrier Actuator - Removal / Installation		HRS		4057.8			0			0
	1159SCH503-55	0528	AFL		1184			0			0
			MOS		188.2			24 May 2008			EATON AEROSPACE
	Airframe		MSC					O/C			
Notes: Q305319											
273209	Stall Barrier System - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: PN: 1159H47073-1 SN: <NONE>											
273302	Elevator Trim Tab Control Wheel Assemblies (Right) - Removal / Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
	43083-406-7	103020	MOS		185.6			13 Aug 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
273306	Elevator Trim Tab Control System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
273321	Elevator Trim Tab Control ROD Assemblies, Forward, Outboard (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273322	Elevator Trim Tab Control ROD Assemblies, Forward, Outboard (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273323	Elevator Trim Tab Control ROD Assemblies, Aft, Outboard (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273324	Elevator Trim Tab Control ROD Assemblies, Aft, Outboard (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273325	Elevator Trim Tab Control ROD Assemblies, Forward, Inboard (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273326	Elevator Trim Tab Control ROD Assemblies, Forward, Inboard (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273327	Elevator Trim Tab Control ROD Assemblies, Aft, Inboard (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
273328	Elevator Trim Tab Control ROD Assemblies, Aft, Inboard (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273401	Elevator Hydraulic Dual Tandem Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH252-169	5581	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC								
Airframe											
Notes: Q312091											
273402	Elevator Hydraulic Dual Tandem Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH252-170	5585	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC								
Airframe											
Notes: Q312091											
273405	Elevator Hardover Prevention System - Operational Test		HRS		0		1000	4057.8	5057.8	5107.8	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
Airframe [HRS: +50/-50]											
273501	Elevator Rotary Variable Differential Transducer (Rvdt) {Left} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1-315A	A0412	MOS		188.2			24 May 2008			
			MSC								
Airframe											
273502	Elevator Rotary Variable Differential Transducer (Rvdt) {Right} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1-315A	A0436	MOS		188.2			24 May 2008			
			MSC								
Airframe											
273503	Transducer, L Elv Trim Pos		HRS		4057.8			0			0
			AFL		1184			0			0
	3A2-266A	B0769	MOS		188.2			24 May 2008			
			MSC								
Airframe											
273504	Transducer, R Elv Trim Pos		HRS		4057.8			0			0
			AFL		1184			0			0
	3A2-266A	B0770	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273505	Rvdt, L Elv Cont Column Posit		HRS		4048.2			9.6			0
	1159SB51917-1	A1829	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			GULSTREAM SAV
	Airframe		MSC					O/C			- FLIGHT TEST IPT
273506	Rvdt, R Elv Cont Column Posit		HRS		4048.2			9.6			0
	1159SB51917-2	A1831	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			GULSTREAM SAV
	Airframe		MSC					O/C			- FLIGHT TEST IPT
273519	Elevator Force Sensor (Left) - Removal / Installation		HRS		4048.2			9.6			0
	1159SCC473-1	TY-01076	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			GULFSTREAM BRN
	Airframe		MSC					O/C			COMPLETIONS IPT
273522	Elevator Force Sensor (Right) - Removal / Installation		HRS		4048.2			9.6			0
	1159SCC473-1	TY-01084	AFL		1179			5			0
			MOS		185.6			13 Aug 2008			GULFSTREAM BRN
	Airframe		MSC					O/C			COMPLETIONS IPT
274101	Flap / Horizontal Stabilizer Control Unit - Removal / Installation		HRS		436.4			3621.4			0
	1159SCC651-7	106141871	AFL		160			1024			0
			MOS		14			01 Dec 2022			N/A
	Airframe		MSC					O/C			
274102	Module, #1 Flap/Stab Auto Rig		HRS		4057.8			0			0
	1159SCC509-3	366	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274103	Module, #2 Flap/Stab Auto Rig		HRS		4057.8			0			0
	1159SCC509-4	428	AFL		1184			0			0
			MOS		188.2			24 May 2008			ASSEMBLY SPECIALTY PRODUCTS INC
	Airframe		MSC					O/C			
274105	Flap / Stabilizer Control System - Operational Test		HRS		436.4			3621.4			0
			AFL		160			1024			0
			MOS		14			01 Dec 2022			
	Airframe		MSC					O/C			
Notes: PN: 1159SCC651-7 SN: <NONE>.											
274106	Emergency Horizontal Stabilizer (Backup MODE) - Operational Test		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.6		48	13 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
274155	Horizontal Stab Control Sys - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
274201	Horizontal Stabilizer Actuator - Removal / Installation		HRS		346.5			3711.3			0
	1159SCC500-9	2510	AFL		129			1055			0
			MOS		11.5			15 Feb 2023			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q307182											
274202	Horizontal Stabilizer Actuator - Lubrication		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		36	04 Jun 2022	30 Jun 2025	31 Jul 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
274203	Horizontal Stabilizer Actuator - Adjustment / Test		HRS		1001.3			3056.5			0
			AFL		319			865			0
			MOS		47.5			16 Feb 2020			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	MM Ref	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Manufacturer
	Ops Number(s)										Date Type
	274204	Horizontal Stabilizer Actuator (Installed Life) - Restore 1159SCC500-9									2510
Airframe					[End Of Month Item]			16 Feb 2020	30 Nov 2031		OVERHAUL
274205	Horizontal Stabilizer Actuator (Upper Gearbox) - Lubrication		HRS AFL MOS		957.9 313 40.9	32	72	3099.9 871			0 0
Airframe					[End Of Month Item] [MOS: +1m/-1m]			03 Sep 2020	31 Oct 2026*	30 Nov 2026	
274206	Horizontal Stabilizer Actuator (Total Life) - Restore 1159SCC500-9	2510	HRS AFL MOS		346.5 129 11.5	-267	168	3711.3 1055			0 0
Airframe								15 Feb 2023	24 May 2036*		
274301	Horizontal Stabilizer Position Resolver - Removal / Installation		HRS AFL MOS MSC	TSN:2868.6 TSN:823 TSN:136	1189.2 361 52.7			2868.6 823			0 0
Airframe	1159SCC652-11	A0143						10 Sep 2019			HAMILTON SUNDSTRAND
Notes: VERIFIED BY Q307182											
274302	Horizontal Stabilizer Position Resolver - Adjustment		HRS AFL MOS MSC		1189.2 361 52.8			2868.6 823			0 0
Airframe								06 Sep 2019			
275001	Flap Assembly (Left) - Removal / Installation		HRS AFL MOS MSC	TSN:3200.1 TSN:904 TSN:158	857.7 280 30.4			3200.1 904			0 0
Airframe	1159CS54102-25	0397						18 Jul 2021			N/A
Notes: VERIFIED BY PQ040											
275002	Flap Assembly (Right) - Removal / Installation		HRS AFL MOS MSC		857.7 280 30.4			3200.1 904			0 0
Airframe	1159CS54102-26	0397						18 Jul 2021			N/A
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275003	Flap System - Operational Test		HRS		436.4			3621.4			0
			AFL		160			1024			0
			MOS		14			01 Dec 2022			
	Airframe		MSC					O/C			
Notes: PN: 1159SCC651-7 SN: <NONE>.											
275004	Flap Control System - Functional Test		HRS		436.4			3621.4			0
			AFL		160			1024			0
			MOS		14			01 Dec 2022			
	Airframe		MSC					O/C			
Notes: PN: 1159SCC651-7 SN: <NONE>.											
275005	Flaps System - Rigging		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
275006	Flap / Stab - Autorig		HRS		1001.3			3056.5			0
			AFL		319			865			0
			MOS		47.5			16 Feb 2020			
	Airframe		MSC					O/C			
Notes: PN: N/A SN: <NONE>.											
275007	L/H Flap Control Relay (K55A)		HRS		4057.8			0			0
	1159AV20504-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GULFSTREAM SAV PROD-IPT
275008	R/H Flap Control Relay (K55A)		HRS		4057.8			0			0
	1159AV20504-2	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
275011	Flap Actuator Gearbox (Left Inboard) - Lubrication		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			AFL		44			1140			0
			MOS		5.4		192	20 Aug 2023	31 Aug 2039	30 Sep 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275012	Flap Actuator Gearbox (Right Inboard) - Lubrication		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			AFL		44			1140			0
			MOS		5.4		192	20 Aug 2023	31 Aug 2039	30 Sep 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275013	Flap Actuator Gearbox (Left Outboard) - Lubrication		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			AFL		44			1140			0
			MOS		5.4		192	20 Aug 2023	31 Aug 2039	30 Sep 2039	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275014	Flap Actuator Gearbox (Right Outboard) - Lubrication		HRS		857.7		4000	3200.1	7200.1	7250.1	0
			AFL		280			904			0
			MOS		30.7		192	09 Jul 2021	31 Jul 2037	31 Aug 2037	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275015	Inboard Flap Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCC601-3	2602	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
Notes: VERIFIED BY PQ040											
275016	Inboard Flap Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCC601-3	2603	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
Notes: VERIFIED BY PQ 040											
275017	Outboard Flap Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCC602-3	2604	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
Notes: VERIFIED BY PQ040											
275018	Outboard Flap Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCC602-3	2592	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275019	Flap Actuator Travel Nut (Left) - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275020	Flap Actuator Travel Nut (Right) - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275021	A Track Flap Rollers (Left Inboard) - Removal / Installation		HRS		4057.8			0			0
	KRP172108FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAMATICS CORPORATION
	Airframe		MSC				O/C				
275022	A Track Flap Rollers (Right Inboard) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP225108FT	NSN	MOS	TSN:6	30.5			15 Jul 2021			N/A
	Airframe		MSC				O/C				
275023	A Track Flap Rollers (Left Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172108FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
	Airframe		MSC				O/C				
275024	A Track Flap Rollers (Right Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172108FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
	Airframe		MSC				O/C				
275025	A Track Flap Rollers (Left Trailing Edge) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	MS14104-4	SN-UNKNOWN	MOS		188.2			24 May 2008			WESCO AIRCRAFT
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275026	A Track Flap Rollers (Right Trailing Edge) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	MS14104-4	SN-UNKNOWN	MOS		188.2			24 May 2008			WESCO AIRCRAFT
			MSC								
Airframe											
275027	B Track Flap Rollers (Left Outboard Upper Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP170810FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275028	B Track Flap Rollers (Right Outboard Upper Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP170810FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275029	B Track Flap Rollers (Left Outboard Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP170912FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275030	B Track Flap Rollers (Right Outboard Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP170912FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275031	B Track Flap Rollers (Left Outboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275032	B Track Flap Rollers (Right Outboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP5520-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275033	B Track Flap Rollers (Left Inboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
Airframe			MSC					O/C			
275034	B Track Flap Rollers (Right Inboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
Airframe			MSC					O/C			
275035	B Track Flap Rollers (Left Inboard Upper Forward) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP170810FT	NSN	MOS	TSN:7	30.5			15 Jul 2021			N/A
Airframe			MSC					O/C			
275036	B Track Flap Rollers (Right Inboard Upper Forward) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP170810FT	NSN	MOS	TSN:7	30.5			15 Jul 2021			N/A
Airframe			MSC					O/C			
275037	B Track Flap Rollers (Left Inboard Upper Aft) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP233012FT	NSN	MOS	TSN:5	30.5			15 Jul 2021			N/A
Airframe			MSC					O/C			
275038	B Track Flap Rollers (Right Inboard Upper Aft) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP233012FT	NSN	MOS	TSN:5	30.5			14 Jul 2021			N/A
Airframe			MSC					O/C			
275039	C Track Flap Rollers (Left Inboard Upper Forward) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP170708FT	NSN	MOS	TSN:4	30.5			15 Jul 2021			N/A
Airframe			MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275040	C Track Flap Rollers (Right Inboard Upper Forward) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP170708FT	NSN	MOS	TSN:4	30.5			15 Jul 2021			N/A
			MSC								
Airframe											
275041	C Track Flap Rollers (Left Inboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275042	C Track Flap Rollers (Right Inboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275043	C Track Flap Rollers (Left Inboard Upper Aft) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP172010FT	NSN	MOS	TSN:7	30.5			15 Jul 2021			N/A
			MSC								
Airframe											
275044	C Track Flap Rollers (Right Inboard Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275045	C Track Flap Rollers (Left Outboard Upper Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP170708FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275046	C Track Flap Rollers (Right Outboard Upper Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP171708FT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275047	C Track Flap Rollers (Left Outboard Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172010FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275048	C Track Flap Rollers (Right Outboard Upper Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172010FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275049	C Track Flap Rollers (Left Outboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275050	C Track Flap Rollers (Right Outboard Lower Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275051	D Track Flap Rollers (Left Outboard) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP171408FT	NSN	MOS	TSN:4	30.5			14 Jul 2021			N/A
			MSC								
Airframe											
275052	D Track Flap Rollers (Right Outboard) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP171408FT	NSN	MOS	TSN:4	30.5			14 Jul 2021			N/A
			MSC								
Airframe											
275053	D Track Flap Rollers (Left Inboard) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP171408FT	NSN	MOS	TSN:4	30.5			14 Jul 2021			N/A
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275054	D Track Flap Rollers (Right Inboard) - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	KRP170708FT	NSN	MOS	TSN:4	30.5			14 Jul 2021			N/A
			MSC								
Airframe											
275055	D Track Flap Rollers (Left Trailing Edge) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172010FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275056	D Track Flap Rollers (Right Trailing Edge) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP172010FT	SN-UNKNOWN	MOS		188.2			24 May 2008			KAMATICS CORPORATION
			MSC								
Airframe											
275057	Flap Roller, Left (C-19)		HRS		4057.8			0			0
			AFL		1184			0			0
	KPR552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275058	Flap Roller, Right (C-19)		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275059	Flap Roller, Left (C-20)		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
275060	Flap Roller, Right (C-20)		HRS		4057.8			0			0
			AFL		1184			0			0
	KRP552-06VT	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275061	Flap Roller, Left (C-21)		HRS		4057.8			0			0
	MS14104-4	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			WESCO
	Airframe		MSC					O/C			AIRCRAFT
275062	Flap Roller, Right (C-21)		HRS		4057.8			0			0
	MS14104-4	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			WESCO
	Airframe		MSC					O/C			AIRCRAFT
275063	Flap Roller, Left (D-22)		HRS		4057.8			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275064	Flap Roller, Right (D-22)		HRS		4057.8			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275065	Flap Roller, Left (D-23)		HRS		4057.8			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275066	Flap Roller, Right (D-23)		HRS		4057.8			0			0
	KRP170708FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KAMATICS
	Airframe		MSC					O/C			CORPORATION
275067	Flap Roller, Left (D-24)		HRS		4057.8			0			0
	MS14104-4	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			WESCO
	Airframe		MSC					O/C			AIRCRAFT

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275068	Flap Roller, Right (D-24)		HRS		4057.8			0			0
	MS14104-4	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			WESCO
	Airframe		MSC					O/C			AIRCRAFT
275101	Control Unit, Flap (Handle)		HRS		4057.8			0			0
	1159SCC505-1FT	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
275102	Flap Control Handle - Removal / Installation		HRS		4057.8			0			0
	4260-0045-1	101202	AFL		1184			0			0
			MOS		188.2			24 May 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
275110	Flap Attach Points (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
			[End Of Month Item]								
275111	Flap Attach Points (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
			[End Of Month Item]								
275201	Flap Power Drive Unit - Removal / Installation		HRS		4057.8			0			0
	1159SCC505-7	0538	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
Notes: VERIFIED BY Q311721											
275202	Valve, Flap Selector		HRS		4057.8			0			0
	1159SCH501-	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
275302	Flap Tracks - General Visual Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3	48		23 May 2023	31 May 2027	30 Jun 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275305	Flap Torque Shaft (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275306	Flap Torque Shaft (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275307	Flap Torque Shaft (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-25	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275308	Flap Torque Shaft (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-25	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275309	Flap Torque Shaft (Left No. 3) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-27	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275310	Flap Torque Shaft (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-27	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275311	Flap Torque Shaft (Left No. 4) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275312	Flap Torque Shaft (Right No. 4) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-23	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
275313	Flap Torque Shaft (Left No. 5) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-21	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
275314	Flap Torque Shaft (Right No. 5) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-21	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON
	Airframe		MSC					O/C			SUNDSTRAND
275315	Flap Torque Shaft (Left No. 6) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-19	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT
	Airframe		MSC					O/C			AIRCRAFT INDUSTRIES INC.
275316	Flap Torque Shaft (Right No. 6) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-19	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT
	Airframe		MSC					O/C			AIRCRAFT INDUSTRIES INC.
275317	Flap Torque Shaft (Left No. 7) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-17	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT
	Airframe		MSC					O/C			AIRCRAFT INDUSTRIES INC.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275318	Flap Torque Shaft (Right No. 7) - Removal / Installation		HRS		4057.8			0			0
	1159SCC504-17	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
275401	Flap Position Feedback Resolver Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCC603-1	0541	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
275402	Flap Position Feedback Resolver Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCC603-1	2509	AFL		1184			0			0
			MOS		188.2			24 May 2008			HAMILTON SUNDSTRAND
	Airframe		MSC					O/C			
276001	Ground Spoiler Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
	1159CS55402-1	0393	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
276002	Ground Spoiler Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
	1159CS55402-2	0393	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276003	Inboard Flight Spoiler Assembly (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CS55403-101	0393	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ040											
276004	Outboard Flight Spoiler Assembly (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CS55404-1	0393	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
276005	Inboard Flight Spoiler Assembly (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CS55403-102	0393	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
276006	Outboard Flight Spoiler Assembly (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CS55404-2	0393	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
276007	Ground Spoiler Actuator Assembly (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH305-25	2572	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276008	Ground Spoiler Actuator Assembly (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH305-26	2577	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ 040											
276009	Flight Spoiler Actuator Assembly (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH250-27	3291	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ040											
276010	Flight Spoiler Actuator Assembly (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH250-28	3313	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ 040											
276011	Spoiler Hydraulic Deactivation Valve (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH501-19	EFS0807	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC							O/C	
Airframe											
Notes: PQ246											
276012	Spoiler Hydraulic Deactivation Valve (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH501-19	EFS0804	MOS		188.2			24 May 2008			EFS AEROSPACE, INC
			MSC							O/C	
Airframe											
Notes: PQ246											
276013	Valve,Gnd Spoil Press Cont MOD		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH507-59	0428C	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC							O/C	
Airframe											
Notes: PQ246											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276014	Switch, Ground Spoiler Press		HRS		4057.8			0			0
	1159SCH213-5	6776	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			BRN SPARES IPT
Notes: VERIFIED BY Q38046											
276015	Selector Hyd, L Spoiler		HRS		4057.8			0			0
	1159SCH501-17	EFS3038	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: PQ040											
276016	Selector Hyd, R Spoiler		HRS		4057.8			0			0
	1159SCH501-17	EFS3012	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
276017	Switch, Gnd Spoiler Arming		HRS		4057.8			0			0
	GAS850A322	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			KORRY
	Airframe		MSC					O/C			ELECTRONICS
276099	Ground Spoiler Hydraulic Pressure Switch - Removal / Installation		HRS		324.3			3733.5			0
	1159SCH213-5	7847	AFL		123			1061			0
			MOS	TSN:5	10.9			03 Mar 2023			
	Airframe		MSC					O/C			
276101	Speed Brake Cables (Left) - Removal / Installation		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276102	Speed Brake Cables (Right) - Removal / Installation		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276104	Speed Brake Cable Assemblies In Fuselage and Overwing AREA to Aft Links - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	15	96	15 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
276105	Speed Brake Cable Assemblies In Main Wheel Well / Wing Trailing Edge - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	10 Jun 2022	30 Jun 2024	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
276106	Speed Brake Control System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
276107	Speed Brake Handle Assembly - Removal / Installation		HRS		4048.2			9.6			0
	4111-0048-1	103010	AFL		1179			5			0
			MOS		185.6				13 Aug 2008		
			MSC					O/C			
Airframe											
Notes: REMOVED P/N 4260-0052-1 S/N 103010											
276121	Speed Brake Control System (Left) - Rigging		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
276122	Speed Brake Control System (Right) - Rigging		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
276140	Speed Brake Cable Assemblies - Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
276151	Lh Spoiler Sys - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276152	Rh Spoiler Sys - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276201	Ground Spoiler Auto Deploy Rejected Takeoff MODE - Operational Test		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.6		48	13 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
276202	Ground Spoiler Manual Retract MODE - Operational Test		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			AFL		280			904			0
			MOS		30.6		48	13 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
276203	Ground Spoiler System - Functional Test		HRS		324.3			3733.5			0
			AFL		123			1061			0
			MOS		10.9			03 Mar 2023			
	Airframe		MSC					O/C			
276205	Ground Spoiler Output Bell Crank (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159CM50232-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276206	Ground Spoiler Output Bell Crank (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159CM50232-6	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276207	Ground Spoiler Pressure Control Module - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH507-55	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GENERAL DYNAMICS AVIATIONS SERVICES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276209	L/H Flap Pillow Block #1		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276210	R/H Flap Pillow Block #1		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276211	L/H Flap Pillow Block #2		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276212	R/H Flap Pillow Block #2		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276213	L/H Flap Pillow Block #3		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276214	R/H Flap Pillow Block #3		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276215	L/H Flap Pillow Block #4		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276216	R/H Flap Pillow Block #4		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276217	L/H Flap Pillow Block #5		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276218	R/H Flap Pillow Block #5		HRS		4057.8			0			0
	1159SCC504-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276301	Inboard Flight Spoiler Bell Crank (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CM50208-7	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276302	Inboard Flight Spoiler Bell Crank (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CM50208-8	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
276303	Outboard Flight Spoiler Bell Crank (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CM50209-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
276304	Outboard Flight Spoiler Bell Crank (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159CM50209-6	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			VOUGHT AIRCRAFT INDUSTRIES INC.
276321	Outboard Flight Spoiler Bellcrank (Left) - Special Detailed		HRS		857.7			3200.1			0
	Inspection		AFL		280		1500	904	2404		0
			MOS		30.6			13 Jul 2021			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276322	Outboard Flight Spoiler Bellcrank (Right) - Special		HRS		857.7			3200.1			0
	Detailed Inspection		AFL		280		1500	904	2404		0
			MOS		30.6			13 Jul 2021			
Airframe											
276401	Ground Spoiler Primary Control Valve - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH403-3	1028A	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: VERIFIED BY Q38046											
276402	Ground Spoiler Secondary Control Valve - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH568-3	0334	MOS		188.2			24 May 2008			MOOG INCORPORATED
			MSC				O/C				
Airframe											
Notes: VERIFIED BY Q38046											
276501	Ground Spoiler Position Sensor Switch (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159AV50506-1	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
276502	Ground Spoiler Position Sensor Switch (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159AV50506-1	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
276505	Spoiler Position Transducer (Left Ground) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	3A1316A	A2266	MOS		188.2			24 May 2008			IPECO INC
			MSC				O/C				
Airframe											
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276506	Spoiler Position Transducer (Right Ground) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1316A	A2275	MOS		188.2			24 May 2008			IPECO INC
			MSC								
Airframe											
Notes: VERIFIED BY PQ 040											
276507	Spoiler Position Transducer (Left Flight) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1316A	A2271	MOS		188.2			24 May 2008			IPECO INC
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
276508	Spoiler Position Transducer (Right Flight) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3A1316A	A2260	MOS		188.2			24 May 2008			IPECO INC
			MSC								
Airframe											
Notes: VERIFIED BY PQ 040											
277001	Gust Lock Cable Systems - Rigging / Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
277002	Gust Lock System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
277003	Gust Lock System - Functional Check		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
Airframe [HRS: +50/-50]											
277005	Gust Lock Cable Assembly (Outboard) FS 84 - FS 362 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
277006	Gust Lock Cable Assembly (Inboard) FS 84 - FS 790 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277007	Gust Lock Cable Assembly (Outboard) FS 362 - FS 410 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277008	Gust Lock Cable Assembly (Outboard) FS 410 - FS 790 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277009	Gust Lock Cable Assembly (Outboard) FS 790 - FS 905 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277010	Gust Lock Cable Assembly (Inboard) FS 790 - FS 905 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277012	Gust Lock Cable Pulleys - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
277015	Lateral Control System Rigging from Wing Rear Beam		HRS		4057.8			0			0
	Station 125 Outboard (Left)		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
277016	Lateral Control System Rigging from Wing Rear Beam Station 125 Outboard (Right)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
277101	Gust Lock Handle Assembly - Removal / Installation		HRS		4057.8			0			0
	3F78495001B	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			MPC PRODUCTS
	Airframe		MSC					O/C			
28 - Fuel											
280003	Fuel Tank Vapor Hazards - Reduction		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
280010	Refueling / Defueling Procedures - Servicing		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.2			25 May 2023			
	Airframe		MSC					O/C			
280011	Fuel Tank - Sumping		HRS		0			4057.8			0
			AFL		0			1184			0
			DATE		35 d		10d	27 Dec 2023	06 Jan 2024		
280012	Microbiological Contamination Test of Fuel Tank - Special Detail Inspection		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1		4	29 Dec 2023	30 Apr 2024	31 May 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
280015	Fuel Tank - Biocide Treatment		HRS		292.3			3765.5			0
			AFL		107			1077			0
			MOS		9.6			12 Apr 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281001	Fuel Tank (Left) - Leak Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
281002	Fuel Tank (Right) - Leak Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
281005	Fuel Tank Contamination (Left) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
281006	Fuel Tank Contamination (Right) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
281010	Wing Centerline Rib - Leak Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
281109	L/H Float Shutoff Valve		HRS		4057.8			0			0
	1159SCP583-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
281110	R/H Float Shutoff Valve		HRS		4057.8			0			0
	1159SCP583-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
281301	Overwing Gravity Fueling Adapter Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	457-1608	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281302	Overwing Gravity Fueling Adapter Assembly (Right) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	457-1608	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
281303	Gravity Fueling Adapter Assembly (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
281304	Gravity Fueling Adapter Assembly (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
281401	Gravity Fuel Drain Sys-OPS Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
281405	Gravity Water / Fuel Drain Valve (Left, Inboard Forward) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	79C3T2	SN-UNKNOWN	MOS		188.2			24 May 2008			ENVIROVAC, INC.
			MSC								
Airframe											
281406	Gravity Water / Fuel Drain Valve (Right, Inboard Forward)		HRS		4057.8			0			0
	- Removal / Installation		AFL		1184			0			0
	79C3T2	SN-UNKNOWN	MOS		188.2			24 May 2008			ENVIROVAC, INC.
			MSC								
Airframe											
281407	Gravity Water / Fuel Drain Valve (Left) - Operational Test		HRS		134.1		500	3923.7	4423.7	4473.7	0
			AFL		44			1140			0
			MOS		4.8			05 Sep 2023			
Airframe [HRS: +50/-50]											
281408	Gravity Water / Fuel Drain Valve (Right) - Operational Test		HRS		134.1		500	3923.7	4423.7	4473.7	0
			AFL		44			1140			0
			MOS		4.8			05 Sep 2023			
Airframe [HRS: +50/-50]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281409	Flapper Check Valve (Left) - General Visual Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281410	Flapper Check Valve (Right) - General Visual Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281415	Heated Fuel Return System - Operational Check		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.5			16 Sep 2015			
	Airframe		MSC O/C								
281503	Vent Float / Pressure Relief Valve (3 Inch) {Left Wing} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	8F111-101A	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC O/C								
281504	Vent Float / Pressure Relief Valve (3 Inch) {Right Wing} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	8F111-101A	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC O/C								
281505	Vent Float / Nonrelieving Valve (AIR Passage) {Left Forward} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP007-3	4759	MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
Notes: VERIFIED BY PQ040											
281506	Vent Float / Nonrelieving Valve (AIR Passage) {Right Forward} - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP007-3	4770	MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281507	Vent Float / Nonrelieving Valve (AIR Passage) {Left Aft} -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCP003-3	3241	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VER BY PQ040											
281508	Vent Float / Nonrelieving Valve (AIR Passage) {Right Aft} -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCP003-3	3266	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VER PQ040											
281509	Vent Float / Nonrelieving Valve (Vent Duct) {Left Forward} -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCP006-1	3339	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY Q309510											
281510	Vent Float / Nonrelieving Valve (Vent Duct) {Right		HRS		4057.8			0			0
	Forward} - Removal / Installation		AFL		1184			0			0
	1159SCP006-1	3355	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY Q309510											
281513	Vent Float / Pressure Relief Valve (1 Inch) {Left Wing} -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCP007-3	4760	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
281514	Vent Float / Pressure Relief Valve (1 Inch) {Right Wing} -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCP007-3	4773	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281515	Wing Vent Float Drain Valve (Left) - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281516	Wing Vent Float Drain Valve (Right) - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281521	Aft Outboard Vent Float Drain (Vent Duct) Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P52025-2	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
281522	Aft Outboard Vent Float Drain (Vent Duct) Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P52025-2	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
281523	Vent Float Drain (Vent Tubing) Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	775C-80NW	3758	MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
Notes: VER BY Q308046											
281524	Vent Float Drain (Vent Tubing) Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	775C-80NW	3814	MOS		188.2			24 May 2008			AUTO VALVE INC
	Airframe		MSC				O/C				
Notes: VER BY Q308046											
281527	Overboard Vent / Ram AIR Inlet Mast (Left) - Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281528	Overboard Vent / Ram AIR Inlet Mast (Right) - Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
281601	Heated Fuel Return Shut-Off Valve (Left) - Removal / Installation		HRS		3387.5			670.3			0
			AFL		985			199			0
	AV24B1441	AA259063	MOS		155.9			04 Feb 2011			AVTEC INC
			MSC								O/C
Airframe											
281602	Heated Fuel Return Shut-Off Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AV24B1441	AA150511	MOS		188.2			24 May 2008			AVTEC INC
			MSC								O/C
Airframe											
282001	Main Fuel Boost Pump (Left) - Removal / Installation		HRS		2943.3			1114.5			0
			AFL		858			326			0
	1159SCP500-7	1658	MOS	TSN:52	136.5			15 Sep 2012			
			MSC								O/C
Airframe											
282002	Main Fuel Boost Pump (Right) - Removal / Installation		HRS		2943.3			1114.5			0
			AFL		858			326			0
	1159SCP500-7	1650	MOS	TSN:52	136.5			15 Sep 2012			
			MSC								O/C
Airframe											
282003	Alternate Fuel Boost Pump (Left) - Removal / Installation		HRS		2943.3			1114.5			0
			AFL		858			326			0
	1159SCP500-7	1662	MOS	TSN:52	136.5			15 Sep 2012			
			MSC								O/C
Airframe											
282004	Alternate Fuel Boost Pump (Right) - Removal / Installation		HRS		2943.3			1114.5			0
			AFL		858			326			0
	1159SCP500-7	1660	MOS	TSN:52	136.5			15 Sep 2012			
			MSC								O/C
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282005	Fuel Boost Pump Emi Filter (Left) - Removal / Installation		HRS		2943.7			1114.1			0
	1159SCP500-15	1310	AFL		858			326			0
			MOS		137			30 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
282006	Fuel Boost Pump Emi Filter (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCP500-15	0890	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VER BY PQ009											
282007	Main Fuel Boost Pump (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282008	Main Fuel Boost Pump (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282009	Alternate Fuel Boost Pump (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282010	Alternate Fuel Boost Pump (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282011	Fuel Boost Pump Control System - Operational Check		HRS		2943.3			1114.5			0
			AFL		858			326			0
			MOS		136.5			15 Sep 2012			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282014	Fuel Boost Pump Emi Filter - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282103	Pressure Fueling - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282107	Suction Defueling - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282110	Pressure Fueling / Defueling Adapter - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61255	1200	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
282112	Engine Suction Fuel Feed (Left) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282113	Engine Suction Fuel Feed (Right) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282115	Defueling Suction Check Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282116	Defueling Suction Check Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
282205	Pressure Fueling Shut-Off Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61086-1	817	MOS		188.2			24 May 2008			
			MSC							O/C	VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
Notes: VERIFIED BY PQ040											
282206	Pressure Fueling Shut-Off Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61086-1	819	MOS		188.2			24 May 2008			
			MSC							O/C	VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
Notes: VERIFIED BY PQ 040											
282207	Pressure Fueling Sensing Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP004	821	MOS		188.2			24 May 2008			
			MSC							O/C	SHAW AERO DEVICES
Airframe											
Notes: VERIFIED BY PQ040											
282208	Pressure Fueling Sensing Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP004	822	MOS		188.2			24 May 2008			
			MSC							O/C	SHAW AERO DEVICES
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282213	High-Level Pilot Valve (Float) No. 1 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61087-4	1594	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ040											
282214	High-Level Pilot Valve (Float) No. 2 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61087-4	1628	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ040											
282215	High-Level Pilot Valve (Float) No. 1 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61087-4	1630	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
282216	High-Level Pilot Valve (Float) No. 2 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	61087-4	1636	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
282217	L High Level Pilot Valve - Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
282218	R High Level Pilot Valve - Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282219	Fuel Tank High-Level Shutoff (Automatic MODE) -		HRS		4057.8			0			0
	Operational Check		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
282220	Remote Fuel S/O Cont--Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
282221	Remote Fueling Solenoid Shut-Off Valve (Left) - Removal		HRS		4057.8			0			0
	/ Installation		AFL		1184			0			0
	V4700-96	830	MOS		188.2			24 May 2008			VALCOR ENG CORP
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
282222	Remote Fueling Solenoid Shut-Off Valve (Right) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	V4700-96	758	MOS		188.2			24 May 2008			VALCOR ENG CORP
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
282223	Fueling / Defueling Precheck Selector Valve No. 1 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	6BS100	2768	MOS		188.2			24 May 2008			ALLEN AIRCRAFT PRODUCTS INC
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
282224	Fueling / Defueling Precheck Selector Valve No. 2 -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	6BS100	2769	MOS		188.2			24 May 2008			ALLEN AIRCRAFT PRODUCTS INC
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282402	Fuel Cross-Flow / Intertank System - Operational Check		HRS		2943.3			1114.5			0
	Airframe		AFL		858			326			0
			MOS		136.5			15 Sep 2012			
			MSC					O/C			
282403	Intertank Shut-Off Valve Motor - Removal / Installation		HRS		2943.3			1114.5			0
	Airframe	AV16B2199	T60410	AFL		858			326		0
				MOS		136.5			15 Sep 2012		GENERAL DYNAMICS AVIATIONS SERVICES
				MSC				O/C			
282404	Intertank Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
	Airframe	AV17B1310C	AA132447	AFL		1184			0		0
				MOS		188.2			24 May 2008		ITT AEROSPACE CONTROLS
				MSC				O/C			
Notes: VERIFIED BY PQ 040											
282405	Intertank Shutoff Valve / Low Fuel Sensor - Functional		HRS		4057.8			0			0
	Airframe	Check		AFL		1184			0		0
				MOS		188.2			24 May 2008		
				MSC				O/C			
282406	Cross-Flow Shut-Off Valve Motor - Removal / Installation		HRS		4057.8			0			0
	Airframe	AV17B1310C	SN-UNKNOWN	AFL		1184			0		0
				MOS		188.2			24 May 2008		ITT AEROSPACE CONTROLS
				MSC				O/C			
282407	Cross-Flow Shut-Off Valve - Removal / Installation		HRS		3687			370.8			0
	Airframe	130004T	U01546	AFL		1080			104		0
				MOS		168.1			29 Jan 2010		GENERAL DYNAMICS AVIATIONS SERVICES
				MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282408	Cross-Flow Shut-Off Valve - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282503	Fuel Boost Pump Inlet Filter Screen (Left Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P52410-1	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
282504	Fuel Boost Pump Inlet Filter Screen (Left Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P54210-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282505	Fuel Boost Pump Inlet Filter Screen (Right Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P54210-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282506	Fuel Boost Pump Inlet Filter Screen (Right Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P54210-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282601	Engine Fuel Distribution System (Fuel Flow) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282602	APU Fuel Distribution System (Fuel Flow) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282603	Engine Feed Dual Wall Fuel Line Shroud (Left) -		HRS		1909.4			2148.4			0
	Functional Test		AFL		573			611			0
			MOS		88.8	24	96	06 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282604	Engine Feed Dual Wall Fuel Line Shroud (Right) -		HRS		1909.4			2148.4			0
	Functional Test		AFL		573			611			0
			MOS		88.8	24	96	06 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282605	APU Feed Dual Wall Fuel Line Shroud - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8	24	96	06 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282606	Engine Feed Dual Wall Fuel Line (Left) - Detailed		HRS		616			3441.8			0
	Inspection		AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282607	Engine Feed Dual Wall Fuel Line (Right) - Detailed		HRS		616			3441.8			0
	Inspection		AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282608	APU Feed Dual Wall Fuel Line - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282609	Engine Heated Return Feed Dual Wall Fuel Line (Left) -		HRS		616			3441.8			0
	Detailed Inspection		AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282610	Engine Heated Return Feed Dual Wall Fuel Line (Right) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
282611	Engine Heated Return Feed Dual Wall Fuel Line Shroud (Left) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8		24	96	06 Sep 2016	30 Sep 2024*	31 Oct 2024
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
282612	Engine Heated Return Feed Dual Wall Fuel Line Shroud (Right) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8		24	96	06 Sep 2016	30 Sep 2024*	31 Oct 2024
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
282613	Fuel Boost Pump Manifold Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P20140-29	HD1235	MOS		188.2				24 May 2008		
			MSC								O/C
Airframe											
Notes: VERIFIED BY PQ040											
282614	Fuel Boost Pump Manifold Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159P20140-30	HD1230	MOS		188.2				24 May 2008		
			MSC								O/C
Airframe											
Notes: VERIFIED BY PQ 040											
282619	Fuel Ejector Pump (Left, Hopper) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SC-P-002-7	0392	MOS		188.2				24 May 2008		
			MSC								O/C
Airframe											
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282620	Fuel Ejector Pump (Right, Hopper) - Removal / Installation		HRS		4057.8			0			0
	1159SCP002-7	0408	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
282621	Fuel Ejector Pump (Left, Mid-Wing) - Removal / Installation		HRS		4057.8			0			0
	1159SCP002-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282627	Fuel Ejector Pump and Check Valves (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282628	Fuel Ejector Pump and Check Valves (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
282629	Engine Fuel Shut-Off Valve (Left) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		24	16 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282630	Engine Fuel Shut-Off Valve (Right) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		24	16 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282631	Engine Fuel Shut-Off Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	AV16B2199	AA142243	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GENERAL DYNAMICS AVIATIONS SERVICES
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282632	Engine Fuel Shut-Off Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	AV16B2199	AA142245	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
282640	APU Fuel Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
	V4700-108-2	0298	AFL		1184			0			0
			MOS		188.2			24 May 2008			CARL F BOOTH & CO INC
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
282641	APU Fuel Shut-Off Valve - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5			16 Jun 2022			
	Airframe		MSC					O/C			
282643	Fuel Ejector Pump Motive Flow Check Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	Z02CV06-7	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
	Airframe		MSC					O/C			
282644	Fuel Ejector Pump Motive Flow Check Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	Z02CV06-7	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282645	Fuel Vapor Return Check Valve No. 1 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P17-533	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
Airframe			MSC				O/C				
282646	Fuel Vapor Return Check Valve No. 1 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P17-533	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
Airframe			MSC				O/C				
282647	Fuel Vapor Return Check Valve No. 2 (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P17-533	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
Airframe			MSC				O/C				
282648	Fuel Vapor Return Check Valve No. 2 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P17-533	SN-UNKNOWN	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES (INC) VAIL
Airframe			MSC				O/C				
282649	Fuel System Manifold Assembly Check Valves (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	28C112	SN-UNKNOWN	MOS		188.2			24 May 2008			ALLEN AIRCRAFT PRODUCTS, INC.
Airframe			MSC				O/C				
282650	Fuel System Manifold Assembly Check Valves (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	28C112	SN-UNKNOWN	MOS		188.2			24 May 2008			ALLEN AIRCRAFT PRODUCTS, INC.
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282651	Main Fuel Boost Pump (Left) - Fuel Leak Check		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCP500-7 SN: <NONE>.											
282652	Main Fuel Boost Pump (Right) - Fuel Leak Check		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCP500-7 SN: <NONE>.											
282653	Alternate Fuel Boost Pump (Left) - Fuel Leak Check		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCP500-7 SN: <NONE>.											
282654	Alternate Fuel Boost Pump (Right) - Fuel Leak Check		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
Airframe			[HRS: +50/-50]								
Notes: PN: 1159SCP500-7 SN: <NONE>.											
284001	Fuel Indicator Functional Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
284002	Indicator, Fuel Quanity		HRS		4057.8			0			0
	366-926-001	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			PARKER HANNIFIN CORPORATION
Airframe											
284101	Fuel Quantity System - Capacitance / Insulation		HRS		440.3			3617.5			0
	Resistance Check		AFL		163			1021			0
			MOS		14.3			21 Nov 2022			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284102	Fuel Quantity Signal Conditioner - Removal / Installation		HRS		4057.8			0			0
	367-933-002	545	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
284103	Fuel System Interface to Aircraft Systems - Operational		HRS		4057.8			0			0
	Check		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284104	Fuel Quantity Measuring / Indication System - Functional		HRS		4057.8			0			0
	Check		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284105	Fuel Quantity Densitometer (Left) - Removal / Installation		HRS		4057.8			0			0
	180-032-002	1751	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284106	Fuel Quantity Densitometer (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	180-032-002	1753	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284107	Fuel Ground Service Control Panel - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	366-926-001	SN-UNKNOWN	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284108	Fuel Ground Service Control Panel - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284110	Fuel Quantity Signal Conditioner - Power / Ground Diode Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284117	L Fuel Quantity Probe Electrical Resistance - Functional Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284118	R Fuel Quantity Probe Electrical Resistance - Functional Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284119	L Fuel Quantity Probe Electrical Capacitance - Functional Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284120	R Fuel Quantity Probe Electrical Capacitance - Functional Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
284121	Fuel Quantity Probe No. 1 (Left) - Removal / Installation		HRS		4057.8			0			0
	021-935-001	0961	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			PARKER HANNIFIN CORPORATION

Notes: VERIFIED BY Q309510

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

284122	Fuel Quantity Probe No. 2 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-001	0950	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

Notes: VERIFIED BY PQ040

284123	Fuel Quantity Probe No. 3 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-002	0937	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

Notes: VERIFIED BY PQ040

284124	Fuel Quantity Probe No. 4 (Left) - Removal / Installation		HRS		4057.8			0			0
	022-901-001	0921	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

Notes: VERIFIED BY Q309510

284125	Fuel Quantity Probe No. 5 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-003	0959	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			

Notes: VERIFIED BY PQ040

284126	Fuel Quantity Probe No. 6 (Left) - Removal / Installation		HRS		440.3			3617.5			0
	020-989-004	2049	AFL		163			1021			0
			MOS	TSN:1	14.3			21 Nov 2022			N/A
	Airframe		MSC					O/C			

Notes: VERIFIED BY PQ040

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284127	Fuel Quantity Probe No. 7 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-005	0962	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284128	Fuel Quantity Probe No. 8 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-006	0948	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284129	Fuel Quantity Probe No. 9 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-007	0643	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284130	Fuel Quantity Probe No. 10 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-008	0985	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284131	Fuel Quantity Probe No. 11 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-009	0957	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284132	Fuel Quantity Probe No. 12 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-010	0956	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC				O/C				HANNIFIN CORPORATION
Notes: VERIFIED BY PQ040											
284133	Fuel Quantity Probe No. 13 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-011	0970	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC				O/C				HANNIFIN CORPORATION
Notes: VERIFIED BY PQ040											
284134	Fuel Quantity Probe No. 14 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-012	0943	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC				O/C				HANNIFIN CORPORATION
Notes: VERIFIED BY PQ040											
284135	Fuel Quantity Probe No. 15 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-013	0952	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC				O/C				HANNIFIN CORPORATION
Notes: VERIFIED BY PQ040											
284136	Fuel Quantity Probe No. 16 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-014	0964	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC				O/C				HANNIFIN CORPORATION
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284137	Fuel Quantity Probe No. 17 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-015	0952	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284138	Fuel Quantity Probe No. 18 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-016	0947	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284139	Fuel Quantity Probe No. 19 (Left) - Removal / Installation		HRS		4057.8			0			0
	020-989-017	1044	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284140	Outboard High Fuel Level Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
	057-022-001	0921	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
284141	Fuel Quantity Probe No. 1 (Right) - Removal / Installation		HRS		4057.8			0			0
	021-935-001	0948	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q309510											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284142	Fuel Quantity Probe No. 2 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-001	0945	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY PQ 040											
284143	Fuel Quantity Probe No. 3 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-002	0936	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY PQ 040											
284144	Fuel Quantity Probe No. 4 (Right) - Removal / Installation		HRS		4057.8			0			0
	022-901-001	0922	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY Q309510											
284145	Fuel Quantity Probe No. 5 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-003	0961	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY PQ 040											
284146	Fuel Quantity Probe No. 6 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-004	0968	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN CORPORATION
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284147	Fuel Quantity Probe No. 7 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-005	0961	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284148	Fuel Quantity Probe No. 8 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-006	0951	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284149	Fuel Quantity Probe No. 9 (Right) - Removal / Installation		HRS		4057.8			0			0
	021-935-002	0545	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284150	Fuel Quantity Probe No. 10 (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	020-989-008	0982	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
284151	Fuel Quantity Probe No. 11 (Right) - Removal / Installation		HRS		4057.8			0			0
	020-989-009	0954	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284152	Fuel Quantity Probe No. 12 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-010	0955	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284153	Fuel Quantity Probe No. 13 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-011	0969	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284154	Fuel Quantity Probe No. 14 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-012	0949	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284155	Fuel Quantity Probe No. 15 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-013	0956	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284156	Fuel Quantity Probe No. 16 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-014	0958	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284157	Fuel Quantity Probe No. 17 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-015	0951	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284158	Fuel Quantity Probe No. 18 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-016	0951	MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284159	Fuel Quantity Probe No. 19 (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	020-989-017	1039	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284160	Outboard High Fuel Level Sensor (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	057-022-001	0946	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
284301	Fuel Tank Temperature Bulb - Functional Check		HRS		260.2			3797.6			0
			AFL		97			1087			0
			MOS		9		48	01 May 2023	31 May 2027	30 Jun 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
284302	Fuel Tank Temperature Bulb (Left) - Removal / Installation		HRS		260.2			3797.6			0
	MS28034-1		AFL		97			1087			0
	SN-UNKNOWN		MOS		9			01 May 2023			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284303	Fuel Tank Temperature Bulb (Right) - Removal / Installation		HRS		260.2			3797.6			0
			AFL		97			1087			0
	MS28034-1	SN-UNKNOWN	MOS		9			01 May 2023			
			MSC							O/C	
Airframe											
284305	Main Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS	TSN:1114.1	2943.7			1114.1			0
			AFL	TSN:326	858			326			0
	8G1594	1189	MOS	TSN:51	137			30 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC							O/C	
Airframe											
284306	Alternate Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS	TSN:1114.1	2943.7			1114.1			0
			AFL	TSN:326	858			326			0
	8G1594	1194	MOS	TSN:51	137			30 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC							O/C	
Airframe											
284307	Main Fuel Boost Pump Pressure Switch (Right) - Removal / Installation		HRS	TSN:1114.1	2943.7			1114.1			0
			AFL	TSN:326	858			326			0
	8G1594	1184	MOS	TSN:51	137			30 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC							O/C	
Airframe											
284308	Alternate Fuel Boost Pump Pressure Switch (Right) - Removal / Installation		HRS	TSN:1114.1	2943.7			1114.1			0
			AFL	TSN:326	858			326			0
	8G1594	1208	MOS	TSN:51	137			30 Aug 2012			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC							O/C	
Airframe											
29 - Hydraulic Power											
290001	Hydraulic System Bleeding Procedure		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.5			15 Jun 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
290002	Hydraulic System Bleed Procedure - Alternate		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
	Airframe		MSC					O/C			
290003	Hydraulic System Automatic Bleed Procedure		HRS		583.8			3474			0
			AFL		211			973			0
			MOS		18.1			28 Jul 2022			
	Airframe		MSC					O/C			
290009	Hydraulic Fluid (Left) - Sampling / Analysis		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
290010	Hydraulic Fluid (Right) - Sampling / Analysis		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
290021	Hydraulic Fluid Heat Exchanger (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	10718000	801	MOS		188.2			24 May 2008			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ040											
290022	Hydraulic Fluid Heat Exchanger (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	10718000	807	MOS		188.2			24 May 2008			GULFSTREAM DALLAS
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
290030	Hydraulic AIR Separator Can Assembly, Removal and Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SB59400-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
290031	L/H Hydraulic AIR Separator Bleeder Valve - Removal and Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
290032	L/H Hydraulic Reservoir Standpipe Bleeder Valve - Removal and Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
290033	R/H Hydraulic Reservoir Standpipe Bleeder Valve - Removal and Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH249-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
290034	R/H Hydraulic Low Pressure Relief Valve - Removal and Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH648-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
290100	Hydraulic Replenisher Tank - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH519-7	0350	MOS		188.2			24 May 2008			
			MSC							O/C	MEGGITT AIRDYNAMICS, INC.
Airframe											
Notes: Q305319											
291001	Left Hydraulic System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
291002	Right Hydraulic System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291003	Hydraulic Systems (Left / Right) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
291006	Abex Engine-Driven Hydraulic Pump (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH505-101	K1749	MOS		188.2			24 May 2008			EATON AEROSPACE
	Airframe		MSC					O/C			
291008	Abex Engine-Driven Hydraulic Pump (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH505-101	K1750	MOS		188.2			24 May 2008			EATON AEROSPACE
	Airframe		MSC					O/C			
291030	Left System Manifold - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH517-11	0371	MOS		188.2			24 May 2008			PALL AEROPOWER CORPORATION
	Airframe		MSC					O/C			
Notes: Q306794											
291031	Right System Manifold - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH518-11	0447	MOS		188.2			24 May 2008			PALL AEROPOWER CORPORATION
	Airframe		MSC					O/C			
Notes: Q306794											
291033	Left System Manifold Filter / Filter Bowl (Main Pressure) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AC-C219F-161	SN-UNKNOWN	MOS		188.2			24 May 2008			PALL AEROPOWER CORPORATION
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291034	Right System Manifold Filter / Filter Bowl (Main Pressure)		HRS		4057.8			0			0
	- Removal / Installation		AFL		1184			0			0
	AC-C219F-161	SN-UNKNOWN	MOS		188.2			24 May 2008			PALL
			MSC					O/C			AEROPOWER CORPORATION
Airframe											
291035	Left System Manifold Filter / Filter Bowl (Main Return) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	AC-C219F-161	SN-UNKNOWN	MOS		188.2			24 May 2008			PALL
			MSC					O/C			AEROPOWER CORPORATION
Airframe											
291036	Right System Manifold Filter / Filter Bowl (Main Return) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	AC-C219F-161	SN-UNKNOWN	MOS		188.2			24 May 2008			PALL
			MSC					O/C			AEROPOWER CORPORATION
Airframe											
291037	Left System Manifold Filter / Filter Bowl (Aux Return) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	ACB451F10	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291038	Auxiliary Hydraulic Pump Manifold Filter Element and		HRS		4057.8			0			0
	Bowl - Removal / Installation		AFL		1184			0			0
	ACB451F8	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291039	Left System Manifold Filter / Filter Bowl (Ptu Case Drain) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	AC-C314F-8Y2	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291040	Power Transfer Unit Manifold Filter and Bowl - Removal / Installation		HRS		3242.3			815.5			0
			AFL		944			240			0
	ACB451F16	NSN	MOS		149			30 Aug 2011			
			MSC							O/C	
Airframe											
291041	Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AC-B451-8	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
291042	Right System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AC-B451-8	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
291403	Left System Manifold Differential Pressure Indicator (Pressure) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	366-929-001	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM DALLAS
			MSC							O/C	
Airframe											
291404	Right System Manifold Differential Pressure Indicator (Pressure) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	TD470UK0901611	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
291405	Left System Manifold Low-Pressure Relief Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AA-9500-D3837	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
291406	Right System Manifold Low-Pressure Relief Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AD-C220-16D281	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291407	Left Engine Hydraulic System Acoustical Filter - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH526-1	841	MOS		188.2			24 May 2008			PULSCO
	Airframe		MSC								DIVISION OF ADVANCED TECHNOLOGY
291408	Right Engine Hydraulic System Acoustical Filter - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH526-1	840	MOS		188.2			24 May 2008			PULSCO
	Airframe		MSC								DIVISION OF ADVANCED TECHNOLOGY
291409	Left Manifold Pressure Switch - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AA-99-00-D3837	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC								
291410	Right System Manifold High-Pressure Relief Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	AD-C220-11D11	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC								
291421	Left System Manifold Fluid Sampling Port - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	ADB942-82D29Y3	SN-UNKNOWN	MOS		188.2			24 May 2008			E A R SPECIALITY
	Airframe		MSC								COMPOSITE AERO
291422	Right System Manifold Fluid Sampling and Bleed Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	ADB942-82D29Y3	SN-UNKNOWN	MOS		188.2			24 May 2008			E A R SPECIALITY
	Airframe		MSC								COMPOSITE AERO

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291429	Hydraulic System Pressure Reducing Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH219-33	SN-UNKNOWN	MOS		188.2			24 May 2008			PNEUDRAULICS INC
			MSC					O/C			
Airframe											
291430	Hydraulic System Pressure Reducing Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH219-33	SN-UNKNOWN	MOS		188.2			24 May 2008			PNEUDRAULICS INC
			MSC					O/C			
Airframe											
291431	Engine-Driven Hydraulic Pump Case Drain Filter Fluid Sample (Left) - Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291432	Engine-Driven Hydraulic Pump Case Drain Filter Fluid Sample (Right) - Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291433	Valve, L Main Press Rtn Sample		HRS		4057.8			0			0
	ADB942-82D29Y3		AFL		1184			0			0
		SN-UNKNOWN	MOS		188.2			24 May 2008			E A R SPECIALITY COMPOSITE AERO
			MSC					O/C			
Airframe											
291434	Valve, R Main Press Rtn Sample		HRS		4057.8			0			0
	ADB942-82D29Y3		AFL		1184			0			0
		SN-UNKNOWN	MOS		188.2			24 May 2008			E A R SPECIALITY COMPOSITE AERO
			MSC					O/C			
Airframe											
291501	Hydraulic System Shut-Off Valve (Left) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291502	Hydraulic System Shut-Off Valve (Right) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	04 Jun 2022	30 Jun 2024	31 Jul 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
291503	Left Hydraulic System Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH239-5	AA149662	MOS		188.2			24 May 2008			ITT AEROSPACE CONTROLS
			MSC					O/C			
Airframe											
Notes: VER BY Q312506											
291504	Right Hydraulic System Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH239-5	AA149674	MOS		188.2			24 May 2008			ITT AEROSPACE CONTROLS
			MSC					O/C			
Airframe											
Notes: VER BY Q312506											
291601	Left System Hydraulic Reservoir - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291602	Right System Hydraulic Reservoir - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
291603	Left System Reservoir - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50125-29	55-5198GT	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: VER BY Q312506											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291604	Right System Reservoir - Removal / Installation		HRS		4057.8			0			0
	1159H50126-31	55-5198GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
Notes: VER BY Q312506											
291611	Hydraulic Reservoir Quantity Transmitter (Left) - Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: PN: 1159SCH525-1 SN: <NONE>.											
291612	Hydraulic Reservoir Quantity Transmitter (Right) - Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: PN: 1159SCH525-3 SN: <NONE>.											
291613	Valve, Hyd. Reservoir Selector- R / I		HRS		4057.8			0			0
	1159SCH602-3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
291701	Hydraulic System Accumulator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCH206-5	60211-2722	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS
	Airframe		MSC					O/C			INC
Notes: Q306794											
291702	Hydraulic System Accumulator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCH206-5	60211-2713	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS
	Airframe		MSC					O/C			INC
Notes: Q306794											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291703	Hydraulic System Accumulator Pressure Gage (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GP20-24	08-0324321	MOS		188.2			24 May 2008			CUSTOM METAL WORKS
			MSC								
Airframe											
Notes: VER BY Q306794											
291704	Hydraulic System Accumulator Pressure Gage (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	GP20-24	08-0222338	MOS		188.2			24 May 2008			CUSTOM METAL WORKS
			MSC								
Airframe											
Notes: VER BY Q306794											
291705	Hydraulic System Accumulator (Left) - Service		HRS		292.3			3765.5			0
			AFL		107			1077			0
			MOS		9.6			12 Apr 2023			
			MSC								
Airframe											
291706	Hydraulic System Accumulator (Right) - Service		HRS		292.3			3765.5			0
			AFL		107			1077			0
			MOS		9.6			12 Apr 2023			
			MSC								
Airframe											
292001	Auxiliary Hyd System--Service		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
292002	Auxiliary Hydraulic System - Functional Test		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.6			13 Jul 2021			
			MSC								
Airframe											
292005	Auxiliary Hydraulic System (Brakes) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292010	Auxiliary Hydraulic System (Nose Wheel Steering) -		HRS		4057.8			0			0
	Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292015	Auxiliary Hydraulic System (Flaps) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292020	Auxiliary Hydraulic System (Main Entrance Door) -		HRS		4057.8			0			0
	Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292025	Auxiliary Hydraulic System (Nose Landing Gear Doors) -		HRS		4057.8			0			0
	Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292030	Auxiliary Hydraulic System (Left / Right Main Landing		HRS		4057.8			0			0
	Gear Doors) - Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292035	Auxiliary Hydraulic System (Nose and Main Landing Gear		HRS		4057.8			0			0
	Doors) - Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292040	Auxiliary Hydraulic System (Landing Gear) - Functional		HRS		4057.8			0			0
	Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292045	Auxiliary Hydraulic System (Rudder) - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			
292101	Auxiliary Hydraulic Pump - Removal / Installation		HRS		857.7			3200.1			0
	1159SCH504-3	MX607568A	AFL		280			904			0
			MOS		30.6			11 Jul 2021			N/A
	Airframe			MSC				O/C			
Notes: VERIFIED BY Q311721											
292102	Auxiliary Hydraulic Boost Pump - Removal / Installation		HRS		4057.8			0			0
	1159SCH520-3	0454	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			PARKER HANNIFIN CORPORATION
Notes: VER BY Q312506											
292201	Power Transfer Unit Hydraulic Pump - Removal / Installation		HRS		4057.8			0			0
	1159SCH511-3	MX718643	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			GENERAL DYNAMICS AVIATIONS SERVICES
Notes: VER BY Q312506											
292202	Transducer, Power Transfer Unit (Ptu) {Sta 780}		HRS		4057.8			0			0
	1159SCAV600-1	HAL3896	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			GULFSTREAM - LONG BEACH
Notes: VER BY Q312506											
292203	Transducer, Lh Sys (Sta 850)		HRS		4057.8			0			0
	1159SCAV600-1	HAL3918	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			GULFSTREAM - LONG BEACH
Notes: Q306794											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292204	Transducer, Rh Sys (Sta 850)		HRS		4057.8			0			0
	1159SCAV600-1	HAL3907	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM -
	Airframe		MSC					O/C			LONG BEACH
Notes: Q306794											
292205	Power Transfer Unit - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
292206	Valve, PtU Sample		HRS		4057.8			0			0
	ADB942-82D29Y3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			E A R SPECIALITY
	Airframe		MSC					O/C			COMPOSITE AERO
292208	Power Transfer Unit ARM Circuit - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
292501	Auxiliary Hydraulic Pump Manifold Differential Pressure Indicator - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			16 Aug 2023			
	Airframe										[HRS: +50/-50]
292502	Power Transfer Unit Manifold Differential Pressure Indicator - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			16 Aug 2023			
	Airframe										[HRS: +50/-50]
292503	Auxiliary Hydraulic Pump Manifold - Removal / Installation		HRS		4057.8			0			0
	1159H51512-3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292504	Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH530-3	SN-UNKNOWN	MOS		188.2			24 May 2008			GOODRICH SENSOR SYSTEMS
			MSC					O/C			
Airframe											
292505	Auxiliary Hydraulic Pump Manifold Relief Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH207-5	SN-UNKNOWN	MOS		188.2			24 May 2008			TACTAIR FLUID CONTROLS INC
			MSC					O/C			
Airframe											
292506	Auxiliary Hydraulic Pump Manifold Differential Pressure Indicator - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	TD470UK096	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292507	Auxiliary Hydraulic Pump Acoustical Filter (Muffler) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H51512-11	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
292508	Power Transfer Unit Manifold - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH529-3	0257	MOS		188.2			24 May 2008			PALL AEROPOWER CORPORATION
			MSC					O/C			
Airframe											
Notes: VER BY Q312506											
292509	Filter/Bowl,Pwr Xfer Manifold		HRS		4057.8			0			0
			AFL		1184			0			0
	AAB451-16Y1D2A	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292510	Power Transfer Unit Manifold Differential Pressure Indicator - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	TD470UK096	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
292511	Switch, Ptp/L Hyd Sys Pressure		HRS		4057.8			0			0
	1206P0215	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	ELECTRO ENTERPRISES INC
Airframe											
292601	Auxiliary Hydraulic System Shut-Off Control - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
292602	Auxiliary Hydraulic Pump Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
	1159SCH516-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	PNEUDRAULICS INC
Airframe											
292603	Power Transfer Unit Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
	1159SCH514-3	0553	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	PALL AEROPower CORPORATION
Airframe											
Notes: VER BY Q312506											
292604	Valve, Aux Motor Shutoff		HRS		4057.8			0			0
	1159SCH514-3	1398	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	PALL AEROPower CORPORATION
Airframe											
Notes: VER BY Q312506											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
293198	Hydraulic Pressure Switch (2600 Psi, Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1203P0142-01	1107	MOS		188.2			24 May 2008			HONEYWELL
			MSC								HPG
Airframe											
Notes: Q306794											
293199	Hydraulic Pressure Switch (2600 Psi, Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1203P0142-01	1085	MOS		188.2			24 May 2008			HONEYWELL
			MSC								HPG
Airframe											
Notes: Q306794											
293203	Hydraulic System Reservoir Temperature Transducer (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH525-19	B1032	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VER BY Q312506											
293204	Hydraulic System Reservoir Temperature Transducer (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH525-21	B0128	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VER BY Q3126506											
293205	Transducer, Pwr Transfer Unit		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50106-9	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
293206	Auxiliary Pressure Transducer - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV600-1	HAL3897	MOS		188.2			24 May 2008			GULFSTREAM -
			MSC								LONG BEACH
Airframe											
Notes: VERIFIED BY Q308046											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
293301	External Quantity Indicator - Removal / Installation		HRS		4057.8			0			0
	366-929-001	523	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
Notes: Q310159											
30 - Ice and Rain Protection											
301100	Wing Anti-Ice Control System - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
301101	Wing Anti-Ice Control Valve (Left) - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	3215600-2	1158	AFL	TSN:691	493			691			0
			MOS	TSN:120	69			01 May 2018			GENERAL
	Airframe		MSC					O/C			DYNAMICS AVIATIONS SERVICES
301102	Wing Anti-Ice Control Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	3215600-2	1178	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC					O/C			DYNAMICS AVIATIONS SERVICES
301105	Wing Anti-Ice Inboard / Outboard Temperature Switch (Left Inboard) - Removal / Installation		HRS		4057.8			0			0
	975-0114-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
301106	Wing Anti-Ice Inboard / Outboard Temperature Switch (Right Inboard) - Removal / Installation		HRS		4057.8			0			0
	975-0114-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301107	Wing Anti-Ice Normal Temperature Switch (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	975-0114-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
301108	Wing Anti-Ice Normal Temperature Switch (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	975-0114-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
301109	Wing Anti-Ice Inboard / Outboard Temperature Switch (Left Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	975-0114-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
301110	Wing Anti-Ice Inboard / Outboard Temperature Switch (Right Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	975-0114-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
301111	Wing Anti-Ice Temperature Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
			MSC						O/C		
Airframe											
301112	Wing Anti-Ice Temperature Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
			MSC						O/C		
Airframe											
301113	Wing Anti-Icing Thermal Sensor (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL ASCA INC.
			MSC						O/C		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301114	Wing Anti-Icing Thermal Sensor (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
301115	Wing Anti-Icing Thermal Sensor (Left No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
301116	Wing Anti-Icing Thermal Sensor (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151834-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
301117	Wing Anti-Ice Thermal Switch (Left) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
	(301117)		MOS		88.7	22	192	08 Sep 2016	30 Sep 2032*	31 Oct 2032	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
301118	Wing Anti-Ice Thermal Switch (Right) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
	(301118)		MOS		88.7	22	192	08 Sep 2016	30 Sep 2032*	31 Oct 2032	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
301121	Wing Hot / Wing Temp Low Message (Left) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							
301122	Wing Hot / Wing Temp Low Message (Right) - Functional Test		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe			[End Of Month Item] [MOS: +1m/-1m]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW	MM Ref									Manufacturer
	Ops Number(s)											Date Type
	301143	Left Wing Normal Anti-Ice Temperature Switch - Operational Test		HRS		1909.4			2148.4			0
AFL					573			611			0	
MOS					88.7			08 Sep 2016				
MSC									O/C			
Airframe												
301144	Right Wing Normal Anti-Ice Temperature Switch - Operational Test		HRS		1909.4			2148.4			0	
			AFL		573			611			0	
			MOS		88.7			08 Sep 2016				
			MSC						O/C			
Airframe												
301301	Wing Anti-Ice Check Valve (Left) - Removal / Installation 3202756-1 1017		HRS	TSN:3100.1	957.9			3099.9			0	
			AFL	TSN:871	313			871			0	
			MOS	TSN:148	40.8			05 Sep 2020			N/A	
			MSC						O/C			
Airframe												
301302	Wing Anti-Ice Check Valve (Right) - Removal / Installation 3202756-1 1019		HRS	TSN:3100.1	957.9			3099.9			0	
			AFL	TSN:871	313			871			0	
			MOS	TSN:148	40.9			04 Sep 2020			N/A	
			MSC						O/C			
Airframe												
301303	Wing Anti-Ice Check Valve (Left) - Detailed Inspection		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
301304	Wing Anti-Ice Check Valve (Right) - Detailed Inspection		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
301307	Wing Anti-Ice (Left) - Operational Test		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		40.8			05 Sep 2020				
			MSC						O/C			
Airframe												
301308	Wing Anti-Ice (Right) - Operational Test		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		40.8			05 Sep 2020				
			MSC						O/C			
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
302101	Cowl Anti-Ice Control Valve Open / Close Switch /		HRS		4057.8			0			0
	Pressure Transducer (Left) - Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
302102	Cowl Anti-Ice Control Valve Open / Close Switch /		HRS		4057.8			0			0
	Pressure Transducer (Right) - Functional Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
302103	Cowl Anti-Ice Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	510-0020-5	D0724	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIRCRAFT BELTS INC
			MSC					O/C			
Airframe											
302104	Cowl Anti-Ice Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	510-0020-5	D0732	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIRCRAFT BELTS INC
			MSC					O/C			
Airframe											
302105	Cowl Anti-Ice Pressure Transducer (Left) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	APTE-227-1000-75G	7445-2-406	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
302106	Cowl Anti-Ice Pressure Transducer (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	APTE-227-1000-75G	7445-2-404	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
302118	Forward Thermal Anti-Ice Duct (Right) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
303103	Angle of Attack Probe Heater - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
303104	Pitot / Static and Total AIR Temperature Probe Heater - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
304021	Windshield Heat Control Unit (No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1042-1	3982	MOS		188.2			24 May 2008			GULFSTREAM - LONG BEACH
	Airframe		MSC					O/C			
304022	Windshield Heat Control Unit (No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1042-1	4101	MOS		188.2			24 May 2008			GULFSTREAM - LONG BEACH
	Airframe		MSC					O/C			
304027	Windshield Heat (Left) - Operational Test		HRS		2130.7			1927.1			0
			AFL		650			534			0
			MOS		98.6			12 Nov 2015			
	Airframe		MSC					O/C			
304028	Windshield Heat (Right) - Operational Test		HRS		751.7			3306.1			0
			AFL		247			937			0
			MOS		23.5			16 Feb 2022			
	Airframe		MSC					O/C			
304105	Windshield Surface Seal (Left) - Detailed Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	38	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
304106	Windshield Surface Seal (Right) - Detailed Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	38	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304107	Windshield Surface Seal (Left) - Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
304108	Windshield Surface Seal (Right) - Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
304110	Cabin Window Heat - Operational Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.2			25 Aug 2020			
	Airframe		MSC					O/C			
304116	Windshield Surface Seal (Left) - Serviceability Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
304117	Windshield Surface Seal (Right) - Serviceability Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
304210	Windshield Rain Removal System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
308001	Ice Detector Probe (Left) - Removal / Installation		HRS		498.9			3558.9			0
	0871HH	02043	AFL		186			998			0
			MOS		16			01 Oct 2022			N/A
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q300454											
308002	Ice Detector Probe (Right) - Removal / Installation		HRS		4057.8			0			0
	0871HH	01107	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			DALLAS
Notes: VERIFIED BY Q300454											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
308003	Ice Detector Probe (Left) - Operational Test		HRS		498.9			3558.9			0
			AFL		186			998			0
			MOS		16			01 Oct 2022			
	Airframe		MSC					O/C			
308004	Ice Detector Probe (Right) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
31 - Indicating/Recording Systems											
312001	Pilot Cockpit Clock - Removal / Installation		HRS	TSN:1055.1	134.1			3923.7			0
	1159SCAV409-2	5487	AFL	TSN:317	44			1140			0
			MOS	TSN:54	4.6			12 Sep 2023			
	Airframe		MSC					O/C			
312002	Copilot Cockpit Clock - Removal / Installation		HRS	TSN:3923.7	134.1			3923.7			0
	1159SCAV409-2	2242	AFL	TSN:1140	44			1140			0
			MOS	TSN:183	4.6			12 Sep 2023			
	Airframe		MSC					O/C			
312501	Thermal Printer - Removal / Installation		HRS		4057.8			0			0
	700750-1915	48402966	AFL		1184			0			0
	4	A	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
313001	Dfdr - Removal / Installation		HRS		857.7			3200.1			0
	980-4710-003	0504	AFL		280			904			0
			MOS		30.3			22 Jul 2021			N/A
	Airframe		MSC					O/C			
313002	Dfdr - Functional Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.6	40	24	12 Jun 2023	31 Jul 2025*	31 Aug 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313006	Dfdr Underwater Locator Beacon - Battery Discard		HRS		857.7			3200.1			0
	810-2042	NSN	AFL		280			904			0
			MOS		30.3			22 Jul 2021	31 Aug 2025		N/A
	Airframe		MSC					DUE			EXPIRATION
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313009	Dfdr Underwater Locator Beacon - Battery Replacement		HRS		857.7			3200.1			0
	810-2042	NSN	AFL		280			904			0
			MOS		30.3			22 Jul 2021			N/A
	Airframe		MSC								
313010	Dfdr Underwater Locator Beacon - Operational Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	48	24	04 Jun 2023	31 Jul 2025*	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
313020	Dfdr Underwater Locator Beacon - Switch Cleaning		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	46	24	06 Jun 2023	31 Jul 2025*	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
313054	Recorder, Quick Access (Mini QAR)		HRS		4025.2			32.6			0
	QAR200-02-00	000554663	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			L3
	Airframe		MSC								
313101	Dfdr Impact Switch - Removal / Installation		HRS		4057.8			0			0
	1159SCAV402-2	2689	AFL		1184			0			0
			MOS		188.2			24 May 2008			DAVTRON INC
	Airframe		MSC								
Notes: Q310169											
313102	Dfdr Tri-Axial Accelerometer - Removal / Installation		HRS		4057.8			0			0
	3001-01-100	0108-12243	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC								AMETEK AEROSPACE GULTON STATHAM PRODUCTS
313105	Dfdr Underwater Locator Beacon - Removal / Installation		HRS		857.7			3200.1			0
	DK120/90	AT120828	AFL		280			904			0
			MOS		30.3			22 Jul 2021			N/A
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314002	Central Maintenance Computer Module - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	PN	SN-UNKNOWN	MOS		65.7			09 Aug 2018			HONEYWELL
			MSC								
Airframe											
314025	Central Maintenance System - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
314030	Modular Avionics Unit No. 1 - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	7024404-1913	08041673	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.7			09 Aug 2018			HONEYWELL
			MSC								
Airframe											
Notes: MOD:A,B,D-F (VERIFIED BY: Q311286)											
314034	Modular Avionics Unit No. 2 - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	7024404-1913	08041687	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.7			09 Aug 2018			HONEYWELL
			MSC								
Airframe											
Notes: MOD:A,B,D-F (VERIFIED BY: Q311286)											
314301	Power Supply Module No. 1 - Removal / Installation		HRS		4057.8			0			0
	7024440-1901	0804A476	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
314302	Power Supply Module No. 2 - Removal / Installation		HRS		4057.8			0			0
	7024440-1901	0804A279	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
314303	Data Base Module No. 1 - Removal / Installation		HRS		2020.5			2037.3			0
	7027208-1903	1604X794	AFL		612			572			0
			MOS		92.7			09 May 2016			
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314304	Data Base Module No. 2 - Removal / Installation		HRS		2020.5			2037.3			0
	7027208-1903	1604X795	AFL		612			572			0
			MOS		92.7			09 May 2016			
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314305	Control I/O Module - Removal / Installation		HRS		4057.8			0			0
	7026534-1902	08043253	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314306	Custom I/O Module No. 1 - Removal / Installation		HRS		2020.5			2037.3			0
	7026540-1903	16036036	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314307	Single Channel Gio Module No. 1 - Removal / Installation		HRS		4057.8			0			0
	7025364-1901	08033624	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314308	Single Channel Gio Module No. 2 - Removal / Installation		HRS		4057.8			0			0
	7025364-1902	08043729	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314310	Dbm - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314311	Network Interface Controller / Processor Module No. 1 - Removal / Installation		HRS		2020.5			2037.3			0
	7038231-1902	1603F561	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
	Airframe		MSC					O/C			INTERNATIONAL
Notes: VERIFIED BY: Q311286											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314312	Network Interface Controller / Processor Module No. 2 - Removal / Installation		HRS		2020.5			2037.3			0
			AFL		612			572			0
	7038231-1902	1603F567	MOS		92.7			09 May 2016			HONEYWELL INTERNATIONAL
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
314313	Dual Channel Gio Module No. 1 - Removal / Installation		HRS		440.3			3617.5			0
			AFL		163			1021			0
	7025365-1902	05031234	MOS		14.1			27 Nov 2022			N/A
			MSC								
Airframe											
Notes: VERIFIED BY: Q311286											
314314	Advanced Graphic Module No. 1 - Removal / Installation		HRS		3253.4			804.4			0
			AFL		949			235			0
	7036410-1901	08030734	MOS		150.8			05 Jul 2011			HONEYWELL
		A-C	MSC								
Airframe											
314317	Dual Channel Gio Module - Return to Service Test		HRS		440.3			3617.5			0
			AFL		163			1021			0
			MOS		14.1			27 Nov 2022			
			MSC								
Airframe											
314320	Modular Avionics Unit - Operational Check		HRS		3253.4			804.4			0
			AFL		949			235			0
			MOS		150.8			05 Jul 2011			
			MSC								
Airframe											
314328^U	Plate, Blank Slot 1 Mau #3		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
Airframe											
314334^U	Plate, Blank Slot 16 Mau #1		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314401	Power Supply Module No. 3 - Removal / Installation		HRS		4057.8			0			0
	7024440-1901	0804A280	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314402	Power Supply Module No. 4 - Removal / Installation		HRS		4057.8			0			0
	7024440-1901	0804A505	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314403	Video Module No. 1 - Removal / Installation		HRS		4057.8			0			0
	7026531-1902	08091588	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314404	Custom I/O Module No. 2 - Removal / Installation		HRS		2020.5			2037.3			0
	7026540-1903	16036011	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314405	Single Channel Gio Module No. 3 - Removal / Installation		HRS		4057.8			0			0
	7025364-1901	08033622	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314406	Single Channel Gio Module No. 4 - Removal / Installation		HRS		4057.8			0			0
	7025364-1901	08033621	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY: Q311286											
314409	Network Interface Controller / Processor Module No. 3 - Removal / Installation		HRS		2020.5			2037.3			0
	7038231-1902	1603F569	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL
	Airframe		MSC					O/C			INTERNATIONAL

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314410	Network Interface Controller / Processor Module No. 4 - Removal / Installation		HRS		2020.5			2037.3			0
			AFL		612			572			0
	7038231-1902	1603F574	MOS		92.7			09 May 2016			HONEYWELL
			MSC								INTERNATIONAL
Airframe											
314411	Dual Channel Gio Module No. 2 - Removal / Installation		HRS		440.3			3617.5			0
			AFL		163			1021			0
	7025365-1902	08013681	MOS		14.1			27 Nov 2022			N/A
			MSC								
Airframe											
314412	Advanced Graphic Module No. 2 - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	7036410-1901	11108356	MOS		42.5			14 Jul 2020			N/A
			MSC								
Airframe											
314500	Single Channel Gio Module - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
314501	Power Supply Module No. 5 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	7024440-1901	0804A278	MOS		188.2			24 May 2008			HONEYWELL
			MSC								
Airframe											
314502	Power Supply Module No. 6 - Removal / Installation		HRS		1909.3			2148.5			0
			AFL		573			611			0
	7024440-1901	0802A058	MOS		88.1			29 Sep 2016			HONEYWELL
			MSC								
Airframe											
314503	Video Module No. 2 - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	7026531-1902	08041581	MOS		188.2			24 May 2008			HONEYWELL
			MSC								
Airframe											
314504	Custom I/O Module No. 3 - Removal / Installation		HRS		2020.5			2037.3			0
			AFL		612			572			0
	7026540-1903	16046057	MOS		92.7			09 May 2016			HONEYWELL
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314505	Single Channel Gio Module No. 5 - Removal / Installation		HRS		4057.8			0			0
	7025364-1901	08043719	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
314506	Single Channel Gio Module No. 6 - Removal / Installation		HRS		4057.8			0			0
	7025364-1902	08043623	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
314507	Network Interface Controller / Processor Module No. 5 - Removal / Installation		HRS		2020.5			2037.3			0
	7038231-1902	1603F447	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL INTERNATIONAL
	Airframe		MSC					O/C			
314508	Network Interface Controller / Processor Module No. 6 - Removal / Installation		HRS		2020.5			2037.3			0
	7038231-1902	1603F526	AFL		612			572			0
			MOS		92.7			09 May 2016			HONEYWELL INTERNATIONAL
	Airframe		MSC					O/C			
314509	Advanced Graphic Module No. 3 - Removal / Installation		HRS		875			3182.8			0
	7036410-1901	08111956	AFL		290			894			0
			MOS		33			01 May 2021			
	Airframe		MSC					O/C			
314510	Advanced Graphic Module No. 4 - Removal / Installation		HRS		957.9			3099.9			0
	7036410-1901	08081424	AFL		313			871			0
			MOS		42.5			14 Jul 2020			N/A
	Airframe		MSC					O/C			
314512	Nic / Processor - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
314513	Custom I/O Module - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314514	Control I/O Module - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			
314521	Nic / Processor Module Battery No. 1 - Discard		HRS		4057.8			0			0
	7025879-400	B279	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
314524	Nic / Processor Module Battery No. 2 - Discard		HRS		4057.8			0			0
	7025879-400	B190	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
314527	Nic / Processor Module Battery No. 3 - Discard		HRS		4057.8			0			0
	7025879-400	B394	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
314530	Nic / Processor Module Battery No. 4 - Discard		HRS		4057.8			0			0
	7025879-400	B288	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
314533	Nic / Processor Module Battery No. 5 - Discard		HRS		4057.8			0			0
	7025879-400	B380	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
314536	Nic / Processor Module Battery No. 6 - Discard		HRS		4057.8			0			0
	7025879-400	B435	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			MANUFACTURE
315001	Central Warning System (Including Audio) - Operational		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
	Test		AFL		44			1140			0
			MOS		5.1			28 Aug 2023			
	Airframe			[HRS: +50/-50]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
315610	Checklist - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
316001	Display Controller (Pilot) - Removal / Installation		HRS		4021.3			36.5			0
	7007540-809	08032597	AFL		1169			15			0
			MOS		184.3			23 Sep 2008			HONEYWELL
	Airframe		MSC					O/C			
316002	Display Controller (Copilot) - Removal / Installation		HRS		4021.3			36.5			0
	7007540-809	08032596	AFL		1169			15			0
			MOS		184.3			23 Sep 2008			HONEYWELL
	Airframe		MSC					O/C			
316003	Display Controller - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
316004	Display Brightness Control Panel - Removal / Installation		HRS		4057.8			0			0
	7007543-903	08041283	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			HPG
Notes: VERIFIED BY PQ514											
316010	Cursor Control Device (Left) - Removal / Installation		HRS		957.9			3099.9			0
	1159F57160-9	0427	AFL		313			871			0
			MOS		42.1			27 Jul 2020			N/A
	Airframe		MSC					O/C			
316011	Cursor Control Device (Left) - Operational Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.1			27 Jul 2020			
	Airframe		MSC					O/C			
316013	Cursor Control Device (Right) - Removal / Installation		HRS		957.9			3099.9			0
	1159F57160-10	0445	AFL		313			871			0
			MOS		42.3			22 Jul 2020			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316021	Display Unit No. 1 - Removal / Installation		HRS		4057.8			0			0
	7028140-901	08043192	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
316022	Display Unit No. 2 - Removal / Installation		HRS		4057.8			0			0
	7028140-901	08043198	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
316023	Display Unit No. 3 - Removal / Installation		HRS		4057.8			0			0
	7028140-901	08043197	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
316024	Display Unit No. 4 - Removal / Installation		HRS		4057.8			0			0
	7028140-901	08043211	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
316027	EDS - Return to Service Test		HRS		4021.3			36.5			0
			AFL		1169			15			0
			MOS		184.2			24 Sep 2008			
	Airframe		MSC					O/C			
316030	Electronic Display System - Return to Service Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
316201	Display Unit Manual Reversion - Operational Test		HRS		1189.2	15.8	1500	2868.6	4384.4*	4434.4	0
			AFL		361			823			0
			MOS		52.9			04 Sep 2019			
	Airframe		[HRS: +50/-50]								
316203	McdU Capability to Display Standby Engine Instruments - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316205	Dfdr Fail Message - Operational Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	45	24	07 Jun 2023	31 Jul 2025*	31 Aug 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
316206	Configuration Message - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.8	55	36	06 Sep 2023	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
316207	Egpws / Windshear Warning System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
316208	Elevator Mistrim / Aileron Retrim Messages - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
319010	Honeywell Planeview Operational Software Master Operating System - Top Level System (White Disk)		HRS		957.9			3099.9			0
	EB7031236-00325		AFL		313			871			0
	35682069		MOS	TSN:1	42.5			14 Jul 2020			
	Airframe		MSC O/C								
319011	Planeview System Charts - Update		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2			24 Jan 2024			
	Airframe		MSC O/C								
319012	Honeywell Planeview, Operational Software (Master Operating System) - Media (White Disk)		HRS		2020.5			2037.3			0
	MM7031235-023		AFL		612			572			0
	UCN35601487		MOS		92.6			13 May 2016			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
319015	Honeywell Planeview, Configuration (Aircraft Options)		HRS		2020.5			2037.3			0
	Software - Top Level System (Yellow Disk)		AFL		612			572			0
	TT60002648-50331	43979	MOS		92.6			13 May 2016			
			MSC							O/C	
Airframe											
319017	Honeywell Planeview, Aircraft Options Data Software -		HRS		884.1			3173.7			0
	Media (White Disk)		AFL		291			893			0
	DM60002648-50414	55507	MOS	TSN:36	33.5			16 Apr 2021			
			MSC							O/C	
Airframe											
319020	Gulfstream, Electronic Checklist Software (Purple Disk)		HRS		957.9			3099.9			0
	GVPV010500007L.ECL		AFL		313			871			0
		5198	MOS	TSN:1	42.5			14 Jul 2020			
			MSC							O/C	
Airframe											
319022	CD, Electronic Checklist Media		HRS		2020.5			2037.3			0
	GVPV010500003L.ECL		AFL		612			572			0
		5198	MOS		92.6			13 May 2016			
			MSC							O/C	
Airframe											
319025	Gulfstream, Setting / Rigging Software (Grey Disk)		HRS		2020.5			2037.3			0
	LZFIA0X451C30 4MAY16		AFL		612			572			0
		5198	MOS		92.6			13 May 2016			
			MSC							O/C	
Airframe											
319027	CD, Settings / Rigging Media		HRS		2020.5			2037.3			0
	LZFIA0X451C30		AFL		612			572			0
		5198	MOS		92.6			13 May 2016			
			MSC							O/C	
Airframe											
319030	Gulfstream, Central Maintenance Computer Loadable		HRS		957.9			3099.9			0
	Diagnostic Information Software (Black Disk)		AFL		313			871			0
	GV_912_00330_01_060420	5198	MOS	TSN:1	42.5			14 Jul 2020			
			MSC							O/C	
Airframe											
319032	CD, Cmc Diagnostic Media		HRS		2020.5			2037.3			0
	GV_911_00323_01_022714		AFL		612			572			0
		5198	MOS		92.6			13 May 2016			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
319037	Programmable CAS Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			
319041	Cms-400 Wiring-Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	7	192	23 Sep 2008	30 Sep 2024*		
	Airframe			[End Of Month Item]							
319042	Cms 400 System-Func Test		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1		24	30 Dec 2023	31 Dec 2025		
	Airframe			[End Of Month Item]							
319043	Cms-400 System Components-Visual Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	7	192	23 Sep 2008	30 Sep 2024*		
	Airframe			[End Of Month Item]							
32 - Landing Gear											
320101	Main Gear Flow Regulator (Left) - Removal / Installation		HRS		4057.8			0			0
	159H10040-155	2797G02	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			AIRLIFT HYDRAULICS INCORPORATED
320102	Main Gear Flow Regulator (Right) - Removal / Installation		HRS		4057.8			0			0
	159H10040-155	2798G02	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			AIRLIFT HYDRAULICS INCORPORATED
321001	Main Landing Gear (Left) - Removal / Installation		HRS		4057.8			0			0
	1159L50001-19	MA0557	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321002	Main Landing Gear (Right) - Removal / Installation		HRS		4057.8			0			0
	1159L50001-20	MA0558	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
321003	Main Landing Gear Components (Left) - Detailed Corrosion Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		48	22 Jul 2020	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321004	Main Landing Gear Components (Right) - Detailed Corrosion Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		48	22 Jul 2020	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321005	Main Landing Gear (Left) - Lubrication		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1	-9	4	29 Dec 2023	30 Apr 2024*	31 May 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321006	Main Landing Gear (Right) - Lubrication		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1	-9	4	29 Dec 2023	30 Apr 2024*	31 May 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
321007	Main Landing Gear Strut Assembly (Left) - Discard		HRS		4057.8			0			0
	1159L50001-19	MA0557	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
321008	Main Landing Gear Strut Assembly (Right) - Discard		HRS		4057.8			0			0
	1159L50001-20	MA0558	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
321009	Main Gear Structural Post (Left) - Discard		HRS		4057.8			0			0
	1159LM50126-9	MK0156	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										GOODRICH CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321010	Main Gear Structural Post (Right) - Discard		HRS		4057.8			0			0
	1159LM50126-10	MK0159	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321011	Main Landing Gear Structural Post (Left) - Restore		HRS		4057.8			0			0
	1159LM50126-9	MK0156	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321012	Main Landing Gear Structural Post (Right) - Restore		HRS	TSN:815.5	3242.3			815.5			0
	1159LM50126-10	MK0159	AFL	TSN:240	944		5000	240	5000		0
			MOS	TSN:39	149				30 Aug 2011		GOODRICH CORPORATION
Airframe											
321013	Main Landing Gear Trunnion Pin (Left Forward) - Discard		HRS		4057.8			0			0
	1159LM50853-3	AAP2362	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321014	Main Landing Gear Trunnion Pin (Right Forward) - Discard		HRS		4057.8			0			0
	1159LM50853-3	AAP2358	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321015	Main Landing Gear Forward Trunnion Pin (Left) - Restore		HRS		4057.8			0			0
	1159LM50853-3	AAP2362	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321016	Main Landing Gear Forward Trunnion Pin (Right) - Restore		HRS		4057.8			0			0
	1159LM50853-3	AAP2358	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321017	Main Landing Gear Trunnion Pin (Left Aft) - Discard		HRS		4057.8			0			0
	1159SCL566-13	MBM0729	AFL		1184		20000	0	20000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321018	Main Landing Gear Trunnion Pin (Right Aft) - Discard		HRS		957.9			3099.9			0
	1159SCL566-17	MBM1993	AFL		313		20000	871	20871		0
			MOS	TSN:3	42.3	146			21 Jul 2020		GOODRICH CORPORATION
Airframe											
321021	Main Landing Gear Spindle Pin (Left) - Discard		HRS		4057.8			0			0
	1159LM50137-7	MBM0487	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
321022	Main Landing Gear Spindle Pin (Right) - Discard		HRS		4057.8			0			0
	1159LM50137-7	MBM0493	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321023	Main Landing Gear Spindle Pin (Left) - Restore		HRS		4057.8			0			0
	1159LM50137-7	MBM0487	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
321024	Main Landing Gear Spindle Pin (Right) - Restore		HRS		4057.8			0			0
	1159LM50137-7	MBM0493	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
321025	Main Landing Gear (Left) - Rigging / Adjustment		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6				13 Jun 2022		
Airframe									O/C		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321026	Main Landing Gear (Right) - Rigging / Adjustment		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			13 Jun 2022			
	Airframe		MSC					O/C			
321027	Main Gear Trunnion Pin (Left Forward) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159LM50853-3	AAP2362	MOS	TSN:100	88.4			18 Sep 2016			GOODRICH CORPORATION
	Airframe		MSC					O/C			
321028	Main Gear Trunnion Pin (Right Forward) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159LM50853-3	AAP2358	MOS	TSN:100	88.4			18 Sep 2016			GOODRICH CORPORATION
	Airframe		MSC					O/C			
321029	Main Gear Trunnion Pin (Left Aft) - Removal / Installation		HRS	TSN:3099.5	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159SCL566-13	MBM0729	MOS	TSN:146	42.3			22 Jul 2020			
	Airframe		MSC					O/C			
321030	Main Gear Trunnion Pin (Right Aft) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	1159SCL566-17	MBM1993	MOS	TSN:3	42.3			22 Jul 2020			GOODRICH
	Airframe		MSC					O/C			
321031	Main Landing Gear (Left) - Restore		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184		5000	0	5000		0
	Airframe		MOS		188.2			24 May 2008			
321032	Main Landing Gear (Right) - Restore		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184		5000	0	5000		0
	Airframe		MOS		188.2			24 May 2008			
321039	Main Landing Gear Sponson Bores (Left) - Structural Inspection		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	(321039) Airframe		MOS		188.2			24 May 2008			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321040	Main Landing Gear Sponson Bores (Right) - Structural Inspection		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		
(321040)											
Airframe											
321043	Main Gear Fairing (Left) - Removal / Installation		HRS		4057.8			0			0
	1159W50401-9	0393	AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
Notes: VERIFIED BY Q112232											
321044	Main Gear Fairing (Right) - Removal / Installation		HRS		4057.8			0			0
	1159W50401-10	0393	AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe											
Notes: VERIFIED BY Q112232											
321045	Main Landing Gear and Attachments (Left) - General Visual Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5				17 Aug 2023		
Airframe											
321046	Main Landing Gear and Attachments (Right) - General Visual Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5				17 Aug 2023		
Airframe											
321201	Main Landing Gear Shock Absorber (Left) - Servicing		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		48	22 Jul 2020	31 Jul 2024	31 Aug 2024	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321202	Main Landing Gear Shock Absorber (Right) - Servicing		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		48	22 Jul 2020	31 Jul 2024	31 Aug 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
321203	Main Gear Shock Absorber (Left) - Discard		HRS		4057.8			0			0
	1159L50100-11	PLT0229	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
321204	Main Gear Shock Absorber (Right) - Discard		HRS		4057.8			0			0
	1159L50100-11	PLT0251	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
321205	Main Gear Shock Absorber (Left) - Restore		HRS		4057.8			0			0
	1159L50100-11	PLT0229	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
321206	Main Gear Shock Absorber (Right) - Restore		HRS		4057.8			0			0
	1159L50100-11	PLT0251	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
321207	Main Gear Shock Strut Attachment Pin (Left Upper Attach Pin) - Discard		HRS		4057.8			0			0
	1159LM50147-11	EXC-0036	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321208	Main Gear Shock Strut Attachment Pin (Right Upper Attach Pin) - Discard		HRS		4057.8			0			0
	1159LM50147-11	EXC-0017	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321209	Main Landing Gear Shock Strut Attach Pin (Left Upper) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50147-11	EXC-0036	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321210	Main Landing Gear Shock Strut Attach Pin (Right Upper) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50147-11	EXC-0017	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321211	Main Gear Shock Strut Attachment Pin (Left Lower Attach Pin) - Discard		HRS		4057.8			0			0
			AFL		1184		16000	0	16000		0
	1159LM50147-11	EXC-0056	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321212	Main Gear Shock Strut Attachment Pin (Right Lower Attach Pin) - Discard		HRS		4057.8			0			0
			AFL		1184		16000	0	16000		0
	1159LM50147-11	EXC-0046	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321213	Main Landing Gear Shock Strut Attach Pin (Left Lower) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50147-11	EXC-0056	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321214	Main Landing Gear Shock Strut Attach Pin (Right Lower) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50147-11	EXC-0046	MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
321215	Main Gear Shock Strut Cylinder Nut (Left) - Discard		HRS		1909.4			2148.4			0
			AFL		573		16000	611	16611		0
	1159LM50112-13	PLT280405	MOS	TSN:20	88.2			25 Sep 2016			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321216	Main Gear Shock Strut Cylinder Nut (Right) - Discard		HRS		1909.4			2148.4			0
	1159LM50112-13	PLT280403	AFL		573		16000	611	16611		0
			MOS	TSN:20	88.2			25 Sep 2016			
Airframe											
321217	Main Landing Gear Shock Absorber (Left) - Removal /		HRS	TSN:3100.4	957.9			3099.9			0
	Installation		AFL	TSN:871	313			871			0
	1159L50100-11	PLT0229	MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC					O/C			
Airframe											
321218	Main Landing Gear Shock Absorber (Right) - Removal /		HRS	TSN:3099.5	957.9			3099.9			0
	Installation		AFL	TSN:871	313			871			0
	1159L50100-11	PLT0251	MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC					O/C			
Airframe											
321221	Main Landing Gear Corrosion Inhibiting Compound		HRS		616			3441.8			0
	Reapplication (Left)		AFL		220			964			0
			MOS		19.8	47	24	05 Jun 2022	31 Jul 2024*	31 Aug 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
321222	Main Landing Gear Corrosion Inhibiting Compound		HRS		616			3441.8			0
	Reapplication (Right)		AFL		220			964			0
			MOS		19.8	47	24	05 Jun 2022	31 Jul 2024*	31 Aug 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
321225	Main Landing Gear Shock Absorber (Left) - Repacking		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
321228	Main Landing Gear Axle Fitting Attach Pin (Left) Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321230	Main Landing Gear Shock Absorber (Right) - Repacking		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
321232	Main Landing Gear Axle Fitting Attach Pin (Right)		HRS		957.9			3099.9			0
	Corrosion Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
	Airframe		MSC					O/C			
321235	Main Landing Gear Axle Fitting and Axle Fitting Nut (Left)		HRS		957.9			3099.9			0
	Corrosion Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
	Airframe		MSC					O/C			
321236	Main Landing Gear Axle Fitting and Axle Fitting Nut		HRS		957.9			3099.9			0
	(Right) Corrosion Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
	Airframe		MSC					O/C			
321239	Main Landing Gear Shock Absorber Upper and Lower		HRS		957.9			3099.9			0
	Attach Pins (Left) Corrosion Inhibiting Compound		AFL		313			871			0
	Application		MOS		42.5			17 Jul 2020			
	Airframe		MSC					O/C			
321240	Main Landing Gear Shock Absorber Upper and Lower		HRS		957.9			3099.9			0
	Attach Pins (Right) Corrosion Inhibiting Compound		AFL		313			871			0
	Application		MOS		42.5			17 Jul 2020			
	Airframe		MSC					O/C			
321243	Main Landing Gear Sidebrace Actuator Attach Pins /		HRS		957.9			3099.9			0
	Trunnion AREA (Left) Corrosion Inhibiting Compound		AFL		313			871			0
	Application		MOS		42.3			21 Jul 2020			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321244	Main Landing Gear Sidebrace Actuator Attach Pins /		HRS		957.9			3099.9			0
	Trunnion AREA (Right) Corrosion Inhibiting Compound		AFL		313			871			0
	Application		MOS		42.3			21 Jul 2020			
			MSC							O/C	
Airframe											
321247	Main Landing Gear Uplock Roller (Left) Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
			MSC							O/C	
Airframe											
321248	Main Landing Gear Uplock Roller (Right) Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.5			17 Jul 2020			
			MSC							O/C	
Airframe											
321251	Main Landing Gear Striker ARM (Left) Corrosion Inhibiting		HRS		957.9			3099.9			0
	Compound Application		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC							O/C	
Airframe											
321252	Main Landing Gear Striker ARM (Right) Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC							O/C	
Airframe											
321255	Nose Landing Gear Shock Strut and Axle Assembly		HRS		957.9			3099.9			0
	Corrosion Inhibiting Compound Application		AFL		313			871			0
			MOS		42.4			19 Jul 2020			
			MSC							O/C	
Airframe											
321256	Nose Landing Gear Trunnion Assembly Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321259	Nose Landing Gear Truss Brace Assembly Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application - Servicing		AFL		313			871			0
			MOS		41.3			21 Aug 2020			
			MSC					O/C			
Airframe											
321260	Nose Landing Gear Upper Trunnion Attach Pins Corrosion		HRS		957.9			3099.9			0
	Inhibiting Compound Application		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC					O/C			
Airframe											
321263	Nose Landing Gear Upper Drag Brace Attach Pin		HRS		957.9			3099.9			0
	Corrosion Inhibiting Compound Application		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC					O/C			
Airframe											
321264	Nose Landing Gear Striker Arms Corrosion Inhibiting		HRS		957.9			3099.9			0
	Compound Application		AFL		313			871			0
			MOS		42.4			19 Jul 2020			
			MSC					O/C			
Airframe											
321301	Main Landing Gear Axle Fitting (Left) - Removal /		HRS	TSN:2148.4	1909.4			2148.4			0
	Installation		AFL	TSN:611	573			611			0
	1159LM50140-7	MK0152	MOS	TSN:100	88.2			26 Sep 2016			
			MSC					O/C			
Airframe											
321302	Main Landing Gear Axle Fitting (Right) - Removal /		HRS	TSN:2148.4	1909.4			2148.4			0
	Installation		AFL	TSN:611	573			611			0
	1159LM50140-8	MK0173	MOS	TSN:100	88.3			21 Sep 2016			
			MSC					O/C			
Airframe											
321303	Main Landing Gear Axle Fitting (Left) - Restore		HRS		4057.8			0			0
	1159LM50140-7	MK0152	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			
Airframe											
											GOODRICH CORPORATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321304	Main Landing Gear Axle Fitting (Right) - Restore		HRS		4057.8			0			0
	1159LM50140-8	MK0173	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		AIRLIFT HYDRAULICS INCORPORATE
Airframe											
321305	Main Landing Gear Axle Fitting Attach Pin (Left) - Discard		HRS		4057.8			0			0
	1159LM50148-1	ETP0174	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
321306	Main Landing Gear Axle Fitting Attach Pin (Right) - Discard		HRS		4057.8			0			0
	1159LM50148-1	ETP0175	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
321307	Main Landing Gear Axle Fitting Attach Pin (Left) - Restore		HRS		4057.8			0			0
	1159LM50148-1	ETP0174	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		STELLEX PRECISION MACHINING, I
Airframe											
321308	Main Landing Gear Axle Fitting Attach Pin (Right) - Restore		HRS		4057.8			0			0
	1159LM50148-1	ETP0175	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		STELLEX PRECISION MACHINING, I
Airframe											
321309	Main Landing Gear Axle Fitting (Left) - Discard		HRS		4057.8			0			0
	1159LM50140-7	MK0152	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
321310	Main Landing Gear Axle Fitting (Right) - Discard		HRS		4057.8			0			0
	1159LM50140-8	MK0173	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321403	Main Landing Gear Side Brace Lower Attach Pin (Left) - Discard		HRS		4057.8			0			0
			AFL		1184		16000	0	16000		0
	1159LM50164-13	MBM0585	MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321404	Main Landing Gear Side Brace Lower Attach Pin (Right) - Discard		HRS		4057.8			0			0
			AFL		1184		16000	0	16000		0
	1159LM50164-13	MBM0603	MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321405	Main Landing Gear Side Brace Lower Attach Pin (Left) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50164-13	MBM0585	MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321406	Main Landing Gear Side Brace Lower Attach Pin (Right) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159LM50164-13	MBM0603	MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											
321407	Main Landing Gear Side Brace (Left) - Discard		HRS		4057.8			0			0
			AFL		1184		20000	0	20000		0
	1159SCL502-11	A861	MOS		188.2				24 May 2008		
Airframe											
321408	Main Landing Gear Side Brace (Right) - Discard		HRS		4057.8			0			0
			AFL		1184		20000	0	20000		0
	1159SCL502-11	A862	MOS		188.2				24 May 2008		
Airframe											
321409	Main Landing Gear Side Brace (Left) - Restore		HRS		4057.8			0			0
			AFL		1184		5000	0	5000		0
	1159SCL502-11	A861	MOS		188.2				24 May 2008		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321410	Main Landing Gear Side Brace (Right) - Restore		HRS		4057.8			0			0
	1159SCL502-11	A862	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		
Airframe											
321801	Main Landing Gear Door Hinges (Left) - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
321802	Main Landing Gear Door Hinges (Right) - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
321803	Main Landing Gear and Doors (Left) - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	33	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
321804	Main Landing Gear and Doors (Right) - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	32	12	06 Jun 2023	31 Jul 2024*	31 Aug 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
321805	Main Gear Door (Left) - Removal / Installation		HRS		4057.8			0			0
	1159B54501-9	0398	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe			MSC				O/C			GENERAL DYNAMICS AVIATIONS SERVICES	
321806	Main Gear Door (Right) - Removal / Installation		HRS		4057.8			0			0
	1159B54501-10	0398	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe			MSC				O/C			GENERAL DYNAMICS AVIATIONS SERVICES	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322001	Nose Landing Gear Assembly - Discard		HRS		4057.8			0			0
	1159L50004-21	PLT0247	AFL		1184		26200	0	26200		0
			MOS		188.2				24 May 2008		GENERAL DYNAMICS AVIATIONS SER
Airframe											
322002	Nose Landing Gear - Removal / Installation		HRS		4057.8			0			0
	1159L50004-21	PLT0247	AFL		1184			0			0
			MOS		188.2				24 May 2008		GENERAL DYNAMICS AVIATIONS SERVICES
Airframe						O/C					
322003	Nose Landing Gear Components - Detailed Corrosion Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.3	10	48	21 Aug 2020	31 Aug 2024*	30 Sep 2024	
Airframe											
											[End Of Month Item] [MOS: +1m/-1m]
322004	Nose Landing Gear - Lubrication		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1.1	-9	4	29 Dec 2023	30 Apr 2024*	31 May 2024	
Airframe											
											[End Of Month Item] [MOS: +1m/-1m]
322005	Nose Landing Gear - Restore		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		
Airframe											
322006	Nose Landing Gear and Attachments - General Visual Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4				20 Aug 2023		
Airframe											
											[HRS: +50/-50]
322200	Nose Landing Gear Shock Strut - Discard		HRS		4057.8			0			0
	1159L50500-13	PLT0247	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	MOS	MSC							Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322201	Nose Landing Gear Shock Strut - Removal / Installation		HRS		4057.8			0			0
	1159L50500-13	PLT0247	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
	Airframe		MSC					O/C			
322202	Nose Landing Gear Shock Strut - Servicing		HRS		539.2			3518.6			0
			AFL		197			987			0
			MOS		16.7		48	10 Sep 2022	30 Sep 2026	31 Oct 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
322205	Nose Landing Gear Shock Strut - Restore		HRS		4057.8			0			0
	1159L50500-13	PLT0247	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
	Airframe										
322206	Nose Landing Gear Shock Strut Cylinder Assembly - Discard		HRS		4057.8			0			0
	1159LM50700-1	PLT0247	AFL		1184		16000	0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
322207	Nose Landing Gear Upper Torque ARM - Removal / Installation		HRS		4057.8			0			0
	1159LM50548-1	PLT0312	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
322208	Nose Landing Gear Lower Torque ARM - Removal / Installation		HRS		4057.8			0			0
	1159LM30553-3	PLT0387	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
	Airframe		MSC					O/C			
322220	Nose Landing Gear Corrosion Inhibiting Compound Reapplication		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	06 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322301	Nose Landing Gear Axle Fitting - Removal / Installation		HRS		4057.8			0			0
	1159LM50521-11	PLT0281	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIRLIFT
	Airframe		MSC					O/C			HYDRAULICS INCORPORATED
322305	Nose Gear Bungee - Removal / Installation		HRS		616			3441.8			0
	1159L10032-205	NSN	AFL		220			964			0
			MOS		19.8			06 Jun 2022			
	Airframe		MSC					O/C			
322306	Nose Landing Gear Bungee - Lubrication		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	06 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
322311	Nose Landing Gear Axle Assembly Piston - Discard		HRS		4057.8			0			0
	1159LM50521-11	PLT0281	AFL		1184		32750	0	32750		0
			MOS		188.2			24 May 2008			
	Airframe										
Notes: 26200 EASA REQUIREMENT											
322401	Nose Landing Gear Trunnion - Discard		HRS		4057.8			0			0
	1159LM50690-3	PLT0315	AFL		1184		22750	0	22750		0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
	Airframe										
Notes: 18200 EASA REQUIREMENT											
322402	Nose Landing Gear Trunnion - Restore		HRS		4057.8			0			0
	1159LM50690-3	PLT0315	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
	Airframe										
322403	Nose Landing Gear Drag Brace - Discard		HRS		4057.8			0			0
	1159LM50585-1	PLT0332	AFL		1184		26200	0	26200		0
			MOS		188.2			24 May 2008			B F GOODRICH
	Airframe										AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322404	Nose Landing Gear Drag Brace - Restore		HRS		4057.8			0			0
	1159LM50585-1	PLT0332	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		B F GOODRICH AEROSPACE
Airframe											
322405	Nose Landing Gear Trunnion Pin (Left) - Discard		HRS		4057.8			0			0
	1159LM50611-3	PLT0100	AFL		1184		32750	0	32750		0
			MOS		188.2				24 May 2008		AAR LANDING GEAR SERVICES
Airframe											
Notes: 26200 EASA REQUIREMENT											
322406	Nose Landing Gear Trunnion Pins (Left) - Restore		HRS		4057.8			0			0
	1159LM50611-3	PLT0100	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		AAR LANDING GEAR SERVICES
Airframe											
322407	Nose Landing Gear Trunnion Pin (Right) - Discard		HRS		4057.8			0			0
	1159LM50613-3	PLT0138	AFL		1184		32750	0	32750		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
Notes: 26200 EASA REQUIREMENT											
322408	Nose Landing Gear Trunnion Pins (Right) - Restore		HRS		4057.8			0			0
	1159LM50613-3	PLT0138	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
322409	Nose Landing Gear Truss Brace Assembly - Discard		HRS		4057.8			0			0
	1159LM40802-5	PLT1088	AFL		1184		32750	0	32750		0
			MOS		188.2				24 May 2008		
Airframe											
Notes: 26200 EASA REQUIREMENT											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322410	Nose Landing Gear Truss Brace Assembly - Restore		HRS		4057.8			0			0
	1159LM50806-1	PLT0208	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
322411	Nose Landing Gear Upper Drag Brace Pin - Discard		HRS		4057.8			0			0
	1159LM40588-19	PLT1523	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
Notes: 4000 EASA REQUIREMENT											
322412	Nose Landing Gear Drag Brace (Upper Pin) - Restore		HRS		4057.8			0			0
	1159LM40588-19	PLT1523	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe						O/C					
322413	Nose Landing Gear Lower Drag Brace Pin - Discard		HRS		4057.8			0			0
	1159LM50587-3	PLT0106	AFL		1184		20000	0	20000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
Notes: 16000 EASA REQUIREMENT											
322414	Nose Landing Gear Lower Drag Brace Pin - Restore		HRS		4057.8			0			0
	1159LM50587-3	PLT0106	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
322415	Nose Landing Gear Actuator Attach Pins - Discard		HRS		4057.8			0			0
	1159LM40583-15	PLT0067	AFL		1184		32750	0	32750		0
			MOS		188.2			24 May 2008			
Airframe											
Notes: 26200 EASA REQUIREMENT											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322416	Nose Landing Gear Actuator Attach Pins - Restore		HRS		4057.8			0			0
	1159LM40583-15	PLT0067	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		PRECISION MACHINE OF SAVANNAH
Airframe											
322417	Nose Landing Gear Strut / Trunnion Pins - Discard		HRS		4057.8			0			0
	1159LM50568-13	PLT0274	AFL		1184		20000	0	20000		0
			MOS		188.2				24 May 2008		B F GOODRICH AEROSPACE
Airframe											
Notes: 16000 EASA REQUIREMENT											
322418	Nose Landing Gear Strut Trunnion Pins - Restore		HRS		4057.8			0			0
	1159LM50568-13	PLT0274	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		B F GOODRICH AEROSPACE
Airframe											
322419	Nose Landing Gear Upper Torque ARM - Discard		HRS		4057.8			0			0
	1159LM50548-1	PLT0312	AFL		1184		32750	0	32750		0
			MOS		188.2				24 May 2008		B F GOODRICH AEROSPACE
Airframe											
Notes: 26200 EASA REQUIREMENT											
322420	Nose Landing Gear Upper Torque ARM - Restore		HRS		4057.8			0			0
	1159LM50548-1	PLT0312	AFL		1184		5000	0	5000		0
			MOS		188.2				24 May 2008		
Airframe											
322421	Nose Landing Gear Lower Torque ARM - Discard		HRS		4057.8			0			0
	1159LM30553-3	PLT0387	AFL		1184		32750	0	32750		0
			MOS		188.2				24 May 2008		GOODRICH CORPORATION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322422	Nose Landing Gear Lower Torque ARM - Restore		HRS		4057.8			0			0
	1159LM30553-3	PLT0387	AFL		1184		5000	0	5000		0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
Airframe											
322423	Nose Landing Gear Truss Brace Pin (Left Forward) - Removal / Installation		HRS		4057.8			0			0
	1159LM40565-3	PLT0347	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											
322424	Nose Landing Gear Trunnion - Removal / Installation		HRS		4057.8			0			0
	1159LM50690-3	PLT0315	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
Airframe											
322425	Nose Landing Gear Drag Brace - Removal / Installation		HRS		4057.8			0			0
	1159LM50585-1	PLT0332	AFL		1184			0			0
			MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
Airframe											
322426	Nose Landing Gear Truss Brace Pin (Right Forward) - Removal / Installation		HRS		4057.8			0			0
	1159LM40565-3	PLT0346	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											
322427	Nose Landing Gear Truss Brace Pin (Left Aft) - Removal / Installation		HRS		4057.8			0			0
	1159LM40565-3	PLT0302	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											
322428	Nose Landing Gear Truss Brace Pin (Right Aft) - Removal / Installation		HRS		4057.8			0			0
	1159LM40565-3	PLT0354	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322431	Truss Brace Assembly, Nose Landing Gear (Forward)		HRS		4057.8			0			0
	1159LM40802-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
322433	Truss Brace Assembly, Nose Landing Gear (Aft)		HRS		4057.8			0			0
	1159LM40806-7	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GOODRICH CORPORATION
322434	Nose Landing Gear Truss Brace Pin (Left Forward) - Discard		HRS		4057.8			0			0
	1159LM40565-3	PLT0347	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
322435	Nose Landing Gear Truss Brace Pin (Right Forward) - Discard		HRS		4057.8			0			0
	1159LM40565-3	PLT0346	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
322436	Nose Landing Gear Truss Brace Pin (Left Aft) - Discard		HRS		4057.8			0			0
	1159LM40565-3	PLT0302	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
322437	Nose Landing Gear Truss Brace Pin (Right Aft) - Discard		HRS		4057.8			0			0
	1159LM40565-3	PLT0354	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
322440	Downlock Link , Nose Landing Gear (Aft)		HRS		4057.8			0			0
	1159LM40815-3	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
322501	Nose Gear Trunnion Assembly - Detailed Inspection		HRS		4057.8			0			0
			AFL			16000**			16000		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322502	Nose Landing Gear Vertical Drag Brace Fitting Lug - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
322503	Nose Landing Gear Horizontal Drag Brace Fitting Skin Attachment - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
322504	Nose Landing Gear Horizontal Drag Brace Fitting (Forward Attach) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
322601	Nose Gear Electrical Harness - Removal / Installation		HRS		4057.8			0			0
	1159SCAV516-1	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			UNISON INDUSTRIES
			MSC					O/C			
Airframe											
322801	Nose Landing Gear Door Hinges - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
322802	Nose Landing Gear and Doors - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	33	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
322805	Valve, Park/Emerg Brake Bleed		HRS		4057.8			0			0
	1159SCH245-5	2774	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											

Notes: VER BY Q308411

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323001	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		616			3441.8			0
	Bottle (Left) - Removal / Installation		AFL		220			964			0
	1159SCH233-5	31444C1	MOS		19.5			16 Jun 2022			
			MSC							O/C	
Airframe											
323002	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		616			3441.8			0
	Bottle (Left) - (Hydrostatic) Restore		AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	31 May 2025		
			[End Of Month Item]								
Airframe											
Notes: PN: 1159SCH233-5 SN: <NONE>.											
323003	Gage, L/G Dump Bottle Press		HRS		4057.8			0			0
	GP20-24	08-0324325	AFL		1184			0			0
			MOS		188.2			24 May 2008			CUSTOM METAL
			MSC							O/C	WORKS
Airframe											
Notes: VER BY Q308411											
323004	Landing Gear Blow-Down Bottle Relief Valve - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH234-5	V587	MOS		188.2			24 May 2008			EATON
			MSC							O/C	AEROSPACE
Airframe											
Notes: VER BY Q308411											
323005	Landing Gear Selector Panel - Removal / Installation		HRS		4057.8			0			0
	A486-19	803	AFL		1184			0			0
			MOS		188.2			24 May 2008			NORTHERN
			MSC							O/C	FIBER GLASS
Airframe											
SALES INC.											
323006	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		192.1			3865.7			0
	Bottle - Servicing		AFL		78			1106			0
			MOS		7.5			16 Jun 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323008	Nose Gear Hydraulic Flow Regulator - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH218-7	1254	MOS		188.2			24 May 2008			PNEUDRAULICS INC
			MSC					O/C			
Airframe											
323009	Landing Gear Hydraulic Selector / Dump Valve - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCH512-19	EFS0503A	MOS		188.2			24 May 2008			KAISER FLUID TECHNOLOGIES
			MSC					O/C			
Airframe											
Notes: VERIFIED BY Q311721											
323010	Transducer, Gear Emerg Press		HRS		4057.8			0			0
	1159SCAV600-1		AFL		1184			0			0
		HAL3862	MOS		188.2			24 May 2008			GULFSTREAM - LONG BEACH
			MSC					O/C			
Airframe											
Notes: VER BY Q308411											
323011	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		192.1			3865.7			0
	Bottle (Right) - Removal / Installation		AFL		78			1106			0
	1159H50091-21	603-15393	MOS		7.5			15 Jun 2023			
			MSC					O/C			
Airframe											
323012	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		192.1			3865.7			0
	Bottle (Right) - (Hydrostatic) Restore		AFL		78			1106			0
			MOS		7.5			60	15 Jun 2023	30 Jun 2028	
			[End Of Month Item]								HYDRO CHECK
Airframe											
323015	Main Landing Gear Spindle Pin (Left) - Removal /		HRS	TSN:3099.5	957.9			3099.9			0
	Installation		AFL	TSN:871	313			871			0
	1159LM50137	MBM0493	MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323016	Main Landing Gear Spindle Pin (Right) - Removal / Installation		HRS	TSN:3099.5	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159LM50137	MBM0487	MOS	TSN:146	42.3			21 Jul 2020			N/A
			MSC							O/C	
Airframe											
323017	Nose Landing Gear Door Close Line Flow Regulator - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH218-7	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
323021	Main Landing Gear Side Brace (Left) - Removal / Installation		HRS	TSN:3099.5	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159SCL502-11	A861	MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC							O/C	
Airframe											
323022	Main Landing Gear Side Brace (Right) - Removal / Installation		HRS	TSN:3099.5	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159SCL502-11	A862	MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC							O/C	
Airframe											
323023	Main Landing Gear Spindle Pin Freeplay (Left) - Detailed Inspection		HRS		2414			1643.8			0
			AFL		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC							O/C	
Airframe											
323024	Main Landing Gear Spindle Pin Freeplay (Right) - Detailed Inspection		HRS		2414			1643.8			0
			AFL		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC							O/C	
Airframe											
323037	Main Landing Gear Bungee (Left) - Lubrication		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	05 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323038	Main Landing Gear Bungee (Right) - Lubrication		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	05 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]										
323039	Main Landing Gear Bungee (Left) - Removal / Installation		HRS		616			3441.8			0
	1159L50903-1	SN-UNKNOWN	AFL		220			964			0
			MOS		19.8			05 Jun 2022			
Airframe			MSC				O/C				
323040	Main Landing Gear Bungee (Right) - Removal / Installation		HRS		616			3441.8			0
	1159L50903-1	NSN	AFL		220			964			0
			MOS		19.8			05 Jun 2022			
Airframe			MSC				O/C				
323041	Main Gear Door Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159H20264-23	55-5198GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
Airframe			MSC				O/C				
Notes: VERIFIED BY Q112232											
323042	Main Gear Door Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159H20264-24	55-5198GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
Airframe			MSC				O/C				
Notes: VER BY Q112232											
323043	Main Gear Door Actuator End CAP Fitting (Left) - Removal / Installation		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
323044	Main Gear Door Actuator End CAP Fitting (Right) - Removal / Installation		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323045	Main Gear Door Actuator End CAP Fitting (Left) - Discard		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184		9500	0	9500		0
			MOS		188.2				24 May 2008		
Airframe											
323046	Main Gear Door Actuator End CAP Fitting (Right) - Discard		HRS		4057.8			0			0
	PN	SN-UNKNOWN	AFL		1184		9500	0	9500		0
			MOS		188.2				24 May 2008		
Airframe											
323051	Main Gear Uplock Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	1159H20263-11	FAH0602	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
Notes: VERIFIED BY PQ040											
323052	Main Gear Uplock Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	1159H20263-12	FAH0675	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
Notes: VERIFIED BY PQ 040											
323053	Valve, L MLG Uplock Restrictor		HRS		4057.8			0			0
	8R3841-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG											
323054	Valve, R MLG Uplock Restrictor		HRS		4057.8			0			0
	8R3841-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG											
323060	Nose Landing Gear Actuator - Removal / Installation		HRS		4057.8			0			0
	1159H20262-23	55-5198GT	AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
GULFSTREAM SAV PROD-IPT											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323061	Nose Gear Door Actuator - Removal / Installation		HRS		4057.8			0			0
	1159H20261-11	55-4126GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
323062	Actuator, Nose Gear Uplock		HRS		4057.8			0			0
	1159H20260-13	55-4128GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
323063	Actuator, Nose Gear Downlock		HRS		4057.8			0			0
	1159L40840-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH CORPORATION
	Airframe		MSC					O/C			
323066	Nose Landing Gear Retract Actuator ROD End (1159SCL567) - Discard		HRS		4057.8			0			0
	1159SCL567-3	2967	AFL		1184	25000		0	25000		0
			MOS		188.2			24 May 2008			
	Airframe										
Notes: 20000 EASA REQUIREMENT											
323101	Main Landing Gear Uplock Timer (Left) - Removal / Installation		HRS		4057.8			0			0
	1159H20265-5	FAH0778	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q112232											
323102	Main Landing Gear Uplock Timer (Right) - Removal / Installation		HRS		4057.8			0			0
	1159H20265-5	FAH0784	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q112232											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323103	Main Landing Gear Retract Timer (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20265-1	FAH7215	MOS		188.2			24 May 2008			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
Notes: VERIFIED BY Q112232											
323104	Main Landing Gear Retract Timer (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20265-1	FAH7282	MOS		188.2			24 May 2008			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
Notes: VERIFIED BY Q112232											
323105	Valve, Lmg Uplock Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
323106	Valve, Rmg Uplock Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
			MSC								SAV PROD-IPT
Airframe											
323201	Main Gear Door Control Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH231-35	3688	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
323202	Main Gear Door Control Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH231-35	3670	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323203	Valve, Lmg Door Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323204	Valve, Rmg Door Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
	Airframe		MSC					O/C			SAV PROD-IPT
323401	Regulator, L 3000 Psi Flow		HRS		4057.8			0			0
	1159SCH218-5	2207	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS
	Airframe		MSC					O/C			INC
323402	Regulator, R 3000 Psi Flow		HRS		4057.8			0			0
	1159SCH218-5	2217	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS
	Airframe		MSC					O/C			INC
323403	Main Gear Hydraulic Swivels (Left Upper) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159H20270-5	55-5195GT	MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC					O/C			DYNAMICS
										AVIATIONS	
										SERVICES	
323404	Main Gear Hydraulic Swivels (Right Upper) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159H20270-6	55-5198GT	MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC					O/C			DYNAMICS
										AVIATIONS	
										SERVICES	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323405	Main Gear Hydraulic Swivels (Left Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20271-8	55-5198GT	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323406	Main Gear Hydraulic Swivels (Right Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20271-7	55-5198GT	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC								
Airframe											
323501	Nose Landing Gear Uplock Timer - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20265-3	FAH7258	MOS		188.2			24 May 2008			FRISBY AEROSPACE LLC.
			MSC								
Airframe											
Notes: VER BY Q308411											
323502	Nose Landing Gear Retract Timer - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H20265-1	FAH7238	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											
Notes: VER BY Q308411											
323601	Nose Gear Door Control Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH231-35	3741	MOS		188.2			24 May 2008			GULFSTREAM - LONG BEACH
			MSC								
Airframe											
Notes: VER BY Q308411											
323602	Valve, Ng Door ACT Shuttle		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH238-9	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323603	Nose Gear Door Actuator - Discard		HRS		4057.8			0			0
	1159H20261	SN-UNKNOWN	AFL		1184		13000	0	13000		0
			MOS		188.2				24 May 2008		
Airframe											
323700	Nose Landing Gear Sequencing Linkage - Check / Adjustment		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6				13 Jun 2022		
			MSC				O/C				
Airframe											
323701	Nose Gear Uplock Actuator - Removal / Installation		HRS		4057.8			0			0
	1159H20260-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											
323801	Nose Gear Hydraulic Swivel - Removal / Installation		HRS		4057.8			0			0
	7438-4	0543	AFL		1184			0			0
			MOS		188.2				24 May 2008		TELEDYNE
			MSC				O/C				CONTROLS
Airframe											
323802	Valve, Ng Uplock ACT Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
323803	Valve, Ng Actuator Shuttle		HRS		4057.8			0			0
	1159SCH238-9	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
323804	Nose Gear Hydraulic Swivel		HRS		4057.8			0			0
	LSA14-15C4S	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323805	Nose Gear Hydraulic Swivel		HRS		4057.8			0			0
	LSA14-15C4S	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
323806	Nose Gear Hydraulic Swivel		HRS		4057.8			0			0
	LSA15-14J6S	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
323807	Nose Gear Hydraulic Swivel		HRS		4057.8			0			0
	LSA15-14J6S	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
323900	Landing Gear - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3			23 Jul 2020			
	Airframe		MSC					O/C			
323901	Landing Gear Emergency Extension - Operational Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.5	38	36	15 Jun 2023	31 Jul 2026*	31 Aug 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
323902	Landing Gear Emergency Extension Bottle Pressure Gage - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
323903	Handle, Landing Gear Emer Extn		HRS		4057.8			0			0
	159F10825-15	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GULFSTREAM SAV PROD-IPT

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323904	Valve, Gear Dump Bottle Relief		HRS		4057.8			0			0
	1159SCH236-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			NUTEK AEROSPACE CORP
	Airframe		MSC					O/C			
323906	Landing Gear Cycling - Operational Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.5			15 Jun 2023			
	Airframe		MSC					O/C			
323907	Wheel Brakes - Operational Test		HRS		260.2			3797.6			0
			AFL		97			1087			0
			MOS		9			01 May 2023			
	Airframe		MSC					O/C			
323908	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - Discard		HRS		2187.6			1870.2			0
	1159SCH233-5	29682C1	AFL		666			518			0
			MOS		101.3		288	21 Aug 2015 31 Mar 2035			
	Airframe										MANUFACTURE
											[End Of Month Item]
323909	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Discard		HRS		616			3441.8			0
	1159H50091-21	603-15393	AFL		220			964			0
			MOS		20		180	01 Jun 2022 30 Apr 2037			
	Airframe										MANUFACTURE
											[End Of Month Item]
323910	Landing Gear Emergency Extension T-Handle Linkage - General Visual Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020 31 Oct 2026* 30 Nov 2026			
	Airframe										
											[End Of Month Item] [MOS: +1m/-1m]
323911	Landing Gear Emergency Extension Blowdown Bottle Relief Valve, Gage and Filler Assembly - General Visual Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	32	36	29 Aug 2023 30 Sep 2026* 31 Oct 2026			
	Airframe										
											[End Of Month Item] [MOS: +1m/-1m]

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324001	Nose Wheel (Left) - Removal / Installation		HRS		616			3441.8			0
	1159L50400-37	5084FZ	AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324002	Nose Wheel (Right) - Removal / Installation		HRS		616			3441.8			0
	1159L50400-37	5039GC	AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324003	Main Wheel (Left Outboard) - Removal / Installation		HRS		192.1			3865.7			0
	1159L56003-9	5177GC	AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324004	Main Wheel (Left Inboard) - Removal / Installation		HRS		192.1			3865.7			0
	1159L56003-9	5099FY	AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324005	Main Wheel (Right Inboard) - Removal / Installation		HRS		43.4			4014.4			0
	AHA2114	5097LD	AFL		16			1168			0
			MOS		2.5			16 Nov 2023			
	Airframe		MSC					O/C			
Notes: TORQUE WRENCH ID # 0426AOO CAL DUE 11/19TORQUE WRENCH ID # 574055 CAL DUE 9//19TIRE GUAGE # 929008 S/N AL57 CAL DUE 1/4/2020											
324006	Main Wheel (Right Outboard) - Removal / Installation		HRS		616			3441.8			0
	1159L56003-9	5096FY	AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324007	Nose Wheel Bearings (Left) - Inspection / Pack		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324008	Nose Wheel Bearings (Right) - Inspection / Pack		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324009	Main Landing Gear Wheel Bearing (Left Outboard) -		HRS		192.1			3865.7			0
	Inspection / Check		AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
			MSC							O/C	
Airframe											
324010	Main Landing Gear Wheel Bearing (Left Inboard) -		HRS		192.1			3865.7			0
	Inspection / Check		AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
			MSC							O/C	
Airframe											
324011	Main Landing Gear Wheel Bearing (Right Inboard) -		HRS		43.4			4014.4			0
	Inspection / Check		AFL		16			1168			0
			MOS		2.5			16 Nov 2023			
			MSC							O/C	
Airframe											
324012	Main Landing Gear Wheel Bearing (Right Outboard) -		HRS		0			4057.8			0
	Inspection / Check		AFL		0			1184			0
			MOS		.9			04 Jan 2024			
			MSC							O/C	
Airframe											
324014	Nose Tire - Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
			MSC							O/C	
Airframe											
324015	Main Tire Assembly (Left Outboard) - Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC							O/C	
Airframe											
324016	Main Tire Assembly (Right Outboard) - Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC							O/C	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324017	Wheel and Brakes - Functional Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
	Airframe		MSC					O/C			
324018	Nose Wheel Ndt (Left) - Special Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					A/R			
324019	Nose Wheel Ndt (Right) - Special Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					A/R			
324020	Main Wheel Ndt (Left Outboard) - Special Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
	Airframe		MSC					A/R			
324021	Main Wheel Ndt (Left Inboard) - Special Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.7			10 Jun 2023			
	Airframe		MSC					A/R			
324022	Main Wheel Ndt (Right Inboard) - Special Detailed Inspection		HRS		43.4			4014.4			0
			AFL		16			1168			0
			MOS		2.5			16 Nov 2023			
	Airframe		MSC					A/R			
324023	Main Wheel Ndt (Right Outboard) - Special Detailed Inspection		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.7			10 Jan 2024			
	Airframe		MSC					A/R			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324033	Main Tire Assembly (Left Inboard) - Inspection		HRS		751.7			3306.1			0
			AFL		247			937			0
			MOS		23.6			13 Feb 2022			
	Airframe		MSC					O/C			
324034	Main Tire Assembly (Right Inboard) - Inspection		HRS		43.4			4014.4			0
			AFL		16			1168			0
			MOS		2.5			16 Nov 2023			
	Airframe		MSC					O/C			
324040	Nose Tire (Left) - Removal / Installation		HRS		616			3441.8			0
	1159SCL507-1	21320491	AFL		220			964			0
			MOS		19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324041	Nose Tire (Right) - Removal / Installation		HRS		616			3441.8			0
	1159SCL507-1	20610359	AFL		220			964			0
			MOS	TSN:2	19.6			12 Jun 2022			
	Airframe		MSC					O/C			
324042	Main Tire (Left Outboard) - Removal / Installation		HRS		192.1			3865.7			0
	350K02-1	23415040	AFL		78			1106			0
			MOS	TSN:6	7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324043	Main Tire (Left Inboard) - Removal / Installation		HRS		192.1			3865.7			0
	350K02-1	23405046	AFL		78			1106			0
			MOS	TSN:6	7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324044	Main Tire (Right Inboard) - Removal / Installation		HRS		43.4			4014.4			0
	1159SCL506-1	22735090	AFL		16			1168			0
			MOS	TSN:10	2.5			16 Nov 2023			
	Airframe		MSC					O/C			
324045	Main Tire (Right Outboard) - Removal / Installation		HRS		0			4057.8			0
	1159SCL506-1	31325241	AFL		0			1184			0
			MOS	TSN:4	.7			10 Jan 2024			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324101	Main Wheel Brakes (Left) - Bleeding Procedures		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.5			17 Jul 2021			
	Airframe		MSC					O/C			
324102	Main Wheel Brakes (Right) - Bleeding Procedures		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
	Airframe		MSC					O/C			
324103	Brake Augmenter Valve - Removal / Installation		HRS		4057.8			0			0
	39-801	512	AFL		1184			0			0
			MOS		188.2			24 May 2008			FINISHMASTER INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311721											
324104	Brake System Hydraulic Fuses - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
324105	Brake Assembly (Left Outboard) - Removal / Installation		HRS	TSN:3099.5	957.9			3099.9			0
	1159SCL504-5	5016GD	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.3			21 Jul 2020			N/A
	Airframe		MSC					O/C			
324106	Brake Assembly (Left Inboard) - Removal / Installation		HRS		957.9			3099.9			0
	1159SCL504-5	059CF	AFL		313			871			0
			MOS		42.3			21 Jul 2020			N/A
	Airframe		MSC					O/C			
324107	Brake Assembly (Right Inboard) - Removal / Installation		HRS		260.2			3797.6			0
	1159SCL504-5	5090DP	AFL		97			1087			0
			MOS		9			01 May 2023			
	Airframe		MSC					O/C			
324108	Brake Assembly (Right Outboard) - Removal / Installation		HRS		134.1			3923.7			0
	1159SCL504-5	053CK	AFL		44			1140			0
			MOS		5.4			20 Aug 2023			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324109	Parking / Emergency Brake Accumulator Pressure Gage - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
324110	Brake System Temperature Sensor (Left Outboard) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
			AFL	TSN:1102	82			1102			0
	1159SCL510-1	H2342	MOS	TSN:180	8.3			23 May 2023			
			MSC					O/C			
Airframe											
324111	Brake System Temperature Sensor (Left Inboard) - Removal / Installation		HRS	TSN:3828.1	229.7			3828.1			0
			AFL	TSN:1102	82			1102			0
	1159SCL510-1	H2343	MOS	TSN:180	8.3			23 May 2023			
			MSC					O/C			
Airframe											
324112	Brake System Temperature Sensor (Right Inboard) - Removal / Installation		HRS	TSN:3797.6	260.2			3797.6			0
			AFL	TSN:1087	97			1087			0
	1159SCL510-1	H1643	MOS	TSN:180	9			01 May 2023			
			MSC					O/C			
Airframe											
324113	Brake System Temperature Sensor (Right Outboard) - Removal / Installation		HRS	TSN:3923.7	134.1			3923.7			0
			AFL	TSN:1140	44			1140			0
	1159SCL510-1	H2341	MOS	TSN:182	5.4			20 Aug 2023			N/A
			MSC					O/C			
Airframe											
324114	Indicator, Brake Pressure(Ckpt 162LCP636		HRS		4057.8			0			0
	08041689		AFL		1184			0			0
			MOS		188.2			24 May 2008			DILLON - MORGANS
			MSC					O/C			
Airframe											
324115	Gage, Brake Accum. Pressure GP20-24		HRS		4057.8			0			0
	08-0324313		AFL		1184			0			0
			MOS		188.2			24 May 2008			CUSTOM METAL WORKS
			MSC					O/C			
Airframe											

Notes: VER BY Q308411

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324116	Dual Brake Metering Valve (Left) - Removal / Installation		HRS		2943.7			1114.1			0
	1159SCL473-3	0998	AFL		858			326			0
			MOS		137			30 Aug 2012			TACTAIR FLUID
	Airframe		MSC					O/C			CONTROLS INC
324117	Dual Brake Metering Valve (Right) - Removal / Installation		HRS		2943.7			1114.1			0
	1159SCL473-3	1002	AFL		858			326			0
			MOS		137			30 Aug 2012			TACTAIR FLUID
	Airframe		MSC					O/C			CONTROLS INC
324118	Brake Shuttle Valve (Forward) - Removal / Installation		HRS		4057.8			0			0
	1159SCH223-5	3815	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC					O/C			DYNAMICS
Notes: VERIFIED BY Q311721											
324119	Brake Shuttle Valve (Aft Auxiliary / Alternate) - Removal / Installation		HRS		4057.8			0			0
	1159SCH223-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC					O/C			DYNAMICS
Notes: VER BY Q308411											
324120	Parking / Emergency Brake Accumulator - Removal / Installation		HRS		2943.7			1114.1			0
	1159SCH206-5	60211-3384NA	AFL		858			326			0
			MOS		137			30 Aug 2012			PNEUDRAULICS
	Airframe		MSC					O/C			INC
324121	Brake Accumulator Pressure Dump Valve - Removal / Installation		HRS		4057.8			0			0
	1159SCH245-5	2789	AFL		1184			0			0
			MOS		188.2			24 May 2008			PARKER
	Airframe		MSC					O/C			HANNIFIN
Notes: VER BY Q308411											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324122	Parking / Emergency Brake Selector Valve - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	64560-3	1440	MOS		188.2			24 May 2008			ARC COM
			MSC								FABRICS
Airframe											
Notes: Q308411											
324123	Parking / Emergency Brake Accumulator Pressure Gauge - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH241-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PROFESSIONAL
			MSC								AIRCRAFT ACCESSORIES
Airframe											
324124	Parking / Emergency Brake Accumulator - Servicing		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
Airframe											
324125	Brake Pressure Transmitter Switch (Left Outboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH240-7	HAL5506	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
324126	Brake Pressure Transmitter Switch (Left Inboard) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH240-7	HAL5467	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
324127	Brake System Hydraulic Fuse (Upper Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3520	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324128	Brake System Hydraulic Fuse (Upper Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3516	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
Notes: VERIFIED BY PQ 040											
324129	Brake System Hydraulic Fuse (Lower Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3515	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
Notes: VERIFIED BY PQ040											
324130	Brake System Hydraulic Fuse (Lower Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3517	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
Notes: VERIFIED BY PQ 040											
324131	Brake Transducer Shuttle Valve (No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50362-5	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
324132	Brake Transducer Shuttle Valve (No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159H50362-3	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC						O/C		
Airframe											
324133	Mechanical Brake Linkage AT Rudder Pedal - General Visual Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324135	Brake Pressure Transmitter Switch (Right Inboard) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCH240-7	HAL5520	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ 040											
324136	Brake Pressure Transmitter Switch (Right Outboard) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCH240-7	HAL5531	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ 040											
324137	Limiter, #1 Brake Flow		HRS		4057.8			0			0
	11226-6-1-7		AFL	87003	1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
324138	Limiter, #2 Brake Flow		HRS		4057.8			0			0
	11226-6-1-7		AFL	86983	1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY Q112232											
324139	Limiter, #3 Brake Flow		HRS		4057.8			0			0
	11226-6-1-7		AFL	89477	1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY Q112232											
324140	Limiter, #4 Brake Flow		HRS		4057.8			0			0
	11226-6-1-7		AFL	87027	1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY Q112232											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324141	Parking Brake Pressure Transducer - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV600-1	HAL3876	MOS		188.2			24 May 2008			GULFSTREAM - LONG BEACH
			MSC								
Airframe											
Notes: VER BY Q308411											
324142	Fuse, Rh Emergency Brake		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3911	MOS		188.2			24 May 2008			EATON AEROSPACE
			MSC								
Airframe											
324143	Fuse, Lh Emergency Brake		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH261-5	3904	MOS		188.2			24 May 2008			EATON AEROSPACE
			MSC								
Airframe											
324144	Main Landing Gear Brake Assembly (Left Outboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
Airframe											
324145	Main Landing Gear Brake Assembly (Left Inboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
Airframe											
324146	Main Landing Gear Brake Assembly (Right Inboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
Airframe											
324147	Main Landing Gear Brake Assembly (Right Outboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.2			25 May 2023			
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324149	Shuttle, R Aft Aux Alt Brake		HRS		2943.7			1114.1			0
	REMOVED	REMOVED	AFL		858			326			0
			MOS		137			30 Aug 2012			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
324151	Brake Metering Valves (Left) - Bleeding Procedure		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137			31 Aug 2012			
	Airframe		MSC					O/C			
324152	Brake Metering Valves (Right) - Bleeding Procedure		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137			31 Aug 2012			
	Airframe		MSC					O/C			
324153	Brake Rotor Drive Clip (Left Outboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
	Airframe		MSC					O/C			
324154	Brake Rotor Drive Clip (Left Inboard) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3			21 Jul 2020			
	Airframe		MSC					O/C			
324155	Brake Rotor Drive Clip (Right Inboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
	Airframe		MSC					O/C			
324156	Brake Rotor Drive Clip (Right Outboard) - Detailed Inspection		HRS		229.7			3828.1			0
			AFL		82			1102			0
			MOS		8.3			23 May 2023			
	Airframe		MSC					N/A			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324183	Nose Wheel and Tire Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
324184	Nose Wheel and Tire Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	PN	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
324201	Antiskid Control Box - Removal / Installation		HRS		4057.8			0			0
	1159SCL501-11	508	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	DUNLOP AEROSPACE BRAKING SYSTEM
Airframe											
324202	Antiskid - Functional Test		HRS		1909.3			2148.5			0
			AFL		573			611			0
			MOS		88.1			29 Sep 2016			
			MSC							O/C	
Airframe											
324203	Antiskid Control Valve - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4			20 Aug 2023			
			MSC							O/C	
Airframe											
324205	Antiskid Control Valve (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCL501-3	926	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ040											
324206	Antiskid Control Valve (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCL501-3	924	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324207	Filter, Anti-Skid Control Valve (Left)		HRS		4057.8			0			0
	27446	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
324208	Filter, Anti-Skid Control Valve (Right)		HRS		4057.8			0			0
	27446	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
324211	Main Wheel and Tire Assembly (Left Outboard) - Removal / Installation		HRS	TSN:3828.1	192.1			3865.7			0
			AFL	TSN:1102	78			1106			0
	1159L56003-9	5177GC	MOS	TSN:180	7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324212	Main Wheel and Tire Assembly (Left Inboard) - Removal / Installation		HRS		192.1			3865.7			0
			AFL		78			1106			0
	1159L56003-9	5099FY	MOS		7.7			10 Jun 2023			
	Airframe		MSC					O/C			
324213	Main Wheel and Tire Assembly (Right Inboard) - Removal / Installation		HRS		43.4			4014.4			0
			AFL		16			1168			0
	1159L56003-9	5097LD	MOS		2.5			16 Nov 2023			N/A
	Airframe		MSC					O/C			
324214	Main Wheel and Tire Assembly (Right Outboard) - Removal / Installation		HRS		0			4057.8			0
			AFL		0			1184			0
	1159L56003-9	5096FY	MOS		.7			10 Jan 2024			
	Airframe		MSC					O/C			
324220	Wheel Speed Monitor Unit - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCL501-9	519	MOS		188.2			24 May 2008			HYDRO-AIRE, INC.
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324221	Wheel Speed Transducer (Left Outboard) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159SCL501-51	0288	MOS	TSN:100	88.3			23 Sep 2016			HYDRO-AIRE, INC.
			MSC								
Airframe											
324222	Wheel Speed Transducer (Left Inboard) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159SCL501-51	0281	MOS	TSN:100	88.3			23 Sep 2016			HYDRO-AIRE, INC.
			MSC								
Airframe											
324223	Wheel Speed Transducer (Right Inboard) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159SCL501-51	0283	MOS	TSN:100	88.3			23 Sep 2016			HYDRO-AIRE, INC.
			MSC								
Airframe											
324224	Wheel Speed Transducer (Right Outboard) - Removal / Installation		HRS	TSN:2148.4	1909.4			2148.4			0
			AFL	TSN:611	573			611			0
	1159SCL501-51	0293	MOS	TSN:100	88.3			23 Sep 2016			HYDRO-AIRE, INC.
			MSC								
Airframe											
324291	Valve, Lh Brake Shuttle		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH223-5	2388	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ040											
324292	Valve, Rh Brake Shuttle		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCH223-5	2177	MOS		188.2			24 May 2008			
			MSC								
Airframe											
Notes: VERIFIED BY PQ 040											
324303	Parking / Emergency Brake - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.4		36	20 Aug 2023 31 Aug 2026 30 Sep 2026			
Airframe [End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324304	Parking / Emergency Brake Cable Assembly - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	2603860-002	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM
			MSC								DALLAS
Airframe											
324305	Brake Wear Indicator (Left Outboard) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
											[HRS: +50/-50]
Airframe											
324306	Brake Wear Indicator (Left Inboard) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
											[HRS: +50/-50]
Airframe											
324307	Brake Wear Indicator (Right Inboard) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
											[HRS: +50/-50]
Airframe											
324308	Brake Wear Indicator (Right Outboard) - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			17 Aug 2023			
											[HRS: +50/-50]
Airframe											
324401	Brake Control System Hydraulic Fuse (Left, Outboard No. 1) - Operational Check		HRS		260.2			3797.6			0
			AFL		97			1087			0
			MOS		9		125	01 May 2023	31 Oct 2033	30 Nov 2033	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
324402	Brake Control System Hydraulic Fuse (Left, Inboard No. 2) - Operational Check		HRS								0
			AFL								0
			MOS				125		31 Dec 2030	31 Jan 2031	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
324403	Brake Control System Hydraulic Fuse (Right, Inboard No. 3) - Operational Check		HRS								0	
			AFL								0	
			MOS				125		31 Dec 2030	31 Jan 2031		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
324404	Brake Control System Hydraulic Fuse (Right, Outboard No. 4) - Operational Check		HRS		134.1			3923.7				0
			AFL		44			1140				0
			MOS		5.4		125	20 Aug 2023	31 Jan 2034	28 Feb 2034		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
324601	Brake Pressure Transducer (Right) - Operational Check		HRS		4057.8			0				0
			AFL		1184			0				0
			MOS		188.2			24 May 2008				
Airframe			MSC				O/C					
324700	Brake Temperature Indication - Functional Test		HRS		134.1			3923.7				0
			AFL		44			1140				0
			MOS		4.9			04 Sep 2023				
Airframe			MSC				O/C					
325001	Nose Wheel Steering Unit - Removal / Installation		HRS		2543.1			1514.7				0
	1159SCL500-61	0397D	AFL		756			428				0
			MOS		119.5			16 Feb 2014			EATON	
Airframe			MSC				O/C				AEROSPACE	
325002	Tiller Assembly - Removal / Installation		HRS		4057.8			0				0
	1159SCL500-55	0586	AFL		1184			0				0
			MOS		188.2			24 May 2008			EATON	
Airframe			MSC				O/C				AEROSPACE	
325003	Steering - Functional Test		HRS		957.9			3099.9				0
			AFL		313			871				0
			MOS		42.3			23 Jul 2020				
Airframe			MSC				O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
325004	Nose Wheel Steering System - Autorig Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
325101	Rudder Pedal Input Transducer Assembly - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCL500-17	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
325201	Nose Wheel Steering Unit - Lubrication		HRS		2176.4			1881.4			0
			AFL		663		2100	521	2621		0
			MOS		100.8			07 Sep 2015			
Airframe											
325202	Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.4		24	20 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
325204	Nose Wheel Steering Collar Assembly - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCL500-23	SN-UNKNOWN	MOS		188.2			24 May 2008			EATON AEROSPACE
	Airframe		MSC					O/C			
325205	Nose Wheel Steering Collar Assembly - Discard		HRS		4057.8			0			0
			AFL		1184		16000	0	16000		0
	1159SCL500-23	SN-UNKNOWN	MOS		188.2			24 May 2008			
Airframe											
326105	Switch, Nose Gear Door		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV452-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326201	Main Gear Weight on Wheels Switch (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV513-1	SN-UNKNOWN	MOS		188.2			24 May 2008			GOODRICH CORPORATION
			MSC					O/C			
Airframe											
326202	Main Gear Weight on Wheels Switch (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV513-1	SN-UNKNOWN	MOS		188.2			24 May 2008			GOODRICH CORPORATION
			MSC					O/C			
Airframe											
326203	Nose Landing Gear Weight on Wheels Switch - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV514-1	SN-UNKNOWN	MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
			MSC					O/C			
Airframe											
326209	Main Landing Gear Weight on Wheels Cable Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV521-3	NSN	MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
			MSC					O/C			
Airframe											
326210	Main Landing Gear Weight on Wheels Cable Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAV521-4	NSN	MOS		188.2			24 May 2008			B F GOODRICH AEROSPACE
			MSC					O/C			
Airframe											
326230	Nose Landing Gear Weight on Wheels System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
327000	Brake Metering Valve Retrofit Program		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
328101	Left Nose Landing Gear Door - Removal / Installation		HRS	TSN:3200.1	857.7			3200.1			0
	1159B50510-49	SN-UNKNOWN	AFL	TSN:904	280			904			0
			MOS	TSN:158	30.3			21 Jul 2021			N/A
	Airframe		MSC							O/C	
328102	Right Nose Landing Gear Door - Removal / Installation		HRS	TSN:3200.1	857.7			3200.1			0
	1159B50510-50	SN-UNKNOWN	AFL	TSN:904	280			904			0
			MOS	TSN:158	30.3			21 Jul 2021			N/A
	Airframe		MSC							O/C	
33 - Lights											
330005	Interior Lights--OPS Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
330006	Exterior Lights--OPS Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC							O/C	
330901	Switch Panel #1		HRS		4025.2			32.6			0
	2501-1-088	319DT	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC							O/C	
330902	Switch Panel #2		HRS		4025.2			32.6			0
	2501-3-047	319JY	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC							O/C	
330903	Switch Panel #3		HRS		1654.7			2403.1			0
	2501-3-063	319DM	AFL		493			691			0
			MOS		68.7			10 May 2018			AIRSHOW
	Airframe		MSC							O/C	
330904	Switch Panel #4		HRS		4025.2			32.6			0
	2501-1-029	319LY	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330905	Switch Panel #5		HRS		4025.2			32.6			0
	2501-1-134	319GR	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330906	Switch Panel #6		HRS		4025.2			32.6			0
	2501-1-006	319KR	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330907	Switch Panel #7		HRS		4025.2			32.6			0
	2501-1-007	319GX	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330908	Switch Panel #8		HRS		4025.2			32.6			0
	2501-1-006	319KV	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330909	Switch Panel #9		HRS		4025.2			32.6			0
	2501-1-065	319KH	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330910	Switch Panel #10		HRS		4025.2			32.6			0
	2501-1-087	319JX	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330911	Switch Panel #11		HRS		4025.2			32.6			0
	2501-1-320	319LB	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330912	Switch Panel #12		HRS		4025.2			32.6			0
	2501-1-009	319LD	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330913	Switch Panel #13		HRS		4025.2			32.6			0
	2501-1-007	319KW	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330914	Switch Panel #14		HRS		4025.2			32.6			0
	2501-1-006	319KT	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330915	Switch Panel #15		HRS		4025.2			32.6			0
	2501-1-030	319FP	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330916	Switch Panel #16		HRS		4025.2			32.6			0
	2501-1-015	319FL	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330917	Switch Panel #17		HRS		4025.2			32.6			0
	2501-1-030	319FR	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330918	Switch Panel #18		HRS		4025.2			32.6			0
	2501-1-087	319JW	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330919	Switch Panel #19		HRS		4025.2			32.6			0
	2501-1-320	319KY	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330920	Switch Panel #20		HRS		4025.2			32.6			0
	2501-1-009	319LC	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330921	Switch Panel #21		HRS		4025.2			32.6			0
	2501-2-155	319KB	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330922	Switch Panel #22		HRS		4025.2			32.6			0
	2501-2-074	319LJ	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330923	Switch Panel #23		HRS		4025.2			32.6			0
	2501-2-075	319WL	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330924	Switch Panel #24		HRS		4025.2			32.6			0
	2501-2-029	319KK	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330925	Switch Panel #25		HRS		4025.2			32.6			0
	2501-2-044	319LF	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330926	Switch Panel #26		HRS		4025.2			32.6			0
	2501-2-045	319FN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330927	Switch Panel #27		HRS		4025.2			32.6			0
	2501-2-030	319LH	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330928	Switch Panel #28		HRS		1654.7			2403.1			0
	2501-2-030	319LG	AFL		493			691			0
			MOS		68.7			10 May 2018			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330929	Switch Panel #29		HRS		4025.2			32.6			0
	2501-2-002	319KM	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330930	Switch Panel #30		HRS		4025.2			32.6			0
	2501-2-004	319LR	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330931	Switch Panel #31		HRS		4025.2			32.6			0
	2501-2-002	319KP	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330932	Switch Panel #32		HRS		4025.2			32.6			0
	2501-2-075	319WM	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330933	Switch Panel #33		HRS		4025.2			32.6			0
	2501-2-110	319KJ	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330934	Switch Panel #34		HRS		4025.2			32.6			0
	2501-4-008	319GT	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330935	Switch Panel #35		HRS		4025.2			32.6			0
	2501-2-241	319DK	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330936	Switch Panel #36		HRS		4025.2			32.6			0
	2501-2-029	319KL	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330937	Switch Panel #37		HRS		4025.2			32.6			0
	2501-2-045	319FN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330938	Switch Panel #38		HRS		4025.2			32.6			0
	2501-2-002	319KN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330939	Switch Panel #39		HRS		4025.2			32.6			0
	2501-2-096	319DJ	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330950	Switch Panel #50		HRS		4025.2			32.6			0
	2501-1-321	319GP	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330951	Switch Panel #51		HRS		4025.2			32.6			0
	2501-1-032	319GV	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
330952	Switch Panel #52		HRS		4025.2			32.6			0
	2501-1-031	319KG	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AIRSHOW
	Airframe		MSC					O/C			
331001	Cockpit Annunciator Dim and Test Control Unit - Removal / Installation		HRS		4057.8			0			0
	1159SCAV526-7	0617	AFL		1184			0			0
			MOS		188.2			24 May 2008			ELECTRONIC CABLE SPECIALISTS
	Airframe		MSC					O/C			
Notes: VERIFIED BY: PQ092											
331010	Tray, Annunciator Lts Test		HRS		4057.8			0			0
	71-1046-1	1133	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHELTON INC
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332051	Light Assy, #1 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332052	Light Assy, #2 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332053	Light Assy, #3 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332054	Light Assy, #4 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332055	Light Assy, #5 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332056	Light Assy, #6 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332057	Light Assy, #7 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332058	Light Assy, #8 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332059	Light Assy, #9 Aisle		HRS		4025.2			32.6			0
	8291-1	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			LUMINESCENT
	Airframe		MSC					O/C			SYS
332104	Power Supply, #4 Protected		HRS		4025.2			32.6			0
	AL-2000	52718	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			
332105	Power Supply, #5 Protected		HRS		4025.2			32.6			0
	AL-2000	52719	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			
332106	Power Supply, #6 Protected		HRS		4025.2			32.6			0
	AL-2000	52720	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			
332141	Power Supply, #1 Aft Lav Prot		HRS		4025.2			32.6			0
	AL-2000	52721	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			
332142	Power Supply, #2 Aft Lav Prot		HRS		4025.2			32.6			0
	AL-2000	52722	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			
332191	Dimmer, #1 Cbn Lights		HRS		4025.2			32.6			0
	AL-2022	3590	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AEROSPACE LTG
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332201	Light Assy, #1 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4279	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332202	Light Assy, #2 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4255	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332203	Light Assy, #3 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4269	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332204	Light Assy, #4 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4275	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332205	Light Assy, #5 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4282	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332206	Light Assy, #6 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000906	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332207	Light Assy, #7 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000903	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332208	Light Assy, #8 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4280	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332209	Light Assy, #9 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000859	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332210	Light Assy, #10 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000880	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332211	Light Assy, #11 Cabin		HRS		1654.7			2403.1			0
	7801-090-500420	3359	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332212	Light Assy, #12 Cabin		HRS		1654.7			2403.1			0
	7801-090-500420	3478	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332213	Light Assy, #13 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4281	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332214	Light Assy, #14 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4278	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332215	Light Assy, #15 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4289	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								
332216	Light Assy, #16 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3347	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332217	Light Assy, #17 Cabin		HRS		1654.7			2403.1			0
	7801-090-500420	3483	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332218	Light Assy, #18 Cabin		HRS		1654.7			2403.1			0
	7801-090-500420	3354	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332219	Light Assy, #19 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000875	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332220	Light Assy, #20 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000857	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332221	Light Assy, #21 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000877	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332222	Light Assy, #22 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000883	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332223	Light Assy, #23 Cabin		HRS		1654.7			2403.1			0
	7801-285-500420	032000822	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332224	Light Assy, #24 Cabin		HRS		1654.7			2403.1			0
	7801-090-500420	3484	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332225	Light Assy, #25 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4467	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332226	Light Assy, #26 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4460	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332227	Light Assy, #27 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4468	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332228	Light Assy, #28 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3353	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332229	Light Assy, #29 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3349	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332230	Light Assy, #30 Cabin		HRS		1654.7			2403.1			0
	7801-105-500420	3220	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332231	Light Assy, #31 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4276	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332232	Light Assy, #32 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4277	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332233	Light Assy, #33 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3348	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332234	Light Assy, #34 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3412	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332235	Light Assy, #35 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3414	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332236	Light Assy, #36 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3351	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332237	Light Assy, #37 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4461	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332238	Light Assy, #38 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4458	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332239	Light Assy, #39 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4462	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332240	Light Assy, #40 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4463	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332241	Light Assy, #41 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4466	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332242	Light Assy, #42 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3342	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332243	Light Assy, #43 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4464	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332244	Light Assy, #44 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4465	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332245	Light Assy, #45 Cabin		HRS		1654.7			2403.1			0
	7801-105-500420	3382	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332246	Light Assy, #46 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3340	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332247	Light Assy, #47 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3343	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332248	Light Assy, #48 Cabin		HRS		1654.7			2403.1			0
	7801-105-500420	3223	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332249	Light Assy, #49 Cabin		HRS		1654.7			2403.1			0
	7801-105-500420	3224	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332250	Light Assy, #50 Cabin		HRS		1654.7			2403.1			0
	7801-120-500420	3345	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332253	Controller, Galley #1		HRS		4057.8			0			0
	1054-1-1/1054-751-12	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
332307	Light Assy, #1 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10387	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332310	Light Assy, #2 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10412	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332313	Light Assy, #3 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10389	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332316	Light Assy, #4 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10390	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332319	Light Assy, #5 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10391	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332322	Light Assy, #6 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10392	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332325	Light Assy, #7 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10393	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332328	Light Assy, #8 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10394	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332331	Light Assy, #9 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10395	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332334	Light Assy, #10 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10396	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332337	Light Assy, #11 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10397	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332340	Light Assy, #12 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10406	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332343	Light Assy, #13 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10435	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332346	Light Assy, #14 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10436	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332349	Light Assy, #15 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10437	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332352	Light Assy, #16 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10438	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332355	Light Assy, #17 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10439	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332358	Light Assy, #18 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10400	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332361	Light Assy, #19 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10401	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332364	Light Assy, #20 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10402	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332367	Light Assy, #21 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10403	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332370	Light Assy, #22 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10404	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332373	Light Assy, #23 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10405	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332376	Light Assy, #24 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10408	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332379	Light Assy, #25 Cabin Spot		HRS		4025.2			32.6			0
	5500-06	10409	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332384	Light Assy, Fwd Lav Spot		HRS		4025.2			32.6			0
	5500-02	10433	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332385	Light Assy, #1 Crew Private		HRS		1654.7			2403.1			0
	7801-300-500420	4283	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332386	Light Assy, #2 Crew Private		HRS		1654.7			2403.1			0
	7801-285-500420	032000870	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332387	Light Assy, #3 Crew Private		HRS		1654.7			2403.1			0
	7801-090-500420	3480	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332388	Light Assy, #4 Crew Private		HRS		1654.7			2403.1			0
	7801-090-500420	3346	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332389	Light Assy, #5 Crew Private		HRS		1654.7			2403.1			0
	7801-300-500420	4274	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332390	Light Assy, #6 Crew Private		HRS		1654.7			2403.1			0
	7801-285-500420	032000871	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332391	Light Assy, #7 Crew Private		HRS		1654.7			2403.1			0
	7801-090-500420	3351	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332392	Light Assy, #8 Crew Private		HRS		1654.7			2403.1			0
	7801-090-500420	3358	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332393	Light Assy #26 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10410	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332394	Light Assy #27 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10411	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332395	Light Assy #28 Cabin Spot		HRS		4025.2			32.6			0
	5500-02	10388	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332398	Light Assy, #1 Aft Lav Spot.		HRS		4025.2			32.6			0
	5500-02	10434	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			B.E. AEROSPACE
	Airframe		MSC					O/C			
332400	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3218	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332401	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3373	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332402	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3372	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332403	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3232	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332404	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3219	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332405	Light Assy		HRS		1654.7			2403.1			0
	7801-105-500420	3368	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
332485	Light, Aft R/H Closet		HRS		4057.8			0			0
	5620-10	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			BE AEROSPACE
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332486	Light, Aft L/H Closet		HRS		4057.8			0			0
	5620-10	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			BE AEROSPACE
	Airframe		MSC					O/C			
332487	Light, Fwd L/H Closet		HRS		4057.8			0			0
	5620-10	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			BE AEROSPACE
	Airframe		MSC					O/C			
332906	Adaptor, Inverter RH3		HRS		4057.8			0			0
	1305-1-5	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIRSHOW INC.
	Airframe		MSC					O/C			
332920	Light Assy#51CABIN		HRS		1654.7			2403.1			0
	7801-300-500420	4457	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
332921	Light Assy#52 Cabin		HRS		1654.7			2403.1			0
	7801-300-500420	4459	AFL		493			691			0
			MOS		65.7			09 Aug 2018			B.E. AEROSPACE
	Airframe		MSC					O/C			
333102	Baggage Compartment Utility Light Assembly No. 1 -		HRS	TSN:3099.9	957.9			3099.9			0
	Removal / Installation (A/C 5033 &AMP;		AFL	TSN:871	313			871			0
	Subsequent Excluding 5037)		MOS	TSN:146	42.5			17 Jul 2020			N/A
	2JA004531011	08SS1504	MSC					O/C			
Airframe											
334001	Landing Light Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
	50-0137-9	2187	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334002	Landing Light Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
	50-0137-10	2096	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			GRIMES AEROSPACE
Notes: VERIFIED BY PQ 040											
334007	Nose Wheel Taxi Lights Lamp (Left) - Replacement		HRS		1654.7			2403.1			0
	TAE0528-1	682	AFL		493			691			0
			MOS		65.7			09 Aug 2018			HONEYWELL
	Airframe		MSC					O/C			GRIMES AEROSPACE
334008	Nose Wheel Taxi Lights Lamp (Center) - Replacement		HRS		1654.7			2403.1			0
	TAE0528-1	686	AFL		493			691			0
			MOS		65.7			09 Aug 2018			HONEYWELL
	Airframe		MSC					O/C			GRIMES AEROSPACE
334009	Nose Wheel Taxi Lights Lamp (Right) - Replacement		HRS		1654.7			2403.1			0
	TAE0528-1	688	AFL		493			691			0
			MOS		65.7			09 Aug 2018			HONEYWELL
	Airframe		MSC					O/C			GRIMES AEROSPACE
334010	Exterior Lights - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
334025	Anticollision Strobe Light Power Supply Unit (Left) - Removal / Installation		HRS		4057.8			0			0
	60-4943-1	1637	AFL		1184			0			0
			MOS		188.2			24 May 2008			TRANSTAR
	Airframe		MSC					O/C			METALS
Notes: VERIFIED BY PQ040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334026	Anticollision Strobe Light Power Supply Unit (Right) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	60-4943-1	1641	MOS		188.2			24 May 2008			TRANSTAR METALS
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ 040											
334027	Anticollision Strobe Light Power Supply Unit (Tail) -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	60-4943-1	1716	MOS		188.2			24 May 2008			TRANSTAR METALS
			MSC					O/C			
Airframe											
Notes: VERIFIED BY PQ514											
334039	Navigation Light Lens (Left) - Removal / Installation		HRS		4057.8			0			0
	1159WP56414-1 SN-UNKNOWN		AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
334040	Navigation Light Lens (Right) - Removal / Installation		HRS		4057.8			0			0
	1159WP56414-2 SN-UNKNOWN		AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC					O/C			
Airframe											
334045	Navigation Position Light Assembly (Tail Upper) -		HRS		3705			352.8			0
	Removal / Installation		AFL		1083			101			0
	30-3041-7	NSN	MOS		169.3			21 Dec 2009			HONEYWELL GRIMES AEROSPACE
			MSC					O/C			
Airframe											
334046	Navigation Position Light Assembly (Tail Lower) -		HRS		1425.6			2632.2			0
	Removal / Installation		AFL		423			761			0
	30-3041-7	NSN	MOS	TSN:6	57.7			08 Apr 2019			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334050	Navigation (Position) Light Lens - Detailed Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.1		24	28 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
334065	Navigation Position Lights (Tail Upper) - Led Replacement		HRS		192.1			3865.7			0
	30-3041-9	6663	AFL		78			1106			0
			MOS	TSN:49	5.9			02 Aug 2023			
Airframe			MSC				O/C				
334066	Navigation Position Lights (Tail Lower) - Led Replacement		HRS		1425.6			2632.2			0
	30-3041-9	6504	AFL		423			761			0
			MOS	TSN:6	57.7			08 Apr 2019			
Airframe			MSC				O/C				
334095	Wing-Tip Anticollision Strobe Light Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
	30-2446-3	2187	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe			MSC				O/C				
Notes: VERIFIED BY PQ040											
334096	Wing-Tip Anticollision Strobe Light Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
	30-2446-3	2079	AFL		1184			0			0
			MOS		188.2			24 May 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe			MSC				O/C				
Notes: VERIFIED BY PQ 040											
334098	Beacon Anticollision Light Assembly - Removal / Installation		HRS		4057.8			0			0
	30-2140-9	1668	AFL		1184			0			0
			MOS		188.2			24 May 2008			AVIATION AVIONICS & INSTRUMENTS CORP
Airframe			MSC				O/C				
Notes: VERIFIED BY Q311644											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334099	Anticollision Strobe Lights - Operational Test		HRS		917.1			3140.7			0
			AFL		303			881			0
			MOS		35.6			12 Feb 2021			
	Airframe		MSC					O/C			
334121	Landing Lights - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
334122	Taxi Lights - Operational Test		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
334123	Wing Tip Flood / Taxi Lights - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
334201	Anti-Collision Strobe - OPS Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
334203	Anticollision Beacon Light - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
334204	Navigational Lights - Operational Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		5.9			02 Aug 2023			
	Airframe		MSC					O/C			
334205	Tail Navigation Position Lights (Upper) - Led Discard		HRS		3705		8000	352.8	8352.8		0
	30-3041-9		AFL		1083			101			0
	1508		MOS		169.3			21 Dec 2009			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334206	Tail Navigation Position Lights (Lower) - Led Discard		HRS		1425.6		8000	2632.2	10632.2		0
	30-3041-9	6504	AFL		423			761			0
			MOS	TSN:6	57.7			08 Apr 2019			
Airframe											
334213	Wing Navigation Position Lights (Left Outboard) - Led Discard		HRS		3705		7000	352.8	7352.8		0
	30-2900-1	3526	AFL		1083			101			0
			MOS		169.3			21 Dec 2009			
Airframe											
334214	Wing Navigation Position Lights (Right Outboard) - Led Discard		HRS		4057.8		7000	0	7000		0
	30-2900-2	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											
334215	Wing Navigation Position Lights (Left Inboard) - Led Discard		HRS		1483.1		7000	2574.7	9574.7		0
	30-2900-1	10187	AFL		435			749			0
			MOS	TSN:8	58.8			07 Mar 2019			
Airframe											
334216	Wing Navigation Position Lights (Right Inboard) - Led Discard		HRS		4057.8		7000	0	7000		0
	30-2900-2	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											
334403	Logo Lights - Operational Check		HRS		292.3			3765.5			0
			AFL		107			1077			0
			MOS		9.6			12 Apr 2023			
Airframe											
335001	Battery Power Supply, Emergency Floorpath Lighting (No. 1)		HRS		4057.8			0			0
	100865	C04310	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
335002	Battery Power Supply, Emergency Floorpath Lighting (No. 2)		HRS		4025.2			32.6			0
			AFL		1170			14			0
	BA5-0933-901	C04390	MOS		184.6			12 Sep 2008			BRUCE
			MSC								
Airframe											
335003	Battery Power Supply, Emergency Floorpath Lighting (No. 3)		HRS		4057.8			0			0
			AFL		1184			0			0
	100865	C04320	MOS		188.2			24 May 2008			
			MSC								
Airframe											
335006	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 1) - Restore		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		18	28 Aug 2023	28 Feb 2025	31 Mar 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: 2013-BR SN: <NONE>.											
335007	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 2) - Restore		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		18	28 Aug 2023	28 Feb 2025	31 Mar 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: 2013-BR SN: <NONE>.											
335008	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 3) - Restore		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		18	28 Aug 2023	28 Feb 2025	31 Mar 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: 2013-BR SN: <NONE>.											
335016	Emergency Floorpath Lighting Battery Pack No. 1 - Removal / Installation		HRS	TSN:75.8	134.1			3923.7			0
			AFL	TSN:34	44			1140			0
	2013-BR	B16157	MOS	TSN:10	5.1			28 Aug 2023			N/A
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
335017	Emergency Floorpath Lighting Battery Pack No. 2 - Removal / Installation		HRS	TSN:75.8	134.1			3923.7			0
			AFL	TSN:34	44			1140			0
	2013-BR	B16215	MOS	TSN:6	5.1			28 Aug 2023			N/A
			MSC								
Airframe											
335018	Emergency Floorpath Lighting Battery Pack No. 3 - Removal / Installation		HRS	TSN:75.8	134.1			3923.7			0
			AFL	TSN:34	44			1140			0
	2013-BR	B16220	MOS	TSN:6	5.1			28 Aug 2023			N/A
			MSC								
Airframe											
335020	Cabin Emergency Lighting - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1			29 Aug 2023	31 Aug 2024	30 Sep 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
335101	L Overwing Emergency Egress Light (Fwd) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
			MSC								
Airframe											
335102	L Overwing Emergency Egress Light (Center) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
			MSC								
Airframe											
335103	L Overwing Emergency Egress Light (Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
335104	R Overwing Emergency Egress Light (Fwd) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
Airframe			MSC				O/C				
335105	R Overwing Emergency Egress Light (Center) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
Airframe			MSC				O/C				
335106	R Overwing Emergency Egress Light (Aft) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	30-2362-1	SN-UNKNOWN	MOS		188.2			24 May 2008			HONEYWELL GRIMES AEROSPACE
Airframe			MSC				O/C				
34 - Navigation											
341001	Radio Altimeter Antenna (No. 1 - Transmit) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DMPN19-2-1	4754	MOS	TSN:146	42.3			23 Jul 2020			N/A
Airframe			MSC				O/C				
341002	Radio Altimeter Antenna (No. 1 - Receive) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM PN19-2-1	4752	MOS	TSN:146	42.3			23 Jul 2020			N/A
Airframe			MSC				O/C				
341003	Radio Altimeter Antenna (No. 2 - Transmit) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM-PN19-2-1	4745	MOS	TSN:146	42.3			23 Jul 2020			N/A
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341004	Radio Altimeter Antenna (No. 2 - Receive) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DMPN19-2-1	4748	MOS	TSN:146	42.3			23 Jul 2020			N/A
			MSC							O/C	
Airframe											
341005	Radio Altimeter System - Operational Check		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	-4	12	04 Jun 2023	31 May 2024*	30 Jun 2024	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
341006	Radio Altimeter System - Zero Altitude Adjustment		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	-4	12	04 Jun 2023	31 May 2024*	30 Jun 2024	
											[End Of Month Item] [MOS: +1m/-1m]
Airframe											
341010	Radio Altimeter R/T No. 1 - Removal / Installation		HRS		4057.8			0			0
	7001840-932	0804E603	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ308. MOD: AG, J-AD											
341011	Radio Altimeter R/T No. 2 - Removal / Installation		HRS		4057.8			0			0
	7001840-932	0804E625	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
			MSC							O/C	
Airframe											
Notes: VERIFIED BY PQ308. MOD: AG, J-AD											
341020	AIR Data Module No. 1 - Removal / Installation		HRS		2414			1643.8			0
	HG1153CA04	08032957	AFL		716			468			0
			MOS		111.8			05 Oct 2014			HONEYWELL
			MSC							O/C	INTERNATIONAL
Airframe											
341021	AIR Data Module No. 2 - Removal / Installation		HRS		2280.7			1777.1			0
	HG1153CA04	08032958	AFL		691			493			0
			MOS		105.7			08 Apr 2015			HONEYWELL
			MSC							O/C	INTERNATIONAL
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341022	AIR Data Module No. 3 - Removal / Installation		HRS		2414			1643.8			0
	HG1153CA04	08032976	AFL		716			468			0
			MOS		111.8			05 Oct 2014			
	Airframe		MSC					O/C			
341023	AIR Data Module No. 1 - Certification		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe		[End Of Month Item]								CALIBRATION
Notes: PN: HG1153CA04 SN: <NONE>.											
341024	AIR Data Module No. 2 - Certification		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe		[End Of Month Item]								CALIBRATION
Notes: PN: HG1153CA04 SN: <NONE>.											
341025	AIR Data Module No. 3 - Certification		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe		[End Of Month Item]								CALIBRATION
Notes: PN: HG1153CA04 SN: <NONE>.											
341029	Digital AIR Data Computing System - Functional Check		HRS		2280.7			1777.1			0
			AFL		691			493			0
			MOS		105.7			08 Apr 2015			
	Airframe		MSC					O/C			
341030	Pitot / Static System - Reconnect Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
341095	Total AIR Temperature Probe - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341098	Total AIR Temperature Probe No. 1 - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	102LK2AG	A78589	MOS		188.2			24 May 2008			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
Notes: VERIFIED BY Q300454											
341099	Total AIR Temperature Probe No. 2 - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	102LK2AG	A78696	MOS		188.2			24 May 2008			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
Notes: VERIFIED BY Q300454											
341100	Pitot / Static Probe (Left Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	0856TK1	250595	MOS		188.2			24 May 2008			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
Notes: Q306884											
341101	Pitot / Static Probe (Right Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	0856TK2	248900	MOS		188.2			24 May 2008			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
Notes: Q306884											
341102	Pitot / Static Probe (Left Upper) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	0856TK3	247795	MOS		188.2			24 May 2008			GOODRICH
			MSC					O/C			SENSOR SYSTEMS
Airframe											
Notes: Q306884											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341103	Pitot / Static Probe (Right Upper) - Removal / Installation		HRS		4057.8			0			0
	0856TK4	249054	AFL		1184			0			0
			MOS		188.2			24 May 2008			GOODRICH
	Airframe		MSC					O/C			SENSOR SYSTEMS
Notes: Q306884											
341304	AIR Data System No. 1 - Functional / Leak Test		HRS		192.1			3865.7			0.08
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe							[End Of Month Item]			
341305	AIR Data System No. 2 - Functional / Leak Test		HRS		192.1			3865.7			0.08
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe							[End Of Month Item]			
Notes: PN: HG1153CA04 SN: <NONE>.											
341306	AIR Data System No. 3 - Functional / Leak Test		HRS		192.1			3865.7			0.08
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe							[End Of Month Item]			
Notes: PN: HG1153CA04 SN: <NONE>.											
341307	Standby Pitot / Static System - Functional / Leak Test		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		12	06 Jun 2023	30 Jun 2024		
	Airframe							[End Of Month Item]			
Notes: PN: 501-1860-0102 SN: <NONE>.											
342001	Standby Ebdi - Removal / Installation		HRS		4057.8			0			0
	501-1871-0101	1369	AFL		1184			0			0
		1.0	MOS		188.2			24 May 2008			HUGHES
	Airframe		MSC					O/C			INDUSTRIAL
Notes: MOD:2,6,7,9											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342005	Integrated Standby Flight Display - Removal / Installation		HRS		4057.8			0			0
	501-1860-0102	1735	AFL		1184			0			0
		2.2	MOS		188.2			24 May 2008			L-3
	Airframe		MSC					O/C			COMMUNICATIO NS AVIONICS SYSTEMS INC.
Notes: MOD:1,2,4-9,12,13,15											
342015	Detachable Configuration Module		HRS		4057.8			0			0
	501-1870-25	1851	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
342602	Display Drive Unit - Removal / Installation		HRS		4057.8			0			0
	7023173-902	08020500	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
342603	Ohu - Removal / Installation		HRS		4057.8			0			0
	7023171-901	08020489	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: PQ040											
342604	Combiner Assembly - Removal / Installation		HRS		4057.8			0			0
	7023172-907	08020863	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
342608	Visual Guidance System - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
342621	Forward Looking Infrared Camera Assembly (Evs) - Preventative Maintenance		HRS		4057.8			0			0
	48534-101	591	AFL		1184			0			0
			MOS		188.2			24 May 2008			KOLLSMAN, INC. OVERHAUL
	Airframe		MSC					O/C			

Notes: DECLARED ON CONDITION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342623	Enhanced Vision System Processor - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	48535-101	575	MOS		188.2			24 May 2008			4 FLIGHT
			MSC								
Airframe											
342624	Enhanced Vision System Sapphire Window Assembly - Functional Test		HRS		4057.8		10000	0	10000	10050	0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			KOLLSMAN, INC.
			MSC								
Airframe	[HRS: +50/-50]										
342625	Evs Window Heat Controller - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	49322-101	569	MOS		188.2			24 May 2008			TAPIS CORP
			MSC								
Airframe	O/C										
342629	Evs Shroud		HRS		4057.8			0			0
			AFL		1184			0			0
	50526-1	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe	O/C										
342633	Enhanced Vision System - Functional Check		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC								
Airframe	O/C										
342650	Forward Looking Infrared Window Assembly - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
			AFL	TSN:691	493			691			0
	48856-101	725	MOS	TSN:123	65.7			09 Aug 2018			KOLLSMAN, INC.
			MSC								
Airframe	O/C										
Notes: B871583 0HRS. VER. BY PQ514											
342701	Integrated Standby Flight Display / Magnetometer - Compensation Adjustment		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe	O/C										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342702	Magnetometer - Removal / Installation		HRS		3145.2			912.6			0
	501-1826-01	2402	AFL		920			264			0
			MOS		145.4			19 Dec 2011			L-3
	Airframe		MSC					O/C			COMMUNICATIO NS AVIONICS SYSTEMS INC.
342710	Integrated Standby Instrument System - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
342715	Integrated Standby Flight Display / Magnetometer - Calibration Check		HRS		3145.2			912.6			0
			AFL		920			264			0
			MOS		145.4			19 Dec 2011			
	Airframe		MSC					O/C			
342801	Standby Electronic Bearing Distance Indicator - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
343001	Marker Beacon Antenna - Removal / Installation		HRS		0			4057.8			0
	S35-2000-10	106-0449	AFL		0			1184			0
			MOS		.8			07 Jan 2024			N/A
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ026											
343003	#1 Diplexer, Marker Beacon		HRS		4057.8			0			0
	DMH21-1	36497	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIL SYSTEMS INC.
	Airframe		MSC					O/C			
343004	Diplexer, Glide Scope Power		HRS		4057.8			0			0
	SSPD-332-3	1416	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
343005	Power Divider, Marker Beacon		HRS		4057.8			0			0
	SSPD-113-39		AFL		1184			0			0
	519		MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
343006	#2 Diplexer, Marker Beacon		HRS		4057.8			0			0
	DMH21-1		AFL		1184			0			0
	36926		MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ026											
343101	Glide Slope Antenna - Removal / Installation		HRS		4057.8			0			0
	S41422-2		AFL		1184			0			0
	3961		MOS		188.2			24 May 2008			CASTLE METALS/A.M. CASTLE & CO
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ308											
344001	Inertial Reference Unit No. 1 - Removal / Installation		HRS		1654.7			2403.1			0
	HG2100AB07		AFL		493			691			0
	56018378		MOS		65.7			09 Aug 2018			AEROCONTROLE X GROUP
	Airframe		MSC					O/C			
344002	Inertial Reference Unit No. 2 - Removal / Installation		HRS		1654.7			2403.1			0
	HG2100AB07		AFL		493			691			0
	56018398		MOS		65.7			09 Aug 2018			AEROCONTROLE X GROUP
	Airframe		MSC					O/C			
344003	Inertial Reference Unit No. 3 - Removal / Installation		HRS		1654.7			2403.1			0
	HG2100AB07		AFL		493			691			0
	56018260		MOS		65.7			09 Aug 2018			AEROCONTROLE X GROUP
	Airframe		MSC					O/C			
344004	Inertial Refrence Sys-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344006	Fan, #2 lru		HRS		4057.8			0			0
	26009688-102	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
344015	Lasertrak Nav Display-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
344025	Irs MODE Select Panel - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
344101	Weather Radar Receiver / Transmitter - Removal / Installation		HRS		4057.8			0			0
	7021450-801	08038338	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: PQ093											
344105	Weather Radar Controller No. 1 - Removal / Installation		HRS		4057.8			0			0
	7006921-825	08033597	AFL		1184			0			0
			MOS		188.2			24 May 2008			REBLING PLASTICS
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
344106	Weather Radar Controller No. 2 - Removal / Installation		HRS		543			3514.8			0
	7006921-825	03032914	AFL		204			980			0
			MOS		17.2			25 Aug 2022			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q310229											
344107	Weather Radar Antenna - Removal / Installation		HRS		4057.8			0			0
	7021451-424	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
344111	Weather Radar System - Operational Check		HRS		543			3514.8			0	
	Airframe		AFL		204			980			0	
			MOS			17.2			25 Aug 2022			
			MSC									
344151	Lightning Sensor Processor Unit - Removal / Installation		HRS		4025.2			32.6			0	
	Airframe	7011822-904	07081737	AFL		1170		14			0	
				MOS		184.6			12 Sep 2008		HONEYWELL	
				MSC								
344152	Lightning Sensor Antenna - Removal / Installation		HRS		4025.2			32.6			0	
	Airframe	7014062-901	07031297	AFL		1170		14			0	
				MOS		184.6			12 Sep 2008		HONEYWELL	
				MSC								
344153	Lightning Sensor Controller - Removal / Installation		HRS		4025.2			32.6			0	
	Airframe	7012738-905	07010663	AFL		1170		14			0	
				MOS		184.6			12 Sep 2008		HONEYWELL	
				MSC								
344201	Egpws Module No. 1 - Removal / Installation		HRS		4057.8			0			0	
	Airframe	7028419-1904	08042172	AFL		1184		0			0	
				MOS		188.2			24 May 2008		HONEYWELL	
				MSC								
344202	Egpws Module No. 2 - Removal / Installation		HRS		4057.8			0			0	
	Airframe	7028419-1904	08042162	AFL		1184		0			0	
				MOS		188.2			24 May 2008		HONEYWELL	
				MSC								
344204	Egpws - Database Update		HRS		192.1			3865.7			0	
	Airframe			AFL		78		1106			0	
				MOS		7.5			16 Jun 2023			
				MSC								
344206	Inertial Reference System No. 1 - Operational Check		HRS		1654.7			2403.1			0	
	Airframe			AFL		493		691			0	
				MOS		65.7			09 Aug 2018			
				MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344207	Enhanced Ground Proximity Windshear Warning System -		HRS		4057.8			0			0
	Return to Service Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
344209	Inertial Reference System No. 3 - Operational Check		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
344301	TCAS Computer - Removal / Installation		HRS		2943.7			1114.1			0
	7517900-55020	20008613	AFL		858			326			0
	A-G	A-B	MOS	TSN:52	136.6			11 Sep 2012			AVGROUP
	Airframe		MSC					O/C			ATLANTA
344302	TCAS - Operational Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3			23 Jul 2020			
	Airframe		MSC					O/C			
344303	TCAS Antenna No. 1 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	7514060-902	10563	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.3			23 Jul 2020			N/A
	Airframe		MSC					O/C			
344304	TCAS Antenna No. 2 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	DM NI50-9-2	10563	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.4			20 Jul 2020			N/A
	Airframe		MSC					O/C			
345001	VOR / Localizer Antenna (Left) - Removal / Installation		HRS		4057.8			0			0
	DMN4-17-1/P	25588	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIL SYSTEMS
	Airframe		MSC					O/C			INC.

Notes: VERIFIED BY Q310447

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345002	VOR / Localizer Antenna (Right) - Removal / Installation		HRS		4057.8			0			0
	DMN4-17-1/P	25598	AFL		1184			0			0
			MOS		188.2			24 May 2008			AIL SYSTEMS INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q310447											
345005	Very High Frequency Omnidirectional Range / Instrument		HRS		4057.8			0			0
	Landing System / Data Link Module No. 1 - Removal /		AFL		1184			0			0
	Installation		MOS		188.2			24 May 2008			HONEYWELL
	7026202-801	08043396	MSC					O/C			
Airframe											
345006	Very High Frequency Omnidirectional Range / Instrument		HRS		4057.8			0			0
	Landing System / Data Link Module No. 2 - Removal /		AFL		1184			0			0
	Installation		MOS		188.2			24 May 2008			HONEYWELL
	7026202-801	08043391	MSC					O/C			
Airframe											
345011	Very High Frequency Omnidirectional Range / Instrument		HRS		0			4057.8			0
	Landing System / Data Link - Functional Check		AFL		0			1184			0
			MOS		.8			07 Jan 2024			
	Airframe		MSC					O/C			
345020	Navigation / Communication System - Functional Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
345060	McdU Software Load (Warranty Managed Program)		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.7			09 Sep 2015			
	Airframe		MSC					O/C			
345101	DME Module No. 1 - Removal / Installation		HRS	TSN:3076.3	981.5			3076.3			0
	7510184-855	0804D820	AFL	TSN:869	315			869			0
			MOS	TSN:141	47.1			27 Feb 2020			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345102	DME Module No. 2 - Removal / Installation		HRS	TSN:3076.3	981.5			3076.3			0
	7510184-855	0711D275	AFL	TSN:869	315			869			0
			MOS	TSN:141	47.1			27 Feb 2020			
	Airframe		MSC					O/C			
345105	DME Antenna No. 1 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	DM NI50-9-2	10862	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.4			20 Jul 2020			N/A
	Airframe		MSC					O/C			
345106	DME Antenna No. 2 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	DM NI50-9-2	10861	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.4			20 Jul 2020			N/A
	Airframe		MSC					O/C			
345109	DME #1 - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
345110	DME #2 - Functional Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
345115	DME - Functional Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.4			20 Jul 2021			
	Airframe		MSC					O/C			
345201	ADF Receiver No. 1 - Removal / Installation		HRS		857.7			3200.1			0
	7510114-855	08044236	AFL		280			904			0
			MOS		30.4			20 Jul 2021			N/A
	Airframe		MSC					O/C			
345202	ADF Receiver No. 2 - Removal / Installation		HRS		857.7			3200.1			0
	7510114-855	1209G359	AFL		280			904			0
			MOS		30.4			20 Jul 2021			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345203	ADF System No. 1 - Operational Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.1			27 Jul 2020			
	Airframe		MSC					O/C			
345204	ADF System No. 2 - Operational Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.1			27 Jul 2020			
	Airframe		MSC					O/C			
345205	ADF Antenna No. 1 - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
	7510300-901	0802E222	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.3			23 Jul 2020			N/A
	Airframe		MSC					O/C			
345206	ADF Antenna No. 2 - Removal / Installation		HRS		957.9			3099.9			0
	7510300-901	1106J411	AFL		313			871			0
			MOS		42.1			27 Jul 2020			N/A
	Airframe		MSC					O/C			
345301	ATC MODE S Diversity Transponder Module No. 1 - Removal / Installation		HRS		1654.7			2403.1			0
	7517402-970	1010G681	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
Notes: MOD: U,W,Z,AA											
345302	ATC MODE S Diversity Transponder Module No. 2 - Removal / Installation		HRS		1654.7			2403.1			0
	7517402-970	1111H757	AFL		493			691			0
			MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
Notes: MOD: U,W,Z,AA											
345305	ATC (No. 1) - Functional Test / Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		24	06 Jun 2023	30 Jun 2025		
	Airframe		[End Of Month Item]								CALIBRATION
Notes: PN: 7517400-950 SN: <NONE>											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345306	ATC (No. 2) - Functional Test / Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8		24	06 Jun 2023	30 Jun 2025		
Airframe				[End Of Month Item]							CALIBRATION
Notes: PN: 7517400-950 SN: <NONE>.											
345315	ATC MODE S Antenna No. 1 (Upper) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM N150-9-2	10528	MOS	TSN:146	42.3			23 Jul 2020			N/A
Airframe			MSC				O/C				
345316	ATC MODE S Antenna No. 2 (Upper) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM N150-9-2	10502	MOS	TSN:146	42.3			23 Jul 2020			N/A
Airframe			MSC				O/C				
345317	ATC MODE S Antenna No. 1 (Lower) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM NI50-9-2	10549	MOS	TSN:146	42.4			20 Jul 2020			N/A
Airframe			MSC				O/C				
345318	ATC MODE S Antenna No. 2 (Lower) - Removal / Installation		HRS	TSN:3100.1	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	DM NI50-9-2	10727	MOS	TSN:146	42.4			20 Jul 2020			N/A
Airframe			MSC				O/C				
345801	GPS Antenna No. 1 - Removal / Installation		HRS		539.2			3518.6			0
	S67-1575-237	825-1834	AFL		197			987			0
			MOS	TSN:91	16.7			10 Sep 2022			
Airframe			MSC				O/C				
345802	GPS Antenna No. 2 - Removal / Installation		HRS	TSN:696.8	957.9			3099.9			0
			AFL	TSN:180	313			871			0
	S67-1575-237	825-1811	MOS		42.1			27 Jul 2020			N/A
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345810	GPS - Operational Check		HRS		539.2			3518.6			0
			AFL		197			987			0
			MOS		16.7			10 Sep 2022			
	Airframe		MSC					O/C			
345813	Global Positioning System Module No. 1 - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	245-604067-100	05121251	MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
345814	Global Positioning System Module No. 2 - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	245-604067-100	05030796	MOS		65.7			09 Aug 2018			
	Airframe		MSC					O/C			
346001	Multifunction Control Display Unit No. 1 - Removal / Installation		HRS		540.2			3517.6			0
			AFL		199			985			0
	A50A000-00-450	A4503103	MOS		16.7			08 Sep 2022			
	Airframe		MSC					O/C			
346002	Multifunction Control Display Unit No. 2 - Removal / Installation		HRS		540.2			3517.6			0
			AFL		199			985			0
	A50A000-00-450	A4504833	MOS		16.7			08 Sep 2022			
	Airframe		MSC					O/C			
346003	Multifunction Control Display Unit No. 3 - Removal / Installation		HRS		540.2			3517.6			0
			AFL		199			985			0
	A50A000-00-450	A4505204	MOS		16.7			08 Sep 2022			
	Airframe		MSC					O/C			
346005	FMS - Software Verification		HRS		2020.5			2037.3			0
			AFL		612			572			0
			MOS		92.6			12 May 2016			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
346025	FMS Nav Database - Update		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.3			23 Jan 2024	21 Feb 2024		
	Airframe		MSC					O/C			EXPIRATION
Notes: NAV DB UPDATED. EXP DATE 17 MAI 2023											
346040	Data Management Unit - Removal / Installation		HRS		4057.8			0			0
	7031051-901	08031554	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ514											
35 - Oxygen											
350001	Oxygen System - Operational Test		HRS		292.3			3765.5			0
			AFL		107			1077			0
			MOS		9.6			12 Apr 2023			
	Airframe		MSC					O/C			
350002	Crew / Passenger Oxygen System Check Valves - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		72	23 Sep 2008	31 Mar 2027	30 Apr 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351001	Crew Oxygen System (Pilot) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351002	Crew Oxygen System (Copilot) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351003	Crew Oxygen System (Observer) - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	[End Of Month Item]								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351011	Crew Oxygen Mask (Pilot) - Restore		HRS		1189.2			2868.6			0
	MC10-15-158	SE18891	AFL		361			823			0
			MOS		52.6		72	12 Sep 2019	01 Sep 2025		IN EROS CORPORATION EXPIRATION
Airframe											
351012	Crew Oxygen Mask (Copilot) - Restore		HRS		1189.2			2868.6			0
	MC10-15-158	SE79334	AFL		361			823			0
			MOS		52.6		72	12 Sep 2019	01 Sep 2025		IN EROS CORPORATION EXPIRATION
Airframe											
351013	Crew Oxygen Mask (Observer) - Restore		HRS		1189.2			2868.6			0
	MC10-15-158	SE79312	AFL		361			823			0
			MOS		52.6		72	12 Sep 2019	01 Sep 2025		IN EROS CORPORATION EXPIRATION
Airframe											
351021	Oxygen Mask and Regulator Stowage Box (Pilot) -		HRS		1189.2			2868.6			0
	Removal / Installation		AFL		361			823			0
	MC10-15-158	SE18891	MOS		52.6			12 Sep 2019			IN EROS CORPORATION
			MSC							O/C	
Airframe											
351022	Oxygen Mask and Regulator Stowage Box (Copilot) -		HRS		1189.2			2868.6			0
	Removal / Installation		AFL		361			823			0
	MC10-15-158	SE79334	MOS		52.6			12 Sep 2019			IN EROS CORPORATION
			MSC							O/C	
Airframe											
351023	Observer Oxygen Mask and Regulator Stowage Box -		HRS		1189.2			2868.6			0
	Removal / Installation		AFL		361			823			0
	MC10-15-158	SE79312	MOS		52.6			12 Sep 2019			IN EROS CORPORATION
			MSC							O/C	
Airframe											
351101	Crew Oxygen Quantity Gage - Removal / Installation		HRS		4057.8			0			0
	163LCP81	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM
			MSC							O/C	BRN SPARES IPT
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351102	Crew Oxygen Servicing Pressure Gage - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P24094	SN-UNKNOWN	MOS		188.2			24 May 2008			HORIZON AEROSPACE LLC
			MSC					O/C			
Airframe											
351110	Crew Oxygen Mask / Regulator / Box Assembly (Pilot) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
351111	Crew Oxygen Mask / Regulator / Box Assembly (Copilot) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
351112	Crew Oxygen Mask / Regulator / Box Assembly (Observer) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		36	16 Jun 2022	30 Jun 2025	31 Jul 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
351201	Crew Oxygen Cylinder (No. 1) - Discard		HRS		616			3441.8			0
	805983-15	C17060904	AFL		220			964			0
			MOS		19.5		180	16 Jun 2022	31 May 2032		
	[End Of Month Item]										
Airframe											
Notes: VERFIED Q310932											
351202	Passenger Oxygen Cylinder (No. 2) - Discard		HRS		1735.4			2322.4			0
	805983-15	ALT842-3706	AFL		520			664			0
			MOS		76.6		180	11 Sep 2017	31 May 2032		AV OX INC
	[End Of Month Item]										
Airframe											
Notes: VERFIED Q310932											
351206	Crew Oxygen Low-Pressure Switch - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		72	16 Jun 2022	30 Jun 2028	31 Jul 2028	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351207	Passenger Oxygen Low Pressure Switch - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		72	16 Jun 2022	30 Jun 2028	31 Jul 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
351211	Crew Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		60	16 Jun 2022	31 Mar 2027		
	Airframe		[End Of Month Item]								
Notes: PN: 805983-15 SN: ALT842-661.											
351212	Passenger Oxygen Bottle (No. 2) - (Hydrostatic) Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		60	16 Jun 2022	30 Jun 2027		
	Airframe		[End Of Month Item]								
Notes: PN: 805983-15 SN: ALT842-3706.											
351221	Crew Oxygen Cylinder and Regulator Assembly - Removal / Installation		HRS		616			3441.8			0
	805983-15 C17060904		AFL		220			964			0
			MOS		19.9			04 Jun 2022			
	Airframe		MSC O/C								
351222	Passenger Oxygen Cylinder (No. 2) - Removal / Installation		HRS		616			3441.8			0
	805983-15 ALT842-3706		AFL		220			964			0
			MOS		19.5			16 Jun 2022			
	Airframe		MSC O/C								
351230	Crew Oxygen Pressure Transducer - Removal / Installation		HRS		4057.8			0			0
	CZ92A5-9 SN-UNKNOWN		AFL		1184			0			0
			MOS		188.2			24 May 2008			CYTEC ENGINEERED MATERIALS
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352003	Passenger Oxygen System (Auto / Manual MODE) - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5			16 Jun 2022			
			MSC					O/C			
Airframe											
352004	Passenger Oxygen Drop-Down Mask Assemblies - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	32	36	29 Aug 2023	30 Sep 2026*	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
352006	Passenger Oxygen System - Flight Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
352009	Passenger Oxygen System (Auto / Manual MODE) - Functional Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	32	36	29 Aug 2023	30 Sep 2026*	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
352013	Crew Oxygen Low-Pressure Switch (No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P24029	2609	MOS		188.2			24 May 2008			PACIFIC PRECISION PRODUCTS
			MSC					O/C			
Airframe											
352014	Passenger Oxygen Control Panel - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	412040-11	0872	MOS		188.2			24 May 2008			ADAMS RITE AEROSPACE
			MSC					O/C			
Airframe											
Notes: Q306884											
352015	Indicator , Pax Oxygen(Cockpit		HRS		4057.8			0			0
			AFL		1184			0			0
	163LCP75	SN-UNKNOWN	MOS		188.2			24 May 2008			HORIZON AEROSPACE LLC
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352016	Passenger Oxygen Pressure Transducer - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	CZ92A5-9	SN-UNKNOWN	MOS		188.2			24 May 2008			CYTEC
	Airframe		MSC					O/C			ENGINEERED MATERIALS
352017	Passenger Oxygen Low-Pressure Switch (No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P24029	2616	MOS		188.2			24 May 2008			PACIFIC
	Airframe		MSC					O/C			PRECISION PRODUCTS
352101	Presentation Unit #1 Oxygen		HRS		4025.2			32.6			0
	833-610-15	2682	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352102	Presentation Unit #2 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08060070	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352103	Presentation Unit #3 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030137	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352104	Presentation Unit #4 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030148	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352105	Presentation Unit #5 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030135	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352106	Presentation Unit #6 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030136	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352107	Presentation Unit #7 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M07110067	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352108	Presentation Unit #8 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M07110071	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352109	Presentation Unit #9 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030144	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352110	Presentation Unit #10 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030149	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352111	Presentation Unit #11 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08060074	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352112	Presentation Unit #12 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08060071	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	
352113	Presentation Unit #13 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030142	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC							O/C	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352114	Presentation Unit #14 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030166	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352115	Presentation Unit #15 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030141	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352116	Presentation Unit #16 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030134	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352117	Presentation Unit #17 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030143	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352118	Presentation Unit #18 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030147	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352119	Presentation Unit #19 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030146	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352120	Presentation Unit, Jumpseat		HRS		4025.2			32.6			0
	833-801-03	D07120116	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352121	Presentation Unit Galley		HRS		4025.2			32.6			0
	833-610-16	M08060073	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352122	Presentation Unit Aft Lav		HRS		4025.2			32.6			0
	833-610-16	M08060068	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352123	Presentation Unit Fwd Lav		HRS		4025.2			32.6			0
	833-610-16	M08060067	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352125	Presentation Unit #20 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08030145	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352126	Presentation Unit #21 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08060069	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352127	Presentation Unit #22 Oxygen		HRS		4025.2			32.6			0
	833-610-15	M08060072	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352128	Presentation Unit #23 Oxygen		HRS		4025.2			32.6			0
	833-610-14	M08030140	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			SCOTT
	Airframe		MSC					O/C			
352501	Outlet, #1 Therapeutic Oxygen		HRS		4025.2			32.6			0
	02C40T01-2C	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			O2 CORP
	Airframe		MSC					O/C			
352506	Therapeutic Oxygen System (Outlet No. 1) - Functional Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	32	36	29 Aug 2023	30 Sep 2026*	31 Oct 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352511	Mask, #1 Therapeutic Oxygen		HRS		4025.2			32.6			0
	O2C52T08-4	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			O2
	Airframe		MSC					O/C			CORPORATION
352516	Therapeutic Oxygen Mask (No. 1) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	32	36	29 Aug 2023	30 Sep 2026*	31 Oct 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
353001	Portable Oxygen Bottle (No. 1) - Removal / Installation		HRS	TSN:1505.7	192.1			3865.7			0
	5600-9M6A-F30AN	P17062971	AFL	TSN:438	78			1106			0
			MOS	TSN:70	7.9			04 Jun 2023			
	Airframe		MSC					O/C			
353002	Portable Oxygen Bottle and Mask Assembly (No. 1) - Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.9	35	12	04 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
353003	Portable Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		60	16 Jun 2022	30 Jun 2027		
	Airframe							[End Of Month Item]			HYDRO CHECK
353004	Portable Oxygen System (No. 1 Bottle) - Operational Test		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.6		36	13 Jul 2021	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
353005	Portable Oxygen Bottle Mask (No. 1) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
353016	Portable Oxygen Mask (No. 1) - Restore		HRS		2202.2			1855.6			0
	10800A2F	20031	AFL		672			512			0
			MOS		102.5			17 Jul 2015			AVOX SYSTEM, INC.
	Airframe		MSC					O/C			OVERHAUL
36 - Pneumatic											
360001	Pneumatic Distribution-Func Ck		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
360002	L Servo Press Reg/Motor-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
360003	R Servo Press Reg/Motor-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
360011	Total Temperature Probe Valve - Removal / Installation		HRS		4057.8			0			0
	320154-4-1	1828	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
361001	Bleed AIR Controller (Left) - Removal / Installation		HRS		2971.8			1086			0
	1151582-6	1151582-01987	AFL		866			318			0
			MOS		138.2			26 Jul 2012			HONEYWELL
	Airframe		MSC					O/C			
361002	Bleed AIR Controller (Right) - Removal / Installation		HRS		4057.8			0			0
	1151582-6	1151582-02279	AFL		1184			0			0
			MOS		188.2			24 May 2008			HONEYWELL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361101	High-Pressure Shut-Off Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3291298-2	935	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361102	High-Pressure Shut-Off Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3291298-2	936	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361103	High-Pressure Stage 5 AIR Nonreturn Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3202752-1	1025	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361104	High-Pressure Stage 5 AIR Nonreturn Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3202752-1	1033	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361105	Bleed AIR Pressure Regulating and Shut-Off Valve (Left) - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	3215662-2	929	MOS		65.7			09 Aug 2018			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361106	Bleed AIR Pressure Regulating and Shut-Off Valve (Right)		HRS		1654.7			2403.1			0
	- Removal / Installation		AFL		493			691			0
	3215662-2	928	MOS		65.7			09 Aug 2018			HONEYWELL
	Airframe		MSC				O/C				ENGINES SYSTEMS & SERVICE
361107	Valve, Airstart Assist		HRS		4057.8			0			0
	PYLB52589		AFL		1184			0			0
		396	MOS		188.2			24 May 2008			SCHEIDL
	Airframe		MSC				O/C				MANUFACTURIN G COMPANY INC
361201	APU Check Valve - Removal / Installation		HRS		4057.8			0			0
	3202754-1		AFL		1184			0			0
		997	MOS		188.2			24 May 2008			GENERAL
	Airframe		MSC				O/C				DYNAMICS AVIATIONS SERVICES
361202	APU Check Valve - Detailed Inspection		HRS		4057.8		5000	0	5000	5050	0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		[HRS: +50/-50]								
361203	Bleed AIR Isolation Shut-Off Valve - Removal / Installation		HRS		4057.8			0			0
	3291826-1		AFL		1184			0			0
		294	MOS		188.2			24 May 2008			HONEYWELL-
	Airframe		MSC				O/C				ENGINEERING SYSTEMS & SERV.

Notes: Q308411

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361204	8TH Stage Valve Servo Regulator and Torque Motor (Left)		HRS		4057.8			0			0
	- Removal / Installation		AFL		1184			0			0
	3215636-2	1213	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361205	8TH Stage Valve Servo Regulator and Torque Motor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3215636-2	1212	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361207	Valve, External AIR Check		HRS		4057.8			0			0
	3202754-1		AFL		1184			0			0
		1003	MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Airframe											
361215	Bleed AIR Flow Control and Pressure Regulation - Operational Test		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC					O/C			
Airframe											
361401	Bleed AIR Precooler (Left) - Removal / Installation		HRS		4057.8			0			0
	2341172-1		AFL		1184			0			0
		516	MOS		188.2			24 May 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC					O/C			
Airframe											
361402	Bleed AIR Precooler (Right) - Removal / Installation		HRS		4057.8			0			0
	2341172-2		AFL		1184			0			0
		504	MOS		188.2			24 May 2008			HONEYWELL
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361403	Precooler Inlet Temperature Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	1150124-07381	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
361404	Precooler Inlet Temperature Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1150124-2	1150124-07383	MOS		188.2			24 May 2008			
			MSC								
Airframe											
361407	Fan AIR Valve (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3291252-1	938	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ENGINES SYSTEMS & SERVICE
Airframe											
361408	Fan AIR Valve (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3291252-1	942	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ENGINES SYSTEMS & SERVICE
Airframe											
362101	Manifold Pressure Sensor (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151584-1	1151584-05609	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
Notes: Q308411											
362102	Manifold Pressure Sensor (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1151584-1	1151584-05608	MOS		188.2			24 May 2008			HONEYWELL
			MSC								ASCA INC.
Airframe											
Notes: Q308411											

38 - Water/Waste

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
380001	Vacuum Toilet (Aft) - Removal / Installation		HRS		4057.8			0			0
	7900268	63-1484	AFL		1184			0			0
			MOS		188.2			24 May 2008			ENVIROVAC, INC.
	Airframe		MSC					O/C			
Notes: VERFIED BY 306859											
380002	Toilet, Fwd Lav		HRS		4025.2			32.6			0
	7900268	63-1464	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			ENVIROMAX
	Airframe		MSC					O/C			
Notes: VERFIED BY 306859											
380003	Vacuum Blower - Removal / Installation		HRS		4057.8			0			0
	7900138-004	0666	AFL		1184			0			0
			MOS		188.2			24 May 2008			ENVIROVAC, INC.
	Airframe		MSC					O/C			
Notes: Q306853											
380004	Logic Control Module - Removal / Installation		HRS		4057.8			0			0
	7700201-002	1901	AFL		1184			0			0
			MOS		188.2			24 May 2008			ENVIROVAC, INC.
	Airframe		MSC					O/C			
Notes: VERFIED BY 306853											
380005	Status Panel - Removal / Installation		HRS		4057.8			0			0
	7700202-004	438	AFL		1184			0			0
			MOS		188.2			24 May 2008			ENVIROVAC, INC.
	Airframe		MSC					O/C			
Notes: VERFIED BY 306853											
380006	Waste Tank - Removal / Installation		HRS		4057.8			0			0
	7900295	43-898	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
Notes: VERFIED BY Q309044											
380008	Valve, Vacuum Toilet Dump		HRS		4057.8			0			0
	2651-375-1	103032	AFL		1184			0			0
			MOS		188.2			24 May 2008			SCALAMANDRE
	Airframe		MSC					O/C			
Notes: VERFIED BY Q309044											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
380009	Vacuum Waste System - Cleaning		HRS		1735.4			2322.4			0
			AFL		520			664			0
			MOS		76.6			12 Sep 2017			
	Airframe		MSC					O/C			
380031	Waste Tank Ultrasonic Level Sensor (Left) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
380032	Waste Tank Ultrasonic Level Sensor (Right) - Cleaning		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
380050	Water System Heater (Water Tank) - Operational Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.1			27 Jul 2020			
	Airframe		MSC					O/C			
381001	Conformal Water Tank - Removal / Installation		HRS	TSN:2403.1	1654.7			2403.1			0
	4E4293-3	N0807801	AFL	TSN:691	493			691			0
			MOS	TSN:123	65.5			14 Aug 2018			GOODRICH
	Airframe		MSC					O/C			
381008	Conformal Water Tank Manual Shut-Off Valve - Removal / Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
	4E4473-1	NI913502	MOS	TSN:26	30.5			15 Jul 2021			N/A
	Airframe		MSC					O/C			
381009	Sensor Assembly, Water Level		HRS		1653			2404.8			0
	4E4185-2	N1234003	AFL		492			692			0
			MOS		65.5			14 Aug 2018			
	Airframe		MSC					O/C			
381011	Heater, Galley Water		HRS		2982			1075.8			0
	MRX2000-102	2002-439	AFL		872			312			0
			MOS		138.7			09 Jul 2012			DYNAMO
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381012	Heater, Fwd Lav Water		HRS		2176.4			1881.4			0
	MRX1000-102	1002-744	AFL		663			521			0
			MOS		100.5			15 Sep 2015			DYNAMO
	Airframe		MSC					O/C			
381013	Heater, Aft Lav Water		HRS		0			4057.8			0
	MRX-1000-102B	1002-821B	AFL		0			1184			0
			MOS	TSN:1	.9			04 Jan 2024			N/A
	Airframe		MSC					O/C			
381023	Water Level Controller - Removal / Installation		HRS		1189.2			2868.6			0
	4E186-1	U0305	AFL		361			823			0
			MOS		52.5			16 Sep 2019			GOODRICH
	Airframe		MSC					O/C			
381029	Water System - Operational Test		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.7			08 Jan 2024			
	Airframe		MSC					O/C			
381031	Valve, Fwd Lav Water		HRS		4025.2			32.6			0
	4E4474-1	N0723304	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
	Airframe		MSC					O/C			
381032	Valve, Water Compartment		HRS		4025.2			32.6			0
	4E4483-1	N0818206	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
	Airframe		MSC					O/C			
381039	Water Sterilizer - Removal / Installation		HRS	TSN:3853.8	134.1			3923.7			0
	09-130021-102	1-0602	AFL	TSN:1122	44			1140			0
			MOS	TSN:178	4.9			04 Sep 2023			N/A
	Airframe		MSC					O/C			
381052	Supply Line Motor Drain Valve - Removal / Installation		HRS		3687			370.8			0
	4E4491-1	N07180035	AFL		1080			104			0
			MOS		167.4			20 Feb 2010			GOODRICH
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381053	Supply / Fill / Purge Valve - Removal / Installation		HRS		917.1			3140.7			0
	4E4492-1	N1520902	AFL		303			881			0
			MOS		35.3			23 Feb 2021			N/A
	Airframe		MSC					O/C			
381055	Power Switching Controller - Removal / Installation		HRS	TSN:2868.6	1189.2			2868.6			0
	4E4265-1	U143	AFL	TSN:823	361			823			0
			MOS	TSN:136	52.5			16 Sep 2019			GOODRICH
	Airframe		MSC					O/C			
381057	Switch, Aft Lav Water Mat		HRS		4025.2			32.6			0
	CVP1723	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			TAPESWITCH
	Airframe		MSC					O/C			
381058	Switch, Fwd Lav Water Mat		HRS		4025.2			32.6			0
	CVP1723	NSN	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			TAPESWITCH
	Airframe		MSC					O/C			
381060	Switch, Aft H2O Heater Blanket		HRS		4057.8			0			0
	2457-1-2	2PPCJ	AFL		1184			0			0
			MOS		188.2			24 May 2008			TAPIS CORP
	Airframe		MSC					O/C			
381065	Contactor, Aft Baggage		HRS		4057.8			0			0
	SA106E	CP-90045	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
381300	Supply Line Motor Drain Valve - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
381301	Drain Line Motor Drain Valve - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	07 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381401	Potable Water Storage Tank - External Fill		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.5			15 Sep 2023			
	Airframe		MSC					O/C			
381501	Water Supply Line Linnerline Heater Controller (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3434-01	1177	MOS		188.2			24 May 2008			COX & COMPANY INC
	Airframe		MSC					O/C			
381502	Water Supply Line Linnerline Heater Controller (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3434-01	1174	MOS		188.2			24 May 2008			TAPIS CORP
	Airframe		MSC					O/C			
381503	Water Supply / Drain Line Innerline Heater Controller - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3434-01	1163	MOS		188.2			24 May 2008			COX & COMPANY INC
	Airframe		MSC					O/C			
381510	Cont, Aft Eer Interline		HRS		4057.8			0			0
			AFL		1184			0			0
	3435-01	425	MOS		188.2			24 May 2008			COX & COMPANY INC
	Airframe		MSC					O/C			
382002	Water Sterilizer Filter - Removal / Installation		HRS		134.1			3923.7			0
			AFL		44			1140			0
	06-133802-001	NSN	MOS		4.9			04 Sep 2023			N/A
	Airframe		MSC					O/C			
382003	Water Sterilizer Filter - Discard		HRS		134.1			3923.7			0
			AFL		44			1140			0
	06-133802-001	NSN	MOS		4.9			04 Sep 2023	30 Sep 2024	31 Oct 2024	N/A
	Airframe		[End Of Month Item] [MOS: +1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
382011	Water System Heater (Water Supply Innerline) -		HRS		4057.8			0			0
	Operational Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
382012	Water System Heater (Water Drain Innerline) -		HRS		4057.8			0			0
	Operational Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
382013	Water System Heater (Supply / Fill / Purge Valve) -		HRS		4025.2			32.6			0
	Operational Test		AFL		1170			14			0
			MOS		184.6			12 Sep 2008			
			MSC					O/C			
Airframe											
382016	Forward Lav Sink Drain Valve		HRS		4057.8			0			0
	300-0015-01	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
382017	Forward Lav Sink Backflow Valve		HRS		4057.8			0			0
	4E4350-1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
382104	Valve, Aft Lav H2O Shutoff		HRS		4025.2			32.6			0
	4E4474-1	N0723305	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC					O/C			
Airframe											
382105	Valve, Aft Galley H2O Shutoff		HRS		4025.2			32.6			0
	4E4474-1	N0722616	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
382107	Vacuum Toilet Rinse Valve (Forward) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	7800001-008	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC								
Airframe											
382116	Backflow Valve, Galley Vent.		HRS		4025.2			32.6			0
	4E4350-1	N0807424	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC								
Airframe											
382118	Backflow Valve, Galley Annex.		HRS		4025.2			32.6			0
	4E4350-1	N0808707	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC								
Airframe											
382121	Expresso Drain Valve		HRS		4025.2			32.6			0
	3000015-01	388	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			EATON
			MSC								
Airframe											
383000	Water System Heater (Aft Drain Mast) - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
383001	Aft Drain Mast - Removal / Installation		HRS	TSN:3099.9	957.9			3099.9			0
	70WS001-216	AS4425	AFL	TSN:871	313			871			0
			MOS	TSN:146	42.3			22 Jul 2020			N/A
			MSC								
Airframe											
383009	Valve, Fwd Lav Vanity Drain		HRS		4025.2			32.6			0
	4E4484-1	N0733046	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC								
Airframe											
383010	Valve, Aft Lav Vanity Drain		HRS		4025.2			32.6			0
	4E4485-1	N0733902	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
383022	Valve, Aft Toilet Drain		HRS		4025.2			32.6			0
	4E4350-1	N0808704	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
	Airframe		MSC					O/C			
383027	Valve, Galley H2O Drain #1		HRS		4025.2			32.6			0
	4E4474-1	N0723308	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			GOODRICH
	Airframe		MSC					O/C			
49 - Airborne Auxiliary Power											
490001	APU - Auxiliary Power Unit - Functional Test		HRS		1776.5			798.5			0
			APUS		1513			326			0
			MOS		136.5			15 Sep 2012			
	APU		MSC					O/C			
490003	APU - APU Performance Run - Functional Test		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491005	APU Enclosure FS 767 - FS 797 - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		24	29 Aug 2023 31 Aug 2025 30 Sep 2025			
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
491007	APU Enclosure Thermal Blanket / Coating - General		HRS		4057.8			0			0
	Visual Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
491101	APU - APU - Removal / Installation		HRS		2575			0			0
	WE3800700-1	P-526	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL AVIATION AFTERMARKET SERVICES
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491104	APU - APU Mount Bracket - General Visual Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491105	APU - APU Isolator Mounts - General Visual Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491201	APU - AIR Inlet Door - Removal / Installation		HRS		2575			0			0
	1159P50703-3	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491206	APU - Auxiliary Power Unit Inlet Door Actuator - Removal / Installation		HRS		2575			0			0
	SYLC52630-2	080303	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			SMITHS AEROSPACE, INC.
	APU		MSC					O/C			
491207	APU Inlet Door and Actuator - Detailed Inspection		HRS		857.7			3200.1			0
			AFL								0
			MOS		30.7		48	10 Jul 2021	10 Jul 2025	10 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
491208	APU - Inlet Door Actuator - Adjustment Test		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491216	APU - AIR Intake Duct Removal / Installation		HRS		2575			0			0
	1159SCP107-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
491300	APU Compartment Drain Collectors - General Visual Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	06 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491301	APU - Auxiliary Power Unit Turbine Plenum Drains - Operational Test		HRS		123.5			2451.5			0
			APUS								0
			MOS		7.5		24	17 Jun 2023	30 Jun 2025	31 Jul 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
APU											
491302	APU - APU Turbine Plenum Drain - Operational Test		HRS		2161			414			0
			APUS		1839			0			0
			MOS		160.5			17 Sep 2010			
			MSC				O/C				
APU											
491303	APU Compartment Drains - (Ezip) - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
			MSC				O/C				
Airframe											
491304	APU Compartment Drains - Operational Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		24	06 Jun 2022	30 Jun 2024	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
491306	Interior and Exterior Surfaces of APU Compartment (APU Box) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
			MSC				O/C				
Airframe											
491350	APU - APU Combustor - Wash		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC				O/C				
APU											
492001	APU - Impeller - Discard		HRS		2575		10000	0	10000		0
	WB3822573-1	07-03501-09266	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
APU											
492002	APU - APU 1ST Stage Turbine Rotor Assembly - Discard		HRS		2575		10000	0	10000		0
	WK3840142-1	072241001474	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
492003	APU - 2ND Stage Turbine Rotor - Discard		HRS		2575		10000	0	10000		0
	WE897994-3	08-01345-00530	APUS		1839			0			0
			MOS		189.4				18 Apr 2008		
APU											
492101	APU - APU Wire Harness - Removal / Installation		HRS		2575			0			0
	3888362	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4				18 Apr 2008		
APU							O/C				
492102	APU - Branched Wiring Harness (Wiring Harness) -		HRS		2575			0			0
	General Visual Inspection		APUS		1839			0			0
			MOS		189.4				18 Apr 2008		
APU							O/C				
492301	APU - Compressor and Turbine Section - Rotation Check		HRS		2575			0			0
	and / or Borescope Inspection		APUS		1839			0			0
			MOS		189.4				18 Apr 2008		
APU							O/C				
492601	APU - Starter Gear / Clutch Module - Removal /		HRS		2575			0			0
	Installation		APUS		1839			0			0
	WK3860976	SN-UNKNOWN	MOS		189.4				18 Apr 2008		
APU							O/C				
493001	APU - APU Engine Fuel and Control System - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4				18 Apr 2008		
APU							O/C				
493004	APU - APU Fuel Filter Element - Removal / Installation		HRS		0			2575			0
	758566	NSN	APUS		0			1839			0
			MOS		1.1				29 Dec 2023		N/A
APU							O/C				

Notes: Filter must be replaced after 50 flight hours but before 75 flight hours per 280015 requirements.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493010	APU - Primary Fuel Shut-Off Valve - Removal / Installation		HRS		2575			0			0
	66917-30286-4	1615	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493011	APU - Fuel Flow Divider Solenoid Valve - Removal / Installation		HRS		2575			0			0
	WE3883738-2	00625	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493012	APU - Fuel Flow Divider Valve - Leakage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493015	APU - Lube Module, Fuel Pump		HRS		2575			0			0
	WE3881600-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493101	APU - Fuel Control Unit - Removal / Installation		HRS		2575			0			0
	441903-4	CUB10565	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			HONEYWELL AVIATION AFTERMARKET SERVICES
493103	APU - Seal Witness Drain Leakage - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493105	APU - APU Fuel Strainer - Removal / Installation		HRS		2575			0			0
	3882496-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			HONEYWELL HPG

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493106	APU - Fuel Strainer - Contamination Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493107	APU - Fuel Strainer - Leakage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493108	APU - Fuel Strainer - Cleaning		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493111	APU - Fuel Nozzles Assy, APU		HRS		2575			0			0
	WE3830464-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493112	APU - Fuel Nozzle Assembly Connections - Leakage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493113	APU - Fuel Nozzle Assemblies - Damage / Contamination Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493301	APU - Flow Divider Supply Tube Assembly - Leakage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493312	APU - Primary and Secondary Fuel Manifolds - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
493321	APU - Orifice Fitting Assembly - Removal / Installation		HRS		2575			0			0
	3616783-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493322	APU - Orifice Fitting Assembly - Drainage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493323	APU - Orifice Fitting Assembly - General Visual / Dimensional Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493401	APU - Fuel Filter Bypass Indicator Valve - Removal / Installation		HRS		2575			0			0
	3883512-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
493402	APU - Fuel Filter Bypass Indicator - Detailed Inspection (Delta P Indicator)		HRS		90		600	2485	3085	3135	0
			APUS		65			1774			0
			MOS		5.1			29 Aug 2023			
	APU							[HRS: +50/-50]			
493404	APU Fuel System Components, Lines and Connections - General Visual Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	(493404) Airframe							[End Of Month Item] [HRS: +50/-50]			
494001	APU - APU Starter Motor - Removal / Installation		HRS		2575			0			0
	2704554-2	1429	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			HONEYWELL AVIATION AFTERMARKET SERVICES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494002	APU - Auxiliary Power Unit Starter - Detailed Inspection		HRS		90		600	2485	3085	3135	0
			APUS		65			1774			0
			MOS		5.1			29 Aug 2023			
	APU				[HRS: +50/-50]						
494003	APU - Starter Motor - Brush Wear Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU						O/C				
494201	APU - APU Ignition Exciter - Removal / Installation		HRS		2575			0			0
	WE3876295-6	080218084773	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU						O/C				HONEYWELL AVIATION AFTERMARKET SERVICES
494202	APU - Left Igniter Plug Lead - Removal / Installation		HRS		2575			0			0
	WE3888353-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU						O/C				HONEYWELL AVIATION AFTERMARKET SERVICES
494203	APU - Right Igniter Plug Lead - Removal / Installation		HRS		2575			0			0
	WE3888353-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU						O/C				HONEYWELL AVIATION AFTERMARKET SERVICES
494205	APU - APU Igniter Plug Lead Electrical Properties (Right)		HRS		2575			0			0
	- Inspection / Check		APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU						O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494206	APU - Igniter Plug (Left) - Removal / Installation		HRS		2575			0			0
	WE3888354-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
494207	APU - Igniter Plug (Right) - Removal / Installation		HRS		2575			0			0
	WE3888354-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
494208	APU - APU Igniter Plug (Left) - Inspection / Check		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
494209	APU - APU Igniter Plug (Right) - Inspection / Check		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
494211	APU - No. 1 APU Ignition / Starting System Ignition		HRS		2575			0			0
	System Igniter Plug - Cleaning / Painting		APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
494212	APU - No. 2 APU Ignition / Starting System Ignition		HRS		2575			0			0
	System Igniter Plug - Cleaning / Painting		APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
495001	APU - APU Surge Control Valve - Removal / Installation		HRS		2575			0			0
	3291212-4	908	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			GENERAL DYNAMICS AVIATIONS SERVICES

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
495002	APU - APU Load Control Valve - Removal / Installation		HRS		2575			0			0
	3291210-4	1548	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL
	APU		MSC					O/C			ENGINES SYSTEMS & SERVICE
495005	APU - Duct, APU Surge Valve		HRS		2575			0			0
	1159P50731-1	0425	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			GULFSTREAM
	APU		MSC					O/C			SAV PROD-IPT
495010	APU - Inlet Pressure Sensor - Removal / Installation		HRS		2575			0			0
	WE3876283-1	081121420770	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL
	APU		MSC					O/C			AEROSPACE ACADEMY
495201	APU - APU Bleed Diffuser - Removal / Installation		HRS		2575			0			0
	WB3827365-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
496101	APU - Electronic Control Unit - Removal / Installation		HRS		2575			0			0
	2118946-10	28-M0112	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL
	APU		MSC					O/C			
497001	APU - Cockpit Overhead Indicator - Removal / Installation		HRS		2575			0			0
	789543-1	0641	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			INTERTECHNIQU
	APU		MSC					O/C			E

Notes: VER BY PQ648

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
497005	APU - Thermocouple, APU #1 Egt		HRS		2575			0			0
	WE3876282-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL INTERNATIONAL INC.
	APU		MSC					O/C			
497007	APU - Time Totalizing Meter - Read and Record		HRS		897			1678			0
			APUS		675			1164			0
			MOS		76.8			05 Sep 2017			
	APU		MSC					O/C			
497010	APU - APU Temperature Sensor (Inlet, T2) - Removal / Installation		HRS		2575			0			0
	MS28034-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			GULFSTREAM DALLAS
	APU		MSC					O/C			
497012	APU - Starter Current Limiter (APU)		HRS		2575			0			0
	133002-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
497015	APU - APU Speed Sensor - Removal / Installation		HRS		2575			0			0
	WE3876281-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL INTERNATIONAL INC.
	APU		MSC					O/C			
498001	APU - APU Exhaust Duct - General Visual Inspection		HRS		90		600	2485	3085	3135	0
			APUS		65			1774			0
			MOS		5.1			29 Aug 2023			
	APU							[HRS: +50/-50]			
499001	APU - APU Oil Level / Remote Oil Panel - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499003	APU - APU AIR / Oil Cooler - Removal / Installation		HRS		2575			0			0
	160534-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			LORI, INC.
	APU		MSC					O/C			
499004	APU - APU Oil Sump Heater - Removal / Installation		HRS		2575			0			0
	WE3876292-2	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
499005	APU - APU Oil Level Sensor - Removal / Installation		HRS		2575			0			0
	WE3876285-1	SN-UNKNOWN	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
499006	APU - APU Low Oil Pressure Switch - Removal / Installation		HRS		2575			0			0
	WE3876291-1	VN09227	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
	APU		MSC					O/C			
499007	APU - Lube Filter Bypass Indicator Valve - Removal / Installation		HRS		2575			0			0
	WE3876293-1	VN11426	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL INTERNATIONAL INC.
	APU		MSC					O/C			
499010	APU - Auxiliary Power Unit Oil System - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
	APU		MSC					O/C			
499014	APU - Generator Filter Bypass Indicator Valve - Removal / Installation		HRS		2575			0			0
	WE3876294-1	VN11426	APUS		1839			0			0
			MOS		189.4			18 Apr 2008			HONEYWELL INTERNATIONAL INC.
	APU		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499015	APU - APU Lube / Generator Filter Elements - Removal / Installation		HRS		2575			0			0
			APUS		1839			0			0
	WE3881767-1	SN-UNKNOWN	MOS		189.4			18 Apr 2008			HONEYWELL
			MSC								
APU											
499019	APU - APU Magnetic Drain Plug - Removal / Installation		HRS		811			1764			0
			APUS		1839			0			0
	572-510-9151	N/A	MOS		70.3			23 Mar 2018			
			MSC								
APU											
499020	APU - Chip Collector - Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC								
APU											
499022	APU - Auxiliary Power Unit Oil - Servicing		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC								
APU											
499025	APU - APU Oil - Change		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC								
APU											
499110	APU - APU Lube Pump Assembly (Pump) Seal Plate - Removal / Installation		HRS		2575			0			0
			APUS		1839			0			0
	715331	SN-UNKNOWN	MOS		189.4			18 Apr 2008			HAMILTON SUNDSTRAND
			MSC								
APU											
499115	APU - Lube Pump Assembly - Removal / Installation		HRS		2575			0			0
			APUS		1839			0			0
	WE3881781-1	VE2288	MOS		189.4			18 Apr 2008			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC								
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499116	APU - Lube Pump Assembly - General Visual / Leakage Inspection		HRS		2575			0			0
			APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC					O/C			
APU											
499125	APU - Turbine Bearing Supply and Return Tube Assembly - Removal / Installation		HRS		2575			0			0
	WE361681-1 SN-UNKNOWN		APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC					O/C			
APU											
499130	APU - APU Deprime / Deoil Valve - Removal / Installation		HRS		2575			0			0
	4141028-4 SN-UNKNOWN		APUS		1839			0			0
			MOS		189.4			18 Apr 2008			
			MSC					O/C			AEROCONTROLE X GROUP
APU											
49APU1	APU		HRS		4057.8			0			0
	WE3800700-1 P-526		AFL		1184			0			0
			MOS		188.6			12 May 2008			
			MSC					E/C			
Airframe											
51 - STD Practices and Struct-Genrl											
510013	External Metallic Surfaces - Polishing		HRS		346.5			3711.3			0
			AFL		129			1055			0
			MOS		11.5			15 Feb 2023			
			MSC					O/C			
Airframe											
[End Of Month Item]											
52 - Doors											
520005	Exterior Cabin Doors and Exits - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016 30 Sep 2024* 31 Oct 2024			
Airframe											
[End Of Month Item] [MOS: +1m/-1m]											
521001	Main Entrance Door - Removal / Installation		HRS		4057.8			0			0
	1159B57011-800-27 5198		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521002	Main Entrance Door Seal - Removal / Installation		HRS		4057.8			0			0
	1159SCB500-11	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
521003	Main Entrance Door Actuator - Removal / Installation		HRS		4057.8			0			0
	159H10030-51	55-5198GT	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: Q300491											
521004	Valve, Main Entrance Door Reducer		HRS		4057.8			0			0
	1159SCH219-25	526	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS INC
	Airframe		MSC					O/C			
Notes: Q300491											
521005	Valve, Main Entrance Door Selector		HRS		4057.8			0			0
	1159SCH247-3	1667G	AFL		1184			0			0
			MOS		188.2			24 May 2008			PNEUDRAULICS INC
	Airframe		MSC					O/C			
Notes: Q300491											
521007	Main Entrance Door Bayonet Position Indicator DOTS - General Visual Inspection		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7	52	72	09 Aug 2018	30 Sep 2024*	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
521008	Main Entrance Door Hinge Pins - Removal / Installation		HRS		134.1			3923.7			0
	1159BM50108-11	NSN	AFL		44			1140			0
			MOS	TSN:45	4.9			03 Sep 2023			N/A
	Airframe		MSC					O/C			
521009	Main Entrance Door Hinge Pins - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.9	58	36	03 Sep 2023	31 Oct 2026*	30 Nov 2026	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521010	Main Entrance Door - Lubrication		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	37	12	06 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521011	Main Entrance Door - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521012	Main Entrance Door Internal - Detailed Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.9	26	72	04 Sep 2019	30 Sep 2025*	31 Oct 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521015	Main Entrance Door - Operating Procedures		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8			06 Jun 2023			
	Airframe		MSC O/C								
521016 (521016)	Main Entrance Door Cables - Tension Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	31	72	04 Sep 2020	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521101	External Door Locks-Key Code		HRS		4057.8			0			0
	ASG550M-14P		AFL	SN-UNKNOWN	1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
523001	Baggage Door - Removal / Installation		HRS	TSN:3099.8	957.9			3099.9			0
	1159B51046-39		AFL	TSN:871	313			871			0
			MOS	TSN:146	42.5			17 Jul 2020			N/A
	Airframe		MSC O/C								
523002	Baggage Compartment Door Inflatable Door Seal -		HRS		4057.8			0			0
	Removal / Installation		AFL		1184			0			0
	1159SCB524-1		MOS	SN-UNKNOWN	188.2			24 May 2008			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
523003	Baggage Compartment Door Seal - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
523004	Baggage Compartment Door Seal AIR Supply Moisture Drain Orifice - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
523005	Baggage Compartment Door - Lubrication		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	38	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
523006	Baggage Compartment Door - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.8	23	96	07 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
523008	Baggage Compartment Door Seal Check Valve - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
523009	Baggage Compartment Door Seal Pressure Regulator - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3215648-1	547	MOS		188.2			24 May 2008			HONEYWELL AVIATION AFTERMARKET SERVICES
	Airframe		MSC				O/C				
523010	Filter, Baggage Compartment Door Seal		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCAC001-1	3179	MOS		188.2			24 May 2008			AIRCRAFT SEAL AND GASKET CORP.
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
523012	Baggage Compartment Door Inflatable Seal System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
523013	Inflatable Door Seal - Purging Procedure		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
523018	Baggage Compartment Door Seal High Flow Pressure Regulator - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	3215634-6	SN-UNKNOWN	MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
523021	Bolts, Baggage Door Stop		HRS		4057.8			0			0
	NAS428K4A12		AFL		1184			0			0
	SN-UNKNOWN		MOS		188.2			24 May 2008			
			MSC					O/C			STORK FOKKER AESP B.V.
Airframe											
523201	Baggage Compartment Door Internal Structure - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
524001	Tail Compartment Door - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6		144	13 Jul 2020	31 Jul 2032	31 Aug 2032	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
524004	Door, Tail Compartment		HRS		4057.8			0			0
	1159B51527-27		AFL		1184			0			0
	5198		MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
525001	Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	38	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
525002	Auxiliary Pressure Bulkhead Door - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6		144	13 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
525004	Auxiliary Pressure Bulkhead Door - Removal / Installation		HRS		4057.8			0			0
	1159HS51886-3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
	[End Of Month Item] [MOS: +1m/-1m]										
527001	Main Entrance Door Secondary Handle Lock Switch and Circuitry - Operational Test		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		24	16 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
527003	Main Entrance Door Locked Relay Circuit - Functional Test		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			AFL		44			1140			0
			MOS		4.6			13 Sep 2023			
	Airframe		[HRS: +50/-50]								
527201	Internal Baggage Door - Functional Check		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.6	-11	48	11 Sep 2023	31 Aug 2027*	30 Sep 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
528103	Door, Nose Gear Fairing		HRS		4057.8			0			0
	1159B50511-800-25	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			LEONARD'S METAL INC.
	[End Of Month Item] [MOS: +1m/-1m]										

53 - Fuselage

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530005	Radome - Removal / Installation		HRS		4057.8			0			0
	1159B57290-9	3-293	AFL		1184			0			0
			MOS		188.2			24 May 2008			GENERAL DYNAMICS AVIATIONS SERVICES
	Airframe		MSC					O/C			
530006	Forward Section		HRS		4057.8			0			0
	1159B50009-804-1	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530007	Cockpit Enclosure		HRS		4057.8			0			0
	1159B30800	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530008	Forward Combo Section		HRS		4057.8			0			0
	1159B57004-801-1	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530009	Center Mid Section		HRS		4057.8			0			0
	1159B50005-801	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530010	Aft Mid Section		HRS		4057.8			0			0
	1159B50009-801PH1	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530011	Torque Box		HRS		4057.8			0			0
	1159B51701-53	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

Notes: VERIFIED BY PQ514

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530012	Aft Fuselage Section		HRS		4057.8			0			0
	1159B50006-801PH2	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530013	Tail Cone Section		HRS		4057.8			0			0
	1159B52901-43	5198	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GULFSTREAM SAV PROD-IPT
Notes: VER BY Q307268											
530014	Dorsal Fin		HRS		4057.8			0			0
	1159B21506	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
530025	Fuselage Penetrations Production and Outfitting Installations - Detailed Inspection		HRS		4057.8			0			0
			AFL			8000**		8000			0
			MOS		188.2			24 May 2008			
	Airframe										
530027	Floorboard Clip Nut - Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41			30 Aug 2020			
	Airframe		MSC					O/C			
530201	Radome to Structure Perimeter Steps - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.5		24	14 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
530205	Birdstrike Plate (Left) - Removal / Installation		HRS		192.1			3865.7			0
	1159B50207-33	A0113686601	AFL		78			1106			0
			MOS		7.7			08 Jun 2023			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530206	Birdstrike Plate (Right) - Removal / Installation		HRS		192.1			3865.7			0
	1159B50207-34	A0113168601	AFL		78			1106			0
			MOS		7.7			08 Jun 2023			
	Airframe		MSC					O/C			
531005	External Lower Fuselage FS -4 Thru FS 758 View from Ground - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
531010	Radome FS -4 Thru FS 63 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
531012	Exterior Radome Fairing Installation - Detailed Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		4.8			05 Sep 2023			
	Airframe							[HRS: +50/-50]			
531013	Enhanced Vision System Fairing and Rain Diverter Fairing - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	18	96	12 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
531014	Enhanced Vision System Sapphire Window Installation - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			AFL		44			1140			0
			MOS		5.5			16 Aug 2023			
	Airframe							[HRS: +50/-50]			
531015	Nose Gear Wheel Well FS 44 - FS 119 - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8		12	05 Jun 2023	30 Jun 2024	31 Jul 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
531016	Nose Landing Gear Skin Cutout - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**	8000			0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531019	Cockpit Internal Skin and Substructure FS 63 Thru FS 145		HRS		4057.8			0			0
	- Detailed Inspection		AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531020	Cockpit Below Floor FS 119 - FS 145 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531025	Lower Fuselage FS 85 - FS 119 Cheek Panel (Left) -		HRS		1909.4			2148.4			0
	Zonal Inspection		AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531026	Lower Fuselage FS 85 - FS 119 Cheek Panel (Right) -		HRS		1909.4			2148.4			0
	Zonal Inspection		AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531030	Internal Cockpit Below Floor FS 63 - FS 85, WI 81 - WI 71		HRS		1909.4			2148.4			0
	- Zonal Inspection		AFL		573			611			0
			MOS		88.7	20	96	10 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531035	Cabin Below Floor FS 229 - FS 426 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	20	96	10 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531036	Cabin Below Floor FS 145 - FS 229 - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		48	14 Jul 2020	31 Jul 2024	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531040	Upper Surface of Center Wing FS 426 - FS 576 from Wheel Well - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531041	Upper Surface of Center Wing FS 426 - FS 576 from Cabin - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	20	96	10 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531045	Main Gear Wheel Wells FS 576 - FS 632 (Left) - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	33	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
531046	Main Gear Wheel Wells FS 576 - FS 632 (Right) - Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	32	12	06 Jun 2023	31 Jul 2024*	31 Aug 2024	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
531047	Main Gear Wheel Wells FS 576 - FS 632 (Cove Panel Drain Holes) - (Enhanced) Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	32	12	06 Jun 2023	31 Jul 2024*	31 Aug 2024	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
531048	Main Gear Wheel Wells FS 576 - FS 632 (Wiring Harness) - (Enhanced) Zonal Inspection		HRS		192.1		500	3865.7	4365.7	4415.7	0
			AFL		78			1106			0
			MOS		7.8	33	12	05 Jun 2023	31 Jul 2024*	31 Aug 2024	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
531050	Overwing AREA FS 354 - FS 736 Between Drag Beam and Wing to Body Fairing (Left) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531051	Overwing AREA FS 354 - FS 736 Between Drag Beam and Wing to Body Fairing (Right) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531055	Aft Cabin Below Floor FS 632 - FS 684 - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531060	Baggage Compartment Below Floor FS 684 - FS 758 - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7		24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531065	External Upper Fuselage FS 63 - FS 758 View from Ground - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531066	External Upper Fuselage FS 63 - FS 758 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	19	96	11 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531068	External Fuselage - General Visual Inspection		HRS		616		2000	3441.8	5441.8		0
			AFL		220		800	964	1764		0
			MOS		19.8			06 Jun 2022			
Airframe											
531070	Cockpit Above Floor FS 63 - FS 145 - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531074	Cabin Above Floor Internal FS 145 - FS 758 - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531075	Cabin Above Floor FS 145 - FS 758 - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
			MSC					O/C			
Airframe											
531076	Cabin Above Floor Internal FS 145 - FS 758 - (Enhanced) Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531080	Left Electronic Equipment Rack FS 141 - FS 166 - Zonal Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	36	24	05 Jun 2023	31 Jul 2025*	31 Aug 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531081	Right Electronic Equipment Rack FS 147 - FS 181 - Zonal Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	36	24	05 Jun 2023	31 Jul 2025*	31 Aug 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531082	Electronic Equipment Rack FS 147 - FS 181 - (Enhanced) Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.9		24	02 Jun 2022	30 Jun 2024	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531085	External Aft Fuselage and Empennage FS 758 - FS 1123 Viewed from Ground - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531090	External Aft Fuselage and Empennage FS 758 - FS 1123 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531093	Lavatory Service Panel Pressure Box Structure - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
531095	Aft Fuselage Above Floor FS 758 - FS 974 - Zonal Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	36	24	05 Jun 2023	31 Jul 2025*	31 Aug 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531100	Aft Fuselage Below Floor FS 758 - FS 797 - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531105	Aft Fuselage Below Floor FS 797 - FS 974 - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531110	Tail Cone FS 974 - FS 1026 - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531115	Cockpit Window Skins (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: ACFT 5045 & SUB 8000 LDG INIT / 3600 LDG RPT											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531116	Cockpit Window Skins (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											
Notes: ACFT 5045 & SUB 8000 LDG INIT / 3600 LDG RPT											
531200	Bulkhead Installation FS 44 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531205	Bulkhead Installation FS 63 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531210	Bulkhead Installation FS 85 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531215	Bulkhead Installation FS 119 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
531218	Cabin Window Ring Frame Windows 6 and 7 (No. 6) - Ndt Inspection		HRS		4057.8			0			0
			AFL				4700**		4700		0
			MOS		188.2			24 May 2008			
Airframe											
531219	Cabin Window Ring Frame Windows 6 and 7 (No. 7) - Ndt Inspection		HRS		4057.8			0			0
			AFL				4700**		4700		0
			MOS		188.2			24 May 2008			
Airframe											
531220	Bulkhead Installation FS 133 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe [End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531225	FS 145 Frame - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531300	Longeron Installation L / R BI 12 FS 119 - 145 (Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		144	14 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531305	Longeron Installation L / R BI 12 FS 119 - 145 (Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		144	14 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531700	Windshield Rails and Posts (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531701	Windshield Rails and Posts (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531704	Cockpit Window Structure (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531705	Side Window Rails and Posts (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531706	Side Window Rails and Posts (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	31 Mar 2026	30 Apr 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531707	Upper Cockpit RAIL (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531708	Upper Cockpit RAIL (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531711	Cockpit Lower RAIL BI 0 Splice - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531715	Side Post Upper Attach (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
531716	Side Post Upper Attach (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
531717	Cockpit Side Post and Lower RAIL Attachment (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				6100**		6100		0
			MOS		188.2			24 May 2008			
	Airframe										
531718	Cockpit Side Post and Lower RAIL Attachment (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				6100**		6100		0
			MOS		188.2			24 May 2008			
	Airframe										
531721	Center Post Lower Attachment - Ndt Inspection		HRS		4057.8			0			0
			AFL				6300**		6300		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531722	Upper Cockpit Center Post - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
531730	Cockpit Center Post - Discard		HRS		4057.8			0			0
	1159BM50024	NSN	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
531733	Cockpit Side Post (Left) - Discard		HRS		4057.8			0			0
	1159BM50025-11	NSN	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
531734	Cockpit Side Post (Right) - Discard		HRS		4057.8			0			0
	1159BM50025	NSN	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
531741	Cockpit Lower RAIL Fastener (Left) - Discard		HRS		4057.8			0			0
	1159BM50033	NSN	AFL		1184	15000		0	15000		0
			MOS		188.2			24 May 2008			
	Airframe										
531742	Cockpit Lower RAIL Fastener (Right) - Discard		HRS		4057.8			0			0
	1159BM50033	NSN	AFL		1184	15000		0	15000		0
			MOS		188.2			24 May 2008			
	Airframe										
531747	FS 465 Mainframe Fittings (Left Forward) - Discard		HRS		4057.8			0			0
	1159BM50913-13	NSN	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										
531748	FS 465 Mainframe Fittings (Right Forward) - Discard		HRS		4057.8			0			0
	1159BM50914-13	NSN	AFL		1184	16000		0	16000		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531749	FS 465 Mainframe Fittings (Left Aft) - Discard		HRS		4057.8			0			0
	1159BM50913-13	NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531750	FS 465 Mainframe Fittings (Right Aft) - Discard		HRS		4057.8			0			0
	1159BM50914-13	NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531753	FS 576 Mainframe Fittings (Left Forward) - Discard		HRS		4057.8			0			0
	1159BM50915-17	NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531754	FS 576 Mainframe Fittings (Left Aft) - Discard		HRS		4057.8			0			0
		NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531757	FS 576 Mainframe Fittings (Right Forward) - Discard		HRS		4057.8			0			0
		NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531758	FS 576 Mainframe Fittings (Right Aft) - Discard		HRS		4057.8			0			0
		NSN	AFL		1184		16000	0	16000		0
			MOS		188.2				24 May 2008		
Airframe											
531900	Nose Wheel Well Trunnion Fitting Assembly - Detailed		HRS		4057.8			0			0
	Inspection		AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC					O/C			
Airframe											
532100	Pedestal Assembly		HRS		4057.8			0			0
	1159SCF551-7	101972	AFL		1184			0			0
			MOS		188.2				24 May 2008		MPC PRODUCTS
			MSC					O/C			
Airframe											
Notes: Q305828											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532105	Cabin Internal Structure Headliner Removed All Penetrations - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42		144	31 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532110	Below Emergency Exits - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	15 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532115	Baggage Door Surround Structure - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532120	Cabin Internal Below Floor and Below Stringer 19 Left / Right - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532125	Longitudinal Skin Splices (Left) - Gvi		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
532126	Longitudinal Skin Splices (Right) - Gvi		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
532201	FS 169 Frames - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184		8000	0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										
532205	FS 417 and FS 515 Frame Inner CAP Splice - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW										Manufacturer
	MM Ref											Date Type
	Ops Number(s)											
532215	Fuselage Stability Frames - Gvi		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
	Airframe		MSC					O/C				
532300	Longeron 22 Installation Under Galley / Lavatory (Wet Areas) FS 145 - FS 426 - Detailed Inspection		HRS		1909.4			2148.4			0	
			AFL		573			611			0	
			MOS		88.6	19	96		11 Sep 2016 30 Sep 2024*	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532305	Longeron 22 Installation Not Under Galleys and Lavatories (Dry Areas), FS 145 - FS 426 - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3		192		23 Sep 2008 30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532320	Left Stringer 6 Splice Fitting - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
	Airframe		MSC					O/C				
532500	Floor Structure Under Galleys, Lavatories FS 139 - FS 758 (Wet Areas) - Detailed Inspection		HRS		1909.4			2148.4			0	
			AFL		573			611			0	
			MOS		88.6	18	96		12 Sep 2016 30 Sep 2024*	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532505	Floor Structure Not Under Galleys, Lavatories FS 139 - FS 758 (Dry Areas) - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3		192**		23 Sep 2008 30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532510	Floorboards FS 426 - FS 632 Between Left / Right BI 30 - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3		192**		23 Sep 2008 30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW										Manufacturer
	MM Ref											Date Type
	Ops Number(s)											
532515	Floorboards FS 426 - FS 632 Outboard Left / Right BI 30 - Detailed Inspection		HRS		4057.8			0				0
			AFL		1184			0				0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532520	Floor Beam and Wing Link FS 465 - FS 576 - Detailed Inspection		HRS		1909.4			2148.4				0
			AFL		573			611				0
			MOS		88.7	20	96	10 Sep 2016	30 Sep 2024*	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532525	Floorboards FS 426 - FS 632 Areas Below Galleys, Lavatory (Wet Areas) - Detailed Inspection		HRS		1909.4			2148.4				0
			AFL		573			611				0
			MOS		88.6	19	96	11 Sep 2016	30 Sep 2024*	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532600	Electronic Equipment Rack to Fuselage Upper Attachment Structure (Left) - Detailed Inspection		HRS		4057.8			0				0
			AFL		1184			0				0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532601	Electronic Equipment Rack to Fuselage Upper Attachment Structure (Right) - Detailed Inspection		HRS		4057.8			0				0
			AFL		1184			0				0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532610	Traffic Alert and Collision Avoidance System Antenna Spacer - Detailed Inspection		HRS		957.9			3099.9				0
			AFL		313			871				0
			MOS		42.5		144	15 Jul 2020	31 Jul 2032	31 Aug 2032		
	Airframe		[End Of Month Item] [MOS: +1m/-1m]									
532901	Main Entrance Door Cutout Surround Structure - Ndt Inspection		HRS		4057.8			0				0
			AFL		1184			0				0
			MOS		188.2			24 May 2008				
	Airframe		O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532905	Main Entrance Door Surround Longerons - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
532920	Main Entrance Door Pin Support - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533110	FS465 / FS576 Production Splices - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533120	Fuselage Skins AT Wing Pressure Box Cutout (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533122	Fuselage Skins AT Wing Pressure Box Cutout (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533201	FS 632 Bulkhead - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533202	FS 426 Bulkhead - Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533203	FS 465 Frame Stringer 9 and Above (Left) - Ndt		HRS		4057.8			0			0
	Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533204	FS 465 Frame Stringer 9 and Above (Right) - Ndt		HRS		4057.8			0			0
	Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533205	FS 465 Frame Stringer 9 and Below (Left) - Ndt		HRS		4057.8			0			0
	Inspection		AFL		1184	8000		0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533206	FS 465 Frame Stringer 9 and Below (Right) - Ndt		HRS		4057.8			0			0
	Inspection		AFL		1184	8000		0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533207	FS 576 Frame (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184	8000		0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533208	FS 576 Frame (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184	8000		0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533211	Window Surround Frame Splice - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184	8000		0	8000		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
533215	Baggage Door Redistribution Frames AT FS 694 and FS 734 - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC					O/C				
Airframe												
533220	Pressure Bulkhead Installation Below Floor FS 758 - Ndt Inspection		HRS		4057.8			0			0	
			AFL				7400**		7400		0	
			MOS		188.2				24 May 2008			
Airframe												
533300	Longeron 24 Left and Right FS 632 - FS 758 - Detailed Inspection		HRS		1909.4			2148.4			0	
			AFL		573			611			0	
			MOS		88.7	20	96		10 Sep 2016 30 Sep 2024* 31 Oct 2024			
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
533305	Dorsal Tee - Ndt Inspection		HRS		4057.8			0			0	
			AFL				13000**		13000		0	
			MOS		188.2				24 May 2008			
Airframe												
533309	Longeron 9 and Longeron 13 (Left No. 9) - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC					O/C				
Airframe												
533310	Longeron 9 and Longeron 13 (Right No. 9) - Detailed Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC					O/C				
Airframe												
533315	Longeron 7 and Longeron 15 AT FS 576 (Left No. 7) - Detailed Inspection		HRS		4057.8			0			0	
			AFL				8000**		8000		0	
			MOS		188.2				24 May 2008			
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533316	Longeron 7 and Longeron 15 AT FS 576 (Right No. 7) - Detailed Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											
533319	Longeron 9 and Longeron 13 (Left No. 13) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533320	Longeron 9 and Longeron 13 (Right No. 13) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533321	Longeron 7 and Longeron 15 AT FS 576 (Left No. 15) - Detailed Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											
533322	Longeron 7 and Longeron 15 AT FS 576 (Right No. 15) - Detailed Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											
533330	Stringer Splices AT FS 684 and FS 758 - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533335	Longeron 22 AT FS 417 - FS 426.5 - Detailed Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533400	Bulkhead Installation FS 426 Aft Face - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533405	Lower Bulkhead Stiffeners and Angles AT FS 632 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533410	Torque Box Installation / Connections - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6		144	13 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533411	Support, L MLG Door ACT-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
533412	Support, R MLG Door ACT - Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
533415	Drag Beam Overwing Installation - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533416	Overwing Drag Beam - Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533421	Forward Wing to Fuselage Fitting (Left) - Inspection		HRS		4057.8			0			0
			AFL				7500**		7500		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533422	Forward Wing to Fuselage Fitting (Right) - Inspection		HRS		4057.8			0			0
			AFL								0
			MOS		188.2			24 May 2008	7500**		
Airframe											
533423	Aft Wing to Fuselage Fitting (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533424	Aft Wing to Fuselage Fitting (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533435	BI 6 Forward Wing to Fuselage Attachment Link - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184		8000	0	8000		0
			MOS		188.2			24 May 2008			
Airframe											
533501	Pressure Floor Tension Straps - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
533510	Frame and Pressure Floor Clips - Detailed Inspection		HRS		4057.8			0			0
			AFL				6800**		6800		0
			MOS		188.2			24 May 2008			
Airframe											
533600	Auxiliary Pressure Bulkhead Installation Below Floor FS 684 - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	20	96	10 Sep 2016	30 Sep 2024*	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533605	Auxiliary Pressure Bulkhead Installation Above Floor FS 684 - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533610	Forward Engine Mounts Installation FS 758 - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6		144	13 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533615	Pressure Bulkhead Installation Below Floor FS 758 - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533620	Pressure Bulkhead FS 758 Composite Panels - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9	32	72	03 Sep 2020	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
533701	Cabin Window Ring Frame Windows 1 Thru 5 (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
533702	Cabin Window Ring Frame Windows 1 Thru 5 (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
533705	Window Frame Structure (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
533706	Window Frame Structure (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533801	Baggage Door Cut Out Surround Skin - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533810	Mid Fuselage Cutouts, Exposed to Exterior - Gvi		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533813	Mid Fuselage Cutouts, Covered By Fairings - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
533817	Wing Link Cutout FS 465 (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
533819	Wing Link Cutout FS 465 (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
534000	Aft Engine Mount Frame Structure - Detailed Inspection		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.5		96	15 Jul 2021	31 Jul 2029	31 Aug 2029	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
534001	Baggage Compartment Electronic Equipment Rack FS 689 - FS 698 - Zonal Inspection		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.7		48	10 Jul 2021	31 Jul 2025	31 Aug 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
534005	Forward Engine Mount Upper Bulkhead Fitting (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				5000**		5000		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534006	Forward Engine Mount Upper Bulkhead Fitting (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				5000**		5000		0
			MOS		188.2			24 May 2008			
Airframe											
534011	Aft Engine Mount Upper Bulkhead Fitting (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
534012	Aft Engine Mount Upper Bulkhead Fitting (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
534202	Flat Pressure Bulkhead Forward and Aft Face Above Floor, FS 758 - Special Detailed Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.8		72	05 Sep 2019	30 Sep 2025	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534203	Primary Pressure Bulkhead Composite Panels / Beams and Metallic Structures Above Floor - Detailed Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.8			05 Sep 2019			
			MSC				-				
Airframe											
534310	Stringer Splices AT FS 850 - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
534715	FS 820 Bulkhead - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184		8000	0	8000		0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534910	Aft Fuselage Belly Access Cutouts - Gvi		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
534915	Aft Fuselage Exposed Cutouts - Det Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
534920	Aft Fuselage Covered Cutouts (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
534922	Aft Fuselage Covered Cutouts (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
	Airframe										
535000	Rudder Actuator Attachment - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184		3600	0	3600		0
			MOS		188.2			24 May 2008			
	Airframe										
535020	Cockpit Crossbeam - Ndt Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										
535028	Tail Compartment Above Floor Electrical Junction Boxes - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
539003	Antenna Interface - Detailed Inspection		HRS		2414			1643.8			0
			AFL		716			468			0
			MOS		111.8			05 Oct 2014			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
539004	Lower Antenna and Penetration Interface - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.4		72	20 Jul 2020	31 Jul 2026	31 Aug 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
539005	Upper Antenna and Penetration Interface - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.9		72	03 Aug 2020	31 Aug 2026	30 Sep 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
54 - Nacelles/Pylons											
541005	Pylons External (Left) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541006	Pylons External (Right) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541010	Pylons Internal (Left) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541011	Pylons Internal (Right) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545003	Pylon Leading Edge (Left) - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
545004	Pylon Leading Edge (Right) - Polishing		HRS		0			4057.8			0	
			AFL		0			1184			0	
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
55 - Stabilizers												
551001	Horizontal Stabilizer - Removal / Installation		HRS		4057.8			0			0	
	1159CS50001-804	GA0893	AFL		1184			0			0	
			MOS		188.2			24 May 2008			STORK FOKKER	
Airframe			MSC	O/C								AESP B.V.
551003	Horizontal Stabilizer - General Visual Inspection		HRS		4057.8			0			0	
			AFL		1184	4000		0	4000		0	
			MOS		188.2			24 May 2008				
Airframe												
551005	Horizontal Leading Edge (Left) - Zonal Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
551006	Horizontal Leading Edge (Right) - Zonal Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
551010	Horizontal Stabilizer Box (Left) - Zonal Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									
551011	Horizontal Stabilizer Box (Right) - Zonal Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024		
Airframe			[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551012	Horizontal Stabilizer Assembly (Interior, Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551013	Horizontal Stabilizer Assembly (Interior, Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551014	Horizontal Stabilizer Hinge and Actuator Fitting - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		144	16 Jul 2020	31 Jul 2032	31 Aug 2032	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551015	Horizontal Stabilizer Trailing Edge (Left) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551016	Horizontal Stabilizer Trailing Edge (Right) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	17	96	13 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551018	Horizontal Stabilizer Access Cutouts - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
	Airframe		MOS		188.2			24 May 2008			
551020	Horizontal Stabilizer Pivot Fitting Lugs - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551022	Horizontal Stabilizer Pivot Fitting Bolts - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184		4800	0	4800		0
			MOS		188.2				24 May 2008		
(551022)											
Airframe											
551025	Horizontal Stabilizer Leading Edge Upper and Lower Surfaces (Left) - General Visual Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.7		72	10 Sep 2019	30 Sep 2025	31 Oct 2025	
Airframe											
551026	Horizontal Stabilizer Leading Edge Upper and Lower Surfaces (Right) - General Visual Inspection		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.7		72	10 Sep 2019	30 Sep 2025	31 Oct 2025	
Airframe											
551027	Horizontal Stabilizer Trailing Edge AREA (Elevator Curtains Removed, Left) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1	13	48	28 Aug 2023	30 Sep 2027*	31 Oct 2027	
Airframe											
551028	Horizontal Stabilizer Trailing Edge AREA (Elevator Curtains Removed, Right) - Detailed Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.3	20	48	21 Aug 2023	30 Sep 2027*	31 Oct 2027	
Airframe											
551029	Horizontal Stabilizer Ultrasound / Mobile Automated Scanner (Left) - Ndt Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.2	28	96	26 Aug 2020	30 Sep 2028*	31 Oct 2028	
Airframe											
551030	Horizontal Stabilizer Ultrasound / Mobile Automated Scanner (Right) - Ndt Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41.2	28	96	26 Aug 2020	30 Sep 2028*	31 Oct 2028	
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551031	Horizontal Stabilizer Leading Edge Internal Structure		HRS		4057.8			0			0
	(Leading Edge Removed, Left) - Detailed Inspection		AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551032	Horizontal Stabilizer Leading Edge Internal Structure		HRS		4057.8			0			0
	(Leading Edge Removed, Right) - Detailed Inspection		AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551033	Horizontal Stabilizer Internal Structure (Left) - Special		HRS		957.9			3099.9			0
	Detailed Inspection		AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551034	Horizontal Stabilizer Internal Structure (Right) - Special		HRS		957.9			3099.9			0
	Detailed Inspection		AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551035	Horizontal Stabilizer Internal Skin / Bond Lines (Left) -		HRS		957.9			3099.9			0
	Detailed Inspection		AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551036	Horizontal Stabilizer Internal Skin / Bond Lines (Right) -		HRS		957.9			3099.9			0
	Detailed Inspection		AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551040	Horizontal Stabilizer Lower Bonded Skin - Hand Scan -		HRS		4057.8			0			0
	Left		AFL		1184			0			0
			MOS		188.2				24 May 2008		
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
551041	Horizontal Stabilizer Lower Bonded Skin - Hand Scan - Right		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2			24 May 2008				
			MSC					O/C				
Airframe												
551042	Horizontal Stabilizer Lower Bonded Skin - Permanent Repair - Left		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2			24 May 2008				
			MSC					O/C				
Airframe												
551043	Horizontal Stabilizer Lower Bonded Skin - Permanent Repair - Right		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2			24 May 2008				
			MSC					O/C				
Airframe												
551044	Horizontal Stabilizer Lower Bonded Skin - Time Limited Repair - Left		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		41.1			28 Aug 2020				
			MSC					O/C				
Airframe												
551045	Horizontal Stabilizer Lower Bonded Skin - Time Limited Repair - Right		HRS		957.9			3099.9			0	
			AFL		313			871			0	
			MOS		41.1			28 Aug 2020				
			MSC					O/C				
Airframe												
551109	Horizontal Stabilizer Rub Blocks - General Visual Inspection		HRS		1189.2		3000	2868.6	5868.6	5918.6	0	
			AFL		361			823			0	
			MOS		52.7			10 Sep 2019				
					[HRS: +50/-50]							
Airframe												
551110	Horizontal Stabilizer Rub Blocks - Functional Test		HRS		1189.2		3000	2868.6	5868.6	5918.6	0	
			AFL		361			823			0	
			MOS		52.6			12 Sep 2019				
					[HRS: +50/-50]							
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551111	Elevator Upper Surface (External) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551113	Horizontal Stabilizer Leading Edge - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551201	Horizontal Stabilizer Internal Corrosion Inhibiting Compound (Left) - Restore		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	26 Aug 2024	26 Nov 2024	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
551202	Horizontal Stabilizer Internal Corrosion Inhibiting Compound (Right) - Restore		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		48**	23 Sep 2008	26 Aug 2024	26 Nov 2024	
	Airframe		[End Of Month Item] [MOS: +3m/-3m]								
552001	Elevator External for Delamination (Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
552002	Elevator External for Delamination (Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
552005	Elevator Hinge (Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	17 Jul 2020	31 Jul 2028	31 Aug 2028	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
552006	Elevator Hinge (Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	17 Jul 2020	31 Jul 2028	31 Aug 2028	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
552010	Elevator Skins and Hinges (Left) - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184		1800	0	1800		0
			MOS		188.2			24 May 2008			
Airframe											
552012	Elevator Hinge Bolts and Sleeves - Detailed Inspection		HRS		4057.8			0			0
			AFL				8300**		8300		0
			MOS		188.2			24 May 2008			
Airframe											
552015	Elevator Skins and Hinges (Right) - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184		1800	0	1800		0
			MOS		188.2			24 May 2008			
Airframe											
553001	Vertical Stabilizer		HRS		4057.8			0			0
	1159CS50003-807	GA0893	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe			MSC			O/C				AEROSPACE
553005	Vertical Stabilizer Leading Edge Lower Section - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553010	Vertical CAP, SATCOM and Bullet Fairing - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	16	96	14 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
553013	Vertical Stabilizer Leading Edge - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553015	Vertical Stabilizer Box Section Internal Structure - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553016	Vertical Stabilizer Box Section Internal Flight Controls - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	16	96	14 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553020	Vertical Stabilizer Rear Beam Aft Face - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	19	96	11 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553025	Vertical Stabilizer Assembly Internal - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553030	Vertical Stabilizer Rudder Support Structure - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
553035	Vertical Stabilizer Upper Boomerang Fittings - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
553036	Vertical Fin to Fuselage- General Visual Inspection		HRS		4057.8			0			0
			AFL		1184		8000	0	8000		0
			MOS		188.2				24 May 2008		
Airframe											
553039	Fuselage Attach Boomerang Fittings - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
553040	Vertical Stabilizer - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184		4000	0	4000		0
			MOS		188.2				24 May 2008		
Airframe											
553042	Vertical Stabilizer Forward STAR Fitting - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
553044	Vertical Stabilizer Aft STAR Fitting - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
553048	Vertical Stabilizer Access Cutouts - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2				24 May 2008		
Airframe											
553410	Vertical Stabilizer Rear Beam AT Pivot Fitting - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
Airframe											
554005	Rudder External for Delamination - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	16 Jul 2020	31 Jul 2028	31 Aug 2028	
Airframe [End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
554010	Rudder Assembly Front Beam Internal - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.4		144	18 Jul 2020	31 Jul 2032	31 Aug 2032	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
554015	Rudder Assembly Hinges, Bushing and Brackets - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192**	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
554020	Rudder Hinge Fittings Bolts and Sleeves - Detailed Inspection		HRS		4057.8			0			0
			AFL				8300**		8300		0
			MOS		188.2				24 May 2008		
Airframe											
554022	Rudder Skins and Hinges - General Visual Inspection		HRS		4057.8			0			0
			AFL		1184		1800	0	1800		0
			MOS		188.2				24 May 2008		
Airframe											
56 - Windows											
560001	Emergency Window Release Mechanism - Functional Test		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42		31	48	30 Jul 2020	31 Aug 2024*	30 Sep 2024
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
561005	Windshield (Left) - Removal / Installation		HRS		2248.8			1809			0
	1159SCB5102-9	13350H9064	AFL		684			500			0
			MOS		104.7				09 May 2015		PPG INDUSTRIES INC
			MSC					O/C			
Airframe											
561006	Windshield (Right) - Removal / Installation		HRS		751.7			3306.1			0
	1159SCB5102-15	22012H5102	AFL		247			937			0
			MOS		23.5				16 Feb 2022		N/A
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
561011	Side Windows (Left) - Removal / Installation		HRS		2130.7			1927.1			0
	1159SCB5100-9	13317H6048	AFL		650			534			0
			MOS	TSN:1	97.9			03 Dec 2015			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
561012	Side Windows (Right) - Removal / Installation		HRS		1189.2			2868.6			0
	1159SCB5100-11	1834H7000	AFL		361			823			0
			MOS	TSN:8	52.7			10 Sep 2019			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
561101	Windshield Weather Seal (Hump Seal) (Left) - Detailed Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.1		24	28 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
561102	Windshield Weather Seal (Hump Seal) (Right) - Detailed Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			AFL		44			1140			0
			MOS		5.1		24	28 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
562001	Fixed Cabin Window (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802699	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562002	Fixed Cabin Window (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802715	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562003	Fixed Cabin Window (Left No. 3) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802687	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562004	Fixed Cabin Window (Left No. 4) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802645	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562005	Fixed Cabin Window (Left No. 5) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802666	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562006	Fixed Cabin Window (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802718	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562007	Fixed Cabin Window (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802692	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562008	Fixed Cabin Window (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802672	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562009	Fixed Cabin Window (Right No. 4) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802652	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562010	Fixed Cabin Window (Right No. 5) - Removal / Installation		HRS		4057.8			0			0
	1159SCCE500-23	0802674	AFL		1184			0			0
			MOS		188.2			24 May 2008			PPG INDUSTRIES
	Airframe		MSC					O/C			INC
Notes: VERIFIED BY Q124646											
562011	Emergency Exit Cabin Window (Left No. 1) - Removal / Installation		HRS	TSN:3100	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159CE50001-79	0802829	MOS	TSN:148	41.2			25 Aug 2020			
	Airframe		MSC					O/C			
562012	Emergency Exit Cabin Window (Left No. 2) - Removal / Installation		HRS	TSN:3100.4	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159CE50001-79	0802823	MOS	TSN:147	42			30 Jul 2020			N/A
	Airframe		MSC					O/C			
562013	Emergency Exit Cabin Window (Right No. 1) - Removal / Installation		HRS	TSN:3100	957.9			3099.9			0
			AFL	TSN:871	313			871			0
	1159CE50001-79	0802785	MOS	TSN:148	41.2			25 Aug 2020			
	Airframe		MSC					O/C			
562014	Emergency Exit Cabin Window (Right No. 2) - Removal / Installation		HRS		957.9			3099.9			0
			AFL		313			871			0
	1159CE50001-79	0802794	MOS	TSN:148	41.2			25 Aug 2020			
	Airframe		MSC					O/C			
562015	Overwing Emergency Exits - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6	19	96	11 Sep 2016 30 Sep 2024* 31 Oct 2024			
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562021	Fixed Cabin Window Inner Pane (Left No. 1) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08080H8681	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											
562022	Fixed Cabin Window Inner Pane (Left No. 2) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08080H8600	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											
562023	Fixed Cabin Window Inner Pane (Left No. 3) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08028H1638	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											
562024	Fixed Cabin Window Inner Pane (Left No. 4) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08070H7167	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											
562025	Fixed Cabin Window Inner Pane (Left No. 5) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08080H8602	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											
562026	Fixed Cabin Window Inner Pane (Right No. 1) - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCCE500-19	08080H8672	MOS		188.2			24 May 2008			PPG INDUSTRIES
			MSC								INC
Airframe											
Notes: VERIFIED BY Q124646											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562027	Fixed Cabin Window Inner Pane (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08080H8609	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
Notes: VERIFIED BY Q124646											
562028	Fixed Cabin Window Inner Pane (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08080H8608	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
Notes: VERIFIED BY Q124646											
562029	Fixed Cabin Window Inner Pane (Right No. 4) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08070H7161	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
Notes: VERIFIED BY Q124646											
562030	Fixed Cabin Window Inner Pane (Right No. 5) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08028H1644	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
Notes: VERIFIED BY Q124646											
562031	Emergency Exit Cabin Window Pane (Left Inner No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08077H8139	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562032	Emergency Exit Cabin Window Pane (Left Inner No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08037H2808	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562033	Emergency Exit Cabin Window Pane (Right Inner No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08098H1495	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562034	Emergency Exit Cabin Window Pane (Right Inner No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-19	08070H7157	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562041	Fixed Cabin Window Outer Pane (Left No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562042	Fixed Cabin Window Outer Pane (Left No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562043	Fixed Cabin Window Outer Pane (Left No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562044	Fixed Cabin Window Outer Pane (Left No. 4) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562045	Fixed Cabin Window Outer Pane (Right No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562046	Fixed Cabin Window Outer Pane (Right No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562047	Fixed Cabin Window Outer Pane (Right No. 3) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562048	Fixed Cabin Window Outer Pane (Right No. 4) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562049	Emergency Exit Cabin Window Pane (Left Outer No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562050	Emergency Exit Cabin Window Pane (Left Outer No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562051	Emergency Exit Cabin Window Pane (Right Outer No. 1) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											
562052	Emergency Exit Cabin Window Pane (Right Outer No. 2) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCCE500-21	SN-UNKNOWN	MOS		188.2			24 May 2008			PPG INDUSTRIES INC
			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562101	Cabin Window (Left No. 1) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562102	Cabin Window (Left No. 2) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562103	Cabin Window (Left No. 3) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562104	Cabin Window (Left No. 4) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562105	Cabin Window (Left No. 5) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562106	Cabin Window (Right No. 1) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562107	Cabin Window (Right No. 2) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562108	Cabin Window (Right No. 3) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562109	Cabin Window (Right No. 4) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562110	Cabin Window (Right No. 5) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562111	Cabin Window (Left Emergency No. 1) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562112	Cabin Window (Left Emergency No. 2) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562113	Cabin Window (Right Emergency No. 1) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562114	Cabin Window (Right Emergency No. 2) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
562115	Cabin Windows - Leak Check		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42			30 Jul 2020			
	Airframe		MSC					O/C			

57 - Wings

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570001	Wing Assy, Left		HRS		4057.8			0			0
	1159W50002-41	893	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
570002	Wing Assy, Right		HRS		4057.8			0			0
	1159W50002-42	893	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
570005	Wing Upper Surface View from on Wing (Left) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570006	Wing Upper Surface View from on Wing (Right) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570009	Wing Lower Surface (Left) - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570010	Wing Lower Surface (Right) - Zonal Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
570013	Upper Wing Extension BI 542 - BI 545 (View from on Wing) {Left} - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570014	Upper Wing Extension BI 542 - BI 545 (View from on Wing) {Right} - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570015	Lower Wing Extension BI 542 - BI 545 (View from Ground) {Left} - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5	13	24	16 Aug 2023	31 Aug 2025*	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570016	Lower Wing Extension BI 542 - BI 545 (View from Ground) {Right} - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.5	13	24	16 Aug 2023	31 Aug 2025*	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570017	Wing Rear Beam AT Aileron (Ws 386 - Ws 479) (Left) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570018	Wing Rear Beam AT Aileron (Ws 386 - Ws 479) (Right) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570200	Wing Box Structure Forward Spar Through Gap Bands (Left) - General Visual Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570201	Wing Box Structure Forward Spar Through Gap Bands (Right) - General Visual Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	21	96	09 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570205	Fuel Tank Internal (Left) - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	15	96	15 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570206	Fuel Tank Internal (Right) - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	16	96	14 Sep 2016	30 Sep 2024*	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
571110	Lower Cover Splice and Coaming Stringers (Left) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										
571112	Lower Cover Splice and Coaming Stringers (Right) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										
571200	Rear Spar - Inspection		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
	Airframe		MSC O/C								
571201	Rear Spar BI 6 - BI 35 (Left) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										
571202	Rear Spar BI 6 - BI 35 (Right) - Ndt Inspection		HRS				30000**		30000		0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
	Airframe										
571203	BI 0 Lower Rib AT Rear Spar - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571204	BI 0 Lower Rib AT Rear Spar (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571207	BI 6 Rib Web AT Forward Fitting (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571208	BI 6 Rib Web AT Forward Fitting (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571209	BI 18.5 Rib (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571210	BI 18.5 Rib (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571211	BI 35.8 Rib AT Wing to Fuselage Fitting (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571212	BI 35.8 Rib AT Wing to Fuselage Fitting (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
571220	Rear Spar Sponson and Trailing Edge Extension (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571222	Rear Spar Sponson and Trailing Edge Extension (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
571225	Rear Spar Covered Areas Outboard of BI 35 (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
571227	Rear Spar Covered Areas Outboard of BI 35 (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
571301	Rear Spar AT Spoiler Actuator Tension Fittings (Left) - Ndt Inspection		HRS		4057.8		20000	0	20000		0
			AFL		1184		8000	0	8000		0
			MOS		188.2			24 May 2008			
Airframe											
571302	Rear Spar AT Spoiler Actuator Tension Fittings (Right) - Ndt Inspection		HRS		4057.8		20000	0	20000		0
			AFL		1184		8000	0	8000		0
			MOS		188.2			24 May 2008			
(571302)											
Airframe											
571401	Lower Sponson Doubler (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				6000**		6000		0
			MOS		188.2			24 May 2008			
Airframe											
571402	Lower Sponson Doubler (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				6000**		6000		0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571403	Rbs 109.5 Sponson Rib (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2				24 May 2008		
Airframe											
571404	Rbs 109.5 Sponson Rib (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2				24 May 2008		
Airframe											
571405	BI 91.06 Sponson Rib (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											
571406	BI 91.06 Sponson Rib (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											
571420	Sponson Lugs (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											
571422	Sponson Lugs (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											
571601	Wing to Fuselage Attach Corrosion Resistant Steel / Titanium Fitting - Detailed Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.5	16	96	14 Sep 2016	30 Sep 2024*	31 Oct 2024	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
571701	BI 0 Lower Wing Skin Splice AT Front Spar (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2				24 May 2008		
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571702	BI 0 Lower Wing Skin Splice AT Front Spar (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
571703	BI 0 Lower Wing Centerline Splice AT Front Spar (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
571704	BI 0 Lower Wing Centerline Splice AT Front Spar (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
571705	BI 0 Lower Wing Skin Splice AT Rear Spar (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
571706	BI 0 Lower Wing Skin Splice AT Rear Spar (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				
Airframe											
571707	Rear Beam Web AT BI 91 Sponson Rib Fastener Holes - Ndt Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
Airframe											
571709	External Rear Beam Web AT BI 49 - Ndt Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
573001	Winglet (Left) - Removal / Installation		HRS		4057.8			0			0
	1159W57131-21	0395	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
573002	Winglet (Right) - Removal / Installation		HRS		4057.8			0			0
	1159W57131-22	0396	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VER BY PQ211											
573005	Wing Extension BI 542 - BI 545 (Left) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573006	Wing Extension BI 542 - BI 545 (Right) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573010	Winglet Blade (View from Ground) {Left} - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6	31	48	13 Jul 2020	31 Aug 2024*	30 Sep 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
573011	Winglet Blade (View from Ground) {Right} - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.6		48	13 Jul 2020	31 Jul 2024	31 Aug 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
574001	Leading Edge, L Wing #1		HRS		4057.8			0			0
	1159W56301-91	921	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574002	Leading Edge, L Wing #2		HRS		4057.8			0			0
	1159W56002-9	929	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574003	Leading Edge, L Wing #3		HRS		4057.8			0			0
	1159W56003-9	924	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574004	Leading Edge, L Wing #4		HRS		4057.8			0			0
	1159W56004-15	929	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574005	Leading Edge, L Wing #5		HRS		4057.8			0			0
	1159W56005-9	928	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574006	Leading Edge, L Wing #6		HRS		4057.8			0			0
	1159W56402-49	912	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574007	Leading Edge, R Wing #1		HRS		4057.8			0			0
	1159W56301-92	921	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574008	Leading Edge, R Wing #2		HRS		4057.8			0			0
	1159W56002-10	924	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574009	Leading Edge, R Wing #3		HRS		4057.8			0			0
	1159W56003-10	922	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574010	Leading Edge, R Wing #4		HRS		4057.8			0			0
	1159W56004-16	915	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574011	Leading Edge, R Wing #5		HRS		4057.8			0			0
	1159W56005-10	923	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574012	Leading Edge, R Wing #6		HRS		4057.8			0			0
	1159W56402-50	906	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY PQ 040											
574013	Wing Leading Edge (Left) - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
574014	Wing Leading Edge (Right) - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
574015	Wing Leading Edge External BI 44.0 - BI 529 Inboard of Navigation Light (Left) - Zonal Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	35	24	05 Jun 2023	31 Jul 2025*	31 Aug 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574016	Wing Leading Edge External BI 44.0 - BI 529 Inboard of Navigation Light (Right) - Zonal Inspection		HRS		192.1			3865.7			0
			AFL		78			1106			0
			MOS		7.8	35	24	05 Jun 2023	31 Jul 2025*	31 Aug 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
574017	Wing Leading Edge With Gap Bands Removed (Left) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
574018	Wing Leading Edge With Gap Bands Removed (Right) - Zonal Inspection		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7	22	96	08 Sep 2016	30 Sep 2024*	31 Oct 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
574019	Wing Leading Edges Removed (Left) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
574020	Wing Leading Edges Removed (Right) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
575001	Wing Trailing Edge (Left) - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		24	29 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
575002	Wing Trailing Edge (Right) - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		24	29 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
575003	Wing Rear Beam (Left) - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		24	29 Aug 2023	31 Aug 2025	30 Sep 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575004	Wing Rear Beam (Right) - Zonal Inspection		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		5.1		24	29 Aug 2023	31 Aug 2025	30 Sep 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575005	Wing Box Section (Left) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
575006	Wing Box Section (Right) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
575007	Wing Tank Internal Inboard 3 Panels Each Wing (Left) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6		24	11 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575008	Wing Tank Internal Inboard 3 Panels Each Wing (Right) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.6		24	11 Jun 2022	30 Jun 2024	31 Jul 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
575013	Flap Track D and Flap Track A Down Load Catch (Left) - Inspection / Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC O/C								
575014	Flap Flight Load Rollers AT Tracks A, B, C and D (Left) - Inspection / Check		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.5			15 Jul 2021			
	Airframe		MSC O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
575015	Flap Track D and Flap Track A Down Load Catch (Right) - Inspection / Check		HRS		857.7			3200.1			0	
			AFL		280			904			0	
			MOS		30.4			18 Jul 2021				
			MSC					O/C				
Airframe												
575021	Wing Rear Beam (Left Enhanced) - Zonal Inspection		HRS		616			3441.8			0	
			AFL		220			964			0	
			MOS		19.7			24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]											
575022	Wing Rear Beam (Right Enhanced) - Zonal Inspection		HRS		616			3441.8			0	
			AFL		220			964			0	
			MOS		19.7			24	08 Jun 2022	30 Jun 2024	31 Jul 2024	
Airframe	[End Of Month Item] [MOS: +1m/-1m]											
575101	Flap B and C Track (Left B Track) - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC						O/C			
Airframe												
575102	Flap B and C Track (Right B Track) - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC						O/C			
Airframe												
575103	Flap B and C Track (Left C Track) - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC						O/C			
Airframe												
575104	Flap B and C Track (Right C Track) - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC						O/C			
Airframe												
575105	Flap A and D Track (Left A Track) - Ndt Inspection		HRS		4057.8			0			0	
			AFL		1184			0			0	
			MOS		188.2				24 May 2008			
			MSC						O/C			
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575106	Flap A and D Track (Right A Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575107	Flap A and D Track (Left D Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575108	Flap A and D Track (Right D Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575111	Flap B and C Track Lower Flange (Left B Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL				7200**		7200		0
			MOS		188.2			24 May 2008			
	Airframe										
575112	Flap B and C Track Lower Flange (Right B Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL				7200**		7200		0
			MOS		188.2			24 May 2008			
	Airframe										
575113	Flap B and C Track Lower Flange (Left C Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL				7200**		7200		0
			MOS		188.2			24 May 2008			
	Airframe										
575114	Flap B and C Track Lower Flange (Right C Track) - Ndt Inspection		HRS		4057.8			0			0
			AFL				7200**		7200		0
			MOS		188.2			24 May 2008			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575115	Flap D Track Lower Flange (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575116	Flap D Track Lower Flange (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575205	Left Wing Box Section - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
	Airframe		MSC					O/C			
575206	Right Wing Box Section - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3			23 Sep 2008			
	Airframe		MSC					O/C			
575210	Flap Front Spar AT A, B, C and D Tracks (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575212	Flap Front Spar AT A, B, C and D Tracks (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
575215	Flap Front Spar AT Spoiler Doors (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											
575217	Flap Front Spar AT Spoiler Doors (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				8000**		8000		0
			MOS		188.2			24 May 2008			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575220	Flap Rear Spar AT B, C and D Track Cutouts (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2				24 May 2008		
Airframe											
575222	Flap Rear Spar AT B, C and D Track Cutouts (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				12000**		12000		0
			MOS		188.2				24 May 2008		
Airframe											
575601	Trailing Edge Flight Control Attach Hinge / Support Fittings (Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42		96	31 Jul 2020	31 Jul 2028	31 Aug 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
575602	Trailing Edge Flight Control Attach Hinge / Support Fittings (Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.3		96	23 Jul 2020	31 Jul 2028	31 Aug 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
576005	Aileron Ballast Weights (Left) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	14 Jul 2020	31 Jul 2028	31 Aug 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
576006	Aileron Ballast Weights (Right) - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	14 Jul 2020	31 Jul 2028	31 Aug 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
576010	Aileron Tab / Spoilers External for Delamination - Detailed Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		96	17 Jul 2020	31 Jul 2028	31 Aug 2028	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
577001	Spoiler Hinge Fitting (Left Ground) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577002	Spoiler Hinge Fitting (Right Ground) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577003	Spoiler Hinge Fitting (Left Inboard Flight) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577004	Spoiler Hinge Fitting (Right Inboard Flight) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577005	Spoiler Hinge Fitting (Left Outboard Flight) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577006	Spoiler Hinge Fitting (Right Outboard Flight) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577210	Spoiler Support Hinges (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577211	Spoiler Support Hinges (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
577215	Spoiler Drive Hinges (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
577216	Spoiler Drive Hinges (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
71 - Power Plant											
710001	Engine (Left) - Removal / Installation		HRS		4057.8			0			0
	BR700-710C4-11		AFL	15499	1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			ROLLS ROYCE CANADA LTD
710002	Engine (Right) - Removal / Installation		HRS		4057.8			0			0
	BR700-710C4-11		AFL	15500	1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			ROLLS ROYCE CANADA LTD
710003	No. 1 Engine - Engine Performance Run		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
710003 (710004)	No. 2 Engine - Engine Performance Run		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
710005	No. 1 Engine - Engine Midlife Inspection		HRS		4057.8		4000	0	4000	4250	0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		[HRS: +250/-250]								

Notes: PN: BR700-710C4-11 SN: 15499. ENGINE DECLARED HARD TIME

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710005 (710006)	No. 2 Engine - Engine Midlife Inspection		HRS		4057.8		4000	0	4000	4250	0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
Engine			[HRS: +250/-250]								
Notes: PN: BR700-710C4-11 SN: 15500. ENGINE DECLARED HARD TIME											
710009	No. 1 Engine - Engine Overhaul		HRS		4057.8		8000	0	8000	8250	0
	BR700-710C4-11	15499	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD.
Engine			[HRS: +250/-250]								
Notes: ENGINE DECLARED HARD TIME											
710009 (710010)	No. 2 Engine - Engine Overhaul		HRS		4057.8		8000	0	8000	8250	0
	BR700-710C4-11	15500	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD.
Engine			[HRS: +250/-250]								
Notes: ENGINE DECLARED HARD TIME											
710011	No. 1 Engine - Engine Run - Pre-Operational Checks		HRS		2176.4				1881.4		0
			ENC		663				521		0
			MOS		100.5				15 Sep 2015		
Engine			MSC				O/C				
710011 (710012)	No. 2 Engine - Engine Run - Pre-Operational Checks		HRS		2176.4				1881.4		0
			ENC		663				521		0
			MOS		100.5				15 Sep 2015		
Engine			MSC				O/C				
710013	No. 1 Engine - Engine Run - Checklist		HRS		592				3465.8		0
			ENC		217				967		0
			MOS		18.9				04 Jul 2022		
Engine			MSC				O/C				
710013 (710014)	No. 2 Engine - Engine Run - Checklist		HRS		498.9				3558.9		0
			ENC		186				998		0
			MOS		15.9				04 Oct 2022		
Engine			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710015	No. 1 Engine - Engine Test 1 - Wet Motor Operation Leak Check		HRS		13.4			4044.4			0
			ENC		4			1180			0
			MOS		1.3			21 Dec 2023			
			MSC					O/C			
Engine											
710015 (710016)	No. 2 Engine - Engine Test 1 - Wet Motor Operation Leak Check		HRS		13.4			4044.4			0
			ENC		4			1180			0
			MOS		1.3			21 Dec 2023			
			MSC					O/C			
Engine											
710017	No. 1 Engine - Engine Run Leak Check Test 2A - Lp Fuel System / Oil System		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC					O/C			
Engine											
710017 (710018)	No. 2 Engine - Engine Run Leak Check Test 2A - Lp Fuel System / Oil System		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC					O/C			
Engine											
710019	No. 1 Engine - Engine Run Leak Check Test 2B - Hp Fuel System		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC					O/C			
Engine											
710019 (710020)	No. 2 Engine - Engine Run Leak Check Test 2B - Hp Fuel System		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC					O/C			
Engine											
710021	Engine Test 3A (Left) - Thrust Reverser Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8			07 Jun 2022			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710022	Engine Test 3A (Right) - Thrust Reverser Check		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8			07 Jun 2022			
	Airframe		MSC					O/C			
710023	Engine Test 3B (Left) - Thrust Reverser / Line Replacement Unit Leak Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
710024	Engine Test 3B (Right) - Thrust Reverser / Line Replacement Unit Leak Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
710025	No. 1 Engine - Engine Test 4 - Engine Power Assurance Check		HRS		2414			1643.8			0
			ENC		716			468			0
			MOS		111.8			05 Oct 2014			
	Engine		MSC					O/C			
710025 (710026)	No. 2 Engine - Engine Test 4 - Engine Power Assurance Check		HRS		2414			1643.8			0
			ENC		716			468			0
			MOS		111.8			05 Oct 2014			
	Engine		MSC					O/C			
710027	No. 1 Engine - Engine Test 5 - Pretested Replacement Engine Test		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
710027 (710028)	No. 2 Engine - Engine Test 5 - Pretested Replacement Engine Test		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710029	No. 1 Engine - Engine Test 6 - Vibration Survey		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
	Engine		MSC						O/C		
710029 (710030)	No. 2 Engine - Engine Test 6 - Vibration Survey		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.3			21 Jan 2024			
	Engine		MSC						O/C		
710031	No. 1 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC						O/C		
710031 (710032)	No. 2 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC						O/C		
710033	No. 1 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance (Alternate)		HRS		4048.2			9.6			0
			ENC		1179			5			0
			MOS		188			30 May 2008			
	Engine		MSC						O/C		
710033 (710034)	No. 2 Engine - Engine Test 7 - Low-Pressure Compressor (Fan) Trim Balance (Alternate)		HRS		4048.2			9.6			0
			ENC		1179			5			0
			MOS		188			30 May 2008			
	Engine		MSC						O/C		
710035	No. 1 Engine - Low-Pressure Compressor (Fan) Blade SET - RE-Index		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC						O/C		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710035 (710036)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8			0			0
	SET - RE-Index		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
710037	No. 1 Engine - Engine Test 9 - Full Authority Digital Engine		HRS		1654.7			2403.1			0
	Control (Fadec) Operational Test		ENC		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC							O/C	
Engine											
710037 (710038)	No. 2 Engine - Engine Test 9 - Full Authority Digital Engine		HRS		1654.7			2403.1			0
	Control (Fadec) Operational Test		ENC		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC							O/C	
Engine											
710039	No. 1 Engine - Cockpit Engine Vibration Monitor (EVM)		HRS		0			4057.8			0
	Card - Vibration Run		ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC							O/C	
Engine											
710039 (710040)	No. 2 Engine - Cockpit Engine Vibration Monitor (EVM)		HRS		0			4057.8			0
	Card - Vibration Run		ENC		0			1184			0
			MOS		.3			21 Jan 2024			
			MSC							O/C	
Engine											
710055	No. 1 Engine - Engine Health Monitoring		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
710055 (710060)	No. 2 Engine - Engine Health Monitoring		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710061	No. 1 Engine - Engine Maintenance Program Declaration		HRS		4048.2			9.6			0
			ENC		1179			5			0
			MOS		184.3			23 Sep 2008			
Engine											
Notes: ENGINE DECLARED HARD TIME											
710061 (710062)	No. 2 Engine - Engine Maintenance Program Declaration		HRS		4048.2			9.6			0
			ENC		1179			5			0
			MOS		184.3			23 Sep 2008			
Engine											
Notes: ENGINE DECLARED HARD TIME											
711001	Inlet Cowl (Left) - Removal / Installation		HRS		4057.8			0			0
	04C0001-019	GVSP199	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				AIRFRAME COMPONENT & REPAIR INC
Airframe											
711002	Inlet Cowl (Right) - Removal / Installation		HRS		4057.8			0			0
	04C0001-020	GVSP199	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC				O/C				AIRFRAME COMPONENT & REPAIR INC
Airframe											
711003	Inlet Cowl Aerodynamic Surfaces (Left) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
			[HRS: +50/-50]								
Airframe											
711004	Inlet Cowl Aerodynamic Surfaces (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711005	Cowl Fasteners and Attachment Features (Left) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			29 Dec 2023			
	Airframe		[HRS: +50/-50]								
711006	Cowl Fasteners and Attachment Features (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711007	Inlet Cowl Rear Bulkhead (Left) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711008	Inlet Cowl Rear Bulkhead (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711015	Fixed Cows (Left) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711016	Fixed Cows (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711017	Apron, L Engine Fixed		HRS		4057.8			0			0
	04E2001-001	GVSP199/SB3567	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711018	Apron, R Engine Fixed		HRS		4057.8			0			0
	04E0002-027	GVSP199/SB3568	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
711019	Lower Cowl Door (Left) - Removal / Installation		HRS	TSN:1643.8	2414			1643.8			0
	04D4002-001	GVSP197/SB3539	AFL	TSN:468	716			468			0
			MOS	TSN:77	111.8			05 Oct 2014			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
711020	Lower Cowl Door (Right) - Removal / Installation		HRS		2414			1643.8			0
	04D4003-001	SN-UNKNOWN	AFL		716			468			0
			MOS		111.8			05 Oct 2014			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
711021	Upper Cowl Door (Left) - Removal / Installation		HRS		4057.8			0			0
	04D4001-001	GVSP197/SB3537	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
711022	Upper Cowl Door (Right) - Removal / Installation		HRS		4057.8			0			0
	04D4001-002	GVSP197/SB3538	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
711109	Inlet Cowl Lipskin (Left) - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711110	Inlet Cowl Lipskin (Right) - Polishing		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.2		6	25 Jan 2024	31 Jul 2024	31 Aug 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711301	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (Viewed from Ground) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711302	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (Viewed from Ground) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		20		24	31 May 2022	31 May 2024	30 Jun 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711305	Powerplant / Nacelle External (View from Platform) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		88.7		96	08 Sep 2016	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711306	Powerplant / Nacelle External (View from Platform) - Zonal Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		88.7		96	08 Sep 2016	30 Sep 2024	31 Oct 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711310	Powerplant Nose Cows Internal (Left) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		144	16 Jul 2020	31 Jul 2032	31 Aug 2032	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
711311	Powerplant Nose Cows Internal (Right) - Zonal Inspection		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		42.5		144	16 Jul 2020	31 Jul 2032	31 Aug 2032	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711315	Powerplant and Nacelle Doors Internal (Left) - Zonal Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
711316	Powerplant and Nacelle Doors Internal (Right) - Zonal Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1.1			28 Dec 2023			
	Airframe		[HRS: +50/-50]								
712011	Chatterproof Bolt (Left Upper) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
712015	Chatterproof Bolt (Left Lower) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
712020	Chatterproof Bolt (Right Upper) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
712024	Chatterproof Bolt (Right Lower) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
712101	Mount, L Engine Fwd Trunnion		HRS		4057.8			0			0
	1159B51971-7	0261	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC				O/C				AEROSPACE

Notes: FOR Q311215

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712102	Mount, R Engine Fwd Trunnion		HRS		4057.8			0			0
	1159B51971-8	0254	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712103	Forward Engine Mount (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712104	Forward Engine Mount (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			
712105	Forward Upper Engine Link (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCP570-1	5172	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHASE WALTON ELASTOMERS
	Airframe		MSC					O/C			
712106	Forward Upper Engine Link (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCP570-1	5175	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHASE WALTON ELASTOMERS
	Airframe		MSC					O/C			
712107	Forward Lower Engine Link (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCP570-1	5173	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHASE WALTON ELASTOMERS
	Airframe		MSC					O/C			
712108	Forward Lower Engine Link (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCP570-1	5176	AFL		1184			0			0
			MOS		188.2			24 May 2008			CHASE WALTON ELASTOMERS
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712109	Link Assemblies (Engine Removed) (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712110	Link Assemblies (Engine Removed) (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712111	Forward Upper Fuselage Link (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159BM51245-5	0046957SIZE-005	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712112	Forward Upper Fuselage Link (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159BM51245-5	051139-003	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712113	Pin, Lh Fuselage/Engine Mount		HRS		4057.8			0			0
			AFL		1184			0			0
	1159BM51246-13	316215-25	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712114	Pin, Rh Fuselage/Engine Mount		HRS		4057.8			0			0
			AFL		1184			0			0
	1159BM51246-13	316215-28	MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712115	Pin, Lh Fuselage/Engine Link		HRS		4057.8			0			0
	1159BM51246-13	0707021-007	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712116	Pin, Rh Fuselage/Engine Link		HRS		4057.8			0			0
	1159BM51246-13	316215-29	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712117	CAP, Lh Beam Brace/Trunnion		HRS		4057.8			0			0
	1159BM51248-11	316221-17	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712118	CAP, Rh Beam Brace/Trunnion		HRS		4057.8			0			0
	1159BM51248-11	316221-18	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712119	CAP, Lh Fuselage/Beam Brace		HRS		4057.8			0			0
	1159BM51248-11	316221-91	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712120	CAP, Rh Fuselage/Beam Brace		HRS		4057.8			0			0
	1159BM51248-11	316221-32	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

712121	Pin, Lh Trunnion/Eng Link UPR		HRS		4057.8			0			0
	1159BM51247-11	E4521-247	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

712122	Pin, Rh Trunnion/Eng Link UPR		HRS		4057.8			0			0
	1159BM51247-11	E4521-460	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

712123	Pin, Lh Trunnion/Eng Link Lwr		HRS		4057.8			0			0
	1159BM51247-11	E4521-253	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

712124	Pin, Rh Trunnion/Eng Link Lwr		HRS		4057.8			0			0
	1159BM51247-11	991054-124	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

712125	CAP, Lh Trunnion/Eng Link UPR		HRS		4057.8			0			0
	1159BM51249-11	045	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

712126	CAP, Rh Trunnion/Eng Link UPR		HRS		4057.8			0			0
	1159BM51249-11	140	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

Notes: VERIFIED BY Q311215

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712127	CAP, Lh Trunnion/Eng Link Lwr		HRS		4057.8			0			0
	1159BM51249-11	103	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: VERIFIED BY Q311215											
712128	CAP, Rh Trunnion/Eng Link Lwr		HRS		4057.8			0			0
	1159BM51249-11	055	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: VERIFIED BY Q311215											
712129	Pin, Lh Link/Engine Mount		HRS		4057.8			0			0
	1159BM51246-15	0707022-005	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712130	Pin, Rh Link/Engine Mount		HRS		4057.8			0			0
	1159BM51246-15	0707022-034	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712131	CAP, Lh Trunnion/Fuselage Lwr		HRS		4057.8			0			0
	1159BM51248-11	316221-53	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712132	CAP, Rh Trunnion/Fuselage Lwr		HRS		4057.8			0			0
	1159BM51248-11	316221-58	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712133	Forward Upper Engine Link (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712134	Forward Upper Engine Link (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712137	Forward Upper Fueselage Link (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				2700**		2700		0
			MOS		188.2			24 May 2008			
	Airframe										
712138	Forward Upper Fueselage Link (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				2700**		2700		0
			MOS		188.2			24 May 2008			
	Airframe										
712139	Forward Engine Mount, PT.F (Lug A) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712140	Forward Engine Mount, PT.F (Lug A) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712141	Forward Engine Mount, PT.E (Lug B) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712142	Forward Engine Mount, PT.E (Lug B) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712143	Forward Engine Mount, PT.C (Lug C) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712144	Forward Engine Mount, PT.C (Lug C) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712145	Forward Engine Mount, PT.G (Lug D) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712146	Forward Engine Mount, PT.G (Lug D) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712147	Forward Engine Mount, PT.N (Lug E) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712148	Forward Engine Mount, PT.N (Lug E) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712149	Forward Engine Mount, PT.U (Lug F) (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712150	Forward Engine Mount, PT.U (Lug F) (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712160	Forward Engine Mount Spherical Bearings and Bearing Inner and Outer Housings (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008 30 Sep 2024			
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712162	Forward Engine Mount Spherical Bearings and Bearing Inner and Outer Housings (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008 30 Sep 2024			
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712201	Mount, L Engine Fwd Fuse-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712202	Mount, R Engine Fwd Fuse-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712203	Mount, L Eng Aft Fuse-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712204	Mount, R Eng Aft Fuse-Insp		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712205	Engine Aft Suspension Upper Strut Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP567-1	TY2496	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712206	Engine Aft Suspension Upper Strut Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP567-1	TY2478	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712207	Engine Aft Suspension Lower Strut Assembly (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP568-1	TY2442	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712208	Engine Aft Suspension Lower Strut Assembly (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP568-1	TY2429	MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712209	Aft Engine Mount Strut Assemblies External (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712210	Aft Engine Mount Strut Assemblies External (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712211	Mount, L Fwd UPR Fwd Fuselage		HRS		4057.8			0			0
	1159BM50505-5	PM0009	AFL		1184			0			0
			MOS		188.2			24 May 2008			STELLEX PRECISION MACHINING, INC
			MSC				O/C				
Airframe											
712212	Mount, L Fwd UPR Aft Fuselage		HRS		4057.8			0			0
	1159BM50505-3	PM0014	AFL		1184			0			0
			MOS		188.2			24 May 2008			STELLEX PRECISION MACHINING, INC
			MSC				O/C				
Airframe											
712213	Mount, L Fwd Lwr Fwd Fuselage		HRS		4057.8			0			0
	1159BM50506-5	046613-001	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
			MSC				O/C				
Airframe											
712214	Mount, L Fwd Lwr Aft Fuselage		HRS		4057.8			0			0
	1159BM50506-1	052852-004	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
712215	Mount, R Fwd UPR Fwd Fuselage		HRS		4057.8			0			0
	1159BM50505-5	PM0008	AFL		1184			0			0
			MOS		188.2			24 May 2008			STELLEX PRECISION MACHINING, INC
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712216	Mount, R Fwd UPR Aft Fuselage		HRS		4057.8			0			0
	1159BM50505-3	PM0016	AFL		1184			0			0
			MOS		188.2			24 May 2008			STELLEX PRECISION MACHINING, INC
	Airframe		MSC					O/C			
712217	Mount, R Fwd Lwr Fwd Fuselage		HRS		4057.8			0			0
	1159BM50506-5	046613-009	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
	Airframe		MSC					O/C			
712218	Mount, R Fwd Lwr Aft Fuselage		HRS		4057.8			0			0
	1159BM50506-1	052168-005	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
712219	Mount, L Aft UPR Fwd Fuselage		HRS		4057.8			0			0
	1159BM50919-13	J065141-002	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712220	Mount, L Aft UPR Aft Fuselage		HRS		4057.8			0			0
	1159BM50923-13	046591-001	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712221	Mount, L Aft Lwr Fwd Fuselage		HRS		4057.8			0			0
	1159BM50921-13	9-24287-01-006	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712222	Mount, L Aft Lwr Aft Fuselage		HRS		4057.8			0			0
	1159BM50924-13	J065301-009	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712223	Mount, R Aft UPR Fwd Fuselage		HRS		4057.8			0			0
	1159BM50919-13	J065141-004	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712224	Mount, R Aft UPR Aft Fuselage		HRS		4057.8			0			0
	1159BM50923-13	052185-010	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712225	Mount, R Aft Lwr Fwd Fuselage		HRS		4057.8			0			0
	1159BM50921-13	9-24287-01-005	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712226	Mount, R Aft Lwr Aft Fuselage		HRS		4057.8			0			0
	1159BM50924-13	J065301-003	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712227	Pin, L Eng Rear Mount Ring		HRS		4057.8			0			0
	1159BM51253-11	011	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311215											
712228	Pin, R Eng Rear Mount Ring		HRS		4057.8			0			0
	1159BM51253-11	0014	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311215											
712229	Pin, Lh Rear UPR Link/Fuselage		HRS		4057.8			0			0
	1159BM51247-11	14521-396	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712230	Pin, Rh Rear UPR Link/Fuselage		HRS		4057.8			0			0
	1159BM51247-11	E4521-412	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER AEROSPACE
	Airframe		MSC					O/C			
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712231	Pin, Lh Rear Lwr Link/Fuselage		HRS		4057.8			0			0
	1159BM51247-11	991054-118	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712232	Pin, Rh Rear Lwr Link/Fuselage		HRS		4057.8			0			0
	1159BM51247-11	991054-114	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712233	CAP, Lh Rear UPR Link/Fuselage		HRS		4057.8			0			0
	1159BM51249-11	131	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712234	CAP, Rh Rear UPR Link/Fuselage		HRS		4057.8			0			0
	1159BM51249-11	144	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712235	CAP, Lh Rear Lwr Link/Fuselage		HRS		4057.8			0			0
	1159BM51249-11	136	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712236	CAP, Rh Rear Lrw Link/Fuselage		HRS		4057.8			0			0
	1159BM51249-11	315999-1-234	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712237	Aft Upper Swaged Strut (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712238	Aft Upper Swaged Strut (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712249	Aft Engine Mount Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712250	Aft Engine Mount Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712301	Engine Thrust Strut (Left) - Removal / Installation		HRS		4057.8			0			0
	1159SCP566-3	TY1213	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			TYEE AIRCRAFT INC
Notes: FOR Q311215											
712302	Engine Thrust Strut (Right) - Removal / Installation		HRS		4057.8			0			0
	1159SCP566-4	TY1177	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			TYEE AIRCRAFT INC
Notes: FOR Q311215											
712303	Thrust and Alignment Strut Assemblies External (Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3	192		23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712304	Thrust and Alignment Strut Assemblies External (Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
712307	Aft Attach Fitting Thrust / Alignment (FS 820, Left) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
712308	Aft Attach Fitting Thrust / Alignment (FS 820, Right) - Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
712309	Pin, Lh Thrust Strut Aft		HRS		4057.8			0			0
	1159BM51253-13	140	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712310	Pin, Rh Thrust Strut Aft		HRS		4057.8			0			0
	1159BM51253-13	101	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712311	Pin, Lh Thrust Strut Fwd		HRS		4057.8			0			0
	1159BM51253-15	345	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
			MSC				O/C				
Airframe											
Notes: FOR Q311215											
712312	Pin, Rh Thrust Strut Fwd		HRS		4057.8			0			0
	1159BM51253-15	352	AFL		1184			0			0
			MOS		188.2			24 May 2008			PRO-FAB, INC.
			MSC				O/C				
Airframe											
Notes: FOR Q311215											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712313	CAP, Lh Thrust Strut Aft		HRS		4057.8			0			0
	1159BM51249-11	132	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712314	CAP, Rh Thrust Strut Aft		HRS		4057.8			0			0
	1159BM51249-11	149	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712315	CAP, Lh Thrust Strut Fwd		HRS		4057.8			0			0
	1159BM51249-11	137	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712316	CAP, Rh Thrust Strut Fwd		HRS		4057.8			0			0
	1159BM51249-11	138	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712317	Mount, L Thrust/Jury Fuselage		HRS		4057.8			0			0
	1159BM51243-7	042705-003	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE
Notes: FOR Q311215											
712318	Mount, R Thrust/Jury Fuselage		HRS		4057.8			0			0
	1159BM51243-8	J065341-004	AFL		1184			0			0
			MOS		188.2			24 May 2008			THAYER
	Airframe		MSC					O/C			AEROSPACE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712321	Thrust Strut Fitting (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712322	Thrust Strut Fitting (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712401	Engine Jury / Alignment Strut (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP578-1	TY0875	MOS		188.2			24 May 2008			TYEE AIRCRAFT INC
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712402	Engine Jury / Alignment Strut (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCP578-2	TY0860	MOS		188.2			24 May 2008			AIRCRAFT SEAL AND GASKET CORP.
	Airframe		MSC					O/C			
Notes: FOR Q311215											
712403	Thrust and Alignment Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712404	Thrust and Alignment Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712407	No. 1 Engine - Tapered Pin Assembly (Upper) - Discard		HRS		4057.8			0			0
			ENC		1184			0			0
	JR29859A	NSN	MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712407 (712408)	No. 2 Engine - Tapered Pin Assembly (Upper) - Discard		HRS		4057.8			0			0
	JR29859A	NSN	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
712409	No. 1 Engine - Tapered Pin Assembly (Lower) - Discard		HRS		4057.8			0			0
	JR29859A	NSN	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
712409 (712410)	No. 2 Engine - Tapered Pin Assembly (Lower) - Discard		HRS		4057.8			0			0
	JR29859A	NSN	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
712500	Engines Declared as Task Oriented		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
712501	Pin, L Engine Thrust		HRS		4057.8			0			0
	1159BM51250-3	0378	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311215											
712502	Pin, R Engine Thrust		HRS		4057.8			0			0
	1159BM51250-3	0414	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
Notes: VERIFIED BY Q311215											
712503	Forward Engine Mount Thrust Pin (Ndt) (Left) - Special		HRS		4057.8			0			0
	Detailed Inspection		AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	Airframe							[End Of Month Item] [MOS: +1m/-1m]			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712504	Forward Engine Mount Thrust Pin (Ndt) (Right) - Special Detailed Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		184.3		192	23 Sep 2008	30 Sep 2024	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
712505	Sleeve, Lh Fwd Mount Taper Pin		HRS		4057.8			0			0
	1159BM51251-3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712506	Sleeve, Rh Fwd Mount Taper Pin		HRS		4057.8			0			0
	1159BM51251-3	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
712507	Engine Attach Pins (Left) - Ndt Inspection		HRS		4057.8			0			0
			AFL				10200**		10200		0
			MOS		188.2			24 May 2008			
	Airframe										
712508	Engine Attach Pins (Right) - Ndt Inspection		HRS		4057.8			0			0
			AFL				10200**		10200		0
			MOS		188.2			24 May 2008			
	Airframe										
717001	No. 1 Engine - Engine Drains Tank Ejector - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	CV41-14	08-0103275	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
717001 (717002)	No. 2 Engine - Engine Drains Tank Ejector - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	CV41-14	08-0103278	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
717003	No. 1 Engine - Drains Collection Tank - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	BRR18235	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
717003 (717004)	No. 2 Engine - Drains Collection Tank - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	BRR18235	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
717005	No. 1 Engine - Element, Motive Flow(EPA)		HRS		4057.8			0			0
	QA07861	SN-UNKNOWN	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			PAS
			MSC							O/C	
Engine											
717005 (717006)	No. 2 Engine - Element, Motive Flow(EPA)		HRS		4057.8			0			0
	QA07861	SN-UNKNOWN	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			PAS
			MSC							O/C	
Engine											
717007	No. 1 Engine - Engine Drains System - Detailed Inspection		HRS		616		1000	3441.8	4441.8	4491.8	0
			ENC		220			964			0
			MOS		19.9			02 Jun 2022			
											[HRS: +50/-50]
Engine											
717007 (717008)	No. 2 Engine - Engine Drains System - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0
			ENC		0			1184			0
			MOS		.9			03 Jan 2024			
											[HRS: +50/-50]
Engine											
717009	No. 1 Engine - Engine Drains Tank Ejector Pump Filter - Clean		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
717009 (717010)	No. 2 Engine - Engine Drains Tank Ejector Pump Filter - Clean		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
71EN1	No. 1 Engine		HRS		4057.8			0			0
	BR700-710C4-11	15499	AFL		1184			0			0
			MOS		188.6			12 May 2008			
			MSC					E/C			
Airframe											
71EN2	No. 2 Engine		HRS		4057.8			0			0
	BR700-710C4-11	15500	AFL		1184			0			0
			MOS		188.6			12 May 2008			
			MSC					E/C			
Airframe											
72 - Engine											
720009	No. 1 Engine - Intermediate Case - Discard		HRS		4057.8			0			0
	BRR22752	01325	ENC		1184	20000		0	20000		0
			MOS		189.4			20 Apr 2008			
Engine											
720009 (720010)	No. 2 Engine - Intermediate Case - Discard		HRS		4057.8			0			0
	BRR22752	01331	ENC		1184	20000		0	20000		0
			MOS		189.2			24 Apr 2008			
Engine											
723001	No. 1 Engine - Low-Pressure Compressor (Fan) Module - Removal / Installation		HRS		4057.8			0			0
	FW33927	CTDK9210	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
723001 (723002)	No. 2 Engine - Low-Pressure Compressor (Fan) Module - Removal / Installation		HRS		4057.8			0			0
	FW33927	CTDK9227	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723101	No. 1 Engine - Low-Pressure Compressor (Fan) Blades -		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
	Detailed Inspection		ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
	Engine		[HRS: +50/-50]								
723101 (723102)	No. 2 Engine - Low-Pressure Compressor (Fan) Blades -		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
	Detailed Inspection		ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
	Engine		[HRS: +50/-50]								
723103	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0		1000	4057.8	5057.8	5107.8	0
	Fillers - Detailed Inspection		ENC		0			1184			0
			MOS		.9			04 Jan 2024			
	Engine		[HRS: +50/-50]								
723103 (723104)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0		1000	4057.8	5057.8	5107.8	0
	Fillers - Detailed Inspection		ENC		0			1184			0
			MOS		.9			04 Jan 2024			
	Engine		[HRS: +50/-50]								
723107	No. 1 Engine - Lp Compressor Disk Assembly - Discard		HRS		4057.8			0			0
	FW33927	CTDK9210	ENC		1184		5600	0	5600		0
			MOS		189.4			20 Apr 2008			
	Engine										
723107 (723108)	No. 2 Engine - Lp Compressor Disk Assembly - Discard		HRS		4057.8			0			0
	FW33927	CTDK9227	ENC		1184		5600	0	5600		0
			MOS		189.2			24 Apr 2008			
	Engine										
723109	No. 1 Engine - Low-Pressure Compressor Inlet Cone -		HRS		0		1000	4057.8	5057.8	5107.8	0
	Detailed Inspection		ENC		0			1184			0
			MOS		.9			03 Jan 2024			
	Engine		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723109 (723110)	No. 2 Engine - Low-Pressure Compressor Inlet Cone - Detailed Inspection		HRS		0		1000	4057.8	5057.8	5107.8	0
			ENC		0			1184			0
			MOS		.9			03 Jan 2024			
[HRS: +50/-50]											
Engine											
723113	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 1 - Removal / Installation		ENC	TSN:11845	0		10000	1184	1184		0
	FW33513	RGE53098	MOS		.5			17 Jan 2024			N/A
Engine											
723113 (723137)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 1 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53238	MOS		.5			17 Jan 2024			N/A
Engine											
723114	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 2 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53094	MOS		.5			17 Jan 2024			N/A
Engine											
723114 (723138)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 2 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53121	MOS		.5			17 Jan 2024			N/A
Engine											
723115	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 3 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53158	MOS		.5			17 Jan 2024			N/A
Engine											
723115 (723139)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 3 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53154	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723116	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 4 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53100	MOS		.5			17 Jan 2024			N/A
Engine											
723116 (723140)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 4 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53202	MOS		.5			17 Jan 2024			N/A
Engine											
723117	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 5 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE51934	MOS		.5			17 Jan 2024			N/A
Engine											
723117 (723141)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 5 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53254	MOS		.5			17 Jan 2024			N/A
Engine											
723118	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 6 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52897	MOS		.5			17 Jan 2024			N/A
Engine											
723118 (723142)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 6 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53210	MOS		.5			17 Jan 2024			N/A
Engine											
723119	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 7 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52472	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723119 (723143)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 7 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53110	MOS		.5			17 Jan 2024			N/A
Engine											
723120	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 8 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53073	MOS		.5			17 Jan 2024			N/A
Engine											
723120 (723144)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 8 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52852	MOS		.5			17 Jan 2024			N/A
Engine											
723121	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 9 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53153	MOS		.5			17 Jan 2024			N/A
Engine											
723121 (723145)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 9 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53265	MOS		.5			17 Jan 2024			N/A
Engine											
723122	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 10 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53097	MOS		.5			17 Jan 2024			N/A
Engine											
723122 (723146)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 10 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53122	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723123	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 11 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53249	MOS		.5			17 Jan 2024			N/A
Engine											
723123 (723147)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 11 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53102	MOS		.5			17 Jan 2024			N/A
Engine											
723124	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 12 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52462	MOS		.5			17 Jan 2024			N/A
Engine											
723124 (723148)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 12 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53120	MOS		.5			17 Jan 2024			N/A
Engine											
723125	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 13 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52602	MOS		.5			17 Jan 2024			N/A
Engine											
723125 (723149)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 13 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52517	MOS		.5			17 Jan 2024			N/A
Engine											
723126	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 14 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53082	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723126 (723150)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 14 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52189	MOS		.5			17 Jan 2024			N/A
Engine											
723127	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 15 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53148	MOS		.5			17 Jan 2024			N/A
Engine											
723127 (723151)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 15 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53057	MOS		.5			17 Jan 2024			N/A
Engine											
723128	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 16 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53047	MOS		.5			17 Jan 2024			N/A
Engine											
723128 (723152)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 16 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53237	MOS		.5			17 Jan 2024			N/A
Engine											
723129	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 17 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53188	MOS		.5			17 Jan 2024			N/A
Engine											
723129 (723153)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 17 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53123	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723130	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 18 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53236	MOS		.5			17 Jan 2024			N/A
Engine											
723130 (723154)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 18 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52943	MOS		.5			17 Jan 2024			N/A
Engine											
723131	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 19 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53028	MOS		.5			17 Jan 2024			N/A
Engine											
723131 (723155)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 19 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53080	MOS		.5			17 Jan 2024			N/A
Engine											
723132	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 20 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52285	MOS		.5			17 Jan 2024			N/A
Engine											
723132 (723156)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 20 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52809	MOS		.5			17 Jan 2024			N/A
Engine											
723133	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 21 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53177	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723133 (723157)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 21 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53215	MOS		.5			17 Jan 2024			N/A
Engine											
723134	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 22 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53055	MOS		.5			17 Jan 2024			N/A
Engine											
723134 (723158)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 22 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53193	MOS		.5			17 Jan 2024			N/A
Engine											
723135	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 23 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52951	MOS		.5			17 Jan 2024			N/A
Engine											
723135 (723159)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 23 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53203	MOS		.5			17 Jan 2024			N/A
Engine											
723136	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 24 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE52940	MOS		.5			17 Jan 2024			N/A
Engine											
723136 (723160)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		0			4057.8			0
	No. 24 - Removal / Installation		ENC	TSN:1184	0		10000	1184	10000		0
	FW33513	RGE53152	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723161	No. 1 Engine - Lp Compressor Front Blade Retaining Ring		HRS		0			4057.8			0
	- Detailed Inspection		ENC		0			1184			0
			MOS		.9			03 Jan 2024			
	Engine		MSC						A/R		
723161 (723162)	No. 2 Engine - Lp Compressor Front Blade Retaining Ring		HRS		0			4057.8			0
	- Detailed Inspection		ENC		0			1184			0
			MOS		.9			03 Jan 2024			
	Engine		MSC						A/R		
723165	No. 1 Engine - Front Blade Retaining Ring - Removal /		HRS		0			4057.8			0
	Installation		ENC		0			1184			0
	BRR20843	ATP0321	MOS		.5			17 Jan 2024			N/A
	Engine		MSC						O/C		
Notes: VERIFIED U410160											
723165 (723166)	No. 2 Engine - Front Blade Retaining Ring - Removal /		HRS		0			4057.8			0
	Installation		ENC		0			1184			0
	BRR20843	ATP0361	MOS		.5			17 Jan 2024			N/A
	Engine		MSC						O/C		
723190	No. 1 Engine - Fan Blade Dry Film Lubricant -		HRS		0			4057.8			0
	Refurbishment		ENC		0			1184			0
			MOS		.7			10 Jan 2024			
	Engine		MSC						O/C		
723190 (723191)	No. 2 Engine - Fan Blade Dry Film Lubricant -		HRS		0			4057.8			0
	Refurbishment		ENC		0			1184			0
			MOS		.7			10 Jan 2024			
	Engine		MSC						O/C		
723201	No. 1 Engine - Fan Outlet Guide Vanes - Detailed		HRS		134.1	-22.5	2000	3923.7	5901.2*	5951.2	0
	Inspection		ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
	Engine		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723201 (723202)	No. 2 Engine - Fan Outlet Guide Vanes - Detailed Inspection		HRS		134.1	-22.5	2000	3923.7	5901.2*	5951.2	0
			ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
[HRS: +50/-50]											
Engine											
723203	No. 1 Engine - Engine Section Stators - Detailed Inspection		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
[HRS: +50/-50]											
Engine											
723203 (723204)	No. 2 Engine - Engine Section Stators - Detailed Inspection		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
[HRS: +50/-50]											
Engine											
723205	No. 1 Engine - Fan Shaft Assembly - Discard		HRS		4057.8			0			0
	BRR23914	CL24535	ENC		1184		25000	0	25000		0
			MOS		189.4			20 Apr 2008			
Engine											
723205 (723206)	No. 2 Engine - Fan Shaft Assembly - Discard		HRS		4057.8			0			0
	BRR23914	CL20264	ENC		1184		25000	0	25000		0
			MOS		189.2			24 Apr 2008			
Engine											
723301	No. 1 Engine - Hp Compressor Rotor Disk Assembly (Stages 7-10) - Discard		HRS		4057.8			0			0
	BRR24357	3622	ENC		1184		15000	0	15000		0
			MOS		189.4			20 Apr 2008			
Engine											
723301 (723302)	No. 2 Engine - Hp Compressor Rotor Disk Assembly (Stages 7-10) - Discard		HRS		4057.8			0			0
	BRR24357	3585	ENC		1184		15000	0	15000		0
			MOS		189.2			24 Apr 2008			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
723303	No. 1 Engine - Hp Compressor Rotor Disk Assembly		HRS		4057.8			0			0	
	(Stages 1-6) - Discard		ENC		1184		15000	0	15000		0	
	BRR24382	2606	MOS		189.4			20 Apr 2008				
Engine												
723303 (723304)	No. 2 Engine - Hp Compressor Rotor Disk Assembly		HRS		4057.8			0			0	
	(Stages 1-6) - Discard		ENC		1184		15000	0	15000		0	
	BRR24382	2557	MOS		189.2			24 Apr 2008				
Engine												
723311	No. 1 Engine - Variable Stator Vane Drive Bracket Bolts - Torque Reapplication		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8				05 Oct 2014			
			MSC					O/C				
Engine												
723311 (723312)	No. 2 Engine - Variable Stator Vane Drive Bracket Bolts - Torque Reapplication		HRS		2414			1643.8			0.3	
			ENC		716			468			0	
			MOS		111.8				05 Oct 2014			
			MSC					O/C				
Engine												
723401	No. 1 Engine - Fan Track / Cold Stream Duct - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0	
			ENC		0			1184			0	
			MOS		.9				03 Jan 2024			
								[HRS: +50/-50]				
Engine												
723401 (723402)	No. 2 Engine - Fan Track / Cold Stream Duct - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0	
			ENC		0			1184			0	
			MOS		.9				03 Jan 2024			
								[HRS: +50/-50]				
Engine												
723403	No. 1 Engine - Fan Case Kevlar Wrap - Detailed Inspection		HRS		1189.2		3000	2868.6	5868.6	5918.6	0	
			ENC		361			823			0	
			MOS		52.8				05 Sep 2019			
								[HRS: +50/-50]				
Engine												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723403 (723404)	No. 2 Engine - Fan Case Kevlar Wrap - Detailed Inspection		HRS		1189.2		3000	2868.6	5868.6	5918.6	0
			ENC		361			823			0
			MOS		52.8			05 Sep 2019			
			[HRS: +50/-50]								
Engine											
723500	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 1 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4			20 Apr 2008			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53098.											
723500 (723501)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 1 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2			24 Apr 2008			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53238.											
723502	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 2 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4			20 Apr 2008			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53094.											
723502 (723503)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 2 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2			24 Apr 2008			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53121.											
723504	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 3 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4			20 Apr 2008			
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53158.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723504 (723505)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 3 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53154.											
723506	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 4 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53100.											
723506 (723507)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 4 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53202.											
723508	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 5 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE51934.											
723508 (723509)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 5 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53254.											
723510	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 6 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52897.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723510 (723511)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 6 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53210.											
723512	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 7 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52472.											
723512 (723513)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 7 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53110.											
723514	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 8 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53073.											
723514 (723515)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 8 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52852.											
723516	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 9 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53153.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723516 (723517)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 9 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53265.											
723518	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 10 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53097.											
723518 (723519)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 10 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53122.											
723520	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 11 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53249.											
723520 (723521)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 11 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53102.											
723522	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 12 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52462.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723522 (723523)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 12 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53120.											
723524	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 13 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52602.											
723524 (723525)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 13 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52517.											
723526	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 14 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53082.											
723526 (723527)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 14 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52189.											
723528	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 15 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53148.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723528 (723529)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 15 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53057.											
723530	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 16 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53047.											
723530 (723531)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 16 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53237.											
723532	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 17 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53188.											
723532 (723533)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 17 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53123.											
723534	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 18 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53236.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723534 (723535)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 18 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52943.											
723536	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 19 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53028.											
723536 (723537)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 19 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53080.											
723538	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 20 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52285.											
723538 (723539)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 20 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52809.											
723540	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 21 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53177.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723540 (723541)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 21 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53215.											
723542	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 22 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53055.											
723542 (723543)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 22 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53193.											
723544	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 23 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52951.											
723544 (723545)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 23 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53203.											
723546	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 24 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.4				20 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE52940.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723546 (723547)	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		4057.8		4000	0	4000	4400	0
	No. 24 Metco 58 Coating - Refurbishment		ENC		1184		3000	0	3000		0
			MOS		189.2				24 Apr 2008		
			[HRS: +400/-400]								
Engine											
Notes: PN: FW33513 SN: RGE53152.											
723801	No. 1 Engine - Nose Cone Assembly - Removal /		HRS		0				4057.8		0
	Installation		ENC		0				1184		0
	BRR24229	4446514/001	MOS		.5				17 Jan 2024		N/A
			MSC				O/C				
Engine											
Notes: VERIFIED U410160											
723801 (723802)	No. 2 Engine - Nose Cone Assembly - Removal /		HRS		0				4057.8		0
	Installation		ENC		0				1184		0
	BRR24229	4309652/001	MOS		.5				16 Jan 2024		N/A
			MSC				O/C				
Engine											
723805	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0				4057.8		0
	Filler No. 1 - Removal / Installation		ENC	TSN:1184	0		6300		1184	6300	0
	BRR22626	HLAH69723	MOS		.5				17 Jan 2024		N/A
Engine											
723805 (723829)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0				4057.8		0
	Filler No. 1 - Removal / Installation		ENC	TSN:1184	0		6300		1184	6300	0
	BRR22626	HLAH7079	MOS		.5				17 Jan 2024		N/A
Engine											
723806	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0				4057.8		0
	Filler No. 2 - Removal / Installation		ENC	TSN:1184	0		6300		1184	6300	0
	BRR22626	HLAH69838	MOS		.5				17 Jan 2024		N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723806 (723830)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 2 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70603	MOS		.5			17 Jan 2024			N/A
Engine											
723807	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 3 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70894	MOS		.5			17 Jan 2024			N/A
Engine											
723807 (723831)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 3 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70997	MOS		.5			17 Jan 2024			N/A
Engine											
723808	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 4 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69937	MOS		.5			17 Jan 2024			N/A
Engine											
723808 (723832)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 4 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70980	MOS		.5			17 Jan 2024			N/A
Engine											
723809	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 5 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70024	MOS		.5			17 Jan 2024			N/A
Engine											
723809 (723833)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 5 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70623	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723810	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 6 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70899	MOS		.5			17 Jan 2024			N/A
Engine											
723810 (723834)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 6 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70983	MOS		.5			17 Jan 2024			N/A
Engine											
723811	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 7 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69943	MOS		.5			17 Jan 2024			N/A
Engine											
723811 (723835)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 7 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70566	MOS		.5			17 Jan 2024			N/A
Engine											
723812	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 8 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69708	MOS		.5			17 Jan 2024			N/A
Engine											
723812 (723836)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 8 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70985	MOS		.5			17 Jan 2024			N/A
Engine											
723813	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 9 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69979	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723813 (723837)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 9 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70987	MOS		.5			17 Jan 2024			N/A
Engine											
723814	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 10 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69916	MOS		.5			17 Jan 2024			N/A
Engine											
723814 (723838)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 10 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70981	MOS		.5			17 Jan 2024			N/A
Engine											
723815	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 11 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69808	MOS		.5			17 Jan 2024			N/A
Engine											
723815 (723839)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 11 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70604	MOS		.5			17 Jan 2024			N/A
Engine											
723816	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 12 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69809	MOS		.5			17 Jan 2024			N/A
Engine											
723816 (723840)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 12 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70996	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723817	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 13 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69715	MOS		.5			17 Jan 2024			N/A
Engine											
723817 (723841)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 13 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70989	MOS		.5			17 Jan 2024			N/A
Engine											
723818	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 14 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69827	MOS		.5			17 Jan 2024			N/A
Engine											
723818 (723842)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 14 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70998	MOS		.5			17 Jan 2024			N/A
Engine											
723819	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 15 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70275	MOS		.5			17 Jan 2024			N/A
Engine											
723819 (723843)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 15 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70986	MOS		.5			17 Jan 2024			N/A
Engine											
723820	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 16 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70895	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723820 (723844)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 16 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70631	MOS		.5			17 Jan 2024			N/A
Engine											
723821	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 17 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69883	MOS		.5			17 Jan 2024			N/A
Engine											
723821 (723845)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 17 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70982	MOS		.5			17 Jan 2024			N/A
Engine											
723822	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 18 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70778	MOS		.5			17 Jan 2024			N/A
Engine											
723822 (723846)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 18 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70995	MOS		.5			17 Jan 2024			N/A
Engine											
723823	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 19 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69815	MOS		.5			17 Jan 2024			N/A
Engine											
723823 (723847)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 19 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70991	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723824	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 20 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70896	MOS		.5			17 Jan 2024			N/A
Engine											
723824 (723848)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 20 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70990	MOS		.5			17 Jan 2024			N/A
Engine											
723825	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 21 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69889	MOS		.5			17 Jan 2024			N/A
Engine											
723825 (723849)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 21 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70992	MOS		.5			17 Jan 2024			N/A
Engine											
723826	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 22 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69820	MOS		.5			17 Jan 2024			N/A
Engine											
723826 (723850)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 22 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70993	MOS		.5			17 Jan 2024			N/A
Engine											
723827	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 23 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70785	MOS		.5			17 Jan 2024			N/A
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723827 (723851)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 23 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70984	MOS		.5			17 Jan 2024			N/A
Engine											
723828	No. 1 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 24 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH69925	MOS		.5			17 Jan 2024			N/A
Engine											
723828 (723852)	No. 2 Engine - Low-Pressure Compressor (Fan) Annulus		HRS		0			4057.8			0
	Filler No. 24 - Removal / Installation		ENC	TSN:1184	0		6300	1184	6300		0
	BRR22626	HLAH70988	MOS		.5			17 Jan 2024			N/A
Engine											
723853	No. 1 Engine - Nose Cone Rotating Fairing - Removal /		HRS		0			4057.8			0
	Installation		ENC		0			1184			0
	BRR24368	BA81995	MOS		.5			16 Jan 2024			N/A
Engine											
723853 (723854)	No. 2 Engine - Nose Cone Rotating Fairing - Removal /		HRS		0			4057.8			0
	Installation		ENC		0			1184			0
	BRR24368	BA81987	MOS		.5			16 Jan 2024			N/A
Engine											
724001	No. 1 Engine - Hp Turbine Rotor Disc, Stage 1 - Discard		HRS		4057.8			0			0
	BRR23952		ENC		1184		6200	0	6200		0
		LDRQA02780	MOS		189.4			20 Apr 2008			
Engine											
724001 (724002)	No. 2 Engine - Hp Turbine Rotor Disc, Stage 1 - Discard		HRS		4057.8			0			0
	BRR23952		ENC		1184		6200	0	6200		0
		LDRQA02795	MOS		189.2			24 Apr 2008			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
724003	No. 1 Engine - Hp Turbine Rotor Disc, Stage 2 - Discard		HRS		4057.8			0			0	
	BRR22008	LDRQA02773	ENC		1184		10500	0	10500		0	
			MOS		189.4				20 Apr 2008			
Engine												
724003 (724004)	No. 2 Engine - Hp Turbine Rotor Disc, Stage 2 - Discard		HRS		4057.8			0			0	
	BRR22008	LDRQA02864	ENC		1184		10500	0	10500		0	
			MOS		189.2				24 Apr 2008			
Engine												
724005	No. 1 Engine - High-Pressure Turbine Stage 1 Rotor Blades - Special Detailed Inspection		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8					05 Oct 2014		
			MSC									
Engine												
724005 (724006)	No. 2 Engine - High-Pressure Turbine Stage 1 Rotor Blades - Special Detailed Inspection		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8					05 Oct 2014		
			MSC									
Engine												
724007	No. 1 Engine - High-Pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8					05 Oct 2014		
			MSC									
Engine												
724007 (724008)	No. 2 Engine - High-Pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8					05 Oct 2014		
			MSC									
Engine												
724009	No. 1 Engine - Combustion Liner - Special Detailed Inspection		HRS		2414			1643.8			0	
			ENC		716			468			0	
			MOS		111.8					05 Oct 2014		
			MSC									
Engine												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
724009 (724010)	No. 2 Engine - Combustion Liner - Special Detailed Inspection		HRS		2414			1643.8			0
			ENC		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC					O/C			
Engine											
724201	No. 1 Engine - Curvic Ring - Discard		HRS		4057.8			0			0
	BRR20340	6813	ENC		1184		15000	0	15000		0
			MOS		189.4			20 Apr 2008			
Engine											
724201 (724202)	No. 2 Engine - Curvic Ring - Discard		HRS		4057.8			0			0
	BRR20340	6814	ENC		1184		15000	0	15000		0
			MOS		189.2			24 Apr 2008			
Engine											
724203	No. 1 Engine - Pipes, Stage 4 AIR		HRS		4057.8			0			0
	BRR23274	SN-UNKNOWN	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
724203 (724204)	No. 2 Engine - Pipes, Stage 4 AIR		HRS		4057.8			0			0
	BRR23274	SN-UNKNOWN	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
725101	No. 1 Engine - Lp Turbine Rotor Shaft - Discard		HRS		4057.8			0			0
	BRR19612	SBAN1177	ENC		1184		25000	0	25000		0
			MOS		189.4			20 Apr 2008			
Engine											
725101 (725102)	No. 2 Engine - Lp Turbine Rotor Shaft - Discard		HRS		4057.8			0			0
	BRR19612	SBAN1147	ENC		1184		25000	0	25000		0
			MOS		189.2			24 Apr 2008			
Engine											
725103	No. 1 Engine - Lp Turbine Rotor Disc, Stage 1 - Discard		HRS		4057.8			0			0
	BRR15535	6677	ENC		1184		25000	0	25000		0
			MOS		189.4			20 Apr 2008			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725103 (725104)	No. 2 Engine - Lp Turbine Rotor Disc, Stage 1 - Discard		HRS		4057.8			0			0
	BRR15535	6703	ENC		1184		25000	0	25000		0
			MOS		189.2				24 Apr 2008		
Engine											
725105	No. 1 Engine - Lp Turbine Rotor Disc, Stage 2 - Discard		HRS		4057.8			0			0
	BRR11896	6683	ENC		1184		25000	0	25000		0
			MOS		189.4				20 Apr 2008		
Engine											
725105 (725106)	No. 2 Engine - Lp Turbine Rotor Disc, Stage 2 - Discard		HRS		4057.8			0			0
	BRR11896	6713	ENC		1184		25000	0	25000		0
			MOS		189.2				24 Apr 2008		
Engine											
725107	No. 1 Engine - No.4 Stubshaft - Discard		HRS		4057.8			0			0
	PN	SN-UNKNOWN	ENC		1184		19000	0	19000		0
			MOS		189.4				20 Apr 2008		
Engine											
725107 (725108)	No. 2 Engine - No.4 Stubshaft - Discard		HRS		4057.8			0			0
	PN	SN-UNKNOWN	ENC		1184		19000	0	19000		0
			MOS		189.2				24 Apr 2008		
Engine											
725109	No. 1 Engine - No.5 Stubshaft		HRS		4057.8			0			0
	BRR40703	1180	ENC		1184			0			0
			MOS		189.4				20 Apr 2008		
			MSC				O/C				
Engine											
725109 (725110)	No. 2 Engine - No.5 Stubshaft		HRS		4057.8			0			0
	BRR40703	1186	ENC		1184			0			0
			MOS		189.2				24 Apr 2008		
			MSC				O/C				
Engine											
726001	No. 1 Engine - Gearbox, Engine Accessory		HRS		4057.8			0			0
	39500228	2048	ENC		1184			0			0
			MOS		189.4				20 Apr 2008		
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
726001 (726002)	No. 2 Engine - Gearbox, Engine Accessory		HRS		4057.8			0			0
	39500228	2050	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
726303	No. 1 Engine - Low-Pressure Turbine Reference Tube		HRS		4057.8		5000	0	5000	5050	0
	Pawl Mechanism Interface and Stirrup - Detailed		ENC		1184			0			0
	Inspection		MOS		189.4			20 Apr 2008			
	Engine		[HRS: +50/-50]								
726303 (726304)	No. 2 Engine - Low-Pressure Turbine Reference Tube		HRS		4057.8		5000	0	5000	5050	0
	Pawl Mechanism Interface and Stirrup - Detailed		ENC		1184			0			0
	Inspection		MOS		189.2			24 Apr 2008			
	Engine		[HRS: +50/-50]								
726309	No. 1 Engine - Fuel Shut-Off Cable (Stirrup to Elbow) -		HRS		4057.8		5000	0	5000	5050	0
	Special Detailed Inspection		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		[HRS: +50/-50]								
726309 (726310)	No. 2 Engine - Fuel Shut-Off Cable (Stirrup to Elbow) -		HRS		4057.8		5000	0	5000	5050	0
	Special Detailed Inspection		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		[HRS: +50/-50]								
727101	No. 1 Engine - Bypass Duct Inner Surface - General		HRS		4057.8			0			0
	Visual Inspection		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
727101 (727102)	No. 2 Engine - Bypass Duct Inner Surface - General		HRS		4057.8			0			0
	Visual Inspection		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
727103	No. 1 Engine - Bypass Duct Inner Surface - General		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
	Visual Inspection		ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
	Engine		[HRS: +50/-50]								
727103 (727104)	No. 2 Engine - Bypass Duct Inner Surface - General		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
	Visual Inspection		ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
	Engine		[HRS: +50/-50]								
73 - Engine Fuel and Control											
731001	No. 1 Engine - Fuel Pump - Removal / Installation		HRS		0			4057.8			0
	828201-2	1625	ENC		0			1184			0
			MOS		.7			09 Jan 2024			N/A
	Engine		MSC				O/C				
731001 (731002)	No. 2 Engine - Fuel Pump - Removal / Installation		HRS		0			4057.8			0
	828201-2	1623	ENC		0			1184			0
			MOS		.6			11 Jan 2024			N/A
	Engine		MSC				O/C				
731005	No. 1 Engine - Fuel Metering Unit - Removal / Installation		HRS		0			4057.8			0
	8061-977	15650523	ENC		0			1184			0
			MOS		.7			09 Jan 2024			N/A
	Engine		MSC				O/C				
731005 (731006)	No. 2 Engine - Fuel Metering Unit - Removal / Installation		HRS		0			4057.8			0
	8061-977	15650515	ENC		0			1184			0
			MOS		.6			11 Jan 2024			N/A
	Engine		MSC				O/C				
731019	No. 1 Engine - Fuel Pump Vespel Coupling - Discard		HRS		0		3500	4057.8	7557.8		0
	39504900	NSN	ENC		0			1184			0
			MOS	TSN:6	.6			11 Jan 2024			N/A
	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731019 (731020)	No. 2 Engine - Fuel Pump Vespel Coupling - Discard		HRS		0		3500	4057.8	7557.8		0
	39504900	NSN	ENC		0			1184			0
			MOS	TSN:6	.6			11 Jan 2024			N/A
Engine											
731021	No. 1 Engine - High Pressure Fuel Filter - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	QA07517	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
731021 (731022)	No. 2 Engine - High Pressure Fuel Filter - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	QA07517	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
731023	No. 1 Engine - Low-Pressure Fuel Filter - Detailed		HRS		2673.4			1384.4			0
	Inspection		ENC		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					O/C			
Engine											
731023 (731024)	No. 2 Engine - Low-Pressure Fuel Filter - Detailed		HRS		2673.4			1384.4			0
	Inspection		ENC		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					O/C			
Engine											
731027	No. 1 Engine - Low-Pressure Fuel Filter - Removal /		HRS		13.4			4044.4			0
	Installation		ENC		4			1180			0
	QA07865	RD22009502	MOS		1.3			21 Dec 2023			
			MSC					O/C			
Engine											
Notes: Filter must be replaced after 50 flight hours but before 75 flight hours per 280015 requirements											
731027 (731028)	No. 2 Engine - Low-Pressure Fuel Filter - Removal /		HRS		13.4			4044.4			0
	Installation		ENC		4			1180			0
	QA07865	RD22009655	MOS		1.3			21 Dec 2023			
			MSC					O/C			
Engine											
Notes: Filter must be replaced after 50 flight hours but before 75 flight hours per 280015 requirements.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731029	No. 1 Engine - Low-Pressure Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	8910-210	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
731029 (731030)	No. 2 Engine - Low-Pressure Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	8910-210	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
731100	No. 1 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26964	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
731100 (731120)	No. 2 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26613	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
731101	No. 1 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26965	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
731101 (731121)	No. 2 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26614	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
731102	No. 1 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26966	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731102 (731122)	No. 2 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26615	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731103	No. 1 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26967	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731103 (731123)	No. 2 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26616	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731104	No. 1 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26968	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731104 (731124)	No. 2 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26617	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731105	No. 1 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26969	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731105 (731125)	No. 2 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26618	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731106	No. 1 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26970	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731106 (731126)	No. 2 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26619	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731107	No. 1 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26971	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731107 (731127)	No. 2 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26620	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731108	No. 1 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26972	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731108 (731128)	No. 2 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26621	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731109	No. 1 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26973	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731109 (731129)	No. 2 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26622	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731110	No. 1 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26974	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731110 (731130)	No. 2 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26623	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731111	No. 1 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26975	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731111 (731131)	No. 2 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26624	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731112	No. 1 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26976	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731112 (731132)	No. 2 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26625	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731113	No. 1 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26977	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731113 (731133)	No. 2 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26626	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731114	No. 1 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26978	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731114 (731134)	No. 2 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26627	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731115	No. 1 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26979	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
731115 (731135)	No. 2 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26628	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
731116	No. 1 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26980	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731116 (731136)	No. 2 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26629	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
731117	No. 1 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26981	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
731117 (731137)	No. 2 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26630	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
731118	No. 1 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26982	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
731118 (731138)	No. 2 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26631	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
731119	No. 1 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26983	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
731119 (731139)	No. 2 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	6940426E14	N26632	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731141	No. 1 Engine - Drains Tank Ejector Inline Filter - Inspection		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
			[HRS: +50/-50]								
Engine											
Notes: PN: QA07861 SN: <NONE>.											
731141 (731142)	No. 2 Engine - Drains Tank Ejector Inline Filter - Inspection		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
			[HRS: +50/-50]								
Engine											
Notes: PN: QA07861 SN: <NONE>.											
731143	No. 1 Engine - Drains Tank Ejector Filter Element - Removal / Installation		HRS	TSN:3923.7	134.1			3923.7			0
			ENC	TSN:1140	44			1140			0
	QA07861	SN-UNKNOWN	MOS	TSN:183	5.4			18 Aug 2023			N/A
			MSC				O/C				
Engine											
731143 (731144)	No. 2 Engine - Drains Tank Ejector Filter Element - Removal / Installation		HRS	TSN:3923.7	134.1			3923.7			0
			ENC	TSN:1140	44			1140			0
	QA07861	SN-UNKNOWN	MOS	TSN:183	5.4			18 Aug 2023			N/A
			MSC				O/C				
Engine											
731201	No. 1 Engine - Engine Fuel Mainfold - Inspection		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC				O/C				
Engine											
731201 (731202)	No. 2 Engine - Engine Fuel Mainfold - Inspection		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC				O/C				
Engine											
731203	No. 1 Engine - Core Fuel Distribution Tubes and Fittings - Inspection		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731203 (731204)	No. 2 Engine - Core Fuel Distribution Tubes and Fittings - Inspection		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
731301	No. 1 Engine - Fuel Return to Tank Valve - Removal / Installation		HRS	TSN:374.8	3394.2			663.6			0
			ENC	TSN:210	988			196			0
	8910-312	11964066	MOS	TSN:2	156.2			26 Jan 2011			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Engine											
731301 (731302)	No. 2 Engine - Fuel Return to Tank Valve - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	8910-312	15659394	MOS		189.2			24 Apr 2008			GENERAL DYNAMICS AVIATIONS SERVICES
			MSC					O/C			
Engine											
731303	No. 1 Engine - Manifold, Splitter / Overspeed		HRS		4057.8			0			0
			ENC		1184			0			0
	8910-214	15582025	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
731303 (731304)	No. 2 Engine - Manifold, Splitter / Overspeed		HRS		4057.8			0			0
			ENC		1184			0			0
	8910-214	15534372	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
732001	No. 1 Engine - Engine Electronic Controller - Removal / Installation		HRS		1654.7			2403.1			0
			ENC		493			691			0
	EECU3000-02AD	BX970162	MOS		65.7			09 Aug 2018			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											

Notes: SWAPPED FOR TS

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732001 (732002)	No. 2 Engine - Engine Electronic Controller - Removal / Installation		HRS		1654.7			2403.1			0
			ENC		493			691			0
	EECO3000-02AD	BX970159	MOS		65.7			09 Aug 2018			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Engine											
Notes: SWAPPED FOR TS											
732103	No. 1 Engine - Dedicated Generator - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	83311-430117	4835	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Engine											
732103 (732104)	No. 2 Engine - Dedicated Generator - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	83311-430117	4834	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC								
Engine											
732105	No. 1 Engine - T30 Thermocouple (Inboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC428-01	RRAD1896	MOS		189.4			20 Apr 2008			GULFSTREAM DALLAS
			MSC								
Engine											
732105 (732106)	No. 2 Engine - T30 Thermocouple (Inboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC428-01	RRAD1895	MOS		189.2			24 Apr 2008			GULFSTREAM DALLAS
			MSC								
Engine											
732107	No. 1 Engine - T30 Thermocouple (Outboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC428-01	RRAD1679	MOS		189.4			20 Apr 2008			GULFSTREAM DALLAS
			MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732107 (732108)	No. 2 Engine - T30 Thermocouple (Outboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC428-01	RRAD1834	MOS		189.2			24 Apr 2008			GULFSTREAM
			MSC								DALLAS
Engine											
732119	No. 1 Engine - Electronic Engine Controller Close Fitting Box - Detailed Inspection		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
											[HRS: +50/-50]
Engine											
732119 (732120)	No. 2 Engine - Electronic Engine Controller Close Fitting Box - Detailed Inspection		HRS		134.1	-42.3	2000	3923.7	5881.4*	5931.4	0
			ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
											[HRS: +50/-50]
Engine											
733101	No. 1 Engine - Fuel Flow Transmitter - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9-217-49	170436-332	MOS	TSN:5	184.3			23 Sep 2008			
			MSC								O/C
Engine											
733101 (733102)	No. 2 Engine - Fuel Flow Transmitter - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9-217-49	170436-372	MOS	TSN:5	184.3			23 Sep 2008			
			MSC								O/C
Engine											
733201	No. 1 Engine - Fuel Temperature Transducer, (A Channel) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	1122806	R9232	MOS		189.4			20 Apr 2008			COVER
			MSC								GRAPHICS INC
Engine											
733201 (733202)	No. 2 Engine - Fuel Temperature Transducer, (A Channel) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	1122806	R3159	MOS		189.2			24 Apr 2008			COVER
			MSC								GRAPHICS INC
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
733203	No. 1 Engine - Fuel Temperature Transducer, (B Channel)		HRS		4057.8			0			0
	- Removal / Installation		ENC		1184			0			0
	1122806	R9901	MOS		189.4			20 Apr 2008			COVER
	Engine		MSC					O/C			GRAPHICS INC
733203 (733204)	No. 2 Engine - Fuel Temperature Transducer, (B Channel)		HRS		4057.8			0			0
	- Removal / Installation		ENC		1184			0			0
	1122806	R9888	MOS		189.2			24 Apr 2008			COVER
	Engine		MSC					O/C			GRAPHICS INC
733301	No. 1 Engine - Fuel Low Pressure Switch - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	21SN04-432	J003319	MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
733301 (733302)	No. 2 Engine - Fuel Low Pressure Switch - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	21SN04-432	J003318	MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
733401	No. 1 Engine - Fuel Differential Pressure Switch - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	21SN04-430	J003327	MOS		189.4			20 Apr 2008			ROLLS- ROYCE
	Engine		MSC					O/C			DEUTSCHLAND LTD. & CO. KG
733401 (733402)	No. 2 Engine - Fuel Differential Pressure Switch - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	21SN04-430	J003326	MOS		189.2			24 Apr 2008			ROLLS- ROYCE
	Engine		MSC					O/C			DEUTSCHLAND LTD. & CO. KG
74 - Ignition											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
741001	No. 1 Engine - Ignition Unit (Outboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9060440-2	08047311	MOS		189.4			20 Apr 2008			UNISON INDUSTRIES
			MSC								
Engine											
741001 (741002)	No. 2 Engine - Ignition Unit (Outboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9060440-2	07361103	MOS		189.2			24 Apr 2008			UNISON INDUSTRIES
			MSC								
Engine											
741003	No. 1 Engine - Ignition Unit (Inboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9060440-2	08079075	MOS		189.4			20 Apr 2008			UNISON INDUSTRIES
			MSC								
Engine											
741003 (741004)	No. 2 Engine - Ignition Unit (Inboard) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	9060440-2	07425272	MOS		189.2			24 Apr 2008			UNISON INDUSTRIES
			MSC								
Engine											
742001	No. 1 Engine - Engine Igniter Plug (No. 1) - Removal / Installation		HRS		0			4057.8			0
			ENC		0			1184			0
	CH34760-2	23050935	MOS	TSN:2	.6			11 Jan 2024			N/A
			MSC								
Engine											
742001 (742002)	No. 2 Engine - Engine Igniter Plug (No. 1) - Removal / Installation		HRS		0			4057.8			0
			ENC		0			1184			0
	CH34760-2	23041458	MOS	TSN:2	.5			16 Jan 2024			N/A
			MSC								
Engine											
742003	No. 1 Engine - Engine Igniter Plug (No. 2) - Removal / Installation		HRS		0			4057.8			0
			ENC		0			1184			0
	CH34760-2	23050940	MOS	TSN:2	.6			11 Jan 2024			N/A
			MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742003 (742004)	No. 2 Engine - Engine Igniter Plug (No. 2) - Removal / Installation		HRS		0			4057.8			0
			ENC		0			1184			0
	CH34760-2	23056337	MOS	TSN:2	.6			11 Jan 2024			N/A
			MSC								
Engine											
742005	No. 1 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0
			ENC		0			1184			0
			MOS		.9			04 Jan 2024			
				[HRS: +50/-50]							
Engine											
742005 (742006)	No. 2 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0
			ENC		0			1184			0
			MOS		.9			04 Jan 2024			
				[HRS: +50/-50]							
Engine											
742007	No. 1 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0
			ENC		0			1184			0
			MOS		.9			04 Jan 2024			
				[HRS: +50/-50]							
Engine											
742007 (742008)	No. 2 Engine - Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection		HRS		0	18.5	1000	4057.8	5076.3*	5126.3	0
			ENC		0			1184			0
			MOS		.9			04 Jan 2024			
				[HRS: +50/-50]							
Engine											
742011	No. 1 Engine - Ignition Lead (No. 1) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	430911-1	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
742011 (742012)	No. 2 Engine - Ignition Lead (No. 1) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	430911-1	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742013	No. 1 Engine - Ignition Lead (No. 2) - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	430911-1	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
742013 (742014)	No. 2 Engine - Ignition Lead (No. 2) - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	430911-1	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
742023	No. 1 Engine - Ignition System - Operational Check		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.4			18 Jan 2024			
			MSC							O/C	
Engine											
742023 (742024)	No. 2 Engine - Ignition System - Operational Check		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		.4			18 Jan 2024			
			MSC							O/C	
Engine											
75 - AIR											
752001	No. 1 Engine - Buffer AIR Valve - Removal / Installation		HRS		4057.8			0			0
	8910-512	15503909	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine											
752001 (752002)	No. 2 Engine - Buffer AIR Valve - Removal / Installation		HRS		4057.8			0			0
	8910-512	15567760	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine											
753001	No. 1 Engine - HP5 Bleed Valve (Left, Lower) - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	EB100420D	ENY254	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753001 (753002)	No. 2 Engine - HP5 Bleed Valve (Left, Lower) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	EPB266	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
753003	No. 1 Engine - HP5 Bleed Valve (Right, Upper) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	ENY255	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
753003 (753004)	No. 2 Engine - HP5 Bleed Valve (Right, Upper) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	EPB439	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
753005	No. 1 Engine - HP5 Bleed Valve (Right, Lower) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	ENY256	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
753005 (753006)	No. 2 Engine - HP5 Bleed Valve (Right, Lower) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	EPB440	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											
753007	No. 1 Engine - HP8 Bleed Valve (Left, Upper) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	ENY257	MOS		189.4			20 Apr 2008			
			MSC					O/C			
Engine											
753007 (753008)	No. 2 Engine - HP8 Bleed Valve (Left, Upper) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EB100420D	EPB441	MOS		189.2			24 Apr 2008			
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753011	No. 1 Engine - Bleed Valve Solenoid Control Block - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EA100118G	EPA116	MOS		189.4			20 Apr 2008			
			MSC							O/C	
Engine											
753011 (753012)	No. 2 Engine - Bleed Valve Solenoid Control Block - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	EA100118G	EPC004	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
753015	No. 1 Engine - Variable Stator Vane Actuator - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	8100-115	15635299	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC							O/C	
Engine											
753015 (753016)	No. 2 Engine - Variable Stator Vane Actuator - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	8100-115	15497064	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC							O/C	
Engine											
76 - Engine Controls											
761001	Throttle Quadrant Assembly - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	1159SCF553-2	103305	MOS		188.2			24 May 2008			ESTERLINE MASON
			MSC							O/C	
Airframe											
763403 (763404)	No. 2 Engine - Engine Fuel Control Switch - Removal / Installation		HRS		498.9			3558.9			0
			ENC		186			998			0
	D738-10-001	5111027	MOS	TSN:11	15.9			04 Oct 2022			N/A
			MSC							O/C	
Engine											
77 - Engine Indicating											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771201	No. 1 Engine - Channel A Hp Speed Probe (No. 1) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9815	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
771201 (771202)	No. 2 Engine - Channel A Hp Speed Probe (No. 1) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9775	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
771203	No. 1 Engine - Channel B Hp Speed Probe (No. 2) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9816	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
771203 (771204)	No. 2 Engine - Channel B Hp Speed Probe (No. 2) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9840	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
771205	No. 1 Engine - Shared Hp Speed Probe (No. 3) - Removal		HRS		4057.8			0			0
	/ Installation		ENC		1184			0			0
	889-3-13	9817	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											
771205 (771206)	No. 2 Engine - Shared Hp Speed Probe (No. 3) - Removal		HRS		4057.8			0			0
	/ Installation		ENC		1184			0			0
	889-3-13	9841	MOS		189.2			24 Apr 2008			
			MSC						O/C		
Engine											
771207	No. 1 Engine - EVM / Idg Hp Speed Probe (No. 4) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9818	MOS		189.4			20 Apr 2008			
			MSC						O/C		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771207 (771208)	No. 2 Engine - EVM / Idg Hp Speed Probe (No. 4) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	889-3-13	9842	MOS		189.2			24 Apr 2008			
			MSC							O/C	
Engine											
772001	No. 1 Engine - Engine Turbine Overheat Thermocouple		HRS		4057.8			0			0
	and Support Tube - Removal / Installation		ENC		1184			0			0
	920-4-14	3005	MOS		189.4			20 Apr 2008			AIRSHOW INC.
			MSC							O/C	
Engine											
772001 (772002)	No. 2 Engine - Engine Turbine Overheat Thermocouple		HRS		4057.8			0			0
	and Support Tube - Removal / Installation		ENC		1184			0			0
	920-4-14	2831	MOS		189.2			24 Apr 2008			AIRSHOW INC.
			MSC							O/C	
Engine											
772003	No. 1 Engine - Thermocouple, #2 Turbine O/H		HRS		4057.8			0			0
	920-4-14		ENC		1184			0			0
		3006	MOS		189.4			20 Apr 2008			AIRSHOW INC.
			MSC							O/C	
Engine											
772003 (772004)	No. 2 Engine - Thermocouple, #2 Turbine O/H		HRS		4057.8			0			0
	920-4-14		ENC		1184			0			0
		2832	MOS		189.2			24 Apr 2008			AIRSHOW INC.
			MSC							O/C	
Engine											
772011	No. 1 Engine - Tgt Thermocouple (No. 1) - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	TC429-01	RRAE03443	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC							O/C	
Engine											
772011 (772012)	No. 2 Engine - Tgt Thermocouple (No. 1) - Removal /		HRS		4057.8			0			0
	Installation		ENC		1184			0			0
	TC429-01	RRAE03462	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC							O/C	
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772013	No. 1 Engine - Tgt Thermocouple (No. 2) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03445	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772013 (772014)	No. 2 Engine - Tgt Thermocouple (No. 2) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03467	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772015	No. 1 Engine - Tgt Thermocouple (No. 3) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03446	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772015 (772016)	No. 2 Engine - Tgt Thermocouple (No. 3) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03521	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772017	No. 1 Engine - Tgt Thermocouple (No. 4) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03449	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			
772017 (772018)	No. 2 Engine - Tgt Thermocouple (No. 4) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03522	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772019	No. 1 Engine - Tgt Thermocouple (No. 5) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03458	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772019 (772020)	No. 2 Engine - Tgt Thermocouple (No. 5) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03525	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772021	No. 1 Engine - Tgt Thermocouple (No. 6) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03464	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772021 (772022)	No. 2 Engine - Tgt Thermocouple (No. 6) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03527	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772023	No. 1 Engine - Tgt Thermocouple (No. 7) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03465	MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											
772023 (772024)	No. 2 Engine - Tgt Thermocouple (No. 7) - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	TC429-01	RRAE03532	MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
773001	Engine Vibration Monitor Unit - Removal / Installation		HRS		4057.8			0			0
	241-265-000-011	AD02581	AFL		1184			0			0
			MOS		188.2			24 May 2008			VIBRO-METER SA
	Airframe		MSC					O/C			
773005	No. 1 Engine - Engine Forward Vibration Tranducer - Removal / Installation		HRS		4057.8			0			0
	144-151-000-301	AC70922	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			GULFSTREAM SAV PROD-IPT
	Engine		MSC					O/C			
773005 (773006)	No. 2 Engine - Engine Forward Vibration Tranducer - Removal / Installation		HRS		4057.8			0			0
	144-151-000-301	AC70926	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			GULFSTREAM SAV PROD-IPT
	Engine		MSC					O/C			
773007	No. 1 Engine - Engine Aft Vibration Transducer - Removal / Installation		HRS		4057.8			0			0
	144-151-000-301	AC70929	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			GULFSTREAM SAV PROD-IPT
	Engine		MSC					O/C			
773007 (773008)	No. 2 Engine - Engine Aft Vibration Transducer - Removal / Installation		HRS		4057.8			0			0
	144-151-000-301	AC70930	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			GULFSTREAM SAV PROD-IPT
	Engine		MSC					O/C			
773101	Engine Vibration Monitor System - Operational Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
78 - Exhaust											
780005	Thrust Reverser and Exhaust (Left) - Zonal Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
Airframe				[HRS: +50/-50]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
780006	Thrust Reverser and Exhaust (Right) - Zonal Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
Airframe			[HRS: +50/-50]								
780007	Thrust Reverser (Left) - Inspection / Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
780008	Thrust Reverser (Right) - Inspection / Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
780009	Thrust Reverser (Left) - Bleed Procedure		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
780010	Thrust Reverser (Right) - Bleed Procedure		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
780015	Thrust Reverser Pivoting Doors Lockout (Left) - Procedure		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
780020	Thrust Reverser Pivoting Doors Lockout (Right) - Procedure		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe			MSC				O/C				
781101	No. 1 Engine - Exhaust Nozzle - Inspection		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		1			31 Dec 2023			
Engine			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
781101 (781102)	No. 2 Engine - Exhaust Nozzle - Inspection		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		1			31 Dec 2023			
	Engine		MSC					O/C			
781103	No. 1 Engine - Exhaust Cone Assembly - Inspection		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		1			31 Dec 2023			
	Engine		MSC					O/C			
781103 (781104)	No. 2 Engine - Exhaust Cone Assembly - Inspection		HRS		0			4057.8			0
			ENC		0			1184			0
			MOS		1			31 Dec 2023			
	Engine		MSC					O/C			
781111	No. 1 Engine - Exhaust Cone Assembly - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	PN	SN-UNKNOWN	MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			
781111 (781112)	No. 2 Engine - Exhaust Cone Assembly - Removal / Installation		HRS		4057.8			0			0
			ENC		1184			0			0
	PN	SN-UNKNOWN	MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
783001	Engine Thrust Reverser (Left) - Removal / Installation		HRS		4057.8			0			0
	25G0001-005	LH399	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
783002	Engine Thrust Reverser (Right) - Removal / Installation		HRS		4057.8			0			0
	25G0001-007	RH400	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			GULFSTREAM - LONG BEACH

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783003	T/Rev Pivot Door Deflector Plates / Fixed Structure		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
	Discharge Fairing (Left) - Detailed Inspection		AFL		0			1184			0
			MOS		1			31 Dec 2023			
	Airframe		[HRS: +50/-50]								
783004	T/Rev Pivot Door Deflector Plates / Fixed Structure		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
	Discharge Fairing (Right) - Detailed Inspection		AFL		0			1184			0
			MOS		1			31 Dec 2023			
	Airframe		[HRS: +50/-50]								
783005	Thrust Reverser Manual Restow System (Left) -		HRS		4057.8			0			0
	Operational Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
783006	Thrust Reverser Manual Restow System (Right) -		HRS		4057.8			0			0
	Operational Test		AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
783007	Thrust Reverser (Left) - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
783008	Thrust Reverser (Right) - Operational Check		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC				O/C				
783009	Thrust Reverser Front Face Torsion Box Front Frame		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
	(Left) - Detailed Inspection		AFL		0			1184			0
			MOS		1			31 Dec 2023			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783010	Thrust Reverser Front Face Torsion Box Front Frame (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
	Airframe		[HRS: +50/-50]								
783013	Thrust Reverser Ground Relay (Left) - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.8	55	36	06 Sep 2023	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
783014	Thrust Reverser Ground Relay (Right) - Operational Test		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.8	55	36	06 Sep 2023	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
783040	Thrust Reverser / Exhaust Flow Path Surface (Left) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
	Airframe		[HRS: +50/-50]								
783041	Thrust Reverser / Exhaust Flow Path Surface (Right) - Detailed Inspection		HRS		0	31.9	1000	4057.8	5089.7*	5139.7	0
			AFL		0			1184			0
			DATE		31 d			31 Dec 2023			
	Airframe		[HRS: +50/-50]								
783101	Thrust Reverser Upper Pivoting Door (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	04G2037-003	UL1417	MOS		188.2			24 May 2008			
			MSC								
	Airframe		O/C								
783102	Thrust Reverser Upper Pivoting Door (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	04G2037-004	UR1394	MOS		188.2			24 May 2008			
			MSC								
	Airframe		O/C								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783103	Thrust Reverser Lower Pivoting Door (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	25G2039-001	LL1261	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783104	Thrust Reverser Lower Pivoting Door (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	25G2039-002	LR1265	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783105	Upper Thrust Reverser Door (Left) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783106	Upper Thrust Reverser Door (Right) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783107	Lower Thrust Reverser Door (Left) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783108	Lower Thrust Reverser Door (Right) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783109	Thrust Reverser Pivoting Doors (Left) - Inspection		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
			MSC							O/C	
Airframe											
783110	Thrust Reverser Pivoting Doors (Right) - Inspection		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
			MSC							O/C	
Airframe											

Notes: PN: P466A 0001 02 SN: DAW3070-08.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783111	Primary Door Actuator ROD End (Left) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		72	07 Jun 2022	30 Jun 2028	31 Jul 2028	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
783112	Primary Door Actuator ROD End (Right) - Detailed Inspection		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.8		72	07 Jun 2022	30 Jun 2028	31 Jul 2028	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
783115	Thrust Reverser Deactivate / Activate (Left) - Procedure		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		.7			08 Jan 2024			
Airframe		MSC O/C									
Notes: PN: 04C0001-020 SN: <NONE>											
783116	Thrust Reverser Deactivate / Activate (Right) - Procedure		HRS		0			4057.8			0
			AFL		0			1184			0
			MOS		1			31 Dec 2023			
Airframe		MSC O/C									
783130	Fan Duct Outer Skin (Left) - General Visual Inspection		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			AFL		44			1140			0
			MOS		5.4			18 Aug 2023			
Airframe		[HRS: +50/-50]									
783131	Fan Duct Outer Skin (Right) - General Visual Inspection		HRS		134.1		4000	3923.7	7923.7	7973.7	0
			AFL		44			1140			0
			MOS		5.4			18 Aug 2023			
Airframe		[HRS: +50/-50]									
783301	T/Rev Isolation Control Unit (Left) - Removal / Installation		HRS		4057.8			0			0
	P463A0001-07	DAW862-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			
Airframe		MSC O/C ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783302	T/Rev Isolation Control Unit (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P463A0001-07	DAW866-08	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783303	T/Rev Direction Control Unit (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P464A 0001-01	DAW814-07	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783304	T/Rev Direction Control Unit (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P464A 0001-01	DAW839-08	MOS		188.2			24 May 2008			
			MSC							O/C	
Airframe											
783305	Upper Door Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P471A0001-01	DAW2753-08	MOS		188.2			24 May 2008			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											
783306	Upper Door Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P471A0001-01	DAW2755-08	MOS		188.2			24 May 2008			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											
783307	Lower Door Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P471A0001-01	DAW2759-08	MOS		188.2			24 May 2008			
			MSC							O/C	ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783308	Lower Door Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	P471A0001-01	DAW2754-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783309	Outer T/Rev Primary Lock Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
	P466A0001-02	DAW3208-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783310	Outer T/Rev Primary Lock Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
	P466A0001-02	NSN	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783311	Upper Thrust Reverser Tertiary Lock (Left) - Removal / Installation		HRS		4057.8			0			0
	P465A0101-00	DAW2945-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783312	Upper Thrust Reverser Tertiary Lock (Right) - Removal / Installation		HRS		4057.8			0			0
	P465A0101-00	DAW2959-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			
783313	Lower Thrust Reverser Tertiary Lock (Left) - Removal / Installation		HRS		4057.8			0			0
	P465A0101-00	DAW2946-08	AFL		1184			0			0
			MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783314	Lower Thrust Reverser Tertiary Lock (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P465A0101-00	DAW2972-08	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783315	Upper Tertiary Lock (Left) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
783316	Upper Tertiary Lock (Right) - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
783317	Inboard T/Rev Primary Lock Actuator (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P466A0001-02	DAW3029-08	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783318	Inboard T/Rev Primary Lock Actuator (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	P466A0001-02	DAW 3071-08	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783319	Isolation Control Unit (Left) - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
783320	Isolation Control Unit (Right) - Servicing		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783321	Inner Primary Lock S-Hook (Left) - Removal / Installation		HRS		4057.8			0			0
	04G0421-055	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783322	Inner Primary Lock S-Hook (Right) - Removal / Installation		HRS		4057.8			0			0
	04G0421-055	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783323	Outer Primary Lock S-Hook (Left) - Removal / Installation		HRS		4057.8			0			0
	04G0421-055	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783324	Outer Primary Lock S-Hook (Right) - Removal / Installation		HRS		4057.8			0			0
	04G0421-055	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783325	Thrust Reverser Upper Tertiary Lock (Left) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783326	Thrust Reverser Upper Tertiary Lock (Right) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783327	Thrust Reverser Lower Tertiary Lock (Left) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783328	Thrust Reverser Lower Tertiary Lock (Right) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC					O/C			
Airframe											
783401	Upper Inboard Door Stow Switch (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N 3262	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783402	Upper Inboard Door Stow Switch (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N3265	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783403	Upper Outboard Door Stow Switch (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N3277	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783404	Upper Outboard Door Stow Switch (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N3268	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											
783405	Lower Inboard Door Stow Switch (Left) - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	T7013-3	0884	MOS		69			01 May 2018			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC					O/C			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783406	Lower Inboard Door Stow Switch (Right) - Removal / Installation		HRS		1654.7			2403.1			0
			AFL		493			691			0
	T7013-3	0896	MOS		69			01 May 2018			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe			MSC								
783407	Lower Outboard Door Stow Switch (Left) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N3274	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe			MSC								
783408	Lower Outboard Door Stow Switch (Right) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	T7013	S/N 3271	MOS		188.2			24 May 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Airframe			MSC								
783409	Door Position Sensor (Left Upper) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	133 F 025 005	A101476	MOS		188.2			24 May 2008			
Airframe			MSC								
783410	Door Position Sensor (Right Upper) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	133 F 025 005	A101466	MOS		188.2			24 May 2008			
Airframe			MSC								
783411	Door Position Sensor (Left Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	133 F 025 005	A101503	MOS		188.2			24 May 2008			
Airframe			MSC								
783412	Door Position Sensor (Right Lower) - Removal / Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	133 F 025 005	A101502	MOS		188.2			24 May 2008			
Airframe			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783413	Thrust Reverser Test Switch (Left) - Removal / Installation		HRS		4057.8			0			0
	101TL2834-6	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			JERRY PAIR
	Airframe		MSC					O/C			
783414	Thrust Reverser Test Switch (Right) - Removal / Installation		HRS		4057.8			0			0
	101TL2834-6	SN-UNKNOWN	AFL		1184			0			0
			MOS		188.2			24 May 2008			JERRY PAIR
	Airframe		MSC					O/C			
783415	Door Position Sensor (Left Upper) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783416	Door Position Sensor (Right Upper) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783417	Door Position Sensor (Left Lower) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
783418	Door Position Sensor (Right Lower) - Adjustment / Test		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		188.2			24 May 2008			
	Airframe		MSC					O/C			
79 - Oil											
790001	Oil Servicing Reservoir - Removal / Installation		HRS		4057.8			0			0
	1159SCP565-3	0373	AFL		1184			0			0
			MOS		188.2			24 May 2008			GULFSTREAM SAV PROD-IPT
	Airframe		MSC					O/C			
Notes: Q306794											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790002	Engine and APU Oil Servicing Pump - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1B5-17	2BD18	MOS		188.2			24 May 2008			PARKER HANNIFIN CORPORATION
			MSC					O/C			
Airframe											
Notes: Q306794											
790004	Oil Replenishing System Selector Valve - Removal /		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	1159SCP105-1	0545	MOS		188.2			24 May 2008			CHASE WALTON ELASTOMERS
			MSC					O/C			
Airframe											
Notes: Q306794											
790011	No. 1 Engine - Magnetic Chip Detectors - Detailed		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
	Inspection		ENC		44			1140			0
			MOS		5.4			20 Aug 2023			
			[HRS: +50/-50]								
Engine											
790011 (790012)	No. 2 Engine - Magnetic Chip Detectors - Detailed		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
	Inspection		ENC		44			1140			0
			MOS		5.4			20 Aug 2023			
			[HRS: +50/-50]								
Engine											
790015	No. 1 Engine - Engine Fwd Bearing Chamber Magnetic		HRS		134.1			3923.7			0
	Chip Detector - Removal / Installation		ENC		44			1140			0
	VA3510-1	13590	MOS		5.4			20 Aug 2023			N/A
			MSC					O/C			
Engine											
790015 (790016)	No. 2 Engine - Engine Fwd Bearing Chamber Magnetic		HRS	TSN:3923.7	134.1			3923.7			0
	Chip Detector - Removal / Installation		ENC	TSN:1140	44			1140			0
	VA3510-1	13587	MOS		5.4			20 Aug 2023			N/A
			MSC					O/C			
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790017	No. 1 Engine - Engine Aft Bearing Chamber Magnetic		HRS		134.1			3923.7			0
	Chip Detector - Removal / Installation		ENC		44			1140			0
	VA3510-1	13577	MOS		5.4			20 Aug 2023			N/A
			MSC								
Engine											
790017 (790018)	No. 2 Engine - Engine Aft Bearing Chamber Magnetic		HRS	TSN:3923.7	134.1			3923.7			0
	Chip Detector - Removal / Installation		ENC	TSN:1140	44			1140			0
	VA3510-1	13570	MOS		5.4			20 Aug 2023			N/A
			MSC								
Engine											
790019	No. 1 Engine - Engine Accessory Gearbox Magnetic Chip		HRS		134.1			3923.7			0
	Detector - Removal / Installation		ENC		44			1140			0
	VA3510-1	13576	MOS		5.4			20 Aug 2023			N/A
			MSC								
Engine											
790019 (790020)	No. 2 Engine - Engine Accessory Gearbox Magnetic Chip		HRS		134.1			3923.7			0
	Detector - Removal / Installation		ENC		44			1140			0
	VA3510-1	13574	MOS		5.4			20 Aug 2023			N/A
			MSC								
Engine											
791101	Engine Oil Tank Sight Gage / Remote Oil Panel (Left) -		HRS		4057.8			0			0
	Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
791102	Engine Oil Tank Sight Gage / Remote Oil Panel (Right) -		HRS		4057.8			0			0
	Inspection		AFL		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
Airframe											
792005	No. 1 Engine - Engine Oil Pump - Removal / Installation		HRS		4057.8			0			0
	LR47000B		ENC		1184			0			0
		C0515	MOS		189.4			20 Apr 2008			
			MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792005 (792006)	No. 2 Engine - Engine Oil Pump - Removal / Installation		HRS		4057.8			0			0
	LR47000B	C0473	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			
792101	No. 1 Engine - Oil Pressure Filter - Detailed Inspection		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			ENC		280			904			0
			MOS		30.7		48	09 Jul 2021	31 Jul 2025	31 Aug 2025	
	Engine							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
792101 (792102)	No. 2 Engine - Oil Pressure Filter - Detailed Inspection		HRS		857.7		1000	3200.1	4200.1	4250.1	0
			ENC		280			904			0
			MOS		30.7		48	09 Jul 2021	31 Jul 2025	31 Aug 2025	
	Engine							[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
792105	No. 1 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		857.7			3200.1			0
	QA08196	NSN	ENC		280			904			0
			MOS	TSN:4	30.7			09 Jul 2021			N/A
	Engine		MSC					O/C			
792105 (792106)	No. 2 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		857.7			3200.1			0
	QA08196	NSN	ENC		280			904			0
			MOS	TSN:4	30.7			09 Jul 2021			N/A
	Engine		MSC					O/C			
792201	No. 1 Engine - Engine Fuel Cooled Oil Cooler - Removal / Installation		HRS		4057.8			0			0
	55006001-21	55006-1313	ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
	Engine		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
792201 (792202)	No. 2 Engine - Engine Fuel Cooled Oil Cooler - Removal / Installation		HRS		4057.8			0			0
	55006001-21	55006-1309	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
	Engine		MSC					O/C			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793001	No. 1 Engine - Oil Filter Differential Pressure Indicator - Detailed Inspection		HRS		134.1	18.1	500	3923.7	4441.8*	4491.8	0
			ENC		44			1140			0
			MOS		5.4			18 Aug 2023			
	Engine		[HRS: +50/-50]								
793001 (793002)	No. 2 Engine - Oil Filter Differential Pressure Indicator - Detailed Inspection		HRS		134.1	37.9	500	3923.7	4461.6*	4511.6	0
			ENC		44			1140			0
			MOS		5.5			17 Aug 2023			
	Engine		[HRS: +50/-50]								
793003	No. 1 Engine - Engine Oil Filter Differential Pressure POP-Up Indicator - Removal / Installation		HRS		4057.8			0			0
	QA07508		ENC		1184			0			0
	RS3-3363		MOS		189.4			20 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC				O/C				
793003 (793004)	No. 2 Engine - Engine Oil Filter Differential Pressure POP-Up Indicator - Removal / Installation		HRS		4057.8			0			0
	QA07508		ENC		1184			0			0
	RS3-3364		MOS		189.2			24 Apr 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
	Engine		MSC				O/C				
793005	No. 1 Engine - Oil Differential Pressure Transducer (No. 1) - Removal / Installation		HRS		4057.8			0			0
	PDCR300164001M1		ENC		1184			0			0
	2678624		MOS		189.4			20 Apr 2008			CAPPLUGS LLC.
	Engine		MSC				O/C				
793005 (793006)	No. 2 Engine - Oil Differential Pressure Transducer (No. 1) - Removal / Installation		HRS		4057.8			0			0
	PDCR300164001M1		ENC		1184			0			0
	2742545		MOS		189.2			24 Apr 2008			CAPPLUGS LLC.
	Engine		MSC				O/C				
793011	No. 1 Engine - Oil Temperature Transducer (No. 1) - Removal / Installation		HRS		4057.8			0			0
	1122806		ENC		1184			0			0
	R9886		MOS		189.4			20 Apr 2008			COVER GRAPHICS INC
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793011 (793012)	No. 2 Engine - Oil Temperature Transducer (No. 1) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	1122806	R2806	MOS		189.2			24 Apr 2008			COVER
	Engine		MSC					O/C			GRAPHICS INC
793015	No. 1 Engine - Oil Filter Differential Pressure Switch -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	21SN04-472	J007885	MOS		189.4			20 Apr 2008			EATON
	Engine		MSC					O/C			AEROSPACE/EN GINEERED SENSORS LLC
793015 (793016)	No. 2 Engine - Oil Filter Differential Pressure Switch -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	21SN04-472	J008776	MOS		189.2			24 Apr 2008			EATON
	Engine		MSC					O/C			AEROSPACE/EN GINEERED SENSORS LLC
793017	No. 1 Engine - Oil Temperature Transducer (No. 2) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	1122806	R9892	MOS		189.4			20 Apr 2008			COVER
	Engine		MSC					O/C			GRAPHICS INC
793017 (793018)	No. 2 Engine - Oil Temperature Transducer (No. 2) -		HRS		4057.8			0			0
	Removal / Installation		ENC		1184			0			0
	1122806	R6147	MOS		189.2			24 Apr 2008			COVER
	Engine		MSC					O/C			GRAPHICS INC
793019	No. 1 Engine - Oil Differential Pressure Transducer (No. 2)		HRS		4057.8			0			0
	- Removal / Installation		ENC		1184			0			0
	PDCR300164001M1	2700821	MOS		189.4			20 Apr 2008			CAPLUGS LLC.
	Engine		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793019 (793020)	No. 2 Engine - Oil Differential Pressure Transducer (No. 2)		HRS		4057.8			0			0
	- Removal / Installation		ENC		1184			0			0
	PDCR300164001M1	2742544	MOS		189.2			24 Apr 2008			CAPPLUGS LLC.
			MSC								
Engine											
80 - Starting											
801001	No. 1 Engine - AIR Turbine Starter - Removal / Installation		HRS		4057.8			0			0
	3505934-8 0308-2103		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			COMPONENT
			MSC								SOURCE INC.
Engine											
801001 (801002)	No. 2 Engine - AIR Turbine Starter - Removal / Installation		HRS		4057.8			0			0
	3505934-8 0408-2106		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			COMPONENT
			MSC								SOURCE INC.
Engine											
801003	No. 1 Engine - Starter Qad Adapter - Removal / Installation		HRS		4057.8			0			0
	3504760-2 SN-UNKNOWN		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC								
Engine											
801003 (801004)	No. 2 Engine - Starter Qad Adapter - Removal / Installation		HRS		4057.8			0			0
	3504760-2 SN-UNKNOWN		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC								
Engine											
801005	No. 1 Engine - Starter AIR Valve - Removal / Installation		HRS		4057.8			0			0
	3291182-4 1207-2199		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			HONEYWELL-
			MSC								ENGINEERING
Engine											
SYSTEMS & SERV.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
801005 (801006) Engine	No. 2 Engine - Starter AIR Valve - Removal / Installation		HRS		4057.8			0			0
	3291182-4	0308-2240	ENC		1184			0			0
			MOS		189.2			24 Apr 2008			HONEYWELL- ENGINEERING SYSTEMS & SERV.
			MSC					O/C			
801009 Engine	No. 1 Engine - AIR Turbine Starter Oil - Change		HRS		2673.4			1384.4			0
			ENC		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					O/C			
801009 (801010) Engine	No. 2 Engine - AIR Turbine Starter Oil - Change		HRS		2673.4			1384.4			0
			ENC		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					O/C			
801011 Engine	No. 1 Engine - AIR Turbine Starter Magnetic Chip Collector - Detailed Inspection		HRS		134.1		1000	3923.7	4923.7	4973.7	0
			ENC		44			1140			0
			MOS		5.4		48	20 Aug 2023	31 Aug 2027	30 Sep 2027	
								[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
801011 (801012) Engine	No. 2 Engine - AIR Turbine Starter Magnetic Chip Collector - Detailed Inspection		HRS		134.1		1000	3923.7	4923.7	4973.7	0
			ENC		44			1140			0
			MOS		5.4		48	20 Aug 2023	31 Aug 2027	30 Sep 2027	
								[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]			
92 - -											
922112^U Airframe	Video AMP		HRS		4025.2			32.6			0
	VA-400-01	030700179	AFL		1170			14			0
			MOS		184.6			12 Sep 2008			AUDIO INT
			MSC					-			

AD - Airworthiness Directives

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2012-0166 (993097) Engine	No. 1 Engine - 2012-0166 Engine - High Pressure Turbine		HRS		2280.7			1777.1			0
	Rotor Disc Stage 1 and Stage 2 Life Limit Implementation		ENC		691			493			0
			MOS		106.2			24 Mar 2015			
			MSC								
EASA 2012-0166 (993098) (993097) Engine	No. 2 Engine - 2012-0166 Engine - High Pressure Turbine		HRS		2280.7			1777.1			0
	Rotor Disc Stage 1 and Stage 2 Life Limit Implementation		ENC		691			493			0
			MOS		106.2			24 Mar 2015			
			MSC								
EASA 2013-0020 (993102) Airframe	EASA AD 2013-0020 - Safety Belts / Torso Restraint		HRS		4057.8			0			0
	Systems - Inspection / Replacement		AFL		1184			0			0
			MOS		130.5			14 Mar 2013			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
EASA 2013-0020 R01 (993107) Airframe	EASA AD 2013-0020R1 - Safety Belts / Torso Restraint		HRS		2749			1308.8			0
	Systems - Inspection / Replacement		AFL		811			373			0
			MOS		127.6			11 Jun 2013			
			MSC								
Notes: INSPECTION PERFORMEDTHERE ARE NO AFECTED (REPAIRED) SEAT BELT TORSO RESTRAINT SYSTEMS											
EASA 2014-0142 R01 (993114) Airframe	EASA AD 2014-0142R1 - Oxygen Mask Regulator		HRS		2414			1643.8			0
	Inflatable Harness / Hose		AFL		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC								
EASA 2022-0110 (992211) Engine	No. 1 Engine - EASA 2022-0110 - Engine - Low Pressure		HRS								0
	Compressor Rotor (Fan) Disc - Inspection		ENC								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
EASA 2022-0110 (992212) (992211) Engine	No. 2 Engine - EASA 2022-0110 - Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection		HRS								0
			ENC								0
			DATE								
			MSC								
EASA 2022-0110 R01 (992213) Engine	No. 1 Engine - EASA 2022-0110 R01 - Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection (Mandatory)		HRS								0
			ENC								0
			DATE								
			MSC								
EASA 2022-0110 R01 (992214) (992213) Engine	No. 2 Engine - EASA 2022-0110 R01 - Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection (Mandatory)		HRS								0
			ENC								0
			DATE								
			MSC								
FAA 1974-08-09 R02 (997427) Airframe	AD 74-08-09 R2 Lavatory Inspection		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
FAA 1974-08-09 R03 (994002) Airframe	AD 74-08-09 R3 Lavatory Paper and Linen Waste Receptacle Enclosure Access Door and Disposal Door Inspection		HRS		0	1000		4057.8	5057.8		0
			AFL		0			1184			0
			MOS		1.1			29 Dec 2023			
FAA 1998-24-27 (999825) Airframe	AD 98-24-27 1ST Tech FIRE Btl		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC								
FAA 1998-25-10 R01 (999831) Airframe	AD 98-25-10R1 Seat Belt Restraint		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2002-21-01 (992204) Airframe	AD 2002-21-01 Britax Sell Appliances		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2003-26-14 (992310) Airframe	AD 2003-26-14 898052 FIRE Bottl		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2004-02-01 (992401) Airframe	AD 2004-02-01 Lg Select Dump Valve		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2005-16-14 (992509) Airframe	AD 2005-16-14 Adel Wiggins Floor Heater - Deactivation		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2005-20-26 (992513) Airframe	AD 2005-20-26 Aviointeriors Model 312 Seats		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			02 Sep 2008			
			MSC					-			
FAA 2006-04-13 R01 (992603) Airframe	AD 2006-04-13 R1 Afm Procedure, Ckpt Displays Malfunction		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2006-18-08 (992608) Airframe	AD 2006-18-08 Goodyear Aviation Tires		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		188.1			28 May 2008			
			MSC					-			
FAA 2006-19-04 PARA (F) (992610) Airframe	AD 2006-19-04 Honeywell International (14 Day)		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			02 Sep 2008			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2006-19-04 PARA (G) (992611) Airframe	AD 2006-19-04 Honeywell International (18 Month)		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			02 Sep 2008			
			MSC								
FAA 2007-07-12 (992704) Airframe	AD 2007-07-12 Honeywell Nav Computer		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			02 Sep 2008			
			MSC								
FAA 2007-12-25 (992707) Airframe	FAA 2007-12-25 - Water/Waste - Revising the Airplane Flight Manuals (AFMS) of Those Airplanes, and Doing Repetitive Functional Checks of the Forward Water Drain/Supply Valves and Applicable Corrective Actions		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			02 Sep 2008			
			MSC								
FAA 2009-17-01 (992902) Airframe	AD 2009-17-01 Inspection for Sealant Applied to the Exterior of the Auxiliary Power Unit (APU) Enclosure		HRS		3785			272.8			0
			AFL		1100			84			0
			MOS		172.7			10 Sep 2009			
			MSC								
FAA 2009-21-10 R01 (992904) Airframe	AD 2009-21-10 R1 Avox Systems and B/E Aerospace Oxygen Cylinder Assemblies		HRS		3655.6			402.2			0
			AFL		1075			109			0
			MOS		166.6			11 Mar 2010			
			MSC								
FAA 2010-01-03 (993001) Airframe	AD 2010-01-03 FIRE Fighting Enterprises Limited Portable Halon 1211 FIRE Extinguishers		HRS		3655.6			402.2			0
			AFL		1075			109			0
			MOS		166.6			11 Mar 2010			
			MSC								
FAA 2010-25-05 TBL 1 (993007) Engine	No. 1 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		4057.8			0			0
	Turbine Discs Stage 1 Assembly Life Limits - Modification		ENC		1184		6200	0	6200		0
			DATE								

Notes: PN: ANY SN: <NONE>.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2010-25-05 TBL 1 (993008) (993007) Engine	No. 2 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		4057.8			0			0
	Turbine Discs Stage 1 Assembly Life Limits - Modification		ENC		1184		6200	0	6200		0
			DATE								
FAA 2010-25-05 TBL 2 (993010) Engine	No. 1 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		4057.8			0			0
	Turbine Discs Stage 2 Assembly Life Limits - Modification		ENC		1184		10500	0	10500		0
			DATE								
FAA 2010-25-05 TBL 2 (993011) (993010) Engine	No. 2 Engine - 2010-25-05 - Engine - High Pressure (Hp)		HRS		4057.8			0			0
	Turbine Discs Stage 2 Assembly Life Limits - Modification		ENC		1184		10500	0	10500		0
			DATE								
FAA 2011-01-09 (993009) Airframe	AD 2011-01-09 B/E Aerospace Pbe (P/N) 119003-11		HRS		3277.1			780.7			0
			AFL		960			224			0
			MOS		151.8			06 Jun 2011			
			MSC				-				
FAA 2011-22-01 (993016) Engine	No. 1 Engine - 2011-22-01 - Engine - General - Change of		HRS		3557.8			500			0
	Life Cycle Counting Method for Touch-and-Go and		ENC		1035			149			0
	Overshoot		MOS		163.3			23 Jun 2010			
			MSC				-				
FAA 2011-22-01 (993017) (993016) Engine	No. 2 Engine - 2011-22-01 - Engine - General - Change of		HRS		3557.8			500			0
	Life Cycle Counting Method for Touch-and-Go and		ENC		1035			149			0
	Overshoot		MOS		163.3			23 Jun 2010			
			MSC				-				
FAA 2011-24-02 (994000) Airframe	AD 2011-24-02 Gulfstream Aerospace Corporation (Third		HRS		3421.8			636			0
	Halon FIRE Bottle for Engines)		AFL		995			189			0
			MOS		157.1			27 Dec 2010			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

FAA 2012-02-08 (994001) Airframe	AD 2012-02-08 - Aviation Communication & Surveillance Systems, Llc		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		136.6			11 Sep 2012			
			MSC								

FAA 2012-26-15 (998000) Airframe	AD 2012-26-15 Honeywell International		HRS		2834.6			1223.2			0
			AFL		830			354			0
			MOS		131.5			15 Feb 2013			
			MSC								

Notes: ADM SN ARE N/A AS PER ADM/ADC/ADAHRS-34-A01, DATED NOVEMBER 6, 2012ADM 1:P PN:HG1153CA0S4/,SN :08032957ADM 2:P PN:HG1153CA0S4/,SN :08032958ADM 3:P PN:HG1153CA0S4/,SN :08032978

FAA 2012-26-15 R01 (998001) Airframe	AD 2012-26-15 R1 Honeywell International		HRS		2125.4			1932.4			0
			AFL		648			536			0
			MOS		97.5			16 Dec 2015			
			MSC								

Notes: *REFER TO CMP 998000

FAA 2013-03-17 (993103) Engine	No. 1 Engine - 2013-03-17 - Engine - High Pressure Turbine Rotor Disc Stage 1 and Stage 2 Life Limitation - Implementation		HRS		2280.7			1777.1			0
			ENC		691			493			0
			MOS		106.2			24 Mar 2015			
			MSC								

Notes: ENGINE 1 HPT STAGE 1 AND STAGE 2 DISCS S/N NOT AFFECTED

FAA 2013-03-17 (993104) (993103) Engine	No. 2 Engine - 2013-03-17 - Engine - High Pressure Turbine Rotor Disc Stage 1 and Stage 2 Life Limitation - Implementation		HRS		2280.7			1777.1			0
			ENC		691			493			0
			MOS		106.2			24 Mar 2015			
			MSC								

Notes: ENGINE 2 HPT STAGE 1 AND STAGE 2 DISCS S/N NOT AFFECTED

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2013-05-13	No. 1 Engine - AD 2013-05-13 - Engine - Accessory		HRS		2749	-1308.8		1308.8			0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		811			373			0
	Coupling		MOS		128.1			28 May 2013			
			MSC								
(994011)	Engine										
Notes: INITIAL INSPECTION - ENG DATA PLATE INSPECTEDAT 4000 ENGINES FH FUEL PUMPS TO BE REPLACED											
FAA 2013-05-13	No. 2 Engine - AD 2013-05-13 - Engine - Accessory		HRS		2749	-1308.8		1308.8			0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		811			373			0
	Coupling		MOS		128.1			28 May 2013			
			MSC								
(994011)	Engine										
Notes: INITIAL INSPECTION - ENG DATA PLATE INSPECTEDAT 4000 ENGINES FH FUEL PUMPS TO BE REPLACED											
FAA 2013-22-19	AD 2013-22-19 Fuel Boost Pump		HRS		2670			1387.8			0
			AFL		785			399			0
			MOS		124.2			25 Sep 2013			
			MSC								
(994013)	Airframe										
Notes: FUEL BOOST PUMPS INSTALLED P/N: 1159SCP500-7FUEL LEAK CHECK INTERVAL OF 500 FH IMPLEMENTED THROUGH MAINTENANCE PROGRAMME ISSUE 2 REV.0 / 25 SEP 2013											
FAA 2014-18-01	AD 2014-18-01 Rockwell Collins MODE S Transponders		HRS		1947.2			2110.6			0
	Tdr-94/Tdr-94D		AFL		587			597			0
			MOS		90.5			17 Jul 2016			
			MSC								
(994015)	Airframe										
Notes: AFFECTED UNITS NOT INSTALLED ON LZ-FIA.REFER TO ATTACHED COMPONENT STATUS REPORT.											
FAA 2015-08-07	AD 2015-08-07 Zodiac Aerotechnics (Formerly		HRS		1827.9			2229.9			0
	Intertechnique Aircraft Systems) - Oxygen Mask Regulator		AFL		554			630			0
	Inflatable Harness - Identification / Replacement		MOS		84.5			16 Jan 2017			
			MSC								
(994018)	Airframe										
FAA 2015-16-04	AD 2015-16-04 Kidde Graviner		HRS		2062.3			1995.5			0
			AFL		625			559			0
			MOS		94.8			06 Mar 2016			
			MSC								
(994019)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2015-23-09 INSPECT (994021) Airframe	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 1 - Inspect)		HRS		2082.5			1975.3			0
			AFL		637			547			0
			MOS		96.5			16 Jan 2016			
			MSC								
FAA 2015-23-09 REPLACE (994022) Airframe	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 2 - Replace)		HRS		2082.5			1975.3			0
			AFL		637			547			0
			MOS		96.5			16 Jan 2016			
			MSC								
FAA 2016-11-20 (994026) Airframe	AD 2016-11-20 - B/E Aerospace Pbe P/N 119003-11		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC								
Notes: EQUIPMENT NOT INSTALLED											
FAA 2016-13-12 (994027) Engine	No. 1 Engine - 2016-13-12 - Engine - Pawl Carrier Pivot Pins, Part Number (P/N) BRR17117, - Remove from Service / Replace		HRS		1909.4			2148.4			0
			ENC		573			611			0
			MOS		87.9			03 Oct 2016			
Notes: ENGINE ESN 15499 - NOT AFFECTED BY AD											
FAA 2016-13-12 (994028) (994027) Engine	No. 2 Engine - 2016-13-12 - Engine - Pawl Carrier Pivot Pins, Part Number (P/N) BRR17117, - Remove from Service / Replace		HRS		1909.4			2148.4			0
			ENC		573			611			0
			MOS		87.9			03 Oct 2016			
Notes: ENGINE ESN 15500 - NOT AFFECTED BY AD											
FAA 2016-18-11 (994029) Airframe	AD 2016-18-11 Gulfstream Aerospace Corporation (MLG End CAP)		HRS		4057.8			0			0
			AFL				9500**		9500		0
			DATE								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2016-22-04 (994034) Airframe	AD 2016-22-04 Gulfstream Aerospace Corporation (ALS Amm Chapter 05-10-10)		HRS		1831.3			2226.5			0
			AFL		556			628			0
			MOS		85.5			15 Dec 2016			
			MSC								
Notes: BHAIR AMP ISS 05 IAW AMM REV.25											
FAA 2017-08-01 (994039) Airframe	AD 2017-08-01 - Gulfstream Aerospace - Fuel Boost Pump		HRS		1785			2272.8			0
			AFL		539			645			0
			MOS		80.2			26 May 2017			
			MSC								
Notes: ALREADY COMPLIED WITH											
FAA 2017-18-12 (994042) Airframe	AD 2017-18-12 B/E Aerospace		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC								
Notes: EQUIPMENT NOT INSTALLED											
FAA 2017-20-08 (994045) Airframe	AD 2017-20-08 - Gulfstream Aerospace - Gulfstream Afm Supplement Incorporation		HRS		1711.1			2346.7			0
			AFL		512			672			0
			MOS		75.1			27 Oct 2017			
			MSC								
FAA 2018-18-14 (994066) Engine	No. 1 Engine - AD 2018-18-14 - Electronic Engine Controller (Eec) Firebox Assembly		HRS		229.7			3828.1			0
			ENC		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
FAA 2018-18-14 (994067) (994066) Engine	No. 2 Engine - AD 2018-18-14 - Electronic Engine Controller (Eec) Firebox Assembly		HRS		229.7			3828.1			0
			ENC		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2018-21-14	AD 2018-21-14 Zodiac Aerotechnics (Formerly		HRS		857.7			3200.1			0
	Intertechnique) - Oxygen Mask Regulator Harness		AFL		280			904			0
	Inflation Hose - Identification / Replacement		MOS		30.6			13 Jul 2021			
(994070)			MSC								
Airframe											
FAA 2021-12-07	No. 1 Engine - Engine - High Pressure Turbine (Hpt)		HRS								0
	Stage 1 Disk - Replace (Mandatory)		ENC								0
			DATE								
(991207)			MSC								
Engine											
FAA 2021-12-07	No. 2 Engine - Engine - High Pressure Turbine (Hpt)		HRS								0
	Stage 1 Disk - Replace (Mandatory)		ENC								0
			DATE								
(991207)			MSC								
Engine											
FAA 2021-23-12	Indicating / Recording / Navigation - Radio (Radar)		HRS		229.7			3828.1			0
	Altimeter - Afm Revision to Incorporate Limitations		AFL		82			1102			0
	(Mandatory)		MOS		8.3			23 May 2023			
(992199)			MSC								
Airframe											
FAA 2021-26-02	2021-26-02 - Landing Gear - Main Landing Gear (MLG)		HRS		313.5			3744.3			0
	Trunnion Pin - Life Limit		AFL		117			1067			0
			MOS		10.5			14 Mar 2023			
(992126)			MSC								
Airframe											
FAA 2022-16-04	2022-16-04 - Horizontal Stabilizer Structure - Horizontal		HRS		13.4			4044.4			0
	Stabilizer Lower Bonded Skin Assemblies - Inspection		AFL		4			1180			0
	(Mandatory)		MOS		1.3			21 Dec 2023			
(992255)			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2022-16-04 PARA (G) (992256) Airframe	2022-16-04 Para (G) - Incorporation of Airworthiness Limitations (ALS) Revisions (Mandatory)		HRS		13.4			4044.4			0
			AFL		4			1180			0
			DATE		41 d			21 Dec 2023			
			MSC								
FAA 2022-16-04 PARA (I) (992257) Airframe	2022-16-04 Para (I) - Perform the Horizontal Stabilizer Lower Skin Resonance C-Scan Inspection (Part II Inspection) for Bond Line Corrosion and Apply Corrosion Inhibiting Compound (Cic); IF Bondline Corrosion Is Found Perform Repair Within 48 Mths (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC								
FAA 2022-24-06 (992224) Engine	No. 1 Engine - Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection (Mandatory)		HRS								0
			ENC								0
			DATE								
			MSC								
FAA 2022-24-06 (992224) Engine	No. 2 Engine - Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection (Mandatory)		HRS								0
			ENC								0
			DATE								
			MSC								
FAA 2022-26-02 PARA (G) EASA (1.1) (991600) Engine	No. 1 Engine - 2022-26-02 Para (G) EASA (1.1) - Replace Each Component before Exceeding the Applicable Life Limit or before Exceeding the Applicable Threshold, or Within the Special Compliance Times Specified In Table 1 of This AD (Mandatory)		HRS		0			4057.8			0
			ENC		0			1184			0
			DATE		20 d			11 Jan 2024			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2022-26-02 PARA (G) EASA (1.1)	No. 2 Engine - 2022-26-02 Para (G) EASA (1.1) - Replace		HRS		0			4057.8			0
	Each Component before Exceeding the Applicable Life		ENC		0			1184			0
	Limit or before Exceeding the Applicable Threshold, or		DATE		20 d			11 Jan 2024			
	Within the Special Compliance Times Specified In Table 1 of This AD (Mandatory)		MSC								
(991600)	Engine										
FAA 2022-26-02 PARA (G) EASA (3)	No. 1 Engine - 2022-26-02 Para (G) EASA (3) - Accessory		HRS		0			4057.8			0
	Gearboxes - Incorporate the Actions and Associated		ENC		0			1184			0
	Thresholds and Intervals, Including Life Limits and		DATE		20 d			11 Jan 2024			
	Maintenance Tasks, Into the Existing Approved Maintenance or Inspection Program, as Applicable (Mandatory)		MSC								
(991601)	Engine										
FAA 2022-26-02 PARA (G) EASA (3)	No. 2 Engine - 2022-26-02 Para (G) EASA (3) - Accessory		HRS		0			4057.8			0
	Gearboxes - Incorporate the Actions and Associated		ENC		0			1184			0
	Thresholds and Intervals, Including Life Limits and		DATE		20 d			11 Jan 2024			
	Maintenance Tasks, Into the Existing Approved Maintenance or Inspection Program, as Applicable (Mandatory)		MSC								
(991601)	Engine										
FAA 2023-02-02	2023-02-02 - Landing Gear System - Life Limit Main		HRS		134.1			3923.7			0
	Landing Gear (MLG) Trunnion Pin (Mandatory)		AFL		44			1140			0
			MOS		4.8			06 Sep 2023			
			MSC								
(992302)	Airframe										
FAA 2023-10-02	Appliance AD - FAA 2023-10-02 - Indicating/Recording		HRS		13.4			4044.4			0
	System/Navigation - Radio Altimeter - Afm Revision		AFL		4			1180			0
	(Mandatory)		MOS		1.3			21 Dec 2023			
			MSC								
(992312)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2023-10-02 PARA (H)	FAA 2023-10-02 Para (H) - Revise the Limitations Section of the Existing Afm (until 30--June- 2023 - Satisfied By		HRS		229.7			3828.1			0
	FAA 2021-23-12) (Mandatory)		AFL		82			1102			0
			MOS		8.3			23 May 2023			
			MSC								
(992313)	Airframe										
FAA 2023-10-02 PARA (I)	FAA 2023-10-02 Para (I) - Revise the Limitations Section and Remove the Afm Revision Required By Para (H)		HRS		13.4			4044.4			0
	(after 30 Jun 2023) (Mandatory)		AFL		4			1180			0
			MOS		1.3			21 Dec 2023			
			MSC								
(992314)	Airframe										
SIAC - Service Information/Bulletins											
941400	FAA NEXTGEN Program Mandate: ADS-B Out Compliance		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.8			05 Sep 2019			
			MSC								
(941400)	Airframe										
941401	FAA NEXTGEN Program Mandate: FANS 1/A+ Compliance		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.4			19 Jul 2021			
			MSC								
(941401)	Airframe										
949005	Cmc Module Reliability Enhancement Program (Mp-17-5501)		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC								
(949005)	Airframe										
9910001^U	Cabin Interior STC ST02093-La-D		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC								
(9910001)	Airframe										
ACB008	Acb 8 Modification-Tail Compartment Ladder		HRS		4021.3			36.5			0
			AFL		1169			15			0
			MOS		184.2			25 Sep 2008			
			MSC								
(990080)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB009 (990090) Airframe	Acb 9 - Operational Limitations - Auxiliary Power Unit (APU)		HRS		3836			221.8			0
			AFL		1129			55			0
			MOS		176.1			28 May 2009			
			MSC								
ACB009A (990091) Airframe	Acb 9A - Operational Limitations - Auxiliary Power Unit (APU)		HRS		3812.9			244.9			0
			AFL		1121			63			0
			MOS		175			01 Jul 2009			
			MSC								
ACB010 PART I (990100) Airframe	Acb 10 Part I - Inspection - Third Engine FIRE Bottle Installation		HRS		3421.4			636.4			0
			AFL		995			189			0
			MOS		157.1			27 Dec 2010			
			MSC								
Notes: APPLIANCE NOT INSTALLED.											
ACB010 PART II (990101) Airframe	Acb 10 Part II - Inspection - Third Engine FIRE Bottle Installation		HRS		3421.4			636.4			0
			AFL		995			189			0
			MOS		157.1			27 Dec 2010			
			MSC								
Notes: PART II NOT APPLICABLE											
ACB010A PART I (990102) Airframe	Acb 10A Part 1 - Inspection - Third Engine FIRE Bottle Installation		HRS		3421.4			636.4			0
			AFL		995			189			0
			MOS		157.1			27 Dec 2010			
			MSC								
Notes: PREVIOUSLY COMPLIED WITH											
ACB010A PART II (990103) Airframe	Acb 10A Part 2 - Inspection - Third Engine FIRE Bottle Installation		HRS		3421.4			636.4			0
			AFL		995			189			0
			MOS		157.1			27 Dec 2010			
			MSC								
Notes: PREVIOUSLY COMPLIED WITH											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB011	Acb 11 - Operational Limitations - Auxiliary Power Unit		HRS		3812.9			244.9			0
	(APU) Enclosure With Thermal Barrier Coating		AFL		1121			63			0
	(990110)		MOS		175			01 Jul 2009			
Airframe											
ACB012	Acb 12 Operational Limitations - Auxiliary Power Unit		HRS		2943.7			1114.1			0
	(APU) Enclosure With Thermal Barrier Coating -		AFL		858			326			0
	Expanded Effectivity		MOS		137.2			25 Aug 2012			
	(990120)		MSC					-			
Airframe											
Notes: SERIAL NUMBER NOT AFFECTED											
ACB013	ACB013 - Engine Turbine / Ducted Fan (ATA 72)		HRS		346.5			3711.3			0
	Inspection - BR710 Fan Disc (Rolls-Royce Nmsb Alert Sb-		AFL		129			1055			0
	BR700-72-A900732), Alert Customer Bulletin		DATE		350 d			15 Feb 2023			
	(Mandatory)		MSC					-			
(990130)											
Airframe											
ASC002B	ASC 2B Digital Flight Recorder System Upgrade		HRS		4048.2			9.6			0
	(970022)		AFL		1179			5			0
	Airframe		MOS		184.9			03 Sep 2008			
			MSC					-			
ASC002C	ASC 2C Digital Flight Data Recorder System Upgrade (88		HRS		4001.8			56			0
	Parameters)		AFL		1168			16			0
	(970023)		MOS		182.2			24 Nov 2008			
	Airframe		MSC					-			
Notes: AIRCRAFT THAT HAVE PREVIOUSLY COMPLIED WITH THE ORIGINAL ISSUE OF ASC 002 DATED DECEMBER 5, 2003; OR ASC 002A DATED NOVEMBER 15, 2006; OR ASC 002B DATED FEBRUARY 20, 2008; HAVE MET THE INTENT OF THIS REVISION.											
ASC002D	ASC 2D Digital Flight Data Recorder System Upgrade (88		HRS		4057.8			0			0
	Parameters)		AFL		1184			0			0
	(970024)		DATE								
	Airframe		MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC008 (970080) Airframe	ASC 8 Max Gross Wgt 75K Placard		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		187.4			18 Jun 2008			
			MSC					-			
ASC008A (970081) Airframe	ASC 8A Maximum Gross Weight 75,000 Pounds		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		119.2			24 Feb 2014			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC008B (970082) Airframe	ASC 8B Maximum Gross Weight 75,000 Pounds		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.7			10 Sep 2019			
			MSC					-			
ASC009 (970090) Airframe	ASC 9 Max Zero Fuel Gross Wgt		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		187.4			18 Jun 2008			
			MSC					-			
ASC009A (970091) Airframe	ASC 9A Maximum Zero Fuel Gross Weight 53,500 Pounds - Placard Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		152.7			09 May 2011			
			MSC					-			
ASC009B (970092) Airframe	ASC 9B Maximum Zero Fuel Gross Weight 53,500 Pounds - Placard Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC011 (970110) Airframe	ASC 11 G550 Data Plate Install		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC014 (970140) Airframe	ASC 14 Category Ii Annunciation - Activation		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.1			29 Aug 2008			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC014A (970141) Airframe	ASC 14A Category Ii Annunciation - Activation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		185.1			29 Aug 2008			
			MSC					-			
ASC033 (970330) Airframe	ASC 33 Bonded Honeycomb Panels		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC035A PART 1 (970351) Airframe	ASC 35A (Part 1) EASA / Jaa Cert - BASIC Requirements		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.4			20 Aug 2008			
			MSC					-			
ASC035A PART 2 (970352) Airframe	ASC 35A (Part 2) EASA / Jaa Cert - BASIC Requirements		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC047 (970470) Airframe	ASC 47 Water System Improvement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC049 (970490) Airframe	ASC 49 Lightning Sensor System (Lss) Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		184.9			03 Sep 2008			
			MSC					-			
ASC049A (970491) Airframe	ASC 49A Lightning Sensor System (Lss) Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		97.7			10 Dec 2015			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC049B (970492) Airframe	ASC 49B Lightning Sensor System (Lss) Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC049C	Navigation (ATA 34) - Lightning Sensor System (Lss) - Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
	(970493)		DATE								
Airframe		MSC									

ASC053	ASC 53 Comm Management Fnc ARINC Direct-Datalink		HRS		4057.8			0			0
			AFL		1184			0			0
	(970530)		MOS		119.2			24 Feb 2014			
Airframe		MSC									

Notes: THIS CODE HAS BEEN CANCELLED.

ASC053A	ASC 53A Communications Management Function ARINC Direct - Datalink Service Provider		HRS		1654.7			2403.1			0
			AFL		493			691			0
	(970531)		MOS		65.7			09 Aug 2018			
Airframe		MSC									

ASC061	ASC 61 Synthetic Vision-Primary Flight Display (Sv-Pfd) Installation		HRS		4021.3			36.5			0
			AFL		1169			15			0
	(970610)		MOS		184.2			24 Sep 2008			
Airframe		MSC									

ASC061 AM1	ASC 61 AM1- Synthetic Vision Primary Flight Display (Sv-Pf)		HRS		4057.8			0			0
			AFL		1184			0			0
	(970611)		MOS		163.9			04 Jun 2010			
Airframe		MSC									

ASC061A	ASC 61A Synthetic Vision-Primary Flight Display (Sv-Pfd) Installation		HRS		4057.8			0			0
			AFL		1184			0			0
	(970612)		MOS		119.2			24 Feb 2014			
Airframe		MSC									

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC061A AM1	ASC 61A AM1 Synthetic Vision - Primary Flight Display		HRS		4057.8			0			0
	(Sv-Pfd) Installation		AFL		1184			0			0
	(970613)		MOS		119.2			24 Feb 2014			
	Airframe		MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC061B	ASC 61B Synthetic Vision-Primary Flight Display (Sv-Pfd)		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	(970614)		DATE								
	Airframe		MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC063A PART I	ASC 63A Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 1		AFL		1184			0			0
	(970631)		MOS		130			01 Apr 2013			
	Airframe		MSC					O/C			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC063A PART II	ASC 63A Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 2		AFL		1184			0			0
	(970632)		MOS		130			01 Apr 2013			
	Airframe		MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC063B PART 1	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 1		AFL		1184			0			0
	(970633)		MOS		92.6			12 May 2016			
	Airframe		MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC063B PART 2	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 2		AFL		1184			0			0
	(970634)		MOS		92.6			12 May 2016			
	Airframe		MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC063B PART 3 (970635) Airframe	ASC 63B Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 3		AFL		1184			0			0
			MOS		92.6			12 May 2016			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC063C PART 1 (970636) Airframe	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 1		AFL		1184			0			0
			DATE								
			MSC								

ASC063C PART 2 (970637) Airframe	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 2		AFL		1184			0			0
			DATE								
			MSC								

ASC063C PART 3 (970638) Airframe	ASC 63C Wing Fuel Transfer Sys Mid-Wing Ejector MOD		HRS		4057.8			0			0
	Part 3		AFL		1184			0			0
			DATE								
			MSC								

ASC065A (970651) Airframe	ASC 65A Runway Awareness Advisory System- Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.4			20 Aug 2008			
			MSC								

ASC071 (970710) Airframe	ASC 71 Micro Quick Access Recorder Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		125.4			20 Aug 2013			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC072 (970720) Airframe	ASC 72 Medeco Door Locks Installation		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.4			18 Aug 2008			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC073 (970730) Airframe	ASC 73 Nose Gear Uplock Hook Spring Replacement		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.8			06 Aug 2008			
			MSC					-			
ASC073A (970731) Airframe	ASC 73A Nose Gear Uplock Hook Spring Replacement		HRS		3889.8			168			0
			AFL		1140			44			0
			MOS		178.5			16 Mar 2009			
			MSC					-			
Notes: PREVIOUS CW ASC073 GAC WO#FP3196 / SEP/22/2008											
ASC074 (970740) Airframe	ASC 74 Dual Brake Metering Valve Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		180.3			23 Jan 2009			
			MSC					-			
ASC074A (970741) Airframe	ASC 74A Dual Brake Metering Valve Replacement		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		136.6			11 Sep 2012			
			MSC					-			
ASC074A AM1 (970742) Airframe	ASC 74A AM1 Dual Brake Metering Valve Replacement		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137.2			25 Aug 2012			
			MSC					-			
ASC080 (970800) Airframe	ASC 80 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC					-			
ASC080 AM1 (970801) Airframe	ASC 80 AM1 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		3468.8			589			0
			AFL		1008			176			0
			MOS		159.1			29 Oct 2010			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC080 AM2 (970802) Airframe	ASC 80 AM2 Modification - Wing Rear Beam - Flight Spoiler Actuator Attachment Point		HRS		3468.8			589			0
			AFL		1008			176			0
			MOS		159.1			29 Oct 2010			
			MSC								
ASC082 (970820) Airframe	ASC 82 Tail Compartment Ladder - Hinge Pin and Placard		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		179.1			27 Feb 2009			
			MSC								
ASC082A (970821) Airframe	ASC 82A Tail Compartment Ladder - Hinge Pin and Placard		HRS		3786.5			271.3			0
			AFL		1102			82			0
			MOS		173.3			23 Aug 2009			
			MSC								
ASC082A AM1 (970822) Airframe	ASC 82A AM1 Tail Compartment Ladder - Hinge Pin and Placard		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC083 (970830) Airframe	ASC 83 Planeview Avionics Enhancement (Cert Fox)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		161.4			19 Aug 2010			
			MSC								
ASC083A (970831) Airframe	ASC 83A Planeview Avionics Enhancement (Cert Fox)		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
ASC084 (970840) Airframe	ASC 84 Enhanced Navigation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		161.4			19 Aug 2010			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC084A (970841) Airframe	ASC 84A Enhanced Navigation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		119.2			24 Feb 2014			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC084B (970842) Airframe	ASC 84B Enhanced Navigation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		104.3			21 May 2015			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC084C (970843) Airframe	ASC 84C Enhanced Navigation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		87.4			19 Oct 2016			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC084D (970844) Airframe	ASC 84D Enhanced Navigation		HRS		1654.7			2403.1			0
			AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC					-			
ASC085 (970850) Airframe	ASC 85 Xm Weather Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		161.4			19 Aug 2010			
			MSC					-			
ASC085A (970851) Airframe	ASC 85A Xm Weather Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		73.4			18 Dec 2017			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC085B (970852) Airframe	ASC 85B Xm Weather Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC085B-CN	ASC085B-Cn - Indicating/Recording - Xm Weather		HRS								0
	Installation (New Installations Discontinued See All Mol-22		AFL								0
	-0016), Aircraft Service Change (Cancelled)		DATE								
	(970852)		MSC								
	Airframe										
ASC087	ASC 87 Canadian Certification Requirements		HRS		4057.8			0			0
	(970870)		AFL		1184			0			0
			DATE								
			MSC								
	Airframe										
ASC089	ASC 89 Stage 4 Noise Standards - Certification		HRS		4057.8			0			0
	(970890)		AFL		1184			0			0
			MOS		125.4			20 Aug 2013			
			MSC								
	Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC090	ASC 90 Auxiliary Power Unit (APU) Enclosure - Thermal		HRS		4057.8			0			0
	Barrier Installation		AFL		1184			0			0
	(970900)		MOS		160.7			10 Sep 2010			
			MSC								
	Airframe										
ASC090 AM1	ASC 90 AM1 Auxiliary Power Unit (APU) Enclosure -		HRS		4057.8			0			0
	Thermal Barrier Installation		AFL		1184			0			0
	(970901)		MOS		155.7			10 Feb 2011			
			MSC								
	Airframe										
ASC090A	ASC 90A Auxiliary Power Unit (APU) Enclosure - Thermal		HRS		2943.7			1114.1			0
	Barrier Installation		AFL		858			326			0
	(970902)		MOS		137.3			21 Aug 2012			
			MSC								
	Airframe										
ASC091	ASC 91 Enhanced Baggage Door Seal System -		HRS		4057.8			0			0
	Installation		AFL		1184			0			0
	(970910)		MOS		119.2			24 Feb 2014			
			MSC								
	Airframe										

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC091A (970911) Airframe	ASC 91A Enhanced Baggage Door Seal System - Installation		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.8			07 Sep 2015			
			MSC								
ASC092 (970920) Airframe	ASC 92 Communication Management Function (Cmf) - SATCOM Direct - Datalink Service Provider		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC093A (970931) Airframe	ASC 93A Aileron Cable Fairleads AT Sponson Rib - Installation		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.7			09 Sep 2015			
			MSC								
ASC094 (970940) Airframe	ASC 94 Landing Gear Door Close - Restrictor		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		149.9			02 Aug 2011			
			MSC								
ASC094A (970941) Airframe	ASC 94A Landing Gear Door Close - Restrictor		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		119.2			24 Feb 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED.											
ASC094B (970942) Airframe	ASC 94B Landing Gear Door Close - Restrictor		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137			31 Aug 2012			
			MSC								
ASC095B (970952) Airframe	ASC 95B Planeview Avionics Enhancement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC096 (970960) Airframe	ASC 96 CPDLC - FANS 1/A		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC097B (970972) Airframe	ASC 97B Data Link Recording		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC099 (970990) Airframe	ASC 99 Aileron and Elevator Power Disconnect - Removal		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC								
ASC099A (970991) Airframe	ASC 99A Aileron and Elevator Power Disconnect - Removal		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		124.9			03 Sep 2013			
			MSC								
Notes: PREVIOUSLY COMPLIED WITH											
ASC103 (971030) Airframe	ASC 103 TCAS 7.1 Installation		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		136.6			11 Sep 2012			
			MSC								
ASC104 (971040) Airframe	ASC 104 Aileron Cable Penetrations AT FS 576.5 Floor Beam - Rework		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		124.7			10 Sep 2013			
			MSC								
ASC105 (971050) Airframe	ASC 105 Automatic Dependent Surveillance - Broadcast (ADS-B) Out Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		103.5			15 Jun 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC105A (971051) Airframe	ASC 105A Automatic Dependent Surveillance - Broadcast		HRS		4057.8			0			0
	(ADS-B) Out Installation		AFL		1184			0			0
			MOS		91.5			15 Jun 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC105B (971052) Airframe	ASC 105B Automatic Dependent Surveillance - Broadcast		HRS		4057.8			0			0
	(ADS-B) Out Installation		AFL		1184			0			0
			MOS		89.2			24 Aug 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC105C (971053) Airframe	ASC 105C Automatic Dependent Surveillance - Broadcast		HRS		1654.7			2403.1			0
	(ADS-B) Out Installation		AFL		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC								
ASC106 (971060) Airframe	ASC 106 Fuel Quantity Signal Conditioner - Revision G		HRS		2414			1643.8			0
	Software		AFL		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC								
ASC107 (971070) Airframe	ASC 107 Planeview Avionics Enhancement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC108 (971080) Airframe	ASC 108 APU Enclosure Non-Compliant Sealant -		HRS		4057.8			0			0
	Modification		AFL		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC109	ASC109 - Stabilizers (ATA 55) - Horizontal Stabilizer		HRS								0
	Interior Corrosion Inhibiting Compound (Cic) - Restorative		AFL								0
	Application, Aircraft Service Change (Mandatory)		MOS				48**		26 Aug 2024	26 Nov 2024	
(971090)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC110	ASC 110 Cockpit Portable FIRE Extinguisher - Relocation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		123.9				02 Oct 2013		
(971100)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC110A PART I	ASC 110A (Part 1) Cockpit Portable FIRE Extinguisher /		HRS		2176.4			1881.4			0
	Pilot Seat Track Stop - Relocation		AFL		663			521			0
			MOS		100.7				09 Sep 2015		
(971101)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC111	ASC 111 Mandates Package (CPDLC / ADS-B Out)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		114.1				29 Jul 2014		
(971110)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC111A	ASC 111A Communication / Navigation (ATA 23 / 34)		HRS		4057.8			0			0
	Mandates Package (CPDLC / ADS-B Out)		AFL		1184			0			0
			DATE								
(971111)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC112	ASC 112 Elevator Hardover Prevention System (Hops) -		HRS		2176.4			1881.4			0
	Improvement		AFL		663			521			0
			MOS		100.6				11 Sep 2015		
(971120)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC113	ASC 113 Planeview Avionics Enhancement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		112.4				18 Sep 2014		
(971130)											
Airframe											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC113A (971131) Airframe	ASC 113A Planeview Avionics Enhancement		HRS		2020.5			2037.3			0
			AFL		612			572			0
			MOS		92.6			13 May 2016			
			MSC					-			
ASC116 (971160) Airframe	ASC 116 Nose Landing Gear (NLG) Harness - Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		100.5			17 Sep 2015			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC116A (971161) Airframe	ASC 116A Nose Landing Gear (NLG) Harness - Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		91			01 Jul 2016			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC116B (971162) Airframe	ASC 116B Nose Landing Gear (NLG) Harness - Installation		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC					-			
ASC116C (971163) Airframe	ASC 116C Nose Landing Gear (NLG) Harness - Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC117 (971170) Airframe	ASC 117 - Baggage Door Striker Plates - Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC120 (971200) Airframe	ASC 120 Engine Driven Pump (Edp) Case Drain Hose Routing In Left Pylon		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.9			03 Sep 2015			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC122 (971220) Airframe	ASC 122 Pressure Supply Line - Modification		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.5			15 Sep 2015			
			MSC					-			
ASC123 (971230) Airframe	ASC 123 Planeview Avionics Enhancement		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		87.9			03 Oct 2016			
			MSC					-			
ASC123A (971231) Airframe	ASC 123A Planeview Avionics Enhancement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		56.5			14 May 2019			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC123B (971232) Airframe	ASC 123B Planeview Avionics Enhancement		HRS		957.9			3099.9			0
			AFL		313			871			0
			DATE		1296 d			14 Jul 2020			
			MSC					-			
ASC123C (971233) Airframe	ASC 123C Planeview Avionics Enhancement		HRS		957.9			3099.9			0
			AFL		313			871			0
			DATE		1296 d			14 Jul 2020			
			MSC					-			
ASC126 (971260) Airframe	ASC 126 Cargo Lights Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC126A (971261) Airframe	ASC126A - Lights (ATA 33) - Cargo Lights Replacement, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC127 (971270) Airframe	ASC 127 Led Navigation and Anticollision Strobe Light Upgrade		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC128 (971280) Airframe	ASC 128 Flashlights - Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		67.3			22 Jun 2018			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC128A (971281) Airframe	ASC 128A Flashlights - Replacement		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC128B (971282) Airframe	Equipment and Furnishings (ATA 25) - Flashlights – Replacement, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC129 (971290) Airframe	ASC 129 Junction Panel Relay Obsolescence Modification		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		63.2			26 Oct 2018			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC129A (971291) Airframe	ASC 129A Junction Panel Relay Obsolescence Modification		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			
ASC132 (971320) Airframe	ASC132 - Fuselage Structure (ATA 53) - Auxiliary Power Unit Enclosure Installation - Modification, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC133 (971330) Airframe	ASC 133 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

ASC133A PART 1	ASC133A - Part 1 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 1 Modification Instructions (-1 Kit, Aft Equipment Bay Installation)), Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
(971331)			MSC								
		Airframe									

ASC133A PART 2	ASC133A - Part 2 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 2 Modification Instructions (-2 Kit, Baggage Compartment Installation)), Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
(971332)			MSC								
		Airframe									

ASC134	ASC 134 Auxiliary Hydraulic Pump - Grounding Installation		HRS		857.7			3200.1			0
			AFL		280			904			0
			DATE		933 d			12 Jul 2021			
(971340)			MSC								
		Airframe									

ASC135	Indicating / Recording (ATA 31) - High-Speed LAN Implementation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
(971350)			MSC								
		Airframe									

ASC136	ASC 136 Wing to Body Fairings Av-Dec Gasket Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		67.4			18 Jun 2018			
(971360)			MSC								
		Airframe									

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ASC136A	ASC 136A Wing to Body Fairings Av-Dec Gasket Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		61.6			13 Dec 2018			
(971361)			MSC								
		Airframe									

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC136B	ASC 136B Wing to Body Fairings Av-Dec Gasket Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
	(971362)			MSC							
Airframe											
ASC137	ASC 137 Horizontal Stabilizer Cove Panels Av-Dec Gasket Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		59.4			19 Feb 2019			
	(971370)			MSC							
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC137A	ASC 137A Horizontal Stabilizer Cove Panels Av-Dec Gasket Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
	(971371)			MSC							
Airframe											
ASC137B	ASC137B - Stablizers (ATA 55) - Horizontal Stabilizer Cove Panels Av-Dec Gasket Installation		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.5			17 Sep 2023			
	(971372)			MSC							
Airframe											
ASC138	ASC 138 Cabin Seat Tracks (FS 426.5 - FS 632.0) Av-Dec Sealant Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
	(971380)			MSC							
Airframe											
ASC138A	Fuselage Structure (ATA 53) - Cabin Seat Tracks (FS 426.5 - FS 632.0) Av-Dec Sealant Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
	(971381)			MSC							
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC139	ASC139 - Fuselage Structure (ATA 53) Elevator Trim		HRS								0
	Servo - Bracket Installation, Aircraft Service Change		AFL								0
	(Optional)		DATE								
(971390)			MSC								-
Airframe											
ASC139A	ASC139A - Fuselage Structure (ATA 53) Elevator Trim		HRS		134.1			3923.7			0
	Servo - Bracket Installation, Aircraft Service Change		AFL		44			1140			0
	(Optional)		DATE		136 d			17 Sep 2023			
(971391)			MSC								-
Airframe											
ASC143	ASC143 - Stabilizers (ATA 55) - Horizontal Stabilizer		HRS								0
	Upper Access Panels Av-Dec Gasket - Installation, Aircraft		AFL								0
	Service Change (Optional)		DATE								
(971430)			MSC								-
Airframe											
ASC148	ASC148 - Communications (ATA 23) - Communications		HRS								0
	Management Function (Cmf) SATCOM Direct (Non-Sita)		AFL								0
	Datalink Service Provider, Aircraft Service Change		DATE								
(971480)	(Optional)		MSC								-
Airframe											
ASC908	ASC 908 Planeview Master Operating System Software		HRS		4057.8			0			0
	Update (Cert Fox)		AFL		1184			0			0
			MOS		161.4			19 Aug 2010			
(979080)			MSC								-
Airframe											
ASC908A	ASC 908A Planeview Master Operating System Software		HRS		3242.3			815.5			0
	Update (Cert Fox)		AFL		944			240			0
			MOS		149			30 Aug 2011			
(979081)			MSC								-
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC909B (979092) Airframe	ASC 909B Planeview Master Operating System Software Update		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC								
ASC910 (979100) Airframe	ASC 910 Planeview Master Operating System Software Update		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
ASC911 (979110) Airframe	ASC 911 Planeview Master Operating System Software Update		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		112.4			18 Sep 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC911A (979111) Airframe	ASC 911A Planeview Master Operating System Software Update		HRS		2020.5			2037.3			0
			AFL		612			572			0
			MOS		92.6			13 May 2016			
			MSC								
ASC912 (979120) Airframe	ASC 912 Planeview Master Operating System Software Update		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		87.9			03 Oct 2016			
			MSC								
ASC912A (979121) Airframe	ASC 912A Planeview Master Operating System Software Update		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		56.5			14 May 2019			
			MSC								

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC912B (979122) Airframe	ASC 912B Planeview Master Operating System Software Update		HRS		957.9			3099.9			0
			AFL		313			871			0
			DATE		1296 d			14 Jul 2020			
			MSC								
ASC912C (979123) Airframe	ASC 912C Planeview Master Operating System Software Update		HRS		957.9			3099.9			0
			AFL		313			871			0
			DATE		1296 d			14 Jul 2020			
			MSC								
BR700-78-101996^U (887862) Airframe	Sb BR700-78-101996 - Right Tru - Introduction of Revised Seal Supports and Inhibition Keeper		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
BR700-78-101996^U (887861) Airframe	Sb BR700-78-101996 - Left Tru - Introduction of Revised Seal Supports and Inhibition Keeper		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
BR700-78-102008 R01^U (887860) Airframe	Sb BR700-78-102008R1 - Right Tru - Introduction of A Drainage Hole Within the Thrust Reverser Fixed Structure to Prevent Corrosion.		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								
BR700-78-102008 R01^U (887859) Airframe	Sb BR700-78-102008R1 - Left Tru - Introduction of A Drainage Hole Within the Thrust Reverser Fixed Structure to Prevent Corrosion.		HRS		4057.8			0			0
			AFL		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-78-900350 R02^U	Sb BR700-78-900350R2 - Inspection of the Spherical Bearing of the Primary Door Lock Actuator (Pdla) and Cleaning of the S-Hook Assembly (Left)		HRS		4057.8			0			0
			AFL		1184			0			0
			MSC								
(887853)											
Airframe											
Notes: PN: P466A0001-01 SN: <NONE>.											
BR700-78-900350 R02^U	Sb BR700-78-900350R2 - Inspection of the Spherical Bearing of the Primary Door Lock Actuator (Pdla) and Cleaning of the S-Hook Assembly (Right)		HRS		4057.8			0			0
			AFL		1184			0			0
			MSC								
(897853)											
Airframe											
Notes: PN: P466A0001-01 SN: <NONE>.											
CB069	Cb 69 MOD-Nose Gear Uplock Hook Spring (ASC 73)		HRS		4048.2			9.6			0
			AFL		1179			5			0
			MOS		185.8			06 Aug 2008			
(980690)			MSC								
Airframe											
CB074	Cb 74 - Flight Spoiler Actuator Attachment Point - Inspection		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		182.6			13 Nov 2008			
(980740)											
Airframe											
CB074A	Cb 74A - Flight Spoiler Actuator Attachment Point - Inspection		HRS		3907.4			150.4			0
			AFL		1148			36			0
			MOS		180.1			29 Jan 2009			
(980741)			MSC								
Airframe											
CB074A AM1	Cb 74A AM1- Flight Spoiler Actuator Attachment Point - Inspection		HRS		3907.4			150.4			0
			AFL		1148			36			0
			MOS		180.1			29 Jan 2009			
(980742)			MSC								
Airframe											
Notes: PREVIOUS C/W CB74A - JAN/29/2009 EO-O-0139/ER-0917											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB080 (980800) Airframe	Cb 80 MOD - Tail Compartment Access Ladder (ASC 082)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		179.1			27 Feb 2009			
			MSC					-			
CB080A (980801) Airframe	Cb 80A MOD - Tail Compartment Access Ladder (ASC 082A)		HRS		3786.5			271.3			0
			AFL		1102			82			0
			MOS		173.2			25 Aug 2009			
			MSC					-			
CB081 (980810) Airframe	Cb 81 - Divan Seat Belt Anchor Installation		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		179.6			13 Feb 2009			
			MSC					-			
CB081A (980811) Airframe	Cb 81A - Divan Seat Belt Anchor Installation		HRS		3855.8			202			0
			AFL		1131			53			0
			MOS		176.8			05 May 2009			
			MSC					-			
CB083 (980830) Airframe	Cb 83 Modification- Wing Rear Beam Flight Spoiler Actuator Attachment Point (ASC 80)		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC					-			
CB083 AM1 (980831) Airframe	Cb 83 AM1 Modification- Wing Rear Beam Flight Spoiler Actuator Attachment Point (ASC 80)		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC					-			
CB084 (980840) Airframe	Cb 84 Replacement - Accessory Gearbox Pressure Relief Valve		HRS		3739.7			318.1			0
			AFL		1091			93			0
			MOS		171.1			28 Oct 2009			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB084 AM1 (980841) Airframe	Cb 84 AM1 Replacement - Accessory Gearbox Pressure Relief Valve		HRS		3739.7			318.1			0
			AFL		1091			93			0
			MOS		171.1			28 Oct 2009			
			MSC								
CB086 (980860) Airframe	Cb 86 Modification - Sealing of Nose Wheel Steering Electrical Connectors		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
CB087 (980870) Airframe	Cb 87 Global Positioning System Cable Installation AT Fuselage Station 139		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
CB089 (980890) Airframe	Cb 89 Replacement - Power Distribution Box Contactors, Pn 5912336-3		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								
CB090 (980900) Airframe	Cb 90 Inspection - Winslow Life Raft		HRS		3687			370.8			0
			AFL		1080			104			0
			MOS		167.5			17 Feb 2010			
			MSC								
Notes: PN: 1421FAUL-6K0-1-100 SN: 14UL-00347 AND 14UL-00348. TWO LIFE RAFTS P/N 1421FAUL-6K0-1-100 ARE INSTALLED: S/N 14UL-00347 AND S/N 14UL-00348											
CB091 (980910) Airframe	Cb 91 Modification - Nose Jack Point		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								
CB092 (980920) Airframe	Cb 92 Modification - Pilot / Copilot Seat - Forward / Aft Adjustment Control Lever		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB093 (980930) Airframe	Cb 93 Inspection - Horizontal Stabilizer Actuator		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC					-			
CB094 (980940) Airframe	Cb 94 Engine (ATA 72), General - Change of Life Counting Method for Touch-and-Go and Overshoot (Rolls-Royce Alert Sb-BR700-72-A900504)		HRS		3557.8			500			0
			AFL		1035			149			0
			MOS		163.3			23 Jun 2010			
			MSC					-			
CB096 (980960) Airframe	Cb 96 Replacement - Emergency Brake Accumulator and Landing Gear Emergency Extension Nitrogen Blow-Down Bottle Charging Valves		HRS		3489.3			568.5			0
			AFL		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC					-			
CB100 (981000) Airframe	Cb 100 Inspection - Crew Seat Inertia Reels		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		163.8			07 Jun 2010			
CB100A (981001) Airframe	Cb 100A Inspection - Crew Seat Inertia Reels		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC					-			
CB102 (981020) Airframe	Cb 102 Modification - Emergency Battery Pack		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC					-			
CB103 (981030) Airframe	Cb 103 Inspection - Fasteners AT Fuselage Station 63, Left and Right Butt Line 19		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB104 (981040) Airframe	Cb 104 Inspection - Engine Electronic Controller Lane A Harness 1A		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
CB107 (981070) Airframe	Cb 107 Inspection - Door Control Valve Hydraulic Lines		HRS		3242.3			815.5			0
			AFL		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
CB108 (981080) Airframe	Cb 108 - Inspection - Left Engine Hydraulic Pressure Line		HRS		2943.3			1114.5			0
			AFL		858			326			0
			MOS		137.5			17 Aug 2012			
CB110 (981100) Airframe	Cb 110 Modification - Landing Gear Door Close - Restrictor Installation (ASC 094)		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		149.9			02 Aug 2011			
			MSC								
CB110A (981101) Airframe	Cb 110A Modification - Landing Gear Door Close - Restrictor Installation (ASC 094)		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137			30 Aug 2012			
			MSC								
CB111 (981110) Airframe	Cb 111 Inspection - Enhanced Vision System (Evs) Radome Support Strut, P/N 1159SCAM561-1		HRS		3064.8			993			0
			AFL		893			291			0
			MOS		142.4			19 Mar 2012			
			MSC								
Notes: PN: 1159SCAM561-1 SN: <NONE>											
CB112 (981120) Airframe	Cb 112 Modification - Tail Compartment Ladder Attach Fittings		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137.3			21 Aug 2012			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB114 (981140) Airframe	Cb 114 Non-Compliance - Stage 3 Noise Certification (ASC 008B)		HRS		3038.5			1019.3			0
			AFL		883			301			0
			MOS		140.3			23 May 2012			
			MSC								
CB116 (981160) Airframe	Cb 116 Inspection - Engine / Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief Discharge Port		HRS		3114.3			943.5			0
			AFL		914			270			0
			MOS		144.3			22 Jan 2012			
			MSC								
CB119 PART I (981190) Airframe	Cb 119 Inspection (Part I) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		140.5			14 May 2012			
			MSC								
CB119 PART II (981191) Airframe	Cb 119 Inspection (Part Ii) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		140.5			14 May 2012			
			MSC								
CB119A PART I (981192) Airframe	Cb 119A Inspection (Part I) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137.2			25 Aug 2012			
			MSC								
Notes: APPLIANCE NOT INSTALLED											
CB119A PART II (981193) Airframe	Cb 119A Inspection (Part Ii) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS		2943.7			1114.1			0
			AFL		858			326			0
			MOS		137.2			25 Aug 2012			
			MSC								
Notes: APPLIANCE NOT INSTALLED											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB120	Cb 120 Inspection - Engine High Pressure (Hp) Fuel Filter		HRS		3043.7			1014.1			0
	Assembly Housing CAP Seal / Seal Ring		AFL		886			298			0
			MOS		141.4			20 Apr 2012			
	(981200)		MSC								
Airframe											
Notes: SERIAL NUMBER NOT AFFECTED											
CB122	Cb 122 Replacement - Fuel Boost Pumps, P/N		HRS		2943.3			1114.5			0
	1159SCP500-5		AFL		858			326			0
			MOS		136.5			15 Sep 2012			
	(981220)		MSC								
Airframe											
CB122A	Cb 122A Replacement - Fuel Boost Pumps, P/N		HRS		1955			2102.8			0
	1159SCP500-5		AFL		591			593			0
			MOS		91.1			29 Jun 2016			
	(981221)		MSC								
Airframe											
Notes: ALREADY COMPLIED WITH ON 15.09.2012											
CB123	Cb 123 Inspection - Rudder Actuator Pressure Monitoring		HRS		2943.7			1114.1			0
	Port Plugs		AFL		858			326			0
			MOS		137.3			21 Aug 2012			
	(981230)		MSC								
Airframe											
Notes: N/A BY SERIAL NUMBER											
CB123A	Cb 123A Inspection - Rudder Actuator Pressure		HRS		2943.7			1114.1			0
	Monitoring Port Plugs		AFL		858			326			0
			MOS		136.6			11 Sep 2012			
	(981231)		MSC								
Airframe											
CB124	Cb 124 Replacement - Nose Wheel Steering Collar		HRS		2943.7			1114.1			0
	Hardware		AFL		858			326			0
			MOS		137.2			24 Aug 2012			
	(981240)		MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB125 (981250) Airframe	Cb 125 Removal - Aileron and Elevator Power Disconnect (ASC 099)		HRS		4057.8			0			0
			AFL		1184		0			0	
			MOS		137		31 Aug 2012				
			MSC				-				
CB125A (981251) Airframe	Cb 125A Removal - Aileron and Elevator Power Disconnect (ASC 099)		HRS		2673.4			1384.4			0
			AFL		787		397			0	
			MOS		124.4		20 Sep 2013				
			MSC				-				
CB127 (981270) Airframe	Cb 127 Inspection - Xm Weather Antenna Doubler Installation		HRS		2414			1643.8			0
			AFL		716		468			0	
			MOS		111.8		05 Oct 2014				
			MSC				-				
Notes: N/A - XM WEATHER IS NOT INSTALLED											
CB128 (981280) Airframe	Cb 128 Inspection - Aft Equipment Bay / Engine Pylon Temperature Sensor Switches		HRS		2883.8			1174			0
			AFL		849		335			0	
			MOS		135		31 Oct 2012				
			MSC				-				
Notes: EQUIP NOT INST											
CB129 (981290) Airframe	Cb 129 Replacement - Elevator Horn Bearings		HRS		2859.8			1198			0
			AFL		843		341			0	
			MOS		133.5		15 Dec 2012				
			MSC				-				
CB129A (981291) Airframe	Cb 129A - Replacement - Elevator Horn Bearings		HRS		2673.4			1384.4			0
			AFL		787		397			0	
			MOS		125.1		29 Aug 2013				
			MSC				-				
CB130 (981300) Airframe	Cb 130 Aileron Cable Feed-Thru Holes AT FS 576.5 (ASC 104)		HRS		2673.4			1384.4			0
			AFL		787		397			0	
			MOS		124.4		20 Sep 2013				
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB131 (981310) Airframe	Cb 131 Inspection - Cabin Window Seals		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					-			
CB132A (981321) Airframe	Cb 132A Flight Controls (ATA 27), Inspection - Gust Lock Handle Assembly on Aircraft With ASC 002		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.4			18 Aug 2013			
			MSC					-			
CB133 (981330) Airframe	Cb 133 - FIRE Protection (ATA 26), Modification - Relocation of Third Engine FIRE Bottle		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.4			18 Aug 2013			
			MSC					-			
CB133A (981331) Airframe	Cb 133A FIRE Protection, Modification - Relocation of Third Engine FIRE Bottle		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.4			18 Aug 2013			
			MSC					-			
CB134 (981340) Airframe	Cb 134 - Inspection - Tail Cone Anticollision Light - Fault Indicator Wiring		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		124.4			20 Sep 2013			
			MSC					-			
CB135 (981350) Airframe	Cb 135 - Replacement - Main Battery Chargers		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB135A (981351) Airframe	Cb 135A - Replacement - Main Battery Chargers		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB136 (981360) Airframe	Cb 136 - Modification - Plug-In Monitors, P/N 7002-260 and 7002-261, Installed With Avds		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC								
CB137 (981370) Airframe	Cb 137 - Inspection - AIR Inlet Door Actuator		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC								
CB138 (981380) Airframe	Cb 138 - Replacement - AIR Inlet Door Actuator		HRS		2673.4			1384.4			0
			AFL		787			397			0
			MOS		125.1			29 Aug 2013			
			MSC								
CB139 (981390) Airframe	Cb 139 - Inspection - Outboard Rudder Trim Cable Installation AT Fuselage Station 733		HRS		2605.4			1452.4			0
			AFL		774			410			0
			MOS		122.6			13 Nov 2013			
			MSC								
Notes: SERIAL NUMBER NOT AFFECTED											
CB140 (981400) Airframe	Cb 140 - Inspection - Fuel Boost Pump Electromagnetic Interference (Emi) Filter Connectors		HRS		2545.9			1511.9			0
			AFL		757			427			0
			MOS		119.4			18 Feb 2014			
			MSC								
Notes: SERIAL NUMBER NOT AFFECTED											
CB141 (981410) Airframe	Cb 141 Inspection - Main Landing Gear Timers - Striker ARM Shaft		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC								
CB142 (981420) Airframe	Cb 142 - Replacement - Motive Flow Lines for Mid-Wing Fuel Ejector (ASC 063A)		HRS		2545.9			1511.9			0
			AFL		757			427			0
			MOS		119.4			18 Feb 2014			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB143 (981430) Airframe	Cb 143 - Inspection - Engine Removable Fairings - Non-Conformance		HRS		2545.9			1511.9			0
			AFL		757			427			0
			MOS		119.4			18 Feb 2014			
			MSC								
Notes: SERIAL NUMBER NOT AFFECTED											
CB144 (981440) Airframe	Cb 144 - Inspection - Passenger Oxygen System - Tube Assembly Bonding		HRS		2545.9			1511.9			0
			AFL		757			427			0
			MOS		119.2			25 Feb 2014			
			MSC								
Notes: N/A BY SERIAL NUMBER EFFECTIVITY (MB)											
CB145 (981450) Airframe	Cb 145 Elevator Hardover Prevention System (Hops) Improvement (ASC 112)		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.6			11 Sep 2015			
			MSC								
CB149 (981490) Airframe	Cb 149 Inspection - Auxiliary Power Unit (APU) Mount Pallet Shimming		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		113.8			05 Aug 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB149A (981491) Airframe	Cb 149A Inspection - Auxiliary Power Unit (APU) Mount Pallet Shimming		HRS		1735.4			2322.4			0
			AFL		520			664			0
			MOS		76.8			07 Sep 2017			
			MSC								
CB150 (981500) Airframe	Cb 150 Modification - Aircraft Main Battery Chargers		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		111.9			03 Oct 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB150A (981501) Airframe	Cb 150A Modification - Aircraft Main Battery Chargers		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.7			10 Sep 2015			
			MSC					-			
CB150B (981502) Airframe	Cb 150B Modification - Aircraft Main Battery Chargers		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC					-			
CB153 (981530) Airframe	Cb 153 - Inspection - Cockpit Overhead Circuit Breaker Panels		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.7			08 Sep 2015			
			MSC					-			
CB154 (981540) Airframe	Cb 154 Inspection - Rudder Actuator Aft ROD End Attaching Hardware		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		107.6			13 Feb 2015			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB154A (981541) Airframe	Cb 154A Inspection - Rudder Actuator Aft ROD End Attaching Hardware		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.7			09 Sep 2015			
			MSC					-			
CB155 (981550) Airframe	Cb 155 Inspection - Engine Driven Pump (Edp) Case Drain Hydraulic Hose - Left Engine Pylon (ASC 120)		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.9			03 Sep 2015			
			MSC					-			
CB158 (981580) Airframe	Cb 158 Inspection - Heated Fuel Return Line Coupling Nut Subassembly		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.5			15 Sep 2015			
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB158A (981581) Airframe	Cb 158A Inspection - Heated Fuel Return Line Coupling		HRS		1756.7			2301.1			0
	Nut Subassembly		AFL		531			653			0
			MOS		79.4			20 Jun 2017			
			MSC								
Notes: PREVIOUSLY COMPLIED WITH											
CB159 (981590) Airframe	Cb 159 Replacement - Main Landing Gear Door Actuator		HRS		2016.2			2041.6			0
	End CAP - Life Limit		AFL		607			577			0
			MOS		92.5			15 May 2016			
			MSC								
Notes: I.A.W. CB 157 - LDG DOOR ACTUATORS HAVE NOT ACCUMULATED 9500 CSN, THEREFORE NOT AFFECTED BY CB 159.											
CB160 (981600) Airframe	Cb 160 Modification - Pressure Supply Line (ASC 122)		HRS		2176.4			1881.4			0
			AFL		663			521			0
			MOS		100.9			03 Sep 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB160A (981601) Airframe	Cb 160A Modification - Pressure Supply Line (ASC 122)		HRS		1947.2			2110.6			0
			AFL		587			597			0
			MOS		90.5			17 Jul 2016			
			MSC								
Notes: PREVIOUSLY COMPLIED WITH											
CB161 (981610) Airframe	Cb 161 Inspection - Elevator Hinge Brackets		HRS		1955			2102.8			0
			AFL		591			593			0
			MOS		91.1			29 Jun 2016			
			MSC								
Notes: LOGBOOK REVIEWED - NO ELEVATOR STOP REPAIRS PRESENT											
CB163 (981630) Airframe	Cb 163 Modification - Nose Landing Gear Electrical		HRS		1909.4			2148.4			0
	Harness Installation (ASC 116A)		AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB163A	Cb 163A Modification - Nose Landing Gear Electrical		HRS		1803			2254.8			0
	Harness Installation (ASC 116B)		AFL		543			641			0
	(981631)		MOS		81.5			17 Apr 2017			
	Airframe		MSC								
Notes: ASC 116B WAS ALREADY COMPLIED WITH AT TIME OF CB 163A PUBLISHING. REFER TO CODE 971162											
CB164 PART I	Cb 164 Modification - Spoiler Throwboard Mounting Point		HRS		1909.4			2148.4			0
	(Part 1)		AFL		573			611			0
	(981640)		MOS		88.7			09 Sep 2016			
	Airframe		MSC								
CB164 PART II	Cb 164 Modification - Spoiler Throwboard Mounting Point		HRS		1909.4			2148.4			0
	(PART2)		AFL		573			611			0
	(981641)		MOS		88.7			09 Sep 2016			
	Airframe		MSC								
CB164A	Cb 164A Modification - Spoiler Throwboard Mounting		HRS		957.9			3099.9			0
	Points		AFL		313			871			0
	(981642)		DATE		1245 d			03 Sep 2020			
	Airframe		MSC								
CB165	Cb 165 Nose Wheel Steering Hydraulic Line Contact With		HRS		1909.4			2148.4			0
	Structure		AFL		573			611			0
	(981650)		MOS		88.7			10 Sep 2016			
	Airframe		MSC								
CB166	Cb 166 Inspection - Rudder Actuator Return Line for		HRS		1909.4			2148.4			0
	Contact With Elevator Torque Tube		AFL		573			611			0
	(981660)		MOS		88.7			10 Sep 2016			
	Airframe		MSC								
CB167	Cb 167 Inspection - Engine Stage 5 AIR Nonreturn Valve		HRS		1909.4			2148.4			0
	(981670)		AFL		573			611			0
	Airframe		MOS		88.7			10 Sep 2016			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB169 (981690) Airframe	Cb 169 Inspection - Wire Installation In Right Electrical Equipment Rack (Reer) Circuit Breaker (Cb) Panel		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			10 Sep 2016			
			MSC								
CB171 (981710) Airframe	Cb 171 Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve		HRS		1955			2102.8			0
			AFL		591			593			0
			MOS		90.8			06 Jul 2016			
			MSC								
Notes: VALVE CONDITION SATISFACTORY - NO EVIDENCE OF INTERNAL LEAKAGE											
CB171A (981711) Airframe	Cb 171A Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve		HRS		1756.7			2301.1			0
			AFL		531			653			0
			MOS		79.4			20 Jun 2017			
			MSC								
Notes: PREVOIUSLY COMPLIED WITH											
CB172 (981720) Airframe	Cb 172 Inspection - Cockpit Overhead Circuit Breaker Panels - Location G3		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.7			09 Sep 2016			
			MSC								
CB174 (981740) Airframe	Cb 174 Inspection - Rudder Actuator Hard Over Protection System (Hops) Wiring Harness Installation		HRS		1909.4			2148.4			0
			AFL		573			611			0
			MOS		88.6			11 Sep 2016			
			MSC								
CB175 (981750) Airframe	Cb 175 Modification - Pedestal Assembly Edge Light Panel Upgrade		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		90.3			22 Jul 2016			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB175A	Cb 175A Modification - Pedestal Assembly Edge Light		HRS		1909.4			2148.4			0
	Panel Upgrade		AFL		573			611			0
	(981751)		MOS		88.4			19 Sep 2016			
	Airframe		MSC								
CB176 (LT IB)	Cb 176 Inspection - Main Landing Gear Wheel Bearings -		HRS		1735.4			2322.4			0
	Non-Conforming (Left Inboard Wheel)		AFL		520			664			0
	(981761)		MOS		76.8			06 Sep 2017			
	Airframe		MSC								
CB176 (LT OB)	Cb 176 Inspection - Main Landing Gear Wheel Bearings -		HRS		1735.4			2322.4			0
	Non-Conforming (Left Outboard Wheel)		AFL		520			664			0
	(981760)		MOS		76.8			06 Sep 2017			
	Airframe		MSC								
CB176 (RT IB)	Cb 176 Inspection - Main Landing Gear Wheel Bearings -		HRS		1735.4			2322.4			0
	Non-Conforming (Right Inboard Wheel)		AFL		520			664			0
	(981762)		MOS		76.8			06 Sep 2017			
	Airframe		MSC								
CB176 (RT OB)	Cb 176 Inspection - Main Landing Gear Wheel Bearings -		HRS		1735.4			2322.4			0
	Non-Conforming (Right Outboard Wheel)		AFL		520			664			0
	(981763)		MOS		76.7			08 Sep 2017			
	Airframe		MSC								
CB177	Cb 177 Inspection - Main Fuel Line Installation		HRS		1909.4			2148.4			0
	(981770)		AFL		573			611			0
	Airframe		MOS		87.9			03 Oct 2016			
			MSC								
CB180	Cb 180 Replacement - Engine Electronic Controller (Eec)		HRS		1654.7			2403.1	0		0
	Firebox Assembly (Rolls-Royce Sb-BR700-73-A101981 /		AFL		493			691	0		0
	Sb-BR700-73-A101985)		MOS		65.7			09 Aug 2018			
	(981800)		MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB180A	Engine and Fuel Control (ATA 73) Replacement - Engine		HRS								0
	Electronic Controller (Eec) Firebox Assembly (Rolls-		AFL								0
	Royce Sb-BR700-73-A101981/Sb-BR700-73-A101985),		DATE								
	Customer Bulletin (Optional)		MSC								
(981801)											
Airframe											
CB187	Cb 187 Modification - Auxiliary Hydraulic Pump Grounding		HRS		857.7			3200.1			0
	Installation (ASC 134)		AFL		280			904			0
			MOS		30.6			11 Jul 2021			
			MSC								
(981870)											
Airframe											
CB189	Cb 189 Inspection - Horizontal Stabilizer Vortex Generator		HRS		4057.8			0			0
	Configuration		AFL		1184			0			0
			MOS		57			30 Apr 2019			
			MSC								
(981890)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB189A	Cb 189A Inspection - Horizontal Stabilizer Vortex		HRS		4057.8			0	0		0
	Generator Configuration		AFL		1184			0	0		0
			DATE								
			MSC								
(981891)											
Airframe											
CB189B	Cb 189B Inspection - Horizontal Stabilizer Vortex		HRS		957.9			3099.9			0
	Generator Configuration		AFL		313			871			0
			MOS		42.4			18 Jul 2020			
			MSC								
(981892)											
Airframe											
CB190B PART I	Cb 190B (Part 1) Inspection - Horizontal Stabilizer Lower		HRS		957.9			3099.9			0
	Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		AFL		313			871			0
			MOS		41			01 Sep 2020			
			MSC								
(981904)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB190B PART II	Cb 190B (Part 2) Inspection - Horizontal Stabilizer Lower Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		41			01 Sep 2020			
	(981905)	Airframe	MSC								
CB190B PART III	Cb 190B (Part 3) Inspection - Horizontal Stabilizer Lower Bonded Skin (Fokker Sb RP-Dgup-18-08.1658)		HRS		957.9			3099.9			0
			AFL		313			871			0
			DATE		1247 d			01 Sep 2020			
	(981906)	Airframe	MSC								
CB192	Cb 192 - Left Engine Thrust Reverser Hydraulic Supply Line and Clips (Rolls Royce Sb-BR700-29-900644)		HRS		1189.2			2868.6			0
			AFL		361			823			0
	(981920)	Airframe	MOS		52.8			05 Sep 2019			
CB194	Cb 194 Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		1189.2			2868.6			0
			AFL		361			823			0
			MOS		52.7			08 Sep 2019			
	(981940)	Airframe	MSC								
CB194A	Cb 194A Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		4057.8			0			0
			AFL		1184			0			0
			MOS		49.9			03 Dec 2019			
	(981941)	Airframe	MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB194B	Cb 194B Modification - Inertial Reference Unit (Iru) Aircraft Personality Module (APM) Configuration Index File Update		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9			03 Sep 2020			
	(981942)	Airframe	MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB197 (981970) Airframe	Cb 197 Inspection - Lavatory Blower Pressure Switch Sensing Port		HRS		957.9			3099.9			0
			AFL		313			871			0
			MOS		40.9			03 Sep 2020			
			MSC								
CB199 (981990) Airframe	Cb 199 Modification - Jetwave System BLV7.1 Software Release (Honeywell Sb Jetwave-23-007)		HRS		981.5			3076.3			0
			AFL		315			869			0
			MOS		47.2			25 Feb 2020			
			MSC								
CB200 (982000) Airframe	Cb 200 Flight Controls (ATA 27), Inspection - Aileron Force Link Wiring Harness Installation		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		19.7			08 Jun 2022			
			MSC								
CB201 (982010) Airframe	Cb 201 Inspection - Outboard Flight Spoiler Bellcrank		HRS								0
			AFL								0
			DATE								
			MSC								
CB201A (982011) Airframe	Cb 201A Flight Controls (ATA 27) - Inspection - Outboard Flight Spoiler Bellcrank, Customer Bulletin		HRS		857.7			3200.1			0
			AFL		280			904			0
			MOS		30.6			13 Jul 2021			
			MSC								
CB201B (982012) Airframe	CB201B - Flight Controls (ATA 27) - Inspection - Outboard Flight Spoiler Bellcrank, Customer Bulletin (Mandatory)		HRS		616			3441.8			0
			AFL		220			964			0
			MOS		20			30 May 2022			
			MSC								
CB203 (982030) Airframe	Cb 203 Installation - Horizontal Stabilizer Cove Panels Av-Dec Gaskets (ASC 137A)		HRS		134.1			3923.7			0
			AFL		44			1140			0
			MOS		4.5			16 Sep 2023			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB206	Flight Controls (ATA 27) - Inspection - Rudder Lower		HRS		134.1			3923.7			0
	Hinge - Swivel #1 Assembly, Customer Bulletin		AFL		44			1140			0
	(Mandatory)		MOS		5.3			21 Aug 2023			
			MSC								
(982060)	Airframe										
CB209	Engine Fuel and Control (ATA 73) - Replacement –		HRS		346.5			3711.3			0
	Engine Fuel Control Dedicated Generator (Rolls-Royce		AFL		129			1055			0
	Sb BR700-73-101856), Customer Bulletin		MOS		11.5			15 Feb 2023			
			MSC								
(982090)	Airframe										
CB209A	Engine Fuel and Control (ATA 73) - Replacement - Engine		HRS		346.5			3711.3			0
	Fuel Control Dedicated Generator (Rolls-Royce Sb		AFL		129			1055			0
	BR700-73-101856), Customer Bulletin (Mandatory)		MOS		11.5			15 Feb 2023			
			MSC								
(982091)	Airframe										
CB209B	CB209B - Engine Fuel and Control (ATA 73) -		HRS								0
	Replacement - Engine Fuel Control Dedicated Generator		AFL								0
	(Rolls-Royce Sb BR700-73-101856), Customer Bulletin		MOS								
	(Mandatory)		MSC								
(982092)	Airframe										
CB211	CB211 - AIR (ATA 75) - Replacement - Variable Stator		HRS								0
	Vane (Vsv) Actuators (Rolls-Royce Nmsb Sb-BR700-75-		AFL								0
	900693), Customer Bulletin (Mandatory)		DATE								
			MSC								
(982110)	Airframe										
CB213	CB213 - Communications (ATA 23) - Modification -		HRS								0
	Jetwave System BLV8.1 Software Release (Honeywell Sb		AFL								0
	Jetwave-23-0009), Customer Bulletin (Cancelled)		DATE								
			MSC								
(982130)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB213A	CB213A - Communications (ATA 23) - Modification -		HRS								0
	Jetwave System BLV8.1 Software Release (Honeywell Sb		AFL								0
	Jetwave-23-0009), Customer Bulletin (Mandatory)		DATE								
(982131)			MSC								
Airframe											
CB214	CB214 - Ice and Rain Protection (ATA 30) - Inspection -		HRS		346.5			3711.3	0		0
	Wing Anti-Ice Supply Duct Installation Behind Landing		AFL		129			1055	0		0
	Light (Temp Suspended See G550-Mol-22-0002),		MOS		11.5			15 Feb 2023			
(982140)			MSC								
Airframe											
CB215	CB215 - FIRE Protection (ATA 26) - Inspection - Engine		HRS		134.1			3923.7			0
	FIRE Bottle Thermal Relief Discharge Port, Customer		AFL		44			1140			0
	Bulletin		MOS		5.5			16 Aug 2023			
(982150)			MSC								
Airframe											
CB216	CB216 - Stabilizers (ATA 55) - Horizontal Stabilizer Interior		HRS		346.5			3711.3			0
	Preventative Corrosion Inhibiting Compound (Cic)		AFL		129			1055			0
	Application, Customer Bulletin (Mandatory)		MOS		11.5			15 Feb 2023			
(982160)			MSC								
Airframe											
CB217	CB217 - Engine Controls (ATA 76), Inspection - Throttle		HRS		346.5			3711.3			0
	Quadrant, Customer Bulletin (Mandatory)		AFL		129			1055			0
			MOS		11.5			15 Feb 2023			
(982170)			MSC								
Airframe											
CB218	CB218 - Stabilizers (ATA 55) - Horizontal Stabilizer Interior		HRS		13.4			4044.4			0
	Mrb Report Task 55.10.00/10 - Maintenance Program		AFL		4			1180			0
	Initiation, Customer Bulletin (Mandatory)		DATE		41 d			21 Dec 2023			
(982180)			MSC								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB219	CB219 - Electrical Power (ATA 24) - Inspection - Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC								
(982190)											
Airframe											
CB219A	Electrical Power (ATA 24) - Inspection – Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC								
(982191)											
Airframe											
CB220	CB220 - Communications (ATA 23) - Replacement - Satellite Data Units (Sdu) DL150-00, Customer Bulletin (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC								
(982200)											
Airframe											
CSB019	Ce-Csb-5019 - CSB019 - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update, Cabin Service Bulletin (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC								
(940190)											
Airframe											
ST02696AT-D	ST02696AT-D Pax Oxy Control		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC								
(901001)											
Airframe											
ST02697AT-D	ST02697AT-D Emergency Lighting		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC								
(901007)											
Airframe											
ST02715AT-D	ST02715AT-D External Camera		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC								
(901010)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ST02796AT-D (901024) Airframe	ST02796AT-D Broad Band Multi-Link Sys (Bbml)		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC					-			
ST02915AT-D (901023) Airframe	ST02915AT-D Lsz-860 Lightning Detector		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC					-			
ST03238AT-D (901367) Airframe	ST03238AT-D SATCOM High Speed Data (Hd-128)(MCS-7100)		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC					-			
ST03290AT-D (901031) Airframe	ST03290AT-D (Atg) Injection Molded Elec Window Shades		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC					-			
ST03533AT-D (901036) Airframe	ST03533AT-D, Aircell Axxess Iridium (Satellite Phone)		HRS		4025.2			32.6			0
			AFL		1170			14			0
			MOS		184.3			22 Sep 2008			
			MSC					-			
SIAE - APU/Engine Service Information/Bulletins											
49-7933 R05 (957935) APU	APU - Sb 49-7933 R05 Airborne Auxiliary Power Unit		HRS		2575			0			0
	(APU) Oil - General - Approved Oils		APUS		1839			0			0
			MOS		96.1			29 Jan 2016			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
49-7933 R06 (957936) APU	APU - Sb 49-7933 R06 Airborne Auxiliary Power Unit		HRS		2575			0			0
	(APU) Oil - General - Approved Oils		APUS		1839			0			0
			MOS		82.6			13 Mar 2017			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49-7933 R08 (957938) APU	APU - Sb 49-7933 R08 Airborne Auxiliary Power Unit		HRS		2575			0			0
	(APU) Oil - General - Approved Oils		APUS		1839			0			0
			DATE								
			MSC						DUE**		
49-8252 (958252) APU	APU - 49-8252 - Airborne - Auxiliary Power Unit (APU) -		HRS		2575			0			0
	Approved Fuels for Honeywell Commercial Apus		APUS		1839			0			0
			DATE								
			MSC						-		
880320 (880320) Engine	No. 1 Engine - Sb BR700-73-900423 - One Time		HRS		4057.8			0			0
	Inspection of Eec Firebox Assembly for Paint Damage		ENC		1184			0			0
			MOS		112.7			09 Sep 2014			
			MSC						-		
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
880320 (890320) (880320) Engine	No. 2 Engine - Sb BR700-73-900423 - One Time		HRS		4057.8			0			0
	Inspection of Eec Firebox Assembly for Paint Damage		ENC		1184			0			0
			MOS		112.7			09 Sep 2014			
			MSC						-		
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
APU-49 R11 APU	APU - Implementation of the Honeywell Spectrometric Oil		HRS								0
	and Filter Analysis Program (Soap) for Honeywell		APUS								0
	Auxiliary Power Units (Apus), Service Information Letter		DATE								
	(Recommended)		MSC								
APU-49 R12 (950011) APU	APU - Sil APU-49 R12 - Implementation of the Honeywell		HRS								0
	Spectrometric Oil and Filter Analysis Program (Soap) for		APUS								0
	Honeywell Auxiliary Power Units (Apus), Service		DATE								
	Information Letter (Recommended)		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
APU-49 R13	APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
(950012)			APUS								0
APU			DATE								
			MSC								
BR700-29-900644	No. 1 Engine - Sb BR700-29-900644 - Left Engine Hydraulic Tubes and Fittings Engine Build Unit (Ebu) - Inspection of Clips and Tubes		HRS		1189.2			2868.6			0
(880660)			ENC		361			823			0
Engine			MOS		52.8			05 Sep 2019			
			MSC								
BR700-29-900644 R01	No. 1 Engine - Sb BR700-29-900644 R01 - Left Engine Hydraulic Tubes and Fittings (Ebu) - Inspection of Clips and Tubes		HRS		616		2000	3441.8	5441.8		0
(882916)			ENC		220			964			0
Engine			MOS		19.9			02 Jun 2022			
BR700-29-900644 R01 (892916)	No. 2 Engine - Sb BR700-29-900644 R01 - Left Engine Hydraulic Tubes and Fittings (Ebu) - Inspection of Clips and Tubes		HRS		616		2000	3441.8	5441.8		0
(882916)			ENC		220			964			0
Engine			MOS		19.9			02 Jun 2022			
BR700-70-900040 R11	No. 1 Engine - Sb BR700-70-900040 (Rev 14) - Engine Life Management - Fixed Interval Rework Engines		HRS		4048.2			9.6			0
(887001)			ENC		1179			5			0
Engine			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-70-900040 R11 (897001)	No. 2 Engine - Sb BR700-70-900040 (Rev 14) - Engine Life Management - Fixed Interval Rework Engines		HRS		4048.2			9.6			0
(887001)			ENC		1179			5			0
Engine			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-70-900294 R03 (887002) Engine	No. 1 Engine - Sb BR700-70-900294 Rev 3 - Task		HRS		4048.2			9.6			0
	Oriented Engine Inspection		ENC		1179			5			0
			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-70-900294 R03 (897002) (887002) Engine	No. 2 Engine - Sb BR700-70-900294 Rev 3 - Task		HRS		4048.2			9.6			0
	Oriented Engine Inspection		ENC		1179			5			0
			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-70-900412 (887003) Engine	No. 1 Engine - Sb BR700-70-900412 - BR710 Engine		HRS		4048.2			9.6			0
	Maint Prog		ENC		1179			5			0
			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-70-900412 (897003) (887003) Engine	No. 2 Engine - Sb BR700-70-900412 - BR710 Engine		HRS		4048.2			9.6			0
	Maint Prog		ENC		1179			5			0
			MOS		186.3			22 Jul 2008			
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-71-102131 (888017) Engine	No. 1 Engine - Sb BR700-71-102131 - Drains System		HRS								0
	Collection Tank - Introduction of Thicker Bracket for the		ENC								0
	Fuel Drains Tank		DATE								
			MSC								
Notes: ENGINE DECLARED HARD TIME											
BR700-71-102131 (898017) (888017) Engine	No. 2 Engine - Sb BR700-71-102131 - Drains System		HRS								0
	Collection Tank - Introduction of Thicker Bracket for the		ENC								0
	Fuel Drains Tank		DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-900384 (887188) Engine	No. 1 Engine - Sb BR700-71-900384 - Engine Electronic Controller (Eec) Harness		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-71-900384 (897188) (887188) Engine	No. 2 Engine - Sb BR700-71-900384 - Engine Electronic Controller (Eec) Harness		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-71-900413 (887189) Engine	No. 1 Engine - Sb BR700-71-900413 - Engine Build Unit (Ebu) Harness		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-71-900413 (897189) (887189) Engine	No. 2 Engine - Sb BR700-71-900413 - Engine Build Unit (Ebu) Harness		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101195 (880285) Engine	No. 1 Engine - Sb BR700-72-101195 - Intermediate Compressor Case		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101195 (890285) (880285) Engine	No. 2 Engine - Sb BR700-72-101195 - Intermediate Compressor Case		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101460 (880435) Engine	No. 1 Engine - Sb BR700-72-101460 Lp Comp Trim Balance Weights		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101460 (890435) (880435) Engine	No. 2 Engine - Sb BR700-72-101460 Lp Comp Trim		HRS		4057.8			0			0
	Balance Weights		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101469 R01 (880611) Engine	No. 1 Engine - Sb BR700-72-101469 R1 - Hp Compressor		HRS		4057.8			0			0
	Vortex Reducer Ring		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101469 R01 (890611) (880611) Engine	No. 2 Engine - Sb BR700-72-101469 R1 - Hp Compressor		HRS		4057.8			0			0
	Vortex Reducer Ring		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101471 (880439) Engine	No. 1 Engine - Sb BR700-72-101471 - Metco 58 Coated		HRS		4057.8			0			0
	Lp Compressor Blades		ENC		1184			0			0
			MOS		189.4			20 Apr 2008			
			MSC								
BR700-72-101471 (880439) (880439) Engine	No. 2 Engine - Sb BR700-72-101471 - Metco 58 Coated		HRS		4057.8			0			0
	Lp Compressor Blades		ENC		1184			0			0
			MOS		189.2			24 Apr 2008			
			MSC								
BR700-72-101474 R01 (880581) Engine	No. 1 Engine - Sb BR700-72-101474R1 - Laser Shock		HRS		4057.8			0			0
	Peened Lp Compressor Rotor Disc		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101474 R01 (890581) (880581) Engine	No. 2 Engine - Sb BR700-72-101474R1 - Laser Shock		HRS		4057.8			0			0
	Peened Lp Compressor Rotor Disc		ENC		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101476 R01 (880612) Engine	No. 1 Engine - Sb BR700-72-101476R1 - Introduction of A		HRS		4057.8			0			0
	New Combustion Chamber Without Cooling Ribs		ENC		1184			0			0
			MOS		99.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101476 R01 (890612) (880612) Engine	No. 2 Engine - Sb BR700-72-101476R1 - Introduction of A		HRS		4057.8			0			0
	New Combustion Chamber Without Cooling Ribs		ENC		1184			0			0
			MOS		99.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101540 R04 (880613) Engine	No. 1 Engine - Sb BR700-72-101540 R4 - Outlet Guide		HRS		4057.8			0			0
	Vane Housing Assembly		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101540 R04 (890613) (880613) Engine	No. 2 Engine - Sb BR700-72-101540 R4 - Outlet Guide		HRS		4057.8			0			0
	Vane Housing Assembly		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101620 (880575) Engine	No. 1 Engine - Sb BR700-72-101620 - Accessory		HRS		4057.8			0			0
	Gearbox Module		ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101620 (890575) (880575) Engine	No. 2 Engine - Sb BR700-72-101620 - Accessory		HRS		4057.8			0			0
	Gearbox Module		ENC		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101837 (883006) Engine	No. 1 Engine - Sb BR700-72-101837 - Introduction of an Hp Turbine Stage 1 Disc Made from A Different Material		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101837 (893006) (883006) Engine	No. 2 Engine - Sb BR700-72-101837 - Introduction of an Hp Turbine Stage 1 Disc Made from A Different Material		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-101858 (880610) Engine	No. 1 Engine - Sb BR700-72-101858 - Introduction of A Hp Compressor Stages 7 to 10 Rotor Disc Assembly With Revised Liner Coating		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		99.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101858 (890610) (880610) Engine	No. 2 Engine - Sb BR700-72-101858 - Introduction of A Hp Compressor Stages 7 to 10 Rotor Disc Assembly With Revised Liner Coating		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		99.8			05 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101891 (880614) Engine	No. 1 Engine - Sb BR700-72-101891 - Introduction of A Redesigned Gearline 12 Assembly Which Is Balanced Including the Permanent Magnetic Alternator (PMA) Rotor		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		106.4			18 Mar 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-72-101891 (890614)	No. 2 Engine - Sb BR700-72-101891 - Introduction of A		HRS		4057.8			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1184			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		106.4			18 Mar 2015			
			MSC								
(880614)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R01	No. 1 Engine - Sb BR700-72-101891R1 - Introduction of A		HRS		4057.8			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1184			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		73.3			21 Dec 2017			
			MSC								
(880624)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R01 (890624)	No. 2 Engine - Sb BR700-72-101891R1 - Introduction of A		HRS		4057.8			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1184			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		73.3			21 Dec 2017			
			MSC								
(880624)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R02	No. 1 Engine - Sb BR700-72-101891R2 - Introduction of A		HRS		4057.8			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1184			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		65.1			27 Aug 2018			
			MSC								
(880644)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-72-101891 R02 (890644)	No. 2 Engine - Sb BR700-72-101891R2 - Introduction of A		HRS		4057.8			0			0
	Redesigned Gearline 12 Assembly Which Is Balanced		ENC		1184			0			0
	Including the Permanent Magnetic Alternator (PMA) Rotor		MOS		65.1			27 Aug 2018			
			MSC								
(880644)											
Engine											

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101891 R03	No. 1 Engine - Sb BR700-72-101891R3 - Introduction of A Redesigned Gearline 12 Assembly Which Is Balanced Including the Permanent Magnetic Alternator (PMA) Rotor		HRS		4057.8			0			0
			ENC		1184			0			0
			MSC								
(880654)											
Engine											
BR700-72-101891 R03 (890654)	No. 2 Engine - Sb BR700-72-101891R3 - Introduction of A Redesigned Gearline 12 Assembly Which Is Balanced Including the Permanent Magnetic Alternator (PMA) Rotor		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
(880654)			MSC								
Engine											
BR700-72-101897	No. 1 Engine - Sb BR700-72-101897 - Introduction of an Alternative Standard of Hp Compressor Stage 1 Blade		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
(880615)			MSC								
Engine											
BR700-72-101897 (890615)	No. 2 Engine - Sb BR700-72-101897 - Introduction of an Alternative Standard of Hp Compressor Stage 1 Blade		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
(880615)			MSC								
Engine											
BR700-72-101969	No. 1 Engine - Sb BR700-72-101969 - Introduction of A New Fan Shaft Assembly With an Additional Inspection Method During the Manufacturing Process		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
(880645)			MSC								
Engine											
BR700-72-101969 (890645)	No. 2 Engine - Sb BR700-72-101969 - Introduction of A New Fan Shaft Assembly With an Additional Inspection Method During the Manufacturing Process		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
(880645)			MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE	MSC							Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102038	No. 1 Engine - Sb BR700-72-102038 - Low Pressure		HRS		4057.8			0			0
	Compressor Internal Gearbox AIR Distribution Tubes -		ENC		1184			0			0
	Introduction of A New AIR Manifold Housing		DATE								
	(880157)		MSC								
Engine											
BR700-72-102038 (890157)	No. 2 Engine - Sb BR700-72-102038 - Low Pressure		HRS		4057.8			0			0
	Compressor Internal Gearbox AIR Distribution Tubes -		ENC		1184			0			0
	Introduction of A New AIR Manifold Housing		DATE								
	(880157)		MSC								
Engine											
BR700-72-102070	No. 1 Engine - Sb BR700-72-102070- Introduction of		HRS		4057.8			0			0
	Alternative Drain Plugs AT the Engine Oil Tank Drain		ENC		1184			0			0
	Location of the Accessory Gearbox		DATE								
	(880657)		MSC								
Engine											
BR700-72-102070 (890657)	No. 2 Engine - Sb BR700-72-102070- Introduction of		HRS		4057.8			0			0
	Alternative Drain Plugs AT the Engine Oil Tank Drain		ENC		1184			0			0
	Location of the Accessory Gearbox		DATE								
	(880657)		MSC								
Engine											
BR700-72-102102	No. 1 Engine - Sb BR700-72-102102 - Introduction of an		HRS		4057.8			0			0
	Intermediate Case With Alternative Bushes Made from A		ENC		1184			0			0
	Different Material		DATE								
	(880648)		MSC								
Engine											
BR700-72-102102 (890648)	No. 2 Engine - Sb BR700-72-102102 - Introduction of an		HRS		4057.8			0			0
	Intermediate Case With Alternative Bushes Made from A		ENC		1184			0			0
	Different Material		DATE								
	(880648)		MSC								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102139	No. 1 Engine - Engine - Low Pressure (Lp) Compressor		HRS								0
	Nose Cone Assembly - Introduction of A Nose Cone		ENC								0
	Assembly With A Modified Nose Cone Coating, Service		DATE								
	Bulletin (Optional)		MSC								
(888830)	Engine										
BR700-72-102139	No. 2 Engine - Engine - Low Pressure (Lp) Compressor		HRS								0
	Nose Cone Assembly - Introduction of A Nose Cone		ENC								0
	Assembly With A Modified Nose Cone Coating, Service		DATE								
	Bulletin (Optional)		MSC								
(888830)	Engine										
BR700-72-102167	No. 1 Engine - Low Pressure (Lp) Turbine Fuel Shut-Off		HRS								0
	(Fso) Cable and Fittings - Introduction of A New Conduit		ENC								0
	Assembly for the Fuel Shut-Off Mechanism, Service		DATE								
	Bulletin (Optional)		MSC								
(888841)	Engine										
BR700-72-102167	No. 2 Engine - Low Pressure (Lp) Turbine Fuel Shut-Off		HRS								0
	(Fso) Cable and Fittings - Introduction of A New Conduit		ENC								0
	Assembly for the Fuel Shut-Off Mechanism, Service		DATE								
	Bulletin (Optional)		MSC								
(888841)	Engine										
BR700-72-102169	No. 1 Engine - Internal Gearbox Drive-Driven Assembly -		HRS								0
	Introduction of an Alternative Spirallock Insert for the		ENC								0
	Radial Drive Shaft (Rds) Lower Support Housing, Service		DATE								
	Bulletin (Optional)		MSC								
(888831)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102169 (898831)	No. 2 Engine - Internal Gearbox Drive-Driven Assembly - Introduction of an Alternative Spirallock Insert for the Radial Drive Shaft (Rds) Lower Support Housing, Service Bulletin (Optional)		HRS								0
			ENC								0
(888831)			DATE								
Engine			MSC								
<hr/>											
BR700-72-102322	No. 1 Engine - BR700-72-102322 - Accessory Gearbox Module and Accessory Gearbox Module Attach Parts and Fittings - Introduction of Alternative Accessory Gearbox Components, Service Bulletin (Optional)		HRS								0
			ENC								0
(888859)			DATE								
Engine			MSC								
<hr/>											
BR700-72-102322 (898859)	No. 2 Engine - BR700-72-102322 - Accessory Gearbox Module and Accessory Gearbox Module Attach Parts and Fittings - Introduction of Alternative Accessory Gearbox Components, Service Bulletin (Optional)		HRS								0
			ENC								0
(888859)			DATE								
Engine			MSC								
<hr/>											
BR700-72-900341	No. 1 Engine - Sb BR700-72-900341 Hp Compressor Blades - Borescope		HRS		4057.8			0			0
			ENC		1184			0			0
(880562)			DATE								
Engine			MSC								
<hr/>											
BR700-72-900341 (890562)	No. 2 Engine - Sb BR700-72-900341 Hp Compressor Blades - Borescope		HRS		4057.8			0			0
			ENC		1184			0			0
(880562)			DATE								
Engine			MSC								
<hr/>											
BR700-72-900409	No. 1 Engine - Sb BR700-72-900409 - Lp Compressor Case		HRS		4057.8			0			0
			ENC		1184			0			0
(880567)			DATE								
Engine			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900409 (890567) (880567) Engine	No. 2 Engine - Sb BR700-72-900409 - Lp Compressor Case		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-900419 (880582) Engine	No. 1 Engine - Sb BR700-72-900419 - Seal Rings and Additional Sealant		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-900419 (890582) (880582) Engine	No. 2 Engine - Sb BR700-72-900419 - Seal Rings and Additional Sealant		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								
BR700-72-900455 PART (A) (887397) Engine	No. 1 Engine - Sb BR700-72-900455 Visual Insp - Lp Compressor Annulus Fillers (Part A)		HRS		3489.3			568.5			0
			ENC		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								
Notes: NO CRACKS FOUND											
BR700-72-900455 PART (A) (897397) (887397) Engine	No. 2 Engine - Sb BR700-72-900455 Visual Insp - Lp Compressor Annulus Fillers (Part A)		HRS		3489.3			568.5			0
			ENC		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								
Notes: NO CRACKS FOUND											
BR700-72-900455 PART (B) (887398) Engine	No. 1 Engine - Sb BR700-72-900455 Eddy Current- Lp Compressor Annulus Fillers (Part B)		HRS		3489.3			568.5			0
			ENC		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900455 PART (B) (897398) (887398) Engine	No. 2 Engine - Sb BR700-72-900455 Eddy Current- Lp Compressor Annulus Fillers (Part B)		HRS		3489.3			568.5			0
			ENC		1011			173			0
			MOS		160.5			17 Sep 2010			
			MSC								
BR700-72-900521 PART A (880596) Engine	No. 1 Engine - Sb BR700-72-900521 (Part A) Visual Inspection - Lp Compressor Annulus Fillers		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		147.9			04 Oct 2011			
			MSC								
BR700-72-900521 PART A (890596) (880596) Engine	No. 2 Engine - Sb BR700-72-900521 (Part A) Visual Inspection - Lp Compressor Annulus Fillers		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		147.9			04 Oct 2011			
			MSC								
BR700-72-900521 PART B (880597) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Eddy Current Inspection - Lp Compressor Annulus Fillers		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		147.9			04 Oct 2011			
			MSC								
BR700-72-900521 PART B (890597) (880597) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Eddy Current Inspection - Lp Compressor Annulus Fillers		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		147.9			04 Oct 2011			
			MSC								
BR700-72-900521 R01 PART A (880591) Engine	No. 1 Engine - Sb BR700-72-900521 (Part A) Rev 1- Inspection - Lp Compressor Annulus Fillers		HRS		3242.3			815.5			0
			ENC		944			240			0
			MOS		149			30 Aug 2011			
BR700-72-900521 R01 PART A (890591) (880591) Engine	No. 2 Engine - Sb BR700-72-900521 (Part A) Rev 1- Inspection - Lp Compressor Annulus Fillers		HRS		3242.3			815.5			0
			ENC		944			240			0
			MOS		149			30 Aug 2011			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900521 R01 PART B (880592) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Rev 1 -		HRS		3242.3			815.5			0
	Inspection - Lp Compressor Annulus Fillers		ENC		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
Notes: REMOVE FREQUENCY AFTER SECOND COMPLIANCE											
BR700-72-900521 R01 PART B (890592) (880592) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Rev 1 -		HRS		3242.3			815.5			0
	Inspection - Lp Compressor Annulus Fillers		ENC		944			240			0
			MOS		149			30 Aug 2011			
			MSC								
Notes: REMOVE FREQUENCY AFTER SECOND COMPLIANCE											
BR700-72-900521 R02 PART A (880589) Engine	No. 1 Engine - Sb BR700-72-900521 (Part A) Rev 2 -		HRS		2943.7			1114.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		858			326			0
			MOS		137.4			19 Aug 2012			
			[End Of Month Item]								
BR700-72-900521 R02 PART A (890589) (880589) Engine	No. 2 Engine - Sb BR700-72-900521 (Part A) Rev 2 -		HRS		2943.7			1114.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		858			326			0
			MOS		137.4			19 Aug 2012			
			[End Of Month Item]								
BR700-72-900521 R02 PART B (880590) Engine	No. 1 Engine - Sb BR700-72-900521 (Part B) Rev 2 -		HRS		2943.7			1114.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		858			326			0
			MOS		137.4			19 Aug 2012			
			MSC								
Notes: N/A BY FILLER S/N RANGE											
BR700-72-900521 R02 PART B (890590) (880590) Engine	No. 2 Engine - Sb BR700-72-900521 (Part B) Rev 2 -		HRS		2943.7			1114.1			0
	Inspection - Lp Compressor Annulus Fillers		ENC		858			326			0
			MOS		137.4			19 Aug 2012			
			MSC								
Notes: N/A BY FILLER S/N RANGE											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900668	No. 1 Engine - Low Pressure (Lp) Compressor Case -		HRS								0
	Inspection Under the Fan Track Liner on Lp Compressor		ENC								0
	Cases of Pre Sb-BR700-72-100981 Standard - Non-		DATE								
	Modification Service Bulletin, Service Bulletin (Recommended)		MSC				ESV**				
(888832)	Engine										
BR700-72-900668	No. 2 Engine - Low Pressure (Lp) Compressor Case -		HRS								0
	Inspection Under the Fan Track Liner on Lp Compressor		ENC								0
	Cases of Pre Sb-BR700-72-100981 Standard - Non-		DATE								
	Modification Service Bulletin, Service Bulletin (Recommended)		MSC				ESV**				
(888832)	Engine										
BR700-72-900743	No. 1 Engine - BR700-72-900743 - Low Pressure (Lp)		HRS								0
	Compressor Rotor Disc - Ultrasonic Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		MOS								
	Bulletin, Service Bulletin (Recommended)		MSC				-				
(888857)	Engine										
BR700-72-900743 (898857)	No. 2 Engine - BR700-72-900743 - Low Pressure (Lp)		HRS								0
	Compressor Rotor Disc - Ultrasonic Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		MOS								
	Bulletin, Service Bulletin (Recommended)		MSC				-				
(888857)	Engine										
BR700-72- A101523 R03	No. 1 Engine - BR700-72-A101523 R03 - Engine - Low		HRS		2082.5			1975.3			0
	Pressure (Lp) Turbine Shut-Off Pawl Carrier - Introduction		ENC		637			547			0
	of Fuel Shut-Off Pawl Carrier Pivot Pins Made from A		MOS		96.5			16 Jan 2016			
	Different Material With Improved Corrosion Protection Properties		MSC				-				
(880128)	Engine										

Notes: ENGINE 1 SN: 15499 - NOT AFFECTED BY SB APPLICABILITY ("PRIOR TO ENGINE SERIAL NUMBER 15330")

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A101523 R03 (890128)	No. 2 Engine - BR700-72-A101523 R03 - Engine - Low Pressure (Lp) Turbine Shut-Off Pawl Carrier - Introduction		HRS		2082.5			1975.3			0
	of Fuel Shut-Off Pawl Carrier Pivot Pins Made from A		ENC		637			547			0
	Different Material With Improved Corrosion Protection		MOS		96.5			16 Jan 2016			
	Properties		MSC								
(880128)											
Engine											
Notes: ENGINE 2 SN: 15500 - NOT AFFECTED BY SB APPLICABILITY ("PRIOR TO ENGINE SERIAL NUMBER 15330")											
BR700-72- A900504 (880044)	No. 1 Engine - Asb BR700-72-A900504 Change of Life		HRS		3557.8			500			0
	Counting Method for Touch-and-Go and Overshoot		ENC		1035			149			0
			MOS		163.3			23 Jun 2010			
			MSC								
(880044)											
Engine											
BR700-72- A900504 (890044)	No. 2 Engine - Asb BR700-72-A900504 Change of Life		HRS		3557.8			500			0
	Counting Method for Touch-and-Go and Overshoot		ENC		1035			149			0
			MOS		163.3			23 Jun 2010			
			MSC								
(880044)											
Engine											
BR700-72- A900509 (880200)	No. 1 Engine - Alert Sb BR700-72-A900509 Replacement		HRS		4057.8			0			0
	of the Fuel Pump Splined Coupling		ENC		1184			0			0
			MOS		142.1			27 Mar 2012			
			MSC								
(880200)											
Engine											
BR700-72- A900509 (890200)	No. 2 Engine - Alert Sb BR700-72-A900509 Replacement		HRS		4057.8			0			0
	of the Fuel Pump Splined Coupling		ENC		1184			0			0
			MOS		142.1			27 Mar 2012			
			MSC								
(880200)											
Engine											
BR700-72- A900509 R01 (880301)	No. 1 Engine - Alert Sb BR700-72-A900509 (Revision 1)		HRS		4057.8			0			0
	Replacement of the Fuel Pump Splined Coupling		ENC		1184			0			0
			MOS		138.5			17 Jul 2012			
			MSC								
(880301)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900509 R01 (890301) (880301) Engine	No. 2 Engine - Alert Sb BR700-72-A900509 (Revision 1) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		138.5			17 Jul 2012			
			MSC								
BR700-72- A900509 R02 (880307) Engine	No. 1 Engine - Alert Sb BR700-72-A900509 (Revision 2) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		137.9			02 Aug 2012			
			MSC								
BR700-72- A900509 R02 (890307) (880307) Engine	No. 2 Engine - Alert Sb BR700-72-A900509 (Revision 2) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		137.9			02 Aug 2012			
			MSC								
BR700-72- A900509 R03 (880309) Engine	No. 1 Engine - Alert Sb BR700-72-A900509 (Revision 3) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		112.9			03 Sep 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72- A900509 R03 (890309) (880309) Engine	No. 2 Engine - Alert Sb BR700-72-A900509 (Revision 3) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		112.9			03 Sep 2014			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72- A900509 R04 (880339) Engine	No. 1 Engine - Alert Sb BR700-72-A900509 (Revision 4) Replacement of the Fuel Pump Splined Coupling		HRS		4057.8			0			0
			ENC		1184			0			0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900509 R04 (890339) (880339) Engine	No. 2 Engine - Alert Sb BR700-72-A900509 (Revision 4)		HRS		4057.8			0			0
	Replacement of the Fuel Pump Splined Coupling		ENC		1184			0			0
			DATE								
			MSC								
BR700-72- A900509 R05 (888854) Engine	No. 1 Engine - Sb BR700-72-A900509 R05 - Accessory		HRS		0			4057.8			0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		0			1184			0
	Coupling - Non-Modification Service Bulletin, Alert Service		DATE		20 d			11 Jan 2024			
	Bulletin (Optional)		MSC								
BR700-72- A900509 R05 (888854) Engine	No. 2 Engine - Sb BR700-72-A900509 R05 - Accessory		HRS		0			4057.8			0
	Gearbox Module - Replacement of the Fuel Pump Splined		ENC		0			1184			0
	Coupling - Non-Modification Service Bulletin, Alert Service		DATE		20 d			11 Jan 2024			
	Bulletin (Optional)		MSC								
BR700-72- A900732 (888855) Engine	No. 1 Engine - Sb BR700-72-A900732 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								
BR700-72- A900732 (888855) Engine	No. 2 Engine - Sb BR700-72-A900732 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72- A900732 R01	No. 1 Engine - BR700-72-A900732 R01 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp -		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								
(888856)	Engine										
BR700-72- A900732 R01 (898856)	No. 2 Engine - BR700-72-A900732 R01 - Low Pressure		HRS								0
	(Lp) Compressor Rotor Disc - Visual Inspection of the Lp -		ENC								0
	Compressor Rotor (Fan) Disc - Non-Modification Service		DATE								
	Bulletin, Alert Service Bulletin (Alert)		MSC								
(888856)	Engine										
BR700-73-101438 R05	No. 1 Engine - Engine Fuel and Control - External Fuel		HRS								0
	System AIR Tubes and Fittings - Introduction of External		ENC								0
	Dressings Changes for New Standard of Engine		DATE								
	Electronic Controller (Eec), Service Bulletin (Optional)		MSC								
(888843)	Engine										
BR700-73-101438 R05	No. 2 Engine - Engine Fuel and Control - External Fuel		HRS								0
	System AIR Tubes and Fittings - Introduction of External		ENC								0
	Dressings Changes for New Standard of Engine		DATE								
	Electronic Controller (Eec), Service Bulletin (Optional)		MSC								
(888843)	Engine										
BR700-73-101438 R05 PART 1	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service		MSC								
Bulletin Introduction of External Dressings Changes With											
Replacement of the Bypass Duct (Production Standard)											
(Optional)											
(880777)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101438 R05 PART 1 (890777)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes With Replacement of the Bypass Duct (Production Standard) (Optional)		MSC								
(880777)											
Engine											
BR700-73-101438 R05 PART 2	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes Without Replacement of the Bypass Duct (Retrofit Standard) (Optional)		MSC								
(880778)											
Engine											
BR700-73-101438 R05 PART 2 (890778)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin Introduction of External Dressings Changes Without Replacement of the Bypass Duct (Retrofit Standard) (Optional)		MSC								
(880778)											
Engine											
BR700-73-101438 R05 PART 3	No. 1 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin RE-Introduction of Bypass Duct Access Panel Attaching Bolts of Pre Service Bulletin Sb-BR700-72- 101286 Standard (Optional)		MSC								
(880780)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101438 R05 PART 3 (890780)	No. 2 Engine - Accomplish Engine Fuel and Control -		HRS								0
	External Fuel System AIR Tubes and Fittings -		ENC								0
	Introduction of External Dressings Changes for New		DATE								
	Standard of Engine Electronic Controller (Eec), Service Bulletin RE-Introduction of Bypass Duct Access Panel Attaching Bolts of Pre Service Bulletin Sb-BR700-72- 101286 Standard (Optional)		MSC								
(880780)	Engine										
BR700-73-101833 R02 (880340)	No. 1 Engine - Sb BR700-73-101833R2 - Introduction of A		HRS		4057.8			0			0
	Revised Drive Shaft Connection for the Fuel Pump		ENC		1184			0			0
			DATE								
			MSC								
(880340)	Engine										
BR700-73-101833 R02 (890340) (880340)	No. 2 Engine - Sb BR700-73-101833R2 - Introduction of A		HRS		4057.8			0			0
	Revised Drive Shaft Connection for the Fuel Pump		ENC		1184			0			0
			DATE								
			MSC				ESV**				
(880340)	Engine										
BR700-73-101833 R03	No. 1 Engine - BR700-73-101833 R03 - Engine Fuel and		HRS								0
	Control - Fuel Pump - Introduction of A Revised Drive		ENC								0
	Shaft Connection for the Fuel Pump, Service Bulletin		DATE								
	(Optional)		MSC								
(888847)	Engine										
BR700-73-101833 R03 (898847)	No. 2 Engine - BR700-73-101833 R03 - Engine Fuel and		HRS								0
	Control - Fuel Pump - Introduction of A Revised Drive		ENC								0
	Shaft Connection for the Fuel Pump, Service Bulletin		DATE								
	(Optional)		MSC								
(888847)	Engine										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW	DATE								Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101856 R02 (880129) Engine	No. 1 Engine - Campaign Sb - BR700-73-101856R2 -		HRS		4057.8			0			0
	Introduction of A New Varnish for the Windings of the		ENC		1184			0			0
	Permanent Magnetic Alternator (PMA)		DATE								
			MSC								
BR700-73-101856 R02 (890129) (880129) Engine	No. 2 Engine - Campaign Sb - BR700-73-101856R2 -		HRS		4057.8			0			0
	Introduction of A New Varnish for the Windings of the		ENC		1184			0			0
	Permanent Magnetic Alternator (PMA)		DATE								
			MSC								
BR700-73-900423 R01 (880324) Engine	No. 1 Engine - Sb BR700-73-900423R1 - One Time		HRS		4057.8			0			0
	Inspection of Eec Firebox Assembly for Paint Damage		ENC		1184			0			0
			MOS		106.7			10 Mar 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-900423 R01 (890324) (880324) Engine	No. 2 Engine - Sb BR700-73-900423R1 - One Time		HRS		4057.8			0			0
	Inspection of Eec Firebox Assembly for Paint Damage		ENC		1184			0			0
			MOS		106.7			10 Mar 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-900423 R04 (888842) Engine	No. 1 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - One-Time Inspection of the		ENC								0
	Eec Firebox Assembly for Paint Damage - Non-		DATE								
	Modification Service Bulletin (This Non-Modification Sb- BR700-73-9000423 Is No Longer Valid and Can Be Closed), Service Bulletin (Optional)		MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

BR700-73-900423 R04	No. 2 Engine - Engine Fuel and Control - Engine		HRS								0
	Electronic Controller (Eec) - One-Time Inspection of the		ENC								0
	Eec Firebox Assembly for Paint Damage - Non-		DATE								
	Modification Service Bulletin (This Non-Modification Sb- BR700-73-9000423 Is No Longer Valid and Can Be Closed), Service Bulletin (Optional)		MSC				-				

(888842)
Engine

BR700-73-900463	No. 1 Engine - Sb BR700-73-900463 - Removal of Eec for		HRS		4057.8			0			0
	C-15 Capacitor Replacement		ENC		1184			0			0
			DATE								
			MSC				-				

(880319)
Engine

BR700-73-900463 (890319)	No. 2 Engine - Sb BR700-73-900463 - Removal of Eec for		HRS		4057.8			0			0
	C-15 Capacitor Replacement		ENC		1184			0			0
			DATE								
			MSC				-				

(880319)
Engine

BR700-73- A101981 R02	No. 1 Engine - Alert Sb BR700-73-A101981R2 -		HRS		4057.8			0			0
	Introduction of A New Eec Firebox Assembly With A		ENC		1184			0			0
	Revised Paint System.		MOS		78.6			12 Jul 2017			
			MSC				-				

(880465)
Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

BR700-73- A101981 R02 (890465)	No. 2 Engine - Alert Sb BR700-73-A101981R2 -		HRS		4057.8			0			0
	Introduction of A New Eec Firebox Assembly With A		ENC		1184			0			0
	Revised Paint System.		MOS		78.6			12 Jul 2017			
			MSC				-				

(880465)
Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73- A101981 R03 (880466) Engine	No. 1 Engine - Alert Sb BR700-73-A101981R3 - Introduction of A New Eec Firebox Assembly With A Revised Paint System.		HRS		1654.7			2403.1	0		0
			ENC		493			691	0		0
			MOS		65.7			09 Aug 2018			
			MSC								
BR700-73- A101981 R03 (890466) (880466) Engine	No. 2 Engine - Alert Sb BR700-73-A101981R3 - Introduction of A New Eec Firebox Assembly With A Revised Paint System.		HRS		1654.7			2403.1			0
			ENC		493			691			0
			MOS		65.7			09 Aug 2018			
			MSC							DUE**	
BR700-73- A101981 R04 (880832) Engine	No. 1 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
BR700-73- A101981 R04 (880832) Engine	No. 2 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								
BR700-73- A101981 R05 (888844) Engine	No. 1 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

**BR700-73-
A101981 R05**

No. 2 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)

HRS
ENC
DATE
MSC

0
0

(888844)
Engine

**BR700-73-
A101985 R04**

No. 1 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)

HRS
ENC
DATE
MSC

0
0

(888833)
Engine

**BR700-73-
A101985 R04**

No. 2 Engine - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of A New Eec Firebox Assembly With A Revised Paint System, Service Bulletin (Optional)

HRS
ENC
DATE
MSC

0
0

(888833)
Engine

**BR700-73-
A900083 R01**

No. 1 Engine - Alert Sb BR700-73-A900083R1 - Replacement of Non-Conforming Parts of the Eec Firebox Assembly

HRS
ENC
MOS
MSC

4057.8
1184
61.5

0
0
14 Dec 2018

0
0

(880131)
Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

**BR700-73-
A900083 R01
(890131)**

No. 2 Engine - Alert Sb BR700-73-A900083R1 - Replacement of Non-Conforming Parts of the Eec Firebox Assembly

HRS
ENC
MOS
MSC

4057.8
1184
61.5

0
0
14 Dec 2018

0
0

(880131)
Engine

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73- A900083 R02 (880133) Engine	No. 1 Engine - Alert Sb BR700-73-A900083R2 -		HRS		229.7			3828.1			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		82			1102			0
	Assembly		MOS		8.3			23 May 2023			
			MSC								
BR700-73- A900083 R02 (890133) (880133) Engine	No. 2 Engine - Alert Sb BR700-73-A900083R2 -		HRS		313.5			3744.3			0
	Replacement of Non-Conforming Parts of the Eec Firebox		ENC		117			1067			0
	Assembly		MOS		10.3			21 Mar 2023			
			MSC								
BR700-73- A900083 R03 (888849) Engine	No. 1 Engine - Engine Fuel and Control Engine Electronic		HRS								0
	Controller (Eec) - Replacement of Non-Conforming Parts		ENC								0
	of the Eec Firebox Assembly - Non-Modification Service		DATE								
	Bulletin, Service Bulletin (Optional)		MSC								
BR700-73- A900083 R03 (888849) Engine	No. 2 Engine - Engine Fuel and Control Engine Electronic		HRS								0
	Controller (Eec) - Replacement of Non-Conforming Parts		ENC								0
	of the Eec Firebox Assembly - Non-Modification Service		DATE								
	Bulletin, Service Bulletin (Optional)		MSC								
BR700-73- A900451 (887396) Engine	No. 1 Engine - Sb BR700-73-A900451 - Combined		HRS		4057.8			0			0
	Overspeed Shutoff Solenoid		ENC		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								
BR700-73- A900451 (897396) (887396) Engine	No. 2 Engine - Sb BR700-73-A900451 - Combined		HRS		4057.8			0			0
	Overspeed Shutoff Solenoid		ENC		1184			0			0
			MOS		188.2			24 May 2008			
			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-102193	No. 1 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
(888835)			DATE								
Engine			MSC								
<hr/>											
BR700-74-102193	No. 2 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
(888835)			DATE								
Engine			MSC								
<hr/>											
BR700-74-102193 R01	No. 1 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
(888837)			DATE								
Engine			MSC								
<hr/>											
BR700-74-102193 R01	No. 2 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
(888837)			DATE								
Engine			MSC								
<hr/>											
BR700-74-102193 R02	No. 1 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS		0			4057.8			0
			ENC		0			1184			0
(888838)			DATE		20 d		11 Jan 2024				
Engine			MSC								
<hr/>											
BR700-74-102193 R02	No. 2 Engine - Ignition - Ignitor Plug - Introduction of A New Ignitor Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS		0			4057.8			0
			ENC		0			1184			0
(888838)			DATE		20 d		11 Jan 2024				
Engine			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-900308 (887532) Engine	No. 1 Engine - Sb BR700-75-900308 - Vsv Mechanism Lubrication		HRS		2414			1643.8			0
			ENC		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC								
BR700-75-900308 (897532) (887532) Engine	No. 2 Engine - Sb BR700-75-900308 - Vsv Mechanism Lubrication		HRS		2414			1643.8			0
			ENC		716			468			0
			MOS		111.8			05 Oct 2014			
			MSC								
BR700-75-900693 (888845) Engine	No. 1 Engine - Campaign Sb - BR700-75-900693 - AIR - Vsv Actuator - Replacement of Variable Stator Vane (Vsv) Actuators - Non-Modification Service Bulletin, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC								
BR700-75-900693 (888845) Engine	No. 2 Engine - Campaign Sb - BR700-75-900693 - AIR - Vsv Actuator - Replacement of Variable Stator Vane (Vsv) Actuators - Non-Modification Service Bulletin, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC								
BR700-77-101875 (880121) Engine	No. 1 Engine - Sb BR700-77-101875 - N2 Speed Probes - Introduction of New Attaching Bolts With Shorter Length		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		99.5			15 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-77-101875 (890121) (880121) Engine	No. 2 Engine - Sb BR700-77-101875 - N2 Speed Probes - Introduction of New Attaching Bolts With Shorter Length		HRS		4057.8			0			0
			ENC		1184			0			0
			MOS		99.5			15 Oct 2015			
			MSC								
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-77-101875 R02 (880134) Engine	No. 1 Engine - Sb BR700-77-101875R2 - N2 Speed		HRS		4057.8			0			0
	Probes - Introduction of New Attaching Bolts With Shorter Length		ENC		1184			0			0
			DATE								
			MSC							DUE**	
BR700-77-101875 R02 (890134) (880134) Engine	No. 2 Engine - Sb BR700-77-101875R2 - N2 Speed		HRS		4057.8			0			0
	Probes - Introduction of New Attaching Bolts With Shorter Length		ENC		1184			0			0
			DATE								
			MSC							DUE**	
BR700-77-900329 (887711) Engine	No. 1 Engine - Sb BR700-77-900329 R1 - N2 Speed		HRS		4057.8			0			0
	Probes		ENC		1184			0			0
			DATE								
			MSC							-	
BR700-77-900329 (897711) (887711) Engine	No. 2 Engine - Sb BR700-77-900329 R1 - N2 Speed		HRS		4057.8			0			0
	Probes		ENC		1184			0			0
			DATE								
			MSC							-	
BR700-78-101983 R02 (888846) Engine	No. 1 Engine - Campaign Sb - BR700-78-101983 R02 - Exhaust - Thrust Reverser Door Stow Switch - Introduction of A New Door Stow Switch With an Improved Functionality, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC							-	
BR700-78-101983 R02 (888846) Engine	No. 2 Engine - Campaign Sb - BR700-78-101983 R02 - Exhaust - Thrust Reverser Door Stow Switch - Introduction of A New Door Stow Switch With an Improved Functionality, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC							-	

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-78-101997	No. 1 Engine - Sb BR700-78-101997 - Introduction of New Fastener Definitions Which Are Used to Mount the Tru Access Panels Onto the Tru Structure.		HRS		4057.8			0			0
			ENC		1184			0			0
(880642)			DATE								
Engine			MSC								
<hr/>											
BR700-78-101997 (890642)	No. 2 Engine - Sb BR700-78-101997 - Introduction of New Fastener Definitions Which Are Used to Mount the Tru Access Panels Onto the Tru Structure.		HRS		4057.8			0			0
			ENC		1184			0			0
(880642)			DATE								
Engine			MSC								
<hr/>											
BR700-79-101803 R01	No. 1 Engine - Sb BR700-79-101803R1 - Introduction of New Oil Pump Unit With Improved Gears		HRS		4057.8			0			0
			ENC		1184			0			0
(887944)			DATE								
Engine			MSC								
<hr/>											
BR700-79-101803 R01 (897944)	No. 2 Engine - Sb BR700-79-101803R1 - Introduction of New Oil Pump Unit With Improved Gears		HRS		4057.8			0			0
			ENC		1184			0			0
(887944)			DATE								
Engine			MSC								
<hr/>											
BR700-80-101900 R01	No. 1 Engine - Sb BR700-80-101900R1 - Introduction of A New AIR Turbine Starter With Revised Oil Seal.		HRS		4057.8			0			0
			ENC		1184			0			0
(880646)			DATE								
Engine			MSC								
<hr/>											
BR700-80-101900 R01 (890646)	No. 2 Engine - Sb BR700-80-101900R1 - Introduction of A New AIR Turbine Starter With Revised Oil Seal.		HRS		4057.8			0			0
			ENC		1184			0			0
(880646)			DATE								
Engine			MSC								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

WE3881600-49-7350 R02

APU - Sb WE3881600-49-7350 R02 - Airborne
 Auxiliarypower- Oil Pump Assembly - Replace Plug, Pn
 AN814-4D With Pn AN814-4DL, Filter Housing, Pn
 WE3881618-1 With Pn WE3881771-1, Oil Filter
 Elements, Pn WE3881639-1 With Pn WE3881767-1, and
 Bolt Pn MS9556-08 With Pn MS9565-08, Service Bulletin
 (Recommended)

HRS
 APUS
 DATE
 MSC

ESV**

0
 0

(952056)

APU